



वी.एस.पी
VSP

RASTRIYA ISPAT NIGAM LIMITED
VISAKHAPATNAM STEEL PLANT
RAW MATERIAL HANDLING PLANT
ELECTRICAL SHIFT REPORT

Date: 28/06/2025

Incharge(s): Saurabh Kumar Yadav

Shift: C

Sl No	Area	Equipment	Problem	Action	From	To	Remarks
1	OHP	TT3 on bypass 1	position bit missing,glass fuse blown,control cable got damaged	control cable proper insulation provided,glass fuse replaced	01:15:00	01:35:00	
2	OHP	co 29	olr acted	reset	02:30:00	02:35:00	
3	OHP	CO 35	BRS acted,not reset	sensor cleaned than ok	23:30:00	23:45:00	
4	OHP	VF 22	MPCB trips,NO contact add on block problem	NO contact bypass	02:20:00	02:40:00	
5	CHP	CC 34 scr2	LT not working,drive trips in overload	reset	22:30:00	22:40:00	
6	CHP	CC 32 SCR5	LT not taking place,M@ mpcb trips	mpcb made on	23:22:00	23:32:00	
7	CHP	CC 31 S3	LT not taking place,drive trips in overload	reset	00:20:00	00:30:00	
8	CHP	CC 105 scr 10	B/C not running,cjs acted	check all control ckt all ok,informed operation for cleaning than healthy	02:25:00	02:55:00	
9	CHP	CC 36 S1	LT not working,OT acted cable not winded properly	cable unwinding and winding done properly	02:25:00	02:40:00	
10	CHP	CC 44	motor trips in overload	reset	03:20:00	03:25:00	
11	CHP	CC 36 S1	luffing not working,mechanical problem,air lock	mechanical problem	04:45:00	05:00:00	