



वी.एस.पी
VSP

RASTRIYA ISPAT NIGAM LIMITED
VISAKHAPATNAM STEEL PLANT
RAW MATERIAL HANDLING PLANT
ELECTRICAL SHIFT REPORT

Date: 26/05/2025

Incharge(s): V Balaji Naik

Shift: B

| Sl No | Area | Equipment | Problem | Action | From | To | Remarks |
|-------|------|--------------|---|---|----------|----------|--|
| 1 | OHP | CO76R | OLR acted | Reset done | 14:00:00 | 14:00:00 | 07.45am to 08.00am |
| 2 | OHP | BRC on CO30 | Bridge conveyor OLR acted | Reset done | 14:00:00 | 14:00:00 | 07.30am to 7.45am |
| 3 | OHP | WOBR on CO6a | Boom conveyor not working found stone struck in ZSS cage and ZSS acting | Stone removed and given clearance | 14:00:00 | 14:00:00 | 08.15am to 08.30am |
| 4 | OHP | CO35 | Stopping and starting found ZSS acting due to slippage of tail end drum | Informed to mechanical and operation | 14:00:00 | 14:00:00 | 08.30am to 08.45am |
| 5 | OHP | CO87 | OLR acted | Reset done | 14:00:00 | 14:00:00 | 01.30pm to 01.45pm |
| 6 | OHP | SCR5 on CC32 | *LT not working found PCRD over tension acted *Slew not working found Slew out put relay glass fuse blown. *TUL CJS not healthy found CJS module problem | * PCRD over tension limit released then ok *Slew out put realy glass fuse replaced. *TUL , CJS module replaced then ok | 14:00:00 | 14:00:00 | 09.50am to 10.10am |
| 7 | CHP | S1 onCC34 | Luffing not working found air lock in system | Informed to mechanical after air lock it is ok | 14:00:00 | 14:00:00 | 07.00am to 07.05am not an electrical delay |
| 8 | CHP | CC223 | Motor not running found C1 contactor A1 and A2 coil supply loase | Tightened then ok | 14:00:00 | 14:00:00 | 08.50am to 09.00am |
| 9 | CHP | SCR2 on CC35 | LT not working found PCRD over tension limit acted | Tension limit released then ok | 14:00:00 | 14:00:00 | 10.20am to 10.30am |



वी.एस.पी
VSP

RASTRIYA ISPAT NIGAM LIMITED
VISAKHAPATNAM STEEL PLANT
RAW MATERIAL HANDLING PLANT
ELECTRICAL SHIFT REPORT

Date: 26/05/2025

Incharge(s): V Balaji Naik

Shift: B

| Sl No | Area | Equipment | Problem | Action | From | To | Remarks |
|-------|------|------------|--|---|----------|----------|--------------------|
| 10 | CHP | S1 on CC34 | LT not working found drive over load fault trip(Mechanical gear box fixing work informed to electrical cable winding done found ok) | Reset done | 14:00:00 | 14:00:00 | 10.10am to 10.20am |
| 11 | CHP | CC131 | Over load trip | Reset done | 14:00:00 | 14:00:00 | 04.00pm to 4.40pm |
| 12 | WT | CP4 | Pusher not moving found communication bit red | In LC10a ether net cable connections re connected then ok | 14:00:00 | 14:00:00 | 10.45am to 11.am |
| 13 | WT | OP9 | Reached to no power zone at parking area after rake completion no delay while reaching to parking zone | Bring back to power zone by arranging jumpers | 14:00:00 | 14:00:00 | 10.30am to 10.40am |