



वी.एस.पी
VSP

RASTRIYA ISPAT NIGAM LIMITED
VISAKHAPATNAM STEEL PLANT
RAW MATERIAL HANDLING PLANT
ELECTRICAL SHIFT REPORT

Date: 30/05/2025

Incharge(s): V Balaji Naik, G Eswara Rao

Shift: C

Sl No	Area	Equipment	Problem	Action	From	To	Remarks
1	OHP	CO29	tripped on olr 4times	reset done	02:20:00	02:35:00	
2	OHP	TT2 on CO21	position sensor and chute jam sensor in bypass condition	bypass removed and kept in ckt	23:00:00	23:10:00	
3	OHP	WOBR on CO6a	BC not running found ZSS acted due to stone struck in ZSS cage	Stone removed then ok	23:00:00	23:30:00	
4	CHP	CC41	Control MCB trip found RL1 control wire loose	Wire tightened then ok	23:20:00	23:35:00	
5	CHP	SCR7 on CC39	LT not working found OT acted	OT limit released then ok	01:25:00	01:35:00	
6	CHP	S3 on CC111	BC not running found Control MCCB trip	Made on	04:40:00	05:00:00	
7	CHP	CC32	Over load acted	Reset done	05:00:00	05:10:00	
8	CHP	R1 on CC31	Boom position signal GVM side not showing checked PLC not communicating	Modem ethernet cable reconnected then ok but position signal not coming further checking in process informed to A shift	05:30:00	05:50:00	