



वी.एस.पी  
VSP

**RASHTRIYA ISPAT NIGAM LIMITED**  
**VISAKHAPATNAM STEEL PLANT**  
**RAW MATERIAL HANDLING PLANT**  
**ELECTRICAL SHIFT REPORT**

Date: 21/10/2025

Shift: C

Incharge(s): Saurabh Kumar Yadav

| Sl No | Area | Equipment    | Problem   | Action  | From     | To       | Remarks                        |
|-------|------|--------------|---|---|----------|----------|--------------------------------|
| 1     | OHP  | TBS on CO 7A | right boom(chp side) luff not taking place,drive trips in OBF fault continuously, drive keypad is not avialable | for reset drive power recycle done,luff up side ok.,control cable checked,drive all outgoing cable checked ,finally given position of boom manually | 00:10:00 | 00:55:00 | to be checked luff drive       |
| 2     | OHP  | CO 29        | OLR acted   | reset   | 01:00:00 | 01:10:00 |                                |
| 3     | OHP  | OC 1A(B)     | OLR acted   | reset   | 02:55:00 | 03:00:00 |                                |
| 4     | CHP  | CC 104 SCR 9 | luffing not working,mpr tripped   | reset   | 01:40:00 | 01:55:00 |                                |
| 5     | CHP  | CC 51        | MPD tripped,stop feeding conveyor   | reset   | 23:00:00 | 05:15:00 | 9 times                        |
| 6     | CHP  | CC 51        | OLR acted   | reset   | 23:05:00 | 23:10:00 |                                |
| 7     | CHP  | CC 52        | OLR acted   | reset   | 00:25:00 | 00:30:00 |                                |
| 8     | WT   | OP 3         | no movement,no power,bottom pad fallen,c clamp bend near col no 72  | power block got @02.10 AM ,c clamp replaced,acb made on   | 01:45:00 | 02:55:00 |                                |
| 9     | WT   | CP 1         | NOT moving,reverse direction,communication problem  | modem power reset   | 23:30:00 | 23:45:00 | no delay,after rake completion |