



वी.एस.पी
VSP

RASHTRIYA ISPAT NIGAM LIMITED
VISAKHAPATNAM STEEL PLANT
RAW MATERIAL HANDLING PLANT
ELECTRICAL SHIFT REPORT

Date: 13/07/2025

Shift: B

Incharge(s): Lal Singh, Arnab Roy

Sl No	Area	Equipment	Problem	Action	From	To	Remarks
1	OHP	CO 27A	BRS bypassed due to RAIN WATER	As per operation request	15:35:00	15:45:00	At module
2	OHP	TBS on CO 7A	LT not working	found in local , kept in remote	16:25:00	16:35:00	
3	OHP	CO 34 BRC	CT not working	Drive tripped in overload , reset done	19:30:00	19:50:00	
4	OHP	CO 22	BRS bypassed on operation request	bcz of belt pieces	21:40:00	21:50:00	
5	OHP	WOBR on CO25	Slew not working	potentiometer at zero and loose . Fixed properly	19:45:00	20:00:00	
6	OHP	CO 29	Belt scale not working	Informed to instrumentation	19:30:00	20:00:00	
7	CHP	CC 112 and CC 111	BRS checked	working well , kept in circuit	14:30:00	15:00:00	
8	CHP	CC 105 , SCR 10	BC not running due to control MCB tripped	MCB reset. Problem repeating , checked found that in pull chord cable earth fault is there. So field wire removed for pull chord and bypassed	15:30:00	17:00:00	
9	CHP	CC 35 , SCR 1	Luff not working	UP limit switch got stucked , made free	19:30:00	19:45:00	
10	CHP	CC 35 , SCR 1	LT pcrd cable in overlapping condition	Checked, guide stucked. Informed to mechanical	19:45:00	20:00:00	
11	CHP	CC 105 , SCR 10	BC not running due to control MCB tripped	LCS cable removed	20:35:00	20:50:00	
12	CHP	CC 54	Tripped on overload (2 times)	reset done	15:20:00 18:15:00	15:35:00 18:20:00	
13	CHP	CC 130	Not healthy due to pull chord acted	reset done	15:45:00	16:00:00	



वी.एस.पी
VSP

RASHTRIYA ISPAT NIGAM LIMITED
VISAKHAPATNAM STEEL PLANT
RAW MATERIAL HANDLING PLANT
ELECTRICAL SHIFT REPORT

Date: 13/07/2025

Shift: B

Incharge(s): Lal Singh, Arnab Roy

Sl No	Area	Equipment	Problem	Action	From	To	Remarks
14	CHP	CC 131	Tripped on overload	reset done	16:20:00 19:06:00	16:25:00 19:10:00	
15	CHP	CC 114	Tripped on overload	reset done	19:40:00	19:55:00	
16	IOSA	TBS	LT end limit acted due to jungle	limit released	17:40:00	18:00:00	
17	IOSA	OC 17A to FLS WOBR	Feedback signal problem due to ZSS acting	ZSS pin broken, adjusted properly	19:20:00	19:35:00	