



वी.एस.पी
VSP

RASTRIYA ISPAT NIGAM LIMITED
VISAKHAPATNAM STEEL PLANT
RAW MATERIAL HANDLING PLANT
ELECTRICAL SHIFT REPORT

Date: 26/06/2025

Shift: A

Incharge(s): Lal Singh, Arnab Roy

| Sl No | Area | Equipment | Problem | Action | From | To | Remarks |
|-------|------|-----------------|---|---|----------|----------|-----------------------|
| 1 | OHP | TBS on CO 22 | LT not working due to pcrd overtension | tension released | 07:35:00 | 07:45:00 | |
| 2 | OHP | CO 37A | BRS in bypass condition | Kept in circuit as per operation request | 08:20:00 | 08:27:00 | |
| 3 | OHP | SB 2A | Bunker level bypass request from operation | bypassed | 08:00:00 | 09:30:00 | again kept in circuit |
| 4 | OHP | CO 34 BRC | BW 1 stopping on ZSS | Probe replaced, still problem . ZSS bypassed and inform to gen shift | 08:45:00 | 09:20:00 | |
| 5 | OHP | VS 1A | OLR acted | reset done | 11:45:00 | 11:50:00 | |
| 6 | OHP | TT 2 | Chute vibrator not working due to bearing damaged | Informed to gen shift | 13:00:00 | 13:10:00 | |
| 7 | OHP | RSCO 1A | Carriage drive tripped on overload | reset done | 07:50:00 | 08:00:00 | |
| 8 | OHP | CO 31 BRC | LT not working | Drive tripping on earth fault. M-5 disconnected and speed reduced . Informed to gen shift | 06:15:00 | 07:00:00 | |
| 9 | CHP | CC 32 | OLR acted | reset done | 07:20:00 | 07:30:00 | |
| 10 | CHP | CC 32 , SCR 5 | BC not running | OLR acted , reset done | 07:25:00 | 07:30:00 | |
| 11 | CHP | CC 32 , SCR 5 | LT not working | M-2 , M-3 tripped . Reset | 11:45:00 | 12:10:00 | |
| 12 | CHP | CC 105 , SCR 10 | BC not running in Rec mode | ZSS interlock checked, but due to coal stucked not working. Then material selection bypassed for CC 105 | 08:00:00 | 09:00:00 | |
| 13 | CHP | CC 112 , SCR 8 | BC not healthy | chute jamming , informed to operation | 08:15:00 | 08:30:00 | |



वी.एस.पी
VSP

RASTRIYA ISPAT NIGAM LIMITED
VISAKHAPATNAM STEEL PLANT
RAW MATERIAL HANDLING PLANT
ELECTRICAL SHIFT REPORT

Date: 26/06/2025

Incharge(s): Lal Singh, Arnab Roy

Shift: A

| Sl No | Area | Equipment | Problem | Action | From | To | Remarks |
|-------|------|------------------|---------------------------------|--|----------|----------|---------|
| 14 | CHP | CC 34 , SCR 2 | Luff not working | Found oil leakage is there, informed to mechanical | 08:30:00 | 09:00:00 | |
| 15 | CHP | CC 31 , R -1 | LT not working | Found that track jamming , informed to operation | 08:30:00 | 08:50:00 | |
| 16 | CHP | CC 54 | OLR acted | reset done | 09:45:00 | 09:50:00 | |
| 17 | CHP | CC 117 | OLR acted | reset done | 10:20:00 | 10:30:00 | |
| 18 | CHP | CC 131 | OLR acted (2 times) | reset done | 12:45:00 | 13:05:00 | |
| 19 | CHP | CC 114 | BRS bypass request by operation | bypassed | 09:25:00 | 09:40:00 | |
| 20 | WT | OC 1A | Pull chord not healthy | Bypassed and informed to gen shift | 09:00:00 | 09:40:00 | |