



वी.एस.पी  
VSP

**RASTRIYA ISPAT NIGAM LIMITED**  
**VISAKHAPATNAM STEEL PLANT**  
**RAW MATERIAL HANDLING PLANT**  
**ELECTRICAL SHIFT REPORT**

Date: 23/06/2025

Shift: A

Incharge(s): Lal Singh, Arnab Roy

Sl No	Area	Equipment	Problem	Action	From	To	Remarks
1	OHP	TBS on CO 22	LT not working	drive tripped in overload , reset done	06:15:00	06:30:00	
2	OHP	CO 68	Tripped in lo fault	reset done	08:55:00	09:10:00	
3	OHP	BRC on CO 34	BW 1 stopping on ZSS	ZSS probe damaged , probe replaced	09:55:00	10:30:00	
4	OHP	CO 8	ZSS problem	kept in bypass on operation request	12:30:00	12:40:00	rectification going on after rake
5	CHP	CC 35 , S-1	TUL chute sensor acting due to rain	Bypassed	10:30:00	10:45:00	kept in circuit at 2 pm
6	CHP	CC 33	Drive end chute sensor acting due to rain	Bypassed	10:35:00	10:55:00	kept in circuit at 2 pm
7	CHP	CC 104 , SCR 9	BC signal missing	Zero speed interlock kept in circuit	11:10:00	11:25:00	
8	CHP	CC 219	Not healthy	Power recycled	10:40:00	10:50:00	
9	CHP	CC 54	Tripped on overload	reset done	06:50:00	06:55:00	
10	CHP	CC 131	Tripped on overload	reset done	12:40:00	12:45:00	
11	CHP	CC 56	Pull chord not healthy	Pull chord reset done, still not healthy. Checked in panel, RL-5 and RL-6 wire loose, so loop given . Also bypassed in IO rack	10:40:00	11:42:00	
12	WT	OP 5	Not moving	R phase problem, jumper provided	10:10:00	10:40:00	