



वी.एस.पी
VSP

RASHTRIYA ISPAT NIGAM LIMITED
VISAKHAPATNAM STEEL PLANT
RAW MATERIAL HANDLING PLANT
ELECTRICAL SHIFT REPORT

Date: 21/12/2025

Shift: B

Incharge(s): Saurabh Kumar Yadav

| Sl No | Area | Equipment | Problem | Action | From | To | Remarks |
|-------|------|---------------|--|--|----------|----------|---|
| 1 | OHP | CO 11(B) | olr acted | RESET | 20:30:00 | 20:40:00 | |
| 2 | OHP | CO111(B) | MPCB TRIPPED(MPCB DAMAGED) | RESET and MPCB REPLACED | 19:00:00 | 19:15:00 | 2 TIMES |
| 3 | OHP | BRC on CO 33m | LT not taking place,pcrd OT acted ,guide problem | informed mechanical | 14:15:00 | 14:35:00 | |
| 4 | OHP | BRC on Co 28 | yard zss cage stucked | cage made free | 16:45:00 | 16:55:00 | |
| 5 | OHP | CO 26 | olr acted | reset | 20:00:00 | 20:05:00 | |
| 6 | OHP | CO 20 | BRS malfunctioning complaint, | both BRS checked and found ok, conveyor run cmd given ,conveyor stops in ZSS fault | 21:35:00 | 22:00:00 | pending complaint,mot or is running gear box side problem |
| 7 | CHP | CC 115 | brs not healthy,terminal loose connection | tightened | 15:50:00 | 16:05:00 | |
| 8 | CHP | CC 51 | mpd tripped | reset | 14:50:00 | 21:00:00 | 20 times |
| 9 | CHP | cc 104 scr9 | slew not working,start PB in operator cabin loose connection | tightened | 16:00:00 | 16:15:00 | |
| 10 | CHP | CC 125 | OLr acted | reset | 17:25:00 | 17:35:00 | |
| 11 | CHP | CC 34 SCR1 | luffing not working,up limit switch stucked | release limit switch | 19:30:00 | 19:45:00 | |
| 12 | CHP | CC 35 SCR3 | slew not working,slew limit acted, coal jamming | informed operation | 21:10:00 | 21:30:00 | |



वी.एस.पी
VSP

RASHTRIYA ISPAT NIGAM LIMITED

VISAKHAPATNAM STEEL PLANT

RAW MATERIAL HANDLING PLANT

ELECTRICAL SHIFT REPORT

Date: 21/12/2025

Incharge(s): Saurabh Kumar Yadav

Shift: B

| Sl No | Area | Equipment | Problem | Action | From | To | Remarks |
|-------|------|---------------|--|---|----------|----------|--|
| 13 | WT | OT1,2,3 and 4 | all red,PLC have not supply,I/C (ACB)tripped of OM4,ACB tripped of WT4 MCC,after made on ACB of WT4 ,I/C(ACB) of OM4 tripped | ACB made on of OM4 and given clearance for OT1,2 and 3 and for OT4 MCC ,ACB made on and all feeder made off,and one by one ,made on ,not used and spare feeder made off | 14:30:00 | 14:55:00 | OT 4 tippler trial run taken and given clearance @4 PM, no rack was there no delay |
| 14 | WT | OT 5 | tippler not healthy,D2 tripped in SPF fault | drive not getting reset,checked and found encoder cable damaged,and encoder bearing jammed,new encoder replaced | 16:30:00 | 17:50:00 | |
| 15 | WT | OT 2 | D2 tripped in pgf1 fault | reset | 19:20:00 | 19:25:00 | |
| 16 | WT | OP7 | no movement,RLS acted | LS released | 17:45:00 | 17:55:00 | |