



वी.एस.पी  
VSP

**RASHTRIYA ISPAT NIGAM LIMITED**  
**VISAKHAPATNAM STEEL PLANT**  
**RAW MATERIAL HANDLING PLANT**  
**ELECTRICAL SHIFT REPORT**

Date: 12/07/2025

Shift: A

Incharge(s): Saurabh Kumar Yadav

Sl No	Area	Equipment	Problem	Action	From	To	Remarks
1	OHP	TBS on co 21	LT not taking place,R/BC up not done by operator	operator fault	06:25:00	06:40:00	
2	OHP	CO 87	olr acted	reset	07:15:00	07:20:00	
3	OHP	BRC 34	LT not working,OT acted PCRD cable overlapping	OT released,cable winded properly	08:30:00	08:45:00	
4	OHP	CO 9	olr acted	reset	13:30:00	13:35:00	
5	OHP	CO 65	CJD acted,module ok,return from module to plc mising,cable problem	cjd bypass in I/O rack and checking going on	13:40:00	14:00:00	cable to be checked in B shift
6	CHP	CC 47	brs acted	sensor cleaned and control cable tightened in TB	07:50:00	08:00:00	
7	CHP	CC 51	olr acted	reset	08:30:00	08:35:00	
8	CHP	CC 131	olr acted	reset	08:50:00	09:00:00	
9	CHP	CC 54	olr acted	reset	09:15:00	09:20:00	
10	CHP	CC 38 scr 3	slew not working ,wrong complaint	slew luffing all ok	09:00:00	09:10:00	
11	CHP	CC 201	ZSS acted,sensor wrong positioned,module malfunctioning	sensor adjusted,module replaced	09:10:00	09:30:00	
12	CHP	C 105 SCR 10	reclaiming mode signal missing	fuse connected in CM 18 fro reclaiming mode	10:30:00	10:35:00	



वी.एस.पी  
VSP

**RASHTRIYA ISPAT NIGAM LIMITED**  
**VISAKHAPATNAM STEEL PLANT**  
**RAW MATERIAL HANDLING PLANT**  
**ELECTRICAL SHIFT REPORT**

Date: 12/07/2025

Incharge(s): Saurabh Kumar Yadav

Shift: A

Sl No	Area	Equipment	Problem	Action	From	To	Remarks
13	WT	OP7	no power in pusher,ACB tripped when pusher sent to parking zone,MCCB tripped near col no 53	ACB made on, checked trolley line and MCCB from pusher location col no.30 to col no 53,MCCB made on near col no 53	06:30:00	07:38:00	No information given by Shift Incharges even though i asked Eswar Rao any pending complaint , he replied no....., tippler non executive and night shift contract worker on site only near OP7