



वी.एस.पी  
VSP

**RASHTRIYA ISPAT NIGAM LIMITED**  
**VISAKHAPATNAM STEEL PLANT**  
**RAW MATERIAL HANDLING PLANT**  
**ELECTRICAL SHIFT REPORT**

Date: 11/10/2025

Shift: A

Incharge(s): Amit Roy

Sl No	Area	Equipment	Problem	Action	From	To	Remarks
1	OHP	BRC on CO-28	PCRD cable problem	Cable fell down due to chain problem.	07:35:00	08:00:00	Informed to mechanical and rectified
2	OHP	WOBR on CO-26	LT not taking place	Guide problem.	08:00:00	08:25:00	Informed to mechanical
3	OHP	CO-29	Reported tripped	OLR acted(3times).Reset done	08:10:00 09:26:00 10:00:00	08:30:00 09:35:00 10:08:00	
4	OHP	CO-10A	Reported tripped	OLR acted.Reset done	12:30:00	12:40:00	
5	OHP	CO-26	Reported tripped	OLR acted.Reset done	12:50:00	13:00:00	
6	OHP	CO-67	Reported Tripped	OLR acted.Reset done	13:45:00	13:55:00	
7	OHP	WOBR on CO-26	B/C not running	OLR acted.Reset done	13:45:00	13:55:00	
8	CHP	Cc-34 SCR-2	LT not taking place	Tension acted.Released and tested okay	07:40:00	07:50:00	
9	CHP	Cc-36 SCR-1	LT not taking place	PCRD gearbox problem.Mechanical attended and rectified	07:23:00	07:35:00	
10	CHP	CC-112 SCR-8	Luff not working	Oil level low.Informed to mechanical	12:04:00	12:25:00	
11	CHP	CC-112 SCR-8	B/C not running	MPD tripped.Reset done and tested okay	13:25:00	13:34:00	
12	CHP	VS-3	Reported tripped	OLR acted(3times) due to jamming.Reset done	09:00:00	10:30:00	
13	CHP	CC-51	Reported Tripped	OLR acted.Reset done	10:00:00	10:05:00	



वी.एस.पी  
VSP

**RASHTRIYA ISPAT NIGAM LIMITED**  
**VISAKHAPATNAM STEEL PLANT**  
**RAW MATERIAL HANDLING PLANT**  
**ELECTRICAL SHIFT REPORT**

Date: 11/10/2025

Incharge(s): Amit Roy

Shift: A

Sl No	Area	Equipment	Problem	Action	From	To	Remarks
14	WT	OP-3	Reported not moving	Emergency stop acted by mechanical	08:20:00	08:30:00	informed to operation
15	WT	OT-3	Reported tripped	Drive tripped on encoder fault.rollers in jamming condition	08:55:00	09:00:00	Informed to operation
16	WT	OP-2	Initial to be bypassed	Bypassed and again kept in line	12:00:00	12:25:00	
17	WT	EOT in CT	Reported hoist not taking place	Contactor R-ph lug got cut.Relugging done	08:45:00	09:00:00	
18	WT	EOT in CT	Reported Hoist not taking place	FWD and REV contactor tips damaged.Tips replaced and tested okay	10:30:00	11:30:00	