



वी.एस.पी
VSP

RASHTRIYA ISPAT NIGAM LIMITED

VISAKHAPATNAM STEEL PLANT

RAW MATERIAL HANDLING PLANT

ELECTRICAL SHIFT REPORT

Date: 29/08/2025

Incharge(s): Amit Roy, K SANKARA RAO

Shift: C

| Sl No | Area | Equipment | Problem | Action | From | To | Remarks |
|-------|------|----------------------|---------------------------------------|---|----------|----------|---|
| 1 | OHP | BRC ON CO -32 | LT NOT TAKING PLACE CHECKED AND FOUND | M-1 OLR ACTED RESET DONE | 22:30:00 | 22:50:00 | |
| 2 | OHP | TBS ON CO-23 | LT NOT TAKING PLACE | CHECKED AND FOUND BRAKES NOT RELEASING EVEN THOUGH MAGNETIZING. | 22:50:00 | 23:10:00 | INFORMED TO MECHANICAL. ADJUSTMENT DONE AND TESTED OKAY |
| 3 | OHP | TBS ON CO-20 | REPORTED LT NOT TAKING PLACE | CHECKED AND FOUND MAIN CONTROL IN OFF CONDITION. MAIN CONTROL MADE ON AND TESTED OKAY | 00:10:00 | 00:30:00 | NO ELECTRICAL DELAY. OPERATOR DIDNT MAKE ON CONTROL. |
| 4 | OHP | CO-29 | REPORTED TRIPPED | OLR ACTED. RESET DONE | 02:30:00 | 02:40:00 | |
| 5 | OHP | CO-26 | REPORTED TRIPPED | OLR ACTED. RESET DONE | 05:20:00 | 05:30:00 | |
| 6 | OHP | TW-6(CO-18 TO CO-23) | REPORTED NOT MOVING | OLR ACTED. RESET DONE | 02:00:00 | 02:10:00 | |
| 7 | OHP | BRC ON CO-31 | REPORTED INTERLOCK PROBLEM | PROBE REPLACED AND ZSS INTERLOCK PROBE NOT CONNECTED AT CJB FOR THE CORRESPONDING FEEDING CONVEYOR. CONNECTED AND TESTED OKAY | 01:15:00 | 02:00:00 | |



वी.एस.पी
VSP

RASHTRIYA ISPAT NIGAM LIMITED
VISAKHAPATNAM STEEL PLANT
RAW MATERIAL HANDLING PLANT
ELECTRICAL SHIFT REPORT

Date: 29/08/2025

Shift: C

Incharge(s): Amit Roy,K SANKARA RAO

| Sl No | Area | Equipment | Problem | Action | From | To | Remarks |
|-------|------|-----------------|---------------------------------|---|----------------------|----------------------|--|
| 8 | CHP | CC-51 | REPORTED TRIPPED. | OLR ACTED.RESET DONE(2TIMES) | 01:10:00 05:30:00 | 01:15:00 05:35:00 | |
| 9 | CHP | CC-114 | REPORTED TRIPPED | OLR ACTED.RESET DONE(2TIMES) | 01:15:00 03:54:00 | 01:25:00 04:00:00 | |
| 10 | CHP | CC-51A | REPORTED TRIPPED | OLR ACTED.RESET DONE | 01:40:00 | 01:45:00 | |
| 11 | CHP | CC-31 SCR-4 | REPORTED ALL DRIVES NOT WORKING | CHECKED AND FOUND CONTROL IN OFF CONDITION.CONTROL MADE ON AND TESTED OKAY.LT ALSO NOT TAKING PLACE.FOUND TRACK JAMMING | 22:40:00 | 23:00:00 | INFORMED TO OPERATION TO CLEAR JAMMING |
| 12 | CHP | CC-40 SCR-3 | REPORTED SLEW NOT TAKING PLACE | SLEW LIMIT ACTED AND JAMMING FOUND.LIMIT RELEASED AND INFORMED TO OPERATION TO CLEAR JAMMING | 00:10:00 | 00:20:00 | |
| 13 | CHP | CC-114 SCR-9 | REPORTED B/C NOT RUNNING | MOTOR OLR ACTED.RESET DONE AND TESTED OKAY | 02:50:00 | 03:00:00 | |
| 14 | CHP | CC-41 | CJD NOT WORKING | CHECKED AND FOUND CJD MODULE PROBLEM.MODULE REPLACED AND TESTED OKAY | 03:10:00 | 03:30:00 | |
| 15 | CHP | CC-108 | REPORTED TRIPPED | OLR ACTED.RESET DONE | 04:25:00 | 04:30:00 | |
| 16 | WT | OP-1 | REPORTED NOT MOVING | DRIVE-6 OLR ACTED.RESET DONE | 03:00:00 | 03:20:00 | |