



वी.एस.पी  
VSP

**RASHTRIYA ISPAT NIGAM LIMITED**  
**VISAKHAPATNAM STEEL PLANT**  
**RAW MATERIAL HANDLING PLANT**  
**ELECTRICAL SHIFT REPORT**

Date: 05/07/2025

Shift: C

Incharge(s): Lal Singh, Arnab Roy

Sl No	Area	Equipment	Problem	Action	From	To	Remarks
1	OHP	RSCO 9A	Tripped on overload	reset done	04:50:00 22:30:00	05:00:00 22:40:00	
2	OHP	VS 2	Tripped on overload	reset done	23:45:00	23:55:00	
3	OHP	CO 50	Tripped on overload	reset done	01:40:00	01:50:00	
4	OHP	BRC on CO 34	CT not moving DUE TO SPEED reference zero in drive	HMI speed selection changed	23:50:00	00:20:00	Lower band frequency set to 9.5 Hz
5	OHP	CO 25 WOBR	LT not moving	M-3 disconnected and MCCB made on	02:00:00	02:45:00	
6	OHP	CO 68 , CO 69	Not healthy	PLC 110V control supply not coming bcz Of no power in OM 25	05:45:00	06:00:00	Checking going on
7	CHP	CC 47	Stopping frequently	Drive power recycled and KA1 relay contact tightened	01:20:00	02:00:00	
8	CHP	CC 36	Reported no power	Control 110 V missing , taken from outside (CC 35 panel)	02:30:00	03:15:00	
9	CHP	CC 33	Stopped bcz of CC 51 overload interlock	CC 51 Overload reset	00:30:00	00:40:00	
10	CHP	CC 131	Tripped on overload	reset done	04:10:00	04:15:00	
11	CHP	CC 31	Flap gate motor tripped	made on	22:50:00	23:00:00	
12	CHP	CC 26	Flap gate MPCB tripped	reset done	22:20:00	22:30:00	
13	CHP	VF 2	not healthy	power recycled	04:30:00	04:35:00	
14	WT	OC 1A	Failed to start	hardware contact of pull chord and emergency bypassed	02:00:00	02:25:00	Kept in circuit