



वी.एस.पी
VSP

RASHTRIYA ISPAT NIGAM LIMITED
VISAKHAPATNAM STEEL PLANT
RAW MATERIAL HANDLING PLANT
ELECTRICAL SHIFT REPORT

Date: 24/07/2025

Shift: B

Incharge(s): Amit Roy,K SANKARA RAO

| Sl No | Area | Equipment | Problem | Action | From | To | Remarks |
|-------|------|----------------|--|--|----------|----------|---|
| 1 | OHP | WOBR ON CO 25 | SLEW NOT TAKING PLACE DRIVE TRIP | RESET THAN OK | 18:45:00 | 19:00:00 | |
| 2 | OHP | CO-43A | ZS NOT WORKING CHECKED GLASS FUSE BLOWN IN CJB | GLASS FUSE REPLACED THAN OK | 17:45:00 | 18:00:00 | |
| 3 | OHP | CO 48 | OLR ACTED | RESET | 16:45:00 | 16:55:00 | |
| 4 | OHP | WOBR- ON CO 6A | LT NOT TAKING PLACE DRIVE HEALTHY NC CONTACT PROBLEM | DRIVE HEALTHY CONTACT BYPASS | 21:00:00 | 21:15:00 | |
| 5 | OHP | WOBR ON CO 29 | LT M4 OLR ACTED | OLR RESET | 20:45:00 | 21:00:00 | |
| 6 | OHP | BRC ON CO 33M | YARD INTERLOCK SPURIOUSLY ACTING | ZS SPEED SETTING CHANGE FROM 7 TO 3 | 18:00:00 | 18:15:00 | |
| 7 | CHP | CC-40 S-1 | Reported Stacking and LT not taking place | TUL CS malfunctioning.Bypassed and LT drive reset done | 14:30:00 | 14:50:00 | TUL CS to be checked and to be kept in line |
| 8 | CHP | CC-32 SCR-5 | LT not taking place | Checked and found M-3 power cable R-ph damaged. cable tapped and tested okay | 15:25:00 | 17:30:00 | |
| 9 | CHP | CC-105 SCR-7 | LT not taking place | OT limit acted | 17:15:00 | 17:30:00 | |
| 10 | CHP | CC-44,107 | Reported not healthy | OLR acted.Reset done | 17:30:00 | 17:45:00 | |
| 11 | CHP | CC-33 SCR-4 | LT not taking place | OT acted.released and tested okay | 16:00:00 | 16:10:00 | |



वी.एस.पी
VSP

RASHTRIYA ISPAT NIGAM LIMITED
VISAKHAPATNAM STEEL PLANT
RAW MATERIAL HANDLING PLANT
ELECTRICAL SHIFT REPORT

Date: 24/07/2025

Incharge(s): Amit Roy,K SANKARA RAO

Shift: B

| Sl No | Area | Equipment | Problem | Action | From | To | Remarks |
|-------|------|-----------------|-------------------------|---|----------|----------|------------------------|
| 12 | CHP | CC-104 SCR 9 | Reported signal missing | LT done and checked and found okay | 17:40:00 | 18:09:00 | |
| 13 | CHP | CC-40 S-1 | LT not working | PCRD cable stuck in guide. released and tested okay | 16:30:00 | 16:45:00 | |
| 14 | CHP | CC-105 SCR-7 | LT not working | PCRD chain damaged | 20:45:00 | 20:55:00 | informed to mechanical |
| 15 | CHP | CC_44 | Reported not healthy | OLR acted.reset done | 20:40:00 | 20:45:00 | |
| 16 | CHP | CC_54 | Reported not healthy | OLR acted.reset done(2times) | 17:50:00 | 18:05:00 | |
| 17 | WT | CC-2(C) | Reported not healthy | OLR acted.reset done | 16:00:00 | 16:15:00 | |
| 18 | WT | SCO-1A(C) | Reported not healthy | OLR acted.reset done | 18:50:00 | 19:00:00 | Track jamming |
| 19 | WT | CO-3 | Reported not healthy | OLR acted.reset done | 16:15:00 | 16:20:00 | |
| 20 | WT | OT-3 | Overpushing | Sensor temporary bypassed and after tripping kept back in line | 20:20:00 | 20:40:00 | |
| 21 | WT | OP-6 | Crossed cut off section | Busbar shorted by jumpers.After pusher movement jumpers removed | 20:40:00 | 21:10:00 | |