



वी.एस.पी
VSP

RASTRIYA ISPAT NIGAM LIMITED
VISAKHAPATNAM STEEL PLANT
RAW MATERIAL HANDLING PLANT
ELECTRICAL SHIFT REPORT

Date: 19/05/2025

Shift: C

Incharge(s): Lal Singh, Arnab Roy

| Sl No | Area | Equipment | Problem | Action | From | To | Remarks |
|-------|------|------------------|---|---|--|--|------------|
| 1 | OHP | WOBR on CO 26 | Slew not working due to drive OLR acted | OLR reset done | 03:20:00 23:50:00 | 03:40:00 00:10:00 | |
| 2 | OHP | CO 35 | OLR acted | reset done | 23:35:00 | 23:45:00 | |
| 3 | OHP | CO 28 | BRS to be bypassed as per operation request | Bypassed in CJB | 03:10:00 | 03:20:00 | |
| 4 | OHP | CO 29 TIS | ZSS acted in running condition | Stone stuck up in pulley . cleaned , then ok | 04:10:00 | 04:20:00 | |
| 5 | OHP | CO 33M | OLR acted | reset done | 05:00:00 | 05:10:00 | |
| 6 | CHP | CC 54 | Tripped in overload | reset done | 00:15:00 02:50:00 03:00:00 04:55:00 05:05:00 | 00:20:00 02:55:00 03:05:00 05:00:00 05:10:00 | |
| 7 | CHP | CC 131 | Tripped in overload | reset done | 01:45:00 02:50:00 04:20:00 | 01:50:00 02:55:00 04:25:00 | |
| 8 | CHP | CC 117 | Tripped in overload | reset done | 02:20:00 03:25:00 | 02:35:00 03:40:00 | |
| 9 | CHP | CC 48 | Belt sway to be bypassed | Bypassed as per operation request | 03:52:00 | 03:58:00 | In IO rack |
| 10 | CHP | CC 34 , S-1 | LT not working , drive tripped | Drive reset | 23:15:00 | 23:30:00 | |
| 11 | CHP | CC 36 , SCR 1 | BC not running due to BSS acted | BSS released , informed to mechanical | 00:15:00 | 00:30:00 | |
| 12 | CHP | CC 39 , SCR 7 | Slew not working | Found material jamming is there , informed operation for cleaning. After cleaning , slewing ok. | 01:20:00 | 01:40:00 | |



वी.एस.पी
VSP

RASTRIYA ISPAT NIGAM LIMITED
VISAKHAPATNAM STEEL PLANT
RAW MATERIAL HANDLING PLANT
ELECTRICAL SHIFT REPORT

Date: 19/05/2025

Incharge(s): Lal Singh, Arnab Roy

Shift: C

| Sl No | Area | Equipment | Problem | Action | From | To | Remarks |
|-------|------|---------------|---|--|----------|----------|----------------------------------|
| 13 | CHP | CC 126 | BSS acted | Bypassed | 02:30:00 | 02:40:00 | again kept in circuit at 6.10 am |
| 14 | CHP | CC 112, SCR 8 | BC selection not showing in Reclaiming mode | PLC recycled, still problem. Reclaiming mode bypassed in programming | 03:50:00 | 04:30:00 | |
| 15 | CHP | CC 112, SCR 8 | LT not working in remote mode | Checking going on. Kept in local and LT done | 05:20:00 | 06:00:00 | Informed to A shift |
| 16 | WT | OT 4 | Drive 2 tripped on pgf 4 fault | reset done | 22:55:00 | 23:00:00 | |
| 17 | WT | OT 5 | Drive not healthy due to OLF fault | Checked, material jamming on rollers. Informed to mechanical. After cleaning, ok | 05:00:00 | 05:30:00 | |