



वी.एस.पी  
VSP

**RASHTRIYA ISPAT NIGAM LIMITED**  
**VISAKHAPATNAM STEEL PLANT**  
**RAW MATERIAL HANDLING PLANT**  
**ELECTRICAL SHIFT REPORT**

Date: 04/12/2025

Incharge(s): Amit Roy

Shift: B

| Sl No | Area | Equipment     | Problem   | Action   | From                             | To                               | Remarks                   |
|-------|------|---------------|---|--|----------------------------------|----------------------------------|---------------------------|
| 1     | OHP  | CO-68         | Reported ZSS acted                                | Checked and found okay   | 15:30:00                         | 16:05:00                         | No problem found          |
| 2     | OHP  | CO-11A        | Reported ZSS acting                               | ZSS cable cut.Rejointed and tested okay  | 15:30:00                         | 15:45:00                         |                           |
| 3     | OHP  | CR-2A         | Reported ZSS acted                                | Probe gap adjusted and tested okay   | 17:35:00                         | 17:55:00                         |                           |
| 4     | OHP  | CO-25         | Reported tripped                                  | OLR acted.Reset done(2 times)  | 19:25:00<br>21:45:00             | 19:35:00<br>21:55:00             |                           |
| 5     | OHP  | BF-3A         | ZSS acting  | Checked and found ZSS targets damaged.Bypassed and target welding done and bypass removed and tested okay              | 20:23:00                         | 21:50:00                         |                           |
| 6     | OHP  | WOBR on CO-6A | Reported slewing not taking place                 | B/C full jamming.Asked to clear material   | 21:50:00                         | 22:00:00                         |                           |
| 7     | CHP  | CC109         | Reported BRS acting                               | Sensors adjusted and tested okay   | 18:50:00                         | 19:10:00                         |                           |
| 8     | CHP  | CC 29         | Reported tripped                                  | OLR acted.Reset done(3 times)  | 15:00:00<br>15:15:00<br>16:10:00 | 15:10:00<br>15:25:00<br>16:15:00 |                           |
| 9     | CHP  | CC 28         | Reported tripped                                  | OLR acted.Reset done   | 20:05:00                         | 20:10:00                         |                           |
| 10    | CHP  | CC-35 SCR-3   | Reported LT not working.                          | Drive tripped.Reset done   | 20:55:00                         | 21:10:00                         |                           |
| 11    | CHP  | Cc 35 SCR-5   | Reported LT not working                           | Wrong complaint  | 21:55:00                         | 22:05:00                         |                           |
| 12    | WT   | OT-5          | Reported side clamping and declamping not working | Checked and found vertical clamp pressure not reaching set point.Set point adjusted and tested okay.Mechanical problem | 20:00:00                         | 21:00:00                         | Not an electrical problem |



वी.एस.पी  
VSP

**RASHTRIYA ISPAT NIGAM LIMITED**  
**VISAKHAPATNAM STEEL PLANT**  
**RAW MATERIAL HANDLING PLANT**  
**ELECTRICAL SHIFT REPORT**

Date: 04/12/2025

Incharge(s): Amit Roy

Shift: B

| Sl No | Area | Equipment | Problem                               | Action                               | From                 | To                   | Remarks |
|-------|------|-----------|---------------------------------------|--------------------------------------|----------------------|----------------------|---------|
| 13    | WT   | Pusher-9  | Reported FWD and Rev not taking place | Reset done in system and tested okay | 17:30:00<br>20:30:00 | 17:40:00<br>20:40:00 |         |