



वी.एस.पी
VSP

RASTRIYA ISPAT NIGAM LIMITED
VISAKHAPATNAM STEEL PLANT
RAW MATERIAL HANDLING PLANT
ELECTRICAL SHIFT REPORT

Date: 26/05/2025

Shift: B

Incharge(s): V Balaji Naik

Sl No	Area	Equipment	Problem	Action	From	To	Remarks
1	OHP	CO76R	OLT acted	Reset done	14:00:00	14:00:00	07.45am to 08.00am
2	OHP	BRC on CO30	Bridge conveyor OLR acted	Reset done	14:00:00	14:00:00	07.30am to 7.45am
3	OHP	WOBR on CO6a	Boom conveyor not working found stone struck in ZSS cage and ZSS acting	Stone removed and given clearance	14:00:00	14:00:00	08.15am to 08.30am
4	OHP	CO35	Stopping and starting found ZSS acting due to slippage of tail end drum	Informed to mechanical and operation	14:00:00	14:00:00	08.30am to 08.45am
5	OHP	CO87	OLR acted	Reset done	14:00:00	14:00:00	01.30pm to 01.45pm
6	OHP	SCR5 on CC32	*LT not working found PCRD over tension acted *Slew not working found Slew out put relay glass fuse blown. *TUL CJS not healthy found CJS module problem	* PCRD over tension limit released then ok *Slew out put relay glass fuse replaced. *TUL , CJS module replaced then ok	14:00:00	14:00:00	09.50am to 10.10am
7	CHP	S1 onCC34	Luffing not working found air lock in system	Informed to mechanical after air lock it is ok	14:00:00	14:00:00	07.00am to 07.05am not an electrical delay
8	CHP	CC223	Motor not running found C1 contactor A1 and A2 coil supply loose	Tightened then ok	14:00:00	14:00:00	08.50am to 09.00am
9	CHP	SCR2 on CC35	LT not working found PCRD over tension limit acted	Tension limit released then ok	14:00:00	14:00:00	10.20am to 10.30am



वी.एस.पी
VSP

RASTRIYA ISPAT NIGAM LIMITED
VISAKHAPATNAM STEEL PLANT
RAW MATERIAL HANDLING PLANT
ELECTRICAL SHIFT REPORT

Date: 26/05/2025

Incharge(s): V Balaji Naik

Shift: B

Sl No	Area	Equipment	Problem	Action	From	To	Remarks
10	CHP	S1 on CC34	LT not working found drive over load fault trip(Mechanical gear box fixing work informed to electrical cable winding done found ok)	Reset done	14:00:00	14:00:00	10.10am to 10.20am
11	CHP	CC131	Over load trip	Reset done	14:00:00	14:00:00	04.00pm to 4.40pm
12	WT	CP4	Pusher not moving found communication bit red	In LC10a ether net cable connections re connected then ok	14:00:00	14:00:00	10.45am to 11.am
13	WT	OP9	Reached to no power zone at parking area after rake completion no delay while reaching to parking zone	Bring back to power zone by arranging jumpers	14:00:00	14:00:00	10.30am to 10.40am