



वी.एस.पी
VSP

RASHTRIYA ISPAT NIGAM LIMITED

VISAKHAPATNAM STEEL PLANT

RAW MATERIAL HANDLING PLANT

ELECTRICAL SHIFT REPORT

Date: 04/10/2025

Shift: A

Incharge(s): Amit Roy

| Sl No | Area | Equipment | Problem | Action | From | To | Remarks |
|-------|------|---------------|-----------------------------------|--|----------------------|----------------------|--------------------------------|
| 1 | OHP | WOBR on CO-29 | Reported Luffing not taking place | Down limit acted.Released and tested okay | 07:00:00 | 07:20:00 | |
| 2 | OHP | BRC on CO-30 | LT not taking place | Skew limit acted. | 08:20:00 | 09:20:00 | Adjusted along with mechanical |
| 3 | OHP | BRC on CO-32 | B/C tripped | OLR acted.Reset done | 08:30:00 10:00:00 | 08:40:00 10:30:00 | |
| 4 | OHP | WOBR on CO-26 | Reported Slewing not taking place | Drive tripped.Reset done | 10:00:00 | 10:20:00 | |
| 5 | OHP | BRC on CO-30 | Reported CT not taking place | CT chain fallen. | 13:30:00 | 13:45:00 | Informed to mechanical |
| 6 | OHP | BRC on CO-30 | B/C tripped | OLR acted.Reset done | 10:10:00 | 10:20:00 | |
| 7 | OHP | TT-1A | CJD not getting reset | Material jamming found | 10:30:00 | 10:40:00 | Informed to operation |
| 8 | CHP | CC-117 | Reported tripped | OLR acted.Reset done | 11:50:00 12:55:00 | 11:55:00 13:00:00 | |
| 9 | CHP | CC-23 | Reported ZSS acting | Checked and found module settings not proper.Settings adjusted and tested okay | 10:20:00 | 10:35:00 | |
| 10 | CHP | CC-39 S-1 | LT not taking place | PCRD overtension.Released and tested okay | 06:48:00 | 07:00:00 | |
| 11 | CHP | CC-32 R-1 | B/C not running. | ZSS interlock cage stuck.Made free and tested okay | 07:50:00 | 08:00:00 | |
| 12 | CHP | CC-39 | Reported tripped | OLR acted.Reset done | 06:55:00 | 06:58:00 | |



वी.एस.पी
VSP

RASHTRIYA ISPAT NIGAM LIMITED
VISAKHAPATNAM STEEL PLANT
RAW MATERIAL HANDLING PLANT
ELECTRICAL SHIFT REPORT

Date: 04/10/2025

Incharge(s): Amit Roy

Shift: A

| Sl No | Area | Equipment | Problem | Action | From | To | Remarks |
|-------|------|-----------------|-----------------------------------|--|----------------------|----------------------|------------------------|
| 13 | CHP | CC-104 SCR-9 | Reported no drives working | Breaker tripped.Made on | 08:43:00 | 08:50:00 | |
| 14 | CHP | CC-41 | ZSS cable cut | ZSS cable joint done | 09:10:00 | 09:20:00 | |
| 15 | CHP | CC-38 SCR-6 | LT not taking place | Drive Tripped.Reset done | 09:35:00 | 09:45:00 | |
| 16 | CHP | CC-36 SCR-1 | Slew and luff not working | oil leakage from tank. | 11:20:00 | 11:30:00 | Informed to mechanical |
| 17 | CHP | CC-34 SCR-2 | LT not working | Overtension acted.Released and tested okay | 13:20:00 | 13:30:00 | |
| 18 | CHP | CC-112 SCR-8 | Reported slewing not taking place | Checked and found no oil in tank | 08:00:00 | 08:20:00 | Informed to mechanical |
| 19 | WT | OP-5 | Reported not moving | Checked and found pusher in decoupled condition. | 07:20:00 | 07:30:00 | Informed to operation |
| 20 | WT | CO-3 | Reported tripped | OLR acted.Reset done | 11:00:00 12:35:00 | 11:10:00 12:45:00 | |