



वी.एस.पी
VSP

RASHTRIYA ISPAT NIGAM LIMITED
VISAKHAPATNAM STEEL PLANT
RAW MATERIAL HANDLING PLANT
ELECTRICAL SHIFT REPORT

Date: 13/07/2025

Shift: C

Incharge(s): V Balaji Naik, G Eswara Rao

Sl No	Area	Equipment	Problem	Action	From	To	Remarks
1	OHP	Stacker on CO22	LT not moving found M2 olr acted	Reset done	23:30:00	23:45:00	
2	OHP	CO67	Not running found ZSS probe damaged	New ZSS probe replaced then ok	03:05:00	03:25:00	
3	OHP	TBS on CO22	Chute vibrator not working found in operator cabin 3 phase supply ok but motor TB B phase not coming	Further needs checking	03:55:00	04:05:00	Starter to be checked further
4	OHP	OM10	All conveyors red found control MCB tripped	Main control MCB made on then ok	01:30:00	01:45:00	
5	OHP	CO50	Reported CJD acted	Chute jam acted due to chute jamming informed to operation then ok	01:50:00	02:00:00	
6	OHP	CO29 belt scale	Reported belt scale not working found belt scale mal functioning	Informed to instrumentation	01:30:00	01:40:00	Needs attention from concern section
7	CHP	SCR10 on CC105	BCnot running found MCB1 tripped	Reset done	23:08:00	23:20:00	02.10am to 02.20am: 03.55am to 04.05am
8	CHP	SCR5 on CC32	LT not working found found OT limit acted	Released then ok	02:25:00	02:35:00	
9	CHP	SCR4 on CC33	LT not working found drive fault SC- F3 fault	Reset done	03:35:00	03:45:00	04.26am to 04.36am
10	CHP	CC45 and CC46	Healthy stop 2 times found noting	No problem found	01:40:00	02:10:00	May check if any further



वी.एस.पी
VSP

RASHTRIYA ISPAT NIGAM LIMITED
VISAKHAPATNAM STEEL PLANT
RAW MATERIAL HANDLING PLANT
ELECTRICAL SHIFT REPORT

Date: 13/07/2025

Incharge(s): V Balaji Naik, G Eswara Rao

Shift: C

Sl No	Area	Equipment	Problem	Action	From	To	Remarks
11	CHP	CC125	OLR acted	Reset done	04:40:00	04:46:00	
12	CHP	SCR5 on CC32	BC not running found over load	Reset done	05:27:00	05:37:00	
13	CHP	CC38	BRS bypassed as per operational requirement	By passed electrical BRS	00:34:00	00:35:00	
14	CHP	CC131	Over load trip 4 times	Reset done	02:00:00	02:05:00	03.30am to 03.35:04.10 am to 04.15am :04.50am to 04.55am
15	CHP	CC54	Over load trip	reset done	06:05:00	06:10:00	
16	WT	OT5	Clamping problem found in cabin after pressing PB for clamping and un clamping then ok , Tippler not rotating found LS1 and LS2 got struck	LS1 and LS3 released then ok (15 boxes over shooted and stream is not ready for tippler rotation	00:00:00	00:30:00	Limit switches may check for struck
17	WT	SCO1A carriage	Over load acted	Reset done	23:00:00	23:05:00	
18	IOSA	TBS	RBC not working found ZSS probe problem	Replaced then ok	01:45:00	02:20:00	