



वी.एस.पी  
VSP

**RASTRIYA ISPAT NIGAM LIMITED**  
**VISAKHAPATNAM STEEL PLANT**  
**RAW MATERIAL HANDLING PLANT**  
**ELECTRICAL SHIFT REPORT**

Date: 03/05/2025

Shift: A

Incharge(s): V Balaji Naik, G Eswara Rao

Sl No	Area	Equipment	Problem	Action	From	To	Remarks
1	OHP	TBS on CO24	LT not working found main control MCB drop	control MCB made on	08:25:00	08:50:00	
2	OHP	BRS on CO4a	Reported BRS not healthy	Found healthy	07:45:00	08:00:00	
3	OHP	CO34	Found red	Control MCB trip	12:45:00	13:00:00	made on
4	CHP	CC132	Over load acted due to over load	Reset done	07:20:00	07:25:00	
5	CHP	CC54	Over load acted	Reset done	11:40:00	11:50:00	
6	CHP	CC51a	OLR trip due to over load	Reset done	10:40:00	10:45:00	
7	CHP	CC131	Over load acted	Reset done	13:00:00	13:20:00	
8	CHP	R1 on CC112	Inter lock failed	PLC power recycling done then ok	07:00:00	07:15:00	
9	CHP	CC104	EPB released at field but showing in system PLC bit not coming	Bypassed at IO rack	07:00:00	07:30:00	
10	CHP	CC44	OLR tripped found over load	informed to operation and reset done	08:30:00	08:35:00	
11	CHP	SCR6 on CC40	LT not working found LT drive trip	reset done	08:30:00 10:15:00	08:35:00 10:25:00	
12	CHP	CC40	ZSS acting frequently found motor running but belt is not running	Informed to mechanical	09:40:00	09:50:00	
13	CHP	CC112	Boom position problem found bit low	wire tightened then ok	10:30:00	10:40:00	
14	CHP	CC42	ZSS frequently acting found probe is not sensing	Probe changed still fault occurring informed to B shift	13:00:00	13:40:00	