



वी.एस.पी  
VSP

**RASHTRIYA ISPAT NIGAM LIMITED**  
**VISAKHAPATNAM STEEL PLANT**  
**RAW MATERIAL HANDLING PLANT**  
**ELECTRICAL SHIFT REPORT**

Date: 21/12/2025

Shift: B

Incharge(s): Saurabh Kumar Yadav

Sl No	Area	Equipment	Problem	Action	From	To	Remarks
1	OHP	CO 11(B)	olr acted	RESET	20:30:00	20:40:00	
2	OHP	CO111(B)	MPCB TRIPPED(MPCB DAMAGED)	RESET and MPCB REPLACED	19:00:00	19:15:00	2 TIMES
3	OHP	BRC on CO 33m	LT not taking place,pcrd OT acted ,guide problem	informed mechanical	14:15:00	14:35:00	
4	OHP	BRC on Co 28	yard zss cage stucked	cage made free	16:45:00	16:55:00	
5	OHP	CO 26	olr acted	reset	20:00:00	20:05:00	
6	OHP	CO 20	BRS malfunctioning complaint,	both BRS checked and found ok, conveyor run cmd given ,conveyor stops in ZSS fault	21:35:00	22:00:00	pending complaint,mot or is running gear box side problem
7	CHP	CC 115	brs not healthy,terminal loose connection	tightened	15:50:00	16:05:00	
8	CHP	CC 51	mpd tripped	reset	14:50:00	21:00:00	20 times
9	CHP	cc 104 scr9	slew not working,start PB in operator cabin loose connection	tightened	16:00:00	16:15:00	
10	CHP	CC 125	OLr acted	reset	17:25:00	17:35:00	
11	CHP	CC 34 SCR1	luffing not working,up limit switch stucked	release limit switch	19:30:00	19:45:00	
12	CHP	CC 35 SCR3	slew not working,slew limit acted, coal jamming	informed operation	21:10:00	21:30:00	



वी.एस.पी  
VSP

# RASHTRIYA ISPAT NIGAM LIMITED

VISAKHAPATNAM STEEL PLANT

RAW MATERIAL HANDLING PLANT

ELECTRICAL SHIFT REPORT

Date: 21/12/2025

Incharge(s): Saurabh Kumar Yadav

Shift: B

Sl No	Area	Equipment	Problem	Action	From	To	Remarks
13	WT	OT1,2,3 and 4	all red,PLC have not supply,I/C (ACB)tripped of OM4,ACB tripped of WT4 MCC,after made on ACB of WT4 ,I/C(ACB) of OM4 tripped	ACB made on of OM4 and given clearance for OT1,2 and 3 and for OT4 MCC ,ACB made on and all feeder made off,and one by one ,made on ,not used and spare feeder made off	14:30:00	14:55:00	OT 4 tippler trial run taken and given clearance @4 PM, no rack was there no delay
14	WT	OT 5	tippler not healthy,D2 tripped in SPF fault	drive not getting reset,checked and found encoder cable damaged,and encoder bearing jammed,new encoder replaced	16:30:00	17:50:00	
15	WT	OT 2	D2 tripped in pgf1 fault	reset	19:20:00	19:25:00	
16	WT	OP7	no movement,RLS acted	LS released	17:45:00	17:55:00	