



वी.एस.पी  
VSP

**RASTRIYA ISPAT NIGAM LIMITED**  
**VISAKHAPATNAM STEEL PLANT**  
**RAW MATERIAL HANDLING PLANT**  
**ELECTRICAL SHIFT REPORT**

Date: 14/06/2025

Shift: A

Incharge(s): V Balaji Naik

Sl No	Area	Equipment	Problem	Action	From	To	Remarks
1	OHP	VF2a	Motor 2 MPCB tripped	Made on	11:55:00	12:05:00	
2	OHP	CO32	OLR acted	Reset doen	10:30:00	10:40:00	
3	OHP	WOBR on CO26	LT not moving found PCRD cable unwinding	Properly winded then ok	07:20:00	07:35:00	
4	OHP	CO11	Carriage drive over load trip due to track jam	Reset done	07:22:00	07:30:00	
5	OHP	CO11	ZSS acted found sensor probejam	Bypassed at CJB	08:47:00	08:54:00	Informed to change after conveyor stopping
6	OHP	RSCO10a carriage	Carriage drive not moving olr acted	Reset done	07:20:00	07:30:00	
7	OHP	CO32	Reported red found OLR acted	Reset done	10:30:00	10:41:00	
8	OHP	WOBR on CO26	Reported not moving checked found PCRD cable unwinding	PCRD cable winding done then ok	07:20:00	07:30:00	
9	OHP	RSC10a	ZSS sensor got hit by tail pulley	ZSS bypassed and infomred to do necessary not hit sensor	07:00:00	07:10:00	Infomed to G shift and B shift regarding this
10	CHP	CC131	Over load acted	Reset done	10:30:00	10:35:00	
11	CHP	CC201 and CC203	Pull card acted	Reset done phisically then ok	06:20:00	06:30:00	



वी.एस.पी  
VSP

**RASTRIYA ISPAT NIGAM LIMITED**  
**VISAKHAPATNAM STEEL PLANT**  
**RAW MATERIAL HANDLING PLANT**  
**ELECTRICAL SHIFT REPORT**

Date: 14/06/2025

Incharge(s): V Balaji Naik

Shift: A

Sl No	Area	Equipment	Problem	Action	From	To	Remarks
12	CHP	SCR6 on CC40	LT drive trip found found fault F30003	Reset done	06:40:00	06:50:00	
13	CHP	SCR5 on CC32	LT drive trip (over load) found wheel not rotating	Informed operation and mechanical Reset done	08:30:00	08:40:00	
14	CHP	SCR2 on Cc34	LT not running found PCRD cable unwinded	Winded and guide adjusted then ok	10:10:00	10:30:00	
15	CHP	CC31	BRS not getting reset	Transmitter and receiver cleaned then ok reset done	10:50:00	11:00:00	
16	CHP	SCR1 on CC36	LT problem found drive trip	Reset done	13:15:00	13:25:00	
17	CHP	CC26a	Chute sensor not working due to loose connection in module	Tightened then ok	12:10:00	12:15:00	
18	WT	OP1	D6 OLR trip during coupling time	reset done	12:00:00	12:10:00	
19	WT	OP10	no power found Incoming breaker tripped in LC10B	Breaker made on then ok	13:30:00	13:50:00	