



वी.एस.पी  
VSP

**RASHTRIYA ISPAT NIGAM LIMITED**  
**VISAKHAPATNAM STEEL PLANT**  
**RAW MATERIAL HANDLING PLANT**  
**ELECTRICAL SHIFT REPORT**

Date: 12/10/2025

Shift: A

Incharge(s): Amit Roy

| Sl No | Area | Equipment    | Problem                 | Action                                                                                                                 | From                             | To                               | Remarks                   |
|-------|------|--------------|-------------------------|------------------------------------------------------------------------------------------------------------------------|----------------------------------|----------------------------------|---------------------------|
| 1     | OHP  | DB-1         | Reported tripped        | OLR acted.Reset done                                                                                                   | 12:45:00                         | 13:00:00                         |                           |
| 2     | OHP  | CO-26        | Reported tripped        | OLR acted.Reset done                                                                                                   | 11:05:00                         | 11:15:00                         |                           |
| 3     | OHP  | TBS on CO-7A | Right luff tripping     | brakes made loose and chute material jamming cleared after boom run and motor hot blowing done and up/down tested okay | 08:20:00                         | 09:30:00                         |                           |
| 4     | CHP  | CC-33        | Reported tripped        | OLR acted(3 times) due to belt overload at T/E.Reset done                                                              | 09:20:00                         | 09:35:00                         | Tripped at 9.20,9.35,9.50 |
| 5     | CHP  | Cc-35 SCR-5  | LT not working          | Drive tripped.Reset done(2 times)                                                                                      | 09:20:00<br>09:50:00             | 09:35:00<br>10:00:00             |                           |
| 6     | CHP  | CC-104 SCR-9 | Slew and B/W not moving | Oil cooler motor trip and oil temperature high.Oil cooler made on and oil temperature found normal and tested okay     | 11:05:00                         | 11:30:00                         |                           |
| 7     | WT   | OC-1A        | Reported Tripped        | OLR acted(3 times).Reset done                                                                                          | 12:00:00<br>12:40:00<br>13:10:00 | 12:05:00<br>12:50:00<br>13:20:00 |                           |
| 8     | IOSA | OC-7B        | Reported fail to start  | Breaker racked out and inserted properly and tested okay                                                               | 07:50:00                         | 08:10:00                         |                           |
| 9     | IOSA | WOBR         | LT not taking place     | PCRD chain problem.Loop given for reclaiming                                                                           | 09:00:00                         | 09:20:00                         | Informed to mechanical    |