



वी.एस.पी  
VSP

# RASHTRIYA ISPAT NIGAM LIMITED

VISAKHAPATNAM STEEL PLANT

RAW MATERIAL HANDLING PLANT

ELECTRICAL SHIFT REPORT

Date: 08/09/2025

Incharge(s): V Balaji Naik

Shift: C

Sl No	Area	Equipment	Problem	Action	From	To	Remarks
1	OHP	TT2 chute vibrator	MPCB tripped	Reset done	02:10:00	02:15:00	
2	OHP	CO35	olr acted	Reset done	23:40:00	23:45:00	
3	OHP	CO26	DMPR acted due to over load	Reset done	01:40:00	01:50:00	
4	OHP	Stacker on CO20	LBC not working found over load acted due to material jammimg 2 times	Reset done	05:00:00	05:10:00	05.20am to 05.30am
5	OHP	CO84	Over laod acted due to over material 2 times	Reset done	04:00:00	04:10:00	04.30am to 04.40am
6	OHP	CO34	olr acted due to over material 3 times	Reset done	05:15:00	05:25:00	05.35am to 05.40am:05.50am to 06.00am
7	OHP	TT2 chute vibrator	Not working found MPCB trip due to over material 2 times	Reset done	02:20:00	02:25:00	03.00am to 03.10am
8	OHP	CO70	BRS bypassed as per operational request	bypassed	04:40:00	04:45:00	
9	CHP	CC54	over load acted 6 times	Reset done	01:00:00	05:10:00	
10	CHP	CC51	MPD acted 6 times stopped feeding conveyor	Reset done	02:10:00	04:45:00	
11	CHP	SCR3 on CC40	LT not working found OT acted due to position at tail end	Reset done	00:20:00	00:30:00	01.00am to 01.10am:02.20am to 02.30am
12	CHP	CC34	Brs bypassed as per operation requirement	bypassed	00:50:00	01:00:00	



वी.एस.पी  
VSP

# RASHTRIYA ISPAT NIGAM LIMITED

VISAKHAPATNAM STEEL PLANT

RAW MATERIAL HANDLING PLANT

ELECTRICAL SHIFT REPORT

Date: 08/09/2025

Incharge(s): V Balaji Naik

Shift: C

Sl No	Area	Equipment	Problem	Action	From	To	Remarks
13	CHP	SCR8 on CC112	BW not working found pump not able to on	Fault reset done then ok	05:20:00	05:35:00	Not an electrical problem
14	CHP	CO34	Over load acted due to heavy jamming	Reset done	23:00:00	23:10:00	11.30am to 11.40am:12.10am to 12.20am
15	WT	OP6	not moving	Wrong complaint	02:40:00	02:45:00	
16	WT	OP3	Breaker tripped while moving forward found bottom pad fallen from trolley line at column no 21	Power block taken for U10 to U12 C clamp adjusted and moved to parking zone again C clamp insulator broken and clamp bend at column no:13, Replaced with new C clamp with watchers to lift the collector pad height to reach trolley line( Informed to operation for not allotting rake to U12 hence no delay no rake)	03:00:00	05:30:00	Trolley line may check at column no 13