



वी.एस.पी
VSP

RASHTRIYA ISPAT NIGAM LIMITED

VISAKHAPATNAM STEEL PLANT

RAW MATERIAL HANDLING PLANT

ELECTRICAL SHIFT REPORT

Date: 12/02/2026

Incharge(s): Amit Roy

Shift: A

| Sl No | Area | Equipment | Problem | Action | From | To | Remarks |
|-------|------|--------------------|---------------------------------|---|----------|----------|---------|
| 1 | OHP | CO-6 | ZSS acting | Probe damaged and cage fixing bolt missing.Probe replaced and cage bolts replaced and tested okay | 06:50:00 | 07:20:00 | |
| 2 | OHP | CR-2A | ZSS acting | Probe gap adjusted and tested okay | 13:25:00 | 13:35:00 | |
| 3 | OHP | RBF-3A(C/D) | LT not moving | Tripped due to material jamming.Reset done | 10:00:00 | 10:15:00 | |
| 4 | OHP | CO-6 | ZSS acting | Module problem.Module replaced and tested okay | 13:30:00 | 14:05:00 | |
| 5 | CHP | CC-27 | Reported CJD not acting | Probe wire got cut. Rejointed and tested okay | 12:00:00 | 12:15:00 | |
| 6 | CHP | CC-51 | MPD tripped | Reset done(4 times) | 07:40:00 | 10:55:00 | |
| 7 | CHP | CC-58 | Reported tripped | OLR acted.Reset done | 06:50:00 | 07:05:00 | |
| 8 | CHP | CC-39 SCR-6 | B/C not running | Chute sensor acted.Sensor cleaned and tested okay | 08:10:00 | 08:25:00 | |
| 9 | CHP | Cc-108 | Reported tripped | OLR acted.Reset done(2 times) | 10:05:00 | 12:05:00 | |
| 10 | WT | EOT in ore tippler | Reported Hoist not taking place | Brake rectifier failed.Replaced and tested okay | 11:00:00 | 12:00:00 | |