



वी.एस.पी  
VSP

**RASTRIYA ISPAT NIGAM LIMITED**  
**VISAKHAPATNAM STEEL PLANT**  
**RAW MATERIAL HANDLING PLANT**  
**ELECTRICAL SHIFT REPORT**

Date: 10/05/2025

Shift: B

Incharge(s): Lal Singh, Arnab Roy

Sl No	Area	Equipment	Problem	Action	From	To	Remarks
1	OHP	CO 10 and CO 7A	BRs bypass request from operation	Bypassed	15:00:00	15:10:00	kept in circuit
2	OHP	CO 35	OLR acted	reset done	17:20:00	17:30:00	
3	OHP	RSCO 1A	Position indication not coming bcz of switch problem	bypassed for SB 3A and SB 5A	15:15:00	15:40:00	Informed to Gen shift for switch changing
4	CHP	CC 54	Tripped in overload	reset done	18:30:00 19:45:00	18:35:00 19:50:00	
5	CHP	CC 113	Stopped in pull chord	Pull chord released	15:30:00	15:40:00	
6	CHP	CC 36 , SCR 1	LT problem, PCRD in zig zag condition	Cable winded properly	15:10:00	16:30:00	
7	CHP	CC 39 , SCR 7	BC not running	Chute sensor acted due to chute jamming . Informed to operation	15:15:00	15:25:00	
8	CHP	CC 33 , SCR 4	BC frequently stopped due to ZSS	Coal piece stucked inside cage, cleaned then ok	15:50:00	16:10:00	
9	CHP	CC 33 , SCR 4	Luffing not working due to LT interlock	LT stopped , then luffing working	19:30:00	20:00:00	
10	CHP	CC 35 , CC 34	No power in machines	In CC 35 IC one HT fuse blown. Also No power in IC due to Feeder 1 tripped ( Panel no -12) in LBDS -4,5. Cable earth fault in CC 35 PCRD cable.	18:30:00	22:00:00	DNW on the job
11	WT	OP 1 and OP4	Communication problem	PLC recycled	15:00:00	15:20:00	