



वी.एस.पी  
VSP

**RASTRIYA ISPAT NIGAM LIMITED**  
**VISAKHAPATNAM STEEL PLANT**  
**RAW MATERIAL HANDLING PLANT**  
**ELECTRICAL SHIFT REPORT**

Date: 19/05/2025

Shift: A

Incharge(s): V Balaji Naik

Sl No	Area	Equipment	Problem	Action	From	To	Remarks
1	OHP	BRC on CO33M	Lt not working found drive trip	Reset done	12:40:00	12:55:00	
2	OHP	CO27a	BRS bypassed as per operation request	By passed	12:30:00	12:40:00	
3	CHP	CC109	Pull card acted	Reset done	11:00:00	11:10:00	
4	CHP	Cc131	over load trip	Reset done	11:00:00	11:05:00	
5	CHP	CC54	Over load trip( 3 times) due to over load	Informed to mechanical after load clearance Reset done	12:05:00	12:15:00	
6	CHP	SCR5 on CC32	Luffing working slowly found BC and BW area coal jamming	Informed to operation	07:25:00	07:35:00	
7	CHP	SCR7 on CC39	Slew not working found anti clock wise limit acted	Informed to operation	08:35:00	08:50:00	
8	CHP	CC108	Healthy stop found ZSS return core loose tightened	Then ok	11:15:00	11:35:00	
9	CHP	CC222	Healthy not showing red and not starting found Drive tripped	Reset done found load on belt informed to operation	12:35:00	12:45:00	
10	CHP	SCR1 on CC36	BC not running found BSS acting	Informed to mechanical	13:30:00	13:45:00	
11	CHP	CC112	BRS not resetting both sensors cleaned	found ok	10:25:00	10:35:00	
12	IOSA	All conveyors	Reported RED found communication problem in PLC	Power recycling done then ok	12:40:00	13:30:00	