



वी.एस.पी  
VSP

**RASTRIYA ISPAT NIGAM LIMITED**  
**VISAKHAPATNAM STEEL PLANT**  
**RAW MATERIAL HANDLING PLANT**  
**ELECTRICAL SHIFT REPORT**

Date: 11/05/2025

Shift: B

Incharge(s): Lal Singh, Arnab Roy

Sl No	Area	Equipment	Problem	Action	From	To	Remarks
1	OHP	CO 35	OLR acted	reset done	15:55:00 17:55:00	16:00:00 18:00:00	
2	OHP	CO 28 , BRC	LT not taking place	Drive tripped on overload , reset done	17:15:00	17:35:00	
3	OHP	CO 25	Overload acted	reset done	20:20:00 20:45:00	20:30:00 20:55:00	
4	OHP	BRC on CO 33M	BW not rotating properly	Oil level low , but oil sensor not working . Sensor cleaned and tested . Oil filled by mechanical	16:00:00	18:00:00	No electrical delay
5	OHP	TBS on CO 23	2 PCRD cable joint flash took place	Power made off ,	17:30:00	22:00:00	DNW on the job
6	CHP	CC 107	Complaint received Drive end chute sensor not working	Checked and found chute sensor working	19:30:00	19:45:00	
7	CHP	CC 54	Tripped in overload	reset done	20:35:00 21:00:00	20:40:00 21:05:00	
8	CHP	CC 131	Tripped in overload	reset done	19:40:00 21:10:00 21:35:00	19:45:00 21:15:00 21:40:00	
9	CHP	CC 38	BRS found in bypassed condition during inspection	Kept in circuit	21:45:00	22:00:00	
10	WT	OT 5	PLC to Limit switch JB high missing	In PLC side 110 V glass fuse blown. Fuse replaced	14:30:00	14:45:00	
11	WT	OP 9 , OP 7	Reverse limit problem	Limits checked. working well. In OP 9 , near track creepers to be cut	14:45:00	15:00:00	



वी.एस.पी  
VSP

**RASTRIYA ISPAT NIGAM LIMITED**  
**VISAKHAPATNAM STEEL PLANT**  
**RAW MATERIAL HANDLING PLANT**  
**ELECTRICAL SHIFT REPORT**

Date: 11/05/2025

Shift: B

Incharge(s): Lal Singh, Arnab Roy

Sl No	Area	Equipment	Problem	Action	From	To	Remarks
12	IOSA	Old WOBR	PCRD cable overlapped	Cable winded properly	18:45:00	19:30:00	