



वी.एस.पी
VSP

RASHTRIYA ISPAT NIGAM LIMITED
VISAKHAPATNAM STEEL PLANT
RAW MATERIAL HANDLING PLANT
ELECTRICAL SHIFT REPORT

Date: 15/11/2025

Shift: A

Incharge(s): K SANKARA RAO

| Sl No | Area | Equipment | Problem | Action | From | To | Remarks |
|-------|------|-------------------|---|--|----------------------|----------------------|---------|
| 1 | OHP | CO-26 | OLR ACTED (2TIMES) | RESET DONE | 07:30:00 10:10:00 | 07:40:00 10:20:00 | |
| 2 | OHP | RSCO-10A | REPORTED STOPPING IN ZSS FOUND PROBE CHECK NUT LOOSE | PROBE CHECK NUT TIGHT THAN OK | 09:50:00 | 10:00:00 | |
| 3 | OHP | BRC ON CO-30 | B/C TRIPPED ON OLR | RESET DONE | 09:15:00 | 09:25:00 | |
| 4 | OHP | CO-58 | REPORTED STOPPING ON ZSS PROBE DIRECT | ZSS PROBE REPLACED WITH NEW PROBE THAN OK | 12:45:00 | 13:40:00 | |
| 5 | CHP | CC-29 TO CC-31 | POSITION INDICATION NOT SHOWING AT I/O RACK FIELD WIRE REMOVED CONDITION | FIELD WIRE CONNECTED THAN OK | 06:50:00 | 07:00:00 | |
| 6 | CHP | CC-54 | OLR ACTED (4TIMES) | RESET DONE | 07:00:00 | 12:00:00 | |
| 7 | CHP | CC-117 | OLR ACTED | RESET DONE | 06:00:00 | 06:10:00 | |
| 8 | CHP | CC-131 | OLR ACTED | RESET DONE | 11:40:00 | 11:45:00 | |
| 9 | CHP | BC STREAM | REPORTED NOT HEALTHY FOUND LC-19 I/C-1 TRIP DUE TO EARTH FAULT | FAULT ISOLATED I/C CHARGED THAN OK | 12:00:00 | 12:15:00 | |
| 10 | CHP | CC-31 SCR-4 | B/C NOT RUNNING FOUND SELECTION PROBLEM | SELECTOR SWITCH KEPT CORRECT POSITION THAN OK | 06:40:00 | 06:50:00 | |
| 11 | CHP | CC-33 SCR-5 | PCRD CABLE FELL DOWN DUE TO SINGLE PHASE | OUT GOING CONNECTION TIGHT THAN CABLE LAYING WAS DONE | 07:50:00 | 08:10:00 | |
| 12 | CHP | CC-104 SCR-9 | SLEW NOT WORKING FOUND RELAY STUCK UP | RELEASED THAN OK | 08:05:00 09:40:00 | 08:15:00 09:55:00 | |
| 13 | CHP | CC-112 SCR-8 | SLEW NOT WORKING LIMIT ACTED DUE TO JAMMING | AFTER CLEANING MATERIAL LIMIT RELEASE THAN OK | 09:20:00 | 09:30:00 | |