



वी.एस.पी  
VSP

# RASHTRIYA ISPAT NIGAM LIMITED

VISAKHAPATNAM STEEL PLANT

RAW MATERIAL HANDLING PLANT

ELECTRICAL SHIFT REPORT

Date: 22/08/2025

Shift: A

Incharge(s): Amit Roy

Sl No	Area	Equipment	Problem	Action	From	To	Remarks
1	OHP	WOBR on CO-26	Reported slew not taking place	OLR acted.Reset done	08:30:00	08:45:00	
2	OHP	WOBR on CO-26	Reported SLeW not taking place	Drive tripped.Reset done	11:50:00	12:00:00	
3	OHP	BRC on CO-31	Reported LT not taking place	CHP side M1 brake supply wire came out.Wire joint and tested okay	07:15:00	07:40:00	Informed to mechanical for brake adjustment as brakes were not opening.
4	OHP	WOBR on CO-29	Reported B/C not moving	Checked and found yard Intelock ZSS module relay contact burnt and control problem. Relay contact changed in module and control rectified and tested okay	08:20:00	09:00:00	
5	OHP	WOBR on CO-29	Reported LT not taking place	M4 olr acted due to track jamming(2times).Reset done	12:00:00 13:00:00	12:20:00 13:15:00	Informed to operation to clear jamming
6	OHP	TT-1A	Reported LT not moving	OLR acted due to belt stuck up due to material.Reset done and LT tested okay	12:10:00	12:15:00	
7	CHP	CC-51	CC-31 Feeding conveyor stopped due to CC-51 MPD	Due to overmaterial on belt(15times)	07:00:00	11:40:00	
8	CHP	CC-51	Tripped on OLR	Reset done	10:12:00	10:30:00	



वी.एस.पी  
VSP

**RASHTRIYA ISPAT NIGAM LIMITED**  
**VISAKHAPATNAM STEEL PLANT**  
**RAW MATERIAL HANDLING PLANT**  
**ELECTRICAL SHIFT REPORT**

Date: 22/08/2025

Incharge(s): Amit Roy

Shift: A

Sl No	Area	Equipment	Problem	Action	From	To	Remarks
9	CHP	CC-51	Reported ZSS acted	Due to jamming	11:45:00	14:00:00	Cleaning is going on
10	CHP	CC-17	ZSS acted	Probe cable damaged. Rejoint done	08:20:00	08:35:00	
11	CHP	CC-29	ZSS acted	Cage stuck up due to material. Material removed and tested okay	11:20:00	11:30:00	
12	CHP	CC-33 SCR-4	LT not working	Track jamming due to material sliding onto track	07:18:00	07:30:00	Informed to operation
13	CHP	CC-111 S-3	Reported signal missing	LT done and tested okay	07:30:00	07:50:00	
14	CHP	CC-40 S-3	B/C not working	Discharge chute jamming	10:05:00	10:20:00	informed to operation
15	CHP	CC-32 SCR-5	Luffing not working	Hose pipe damaged and oil leaking	10:42:00	11:00:00	informed to mechanical
16	CHP	CC-38 SCR-6	TUL CS not healthy	Cable rejoin done and tested okay	12:50:00	13:05:00	
17	CHP	CC-32 SCR-5	Luffing not working	solenoid plug cleaning done and tested okay	13:00:00	13:20:00	
18	WT	OT-5	Reported not moving	PLC side LS high found missing. Glass fuse blown. Field wire removed and LS bypassed	10:35:00	10:50:00	TO be checked
19	IOSA	OC-23A	Reported ZSS acting	Checked and found Stone struck between cage and probe. Stone removed and tested okay	12:35:00	12:45:00	