



## **Avaya Solution & Interoperability Test Lab**

---

# **Application Notes for Tandberg, Polycom and Avaya Endpoints with Avaya Communication Manager Utilizing H.323 Signaling - Issue 1.1**

### **Abstract**

These Application Notes present the procedures for configuring connectivity between Tandberg, Polycom and Avaya endpoints with Avaya Communication Manager via H.323 signaling.

Information in these Application Notes has been obtained through DevConnect compliance testing and additional technical discussions. Testing was conducted via the DevConnect Program at the Avaya Solution and Interoperability Test Lab.

# 1. Introduction

These Application Notes present the procedures for configuring connectivity between Tandberg, Polycom and Avaya endpoints with Avaya Communication Manager via H.323 signaling.

**Figure 1** illustrates the sample configuration utilized for this compliance tested solution. Avaya Communication Manager was comprised of a pair of Avaya S8710 Servers and an Avaya G650 Media Gateway. Avaya Communication Manager provided authentication, registration and feature server functionality for the video enabled endpoints via H.323 signaling, as well as audio only connectivity for all endpoints in this compliance tested solution. For example, any endpoint associated with Avaya Communication Manager, including the video enabled endpoints can, at a minimum, have audio only call connectivity. All video codec functionality is dependent on the hardware, e.g., video codec, installed on the endpoint. Note that although Avaya Communication Manager does not provide video codec support, Avaya Communication Manager is involved in the signaling for video calls. In this way, Avaya Communication Manager can be administered to provide Call Admission Control (CAC) regarding the bandwidth required for video.

The Tandberg Centric 1700 MXP operates both as a multi-point control unit and PC display, enabling seamless and real-time face-to-face collaboration at the desktop.

- Multi-point control unit for conferencing up to 4 video and 3 audio endpoints
- H.235 and IEEE 802.1x authentication
- Video compliant with the H.264 standard


Tandberg Centric 150 MXP provides communication for the individual workspace by allowing end users to place video and voice calls.

- Up to 512 kbps IP
- H.235 Authentication
- Video compliant with the H.264 standard

The Polycom VSX 3000 operates both as a multi-point control unit and PC display, enabling seamless and real-time face-to-face collaboration at the desktop.

- Multi-point control unit for conferencing up to 4 video enabled endpoints
- Video compliant with the H.264 standard

To account for the SIP telephones in this sample configuration, Avaya SIP Enablement Services was utilized as a SIP registration server only.



**Figure 1: Sample Configuration**

## 2. Equipment Validated

Table 1 list the equipment and software/firmware versions that were used for this sample configuration.

Equipment	Version
Avaya S8710 Servers	Avaya Communication Manager 4.0 (R014x.00.1.731.2)
Avaya G650 Media Gateway: <ul style="list-style-type: none"><li>• Avaya TN2312BP (IPSI)</li><li>• Avaya TN799DP (C-LAN)</li><li>• Avaya TN2302AP (MEDPRO)</li></ul>	HW12 FW040 HW01 FW024 HW20 FW117
Avaya SIP Enablement Services	SES 4.0 (04.0-04.0.033.6)
Avaya C364T-PWR Converged Stackable Switch	4.5.14
Avaya 4600 Series IP Telephones	2.8 (H.323)
Avaya 4600 Series IP Telephones	2.2.2 (SIP)
Avaya 9600 Series IP Telephones	1.5 (H.323)
Avaya IP Softphone	6.0.0.25
Avaya 6408D+ Digital Telephones	--
Analog Telephones	--
Polycom VSX 3000	8.5.3
Tandberg Centric 150 MXP	L5.0
Tandberg Centric 1700 MXP	F6.1

**Table 1: Equipment and Software Versions**

### 3. Avaya Communication Manager Configuration

This section describes the configuration for enabling Avaya Communication Manager to interoperate with the video enabled endpoints in this sample configuration.

Avaya Communication Manager was administered from the System Access Terminal (SAT). In these Application Notes the SAT screens are shown with a gray shaded background. In some instances, the information from the original screen has been edited or annotated for brevity or clarity in presentation. For example, entries and/or fields in the SAT screens that were either modified or were required for these Application Notes are displayed with boldface type. Refer to [1] and [2] for additional information regarding the administration of Avaya Communication Manager.

### 3.1. Verify Licensing

The following steps verify licensing on Avaya Communication Manager that is required to support the configuration described in these Application Notes. If a required feature is not enabled or there is insufficient capacity, contact an authorized Avaya account representative to make the appropriate changes.

Step	Description
3.1.1	<p>Issue the command “<b>display system-parameters customer-options</b>” and proceed to page 2. Verify that there is sufficient licensing for the following:</p> <ul style="list-style-type: none"> <li>The <b>Maximum Video Capable H.323 Stations</b> field must be greater than or equal to the number of H.323 video enabled stations in the network. In this sample configuration, the Tandberg and Polycom endpoints are video capable stations. <ul style="list-style-type: none"> <li>The Tandberg Centric 1700 MXP is administered as four H.323 video enabled stations.</li> <li>The Polycom VSX 3000 is administered as three H.323 video enabled stations.</li> <li>The Tandberg Centric 150 MXP is administered as two H.323 video enabled stations. Note that the Tandberg Centric 150 MXP is administered as two H.323 video enabled stations to support multiple calling lines (see <b>Step 3.5.2</b>). Since the Tandberg Centric 1700 MXP does not support multiple call appearances, this is a work around to emulate a station with multiple call appearances. The Tandberg Centric 1700 MXP may be administered as a single H.323 video enabled station.</li> </ul> </li> <li>The <b>Maximum Video Capable IP Softphones</b> field must be greater than or equal to the number of Avaya IP Softphones enabled with video capabilities in the network.</li> </ul>
	<pre>display system-parameters customer-options</pre> <p style="text-align: right;">Page 2 of 10</p> <pre> OPTIONAL FEATURES  IP PORT CAPACITIES Maximum Administered H.323 Trunks: 800 20 Maximum Concurrently Registered IP Stations: 100 11 Maximum Administered Remote Office Trunks: 0 0 Maximum Concurrently Registered Remote Office Stations: 0 0 Maximum Concurrently Registered IP eCons: 0 0 Max Concur Registered Unauthenticated H.323 Stations: 100 0 Maximum Video Capable H.323 Stations: 100 16 Maximum Video Capable IP Softphones: 100 5 Maximum Administered SIP Trunks: 800 225  Maximum Number of DS1 Boards with Echo Cancellation: 0 0 Maximum TN2501 VAL Boards: 10 0 Maximum Media Gateway VAL Sources: 0 0 Maximum TN2602 Boards with 80 VoIP Channels: 128 0 Maximum TN2602 Boards with 320 VoIP Channels: 128 0 Maximum Number of Expanded Meet-me Conference Ports: 0 0  (NOTE: You must logoff &amp; login to effect the permission changes.) </pre>

## 3.2. Configure Connectivity

This section describes the steps for configuring connectivity between the Tandberg, Polycom and Avaya endpoints in this sample configuration with Avaya Communication Manager.

Step	Description
3.2.1	<p>Issue the command “<b>change ip-codec-set &lt;n&gt;</b>”, where <b>n</b> is the number of an available codec set. Add entries for audio codecs that are supported by the endpoints in a network.</p> <ul style="list-style-type: none"> <li>The Tandberg endpoints support <b>G.711MU</b> and <b>G.722.1-32K</b>.</li> <li>The Polycom VSX 3000 supports <b>SIREN14-48K</b>, <b>G.711MU</b>, <b>G.722.1-32K</b> and <b>G.729A</b>.</li> </ul> <pre> change ip-codec-set 2 Page 1 of 2  IP Codec Set  Codec Set: 2  Audio          Silence      Frames      Packet Codec          Suppression  Per Pkt     Size(ms) 1: SIREN14-48K          1          20 2: G.722.1-32K          1          20 3: G.729A              n           2          20 4: G.711MU             n           2          20 5: 6: 7: </pre>
3.2.2	<p>Proceed to Page 2 and enable direct IP multimedia. The <b>Maximum Call Rate for Direct-IP Multimedia</b> field is the combined audio and video transmit/receive rate for a call. This field is utilized to limit the bandwidth used for calls within an IP network region. For these Application Notes, the field was set well above the expected call rate.</p> <pre> change ip-codec-set 2 Page 2 of 2  IP Codec Set  Allow Direct-IP Multimedia? y Maximum Call Rate for Direct-IP Multimedia: 5120:Kbits Maximum Call Rate for Priority Direct-IP Multimedia: 384:Kbits  Mode          Redundancy FAX           relay      0 Modem         off        0 TDD/TTY       US         3 Clear-channel n         0 </pre>

Step	Description
3.2.3	<p>Issue the command “<b>change ip-network-region &lt;n&gt;</b>”, where <b>n</b> is the number of an available IP network region and provision an IP network region for the Tandberg and Polycom endpoints. Administer settings as displayed:</p> <ul style="list-style-type: none"> <li>Enter the number of the IP codec set provisioned in <b>Step 3.2.1</b> in the <b>Codec Set</b> field.</li> <li>Use default settings for remaining fields.</li> </ul> <p><i><b>Note:</b> It is not required that a second IP network region be created. By default, any IP endpoint associated with Avaya Communication Manager will correlate with IP network region 1. For this sample configuration, a second IP network region was created to allow for the following:</i></p> <ul style="list-style-type: none"> <li><i>A distinct setting for the <b>Authoritative Domain</b> field.</i></li> <li><i>An IP codec set to account for the video enabled endpoints in this sample configuration (see <b>Step 3.2.1</b>).</i></li> <li><i>A unique setting for the <b>H.323 SECURITY PROFILES</b> field (see <b>Step 3.2.4</b>).</i></li> <li><i>The option of restricting the bandwidth over the Wide Area Network (WAN) interface between IP network regions for video calls (see <b>Step 3.2.5</b>).</i></li> </ul> <pre> change ip-network-region 100                                      Page    1 of   19                                       IP NETWORK REGION  Region: 100 Location:      Authoritative Domain: avaya.com Name: H.323 Video MEDIA PARAMETERS      Intra-region IP-IP Direct Audio: yes Codec Set: 2          Inter-region IP-IP Direct Audio: yes                       IP Audio Hairpinning? n UDP Port Min: 2048 UDP Port Max: 3329 DIFFSERV/TOS PARAMETERS      RTCP Reporting Enabled? y Call Control PHB Value: 46    RTCP MONITOR SERVER PARAMETERS Audio PHB Value: 46          Use Default Server Parameters? y Video PHB Value: 26 802.1P/Q PARAMETERS Call Control 802.1p Priority: 6 Audio 802.1p Priority: 6 Video 802.1p Priority: 5      AUDIO RESOURCE RESERVATION PARAMETERS H.323 IP ENDPOINTS          RSVP Enabled? n H.323 Link Bounce Recovery? y Idle Traffic Interval (sec): 20 Keep-Alive Interval (sec): 5 Keep-Alive Count: 5 </pre>



Step	Description
3.2.4	<p>Proceed to Page 2 and enable H.323 endpoints to register with Avaya Communication Manager using any of the H.323 authentication methods supported by Avaya Communication Manager.</p>
	<pre> change ip-network-region 100 Page 2 of 19  IP NETWORK REGION  INTER-GATEWAY ALTERNATE ROUTING / DIAL PLAN TRANSPARENCY Incoming LDN Extension: Conversion To Full Public Number - Delete:      Insert: Maximum Number of Trunks to Use for IGAR: Dial Plan Transparency in Survivable Mode? n  BACKUP SERVERS(IN PRIORITY ORDER)      H.323 SECURITY PROFILES 1                                     1    any-auth 2                                     2 3                                     3 4                                     4 5 6                                     Allow SIP URI Conversion? y  TCP SIGNALING LINK ESTABLISHMENT FOR AVAYA H.323 ENDPOINTS Near End Establishes TCP Signaling Socket? y Near End TCP Port Min: 61440 Near End TCP Port Max: 61444 </pre>

Step	Description
3.2.5	<p>Proceed to Page 3 and enable inter-region connectivity between IP network regions 100 and 1 by entering the number of the IP codec set provisioned in <b>Step 3.2.1</b> in the <b>codec set</b> field. By default, the C-LAN and all Avaya IP endpoints are assigned to IP network region 1. For this sample configuration, the Tandberg and Polycom endpoints are assigned to IP network region 100 (see <b>Step 3.2.6</b>).</p> <p><i><b>Note:</b> The default value for the <b>Units</b> field allows unlimited bandwidth allocation for calls between IP network regions. This has significance for video, as a video call may have high bandwidth requirements. If the goal is to preserve bandwidth over the WAN, enter appropriate settings under <b>WAN-BW-limits</b>.</i></p> <pre> change ip-network-region 100 Page 3 of 19  Inter Network Region Connection Management  src dst codec direct WAN-BW-limits Video Dyn rgn rgn set WAN Units Total Norm Prio Shr Intervening-regions CAC IGAR 100 1 2 y NoLimit 100 2 100 3 100 4 100 5 100 6 100 7 100 8 100 9 100 10 100 11 100 12 100 13 100 14 100 15 </pre>
3.2.6	<p>Issue the command “<b>change ip-network-map</b>” and administer settings to assign a range of IP addresses to an IP network region as displayed. For this sample configuration, the Tandberg and Polycom endpoints are assigned static IP addresses that are in this range. Therefore, the Tandberg and Polycom endpoints are assigned to the IP network region provisioned in <b>Steps 3.2.3 - 3.2.5</b>.</p> <pre> change ip-network-map Page 1 of 32  IP ADDRESS MAPPING  From IP Address (To IP Address Subnet Region VLAN Emergency 192.168.12 .50 192.168.12 .59 or Mask) 100 n Location Extension </pre>

### 3.3. Configure an H.323 Station to Support Avaya IP Softphone

This section describes the steps for configuring an H.323 station on Avaya Communication Manager to support Avaya IP Softphone.

Step	Description
3.3.1	<p>Issue the command “<b>change station &lt;n&gt;</b>”, where <b>n</b> is the extension of an existing station and administer settings to enable video for this station as displayed. Repeat this step for each Avaya H.323 station that is required to support Avaya IP Softphone and video.</p> <p><i>Note: These Application Notes include an Avaya IP Softphone that is associated with this station. Refer to [3] for administering Avaya IP Softphone.</i></p> <pre>change station 33005                                     Page 1 of 5                                  STATION  Extension: 33005                      Lock Messages? n          BCC: 0 Type: 9620                          Security Code: 123456        TN: 1 Port: S00021                        Coverage Path 1:          COR: 1 Name: H.323 33005 Video              Coverage Path 2:          COS: 1                                 Hunt-to Station:  STATION OPTIONS                                  Time of Day Lock Table: Loss Group: 19                      Personalized Ringing Pattern: 1                                 Message Lamp Ext: 33005 Speakerphone: 2-way                Mute Button Enabled? y Display Language: english Survivable GK Node Name: Survivable COR: internal Survivable Trunk Dest? y                                  Media Complex Ext:                                 IP SoftPhone? y                                  IP Video Softphone? y                                  Customizable Labels? y</pre>

### 3.4. Configure H.323 Stations to Support the Tandberg Centric 1700 MXP

This section describes the steps for configuring H.323 stations on Avaya Communication Manager to support the Tandberg Centric 1700 MXP. Each Tandberg Centric 1700 MXP requires the administration of four stations in Avaya Communication Manager. Repeat the steps in this section for each Tandberg Centric 1700 MXP in the network.

Step	Description
3.4.1	Issue the command “ <b>add station &lt;n&gt;</b> ”, where <b>n</b> is the extension of an available station and administer settings as displayed.
	<pre> add station 33621                                     Page    1 of    4                                  STATION  Extension: 33621                                Lock Messages? n                BCC: 0   Type: H.323                                Security Code: 123456            TN: 1   Port: IP                                Coverage Path 1:                COR: 1   Name: Tandberg1700                       Coverage Path 2:                COS: 1                                 Hunt-to Station:                Tests? y  STATION OPTIONS                                  Time of Day Lock Table:       Loss Group: 19                Message Waiting Indicator: none                                  Authentication Required? y                                  Survivable COR: internal       Survivable Trunk Dest? y       DTMF over IP: in-band                                  IP Video? y </pre>
3.4.2	Repeat <b>Step 3.4.1</b> to add the “second” station for the Tandberg Centric 1700 MXP. For this sample configuration, extension 33622 was used.
3.4.3	Repeat <b>Step 3.4.1</b> to add the “third” station for the Tandberg Centric 1700 MXP. For this sample configuration, extension 33623 was used.
3.4.4	Repeat <b>Step 3.4.1</b> to add the “fourth” station for the Tandberg Centric 1700 MXP. For this sample configuration, extension 33624 was used.

Step	Description
3.4.5	<p>Issue the command “<b>change station &lt;n&gt;</b>”, where <b>n</b> is the extension of the “first” station configured for the Tandberg Centric 1700 MXP and administer settings as displayed. Set the <b>Hunt-to Station</b> field to the extension of the “second” station configured for the Tandberg Centric 1700 MXP.</p> <pre> change station 33621 Page 1 of 4  STATION  Extension: 33621          Lock Messages? n          BCC: 0 Type: H.323              Security Code: 123456      TN: 1 Port: IP                 Coverage Path 1:          COR: 1 Name: Tandberg1700       Coverage Path 2:          COS: 1                         <b>Hunt-to Station: 33622</b>      Tests? y  STATION OPTIONS  Loss Group: 19           Time of Day Lock Table:                         Message Waiting Indicator: none                          Authentication Required? y  Survivable COR: internal Survivable Trunk Dest? y DTMF over IP: in-band  IP Video? y </pre>
3.4.6	Repeat <b>Step 3.4.5</b> to administer the “second” station configured for the Tandberg Centric 1700 MXP. Set Hunt-to Station field to the extension of the “third” station configured for the Tandberg Centric 1700 MXP.
3.4.7	Repeat <b>Step 3.4.5</b> to administer the “third” station configured for the Tandberg Centric 1700 MXP. Set Hunt-to Station field to the extension of the “fourth” station configured for the Tandberg Centric 1700 MXP.
3.4.8	Repeat <b>Step 3.4.5</b> to administer the “fourth” station configured for the Tandberg Centric 1700 MXP. Set Hunt-to Station field to the extension of the “first” station configured for the Tandberg Centric 1700 MXP.

### 3.5. Configure H.323 Stations to Support the Tandberg Centric 150 MXP

This section describes the steps for configuring an H.323 station on Avaya Communication Manager to support the Tandberg Centric 150 MXP.

Step	Description
3.5.1	<p>Issue the command “<b>add station &lt;n&gt;</b>”, where <b>n</b> is the extension of an available station and administer settings as displayed. Repeat this step for each Tandberg Centric 150 MXP in the network.</p> <pre> add station 33611                                     Page   1 of   4                                  STATION  Extension: 33611                                Lock Messages? n           BCC: 0   Type: H.323                                Security Code: 123456       TN: 1   Port: IP                                Coverage Path 1:           COR: 1   Name: Tandberg150                       Coverage Path 2:           COS: 1  Hunt-to Station:          Tests? y  STATION OPTIONS                                  Time of Day Lock Table:       Loss Group: 19                       Message Waiting Indicator: none   Authentication Required? y                                  Survivable COR: internal       Survivable Trunk Dest? y       DTMF over IP: in-band   IP Video? y           </pre>

Step	Description
3.5.2	<p><b>[Optional]</b> Repeat <b>Step 3.5.1</b> to add the “second” station for the Tandberg Centric 150 MXP. For this sample configuration, extension 33612 was used. This second station is utilized to support a second calling line and is an optional step. Note that the Tandberg Centric 150 MXP supports a maximum of two calling lines. If this step is performed, then <b>Step 3.5.3</b> must be performed.</p>
3.5.3	<p>Issue the command “<b>change station &lt;n&gt;</b>”, where <b>n</b> is the extension of the “first” station configured for the Tandberg Centric 150 MXP and administer settings as displayed. Set the <b>Hunt-to Station</b> field to the extension of the “second” station configured for the Tandberg Centric 150 MXP.</p> <p><i><b>Note:</b> Since there are only two stations used to support the Tandberg Centric 150 MXP, it is sufficient to only administer hunting from the first station to the second station. It is not necessary to then administer the second station to hunt back to the first station. If more than two stations are used, it is necessary to complete the “loop” and administer the last station to hunt to the first station, as administered for the Tandberg Centric 1700 MXP.</i></p> <pre> change station 33611 Page 1 of 4  STATION Extension: 33611          Lock Messages? n          BCC: 0 Type: H.323              Security Code: 123456      TN: 1 Port: IP                  Coverage Path 1:           COR: 1 Name: Tandberg150         Coverage Path 2:           COS: 1                           <b>Hunt-to Station: 33612</b>      Tests? y  STATION OPTIONS Loss Group: 19            Time of Day Lock Table:                           Message Waiting Indicator: none                           Authentication Required? y  Survivable COR: internal Survivable Trunk Dest? y DTMF over IP: in-band IP Video? y </pre>

### 3.6. Configure H.323 Stations to Support the Polycom VSX 3000

This section describes the steps for configuring H.323 stations on Avaya Communication Manager to support the Polycom VSX 3000. Each Polycom VSX 3000 requires the administration of three stations in Avaya Communication Manager. Repeat the steps in this section for each Polycom VSX 3000 in the network.

Step	Description
3.6.1	Issue the command “ <b>add station &lt;n&gt;</b> ”, where <b>n</b> is the extension of an available station and administer settings as displayed.
	<pre>add station 33501                                     Page 1 of 4                                  STATION  Extension: 33501                                Lock Messages? n                BCC: 0   Type: H.323                                Security Code: 123456            TN: 1   Port: IP                                    Coverage Path 1:                COR: 1   Name: VSX 3000                            Coverage Path 2:                COS: 1  Hunt-to Station:                Tests? y  STATION OPTIONS                                  Time of Day Lock Table:                                 Message Waiting Indicator: none                                  Authentication Required? y                                  Survivable COR: internal                                 Survivable Trunk Dest? y                                 DTMF over IP: in-band                                  IP Video? y</pre>
3.6.2	Repeat <b>Step 3.6.1</b> to add the “second” station for the Polycom VSX 3000. For this sample configuration, extension 33502 was used.
3.6.3	Repeat <b>Step 3.6.1</b> to add the “third” station for the Polycom VSX 3000. For this sample configuration, extension 33503 was used.



Step	Description
3.6.4	<p>Issue the command “<b>change station &lt;n&gt;</b>”, where <b>n</b> is the extension of the “first” station configured for the Polycom VSX 3000 and administer settings as displayed. Set the <b>Hunt-to Station</b> field to the extension of the “second” station configured for the Polycom VSX 3000.</p> <pre> change station 33501 Page 1 of 4  STATION  Extension: 33501          Lock Messages? n          BCC: 0 Type: H.323              Security Code: 123456      TN: 1 Port: IP                 Coverage Path 1:          COR: 1 Name: VSX 3000           Coverage Path 2:          COS: 1                         <b>Hunt-to Station: 33502</b>      Tests? y  STATION OPTIONS  Loss Group: 19           Time of Day Lock Table:                         Message Waiting Indicator: none                          Authentication Required? y  Survivable COR: internal Survivable Trunk Dest? y DTMF over IP: in-band  IP Video? y </pre>
3.6.5	Repeat <b>Step 3.6.5</b> to administer the “second” station configured for the Polycom VSX 3000. Set Hunt-to Station field to the extension of the “third” station configured for the Polycom VSX 3000.
3.6.6	Repeat <b>Step 3.6.5</b> to administer the “third” station configured for the Polycom VSX 3000. Set Hunt-to Station field to the extension of the “first” station configured for the Polycom VSX 3000.


## 4. Tandberg Configuration

This section describes the steps for configuring the Tandberg endpoints. The configuration of the Tandberg endpoints may be administered via Control Panel Menus or the Command Line Interface (CLI). It should be noted that the Tandberg endpoints do not support DHCP Option 242, see **Section 6.2.1** for details. Therefore, the information for the H.323 gatekeeper must be input via the Control Panel Menus, or the CLI. For these Application Notes, DHCP was disabled and information regarding IP addressing was entered statically via the Control Panel Menus. Static IP addressing also simplified the assignment of the Tandberg endpoints to the correct IP network region administered on Avaya Communication. Refer to [4] and [5] for additional information regarding the administration of the Tandberg endpoints.

### 4.1. Configure the Tandberg Centric 1700 MXP

This section describes the steps for configuring the Tandberg Centric 1700 MXP.

**Figure 2** illustrates the Control Panel Menus, which are accessed using the remote control unit for the Tandberg Centric 1700 MXP. Use the appropriate buttons on the remote control unit to open the Control Panel Menus as displayed to provide static IP address parameters. Reboot to apply the changes.



**Figure 2: Tandberg Centric 1700 MXP Control Panel Menus**

Step	Description
4.1.1	Log in to the Tandberg Centric 1700 MXP via Secure Shell (SSH) with the appropriate credentials. From the CLI, enter commands as displayed.
	<i>Note: The commands of the type, “xConfiguration H323Gatekeeper Avaya” must be entered via the CLI. Optionally, the others may be entered via the Control Panel Menus on the Tandberg Centric 1700 MXP.</i>
	<pre> xConfiguration H323 Mode: On xConfiguration H323CallSetup Mode: Gatekeeper xConfiguration H323Prefix: "" xConfiguration H323Gatekeeper Discovery: Manual xConfiguration H323Gatekeeper Address: &lt;IP Address of CLAN&gt; xConfiguration H323Gatekeeper Authentication Mode: Off xConfiguration H323Gatekeeper Authentication ID: "" xConfiguration H323Gatekeeper MultipleAlias: Off xConfiguration H323Gatekeeper Avaya Mode: On xConfiguration H323Gatekeeper Avaya AnnexH: On xConfiguration H323Gatekeeper Avaya MultipointCount: 0 xConfiguration H323Gatekeeper Avaya Password: &lt;Security Code from Step 3.4.1&gt; xConfiguration Conference H323Alias E164: &lt;Station Extension from Step 3.4.1&gt; xConfiguration Conference H323Alias ID: "" </pre>
4.1.2	To apply the administrative changes, enter <b>boot</b> form the Tandberg Centric 1700 MXP CLI.
	<pre> boot  OK Boot requested, restarting </pre>

## 4.2. Configure the Tandberg Centric 150 MXP

This section describes the steps for configuring the Tandberg Centric 150 MXP.

**Figure 3** illustrates the keypad on the Tandberg Centric 150 MXP, which is used to access the Control Panel Menus. Press the button as displayed to open the Control Panel Menus. Refer to **Figure 2** for navigating to the appropriate menu to provide static IP address parameters.



**Figure 3: Tandberg Centric 150 MXP Keypad**

Step	Description
4.2.1	<p>Log in to the Tandberg Centric 150 MXP via Secure Shell (SSH) with the appropriate credentials. From the CLI, enter commands as displayed.</p> <p><i><b>Note:</b> The commands of the type, “<b>xConfiguration H323Gatekeeper Avaya</b>” must be entered via the CLI. Optionally, the others may be entered via the keypad on the Tandberg Centric 150 MXP. In particular, it should be noted that to enable multiple line appearances for the Tandberg Centric 150 MXP, the variable for the <b>xConfiguration H323Gatekeeper Avaya MultipointCount</b> is set to 2.</i></p> <pre>xConfiguration H323CallSetup Mode: Gatekeeper xConfiguration H323Gatekeeper Discovery: Manual xConfiguration H323Gatekeeper Address: &lt;IP Address of CLAN&gt; xConfiguration H323Gatekeeper Authentication Mode: Off xConfiguration H323Gatekeeper Authentication ID: "" xConfiguration H323Gatekeeper MultipleAlias: Off <b>xConfiguration H323Gatekeeper Avaya</b> Mode: On <b>xConfiguration H323Gatekeeper Avaya</b> AnnexH: On <b>xConfiguration H323Gatekeeper Avaya MultipointCount: 2</b> <b>xconfiguration H323Gatekeeper Avaya</b> Password: &lt;Security Code from Step 3.5.1&gt; xConfiguration Conference H323Alias E164: &lt;Station Extension from Step 3.5.1&gt; xConfiguration Conference H323Alias ID: ""</pre>



Step	Description
4.2.2	To apply the administrative changes, enter <b>boot</b> from the Tandberg Centric 1700 MXP CLI.
	<pre>boot OK Boot requested, restarting</pre>


## 5. Polycom VSX 3000 Configuration

This section describes the steps for configuring the Polycom VSX 3000. The configuration of the Polycom VSX 3000 may be administered via configuration screens accessed by a remote control unit or a web interface. Access the web interface from a web browser by entering **http://<IP address of the Polycom VSX 3000>** into the web browser's Uniform Resource Locator (URL) bar. Note that if Security Mode is enabled on the Polycom VSX 3000, use "https" to access the web interface. It should be noted that the Polycom VSX 3000 does not support DHCP Option 242, see **Section 6.2.1** for details. Therefore, the information for the H.323 gatekeeper must be input via the configuration screens or the web interface. For these Application Notes, DHCP was disabled and information regarding IP addressing was entered statically via the configuration screens. Static IP addressing also simplified the assignment of the Polycom VSX 3000 to the correct IP network region administered on Avaya Communication. Refer to [6] for additional information regarding the configuration presented in this section.

## 5.1. Verify Licensing


The following steps verify licensing on the Polycom VSX 3000 that is required to support the configuration described in these Application Notes. If a required feature is not enabled, contact an authorized Avaya or Polycom account representative to make the appropriate changes. The configuration presented in this section was administered via the web interface.

Step	Description
5.1.1	<p>From the <b>Admin Settings</b> tab, navigate to <b>General Settings</b> → <b>Options</b> and verify that there is a  for the Avaya option. If not, proceed to <b>Step 5.1.2</b>, otherwise, skip to <b>Section 5.2</b>.</p>  <p>The screenshot shows the Polycom VSX 3000 web interface in Microsoft Internet Explorer. The browser address bar shows 'http://192.168.12.55/u_index2.htm'. The interface has a navigation bar with tabs: 'Place a Call', 'Admin Settings', 'Diagnostics', 'Utilities', and 'Home'. The 'Admin Settings' tab is active, showing a sub-menu with 'General Settings', 'System Settings', 'Home Screen Settings', 'Sites', 'Security', 'Location', 'Date and Time', 'Options', 'Network', 'Monitors', 'Cameras', 'Audio Settings', 'LAN Properties', 'Global Services', and 'Tools'. The 'Options' sub-menu is expanded, showing a list of options: 'Multipoint', 'People+Content IP', 'Avaya', and 'PCAS'. The 'Avaya' option is checked with a green checkmark, while the others are unchecked with red X marks. The 'Key' field is highlighted with a red box and contains the value 'k7cf2ad7-5bc0-0000-0011'. An 'Update' button is visible next to the key field.</p>

Step	Description
5.1.2	<p>From the <b>Home</b> tab, navigate to <b>Tools</b> ➔ <b>System information</b> and note the <b>Serial Number</b>. Provide this serial number to an authorized Avaya or Polycom account representative. The representative will generate a <b>Key</b> that is entered in the <b>Options</b> column as displayed in <b>Step 5.1.1</b>.</p> <p><i>Note: The <b>Serial Number</b> and <b>Key</b> fields displayed in Section 5.1 are not actual values. They have been modified to illustrate licensing required for the Polycom VSX 3000 to support the configuration described in these Application Notes.</i></p> 

## 5.2. Configure the Polycom VSX 3000

This section describes the steps for configuring the Polycom VSX 3000. The configuration presented in this section was administered via the web interface.

Step	Description
5.2.1	<p>From the <b>Admin Settings</b> tab, navigate to <b>Network → IP Network</b> and administer settings as displayed. The settings highlighted were associated with configuration administered on Avaya Communication Manager in <b>Section 3</b>.</p> <p><i>Note: If required, the Polycom VSX 3000 will automatically prompt for a reboot to apply the administrative changes.</i></p> 



## 6. Interoperability Compliance Testing

### 6.1. General Test Approach

The general test approach was to verify audio/video calls between the Avaya, Tandberg and Polycom endpoints. Serviceability and performance testing was also performed to assess the reliability of the joint solution. The main objectives were to verify the following:

- Tandberg and Polycom endpoints successfully register with Avaya Communication Manager using secure Annex H Authentication
- Point-to-point video calls are successfully completed between:
  - Tandberg endpoints
  - Tandberg endpoints and Avaya IP Softphone
  - Tandberg endpoints and the Polycom VSX 3000
- Point-to-point voice-only calls are successfully completed between:
  - Tandberg endpoints and Avaya H.323, SIP, Analog and Digital telephones
- A multi-point video call is successfully established on the Tandberg Centric 1700 MXP with three other video enabled endpoints (Tandberg videoconference endpoint, Avaya IP Softphone with Video and the Polycom VSX 3000) and one Avaya telephone
- Call conferencing for both video and audio only endpoints, provided by the Tandberg and Polycom multi-point control units
- Call control features provided by Avaya Communication Manager:
  - Call transfer from an audio only endpoint to a video enabled endpoint and back to an audio only endpoint
  - Call transfer from Avaya IP Softphone to an audio only endpoint and back to a video enabled endpoint
  - Call hold/resume initiated from Avaya IP Softphone
- Codecs:
  - Audio: G.711MU, G.729A, SIREN14-48K, G.722.1-32K
  - Video: H.263, H.264
- Voice and video quality, verified subjectively using endpoints participating in a conference
- DTMF origination/termination as defined by RFC 2833
- Serviceability testing, including failures such as cable pulls, hardware and software resets

### 6.2. Test Results

All test cases, as defined by the general test approach, passed.

#### 6.2.1. Observations

The following observations were noted during testing:

- The Tandberg and Polycom endpoints do not support DHCP Option 242. This option is required in a network if there are Avaya 9600 Series Telephones present and DHCP is utilized. The work around is to statically configure the H.323 gatekeeper on the Tandberg and Polycom endpoints.

- A call to a Tandberg endpoint that is rejected by the Tandberg endpoint is not cleared properly with respect to the calling party. The calling party continues to hear ringing following the call reject invoked by the Tandberg endpoint.
- A call to a Tandberg endpoint that is set to Do Not Disturb is not handled properly with respect to the calling party. The calling party hears ringing, while the Tandberg endpoint remains in the idle state.
- The Tandberg endpoints do not support call transfer when configured for H.323.
- When the Polycom VSX 3000 is in a call with a video enabled endpoint and adds an audio only endpoint to the call, there is no audio between the video enabled endpoint and the audio only endpoint. However, both endpoints have two way audio with the Polycom VSX 3000.


## 7. Verification Steps

The following steps were used to verify the administrative steps presented in these Application Notes and are applicable for similar configurations in the field.

Step	Description																																																																																																
7.1.1	<p>Verify endpoints register with Avaya Communication Manager. Note the following:</p> <ul style="list-style-type: none"><li>• The Avaya endpoints associated with <b>33005</b> are registered to IP network region <b>1</b>.</li><li>• The three endpoints provisioned for the Polycom VSX 3000: <b>33501</b>, <b>33502</b> and <b>33503</b> are registered to IP network region <b>100</b>.</li><li>• The two endpoints provisioned for the Tandberg Centric 150 MXP: <b>33611</b> and <b>33612</b> are registered to IP network region <b>100</b>.</li><li>• The four endpoints provisioned for the Tandberg Centric 1700 MXP: <b>33621</b>, <b>33622</b>, <b>33623</b> and <b>33624</b> are registered to IP network region <b>100</b>.</li></ul>																																																																																																
	<div>list registered-ip-stations<div>Page1</div></div> <div>REGISTERED IP STATIONS</div> <table><tr><th>Station Ext/ Orig Port</th><th>Set Type</th><th>Product ID</th><th>Prod Rel</th><th>Station IP Address</th><th>Net Rgn</th><th>Gatekeeper IP Address</th><th>TCP Skt</th></tr><tr><td>33005</td><td>9620</td><td>IP_Phone</td><td>1.500</td><td>192.168.12.111</td><td>1</td><td>192.168.11.10</td><td>y</td></tr><tr><td>33005</td><td>9620</td><td>IP_Soft</td><td>5.242</td><td>192.168.12.114</td><td>1</td><td>192.168.11.10</td><td>y</td></tr><tr><td>33501</td><td>H.323</td><td>VSX 3000</td><td>0. 0</td><td>192.168.12.55</td><td>100</td><td>192.168.11.10</td><td>n</td></tr><tr><td>33502</td><td>H.323</td><td>VSX 3000</td><td>0. 0</td><td>192.168.12.55</td><td>100</td><td>192.168.11.10</td><td>n</td></tr><tr><td>33503</td><td>H.323</td><td>VSX 3000</td><td>0. 0</td><td>192.168.12.55</td><td>100</td><td>192.168.11.10</td><td>n</td></tr><tr><td>33611</td><td>H.323</td><td>Tandberg</td><td>0. 0</td><td>192.168.12.52</td><td>100</td><td>192.168.11.10</td><td>n</td></tr><tr><td>33612</td><td>H.323</td><td>Tandberg</td><td>0. 0</td><td>192.168.12.52</td><td>100</td><td>192.168.11.10</td><td>n</td></tr><tr><td>33621</td><td>H.323</td><td>Tandberg</td><td>0. 0</td><td>192.168.12.53</td><td>100</td><td>192.168.11.10</td><td>n</td></tr><tr><td>33622</td><td>H.323</td><td>Tandberg</td><td>0. 0</td><td>192.168.12.53</td><td>100</td><td>192.168.11.10</td><td>n</td></tr><tr><td>33623</td><td>H.323</td><td>Tandberg</td><td>0. 0</td><td>192.168.12.53</td><td>100</td><td>192.168.11.10</td><td>n</td></tr><tr><td>33624</td><td>H.323</td><td>Tandberg</td><td>0. 0</td><td>192.168.12.53</td><td>100</td><td>192.168.11.10</td><td>n</td></tr></table>	Station Ext/ Orig Port	Set Type	Product ID	Prod Rel	Station IP Address	Net Rgn	Gatekeeper IP Address	TCP Skt	33005	9620	IP_Phone	1.500	192.168.12.111	1	192.168.11.10	y	33005	9620	IP_Soft	5.242	192.168.12.114	1	192.168.11.10	y	33501	H.323	VSX 3000	0. 0	192.168.12.55	100	192.168.11.10	n	33502	H.323	VSX 3000	0. 0	192.168.12.55	100	192.168.11.10	n	33503	H.323	VSX 3000	0. 0	192.168.12.55	100	192.168.11.10	n	33611	H.323	Tandberg	0. 0	192.168.12.52	100	192.168.11.10	n	33612	H.323	Tandberg	0. 0	192.168.12.52	100	192.168.11.10	n	33621	H.323	Tandberg	0. 0	192.168.12.53	100	192.168.11.10	n	33622	H.323	Tandberg	0. 0	192.168.12.53	100	192.168.11.10	n	33623	H.323	Tandberg	0. 0	192.168.12.53	100	192.168.11.10	n	33624	H.323	Tandberg	0. 0	192.168.12.53	100	192.168.11.10	n
Station Ext/ Orig Port	Set Type	Product ID	Prod Rel	Station IP Address	Net Rgn	Gatekeeper IP Address	TCP Skt																																																																																										
33005	9620	IP_Phone	1.500	192.168.12.111	1	192.168.11.10	y																																																																																										
33005	9620	IP_Soft	5.242	192.168.12.114	1	192.168.11.10	y																																																																																										
33501	H.323	VSX 3000	0. 0	192.168.12.55	100	192.168.11.10	n																																																																																										
33502	H.323	VSX 3000	0. 0	192.168.12.55	100	192.168.11.10	n																																																																																										
33503	H.323	VSX 3000	0. 0	192.168.12.55	100	192.168.11.10	n																																																																																										
33611	H.323	Tandberg	0. 0	192.168.12.52	100	192.168.11.10	n																																																																																										
33612	H.323	Tandberg	0. 0	192.168.12.52	100	192.168.11.10	n																																																																																										
33621	H.323	Tandberg	0. 0	192.168.12.53	100	192.168.11.10	n																																																																																										
33622	H.323	Tandberg	0. 0	192.168.12.53	100	192.168.11.10	n																																																																																										
33623	H.323	Tandberg	0. 0	192.168.12.53	100	192.168.11.10	n																																																																																										
33624	H.323	Tandberg	0. 0	192.168.12.53	100	192.168.11.10	n																																																																																										

Step	Description
7.1.2	<p>Verify the endpoints administered in these Application Notes can originate/terminate audio/video calls. The following scenario will provide a basis for verifying the administration presented in these Application Notes.</p> <ul style="list-style-type: none"> <li>Place a call from the Tandberg Centric 150 MXP to the Polycom VSX 3000.</li> <li>If the call completes, obtain status on the call from Avaya Communication Manager by issuing the command “<b>status station &lt;n&gt;</b>”, where <b>n</b> is the extension of the Tandberg Centric 150 MXP. Note the items as displayed with boldface type.</li> </ul>
	<pre> status station 33611 Page 1 of 7  GENERAL STATUS Administered Type: H.323      Service State: in-service/off-hook Connected Type: N/A          TCP Signal Status: not connected Extension: 33611 Port: S00015                 Parameter Download: not-applicable Call Parked? no             SAC Activated? no Ring Cut Off Act? no Active Coverage Option: 1  EC500 Status: N/A           Off-PBX Service State: N/A Message Waiting: Connected Ports: S00019  Limit Incoming Calls? no  User Cntrl Restr: none Group Cntrl Restr: none  HOSPITALITY STATUS Awaken at: User DND: not activated Group DND: not activated Room Status: non-guest room </pre>
7.1.3	<p>Proceed to Page 4 and note the items as displayed with boldface type.</p>
	<pre> status station 33611 Page 4 of 7  AUDIO CHANNEL Port: S00015 G.711MU      Switch-End Audio Location: IP Address Other-End: 192.168. 12. 55      Port  Node Name      Rgn Set-End: 192.168. 12. 52      49270      100 Audio Connection Type: ip-direct 2326      100 </pre>

Step	Description
7.1.4	<p data-bbox="297 268 1510 378">Call statistics are also obtained from the Tandberg Centric 150 MXP by issuing the command “<b>xstatus Call</b>” from the Tandberg Centric 150 MXP CLI. Utilizing the call from <b>Step 7.1.2</b>, the following statistics are displayed.</p> <pre data-bbox="297 415 1510 1522"> <b>xstatus call</b>  *s Call 1 (status=Synced, type=Vtlph, protocol=H323, direction=Outgoing, logTag=3):   CallRate: 512   RemoteNumber: "33501"   Mute: Off   Microphone: On   Duration: 74   Channels 1 (type=Incoming):     Rate: 512     Restrict: Off     Encryption (status=Off): /     Audio (status=Active):       Protocol: G711       Rate: 64     Video 1 (status=Active):       Protocol: H264       Resolution: SIF       Rate: 448     Video 2 (status=Inactive): /     Data (status=Inactive): /   Channels 2 (type=Outgoing):     Rate: 512     Restrict: Off     Encryption (status=Off): /     Audio (status=Active):       Protocol: G711       Rate: 64     Video 1 (status=Active):       Protocol: H264       Resolution: SIF       Rate: 448     Video 2 (status=Inactive): /     Data (status=Inactive): / *s/end  *s Call 2 (status=Disconnected, type=NA, protocol=NA, direction=NA, logTag=NA):   Cause: 16 *s/end  OK </pre>

Step	Description
7.1.5	<p>Call statistics are also obtained from the Polycom VSX 3000 web interface. From the <b>Diagnostics</b> tab, navigate to <b>System Status</b> → <b>System Status</b> and click <b><u>In a Call</u></b>.</p> 

Step	Description
7.1.6	Utilizing the call from <b>Step 7.1.2</b> , note the statistics as displayed in the <b>Call Statistics</b> screen.

Call speed, audio and video protocols, annexes, and error count for the call in progress.

Call	Call Type:	Speed	Far Site	Call Status
1	h323	512	Tandberg150	

**Transmit**

512 K	
H.264	
---	
SIF	
G.711U	
0	
0.0 %	
Disabled	
Tandberg150	
82010100/Tandberg/50	
192.168.11.10	
H.323	
64 K	64 K
448 K	448 K
128 K	95 K
29.9	29.8
0	0
9 ms	4 ms
0	0
0 ms	0 ms
0	

**Receive**

512 K
H.264
---
SIF
G.711U
0
0.0 %

## 8. Conclusion

These Application Notes presented a compliance-tested solution comprised of Tandberg, Polycom and Avaya endpoints with Avaya Communication Manager. This solution enables connectivity between the aforementioned endpoints and Avaya Communication Manager via H.323 signaling.

## 9. Additional References

Avaya references are available at <http://support.avaya.com>.

- [1] *Administrator Guide for Avaya Communication Manager*, Issue 3.1, Doc ID: 03-300509, February 2007.
- [2] *Administration for Network Connectivity for Avaya Communication Manager*, Issue 12, Doc ID: 555-233-504, February 2007.
- [3] *IP Softphone Release 6.0 User Reference*, Issue 1, Doc ID: N/A, May 2007

Tandberg references are available at: <http://www.tandberg.com/>.

- [4] *Tandberg MXP Administrator's Guide (F6)*, Doc ID: 0 D14033.01, March 2007.
- [5] *Tandberg 150MXP Administrator's Guide (L5)*, Doc ID: 0 D14061.01, May 2007.

Polycom references are available at: <http://www.polycom.com/>.

- [6] *Administrator's Guide for the VSX Series Version 8.5.3*, Doc ID: 3725-20235-011/A, February 2007.

---

**©2008 Avaya Inc. All Rights Reserved.**

Avaya and the Avaya Logo are trademarks of Avaya Inc. All trademarks identified by ® and ™ are registered trademarks or trademarks, respectively, of Avaya Inc. All other trademarks are the property of their respective owners. The information provided in these Application Notes is subject to change without notice. The configurations, technical data and recommendations provided in these Application Notes are believed to be accurate and dependable, but are presented without express or implied warranty. Users are responsible for their application of any products specified in these Application Notes.

Please e-mail any questions or comments pertaining to these Application Notes along with the full title name and filename, located in the lower right corner, directly to the Avaya DevConnect Program at [devconnect@avaya.com](mailto:devconnect@avaya.com).