


MECH 423 Lecture 23

Printed Circuit Boards (PCB)



- * PCBs are not for DIY
- * Do not skip the soldermask
- * Cost: \$200-500 per run

CAD Tools

Protel (Altium Designer) — PCB Artist
OrCAD
EAGLE (free)

CAD Process

Schematic Capture

Output: Netlist (Net - electrical node)

PCB Layout

- Place components
- Draw copper traces

- Layout - versus - schematic (LVS)

Library

Schematic

PCB

Part (connects sch to PCB)

- Design Rule Check (DRC)

- Output: Gerber file:

- Signal wires
- Power wires
- Add vias
- Pour ground plane

- Copper layers
- Solder mask layer (inverse)
- Screen printing
- paste

Notes on development Process


* Plan for > 1 iteration

* First make "mule" board


↳ Not in the final form-factor
↳ Easy to debug.

* Embrace zero ohm resistors


Goal of soldering: Get the solder to wet on metal



Good solder joint



Why soldering is difficult: We have only 2 arms, not 4




① Tin wire 1 (melt solder on wire 1)

② Tin wire 2

③ Take the solder away, press wire 1 & 2 together


Components

Through hole



Surface mount (SMT)

$L = 120 \text{ mil}$
 $W = 60 \text{ mil}$
 1206
 0805




103 = 10k

of zeros

First 2 digits


0603 ← Min size
 0402 for hand soldering.
 0201

- Not every component can be hand soldered.




Ball grid arrays

Soldering SMT components



- ① Tin pad #1
- ② Install component, heat up pad.
- ③ Use tweezers to align component while solder is hot
- ④ Add solder to pad #2.



- ① Put solder on pad #1
- ② Add the part
- ③ Align w/ tweezers
- ④ Apply solder to all other pads
- ⑤ Use solder braid pads to remove solder bridges

1 2 3 4