





# Road Safety Intervention Report



**Prof Venkatesh Balasubramanian, PhD**  
*RBG Labs, Department of Engineering Design*  
*IIT Madras, Chennai 600036*  
**Email:** [chanakya@iitm.ac.in](mailto:chanakya@iitm.ac.in)





## Road Safety Intervention Report CoERS, IIT Madras

**Table 1 Road Safety Intervention Report**

<b>A Road Sign</b>				
<b>1</b>	4+200 LHS MCW		<ul style="list-style-type: none"> <li>➤ The speed limit sign is absent before the academic zone.</li> </ul>	<ul style="list-style-type: none"> <li>➤ The maximum speed limit sign shall be provided for the school zone as per clause 14.8.8 of IRC:67-2022.</li> </ul>
<b>2</b>	4+250 LHS MCW		<ul style="list-style-type: none"> <li>➤ The school ahead sign provided on MCW is non-standard</li> </ul>	<ul style="list-style-type: none"> <li>➤ The non-standard school ahead sign shall be replaced by the standard sign as per clause 15.28 of IRC: 67-2022.</li> </ul>
<b>3</b>	4+425 LHS MCW		<ul style="list-style-type: none"> <li>➤ Fuel station ahead sign board absent.</li> </ul>	<ul style="list-style-type: none"> <li>➤ Informatory fuel pump sign shall be installed as per clause 17.7 of IRC: 67-2022.</li> </ul>
<b>4</b>	4+550 LHS MCW		<ul style="list-style-type: none"> <li>➤ The side road ahead sign is absent on MCW.</li> </ul>	<ul style="list-style-type: none"> <li>➤ Side road ahead sign shall be installed as per clause 15.9 of IRC: 67-2022.</li> </ul>





## Road Safety Intervention Report

CoERS, IIT Madras

5	4+580 LHS MCW		➤ The side road ahead sign is absent on MCW.	➤ A side road ahead sign shall be installed as per clause 15.9 of IRC: 67-2022.
6	4+550 RHS MCW		➤ No Parking sign provided near the market is non-standard.	➤ The Non-standard No Parking sign shall be replaced with a standard sign as per clause 14.7.5 of IRC: 67-2022.
7	304+650 LHS MCW		➤ Pedestrian crossing sign missing before the approach of the installed pedestrian crossing.	➤ Pedestrian crossing sign shall be provided before the approach of the installed pedestrian crossing to warn the drivers about its presence, as per clause 15.27 of IRC:67-2022.
8	305+770 LHS MCW		➤ Pedestrian crossing sign missing before the approach of the provided pedestrian crossing.	➤ Pedestrian crossing sign shall be provided before the approach of the installed pedestrian crossing to warn the drivers about its presence, as per clause 15.27 of IRC:67-2022.





## Road Safety Intervention Report

CoERS, IIT Madras

B Road Marking				
1	4+100 LHS MCW		<ul style="list-style-type: none"> <li>➤ Longitudinal markings are faded on the MCW for about 200m near the college.</li> </ul>	<ul style="list-style-type: none"> <li>➤ The longitudinal markings (edge lines and lane markings) shall be repainted to make them clear during the day and retroreflective in the nighttime as per clause 3.1 of IRC:35-2015.</li> </ul>
2	246+750 RHS MCW		<ul style="list-style-type: none"> <li>➤ Pedestrian crossing provided on the median opening is faded (3.5 m width for each lane on four lane divided highway).</li> </ul>	<ul style="list-style-type: none"> <li>➤ Faded pedestrian crossing needs to be repainted as per clause 11.3 of IRC:35-2015.</li> </ul>
3	304+500 to 304+600 LHS & RHS MCW		<ul style="list-style-type: none"> <li>➤ The provided road studs were non retroreflective.</li> </ul>	<ul style="list-style-type: none"> <li>➤ New retroreflective Red-White Bidirectional road studs shall be provided on the edge line as per clause 5.4.6 and Table 5.1 of IRC:35-2015.</li> </ul>
4	361+500 & 361+750 RHS MCW		<ul style="list-style-type: none"> <li>➤ Pedestrian crossing marking is missing near the school zone.</li> </ul>	<ul style="list-style-type: none"> <li>➤ Pedestrian crossing markings across the road shall be provided as per clause 9.8.4 of IRC:SP:73-2018 and painted as per clause 11.3 of IRC:35-2015.</li> </ul>


## Road Safety Intervention Report

### CoERS, IIT Madras

<b>C Pavement Condition</b>				
1	305+850 LHS Side Road		➤ Pothole of area 2.5 sqm and 20 mm depth was observed on the side road and waterlogging was also observed.	➤ Potholes shall be treated for smooth and safe movement of vehicles and prevent waterlogging which could damage the pavement as per clause 7.5.3.5 of IRC:82-2023.
<b>D Traffic signal</b>				
1	100+300 LHS MCW		➤ Solar blinker provided at the median notch is not in working condition.	➤ Solar blinkers shall be repaired and maintained at the median notch as per clause 4.2 of IRC: 93-1985 to enhance the delineation and alert the road user.
<b>E Facilities</b>				
1	305+100 LHS & RHS MCW		➤ The entire stretch lacks proper lighting facilities for illumination.	➤ The entire stretch shall be provided with streetlights for better nighttime visibility, as per clause 12.4 of IRC:SP:73-2018.
<b>F Roadside Furniture</b>				
1	304+950 LHS & RHS MCW		➤ FMM was found missing for the minor bridge of 16 m length.	➤ FMM shall be provided at the minor bridge for nighttime delineation as per clause 4 of IRC:79-2019.

## Road Safety Intervention Report

CoERS, IIT Madras

2	362+380 to 362+500 LHS MCW		➤ Delineators are missing for the curve section.	➤ The roadside shall be provided with roadway indicators (Delineators or Guide Poles) for better nighttime delineation as per clause 3 of IRC:79-2019.
---	--	---	--	--



## Header

*CoERS, IIT Madras*

---

