

Four/Five Axis TB6560 CNC Driver Users Manual

Revision 2.0

Univelop Comp. Tech. LLC.
<http://www.cncgeeker.com>

Oct. 16. 2009

Content

1. GENERAL INFORMATION	3
1.1. Scope	3
1.2. General Description	3
1.3. Key Features	3
2. Descriptions of 4/5-AXIS CNC Board	4
2.1. Photo of 4/5-AXIS CNC Boards	4
2.2. Key Features	4
2.3. Electrical Characteristics (recommend)	4
3. Hardware Installation	5
3.1. Board Connection	5
3.2. Board Configuration	7
3.3. CONNECTING POWER SUPPLY TO DRIVE BOARD	7
3.4. SELECTING AND CONNECTING STEPPER MOTORS	7
3.5. CONNECTING with Computer by DB25	9
3.6. Manual Control (Optional)	10
3.7. Limit Signals	10
3.8. Setup Checklist	10
Appendix	10
A. Change the preset current of the board by changing the value of R12/R13, R22/R23, R32/R33	10

1. GENERAL INFORMATION

1.1. Scope

This document describes the basic functionality and the electrical specifications of Univelop Tech. LLC's Four/Five Axis TB6560 CNC Driver Boards.

1.2. General Description

Univelop Tech. LLC's Four Axis CNC Driver Board is designed to communicate directly with KCAM4, MACH 2/3, NINOS, etc..., which supports parallel port.

1.3. Key Features

- Supports KCAM4, MACH 2/3, NINOS, etc...
- Two phase bipolar (chopper) pulse width modulating technology
- Resolution 1, 1/2, 1/8, 1/16 micro stepping output
- Suitable for 4, 6, or 8 wire motors
- Absolute Maximum Ratings: 40VDC @ 3.5 amps(peak) /phase motor output*
- Current adjustable at 100%, 75%, 50%, 20% of full current by on-board switch**
- Voltage regulator is on board for TB6560
- Stop Button for emergency stop
- Limit/Home Signal input
- Manual Control Module is available (Optional)
- Step Current® Technology is included: Step Current® technology is used to decrease the current up to 1/2, when motors are in idle for all axis so as to protect expensive step motor and driver board for long time running.
- Built-in **overheat protection** circuit
- Discrete board design

Comparison between Univelop V 2.0 (TB6560) CNC driver and V 1.0 (TA7835) CNC driver board:

	V 1.0 (TA7835)	V 2.0 (TB6560)
IC Overheat protection	N/A	Built-in
Current Adjustable	100%/50%	100%/75%/50%/20%
Current for motor	Peak 2.5A	Peak 3.5A [*,**]
Voltage for motor	Max 35V	Max 40V [*,**]
Micro stepping	1 – 1/8	1 – 1/16
Frequency (f _{osc})	Max 80khz	Max 600khz
Chip manufactory	Old technology	Current technology, ,makes IC chips get less heat at the same current

* See TB6560 Datasheet (2007) by TOSHIBA

** The full current is preset at 2.5A by R12/R13 (0.2ohm) for this board (you can adjust it by changing resister).

2. Descriptions of 4/5-AXIS CNC Board

2.1. Photo of 4/5-AXIS CNC Boards




Fig. 1 Four/Five Axis CNC Interface Board
Dimension: 100mm X 50mm.




Fig. 2 1-Axis CNC Driver Board
Dimension: 100mm X 58mm.

2.2. Key Features

2.3. Electrical Characteristics (recommend)


Symbol	Parameter	Min	Typical	Max	Units
T_{STR}	Storage Temperature	- 40		+150	°C
T_{OP}	Working Temperature	- 15	+ 25	+ 85	°C
I_{CC}	Current	50	100	200	MA
+12V	Motor Voltage	5	24	34 [*]	V
+7V	Board Voltage	7	9	12	V

3. Hardware Installation


3.1. Board Connection

Use four 6-pin cables to connect the interface board and four 1-axis driver boards, if it is 4-axis CNC driver module. Use five 6-pin cables to connect the interface board and five 1-axis driver boards, if it is 5-axis CNC driver module.


4-Axis Connection:



5-Axis Connection:



UNVELOP Four/Five Axis TB6560 CNC Driver Board V2.0 Users Manual



Pin configuration for connection

Pin		
CW	Voltage to switch direction	2V-5V(10ma) as High, <1V as low
GND	GND	
CK	CK	Input pulse to drive motor (max 25Khz)

3.2. Board Configuration

1-Axis CNC Driver Board:

P11: Step Current® Technique:


P11	
1-2	StepCurrent
2-3	Normal

S1-1	-2	
M2	M1	step/i
OFF	OFF	1
OFF	ON	2
ON	OFF	16
ON	ON	8

-3	-4	
DCY2	DCY1	Decay
OFF	OFF	0%
OFF	ON	25%
ON	OFF	50%
ON	ON	100%

S2: -2	-1	
TQ2	TQ1	I
OFF	OFF	100%
OFF	ON	75%
ON	OFF	50%
ON	ON	20%

LEDs and Fan connection on board:



P1	D2	D6	D5	D1
5V Fan connection	Power	Init.	OverHeat	StepCurrent

3.3. CONNECTING POWER SUPPLY TO DRIVE BOARD

1. Connect suitable power supply at Input outlet on front of controller
 +7V and GND is connected with a power supply with >+7V and 1amp.
 +12V and GND is connected with a power supply with >+12V and 1-6amp. 12-34v DC
 @ 2-6amp switching power supply recommended

3.4. SELECTING AND CONNECTING STEPPER MOTORS


WARNING: INCORRECT WIRING OF THE STEPPER MOTOR TO THE DRIVE BOARD CAN LEAD TO IMMEDIATE DAMAGE OF DRIVE BOARD - DO NOT CONNECT OR DISCONNECT MOTORS WHILE POWER IS ON

4 Wire, 6 Wire, and 8 Wire stepper motors can be used with 3-AXIS CNC Board. 4 Wire motors are recommended as they are by their manufacture true bipolar motors and

UNIVELOP Four/Five Axis TB6560 CNC Driver Board V2.0 Users Manual


easier to properly connect to stepper motor drive controller It is critical to obtain a proper motor coil diagram of any motor you wish to utilize (making cross connections between the two coils will destroy the control circuitry) 1.8 deg per step resolution is the industry standard for most automation grade stepper motors and is recommended for most applications

4 WIRE STEPPER DIAGRAM



Each wire is connected to its corresponding terminal block location (i.e. A# wire is connected at A- location)


6 WIRE STEPPER DIAGRAM (SERIES WIRING)



Center wire of each coil not connected (insulate termination)

Remaining wires are connected to their corresponding terminal block location (i.e. A# wire is connected at A- location).

8 WIRE STEPPER DIAGRAM




2 center wires of each coil connected (insulate connection) Remaining wires are connected to their corresponding terminal block location (i.e. A# wire is connected at A- location).

If using 6 or 8 wire motors, connected using series wiring method, reduce labeled amperage rating by **50%** (i.e. a motor rated at 4 amps should thus be considered now rated at 2 amps)

3.5. CONNECTING with Computer by DB25

The following is to aid in the setup of the use of controller with various CAM software programs operating on your computer.



DB25 PIN USAGE:

4 Axis Configurations

	X	Y	Z	A
CK (out)	2	4	6	8
CW/CCW (out)	3	5	7	9
Limit (in)	15	11	12	13
Stop (in)	10			

* Pins 18-25 of DB25 are GND.

5 Axis Configurations

	X	Y	Z	A	C
CK (out)	2	4	6	8	17
CW/CCW	3	5	7	9	16

UNIVELop Four/Five Axis TB6560 CNC Driver Board V2.0 Users Manual

(out)					
Limit (in)	15	11	12	13	
Stop (in)	10				

* Pins 18-25 of DB25 are GND.

It is critical that the connection between computer parallel port and motor drive board be direct with the use of adapters (If your computer does not feature a DB25 outlet, you must install one, (these can be achieved via PCMCIA cards on laptop computers)) The use of adapters and hubs is not advisable and most likely will not work.

3.6. Manual Control (Optional)

3.7. Limit Signals

P2: Option Signal Input

P3: Emergence Stop

P4: Limit A

P5: Limit Z

P6: Limit Y

P7: Limit X

	X	Y	Z	A	C
Limit (in)	15	11	12	13	
Stop (in)	10				

3.8. Setup Checklist

- Setup output pin configuration on chosen control software.
- Setup pins in the boards
- Connect power supply to stepper board (make sure power is turned off)
- Connect stepper motors
- Connect Parallel cable between computer and controller
- Turn power on
- Attempt to jog each axis with software (if axis turns in opposite direction of desired direction - attempt axis rotation reversal via software- if unable to do so switch 2 wires for one coil (i.e. switch A with A#, do not switch wires between coils)
- You are now done and able to begin using your new stepper motor drive
- **REMEMBER NEVER CONNECT OR DISCONNECT MOTORS WHILE POWER IS ON**

Appendix

A. Change the preset current of the board by changing the value of R12/R13, R22/R23, R32/R33

The value of $I_{out}(A) = 0.5V/R12(Ohm)$, $I_{out}(A) = 0.5V/R13(Ohm)$. The peak of I_{out} can't be exceed 3.5A.