

Unit - III

3.4 Ideal Transformer, Losses and Efficiency

Dr.Santhosh.T.K.

World's Largest Transformer



- SIEMENS's transformer factory in Nuremberg (Germany) to China
- 1,100KV transformer for the world's largest HVDC project in China
- capacity of 587 MVA
- Transformer size: 37.5 x 12 x 14.4 (m)
- Weight ~ 900 tons



Syllabus


UNIT – III

10 Periods

Principles of Electro Magnetics and Electro-mechanics: Electricity and Magnetism - magnetic field and faraday's law - self and mutual inductance - Ampere's law - Magnetic circuit - Magnetic material and B-H Curve – Single phase transformer - principle of operation - EMF equation - voltage ratio - current ratio – KVA rating - Electromechanical energy conversion – Elementary generator and motors.



Ideal Transformers

- **Zero leakage flux:**
 - Fluxes produced by the primary and secondary currents are confined within the core
- **The windings have no resistance:**
 - Induced voltages equal applied voltages
- **The core has infinite permeability**
 - Reluctance of the core is zero
 - Negligible current is required to establish magnetic flux
- **Loss-less magnetic core**
 - No hysteresis or eddy currents



Symbol for ideal transformer

Ideal transformer



V_1 – supply voltage ;
 V_2 – output voltage;
 I_m – magnetising current;
 E_1 – self induced emf ;

I_1 – no load input current ;
 I_2 – output current
 E_2 – mutually induced emf

Transformer Equations

Using Faraday's law, expressions for the primary and secondary voltages is as follows.

$$V_2 = N_2 \frac{d\Phi}{dt}.$$

$$V_1 = N_1 \frac{d\Phi}{dt}.$$

Dividing the above equations we get,

$$\frac{V_2}{V_1} = \frac{N_2}{N_1}.$$

Assuming that there is no power loss,

$$V_2 I_2 = V_1 I_1.$$

$$\frac{V_2}{V_1} = \frac{I_1}{I_2} = \frac{N_2}{N_1} = K. \quad \text{K - transformation ratio}$$

EMF Equation of a transformer

Let N_1 = No. of primary turns

N_2 = No. of secondary turns

Φ_m = Maximum flux density in transformer core in Weber

= $B_m A$ where B_m -> flux density in the transformer core

A -> cross sectional Area of the transformer

In an EMF equation, flux increases from its zero value to maximum value Φ_m in one quarter of cycle

$$\text{Average rate of change of flux} = \Phi_m / (1/4f) = 4f \Phi_m \text{ wb/sec} \quad \dots\dots(1)$$

$$\text{The average value of emf induced / turn} = 4f \Phi_m \quad \dots\dots(2)$$

If flux Φ_m varies sinusoid ally, then R.M.S value of induced EMF is obtained by multiplying the average value with form factor.

EMF Equation of a transformer -contd

$$\begin{aligned}\text{Form factor} &= \text{R.M.S value} / \text{Average value} = \frac{V_m / \sqrt{2}}{2V_m / \pi} \quad \text{.....(3)} \\ &= 1.11 \text{ (for sine wave)}\end{aligned}$$

$$\text{R.M.S value of EMF/turn} = 1.11 * 4f\Phi_m \text{ volts} \quad \text{.....(4)}$$

Now,


R.M.S value of the induced EMF in the whole primary winding =
(induced EMF/turn)*No of primary turns.

$$E_1 = 4.44fN_1\Phi_m \quad \text{.....(5)}$$

Illy,

$$E_2 = 4.44fN_2\Phi_m \quad \text{.....(6)}$$

Transformer



EMF equation of transformer - contd

If i_p is sinusoidal, the flux produced also sinusoidal, i.e

$$\Phi = \Phi_m \sin 2\pi ft \quad \dots\dots(7)$$

therefore
$$v_1 = N_1 \frac{d(\Phi_m \sin 2\pi ft)}{dt}$$

$$v_1 = N_1 2\pi f \Phi_m \cos 2\pi ft = N_1 2\pi f \Phi_m \sin (2\pi ft + \pi/2) \quad \dots\dots(8)$$

$$\text{The peak value} = V_{pm} = N_1 2\pi f \Phi_m \quad \dots\dots(9)$$

and v_1 is leading the flux by $\pi/2$.

$$\text{The rms value } V_1 = \frac{V_{1m}}{\sqrt{2}} = 0.707 \times N_1 2\pi f \Phi_m = 4.44 N_1 f \Phi_m \quad \dots\dots(10)$$

Voltage regulation of Transformer

$$\text{Voltage regulation} = \frac{\text{no - load voltage} - \text{full - load voltage}}{\text{no - load voltage}}$$

$$\text{recall } \frac{V_s}{V_p} = \frac{N_s}{N_p}$$

$$\text{Secondary voltage on no-load } V_2 = V_1 \left(\frac{N_2}{N_1} \right)$$

V_2 is a secondary terminal voltage on full load

Substitute we have

$$\text{Voltage regulation} = \frac{V_1 \left(\frac{N_2}{N_1} \right) - V_2}{V_1 \left(\frac{N_2}{N_1} \right)}$$

Transformer Efficiency

Transformer efficiency is defined as (applies to motors, generators and transformers):

$$\eta = \frac{P_{out}}{P_{in}} \times 100\%$$

$$\eta = \frac{P_{out}}{P_{out} + P_{loss}} \times 100\%$$

Types of losses incurred in a transformer:

- Copper I^2R losses

- Hysteresis losses

- Eddy current losses

Therefore, for a transformer, efficiency may be calculated using the following:

$$\eta = \frac{V_S I_S \cos \theta}{P_{Cu} + P_{core} + V_S I_S \cos \theta} \times 100\%$$

All day efficiency


All day efficiency is defined as the ratio of total energy output of transformer to the total energy input in 24 hours.

$$\text{ordinary commercial efficiency} = \frac{\text{out put in watts}}{\text{input in watts}}$$

$$\eta_{all\ day} = \frac{\text{output in kWh}}{\text{Input in kWh}} \text{ (for 24 hours)}$$

- All day efficiency is always less than the commercial efficiency


Transformer with conservator and breather




Parts of a transformer

- Conservator
 - Oil is stored in the conservator
 - It prevents the oil from moisture contact in air during the expansion and contraction.
- Breather
 - It is a device which contains silica gel crystals.
 - The gel absorbs the moisture in the atmosphere when the oil expands and contracts.
- Explosive Vent
 - It bursts when pressure inside the transformer becomes excessive and protects the transformer from damage.
- Transformer Tank filled with transformer Oil

Transformer-No load condition




Phasor diagram: Transformer on No-load



(a) Transformer on no-load (b) Phasor diagram of a transformer on no-load


Transformer – On load condition



Transformers

Given that the intermediate current is 1 A, what is the current through the lightbulb?

- 1) $\frac{1}{4}$ A
- 2) $\frac{1}{2}$ A
- 3) 1 A
- 4) 2 A
- 5) 5 A



Transformers

Given that the intermediate current is 1 A, what is the current through the lightbulb?

1) $1/4$ A

2) $1/2$ A

3) 1 A


4) 2 A

5) 5 A

Power in = Power out

$$240 \text{ V} \times 1 \text{ A} = 120 \text{ V} \times ???$$

The unknown current is 2 A.




Transformers

A 6 V battery is connected to one side of a transformer.

Compared to the voltage drop across coil A, the voltage across coil B is:

- 1) greater than 6 V
- 2) 6 V
- 3) less than 6 V
- 4) zero




Transformers

A 6 V battery is connected to one side of a transformer. Compared to the voltage drop across coil A, the voltage across coil B is:

- 1) greater than 6 V
- 2) 6 V
- 3) less than 6 V
- 4) zero

The voltage across B is zero.
Only a **changing** magnetic flux induces an emf. Batteries can provide only **dc current**.



1. A 250 kVA, 11 000 V/400 V, 50 Hz single-phase transformer has 80 turns on the secondary. Calculate: (a) the approximate values of the primary and secondary currents; (b) the approximate number of primary turns; (c) the maximum value of the flux.

2. The maximum flux density in the core of a 250/3000-volt, 50 Hz transformer is 1.2 Wb/m^2 . If the EMF per turn is 8 V, determine (i) primary and secondary turns

Voltage regulation of Transformer

$$\text{Voltage regulation} = \frac{\text{no - load voltage} - \text{full - load voltage}}{\text{no - load voltage}}$$

recall $\frac{V_s}{V_p} = \frac{N_s}{N_p}$

Secondary voltage on no-load $V_2 = V_1 \left(\frac{N_2}{N_1} \right)$

V_2 is a secondary terminal voltage on full load

Substitute we have

$$\text{Voltage regulation} = \frac{V_1 \left(\frac{N_2}{N_1} \right) - V_2}{V_1 \left(\frac{N_2}{N_1} \right)}$$

Transformer Efficiency

Transformer efficiency is defined as (applies to motors, generators and transformers):

$$\eta = \frac{P_{out}}{P_{in}} \times 100\%$$

$$\eta = \frac{P_{out}}{P_{out} + P_{loss}} \times 100\%$$

Types of losses incurred in a transformer:

- Copper I^2R losses

- Hysteresis losses

- Eddy current losses

Therefore, for a transformer, efficiency may be calculated using the following:

$$\eta = \frac{V_S I_S \cos \theta}{P_{Cu} + P_{core} + V_S I_S \cos \theta} \times 100\%$$

Losses in a transformer

Core or Iron loss:

$$W_h = \eta B_{max}^{1.6} f V \text{ watt}$$

$$W_e = \eta B_{max}^2 f^2 t^2 \text{ watt}$$

Copper loss:

$$\text{Total Copper loss} = I_1^2 R_1 + I_2^2 R_2$$


4. In a 25-kVA, 2000/200 V single phase transformer, the iron and full-load copper losses are 350 and 400 W respectively. Calculate the efficiency at unity power factor at full load.

5. In a 25-kVA, 2000/200 V single phase transformer, the iron and full-load copper losses are 350 and 400 W respectively. Calculate the efficiency with unity power factor at half full-load.

Summary

- Ideal Transformer
- Problems
 - EMF equation
 - Magnetic Circuits
 - Efficiency
 - Losses

3. A transformer core made of annealed steel sheet has the form and dimensions shown in Figure. A coil of N turns is wound on the central limb. The average length of magnetic circuit (i.e. path ABCDA or path EFGHE) is 30 cm. Determine the ampere-turns of the coil required to produce a flux density of 1 Wb/m^2 in the central leg. What will be the total amount of flux in the central leg and in each outside leg? Given that for annealed sheet steel (from B-H curve), $H = 200 \text{ AT/m}$ at 1 Wb/m^2 .




(a) Ampere - turns ✓

(b) flux

parallel magnetic circuit

$$H \cdot l = NI \leftarrow AT$$

$$200 \times 30 \times 10^{-2} = AT$$



$$B_c = 1 \text{ wb/m}^2$$

$$B = \frac{\Phi}{A}$$

$$\Phi = B \times A$$

$$\begin{aligned} \text{Area of central leg} &= 6 \times 10^{-2} \times 6 \times 10^{-2} \\ &= 0.0036 \text{ m}^2 \end{aligned}$$

$$\Phi_c = 1 \times 0.0036$$

$$\Phi_c = 0.0036 \text{ wb}$$

$$\Phi_o = \frac{0.0036}{2} = 0.0018 \text{ wb}$$

$$\begin{aligned} (a) \Rightarrow AT &= (H) l \\ &= 200 \times 30 \times 10^{-2} \\ &= 60 \text{ AT} \end{aligned}$$

$$\begin{aligned} \text{Area} &\Rightarrow 0.03 \times 0.06 \\ &\Rightarrow \end{aligned}$$