

Flag Clearing Issue in UART IIR Registers

ET Rev. 1.00

Introduction

Among the flags in the UARTn_IIR Register, TXE and DMA RX Complete flags are sometimes cleared regardless of user intent.

This document explains why unintentional “Clear” issues occur and provides software solutions to prevent them.

This document applies to the devices listed in Table 1.

Table 1. Device Identification

Base Product	Part Number
AC30M1xxx	AC30M1464LBN, AC30M1364LBN, AC30M1364UB, AC30M1332LBN, AC30M1332UB
A31G21x	A31G213CL, A31G213SQ, A31G213KN, A31G213KU, A31G213GR, A31G212CL, A31G212SQ, A31G212KN, A31G212KU, A31G212GR
A31T21x	A31T216RL, A31T216CL, A31T216SN, A31T214RL, A31T214CL, A31T214SN, A31T214IU, A31T216RL2, A31T216CL2, A31T216SN2, A31T214RL2, A31T214CL2, A31T214SN2, A31T214IU2
A31G22x	A31G226ML2, A31G226MM2, A31G226RM2, A31G226RL2, A31G226CL2, A31G224MM2, A31G224ML2, A31G224RM2, A31G224RL2, A31G224CL2, A31G226ML, A31G226MM, A31G226RM, A31G226RL, A31G226CL, A31G224MM, A31G224ML, A31G224RM, A31G224RL, A31G224CL,
A31G31x	A31G316MM, A31G316ML, A31G316RM, A31G316RL, A31G314MM, A31G314ML, A31G314RM, A31G314RL, A31G314CL, A31G314CU, A31G314SN, A31G313RM, A31G313RL, A31G313CL, A31G313CU, A31G313SN
A31M22x	A31M223CL2N, A31M223KN2N, A31M223GR2N
A33Mx064	A33M3064LB, A33M4064LB
AC33Mx128	AC33M8128, AC33M8128L, AC33M6128L
A33M11x	A33M116RL, A33M116RM, A33M114RL, A33M116CL, A33M114CL, A33M114SN
A34M41x	A34M418YL, A34M418VL, A34M418RL, A34M416VL, A34M416RL, A34M414VL, A34M414RL,
A34M420	A34M420YL, A34M420VL, A34M420RL
A34M456	A34M456VL, A34M456RL
A34L716	A34L716VL, A34L716RL
A31G112 *	A31G112CL, A31G112SN, A31G112SQ, A31G112KN, A31G112KU, A31G112KY, A31G112GR, A31G112LU, A31G111KN, A31G111KU, A31G111GR, A31G111LU
A31G123 *	A31G123ML, A31G123MM, A31G123RL, A31G123RM, A31G123RN, A31G123CL, A31G123SQ, A31G123KN, A31G123KU, A31G123KY, A31G122ML, A31G122MM, A31G122RL, A31G122RM
A31R713 *	A31R713CL, A31R713ML, A31R713RT
A31L123 *	A31L123RL, A31L123CL, A31L123KN, A31L123KU, A31L123GR, A31L123LU, A31L122RL, A31L122CL, A31L122KN, A31L122KU, A31L122GR, A31L122LU
A31L214 *	A31L214ML, A31L214RL, A31L214CL, A31L214KN, A31L214KU, A31L213ML, A31L213RL, A31L213CL, A31L213KN, A31L213KU
A31L222 *	A31L222FR, A31L222FU, A31L222AR, A31L221FR, A31L221FU, A31L221AR
A31S134 *	A31S134RL, A31S134CL, A31S134SN, A31S134KN, A31S134KU

* The DMA information described in this document does not apply to the products marked with an “*”.

Contents

Introduction.....	1
1. Flag Clearing in UART IIR Register	5
1.1 Description of Limitation	5
1.1.1 TXE Flag Clearing	5
1.1.2 DMA RX Complete Flag Clearing	5
1.2 Workaround.....	6
1.2.1 Software Solutions.....	6
Revision History	8

List of Tables

Table 1. Device Identification	1
--------------------------------------	---

List of Figures

Figure 1. Example Code: Interrupt Handler Code on UART0 Channel	7
-----------------------------------------------------------------------	---

1. Flag Clearing in UART IIR Register

1.1 Description of Limitation

1.1.1 TXE Flag Clearing

If the Transmit Complete (TXE) occurs at the time of reading the UARTn_IIR, a TXE flag can be unintentionally cleared, in which case a TXE interrupt will not occur.

UARTn_IIR is a Read Clear register. If a TXE occurs “after the Read is executed and before the Clear is executed” for this register, the TXE flag will also be cleared during the Read and Clear process of UARTn_IIR.

1.1.2 DMA RX Complete Flag Clearing

If any of the Receive Line Status (RLS), Data Received (DR), or Transmit Hold Register Empty (THRE) interrupts are enabled with the DMA RX Complete interrupt, the DMA RX Complete Interrupt flag may be cleared regardless of intent, in which case the DMA RX Complete interrupt will not occur.

If DMA RX Complete is pending at the same time as a higher priority interrupt, reading the IIR when the higher priority interrupt is executed will clear the DMA RX Complete flag as well.

1.2 Workaround

To prevent unintentional clearing of these flags, you should use a method that replaces the TXE and DMA RX Complete flags.

1.2.1 Software Solutions

Clear TXE Flag

We recommended using the THRE interrupt instead of the TXE interrupt.

If you need to use the TXE interrupt, you must first check the status of TEMT in the UARTn_LSR register, which corresponds to the root of the TXE flag, and TXEIE in the UARTn_IER register, which is the TXE interrupt permission register.

When using the fallback code, the TXEIE in the UARTn_IER register must be set to '0' if the transmission is not required, and the TXEIE in the UARTn_IER register must be set to '1' if the transmission is required.

Clear DMA RX Complete Flag

It is not a problem to use DMA RX Complete interrupt and lower priority interrupt at the same time.

If you must use the DMA RX Complete interrupt and higher priority interrupt simultaneously, you must first check the status of DRXIEN of the UARTn_IER register and EOT of the DMA_n_SR register.

After the processing, DRXIEN in the UARTn_IER register should be set to '0' or DMA should be reset so that EOT in the DMA_n_SR register becomes '0'.

Software Solution Guide Code

Figure 1 is an example code that applies the defense code described above. It uses the Interrupt Handler code for the channel UART0 as an example.

Figure 1. Example Code: Interrupt Handler Code on UART0 Channel

```

1  uint8_t g_un8RxBuf;
2  void UARTn_IRQHandler (void)
3  {
4      uint32_t status_IIR = 0;
5      uint32_t status_LSR = 0;
6
7      status_IIR = UART0->IIR;          /* Make sure to read and process it only once */
8      if (status_IIR & 0x06)            /* Handling by RLS */
9      {
10         status_LSR = UART0->LSR;
11         /* ERROR processing routine */
12     }
13     else
14     {
15         /* Issue with clearing the DMA RX Complete Flag */
16         if (((status_IIR & 0x0C) == 0x0C) ||
17             ((UART0->IER & UART_IER_DRXIEN_Msk) && (DMA0->SR & DMA_SR_EOT_Msk)))
18         {
19             UART0->IER &= ~UART_IER_DRXIEN_Msk;
20             /* DMA RX completion handling */
21             /* (Reconfigure DMA RX options and initiate DMA RX Start) */
22         }
23         else if (status_IIR & 0x04)      /* Handling by DR */
24         {
25             status_LSR = UART0->LSR;
26             g_un8RxBuf = UART0->RBR;
27             /* RX processing routine */
28         }
29
30         if ((status_IIR & 0x0A) == 0x0A) /* Handling by DMA TX Complete */
31         {
32             /* DMA TX completion handling */
33         }
34         else if (status_IIR & 0x02)      /* Handling by THRE */
35         {
36             /* TX processing routine */
37         }
38     }
39     /* Issue with clearing the TXE flag */
40     if ((status_IIR & 0x10) ||
41         ((UART0->IER & UART_IER_TXEIE_Msk) && (UART0->LSR & UART_LSR_TEMT_Msk)))
42     {
43         /* TX processing routine */
44         /* (Set UARTn_IER &= ~UART_IER_TXEIE_Msk when packet transmission is complete) */
45         /* (Set UARTn_IER |= UART_IER_TXEIE_Msk when transmission starts) */
46     }
47 }

```

Revision History

Revision	Date	Notes
1.00	Nov. 29, 2024	Initial release.

Korea**Regional Office, Seoul**

R&D, Marketing & Sales
8th Fl., 330, Yeongdong-daero,
Gangnam-gu, Seoul,
06177, Korea

Tel: +82-2-2193-2200

Fax: +82-2-508-6903

www.abovsemi.com

HQ, Ochang

R&D, QA, and Test Center
37, Gangni 1-gil, Ochang-eup,
Cheongwon-gun,
Chungcheongbuk-do, 28126, Korea

Tel: +82-43-219-5200

Fax: +82-43-217-3534

www.abovsemi.com

Domestic Sales Manager

Tel: +82-2-2193-2206

Fax: +82-2-508-6903

Email: sales_kr@abov.co.kr

Global Sales Manager

Tel: +82-2-2193-2281

Fax: +82-2-508-6903

Email: sales_gl@abov.co.kr

China Sales Manager

Tel: +86-755-8287-2205

Fax: +86-755-8287-2204

Email: sales_cn@abov.co.kr

ABOV Disclaimer**IMPORTANT NOTICE – PLEASE READ CAREFULLY**

ABOV Semiconductor (“ABOV”) reserves the right to make changes, corrections, enhancements, modifications, and improvements to ABOV products and/or to this document at any time without notice. **ABOV DOES NOT GIVE WARRANTIES AS TO THE ACCURACY OR COMPLETENESS OF THE INFORMATION INCLUDED HEREIN.** Purchasers should obtain the latest relevant information of ABOV products before placing orders. Purchasers are entirely responsible for the choice, selection, and use of ABOV products and ABOV assumes no liability for application assistance or the design of purchasers' products. **NO LICENSE, EXPRESS OR IMPLIED, TO ANY INTELLECTUAL PROPERTY RIGHTS IS GRANTED BY ABOV HEREIN. ABOV DISCLAIMS ALL EXPRESS AND IMPLIED WARRANTIES AND SHALL NOT BE RESPONSIBLE OR LIABLE FOR ANY INJURIES OR DAMAGES RELATED TO USE OF ABOV PRODUCTS IN SUCH UNAUTHORIZED APPLICATIONS.** ABOV and the ABOV logo are trademarks of ABOV. For additional information about ABOV trademarks, please refer to https://www.abov.co.kr/en/about/corporate_identity.php. All other product or service names are the property of their respective owners. Information in this document supersedes and replaces the information previously supplied in any former versions of this document.

© 2024 ABOV Semiconductor – All rights reserved