

## MCE Case Study

**Customer:** International Paper, Eastover Mill

**Asset:** 75 HP AC Induction Motor (Critical Pump Application)

**Scope:** Critical motor evaluated with Baker AWA Tester during 2012 fall outage

**Findings:** Test data recoded 10/1/12 indicated low insulation resistance & excessive leakage current. Investigation of motor connections in motor connection box revealed damaged cable insulation. Test data recorded 10/2/12 (post repairs) confirm successful repair and motor safe for operation.

Results Summary		Test Date/Time 10/1/2012 2:29:11 PM	
Test ID:	IP 480V < 100 HP StepV	Repair/Job #	
Tested By		Tested For	
Room #		MCC	
Location	2 Paper Machine-452	Legacy #	472005008
<b>Temp Status</b>	<b>Tested</b>	<b>PI Status</b>	<b>PASS</b>
Temp	35.0°C 95.0°F	Volts (V)	500
<b>Resist Status</b>	<b>PASS</b>	DA Ratio	1.0
L1-L2 (Ohms)	0.0755 Corr: 0.0727	PI Ratio	DA Only
L2-L3 (Ohms)	0.0755 Corr: 0.0727	<b>Step-Voltage</b>	<b>PASS</b>
L3-L1 (Ohms)	0.0755 Corr: 0.0727	Volts (V)	2000
Max Delta R %	0.005	I(μA)	0.15
Coil 1 (Ohms)	0.0378 Corr: 0.0364	Resist (Mohm)	13429 At 40°C 9495
Coil 2 (Ohms)	0.0378 Corr: 0.0364	<b>Surge Status</b>	<b>PASS</b>
Coil 3 (Ohms)	0.0378 Corr: 0.0364	Peak Volt(V) L1	2020
<b>Megohm Status</b>	<b>OVER CURRENT</b>	Peak Volt(V) L2	2020
Volts (V)	90	Peak Volt(V) L3	2020
I(μA)	930.00	Max P-P EAR(%)	1.6/1.8/1.8
Resist (Mohm)	0	EAR 1-2/2-3/3-1(%)	No Test

