



1807 Boulevard West  
Richmond, VA 23230  
Ph (804) 219-0130  
Fax (804) 219-0132  
[www.eeco-net.com](http://www.eeco-net.com)

---

# ***Digital Diagnostics Report***

## **Infrared Thermography Report**

Prepared for:

**Customer**

Prepared by:

**Travis Beattie, Reliability Specialist**

Date Prepared:

**June 29, 2013**

Survey Date

**June 26-28, 2013**

**Travis Beattie  
Reliability Specialist**

**Richmond Service Center  
1807 Boulevard West. Richmond Va. 23230**

**Direct: (804) 219-0130  
Fax: (804) 219-0132  
[travis.beattie@eeco-net.com](mailto:travis.beattie@eeco-net.com)**



1807 Boulevard West  
Richmond, VA 23230  
Ph (804) 219-0130  
Fax (804) 219-0132  
[www.eeco-net.com](http://www.eeco-net.com)

June 29, 2013

Re: Thermography Report

Mark,

Please find the following report from the Predictive Maintenance Services performed on June 26-28, 2013. The following pages contain a summary of the machinery analyzed followed by diagnosis pages for identified problems. Issues were identified the following equipment.

PECC 2 Turbine Compt Heater  
PECC 3 Cooling Water Fan Motor 88FC-4

Thank you, for choosing Electrical Equipment Company. If there are any further questions or concerns please contact me at 804-219-0130.

Sincerely,

*J. Travis Beattie*

Travis Beattie  
Reliability Specialist

# Equipment Summary

## SEVERITY RATINGS

<b>NONE</b>	The equipment should be operated as normal, with confidence. There are no indications of failure.
<b>LOW</b>	The equipment should be operated as normal, with confidence. There are indications/conditions that are evident but not critical.
<b>MEDIUM</b>	The equipment may be operated/operable, but should be monitored closely. There are issues that will effect performance/reliability. The item will need maintenance soon.
<b>HIGH</b>	The equipment should not be operated to prevent the risk of extensive damage or catastrophic failure.

Equipment	Problem Area	Severity
<b>PECC 1 MCC 1</b>		>
MCC Incoming Line		>
Liquid Fuel Forwarding Pump	Equipment Not Available	
Battery Charger 1		>
Spare 30A Feeder		>
Air Conditioner 88KA-1		>
Undervoltage Relay 27MC-1		>
Evap Cooler 88AC-1A, 2A		>
Switchgear Compartment		>
Turbine Compartment Heater 23-IT-1		>
ACC. Compt Space Heater 23HA-1		>
23VS-1 Gas Valve Compt Space Heater		>
Exhaust Frame Blower 88TK-1		>
Lube Mist Separator Motor 88QV-1A		>
Gen Bearing Evac Pump 88BQ-1		>
Lube Tank Immersion Heater 23QT-1.2		>
24 CKT Panelboard		>
Transformer 480-240/120 1PH		>
Cooling Water Pump 88WC-1		>
Brushless Exciter EX2000BR		>
Gas Compt Vent Fan 88VL-1		>



# Equipment Summary

Equipment	Problem Area	Severity
<b>PECC 2 MCC 1</b>		>
MCC Incoming Line		>
Liquid Fuel Forwarding Pump		<b>X</b>
Battery Charger 1		>
Spare 30A Feeder		>
Air Conditioner 88KA-1		>
Undervoltage Relay 27MC-1		>
Evap Cooler 88AC-1A, 2A		>
Switchgear Compartment		>
Turbine Compartment Heater 23-IT-1	Hot C Phase at Overload Component	<b>HIGH</b>
ACC. Compt Space Heater 23HA-1		>
23VS-1 Gas Valve Compt Space Heater		>
Exhaust Frame Blower 88TK-1		>
Lube Mist Separator Motor 88QV-1A		>
Gen Bearing Evac Pump 88BQ-1		>
Lube Tank Immersion Heater 23QT-1.2		>
24 CKT Panelboard		>
Transformer 480-240/120 1PH		>
Cooling Water Pump 88WC-1		>
Brushless Exciter EX2000BR		>
Gas Compt Vent Fan 88VL-1		>
Cooling Water Fan Motor 88FC-3		>
Cooling Water Fan Motor 88FC-1		>
Turbine Compt Cooling Air Fan 88BT-1		>
Fire Protection Relay Panel		>
Load Compt Vent Fan 88VG-1		>



# Equipment Summary

Equipment	Problem Area	Severity
<b>PECC 3 MCC 2</b>		
Incoming Line		>
Evap Cooler Water Pumps 88AC-1A, 2A		>
ACC Compt Space heater 23HA-2		>
Battery Charger 2		>
Air Conditioner 88KA-2		>
Undervoltage Relay 27MC-2		>
Exhaust frame Blower 2 88TK 2		>
ACC Compt Space Heater 23HA-3		>
Turbine Compt Space heater 23HT-3		>
Turbine Compt Heater 23HT-2		>
Auxiliary Lube Oil Pump 88QA-1		>
Torque Adjuster Drive Motor 88TM-1		>
Hydraulic Supply Pump 88HG-1		>
Co2 Skid LP Tank Heater 88RC-1A		>
Cooling Water Fan Motor 88FC-4	Hot C Phase at Overload Component	<b>MEDIUM</b>
Atomizing Air Compressor 88AB-1		>
Spare 30A Feeder		>
Control Compt Heater 23HG-1.20 23KE-1		>
Load Compt Vent Fan 88VG-2		>
Cooling Water Fan Motor 88FC-2		>
Cooling Water Pump 88WC-2		>
Turbine Compt Cooling Air Fan 88BT-2		>
Gas Compt Vent Fan 88VL-2		>
<b>PECC 3 Batteries</b>		
Incoming Line		>
Emerg Lube Oil Pump		>
Panelboard & DSW 125V DC		>
Battery Chargers 1&2		>
Battery Compartment		>

# Exceptions Detailed Analysis



## EQUIPMENT

PECC 2 Turbine Compt Heater

## COMPANY

## DATE

6/26/2013

## ANALYST

Travis Beattie

## SEVERITY

**HIGH**

## Explanation:

C Phase on overload component is 358F hotter than A and B Phases.  
Evaluate overload for replacement. Prep conductor and re-terminate.



File Location	E:\Images\IR20130626_0833.is2
Image Time	6/26/2013 11:55:45 AM
Emissivity	0.95
Background Temp	68.0 °F
Image Range	83.8 °F to 481.0 °F
Average Temp	128.6 °F
Camera Model	Ti45FT
Camera Manufacturer	Fluke
Calibration Range	-4.0 °F to 662.0 °F
Camera Serial Number	Ti45FT-0807261
Lens Description	20mm/F0.8
Lens Serial Number	40948-8922
DSP Version	4.7.0.0
OCA Version	3.0.6.12



# Exceptions Detailed Analysis



## EQUIPMENT

PECC 3 Cooling Water Fan  
Motor 88FC-4

## COMPANY

## DATE

6/26/2013

## ANALYST

Travis Beattie

## SEVERITY


**MEDIUM**

## Explanation:

Problem corrected in the field. Had a very short screw holding the component in place. Replaced with longer screw and tightened.



File Location	E:\Images\IR20130626_0834.is2
Image Time	6/26/2013 2:55:31 PM
Emissivity	0.95
Background Temp	68.0 °F
Image Range	86.0 °F to 285.0 °F
Average Temp	114.7 °F
Camera Model	Ti45FT
Camera Manufacturer	Fluke
Calibration Range	-4.0 °F to 662.0 °F
Camera Serial Number	Ti45FT-0807261
Lens Description	20mm/F0.8
Lens Serial Number	40948-8922
DSP Version	4.7.0.0
OCA Version	3.0.6.12



**After Scan**