


3- ϕ Induction Motor:



↳ Stator

- (i) Stator frame
- (ii) Stator core
- (iii) Stator winding

↳ Rotor

- (i) Squirrel - Res. is fixed
- (ii) ~~Phase~~ wound - Res is variable.
Phase wound Rotor

Construction

It mainly have two parts stator and rotor

Stator:

It is the stationary part of the motor and has 3 main parts
→ outer frame, stator core & stator winding

Outer frame - its main function is to support the and the to protect the inner part of the core machine.

Stator Core - It mainly carries the Alternating MF which produce hysteresis and eddy currents loss. therefore core is built up of high grade silicone steel.

Stator winding - It mainly carries a 3 phase winding which is mainly supply from 3-phase supply system.

Rotor:

It is the rotating part of the motor and they are of two types.


→ Squirrel

→ Phase wound motor / Slip ring motor.

Torque Slip Curve:

$$T = \frac{3}{\omega_s} \cdot \frac{S E_2^2 R_s}{R_2^2 + S X_2^2}$$

$$S = \frac{N_s - N_r}{N_s}$$



~~Case I~~ S is the Slip
 R_2 and X_2 are the resistance
 and reactance of
 the motor.

Case I - At synchronous speed, slip
 is zero.

Case II - When motor speed is very
 near to the synchronous speed
 that is when this slip is very low
 the term $(S X_2)^2$ is very less than
 and is neglected.

$$[(S X_2)^2 \ll R_2^2]$$

$$T = \frac{3 \cdot S E_2^2 R_2}{\omega_s R_2^2} = K S \quad T \propto K S$$

Case III - As the slip increases torque
 increases and attains its maximum
 value.

$$R_2 = S X_2$$

$$S = \frac{R_2}{X_2}$$

This maximum value of torque
 is known as breakdown or pullout
 torque. It will fall down.

Case IV - With further increase
 in slip due to increase in

load beyond the point of max torque ($s = R_2 / X_2$). The value of slip will be more and value of resistance is negligible.

$$[(s X_2)^2 \gg R_2^2]$$

$$T \propto \frac{1}{s}$$

Hence, at high value of slip (the slip beyond the maximum torque, torque is inversely proportional to slip).

Hence, with the increase of slip beyond the point of maximum torque due to increase in load torque decreases. The result is that the motor couldn't pick up the maximum load and slows down and finally it comes to rest position.

Speed Control of 3 ϕ Induction Motor

- By Change in the value of slip /
- By running the motor at specified load (maintaining value of R_2 & reactance)
- By change in the no. of poles
- By change in slight variation in the frequency ($\pm 2\%$).
- By control in input voltage ($\pm 1\%$)