


Springback



Look up Ks from table.

$$K_s = \frac{\alpha_f}{\alpha_i} = \frac{(2R_i/t) + 1}{(2R_f/t) + 1}$$

Can't look up Ks from table. Need material properties.

$$\frac{R_i}{R_f} = 4 \left(\frac{R_i S_y}{E t} \right)^3 - 3 \left(\frac{R_i S_y}{E t} \right) + 1$$

Limiting Drawing Ratio

$$LDR < \frac{D_o}{D_p}$$

Normal anisotropy/plastic anisotropy/strain ratio

$$R = \frac{\epsilon_w}{\epsilon_t} = \frac{\ln \left(\frac{w_o}{w_f} \right)}{\ln \left(\frac{t_o}{t_f} \right)}$$

Planar anisotropy

$$\bar{R} = \frac{R_0 + 2R_{45} + R_{90}}{4}$$

Want a high \bar{R} for good LDR.

$$\Delta R = \frac{R_0 - 2R_{45} + R_{90}}{2}$$

Low ΔR for good LDR

$\Delta R = 0 \rightarrow$ no earing (same in all directions)

$\Delta R \uparrow =$ height of ears increases

Desirable to have a larger die and punch radii.



Maximum punch force

$$F_{max} = \pi D_p t_o S_{ut} \left(\frac{D_o}{D_p} - 0.7 \right)$$

Polymer Properties

Increasing temperature, the strength and modulus of elasticity decrease, and the toughness increases (thermoplastics)

Structure



Increasing crystallinity








Figure 1 - Schematic diagram illustrating the steps involved in cross-linking: a) starting resin material with low-molecular-mass monomers (A-stage monomers); b) linear growth and branching (B-stage material or prepolymer); c) gelled, but still incomplete network; d) fully cured polymer (C-stage thermoset).



Thermoset - irreversible
Thermoplastic - reversible

Behavior

Typical stress strain curve



Glass transition temperature




Table 15.2 Melting and Glass Transition Temperatures for Some of the More Common Polymeric Materials

Material	Glass Transition Temperature (°C / °F)	Melting Temperature (°C / °F)
Polyethylene (low density)	-100 (-148)	115 (240)
Polyethylene (high density)	-90 (-130)	135 (275)
Polypropylene	-10 (-130)	170 (325)
Nylon 6,6	50 (120)	260 (500)
Polyethylene terephthalate (PET)	70 (158)	260 (500)
Poly(vinyl chloride)	80 (176)	212 (413)
Polystyrene	100 (212)	240 (465)
Polycarbonate	150 (302)	260 (500)


Table 8.1 Room-Temperature Yield Strength and Plane Strain Fracture Toughness Data for Selected Engineering Materials

Material	Yield Strength (MPa)	Yield Strength (ksi)	Plane Strain Fracture Toughness (MPa√m)	Plane Strain Fracture Toughness (ksi√in)
Aluminum alloy* (2024-T3)	495	72	24	22
Aluminum alloy* (7075-T6)	545	79	44	40
Titanium alloy* (Ti-6Al-4V)	955	137	55	50
Alloy steel* (AISI 4340 @ 200°C)	1680	239	50.0	45.8
Alloy steel* (AISI 4340 @ 425°C)	1420	206	47.4	43.0
Ceramics	—	—	0.2-1.4	0.18-1.27
Soda lime glass	—	—	0.7-0.8	0.64-0.73
Aluminum oxide	—	—	2.7-5.0	2.3-4.4
Polymer	25.0-40.0	3.6-5.8	0.7-1.1	0.64-1.0
Polyethylene (PE)	55.0-75.0	7.9-10.8	0.7-1.6	0.64-1.5
Polyethylene terephthalate (PET)	42.1	6.0	2.2	2.0

Failure of Polymers

Failure modes

- Cracking - many small cracks on the surface typically caused by chemical or UV attacks
- Stress whitening - stress causes polymer molecules to reorient, making them scatter light differently
- Water absorption - as region + dimension increases environment change




Polymer Processing

Processing Basics

Viscosity/Temperature


To shape thermo plastics, they must be heated so they soften to the consistency of a liquid. A liquid in liquid form is called 'polymer melt'.

Study of polymer flow is called Rheology



<https://youtu.be/RMjtmr3CaA>

Injection Molding Press



Injection molding is very similar to hot chamber die casting. The pellets or granules are fed into a heated cylinder, where they are melted, then forced into a split-die chamber, either by a hydraulic plunger or by the rotating screw of an extruder. Most modern equipment is of the reciprocating-screw type. As the pressure builds up at the mold entrance, the screw starts to move backward and under pressure, to a predetermined distance, thus controlling the volume of material to be injected. The screw then stops rotating and is pushed forward hydraulically, forcing the molten plastic into the mold cavity. Injection-molding pressures usually range from 70 to 200 MPa (10-30 ksi).

In extrusion, raw thermoplastic materials, in the form of pellets, granules, or powder, are placed into a hopper and fed into the extruder barrel. The barrel is equipped with a screw that blends and conveys the pellets down the barrel. The internal friction and shear stresses developed from the mechanical action of the screw, along with heaters around the extruder's barrel, heats the pellets and liquefies them. The screw action also builds up pressure in the barrel.

Blow molding is a modified combination of extrusion and injection-molding processes. In injection blow molding, a short tubular preform (parison) is first injection molded. The parison can be stored for future molding, or it can be used immediately. If used immediately, the parison molds are opened, and the parison is transferred to a blow-molding die. Hot air is injected into the parison, which expands and fills the mold cavity. Typical products made include plastic beverage bottles and hollow containers.

