



Mechanics**I****n** **Design and** **Manufacturing**




+ Casting and Heat Treatment

Solidification Process Categories




Solidification



- Pure metals




Phase diagram (binary alloy)



Casting and microstructure




Dendrite formation



- Effects of cooling rate

Sand Casting Process (expendable mold)



<https://www.youtube.com/watch?v=BjQCrL8moqw>



Lost-wax
titanium hammer




<https://youtu.be/WXFRRg8YMT0?t=82> 91

Mold Filling and Solidification



- Bernoulli



- Mass Continuity


- Turbulence

- Tapered sprue design – Find diameter at gate so no aspiration



(Given: $Q=0.01 \text{ m}^3/\text{min}$, $h=200\text{mm}$, $D_1=20\text{mm}$, $\eta=0.004 \text{ N-s/m}^2$, $\rho_{\text{al}}=2700\text{kg/m}^3$)

Solidification

- Cooling is a function of the ratio of size and shape of the casting. (Chvorinov's rule)
- Determine if riser cools faster than the casting




Shrinkage



Groover 6th ed.




Metal	Shrinkage
Aluminum alloys	1.3%
Brass, yellow	1.5%
Bronze	1.6%
Cast iron, grey	1.0%
Cast iron, white	2.1%
Magnesium alloy	1.3%
Steel, carbon	1.8%
Tin	2.0%
Zinc	1.3%

- Design/Mitigation






Groover 6th ed.



Furnaces







Permanent Mold Casting Processes










Expendable Mold Processes




Other Casting Process



Casting Defects



Heat Treating







Iron-Carbon Phases/Microconstituents

- **Phases**



- Ferrite –
- Austenite –
- Cementite –

- **Microconstituents**


- Pearlite -
- Martensite -
- Bainite -



Iron-Carbon Phase Diagram






TTT Diagram






Consider microstructure resulting from

1. Rapid cool to 350 °C hold for 10⁴s, then quench
2. Rapid cool to 250 °C, hold for 100s, then quench
3. Rapidly cool to 650 °C, hold for 20s, rapidly cool to 400 °C, hold for 10³s, then quench



Adapted from Callister 8e.

CCT Diagram



Atlas of Time Temperature
Diagrams for Irons and Steels,
Vander Voort

Quenching

- Various quenching media are used to affect cooling rate


-

-

-


-

- Die quenching





Annealing - Steels

- Full Annealing
- Process Annealing
- Spheroidizing



- Normalizing

Tempering




Zaereth

<https://commons.wikimedia.org/w/index.php?curid=18561876>



- Austempering

- Martempering

- Maraging




Heat Treating Non-Ferrous Materials




- Solution Treatment

- Precipitate/Age Hardening


Design Considerations





Using radii or fillets to avoid corners and provide uniform cross section.




Deep cavities should be on one side of the casting where possible.




Design Considerations 2




Sloping bosses can be designed for straight die parting to simplify die design.



Side cores can be eliminated with this hole design.




Wall sections should be uniform.



Ribs and/or fillets improve bosses.

Design Considerations 3




- Geometry

- Allowances

- Draft

- Dimensional Tolerance

Economic Considerations



Copyright ©2017 Pearson Education, All Rights Reserved.



Heat Treating Equipment



Design for heat treating

- Avoid cracking warping, non-uniform properties (unless desired)
- Cooling rate must be uniform
- Guidelines, uniform thickness (or transition between sections of different thicknesses should be gradual)
- Avoid internal or external sharp corners
- Be aware that holes, grooves, keyways, splines etc. may be difficult to heat treat/crack during quenching
- Large surfaces with thin cross sections may warp

Color Chart

