

Lab 6 Pseudocode

//Function Prototypes

```
void Port_Init(void), void PCA_Init (void), void XBR0_Init(), void SMB_Init(void), void  
ADC_Init(void), unsigned char read_AD_input(unsigned char n), void PCA_ISR (void)  
__interrupt 9,  
void tiltConfig(void), unsigned int RangerRead(void), void pause(unsigned char m), void  
ErrorandHeading(void), void Setup(void), unsigned int CompassRead(void), void  
updateFans(long fanPW);
```

//Global Variables

```
unsigned int __xdata PCA_start = 28672, signed int __xdata PW_FAN_C = 2750, signed int  
__xdata PW_FAN_R = 2000, signed int __xdata PW_FAN_F = 3500 signed int __xdata  
NOM_DIST = 75,  
signed int __xdata NOM_SPEED = 100, char new_range = 0, char new_compass = 0, char  
RangerCount = 0, char CompassCount = 0, signed int Kp = 0, signed int Kd = 0, signed int  
desired,  
signed int new_desired, char input, int counts = 0, char display_count = 0, int mult, int heading,  
int old_heading, unsigned int PW, long tmp_pw, signed int new_error = 0,  
signed int old_error = 0, signed int speed, signed int range = 50, int volt
```

//Main Function

```
call Inits (Sys Init, putchar, Port Init, XBRO Init, PCA Init, SMB Init, ADC Init)  
pause(50) //long pause for things to warm up  
call "setup" function to set gains and desired heading  
define the values to be printed  
while(1)  
    if(new_range)  
        range = ranger value  
        new_range = 0  
    if(new_compass)  
        heading = compass value  
        call "ErrorandHeading" function to calculate error and change desired heading  
based off range  
    tmp_pw = motor neutral + kp*error/10 + kd*change in error  
    make sure tmp_pw within range  
    set motor pulsewidth  
    reset motor pulsewidth based off rotational speed if need be  
    new_compass = 0  
    if(display_count >=10)
```

```
calculate voltage  
printf necessary values  
lcd print heading, range, and voltage  
display_count = 0
```