

VIRGINIA ELECTRIC AND POWER COMPANY  
RICHMOND, VIRGINIA 23261

10CFR50.73

**Virginia Electric and Power Company  
North Anna Power Station  
1022 Haley Drive  
Mineral, Virginia 23117**

November 30, 2023

Attention: Document Control Desk  
U. S. Nuclear Regulatory Commission  
Washington, DC 20555-0001

Serial No.: 23-321  
NAPS: RAP  
Docket Nos.: 50-339  
License Nos.: NPF-7


Dear Sir or Madam:

Pursuant to 10CFR50.73, Virginia Electric and Power Company hereby submits the following Licensee Event Report applicable to North Anna Power Station Unit 2.

Report No. 50-339/2023-001-00

This report has been reviewed by the Facility Safety Review Committee and will be forwarded to the Management Safety Review Committee for its review.

Sincerely,



Lisa Hilbert  
Site Vice President  
North Anna Power Station

Enclosure

Commitments contained in this letter: None

cc: United States Nuclear Regulatory Commission  
Region II  
Marquis One Tower  
245 Peachtree Center Ave., NE, Suite 1200  
Atlanta, Georgia 30303-1257

NRC Senior Resident Inspector  
North Anna Power Station

1E22  
NRR



## LICENSEE EVENT REPORT (LER)

(See Page 2 for required number of digits/characters for each block)

(See NUREG-1022, R.3 for instruction and guidance for completing this form  
<http://www.nrc.gov/reading-rm/doc-collections/nuregs/staff/sr1022/r3/>)

Estimated burden per response to comply with this mandatory collection request: 80 hours. Reported lessons learned are incorporated into the licensing process and fed back to industry. Send comments regarding burden estimate to the FOIA, Library, and Information Collections Branch (T-6 A10M), U. S. Nuclear Regulatory Commission, Washington, DC 20555-0001, or by email to [Infocollections.Resource@nrc.gov](mailto:Infocollections.Resource@nrc.gov), and the OMB reviewer at: OMB Office of Information and Regulatory Affairs, (3150-0104), Attn: Desk Officer for the Nuclear Regulatory Commission, 725 17th Street NW, Washington, DC 20503; email: [ofra\\_submission@omb.eop.gov](mailto:ofra_submission@omb.eop.gov). The NRC may not conduct or sponsor, and a person is not required to respond to, a collection of information unless the document requesting or requiring the collection displays a currently valid OMB control number.

## 1. Facility Name

North Anna Power Station

☒ 050☐ 052

## 2. Docket Number

00339

## 3. Page

1 OF 3

## 4. Title

Reactor Coolant Pressure Boundary Leak Due to Poor Weld Workmanship

## 5. Event Date

Month	Day	Year
10	03	2023

## 6. LER Number

Year	Sequential Number	Revision No.
2023	001	00

## 7. Report Date

Month	Day	Year
11	30	2023

## 8. Other Facilities Involved

Facility Name	<input type="checkbox"/> 050	Docket Number
Facility Name	<input type="checkbox"/> 052	Docket Number

## 9. Operating Mode

6

## 10. Power Level

000

## 11. This Report is Submitted Pursuant to the Requirements of 10 CFR §: (Check all that apply)

10 CFR Part 20	<input type="checkbox"/> 20.2203(a)(2)(vi)	10 CFR Part 50	<input checked="" type="checkbox"/> 50.73(a)(2)(II)(A)	<input type="checkbox"/> 50.73(a)(2)(vIII)(A)	<input type="checkbox"/> 73.1200(a)
<input type="checkbox"/> 20.2201(b)	<input type="checkbox"/> 20.2203(a)(3)(I)	<input type="checkbox"/> 50.36(c)(1)(I)(A)	<input type="checkbox"/> 50.73(a)(2)(II)(B)	<input type="checkbox"/> 50.73(a)(2)(vIII)(B)	<input type="checkbox"/> 73.1200(b)
<input type="checkbox"/> 20.2201(d)	<input type="checkbox"/> 20.2203(a)(3)(II)	<input type="checkbox"/> 50.36(c)(1)(II)(A)	<input type="checkbox"/> 50.73(a)(2)(III)	<input type="checkbox"/> 50.73(a)(2)(IX)(A)	<input type="checkbox"/> 73.1200(c)
<input type="checkbox"/> 20.2203(a)(1)	<input type="checkbox"/> 20.2203(a)(4)	<input type="checkbox"/> 50.36(c)(2)	<input type="checkbox"/> 50.73(a)(2)(IV)(A)	<input type="checkbox"/> 50.73(a)(2)(X)	<input type="checkbox"/> 73.1200(d)
<input type="checkbox"/> 20.2203(a)(2)(I)	10 CFR Part 21	<input type="checkbox"/> 50.46(a)(3)(II)	<input type="checkbox"/> 50.73(a)(2)(V)(A)	10 CFR Part 73	<input type="checkbox"/> 73.1200(e)
<input type="checkbox"/> 20.2203(a)(2)(II)	<input type="checkbox"/> 21.2(c)	<input type="checkbox"/> 50.69(g)	<input type="checkbox"/> 50.73(a)(2)(V)(B)	<input type="checkbox"/> 73.77(a)(1)	<input type="checkbox"/> 73.1200(f)
<input type="checkbox"/> 20.2203(a)(2)(III)		<input type="checkbox"/> 50.73(a)(2)(I)(A)	<input type="checkbox"/> 50.73(a)(2)(V)(C)	<input type="checkbox"/> 73.77(a)(2)(I)	<input type="checkbox"/> 73.1200(g)
<input type="checkbox"/> 20.2203(a)(2)(IV)		<input type="checkbox"/> 50.73(a)(2)(I)(B)	<input type="checkbox"/> 50.73(a)(2)(V)(D)	<input type="checkbox"/> 73.77(a)(2)(II)	<input type="checkbox"/> 73.1200(h)
<input type="checkbox"/> 20.2203(a)(2)(V)		<input type="checkbox"/> 50.73(a)(2)(I)(C)	<input type="checkbox"/> 50.73(a)(2)(VII)		

☐ OTHER (Specify here, in abstract, or NRC 366A).

## 12. Licensee Contact for this LER

## Licensee Contact

Lisa Hilbert, Site Vice President

## Phone Number (Include area code)

(540) 894-2101

## 13. Complete One Line for each Component Failure Described in this Report

Cause	System	Component	Manufacturer	Reportable to IRIS	Cause	System	Component	Manufacturer	Reportable to IRIS
A	AB	TBG	—	Y					

## 14. Supplemental Report Expected

☒ No ☐ Yes (If yes, complete 15. Expected Submission Date)

## 15. Expected Submission Date

Month	Day	Year

## 16. Abstract (Limit to 1326 spaces, i.e., approximately 13 single-spaced typewritten lines)

On September 11, 2023, at 1558 hours with Unit 2 in Mode 5 at 140 degrees F and 30 psig for a refueling outage, a boric acid leak was discovered on tubing associated with a Pressurizer level transmitter. The leak was not quantifiable as it consisted of a small amount of dry boric acid. Non-destructive examination (NDE) was performed on the leak to determine if it was a through wall leak. On October 3, 2023, at 1154 with Unit 2 in Mode 6 at 100 degrees F and atmospheric pressure, the NDE determined the leak was a through wall leak. This failure constitutes welding or material defects in the primary coolant system that cannot be found acceptable under ASME Section XI. Therefore, an 8-hour report was made for a degraded condition under 10 CFR 50.72(b)(3)(ii)(A).

The direct cause of the weld failure was due to inadequate welding process control by the welder. Unit 1 was not impacted by this event. The health and safety of the public were not affected by this event.

**LICENSEE EVENT REPORT (LER)  
CONTINUATION SHEET**

(See NUREG-1022, R.3 for instruction and guidance for completing this form  
<http://www.nrc.gov/reading-rm/doc-collections/nuregs/staff/sr1022/r3/>)

Estimated burden per response to comply with this mandatory collection request: 80 hours. Reported lessons learned are incorporated into the licensing process and fed back to industry. Send comments regarding burden estimate to the FOIA, Library, and Information Collections Branch (T-6 A10M), U. S. Nuclear Regulatory Commission, Washington, DC 20555-0001, or by email to [Infocollects.Resource@nrc.gov](mailto:Infocollects.Resource@nrc.gov), and the OMB reviewer at: OMB Office of Information and Regulatory Affairs, (3150-0104), Attn: Desk Officer for the Nuclear Regulatory Commission, 725 17th Street NW, Washington, DC 20503; email: [oir\\_submission@omb.eop.gov](mailto:oir_submission@omb.eop.gov). The NRC may not conduct or sponsor, and a person is not required to respond to, a collection of information unless the document requesting or requiring the collection displays a currently valid OMB control number.

<b>1. FACILITY NAME</b> North Anna Power Station	<input checked="" type="checkbox"/> <b>050</b>	<b>2. DOCKET NUMBER</b> 00339	<b>3. LER NUMBER</b>		
	<input type="checkbox"/> <b>052</b>		<b>YEAR</b> 2023	<b>SEQUENTIAL NUMBER</b> 001	<b>REV NO.</b> 00

**NARRATIVE****1.0 Description of Event**

On September 11, 2023, at 1558 hours with Unit 2 in Mode 5 at 140 degrees F and 30 psig for a refueling outage, a boric acid leak was discovered on tubing associated with a Pressurizer (EIS Component PZR, System AB) level transmitter (EIS Component LT, System AB). The leak was not quantifiable as it consisted of a small amount of dry boric acid.

Non-destructive examination (NDE) was performed on the leak to determine if it was a through wall leak. On October 3, 2023, at 1154 with Unit 2 in Mode 6 at 100 degrees F and atmospheric pressure, the NDE determined the leak was a through wall leak. This failure constituted welding or material defects in the primary coolant system that cannot be found acceptable under ASME Section XI. Therefore, an 8-hour report was made for a degraded condition under 10 CFR 50.72(b) (3)(ii)(A). This weld was part of an instrument tubing design change that was implemented in 1998.

**2.0 Significant Safety Consequences and Implications**

No significant safety consequences resulted from this event. The leak was discovered while Unit 2 was shut down for a refueling outage. The leak was not quantifiable based on the small amount of boric acid noted and, therefore, well within the capability of one charging pump (EIS Component P, System CB). The health and safety of the public were not affected by this event.

**3.0 Cause of the Event**

The direct cause of the weld failure was due to inadequate welding process control by the welder. The specific socket welds in question exhibited poor workmanship by having a large degree of melt-through and suck-back on the inside surface, and multiple arc strikes and excessive grinding on the outside surface. During the metallurgical failure analysis, the sample was sectioned through the area of suspected leakage, which revealed a lack of fusion defect between the weldment and base metal. The degree of lack of fusion confirmed in the laboratory analysis was substantial enough to provide the eventual leak path after a 25-year service period.

**4.0 Immediate Corrective Action**

Both the leaking socket welded coupling and a non-leaking downstream socket welded coupling were replaced. NDE surface examinations were performed on the replacement socket welds, and the area was also examined during an external leakage check.

**5.0 Additional Corrective Actions**

Additional Liquid Penetrant (LP) exams were performed on tubing welds from the pressurizer steam space to a different Pressurizer level transmitter. No weld flaws or boric acid residue was identified during these examinations. For the next refueling outages for each unit, work orders have been created to inspect tubing socket welds that were fabricated in a similar timeframe, under similar field conditions, using the same welding and inspection procedures, and had an overlap of qualified welders performing the work.



# LICENSEE EVENT REPORT (LER) CONTINUATION SHEET

(See NUREG-1022, R.3 for instruction and guidance for completing this form  
<http://www.nrc.gov/reading-rm/doc-collections/nuregs/staff/sr1022/r3/>)

Estimated burden per response to comply with this mandatory collection request: 80 hours. Reported lessons learned are incorporated into the licensing process and fed back to industry. Send comments regarding burden estimate to the FOIA, Library, and Information Collections Branch (T-6 A10M), U. S. Nuclear Regulatory Commission, Washington, DC 20555-0001, or by email to [Infocollects.Resource@nrc.gov](mailto:Infocollects.Resource@nrc.gov), and the OMB reviewer at: OMB Office of Information and Regulatory Affairs, (3150-0104), Attn: Desk Officer for the Nuclear Regulatory Commission, 725 17th Street NW, Washington, DC 20503; email: [aira\\_submission@omb.eop.gov](mailto:aira_submission@omb.eop.gov). The NRC may not conduct or sponsor, and a person is not required to respond to, a collection of information unless the document requesting or requiring the collection displays a currently valid OMB control number.

<b>1. FACILITY NAME</b>		<input checked="" type="checkbox"/> 050  <input type="checkbox"/> 052	<b>2. DOCKET NUMBER</b>	<b>3. LER NUMBER</b>		
North Anna Power Station			00339	YEAR	SEQUENTIAL NUMBER	REV NO.
				2023	- 001	- 00

## NARRATIVE

### 6.0 Actions to Prevent Recurrence

Nuclear Welding Program Authorized By training will be updated to include this operating experience (OE) of workmanship issues when welding tubing.

### 7.0 Similar Events

No similar events have been noted at North Anna for instrument tube welding failures.

### 8.0 Additional Information

Unit 1 was unaffected by this event.