



Paul M. Swift
Site Vice President

R.E. Ginna Nuclear Power Plant
1503 Lake Rd.
Ontario, NY 14519

315-791-5200 Office
www.exeloncorp.com

December 2, 2021

U. S. Nuclear Regulatory Commission
ATTN: Document Control Desk
Washington, DC 20555-0001

RE. Ginna Nuclear Power Plant
Renewed Facility Operating License No. DPR-18
NRC Docket No. 50-244

Subject: LER 2021-002, Valid Auxiliary Feedwater System Actuation on Lowered Steam Generator Level due to Failure to Control Main Feed Water Flow and Delay in Closing Main Steam Isolation Valves

The attached Licensee Event Report (LER) 2021-002 is submitted under the provisions of NUREG-1022, Event Reporting Guidelines. There are no new commitments contained in this submittal. This submittal is for revision 0 of the LER.

Should you have any questions regarding this submittal, please contact Chris Bradshaw at (315) 791-3246.

Sincerely,

A handwritten signature in black ink, appearing to read "Paul Swift", with a long horizontal line extending to the left.

Paul Swift

Attachment: LER 2021-002

cc: NRC Regional Administrator, Region 1
NRC Project Manager, Ginna
NRC Resident Inspector, Ginna (e-mail)

Attachment

LER 2021-002, Revision 0



LICENSEE EVENT REPORT (LER)

(See Page 3 for required number of digits/characters for each block)

(See NUREG-1022, R.3 for instruction and guidance for completing this form
<http://www.nrc.gov/reading-rm/doc-collections/nuregs/staff/sr1022/r3/>)

Estimated burden per response to comply with this mandatory collection request: 80 hours. Reported lessons learned are incorporated into the licensing process and fed back to industry. Send comments regarding burden estimate to the FOIA, Library, and Information Collections Branch (T-6 A10M), U.S. Nuclear Regulatory Commission, Washington, DC 20555-0001, or by e-mail to Infocollcts.Resource@nrc.gov, and the OMB reviewer at: OMB Office of Information and Regulatory Affairs, (3150-0104), Attn: Desk all: oir_submission@omb.eop.gov. The NRC may not conduct or sponsor, and a person is not required to respond to, a collection of information unless the document requesting or requiring the collection displays a currently valid OMB control number.

1. Facility Name R.E. Ginna Nuclear Power Plant, Unit 1						2. Docket Number 05000 244			3. Page 1 OF 4																												
4. Title Valid Auxiliary Feedwater System Actuation on Lowered Steam Generator Level due to Failure to Control Main Feed Water Flow and Delay in Closing Main Steam Isolation Valves																																					
5. Event Date <table border="1" style="width:100%; border-collapse: collapse;"> <tr> <th>Month</th> <th>Day</th> <th>Year</th> </tr> <tr> <td>10</td> <td>04</td> <td>2021</td> </tr> </table>			Month	Day	Year	10	04	2021	6. LER Number <table border="1" style="width:100%; border-collapse: collapse;"> <tr> <th>Year</th> <th>Sequential Number</th> <th>Revision No.</th> </tr> <tr> <td>2021</td> <td>- 002 -</td> <td>00</td> </tr> </table>			Year	Sequential Number	Revision No.	2021	- 002 -	00	7. Report Date <table border="1" style="width:100%; border-collapse: collapse;"> <tr> <th>Month</th> <th>Day</th> <th>Year</th> </tr> <tr> <td>12</td> <td>02</td> <td>2021</td> </tr> </table>			Month	Day	Year	12	02	2021	8. Other Facilities Involved <table border="1" style="width:100%; border-collapse: collapse;"> <tr> <th>Facility Name</th> <th>Docket Number</th> </tr> <tr> <td></td> <td>05000</td> </tr> <tr> <th>Facility Name</th> <th>Docket Number</th> </tr> <tr> <td></td> <td>05000</td> </tr> </table>			Facility Name	Docket Number		05000	Facility Name	Docket Number		05000
Month	Day	Year																																			
10	04	2021																																			
Year	Sequential Number	Revision No.																																			
2021	- 002 -	00																																			
Month	Day	Year																																			
12	02	2021																																			
Facility Name	Docket Number																																				
	05000																																				
Facility Name	Docket Number																																				
	05000																																				
9. Operating Mode 3						10. Power Level 000																															
11. This Report is Submitted Pursuant to the Requirements of 10 CFR §: (Check all that apply)																																					
10 CFR Part 20		<input type="checkbox"/> 20.2203(a)(2)(vi)		<input type="checkbox"/> 50.36(c)(2)		<input checked="" type="checkbox"/> 50.73(a)(2)(iv)(A)		<input type="checkbox"/> 50.73(a)(2)(x)																													
<input type="checkbox"/> 20.2201(b)		<input type="checkbox"/> 20.2203(a)(3)(i)		<input type="checkbox"/> 50.46(a)(3)(ii)		<input type="checkbox"/> 50.73(a)(2)(v)(A)		10 CFR Part 73																													
<input type="checkbox"/> 20.2201(d)		<input type="checkbox"/> 20.2203(a)(3)(ii)		<input type="checkbox"/> 50.69(g)		<input type="checkbox"/> 50.73(a)(2)(v)(B)		<input type="checkbox"/> 73.71(a)(4)																													
<input type="checkbox"/> 20.2203(a)(1)		<input type="checkbox"/> 20.2203(a)(4)		<input type="checkbox"/> 50.73(a)(2)(i)(A)		<input type="checkbox"/> 50.73(a)(2)(v)(C)		<input type="checkbox"/> 73.71(a)(5)																													
<input type="checkbox"/> 20.2203(a)(2)(i)		10 CFR Part 21		<input type="checkbox"/> 50.73(a)(2)(i)(B)		<input type="checkbox"/> 50.73(a)(2)(v)(D)		<input type="checkbox"/> 73.77(a)(1)(i)																													
<input type="checkbox"/> 20.2203(a)(2)(ii)		<input type="checkbox"/> 21.2(c)		<input type="checkbox"/> 50.73(a)(2)(i)(C)		<input type="checkbox"/> 50.73(a)(2)(vii)		<input type="checkbox"/> 73.77(a)(2)(i)																													
<input type="checkbox"/> 20.2203(a)(2)(iii)		10 CFR Part 50		<input type="checkbox"/> 50.73(a)(2)(ii)(A)		<input type="checkbox"/> 50.73(a)(2)(viii)(A)		<input type="checkbox"/> 73.77(a)(2)(ii)																													
<input type="checkbox"/> 20.2203(a)(2)(iv)		<input type="checkbox"/> 50.36(c)(1)(i)(A)		<input type="checkbox"/> 50.73(a)(2)(ii)(B)		<input type="checkbox"/> 50.73(a)(2)(viii)(B)																															
<input type="checkbox"/> 20.2203(a)(2)(v)		<input type="checkbox"/> 50.36(c)(1)(ii)(A)		<input type="checkbox"/> 50.73(a)(2)(iii)		<input type="checkbox"/> 50.73(a)(2)(ix)(A)																															
<input type="checkbox"/> OTHER (Specify here, in abstract, or NRC 366A).																																					
12. Licensee Contact for this LER																																					
Licensee Contact Christopher Bradshaw, Regulatory Assurance Manager								Phone Number (Include area code) 3157913246																													
13. Complete One Line for each Component Failure Described in this Report																																					
Cause	System	Component	Manufacturer	Reportable to IRIS		Cause	System	Component	Manufacturer	Reportable to IRIS																											
N/A	N/A	N/A	N/A	N/A																																	
14. Supplemental Report Expected <input checked="" type="checkbox"/> No <input type="checkbox"/> Yes (If yes, complete 15. Expected Submission Date)						15. Expected Submission Date <table border="1" style="width:100%; border-collapse: collapse;"> <tr> <th>Month</th> <th>Day</th> <th>Year</th> </tr> <tr> <td></td> <td></td> <td></td> </tr> </table>						Month	Day	Year																							
Month	Day	Year																																			
16. Abstract (Limit to 1560 spaces, i.e., approximately 15 single-spaced typewritten lines) On 10/4/21 during a shutdown for the 2021 Refueling Outage, following the planned reactor trip, Reactor Coolant Average Temperature (Tavg) lowered due to overfeeding the 'B' Steam Generator (S/G). To maintain Tavg, feed to the S/Gs was minimized. During the cooldown, 'A' S/G lowered and a valid actuation of the Auxiliary Feedwater (AFW) System occurred. The valid actuation of the AFW System is reportable per 10CFR50.72(b)(3)(iv)(A) and 10CFR50.73.(a)(2)(iv)(A). No equipment position changes were noted as a result of the actuation, which is the expected response for the given plant conditions. The causes of this event were Operators failed to control Main Feedwater Flow following Reactor Trip resulting in a cooldown and did not promptly close the Main Steam Isolation Valves (MSIVs). Corrective actions include procedures revisions to include specific guidance on FRV Bypass Valve and MSIV closure. Training will be conducted to address gaps in Tavg control following Reactor Trip.																																					

**LICENSEE EVENT REPORT (LER)
CONTINUATION SHEET**

(See NUREG-1022, R.3 for instruction and guidance for completing this form
<http://www.nrc.gov/reading-rm/doc-collections/nuregs/staff/sr1022/r3/>)

Estimated burden per response to comply with this mandatory collection request: 80 hours. Reported lessons learned are incorporated into the licensing process and fed back to industry. Send comments regarding burden estimate to the FOIA, Library, and Information Collections Branch (T-6 A10M), U. S. Nuclear Regulatory Commission, Washington, DC 20555-0001, or by e-mail to Infocollections.Resource@nrc.gov, and the OMB reviewer at: OMB Office of Information and Regulatory Affairs, (3150-0104), Attn: Desk Officer for the Nuclear Regulatory Commission, 725 17th Street NW, Washington, DC 20503; e-mail: oir_submission@omb.eop.gov. The NRC may not conduct or sponsor, and a person is not required to respond to, a collection of information unless the document requesting or requiring the collection displays a currently valid OMB control number.

1. FACILITY NAME	2. DOCKET NUMBER	3. LER NUMBER		
		YEAR	SEQUENTIAL NUMBER	REV NO.
R.E. Ginna Nuclear Power Plant, Unit 1	05000-244	2021	002	00

NARRATIVE**I. PRE-EVENT PLANT CONDITIONS**

At the time of the event, the plant was in MODE 3 following a planned manual reactor trip during a plant shutdown.

II. DESCRIPTION OF EVENT**A. EVENT**

On 10/4/21 during a shutdown for the 2021 Refueling Outage, following the planned reactor trip, Reactor Coolant Average Temperature (Tavg) lowered due to overfeeding the 'B' Steam Generator (S/G). To maintain Tavg, feed to the S/Gs was minimized. During the cooldown, 'A' S/G lowered and resulted in an unplanned entry into LCO 3.4.5, Reactor Coolant System (RCS) Loops - MODES 1, $\leq 8.5\%$ rated thermal power (RTP), 2, and 3.

As S/G Level lowered, a valid Auxiliary Feedwater (AFW) actuation signal was generated. The 'A' Train AFW System was already in service and aligned when the actuation signal was generated. No equipment position changes were noted as a result of the actuation, which is the expected response for the given plant conditions. Prior to the reactor trip, the 'B' Feedwater Regulating Valve (FRV) Bypass Valve was placed in manual. Following the reactor trip, the 'B' FRV Bypass Valve did not close. When in manual, FRVs and FRV Bypass Valves will not automatically close on a reactor trip. 'B' S/G level rose to a maximum of 63% over 8 minutes prior to the FRV Bypass Valve being manually closed by Operators.

Feedwater was secured to the S/Gs; however, Tavg lowered and stabilized at approximately 535 degrees. During this time the 'B' Main Feedwater Pump was secured so AFW flow could be established and was subsequently minimized to reduce the cooldown effects on Tavg. 'A' S/G level lowered to 6% and the Main Steam Isolation Valves (MSIVs) were closed to limit secondary side steam flows and raise Tavg. After closing the MSIVs, Tavg stabilized at approximately 547 degrees and 'A' S/G level was restored to approximately 52%.

B. INOPERABLE STRUCTURES, COMPONENTS, OR SYSTEMS THAT CONTRIBUTED TO THE EVENT:

None



LICENSEE EVENT REPORT (LER) CONTINUATION SHEET

(See NUREG-1022, R.3 for instruction and guidance for completing this form
<http://www.nrc.gov/reading-rm/doc-collections/nuregs/staff/sr1022/r3/>)

Estimated burden per response to comply with this mandatory collection request: 80 hours. Reported lessons learned are incorporated into the licensing process and fed back to industry. Send comments regarding burden estimate to the FOIA, Library, and Information Collections Branch (T-6 A10M), U. S. Nuclear Regulatory Commission, Washington, DC 20555-0001, or by e-mail to Infocollections.Resource@nrc.gov, and the OMB reviewer at: OMB Office of Information and Regulatory Affairs, (3150-0104), Attn: Desk Officer for the Nuclear Regulatory Commission, 725 17th Street NW, Washington, DC 20503; e-mail: oir_submission@omb.eop.gov. The NRC may not conduct or sponsor, and a person is not required to respond to, a collection of information unless the document requesting or requiring the collection displays a currently valid OMB control number.

1. FACILITY NAME	2. DOCKET NUMBER	3. LER NUMBER		
R.E. Ginna Nuclear Power Plant, Unit 1	05000- 244	YEAR 2021	SEQUENTIAL NUMBER 002	REV NO. 00

NARRATIVE

C. DATES AND APPROXIMATE TIMES OF MAJOR OCCURENCES:

0010 10/04/2021 Manual Reactor Trip
0031 10/04/2021 AFW System actuation signal due to low 'A' S/G water level
0032 10/04/2021 'A' RCS Loop declared inoperable due to low 'A' S/G water level
0041 10/04/2021 Main Steam Isolation Valves Closed
0046 10/04/2021 'A' RCS Loop declared Operable

D. OTHER SYSTEMS OR SECONDARY FUNCTIONS AFFECTED:

'A' RCS Loop declared inoperable due to low water level in the 'A' S/G in MODE 3

E. METHOD OF DISCOVERY:

Self-revealing: At 0031 on 10/04/2021 in MODE 3, S/G 'A' Narrow Range Water Level went low causing an AFW System actuation signal. AFW was in service at the time of the event providing decay heat removal.

F. SAFETY SYSTEM RESPONSES:

The 'A' Train AFW System was already in service and aligned when the actuation signal was generated. No equipment position changes were noted as a result of the actuation, which is the expected response for the given plant conditions.

III. CAUSE OF EVENT:

Operators did not close the 'B' Main Feedwater Regulating Valve Bypass Valve following Reactor Trip resulting in a cooldown and did not promptly close the Main Steam Isolation Valves

IV. ASSESSMENT OF THE SAFETY CONSEQUENCES OF THE EVENT:

In Mode 1 \leq 8.5% Power and Mode 2, the Reactor Coolant Pumps (RCP) are used to provide forced circulation of the reactor coolant to ensure mixing of the coolant for proper boration and chemistry control and to remove the limited amount of reactor heat. In MODE 3, the RCPs are used to provide forced circulation for heat removal during heatup and cooldown. The Mode 1 \leq 8.5% Power, Mode 2, and Mode 3 reactor and decay heat removal requirements are low enough that a single RCS loop with one RCP running is sufficient to remove core decay heat. However, two RCS loops are required to be Operable to ensure redundant capability for decay heat removal.

Operator action restored the 'A' RCS Loop to Operable within 14 minutes. RCS decay heat removal was not challenged during the event. As such this event was not significant with respect to the health and safety of the public.

**LICENSEE EVENT REPORT (LER)
CONTINUATION SHEET**

(See NUREG-1022, R.3 for instruction and guidance for completing this form
<http://www.nrc.gov/reading-rm/doc-collections/nuregs/staff/sr1022/r3/>)

Estimated burden per response to comply with this mandatory collection request: 80 hours. Reported lessons learned are incorporated into the licensing process and fed back to industry. Send comments regarding burden estimate to the FOIA, Library, and Information Collections Branch (T-6 A10M), U. S. Nuclear Regulatory Commission, Washington, DC 20555-0001, or by e-mail to Infocollects.Resource@nrc.gov, and the OMB reviewer at: OMB Office of Information and Regulatory Affairs, (3150-0104), Attn: Desk Officer for the Nuclear Regulatory Commission, 725 17th Street NW, Washington, DC 20503; e-mail: oir_submission@omb.eop.gov. The NRC may not conduct or sponsor, and a person is not required to respond to, a collection of information unless the document requesting or requiring the collection displays a currently valid OMB control number.

1. FACILITY NAME	2. DOCKET NUMBER	3. LER NUMBER		
		YEAR	SEQUENTIAL NUMBER	REV NO.
R.E. Ginna Nuclear Power Plant, Unit 1	05000-244	2021	002	00

NARRATIVE**V. CORRECTIVE ACTIONS**

Operations guidance for closure of both the Main Feedwater Regulating Valves and Main Steam Isolation Valves will be added to the shutdown procedures. Training solutions will be used to address the gaps in temperature control following Reactor Trip.

VI. ADDITIONAL INFORMATION:

None

A. FAILED COMPONENTS:

None

B. PREVIOUS LERs ON SIMILAR EVENTS:

A LER historical search was conducted and no similar LER events were identified.

C. THE ENERGY INDUSTRY IDENTIFICATION SYSTEM (EIS) COMPONENT FUNCTION IDENTIFIER AND SYSTEM NAME OF EACH COMPONENT OR SYSTEM REFERRED TO IN THIS LER:

COMPONENT - Flow Control Valve

IEEE 803 FUNCTION NUMBER - FCV

IEEE 805 SYSTEM IDENTIFICATION - SJ