



1717 Wakonade Drive
Welch, MN 55089

November 18, 2021

L-PI-21-043
10 CFR 50.73

ATTN: Document Control Desk
U.S. Nuclear Regulatory Commission
Washington, DC 20555-0001

Prairie Island Nuclear Generating Plant, Unit 2
Docket No. 50-306
Renewed Facility Operating License No. DPR-60

Prairie Island Nuclear Generating Plant (PINGP) Unit 2 Licensee Event Report 2021-001-00

Northern States Power Company, a Minnesota corporation, doing business as Xcel Energy (hereafter "NSPM"), hereby submits Licensee Event Report (LER) 50-306/2021-001-00 per 10 CFR 50.73(a)(2)(iv)(A).

If you have any questions about this submittal, please contact Carrie Seipp, Senior Regulatory Engineer, at 612-330-5576.

Summary of Commitments

This letter makes no new commitments and no revisions to existing commitments.

A handwritten signature in black ink, appearing to read 'Christopher P. Domingos'.

Christopher P. Domingos
Site Vice President, Prairie Island Nuclear Generating Plant
Northern States Power Company – Minnesota

Enclosure (1)

cc: Administrator, Region III, USNRC
Project Manager, Prairie Island, USNRC
Resident Inspector, Prairie Island, USNRC
State of Minnesota

ENCLOSURE 1

**PRAIRIE ISLAND NUCLEAR GENERATING PLANT
LICENSEE EVENT REPORT 50-306/2021-001-00**

2 pages follow

NRC FORM 366 (08-2020)		U.S. NUCLEAR REGULATORY COMMISSION			APPROVED BY OMB: NO. 3150-0104		EXPIRES: 08/31/2023												
 LICENSEE EVENT REPORT (LER) (See Page 3 for required number of digits/characters for each block) (See NUREG-1022, R.3 for instruction and guidance for completing this form https://www.nrc.gov/reading-rm/doc-collections/nuregs/staff/sr1022/r3/)										Estimated burden per response to comply with this mandatory collection request: 80 hours. Reported lessons learned are incorporated into the licensing process and fed back to industry. Send comments regarding burden estimate to the FOIA, Library, and Information Collections Branch (T-6 A10M), U.S. Nuclear Regulatory Commission, Washington, DC 20555-0001, or by e-mail to Infocollect.Resource@nrc.gov , and the OMB reviewer at: OMB Office of Information and Regulatory Affairs, (3150-0104), Attn: Desk all: ofra_submission@omb.eop.gov . The NRC may not conduct or sponsor, and a person is not required to respond to, a collection of information unless the document requesting or requiring the collection displays a currently valid OMB control number.									
1. Facility Name Prairie Island Nuclear Generating Plant, Unit 2					2. Docket Number 05000306			3. Page 1 OF 2											
4. Title 22 Turbine Driven Auxiliary Feedwater Pump Actuation Signal Due to Procedure Error																			
5. Event Date			6. LER Number			7. Report Date			8. Other Facilities Involved										
Month	Day	Year	Year	Sequential Number	Rev No.	Month	Day	Year	Facility Name	Docket Number									
10	03	2021	2021	- 001 -	00	11	18	2021	Facility Name	Docket Number									
										05000									
										05000									
9. Operating Mode 5					10. Power Level 0														
11. This Report is Submitted Pursuant to the Requirements of 10 CFR §: (Check all that apply)																			
10 CFR Part 20		<input type="checkbox"/> 20.2203(a)(2)(vi)		<input type="checkbox"/> 50.36(c)(2)		<input checked="" type="checkbox"/> 50.73(a)(2)(iv)(A)		<input type="checkbox"/> 50.73(a)(2)(x)											
<input type="checkbox"/> 20.2201(b)		<input type="checkbox"/> 20.2203(a)(3)(i)		<input type="checkbox"/> 50.46(a)(3)(ii)		<input type="checkbox"/> 50.73(a)(2)(v)(A)		10 CFR Part 73											
<input type="checkbox"/> 20.2201(d)		<input type="checkbox"/> 20.2203(a)(3)(ii)		<input type="checkbox"/> 50.69(g)		<input type="checkbox"/> 50.73(a)(2)(v)(B)		<input type="checkbox"/> 73.71(a)(4)											
<input type="checkbox"/> 20.2203(a)(1)		<input type="checkbox"/> 20.2203(a)(4)		<input type="checkbox"/> 50.73(a)(2)(i)(A)		<input type="checkbox"/> 50.73(a)(2)(v)(C)		<input type="checkbox"/> 73.71(a)(5)											
<input type="checkbox"/> 20.2203(a)(2)(i)		10 CFR Part 21		<input type="checkbox"/> 50.73(a)(2)(i)(B)		<input type="checkbox"/> 50.73(a)(2)(v)(D)		<input type="checkbox"/> 73.77(a)(1)(i)											
<input type="checkbox"/> 20.2203(a)(2)(ii)		<input type="checkbox"/> 21.2(c)		<input type="checkbox"/> 50.73(a)(2)(i)(C)		<input type="checkbox"/> 50.73(a)(2)(vii)		<input type="checkbox"/> 73.77(a)(2)(i)											
<input type="checkbox"/> 20.2203(a)(2)(iii)		10 CFR Part 50		<input type="checkbox"/> 50.73(a)(2)(ii)(A)		<input type="checkbox"/> 50.73(a)(2)(viii)(A)		<input type="checkbox"/> 73.77(a)(2)(ii)											
<input type="checkbox"/> 20.2203(a)(2)(iv)		<input type="checkbox"/> 50.36(c)(1)(i)(A)		<input type="checkbox"/> 50.73(a)(2)(ii)(B)		<input type="checkbox"/> 50.73(a)(2)(viii)(B)													
<input type="checkbox"/> 20.2203(a)(2)(v)		<input type="checkbox"/> 50.36(c)(1)(ii)(A)		<input type="checkbox"/> 50.73(a)(2)(iii)		<input type="checkbox"/> 50.73(a)(2)(ix)(A)													
<input type="checkbox"/> Other (Specify here, in Abstract, or in NRC 366A).																			
12. Licensee Contact for this LER																			
Licensee Contact Carrie Seipp, Senior Regulatory Engineer								Phone Number (Include Area Code) (612) 330-5576											
13. Complete One Line for each Component Failure Described in this Report																			
Cause	System	Component	Manufacturer	Reportable To IRIS	Cause	System	Component	Manufacturer	Reportable To IRIS										
14. Supplemental Report Expected							15. Expected Submission Date		Month	Day									
<input checked="" type="checkbox"/> No							<input type="checkbox"/> Yes (If yes, complete 15. Expected Submission Date)												
16. Abstract (Limit to 1560 spaces, i.e., approximately 15 single-spaced typewritten lines) On October 3, 2021, with Prairie Island Nuclear Generating Plant (PINGP) Unit 2 in Cold Shutdown, the 22 Turbine Driven Auxiliary Feedwater (AFW) Pump received a valid actuation signal. While performing the prerequisite checklists for Surveillance Procedure (SP) 2083A "Unit 2 Integrated SI Test with a Simulated Loss of Offsite Power Train A," the Train B 22 Turbine Driven Auxiliary Feedwater (AFW) Pump selector switch in the Main Control Room was placed in Shutdown Auto from Manual. This, combined with having the Non-Safety Related 4160 Volt buses 21 and 22 isolated for maintenance, completed the automatic start signal. The turbine and pump did not turn because the equipment was out of service with the steam supply valves closed. This event is reportable under 10CFR 50.73(a)(2)(iv)(A) due to a valid Pressurized Water Reactor Auxiliary Feedwater actuation signal. There was no impact on the ability to maintain safe shutdown conditions. The system operated as designed. The cause of this event was a latent procedure error in SP 2083A. The corrective action was an update to the SP 2083A prerequisite checklist to place the 22 Turbine Driven AFW Pump selector switch to Manual.																			

NRC FORM 366A (08-2020)	U.S. NUCLEAR REGULATORY COMMISSION LICENSEE EVENT REPORT (LER) CONTINUATION SHEET	APPROVED BY OMB: NO. 3150-0104 EXPIRES: 08/31/2023	Estimated burden per response to comply with this mandatory collection request: 80 hours. Reported lessons learned are incorporated into the licensing process and fed back to industry. Send comments regarding burden estimate to the FOIA, Library, and Information Collections Branch (T-6 A10M), U.S. Nuclear Regulatory Commission, Washington, DC 20555-0001, or by e-mail to Infocollections.Resource@nrc.gov , and the OMB reviewer at: OMB Office of Information and Regulatory Affairs, (3150-0104), Attn: Desk ail: oir_submission@omb.eop.gov . The NRC may not conduct or sponsor, and a person is not required to respond to, a collection of information unless the document requesting or requiring the collection displays a currently valid OMB control number.		
(See NUREG-1022, R.3 for instruction and guidance for completing this form https://www.nrc.gov/reading-rm/doc-collections/nuregs/staff/sr1022/r3/)					
1. FACILITY NAME	2. DOCKET NUMBER	3. LER NUMBER			
Prairie Island Nuclear Generating Plant, Unit 2	05000306	YEAR	SEQUENTIAL NUMBER	REV NO.	
		2021	- 001	- 00	
NARRATIVE EVENT DESCRIPTION <p>On October 3, 2021, the Prairie Island Nuclear Generating Plant (PINGP) Unit 2 was in Mode 5, Cold Shutdown, at 0 percent power with Non-Safety Related 4160 Volt buses 21 and 22 isolated for maintenance. At 1525 CDT, the 22 Turbine Driven Auxiliary Feedwater (AFW) Pump received an unplanned actuation signal while performing the prerequisite checklists of Surveillance Procedure (SP) 2083A "Unit 2 Integrated SI Test with a Simulated Loss of Offsite Power Train A" when the 22 Turbine Driven AFW Pump selector switch in the Main Control Room was placed in Shutdown Auto from Manual.</p> <p>This event is reportable under 10CFR 50.73(a)(2)(iv)(A) due to a valid Pressurized Water Reactor Auxiliary Feedwater actuation signal, per NUREG 1022, Revision 3.</p>					
EVENT ANALYSIS <p>The 22 Turbine Driven AFW Pump is a part of the PINGP AFW System (EIS CODE: BA). The AFW System automatically supplies feedwater to the steam generators (SG) to remove decay heat from the Reactor Coolant System upon the loss of normal feedwater supply. The AFW system is configured into two redundant trains. One train has a turbine driven AFW pump; the other has a motor driven AFW pump. One automatic start signal for the turbine driven AFW Pump is the loss of both non-safety related 4160 Volt buses that provide power to the Main Feedwater (MFW) pumps. A loss of power for both MFW pumps will start the turbine driven AFW pump to ensure that at least one SG contains enough water to serve as the heat sink for reactor decay heat and sensible heat removal following the reactor trip.</p> <p>With Non-Safety Related 4160 Volt buses 21 and 22 isolated for maintenance, placing the 22 Turbine Driven AFW Pump selector switch in Shutdown Auto completed the automatic start signal causing the associated 22 Turbine Driven AFW Pump Steam Block Valve to open. The turbine and pump did not turn because the equipment was out of service with the steam supply valves closed. The 22 Turbine Driven AFW Pump Steam Block Valve then returned to the closed position on a Low Pump discharge pressure signal.</p>					
ASSESSMENT OF SAFETY CONSEQUENCES <p>The actuation signal for the 22 Turbine Driven AFW Pump did not challenge the ability to maintain safe shutdown conditions. There were no radiological, environmental, or industrial impacts associated with this event. The health and safety of the public and site personnel were not impacted during this event.</p>					
CAUSE OF THE EVENT <p>The cause of this event was a latent procedure error in SP 2083A from when the procedure was changed from testing both trains of the system to testing each of the trains separately.</p>					
CORRECTIVE ACTIONS <p>Operations updated the SP 2083A prerequisite checklist to place the 22 Turbine Driven AFW Pump selector switch to Manual.</p>					
PREVIOUS SIMILAR EVENTS <p>No previous similar events have occurred at PINGP in the prior 3 years.</p>					