

Software Development Kit Release Notes SDK 6.3.4

December 19, 2013

Broadcom
Network Switching

Section 1: About This Document

These are the Release Notes for the Broadcom Network Switching Software Development Kit Release 6.3.4.

This document provides a general description of the release and its new features. It also describes the chips supported by the release, BCM/BCMx API additions or changes, resolved issues, and any relevant open issues.

Section 2: Product Documentation

The following documents are available through Broadcom's Customer Support Portal, <http://support.broadcom.com>. They are the primary source of information and should be referenced when using this release:

Table 1: Product Documentation

<i>Document</i>	<i>Description</i>
56XX-PG634-R	BCM and BCMX API Reference Guide. This manual describes the theory of operations of the API and all existing BCM and BCMX APIs for this release.
56XX-PG707-R	Stacking Software Guide This guide describes how to use the discovery and stacking applications provided in this release.
56XX-PG817-R	Platform Guide This guide describes the SDK source and Makefile structure, abstraction and porting layers, device specific interactions, and the platform/operating system specific features of the SDK. If this is your first time working with the SDK, start with this document.

Section 3: Release Media

The Software Development Kit is released as a gzipped tar file on the Broadcom Customer Support Portal, <http://support.broadcom.com>. The Network Switching Software Platform Guide, also available on the Customer Support Portal, provides documentation on the various components, the source directory layout, how to build the release for various platforms, and how to customize and port the software to new platforms.

Section 4: Support

Questions, feedback, and/or suggestions should be sent to your Broadcom FAE.

Section 5: Firmware Compatibility Matrix

The following table shows compatibility between different versions of SDK and Firmware releases.

BCM56440 FIRMWARE COMPATIBILITY MATRIX

Table 2:

SDK	Firmware 2.0	Firmware 2.1	Firmware 2.2	Firmware 3.0.0	Firmware 3.0.1	Firmware 3.1.0	Firmware 3.2.0	Firmware 3.2.1	Firmware 3.2.2
SDK-6.2.0	Yes	No	No	No	No	No	No	No	No
SDK-6.2.1	No	No	Yes	No	No	No	No	No	No
SDK-6.2.3	No	No	Yes	Yes	Yes	Yes	No	No	No
SDK-6.2.4	No	No	Yes	Yes	Yes	Yes	No	No	No
SDK-6.2.5	No	No	Yes	Yes	Yes	Yes	No	No	No
SDK-6.2.6	No	No	Yes	Yes	Yes	Yes	No	No	No
SDK-6.2.7	No	No	Yes	Yes	Yes	Yes	No	No	No
SDK-6.2.8	No	No	Yes	Yes	Yes	Yes	No	No	No
SDK-6.2.9	No	No	Yes	Yes	Yes	Yes	No	No	No
SDK-6.3.0	No	No	No	Yes	Yes	No	Yes	No	No
SDK-6.3.1	No	No	No	No	No	No	Yes	Yes	Yes
SDK-6.3.2	No	No	No	No	No	No	Yes	Yes	Yes
SDK-6.3.3	No	No	No	No	No	No	Yes*	Yes*	Yes*
SDK-6.3.4	No	No	No	No	No	No	Yes	Yes	Yes

* In order to support embedded applications, a patch is needed to merge the fix for SDK-53008 to SDK 6.3.3 release.

BCM56640 FIRMWARE COMPATIBILITY MATRIX

Table 3:

SDK	Firmware 3.0.0	Firmware 3.0.1	Firmware 3.1.0	Firmware 3.2.0	Firmware 3.2.1	Firmware 3.2.2
SDK-6.2.3	No	No	No	No	No	No
SDK-6.2.4	No	No	No	No	No	No
SDK-6.2.5	Yes	Yes	Yes	No	No	No
SDK-6.2.6	No	No	Yes	No	No	No
SDK-6.2.7	No	No	Yes	No	No	No
SDK-6.2.8	No	No	Yes	No	No	No
SDK-6.2.9	No	No	Yes	No	No	No
SDK-6.3.0	Yes	Yes	No	No	No	No
SDK-6.3.1	No	No	No	Yes	Yes	Yes
SDK-6.3.2	No	No	No	Yes	Yes	Yes
SDK-6.3.3	No	No	No	Yes	Yes	Yes
SDK-6.3.4	No	No	No	Yes	Yes	Yes

BCM88650 FIRMWARE COMPATIBILITY MATRIX

Table 4:

SDK	Firmware 3.0.0	Firmware 3.0.1	Firmware 3.1.0	Firmware 3.2.0	Firmware 3.2.1	Firmware 3.2.2
SDK-6.2.3	Yes	Yes	No	No	No	No
SDK-6.2.4	Yes	Yes	No	No	No	No
SDK-6.2.5	Yes	Yes	No	No	No	No
SDK-6.2.6	No	No	Yes	No	No	No
SDK-6.2.7	No	No	Yes	No	No	No
SDK-6.2.8	No	No	Yes	No	No	No
SDK-6.2.9	No	No	Yes	No	No	No
SDK-6.3.0	Yes	Yes	No	Yes	No	No
SDK-6.3.1	No	No	No	Yes	Yes	Yes
SDK-6.3.2	No	No	No	Yes	Yes	Yes
SDK-6.3.3	No	No	No	Yes	Yes	Yes
SDK-6.3.4	No	No	No	Yes	Yes	Yes

BCM56850 FIRMWARE COMPATIBILITY MATRIX

Table 5:

<i>SDK</i>	<i>Firmware 3.1.0</i>	<i>Firmware 3.2.0</i>	<i>Firmware 3.2.1</i>	<i>Firmware 3.2.2</i>
SDK-6.2.6	Yes	No	No	No
SDK-6.2.7	Yes	No	No	No
SDK-6.2.8	No	Yes	No	No
SDK-6.2.9	No	Yes	No	No
SDK-6.3.0	No	Yes	No	No
SDK-6.3.1	No	Yes	Yes	Yes
SDK-6.3.2	No	Yes	Yes	Yes
SDK-6.3.3	No	Yes	Yes	Yes
SDK-6.3.4	No	Yes	Yes	Yes

BCM88030 FIRMWARE COMPATIBILITY MATRIX

Table 6:

<i>SDK</i>	<i>Firmware 3.2.0</i>	<i>Firmware 3.2.1</i>	<i>Firmware 3.2.1</i>
SDK-6.2.8	Yes	No	No
SDK-6.2.9	Yes	No	No
SDK-6.3.1	Yes	Yes	Yes
SDK-6.3.2	Yes	Yes	Yes
SDK-6.3.3	Yes	Yes	Yes
SDK-6.3.4	Yes	Yes	Yes

BMACSEC SDK COMPATIBILITY MATRIX

Table 7:

<i>Switch SDK Release</i>	<i>BMACSEC SDK Release</i>
5.10.2	3.1
5.10.3	3.2
6.0.1	3.3
5.10.4	3.4
6.0.2	3.4
6.2.0	3.5
5.11.0	3.6
6.2.1	3.7
6.2.2	3.8
6.2.3	3.8
5.11.1	3.9
6.2.4	3.9
6.2.5	3.10
6.2.6	3.11
6.2.7	3.12
6.2.8	3.13
6.2.9	3.14
6.3.0	4.0
6.3.1	4.1
6.3.2	4.2
6.3.3	4.3
6.3.4	4.4

Section 6: New in this Release

This section describes feature and device support that is introduced in this release.

SUMMARY OF NEW FEATURES

TRIDENT2 (BCM56850)

- ALPM feature is GA in this release. The ALPM feature supports, IPv4, IPV6-64 and IPV6-128 routes in Parallel and Combined Modes. To enable ALPM feature compile flag `ALPM_ENABLE` needs to be added to Make.local file.
- The following config properties could be configured for ALPM mode operation. The Trident2 UFT configuration needs to be configured for ALPM mode.

Table 8:

<i>l2_mem_entries</i>	<i>Number of L2 entries</i>	
<code>l3_alpm_enable</code>	The config property <code>l3_alpm_enable</code> need to be configured to enable ALPM.	<ul style="list-style-type: none"> 0 - ALPM Disable 1 - ALPM Parallel Mode 2 - ALPM Combined Mode
<code>ipv6_lpm_128b_enable</code>	Enable V6-128 bit or V6-64 bitroutes.	<ul style="list-style-type: none"> 1 - Enable V6-128bit. Default is disabled. 0 - Enable V6-64bit. Also <code>num_ipv6_lpm_128b_entries</code> should be 0.

- Following table sizes have been verified in 6.3.4 Release

Table 9:

	<i>Parallel Mode</i>	<i>Combined Mode</i>
IPV4	64K + 64K	128K
IPV6-64	21K + 21K	85K
IPV6-128 (50-50 IPV4 Profile)	2.5K + 2.5K / 32K + 32K IPV4	5K / 64K IPV4

ARAD

- Support new IP tunnel termination lookup key {DIP, SIP, IPV4.Next-protocol}. IPV4 next protocol is useful to configure multiple separate VPNs, with same DIP and SIP, but with different tunnel-types.
- Improved TM diagnostics. Display TDM editing: `tdm edit port=x` Use block-level timer to synchronize debug counter readings and allow rate measurements on block level (`GTimer enable/trigger/read/stop`, `diag count interval=x`) Display E2E scheduler rate (`diag rates sch`) Display ingress resources congestion level (`"diag ing_congestion"`)

HELIX4

- APP-IQ has been enhanced. In some case new APIs have been added or existing APIs augmented. The feature improvements fall under the following category. The Flow tracker must be available as an independent entity. It is not necessary for FT to work in conjunction with Signature Match Engine. Provides the ability for Signature Match Engine to just provide/send packets to the HOST CPU (after the match with all information regarding the match made available) so that the Host CPU can install the policy/actions to take for a flow. Allows customers to see the resource usage for a given "Rule" and determine if this can be accommodated. Exposes all Actions and Statistics from HW. Flow tracker is available as an independent entity. It is not necessary for FT to work in conjunction with Signature Match Engine.
- Warmboot feature has been qualified to be BETA quality. SDK release 6.3.4 is also tested for upgrade path from the previous



maintenance release SDK 6.3.3

- Flexport Hotswap - Beta Quality The Flexport hotswap feature is supported for the following SKUs: BCM56340, BCM56342, BCM56344, BCM56040, BCM56041, BCM56547, BCM56548 The following Flexport transitions have been verified on HX4 SKUs. HG[42] -> 2xHGd[21], 4xHGd[11], 4xXFI, 4x1GE, 4x2.5GE HG[21] -> 2xHGd[21], 4xHGd[11], 4xXFI, 4x1GE, 4x2.5GE 2xHGd[21] -> HG[42], 4xXFI, 4x1GE, 4x2.5GE 4xHGd[11] -> HG[42], 2xHGd[21], 4xXFI 2xRXAUI -> HG[42], 2xHGd[21], 4xHGd[11] 4xXFI -> HG[42], 4xHGd[11] 4x1GE -> HG[42], 4xHGd[11] 4x2.5GE -> HG[42] Known issues: The following Flexport transitions are not supported in 6.3.4 due to known issues. Port transitions to 2xRXAUI, HG[21] 4xXFI/ 4x1GE/4x2.5GE to 2xHGd[21]

KATANA2

- Destination Module based VoQ (DMVoQ) is now available. Please note that this feature is still under test.
- SDK now supports additional APIs that allow TR- 101/156/200 compliance. The APIs in the following areas were enhanced create subport Virtual port based on LLVID, LLVID + INNER VID or LLVID + OUTER VID. support the new VLAN TRANSLATE KEY(LLVID, LLVID + INNER VID and LLVID + OUTER VID) to support drop action to deal ltag/unltag packets per chip control of LLTAG relevant attributes Virtual Port cross connect
- Warmboot support is available for preview ONLY.
- Soft Error Recovery infrastructure is complete with the addition of coverage for TCAMs

ARAD+

- Support for IPMC and IGMP-snooping after exiting tunnel (VXLAN, L2GRE, VPLS)
- Support for Trill multi-homing: End-station is multi-homed to multiple RBridges.
- Allow the unicast LAG-LB-Key in stacking to be 16 bits
- OAM events: Support the DMA reroute writes intended to the Interrupt Message Register to a local host memory
- Support OAM accelerated loopback
- Support new IP tunnel termination lookup key {DIP, SIP, IPV4.Next-protocol}. IPV4 next protocol is useful to configure multiple separate VPNs, with same DIP and SIP, but with different tunnel-types.
- Improved TM diagnostics: Display TDM editing: tdm edit port=x Use block-level timer to synchronize debug counter readings and allow rate measurements on block level (GTimer enable/trigger/read/stop, diag count interval=x) Display E2E scheduler rate (diag rates sch) Display ingress resources congestion level ("diag ing_congestion")

CALADAN3

- MPLS RCE: Broadcom G3P1 microcode supports ingress MPLS stream enhanced with RCE lookup customized for MPLS traffic.
- E-Tree: Broadcom Microcode and SDK E-Tree enhancements provide host applications the ability to implement E-Tree services over MPLS networks.
- E-LAN: Broadcom Microcode and SDK enhancements to provide host applications the ability to implement E-LAN solutions specifically related to MPLS PW.
- Support for overlapped tables in assembler, MDE and Model : Broadcom MDE tools supports overlapping of tables in the assembler, model and MDE tools environment.
- PPE table view: MDE User Interface view support for PPE CSV (comma separated values) rules file.
- Full fast set/get support: Some custom streamlined table access methods have been added to MDE to provide faster access to some fields.
- Improved multi-stream editor view: The multi-stream view has been reworked in the MDE to provide editor linkage, better layout and greater flexibility



HURRICANE-2

- Production Ready
- Support for 4x10GE on TSC1 has been added for the following devices 56150, 56151, 56152, 53347, 53346

TRIUMPH-3

- APP-IQ has been enhanced. See HELIX4 ([page 14](#)) for details

WARMBOOT: VALIDATED WARMBOOT UPGRADES.

Following warmboot upgrades have been validated in this release.

Table 10: Validated Warmboot upgrades

<i>Software upgrade</i>	<i>Supported</i>
6.3.3 to 6.3.4	Yes
6.2.9 to 6.3.4	Yes

THINGS TO NOTE

This section lists items that require special attention.

BCM_X API DEPRECATION

BCM_X APIs have not been enhanced or supported for newer devices since SDK-5.10.2. Legacy BCM_X APIs, supported in SDK-5.10.2 will be deprecated starting with SDK-6.3.5 release. Customers are encouraged to transition from BCM_X APIs to their equivalent BCM APIs.

Please contact Broadcom application support for any help in the transition.

WARMBOOT: KNOWN ISSUES

Customers can upgrade from SDK-6.2.9 to SDK-6.3.2 except when Flexible Statistics are used in conjunction with VFP. Customers need to patch the fix for SDK-43743 in order to upgrade to SDK-6.3.2 only when using Flexible Statistics with VFP rules.

Please contact your Broadcom FAE for any help.

BCM8483X PHY FIRMWARE

Status of F/W version 1.67 released with SDK is preview. Check support.broadcom.com for latest available validated firmware for the BCM8483X family devices. Consult F/W release notes for known issues.

BCM8484X PHY FIRMWARE

Status of F/W version 1.06 released with SDK is preview. Check support.broadcom.com for latest available validated firmware for the BCM8484X family devices. Consult F/W release notes for known issues.

SPN_PHY_PORT_PRIMARY_AND_OFFSET

Setting of the config property `spn_PHY_PORT_PRIMARY_AND_OFFSET` is absolutely required for the following PHYs. BCM54880E BCM54680E BCM54682E BCM54685E BCM54640E BCM542XX

BCM56850 HANDLING OF MODULE_64PORTS

Setting `module_64ports=1` config variable indicates that one module ID covers 64 ports. Please, note that while on the earlier devices this effectively meant choosing a single-modid mode for the device due to the fact that the total number of ports was less than 64, on devices that have more than 64 ports, such as BCM56850 (what about 56840?) it means choosing dual-modid mode instead. Please, always use `bcm_stk_modid_count()` to get the actual number of modids required by a given device. Also, note that the API `bcm_port_gport_get()` is the only correct way to translate the physical port number into a `MODPORT_GPORT` and it works correctly regardless of the number of modids assigned to the device

OCCASIONAL STACK ATTACH FAILURES

There may be occasional stack attach failures due to the stack master attaching a slave device before slave programming is complete. Use the `stk.soc` config variable `stktopomasterdelay` to increase the length of time the stack master will wait before attaching a slave.



UNBALANCED MUTEX WARNING

A potential issue with unbalanced mutexes has been uncovered in previous releases of SDK and special code has been added to automatically detect that condition. While we believe that we've identified all these issues in our regression testing, there is a slight probability that you can see the following message on the console:

WARNING: Mutex "mutex_name" has not been unlocked before being destroyed.

Current owner is "thread_name" .

Should you see such a warning, please, copy it verbatim and contact Broadcom Support.

BCM PORT CONTROLS

A set of BCM port controls `bcm_port_control_t` have changed their enumeration values between SDK-6.3.0 and SDK-6.3.1.

The implication is that RPC between systems running SDK-6.3.0 on one and SDK-6.3.1 on another will not work properly for BCM port controls.

IP ROUTE LOOKUP

If a packet destination IP lookup falls in between 2 route prefixes having a common prefix part and differing lengths, then the lower route prefix, which is the correct match, may not always be returned correctly.

NEW DEVICES AND SYSTEMS

For any given SDK release, support for certain devices may be provided in Preview or Supported status. Devices in preview status are provided to allow early integration of the customer's application with the SDK APIs that support that device. This software has not been tested on the physical target device and should not be expected to fully function.

Devices in "Supported" status have completed the full QA process and are intended for use in production systems. It is expected that customers would integrate the version of the SDK which provides "Supported" status for their use on actual development or production systems.

Table 11: Supported Switch Devices

Family	Devices	Description
BCM56230	BCM56230 B1	12-Port GbE Multilayer Switch
BCM56231	B1	6-Port GbE Multilayer Switch
BCM56340	BCM56040 A0	1xF.QSGMII + 3xF.HG[42] + 1GE
BCM56340	BCM56042	12x2.5GE/1GE + 12x2.5GE/1GE + 1GE
BCM56340	BCM56344	10xF.QSGMII + 3xFlex[4x10] + 1GE
BCM56640	BCM56045 B0	3xF.40GE + 3xF.HG[42] + 1GE
BCM56640	BCM56046 B0	3xF.40GE + 2xF.HG[42] + 1GE
BCM56340	BCM56340 A0	12xF.QSGMII + Flex[4x10] + 2xHG[21] + 1GE, 12xF.QSGMII + 4xSGMII + 2xXFI + 2xHGd[21] + 1GE
BCM56340	BCM56342 A0	7xF.QSGMII + Flex[4x10] + 2xHG[21] + 1GE
BCM56450	BCM56450 A0	24-port GbE Multilayer Switch with 4-port 10 GbE uplinks, stacking, integrated CPU and Traffic Manager
BCM56450	BCM56455	2 x 20GE (G.INT) + 2 x HG13
BCM56450	BCM56456	1 x XAUI + 8 x GE
BCM56544	BCM56544 B0	10xF.XAUI + 4xHG[21] + 1GE, 10xF.XAUI + 4xXFI, 10xF.XAUI + 2xHG[42], 4xXAUI + 12xXFI + 1GE Multilayer Ethernet Switch
BCM56545	BCM56545 B0	48xGE + 2xHG[42] + 2xHG[21] + 1GE, 48xGE + 4xXFI + 2xHG[42] + 1GE, 48xGE + 8xXFI + 1GE, 24xGE + 4xXAUI + 2xXFI + 2xHG[12] + 1GE Multilayer Ethernet Switch
BCM56340	BCM56547 A0	10xF.QSGMII + 3xF.HG[42] + 1GE, 12xF.QSGMII + 2xF.HG[42] + 1GE, 12xF.QSGMII + F.HG[42] + 2xHG[42] + 1GE
BCM56340	BCM56548 A0	7xF.QSGMII + 3xF.HG[42] + 1GE
BCM56850	BCM56830 A1	960Gbps Ethernet Switch
BCM56850	BCM56751P A2	1.28Tbps I/O, 960Gbps Core Ethernet Switch Fabric
BCM56850	BCM56751P A1	1.28Tbps I/O, 960Gbps Core Ethernet Switch Fabric
BCM56850	BCM56830 A1	960Gbps Ethernet Switch
BCM56850	BCM56830 A2	960Gbps Ethernet Switch
BCM56851	BCM56751 A2	1.28Tbps I/O, 960Gbps Core Ethernet Switch Fabric
BCM88650	BCM88650 B1	200 GBps DNX Traffic Manager and Packet Processor
BCM88030	BCM88030 A0	Scalable Switching 100Gbps Full-Duplex Programmable Packet Processor
88660	88660 A0	DNX 200G Flexible Packet Processor with Integrated Traffic Management
BCM56340	BCM56041	Ranger device, meant for embedded connectivity supports 1Ge (port 49), 2 X GE (iPROC), Flex 4x10G, 3 X 4 X 10G
BCM56850	BCM56852 A2	100x10G, 960Gbps Multilayer Switch

Table 12: Preview Switch Devices

Family	Devices	Description
BCM56450	BCM55455	Katana2 Access 1 x XAUI + 8 x GE without L3 routing and MPLS features



Table 13: Preview PHYS

Device	Driver Family	Description
BCM84780	BCM84740	Octal-Channel 10 GbE SFI-to-XFI PHY with 1588. Firmware version 0x128 Implemented <code>postcursor2_tap</code> config setting in preemphasis set/get API. Add PRBS support for 1Gbps mode. Enhance Interface set/get. Expose Squelching & Polarity flip to user through <code>control_set</code> .
BCM84784	BCM84740	Dual 40GbE/Octal 10GbE QSFP+ XLPPI-to-XLAUI PHY. Firmware version 0x125 Implemented <code>postcursor2_tap</code> config setting in preemphasis set/get API. Add PRBS support for 1Gbps mode. Enhance Interface set/get. Expose Squelching & Polarity flip to user through <code>control_set</code> .
BCM84758	BCM84740	10GbE Quad SFI-XFI PHY with IEEE 1588 Firmware version 0x128 Implemented <code>postcursor2_tap</code> config setting in preemphasis set/get API. Add PRBS support for 1Gbps mode. Enhance Interface set/get. Expose Squelching & Polarity flip to user through <code>control_set</code> .
BCM84164	BCM84740	Quad 10GBASE-KR-to-XFI or 40GBASE-KR4-to-XLAUI Transceiver Firmware version 0x128 Add PRBS support for 1Gbps mode. Bug fix for Auto negotiation. Enhance Interface set/get. Expose Squelching & Polarity flip to user through <code>control_set</code> .
BCM84168	BCM84740	Octal 10GBASE-KR-to-XFI or Dual 40GBASE-KR4-to-XLAUI Transceiver. Firmware version 0x128 Add PRBS support for 1Gbps mode. Bug fix for Auto negotiation. Enhance Interface set/get. Expose Squelching & Polarity flip to user through <code>control_set</code> .
BCM82328	BCM82328	Dual 40 GbE/Octal 10 GbE QSFP+ XLPPI-to-XLAUI PHY. Firmware version 6 "(Preview) CR/CR4 preview support is added i.e. new FW version 0x6 Fast eyescan support is added. DSC support is added. Setting of config property <code>spn_PHY_MOD_AUTO_DETECT</code> is added
BCM84741 B0	BCM84756	40GbE XLPPI-to-XLAUI/Quad 10G with IEEE MACsec/1588 Firmware version 0x0128 [Preview]
BCM84333_B1	8481	Quad 10GBASE-T Transceiver. Firmware version 1.67 (Preview) (Needs additional software component)

SUMMARY OF BCM API CHANGES

This section summarizes BCM and BCMX API changes in this release. Complete documentation is available in the Network Switching Software Programmer's Guide [**56XX-PG634-R]. (See section 2 earlier in this document for availability).

SECURITY

New Authentication mode flag has been added.

- `BCM_AUTH_DROP_UNKNOWN` - Drop SLF packets without L2 learning while authorized

BIDIRECTIONAL FORWARDING DETECTION

BFD ENDPOINT INFO

New field has been added to `bcm_bfd_endpoint_info_s` structure.

```
typedef struct bcm_bfd_endpoint_info_s {
    ...
    bcm_bfd_endpoint_t remote_id; /* remote endpoint identifier */
    ...
} bcm_bfd_endpoint_info_t;
```

CLASS OF SERVICE CONFIGURATION

New COSQ control types have been added.

Table 14: CoSQ Control Type Values

<i>Value</i>	<i>Description</i>	<i>Arg value</i>
<code>bcmCosqControlPortQueueUcast</code>	According to port and cosq, retrieve hw queue number used by PBSMH UC header	hw queue number of PBSMH UC packet headers.
<code>bcmCosqControlPortQueueMcast</code>	According to port and cosq, retrieve hw queue number used by PBSMH MC header	hw queue number of PBSMH MC packet headers.

New enums for CosQ controls for drop limit alpha values have been added.

Table 15: `bcmCosqControlDropLimitAlpha` Arg value

<i>Name</i>	<i>Description</i>
<code>CosqControlDropLimitAlpha_1_64</code>	Use 1/64 as the alpha value for dynamic threshold.
<code>CosqControlDropLimitAlpha_1_32</code>	Use 1/32 as the alpha value for dynamic threshold.
<code>CosqControlDropLimitAlpha_1_16</code>	Use 1/16 as the alpha value for dynamic threshold.
<code>CosqControlDropLimitAlpha_1_8</code>	Use 1/8 as the alpha value for dynamic threshold.
<code>CosqControlDropLimitAlpha_1_4</code>	Use 1/4 as the alpha value for dynamic threshold.
<code>CosqControlDropLimitAlpha_1_2</code>	Use 1/2 as the alpha value for dynamic threshold.
<code>CosqControlDropLimitAlpha_1</code>	Use 1 as the alpha value for dynamic threshold.
<code>CosqControlDropLimitAlpha_2</code>	Use 2 as the alpha value for dynamic threshold.
<code>CosqControlDropLimitAlpha_4</code>	Use 4 as the alpha value for dynamic threshold.



Table 15: bcmCosqControlDropLimitAlpha Arg value

Name	Description
CosqControlDropLimitAlpha_1_128	Use 1/128 as the alpha value for dynamic threshold.
CosqControlDropLimitAlpha_8	Use 8 as the alpha value for dynamic threshold.

Following CosQ API's have been modified .

bcm_cosq_bst_profile_set **bcm_cosq_bst_profile_get**

Set/Get the BST profile for CosQ objects

Syntax

```
#include <bcm/cosq.h>
int bcm_cosq_bst_profile_set(int unit, bcm_gport_t port,
                             bcm_cos_queue_t cosq, bcm_bst_stat_id_t bid,
                             bcm_cosq_bst_profile_t *profile);
```

Parameters

unit	BCM device number
port	Device or logical port or GPORT ID
cosq	Cosq object offset identifier
bid	BST stat ID to identify the COSQ resource/object
profile	BST profile configuration

Description

Configure or retrieve the BST (buffer statistics tracking) configuration for the specified MMU resource. MMU resource is identified by the combination of port, cosq and bid parameters. port parameter can be port gport, queue gport. bid parameter identifies the MMU resource, for instance the bid bcmBstStatIdEgrPool identifies the egress service pool resource. cosq parameter identifies the object within the various instances of resources within the identified resource.

The bid parameter can be one of the following from the table

Table 16: BCM BST CoSQ IDs

flag	Description
bcmBstStatIdDevice	Device wide resource
bcmBstStatIdEgrPool	Egress service pool
bcmBstStatIdIngPool	Ingress service pool
bcmBstStatIdPortPool	Shared pool per port per service pool
bcmBstStatIdPriGroupShared	Priority group
bcmBstStatIdPriGroupHeadroom	Headroom buffer
bcmBstStatIdUcast	unicast queue
bcmBstStatIdMcast	multicast queue

```
typedef struct bcm_cosq_bst_profile_s {
    uint32 byte;
```



```
} bcm_cosq_bst_profile_t;
```

Returns

BCM_E_NONE

BCM_E_XXX

bcm_cosq_bst_stat_sync

Sync the HW stats value to SW copy for all or given BST resource.

Syntax

```
#include <bcm/cosq.h>
int bcm_cosq_bst_stat_sync(int unit, bcm_bst_stat_id_t bid);
```

Parameters

unit	BCM device number
bid	BST stat ID to identify the COSQ resource/object

Description

API to sync the Hardware stats for all or given BST resources to the Software copy. During this sync, BST status will be disabled, in order to maintain consistency of the stats to a defined time and Post sync, the BST status will be restored. This is required to be used before calling `bst_stat_get()` to get latest or updated stats value.

Returns

BCM_E_NONE

BCM_E_XXX

bcm_cosq_bst_stat_get

Get the current statistic/count of specified BST profile

Syntax

```
#include <bcm/cosq.h>
int bcm_cosq_bst_stat_get(int unit, bcm_gport_t gport, bcm_cos_queue_t
cosq,
                                bcm_bst_stat_id_t bid, uint32 options,
uint64 *pvalue);
```

Parameters

unit	BCM device number
port	Device or logical port or GPORT ID
cosq	Cosq object offset identifier
bid	BST stat ID to identify the COSQ resource/object
options	options to perform clear-on-read
pvalue	stat value to return.

Description

Retrieve the BST (buffer statistics tracking) statistic for the specified MMU resource. MMU resource is identified by the combination of port, cosq and bid parameters. port parameter can be port gport, queue gport. bid parameter identifies the MMU resource, for instance the flag bcmBstStatIdEgrPool identifies the egress service pool resource. cosq parameter identifies the object within the various instances of resources within the identified resource. if option BCM_COSQ_STAT_CLEAR is present, a memory/register clear will be performed after stat reading.

Returns

BCM_E_NONE
BCM_E_XXX

bcm_cosq_bst_stat_multi_get

Get the current statistic/count of multiple specified BST profile

Syntax

```
#include <bcm/cosq.h>
int bcm_cosq_bst_stat_multi_get(int unit, bcm_gport_t gport,
bcm_cos_queue_t cosq,
                                uint32 options, int max_values,
bcm_bst_stat_id_t *id_list, uint64 *values);
```


Parameters

unit	BCM device number
gport	Device or logical port or GPORT ID
cosq	Cosq object offset identifier
options	options to perform clear-on-read
max_values	Number of elements in id_list and pvalue
id_list	Array of BST stat ID list to identify the COSQ resource/object
pvalue	Array of stat value to return.

Description

Retrieve the BST (buffer statistics tracking) statistic for multiple specified MMU resource. MMU resource is identified by the combination of port, cosq and bid parameters. port parameter can be port gport, queue gport. bid parameter identifies the MMU resource, for instance the flag bcmBstStatIdEgrPool identifies the egress service pool resource. cosq parameter identifies the object within the various instances of resources within the identified resource. if option BCM_COSQ_STAT_CLEAR is present, a memory/register clear will be performed after stat reading.

Returns

BCM_E_NONE
BCM_E_XXX

bcm_cosq_bst_stat_clear

Clear the current statistic/count of specified BST profile

Syntax

```
#include <bcm/cosq.h>
int bcm_cosq_bst_stat_clear(int unit, bcm_gport_t gport,
bcm_cos_queue_t cosq,
                        bcm_bst_stat_id_t bid);
```

Parameters

unit	BCM device number
gport	Device or logical port or GPORT ID
cosq	Cosq object offset identifier
bid	BST stat ID to identify the COSQ resource/object

Description

Clear the BST (buffer statistics tracking) statistic for the specified MMU resource. MMU resource is identified by the combination of port, cosq and bid parameters. port parameter can be port gport, queue gport. bid parameter identifies the MMU resource, for instance the bid bcmBstStatIdEgrPool identifies the egress service pool resource. cosq parameter identifies the object within the various instances of resources within the identified resource.

Returns

BCM_E_NONE

BCM_E_XXX

bcm_cosq_stat_sync_get bcm_cosq_stat_sync_get32

Force an immediate counter update and retrieve MMU drop statistics.

Syntax

```
#include <bcm/cosq.h>
int
bcm_cosq_stat_sync_get(
    int unit,
    bcm_gport_t gport,
    bcm_cos_queue_t cosq,
    bcm_cosq_stat_t stat,
    uint64 *value);
int
bcm_cosq_stat_sync_get32(
    int unit,
    bcm_gport_t gport,
    bcm_cos_queue_t cosq,
    bcm_cosq_stat_t stat,
    uint32 *value);
```

Parameters

unit	(IN) Unit number.
gport	(IN) GPORT ID.
cosq	(IN) CoS Queue.
stat	(IN) Statistic to be retrieved. See table
value	(OUT) (for "_get") statistic value.
value	(IN) (for "_set") statistic value.

Description

Similar to `bcm_cosq_stat_get()`, value returned is software accumulated counter synced with the hardware counter.

Returns

BCM_E_NONE

BCM_E_XXX

FIBER CHANNEL OVER ETHERNET

Following new fields have been added to bcm_fcoe_intf_config_t structure.

```
typedef struct bcm_fcoe_intf_config_s {
    ...
    bcm_fcoe_intf_vsan_id_source_t vsan_source;
    bcm_fcoe_intf_vsan_pri_source_t vsan_pri_source;
} bcm_fcoe_intf_config_t;

/* FCOE Interface VSAN ID source */
typedef enum bcm_fcoe_intf_vsan_id_source_e {
    bcmFcoeIntfVsanSet,          /* Get VSAN ID from table entry */
    bcmFcoeIntfVsanInternal,     /* Get VSAN ID from internal VSAN ID */
    bcmFcoeIntfVsanInnerVlan,    /* Get VSAN ID from internal ITAG */
    bcmFcoeIntfVsanOuterVlan     /* Get VSAN ID from internal OVID */
} bcm_fcoe_intf_vsan_id_source_t;

/* FCOE Interface VSAN Priority source */
typedef enum bcm_fcoe_intf_vsan_pri_source_e {
    bcmFcoeIntfVsanPriSet,       /* Use VSAN PRI from table entry */
    bcmFcoeIntfVsanPriInternal,  /* Get VSAN PRI from internal VSAN
PRI */
    bcmFcoeIntfVsanPriRemark     /* Get VSAN PRI from internal PRI */
} bcm_fcoe_intf_vsan_pri_source_t;
```

Following flags have been deprecated and enums have been added instead.

```
#define BCM_FCOE_INTF_VSAN_SET          0x00000008 /* From Egress
Interface */
#define BCM_FCOE_INTF_VSAN_INTERNAL     0x00000010 /* From Internal
Vsan ID */
#define BCM_FCOE_INTF_VSAN_INNER_VLAN   0x00000020 /* From Inner-VID */
#define BCM_FCOE_INTF_VSAN_OUTER_VLAN   0x00000040 /* From Outer-VID */
#define BCM_FCOE_INTF_VSAN_PRI_SET      0x00000080 /* From Egress
interface */
#define BCM_FCOE_INTF_VSAN_PRI_INTERNAL 0x00000100 /* From Internal
Vsan Pri */
#define BCM_FCOE_INTF_VSAN_PRI_REMARK   0x00000200 /* Remark using
QOS map id */
```

New FCOE VSAN translate keys have been added.

Table 17: FCOE VSAN Translate Keys

<i>Name</i>	<i>heading Purpose</i>
bcmFcoeVsanTranslateKeyInvalid	Invalid Key Type
bcmFcoeVsanTranslateKeyDouble	Use O-VID and I-VID, use only with BCM_FCOE_VSAN_ACTION_INGRESS flag
bcmFcoeVsanTranslateKeyOuter	Use O-VID, use only with BCM_FCOE_VSAN_ACTION_INGRESS flag
bcmFcoeVsanTranslateKeyInner	Use I-VID, use only with BCM_FCOE_VSAN_ACTION_INGRESS flag
bcmFcoeVsanTranslateKeyOuterTag	Use O-TAG, use only with BCM_FCOE_VSAN_ACTION_INGRESS flag
bcmFcoeVsanTranslateKeyInnerTag	Use I-TAG, use only with BCM_FCOE_VSAN_ACTION_INGRESS flag
bcmFcoeVsanTranslateKeyOuterPri	Use (VLAN-PRI, VLAN-CFI of O-TAG), use only with BCM_FCOE_VSAN_ACTION_INGRESS flag
bcmFcoeVsanTranslateKeyPortDouble	Use Port, O-VID and I-VID, use only with BCM_FCOE_VSAN_ACTION_INGRESS flag
bcmFcoeVsanTranslateKeyPortOuter	Use Port, O-VID, use only with BCM_FCOE_VSAN_ACTION_INGRESS flag
bcmFcoeVsanTranslateKeyPortInner	Use Port, I-VID, use only with BCM_FCOE_VSAN_ACTION_INGRESS flag
bcmFcoeVsanTranslateKeyPortOuterTag	Use Port, O-TAG, use only with BCM_FCOE_VSAN_ACTION_INGRESS flag
bcmFcoeVsanTranslateKeyPortInnerTag	Use Port, I-TAG, use only with BCM_FCOE_VSAN_ACTION_INGRESS flag
bcmFcoeVsanTranslateKeyPortOuterPri	Use Port, (VLAN-PRI, VLAN-CFI of O-TAG), use only with BCM_FCOE_VSAN_ACTION_INGRESS flag
BcmFcoeVsanTranslateKeyPortDoubleVsan	Use Port, I-VID, O-VID and VSAN-ID
bcmFcoeVsanTranslateKeyPortInnerVsan	Use Port, I-VID and VSAN-ID
bcmFcoeVsanTranslateKeyPortOuterVsan	Use Port, O-VID and VSAN-ID

FIELD PROCESSOR

New BCM FIELD Data Formats for MPLS packet have been added.

Table 18: Number of MPLS Labels

<i>Mpls Flags</i>	<i>Purpose</i>
BCM_FIELD_DATA_FORMAT_MPLS_THREE_LABELS	Three labels MPLS packet.
BCM_FIELD_DATA_FORMAT_MPLS_FOUR_LABELS	Four labels MPLS packet.
BCM_FIELD_DATA_FORMAT_MPLS_FIVE_LABELS	Five labels MPLS packet.

New BCM FIELD Data Formats for have been added.

Table 19: Misc Flags

<i>Misc Flags</i>	<i>Purpose</i>
BCM_FIELD_DATA_FORMAT_F_ENCAP_STACK	Indicates incoming packet is a Higig Packet.
BCM_FIELD_DATA_FORMAT_F_MASK	Mask.

New Field has been added to `bcm_field_data_packet_format_t` structure.

```
/* Packet format based DATA qualifier specification structure. */
typedef struct bcm_field_data_packet_format_s {
    ...
    uint32 flags; /* Flags. (FIELD_DATA_FORMAT_F_XXX) */
} bcm_field_data_packet_format_t;
```

New BCM Field Fibre Channel Zone Check values have been added.

Table 20: FibreChanZoneCheck values (for `bcm_field_qualify_FibreChanZoneCheck`)

BCM_FIELD_FIBRE_CHAN_ZONE_CHECK_XXX	Purpose
BCM_FIELD_FIBRE_CHAN_ZONE_CHECK_NOT_DO NE	Zone Check is not enabled
BCM_FIELD_FIBRE_CHAN_ZONE_CHECK_ALLOW	Zone Check entry Hit and action is Allow
BCM_FIELD_FIBRE_CHAN_ZONE_CHECK_MISS	Zone Check entry Miss
BCM_FIELD_FIBRE_CHAN_ZONE_CHECK_DENY	Zone Check entry Hit and action is Deny

New Field Qualifiers have been added.

Table 21: Field Qualifiers

Qualifier	Purpose
bcmFieldQualifyOamMdl	Qualifies OAM Maintenance Domain Levels.

New Field Actions have been added.

Table 22: Field Actions

Action	Description	param0	param1
bcmFieldActionEtagNew	Replace packet Port Extender ETAG if present, add if not present. Action will be taken irrespective of the incoming packet color.	ETAG	n/a
bcmFieldActionEtagDelete	Delete packet Port Extender ETAG. Action will be taken irrespective of the incoming packet color.	n/a	n/a

New Field has been added to `bcm_field_group_config_t` structure.

```
/*
 * Group configuration structure. Used to create a field group with
 * specific attributes.
```

```
        */
        typedef struct bcm_field_group_config_s {
            ...
            int max_entry_priorities;          /* Number of entries priorities
in the                                         group. 0 means unlimited. */

        } bcm_field_group_config_t;

        typedef bcm_field_group_config_t      bcmx_field_group_config_t;
```

New Field APIs have been added.

bcm_field_qualify_XXX

Add a qualification to a field entry

Syntax

```
#include <bcm/field.h>

int bcm_field_qualify_HiGigProxy(int unit, bcm_field_entry_t entry,
                                uint8 data, uint8 mask);

int bcm_field_qualify_OamMdl(int unit, bcm_field_entry_t entry,
                             uint8 data, uint8 mask);
```

Parameters

unit	BCM device number
entry	Field entry ID
data	Data to match against
mask	Mask to choose which bits of data to match against
range	Which range checker to qualify on
invert	Invert range checker if 1; clear range check if negative

Description

Adds a qualification to a filter entry. Each qualification added makes the entry more specific and match fewer possible packets.

bcm_field_qualify_XXX_get

Get a qualification match criteria from a field entry

Syntax

```
#include <bcm/field.h>

int bcm_field_qualify_HiGigProxy_get(int unit, bcm_field_entry_t entry,
                                     uint8 *data, uint8 *mask);
```

```
int bcm_field_qualify_OamMdl_get(int unit, bcm_field_entry_t entry,
                                uint8 *data, uint8 *mask);
```

Parameters

unit	BCM device number
entry	Field entry ID
data	Data to match against
mask	Mask to choose which bits of data to match against

Description

Get a match criteria for a specific qualifier from a field entry.

KERNEL NETWORK (KNET) CONFIGURATION

New Rx packet filters have been added.

```
typedef struct bcm_knet_filter_s {
    ...
    int dest_proto;                /* If non-zero this value overrides the
                                   default protocol type when matching
                                   packet is passed to network stack. */
    ...
    int mirror_proto;             /* If non-zero this value overrides the
                                   default protocol type when matching
                                   packet is passed to network stack. */
    ...
} bcm_knet_filter_t;
```

L2GRE

New L2GRE VPN flags have been added.

Table 23: L2GRE VPN flags

BCM_L2GRE_VPN_REPLACE	Replace attributes of an existed VPN
BCM_L2GRE_VPN_UNKNOWN_UCAST_REPLACE	Replace unknown unicast mc-group of an existed VPN
BCM_L2GRE_VPN_UNKNOWN_MCAST_REPLACE	Replace unknown multicast mc-group of an existed VPN
BCM_L2GRE_VPN_BCAST_REPLACE	Replace broadcast mc-group of an existed VPN

L2GRE port flag has been deprecated.

Table 24: L2GRE port flags

Name	Purpose
BCM_L2GRE_MULTIPATH	Create L2GRE port with specified ID

LAYER 3 MANAGEMENT

New Layer 3 flags have been added.

Table 25: BCM Layer 3 Flags

<i>Name</i>	<i>Purpose</i>
BCM_L3_ECMP_RH_REPLACE	Replace ECMP member without RH flowset table shuffle.

OPERATIONS, ADMINISTRATION, AND MAINTENANCE

OAM LOSS MEASUREMENT OBJECT

New OAM Loss Measurement flag has been added.

Table 26: OAM Loss Measurement Flag Definitions

<i>Flag</i>	<i>Description</i>
BCM_OAM_LOSS_UPDATE	Update LM settings for given endpoint (statistics remain unchanged).

OAM DELAY MEASUREMENT OBJECT

New OAM Delay Measurement flag has been added.

Table 27: OAM Delay Measurement Flag Definitions

<i>Flag</i>	<i>Description</i>
BCM_OAM_DELAY_UPDATE	Update DM settings for given endpoint (statistics remain unchanged).

OAM LOOPBACK OBJECTS

New field has been added to `bcm_oam_loopback_t` structure.

```

/* OAM loopback object. */
typedef struct bcm_oam_loopback_s {
    ...
    bcm_mac_t peer_da_mac_address /* MAC DA in Loopback
injection, in
                                case remote_id is not specified */
} bcm_oam_loopback_t;

```

New OAM Loopback flag has been added.

Table 28: OAM Loopback Flag Definitions

<i>Flag</i>	<i>Description</i>
BCM_OAM_LOOPBACK_UPDATE	Update loopback settings for given endpoint (statistics remain unchanged).

POLICER CONFIGURATION

New Policer Group Mode has been added.

Table 29: Policer Group Modes

<i>Mode</i>	<i>Description</i>
bcmPolicerGroupModeShortIntPri	A set of 8 policers based on internal priority

New Policer flag has been added.

Table 30: Policer Flags

<i>Mode</i>	<i>Purpose</i>
BCM_POLICER_MIXED_MICRO_MACRO	Micro Policer not associated to Hierarchy/Macro Envelope.

PORT CONFIGURATION

New Port Controls have been added.

Table 31: bcm_port_control_t

<i>bcmPortControlRxFastLOS</i>	<i>Enable/disable accelerated linkscan capability on port.</i>
bcmPortControlStatCollectionEnable	Enable/disable the gathering of MIB statistics on the port.
bcmPortControlFcoeTranslateKeyFirst	Sets FCOE VSAN translation first key type, use with bcm_fcoe_vsan_translate_key_t types
bcmPortControlFcoeTranslateKeySecond	Sets FCOE VSAN translation second key type, use with bcm_fcoe_vsan_translate_key_t types
bcmPortControlMmuDrain	Request to drain the cells of the port.
bcmPortControlMmuTrafficEnable	Request to enable/disable enqueueing the packets to the port.

New Port PHY Controls for RX LOS have been added.

Table 32: RX_LOS Values

<i>Value</i>	<i>Meaning</i>
BCM_PORT_PHY_CONTROL_RX_LOS_NONE	Specify to Disable Software/Firmware Rx Los Feature
BCM_PORT_PHY_CONTROL_RX_LOS_SOFTWARE	Specify to Enable Software Rx Los Feature
BCM_PORT_PHY_CONTROL_RX_LOS_FIRMWARE	Specify to Enable Firmware Rx Los Feature

New Port PHY control has been added.

New Generic Port match flags have been added.

Table 33: Generic Port Match Criteria

<i>BCM_PORT_MATCH_PORT_VLAN16</i>	<i>Match on the physical port and outer VLAN Tag.</i>
<i>BCM_PORT_MATCH_PORT_PON_TUNNEL_PCP</i>	Mod/port/trunk + PON Tunnel Value + Outer PCP.

New Port Class Id selection has been added.

REGEX API

New flag has been added to `bcm_regex_config_t`.

Table 34: *bcm_regex_config_t* flags

<i>flag Value</i>	<i>Description</i>
<i>BCM_REGEX_USE_POLICY_ID</i>	Actions are provided to matches via policies.

New flag has been added to report events

Table 35: *bcm_regex_config_t* report_flags

<i>flag Value</i>	<i>Description</i>
<i>BCM_REGEX_REPORT_ALL</i>	Provide all notifications including when a session does not match.

New fields have been added to `bcm_regex_match_t` structure.

```

typedef struct bcm_regex_match_s {
    ...
    int sig_id; /* The signature ID assigned
by the SDK */
    bcm_regex_policy_t policy_id; /* The ID of the policy to
be used if
BCM_REGEX_USE_POLICY_ID is
configured. */
} bcm_regex_match_t;
```

New flag has been added to `bcm_regex_match_t`.

Table 36: *bcm_regex_match_t* flags

<i>flag Value</i>	<i>Description</i>
<i>BCM_REGEX_MATCH_SIG_ID_RETURN</i>	Return the hardware signature ID.

The value `BCM_REGEX_MAX_PATTERN_SIZE` specifies the size of the largest regular expression pattern that can be configured as part of a match.

- `BCM_REGEX_MAX_PATTERN_SIZE`

New fields have been added to `bcm_regex_report_t` structure.

```
typedef struct bcm_regex_report_s {  
    ...  
    uint32 refresh_timestamp;    /* Session refresh packet timestamp  
(10ms granularity). */  
} bcm_regex_report_t;
```

bcm_regex_get_match_id

Return user-provided Match ID for a created signature ID.

Syntax

```
#include <bcm/bregex.h>  
int bcm_regex_get_match_id(int unit,  
                           int signature_id,  
                           int *match_id);
```

Parameters

<code>unit</code>	(IN) Unit number.
<code>signature_id</code>	(IN) Signature ID for which to get Match ID
<code>match_id</code>	(OUT) Match ID used when signature created

Description

`bcm_regex_get_match_id` will return the user-provided match ID for a given hardware signature.

Returns

BCM_E_XXX

bcm_regex_get_sig_id

Return hardware Signature ID for a user provided Match ID.

Syntax

```
#include <bcm/bregex.h>  
int bcm_regex_get_sig_id(int unit,  
                         int match_id,  
                         int *signature_id);
```

Parameters

unit	(IN) Unit number.
match_id	(IN) Match ID for which to get Signature ID
signature_id	(OUT) Signature ID used when signature created

Description

bcm_regex_get_sig_id returns the hardware signature ID for a user-provided match ID.

Returns

BCM_E_XXX

bcm_regex_engine_info_get

Return information about the Signature Matching Engine.

Syntax

```
#include <bcm/bregex.h>
int bcm_regex_engine_info_get(int unit,
                              int engine_id,
                              bcm_regex_engine_info_t *regex_engine_info);
```

Parameters

unit	(IN) Unit number.
engine_id	(IN) Engine ID for which to get the info.
regex_engine_info	(OUT) Information about the signature matching engine.

Description

Returns info about a particular engine or all engines. The info is returned in a `bcm_regex_engine_info_t` structure:

```
typedef struct bcm_regex_engine_info_s {
    int size;          /* Static size of largest memory that a single
engine (or
                        SME) can use. */
    int free_size;     /* Available free memory on the specified engine,
or on all
                        engines. */
} bcm_regex_engine_info_t;
```

The value `BCM_REGEX_ENGINE_ALL` used as `engine_id` in the `bcm_regex_engine_info_get` API specifies that the info to be returned is for all engines (i.e. the whole SME).

- `BCM_REGEX_ENGINE_ALL`

Returns

BCM_E_XXX

bcm_regex_info_get

Return various info about the Flow Tracker Session and Policy tables.

Syntax

```
#include <bcm/bregex.h>
int bcm_regex_info_get(int unit,
                       bcm_regex_info_t *regex_info);
```

Parameters

unit	(IN) Unit number.
regex_info	(OUT) Information about the FT session and policy

Description

`bcm_regex_info_get` returns information about the session and policy tables in a `bcm_regex_info_t` structure. The format of the structure is:

```
typedef struct bcm_regex_info_s {
    int session_size;           /* Static size of entire Flow Tracker
session table. */
    int session_free_size_ipv4; /* Total free memory for IPv4 sessions
available in the FT. */
    int session_free_size_ipv6; /* Total free memory for IPv6 sessions
available in the FT. */
    int policy_size;           /* Size of the Flow Tracker policy
table (number of entries). */
    int policy_free_size;      /* Free entries in the Flow Tracker
policy table. */
} bcm_regex_info_t;
```

Returns

BCM_E_XXX

bcm_regex_stat_get

Retrieve a specified regex Flow Tracker statistic.

Syntax

```
#include <bcm/bregex.h>
int bcm_regex_stat_get(int unit,
                       bcm_regex_stat_t type,
                       uint64 *val);
```

Parameters

unit	(IN) Unit number.
type	(IN) The enum value of the statistic to get.
val	(OUT) Value of the Flow Tracker statistic specified in

Description

`bcm_regex_stat_get` returns one of the flow tracker statistics. Which statistic is determined by using one of the following enumerated values:

```
typedef enum bcm_regex_stat_e {
    bcmStatRegexSessionFirst = 0,          /* Beginning of Session part
of list */
    bcmStatRegexSessionEntriesInUse = 0, /* 32-bit counter, Current
number of
                                session entries in use */
    bcmStatRegexSessionFlowsCreated = 1, /* 32-bit counter, Cumulative
number of
                                flows created in flow tracker session
                                table */
    bcmStatRegexSessionMaxFlowsInUse = 2, /* 32-bit counter, Maximum
number of
                                flows in use, high watermark */
    bcmStatRegexSessionFlowsMissedTCP = 3, /* 32-bit counter,
Cumulative number of
                                TCP flows that could not be inserted
                                because of bucket full */
    bcmStatRegexSessionFlowsMissedUDP = 4, /* 32-bit counter,
Cumulative number of
                                UDP flows that could not be inserted
                                because of bucket full */
    bcmStatRegexSessionCmdWaitTimeouts = 5, /* 32-bit counter, Number
of flows for
                                which no results packet
was received */
    bcmStatRegexSessionUnusedResults = 6, /* 32-bit counter, Number
of results
                                packets that were ignored */
    bcmStatRegexSessionSuppressedActions = 7, /* 32-bit counter,
Number of flows
                                created where actions inhibited by
                                VFP */
    bcmStatRegexSessionTcpSynData = 8, /* 32-bit counter, Number
of flows
                                created with TCP SYN data */
    bcmStatRegexSessionL4Invalid = 9, /* 32-bit counter, Number
of packets
                                seen where L4 offset/length could not
                                be determined */
    bcmStatRegexSessionL4PortsExcluded = 10, /* 32-bit counter,
Number of flows not
                                created because of L4Port Table
```



```

                                exclusion */
bcmStatRegexSessionLast = 10,      /* End of Session part of list */
bcmStatRegexSigMatchFirst = 21,    /* Beginning of SigMatch
part of list */
bcmStatRegexSigMatchPacketsReceived = 21, /* 32-bit counter,
Number of packets
                                received by the Signature Match for
                                inspection */
bcmStatRegexSigMatchPacketsSent = 22, /* 32-bit counter, Number
of packets
                                sent by Signature Match for reporting
                                to the Flow Tracker */
bcmStatRegexSigMatchPacketsDropped = 23, /* 32-bit counter, Total
number of
                                packets dropped without match
                                processing */
bcmStatRegexSigMatchBytesMatched = 24, /* 32-bit counter, Number
of L4 payload
                                bytes processed by the
regex engines */
bcmStatRegexSigMatchMatchedFlows = 25, /* 32-bit counter, Number
of flows that
                                were successfully matched */
bcmStatRegexSigMatchUnmatchedFlows = 26, /* 32-bit counter,
Number of flows that
                                were not successfully matches */
bcmStatRegexSigMatchTotalMatch = 27, /* 32-bit counter, Number
of matches
                                successfully detected by the Regex
                                engines (includes unreported
matches) */
bcmStatRegexSigMatchCrossSigFlags = 28, /* 32-bit counter, Number
of updates to
                                cross-signature flags */
bcmStatRegexSigMatchFragmentsReceived = 29, /* 32-bit counter,
Number of fragmented
                                packets received */
bcmStatRegexSigMatchInPacketError = 30, /* 32-bit counter, Number
of packets
                                dropped for incorrect framing signals
                                (SOP, EOP) or error signal asserted
                                anywhere in the packet */
bcmStatRegexSigMatchFlowTrackerError = 31, /* 32-bit counter,
Number of packets
                                dropped because the FT indicated an
                                error in a queued packet before EOP */
bcmStatRegexSigMatchPacketLengthError = 32, /* 32-bit counter,
Number of packets
                                dropped because of a length error */
bcmStatRegexSigMatchL4ChecksumError = 33, /* 32-bit counter,
Number of packets
                                dropped because of an invalid L4
                                (TCP/UDP) checksum */
```

```
        bcmStatRegexSigMatchFlowDonePacketDrop = 34, /* 32-bit counter,
Number of flows that
        encountered an invalid Flow Table
        entry error */
        bcmStatRegexSigMatchFlowTimestampError = 35, /* 32-bit counter,
Number of packets
        with timestamp errors -- the first
        packet of the current flow was lost */
        bcmStatRegexSigMatchFlowPacketNumError = 36, /* 32-bit counter,
Number of flows that
        encountered an FT packet number
        mismatch */
        bcmStatRegexSigMatchECCError = 37, /* 32-bit counter, Number of
        uncorrectable ECC errors detected */
        bcmStatRegexSigMatchLast = 37, /* End of SigMatch part of
list */
        bcmStatRegexLast = 37, /* End of list */
        bcmStatRegexCount = 27 /* Number of unique enums
in the list */
    } bcm_regex_stat_t;
```

Returns

BCM_E_XXX

bcm_regex_stat_set

Set a specified regex Flow Tracker statistic.

Syntax

```
#include <bcm/bregex.h>
int bcm_regex_stat_set(int unit,
                      bcm_regex_stat_t type,
                      uint64 val);
```

Parameters

unit	(IN) Unit number.
type	(IN) The enum value of the statistic to set.
val	(IN) Value of the Flow Tracker statistic to set

Description

`bcm_regex_stat_set` will set the value of the indicated counter.

Returns

BCM_E_XXX

REGEX POLICIES

Actions taken as a result of a signature match are configured using policies. The policy table used by the regex module is identical to that used by the Ingress Field Processor. The APIs for configuring policies are also similar to those used by the Field Processor. Note that policy 0 is reserved. It is used when the Flow Tracker fails to create a session entry in its table.

bcm_regex_policy_create

Create a blank regex policy.

Syntax

```
#include <bcm/bregex.h>
int bcm_regex_policy_create(int unit,
                           int flags,
                           bcm_regex_policy_t *policy);
```

Parameters

unit	(IN) Unit number.
flags	(IN) REGEX_POLICY_XXX flags
policy	(OUT) ID of policy to be created.

Description

Creates an empty policy. To create a policy with a given ID, use the BCM_REGEX_FLOW_WITH_ID flag. To destroy the policy, use the bcm_regex_policy_destroy api.

The flag value BCM_REGEX_POLICY_WITH_ID passed to the flags parameter, specifies that the policy parameter is to be used as the policy ID to be created.

- BCM_REGEX_POLICY_WITH_ID

Returns

BCM_E_XXX

bcm_regex_policy_destroy

Destroy a regex policy. This deallocates memory only.

Syntax

```
#include <bcm/bregex.h>
int bcm_regex_policy_destroy(int unit,
                           bcm_regex_policy_t policy);
```

Parameters

<code>unit</code>	(IN) Unit number.
<code>policy</code>	(IN) ID of policy to be destroyed.

Description

This API deallocates the memory which contains a software policy. If the policy has been installed in hardware, the function would invoke a `bcm_regex_policy_remove` API to clean up the policy in hardware and free hardware resources.

Returns

BCM_E_XXX

bcm_regex_policy_destroy_all

Destroy all regex policy entries.

Syntax

```
#include <bcm/bregex.h>
int bcm_regex_policy_destroy_all(int unit);
```

Parameters

<code>unit</code>	(IN) Unit number.
-------------------	-------------------

Description

Destroys all regex policy entries.

Returns

BCM_E_XXX

bcm_regex_policy_install

Install a regex policy into the hardware tables.

Syntax

```
#include <bcm/bregex.h>
int bcm_regex_policy_install(int unit,
                             bcm_regex_policy_t policy);
```

Parameters

<code>unit</code>	(IN) Unit number.
<code>policy</code>	(IN) ID of policy to be installed.

Description

Installs a policy into the hardware tables. The policy should be configured before installing by adding actions using `bcm_regex_policy_action_add`. The `bcm_regex_policy_t` object is not consumed or destroyed. It can be used to remove or update the policy.

Returns

`BCM_E_XXX`

`bcm_regex_policy_remove`

Remove a regex policy from the hardware tables.

Syntax

```
#include <bcm/bregex.h>
int bcm_regex_policy_remove(int unit,
                           bcm_regex_policy_t policy);
```

Parameters

<code>unit</code>	(IN) Unit number.
<code>policy</code>	(IN) ID of policy to be removed.

Description

Removes a policy from the hardware tables. This does not destroy the policy; it only uninstalls it from the hardware tables. Destroy a policy using `bcm_regex_policy_destroy`.

Returns

`BCM_E_XXX`

`bcm_regex_policy_action_add`

Add an action to a regex policy.

Syntax

```
#include <bcm/bregex.h>
int bcm_regex_policy_action_add(int unit,
                               bcm_regex_policy_t policy,
                               bcm_field_action_t action,
                               uint32 param0,
                               uint32 param1);
```

Parameters

unit	(IN) Unit number.
policy	(IN) ID of policy to be modified.
action	(IN) Field processor action value
param0	(IN) Action-dependent value; 0 if not used
param1	(IN) Action-dependent value; 0 if not used

Description

Adds an action to be performed when this policy is applied to a packet. Multiple actions may be added for a policy by calling this function repeatedly. The actions which may be added are a subset (hardware dependent) of those defined in the `fp_actions` section.

Returns

BCM_E_XXX

bcm_regex_policy_action_mac_add

Add an action to a policy.

Syntax

```
#include <bcm/bregex.h>
int bcm_regex_policy_action_mac_add(int unit,
                                     bcm_regex_policy_t policy,
                                     bcm_field_action_t action,
                                     bcm_mac_t mac);
```

Parameters

unit	(IN) Unit number.
policy	(IN) Regex policy Id.
action	(IN) Field action value
mac	(IN) MAC address for actions involving src/dst MAC.

Description

Add an action involving a src/dst MAC to a policy.

Returns

BCM_E_XXX

bcm_regex_policy_action_ports_add

Add an action to a regex policy.

Syntax

```
#include <bcm/bregex.h>
int bcm_regex_policy_action_ports_add(int unit,
                                     bcm_regex_policy_t policy,
                                     bcm_field_action_t action,
                                     bcm_pbmp_t pbmp);
```

Parameters

unit	(IN) Unit number.
policy	(IN) regex policy ID
action	(IN) Field action value
pbmp	(IN) pbmp for actions involving port bitmap

Description

Add an action involving a pbmp to a regex policy.

Returns

BCM_E_XXX

bcm_regex_policy_action_delete

Delete an action from a regex policy.

Syntax

```
#include <bcm/bregex.h>
int bcm_regex_policy_action_delete(int unit,
                                   bcm_regex_policy_t policy,
                                   bcm_field_action_t action,
                                   uint32 param0,
                                   uint32 param1);
```

Parameters

unit	(IN) Unit number.
policy	(IN) ID of policy to be modified.
action	(IN) Field processor action value
param0	(IN) Action-dependent value; 0 if not used
param1	(IN) Action-dependent value; 0 if not used

Description

Delete an action from a regex policy.

Returns

BCM_E_XXX

bcm_regex_policy_action_get

Retrieve the parameters for an action previously added to a regex policy.

Syntax

```
#include <bcm/bregex.h>
int bcm_regex_policy_action_get(int unit,
                                bcm_regex_policy_t policy,
                                bcm_field_action_t action,
                                uint32 *param0,
                                uint32 *param1);
```

Parameters

unit	(IN) Unit number.
policy	(IN) regex policy ID.
action	(IN) Field processor action value
param0	(OUT) Action-dependent value
param1	(OUT) Action-dependent value

Description

Retrieves the parameters used for a particular action that was previously added to a regex policy.

Returns

BCM_E_XXX

bcm_regex_policy_action_mac_get

Retrieve the parameters for an action previously added to a regex policy.

Syntax

```
#include <bcm/bregex.h>
int bcm_regex_policy_action_mac_get(int unit,
                                     bcm_regex_policy_t policy,
                                     bcm_field_action_t action,
                                     bcm_mac_t *mac);
```

Parameters

<code>unit</code>	(IN) Unit number.
<code>policy</code>	(IN) Regex policy ID.
<code>action</code>	(IN) Field action value.
<code>mac</code>	(OUT) MAC address for actions involving src/dst MAC.

Description

Retrieve the parameters for an action involving a src/dst MAC previously added to a regex policy.

Returns

BCM_E_XXX

bcm_regex_policy_action_ports_get

Retrieve the parameters for an action previously added to a regex policy.

Syntax

```
#include <bcm/bregex.h>
int bcm_regex_policy_action_ports_get(int unit,
                                     bcm_regex_policy_t policy,
                                     bcm_field_action_t action,
                                     bcm_pbmp_t *pbmp);
```

Parameters

<code>unit</code>	(IN) Unit number.
<code>policy</code>	(IN) Regex policy ID
<code>action</code>	(IN) Field action value
<code>pbmp</code>	(OUT) pbmp for actions involving port bitmap

Description

Retrieve the parameters for an action involving a pbmp previously added to a regex policy.

Returns

BCM_E_XXX

bcm_regex_policy_action_remove

Remove an action from a regex_policy. Same as `bcm_regex_policy_action_delete` for actions without parameters.

Syntax

```
#include <bcm/bregex.h>
```

```
int bcm_regex_policy_action_remove(int unit,  
                                   bcm_regex_policy_t policy,  
                                   bcm_field_action_t action);
```

Parameters

unit	(IN) Unit number.
policy	(IN) ID of policy to be modified.
action	(IN) Field processor action value

Description

Remove an action from a `regex_policy`. Same as `bcm_regex_policy_action_delete` for actions without parameters.

Returns

BCM_E_XXX

bcm_regex_policy_action_remove_all

Remove all actions from a `regex_policy`.

Syntax

```
#include <bcm/bregex.h>  
int bcm_regex_policy_action_remove_all(int unit,  
                                       bcm_regex_policy_t policy);
```

Parameters

unit	(IN) Unit number.
policy	(IN) ID of policy to be modified.

Description

Remove all actions from a `regex_policy`.

Returns

BCM_E_XXX

REGEX POLICY POLICERS

The regex engine policies may have policers (meters) attached for tracking ingress bandwidth. Since each policy may be applied to multiple flows, the tracking granularity is on a per-policy basis. Only one meter pool is allocated for use by the regex engine. As a result, hierarchical meters are not supported so only level 0 may be used.

bcm_regex_policy_policer_attach

Attach a policer to a regex policy.

Syntax

```
#include <bcm/bregex.h>
int bcm_regex_policy_policer_attach(int unit,
                                   bcm_regex_policy_t policy,
                                   int level,
                                   bcm_policer_t policer_id);
```

Parameters

unit	(IN) Unit number.
policy	(IN) Regex policy ID.
level	(IN) Policer level.
policer_id	(IN) Policer ID.

Description

Attach a policer to a regex policy. See `fp_apis_policer` for policer creation and properties definition.

Returns

BCM_E_XXX

bcm_regex_policy_policer_detach

Detach a policer from a regex policy.

Syntax

```
#include <bcm/bregex.h>
int bcm_regex_policy_policer_detach(int unit,
                                   bcm_regex_policy_t policy,
                                   int level);
```

Parameters

unit	(IN) Unit number.
policy	(IN) Regex policy ID.
level	(IN) Policer level.

Description

Detach a policer from a regex policy.

Returns

BCM_E_XXX

bcm_regex_policy_policer_detach_all

Detach all policers from a regex policy.

Syntax

```
#include <bcm/bregex.h>
int bcm_regex_policy_policer_detach_all(int unit,
                                         bcm_regex_policy_t policy);
```

Parameters

unit	(IN) Unit number.
policy	(IN) Regex policy ID.

Description

Detach all policers from a regex policy.

Returns

BCM_E_XXX

bcm_regex_policy_policer_get

Get the policer(s) attached to a regex policy.

Syntax

```
#include <bcm/bregex.h>
int bcm_regex_policy_policer_get(int unit,
                                  bcm_regex_policy_t policy,
                                  int level,
                                  bcm_policer_t *policer_id);
```

Parameters

unit	(IN) Unit number.
policy	(IN) Regex policy ID.
level	(IN) Policer level.
policer_id	(OUT) Policer ID.

Description

Get the policer(s) attached to a regex policy.

Returns

BCM_E_XXX

REGEX POLICY STATISTICS

bcm_regex_stat_create

Create stat collection entity.

Syntax

```
#include <bcm/bregex.h>
int bcm_regex_stat_create(int unit,
                          int flags,
                          int nstat,
                          bcm_field_stat_t *stat_arr,
                          int *stat_id);
```

Parameters

unit	(IN) Unit number.
flags	(IN) REGEX_STAT_XXX flags
nstat	(IN) Number of elements in stat_arr - counter types
stat_arr	(IN) Array of counters to be collected in statistics
stat_id	(OUT) Statistics entity ID.

Description

Creates an aggregated entity describing set of counters. The entity might be attached to regex policy entries and used for various counters collection.

The flag value BCM_REGEX_STAT_WITH_ID passed to the flags parameter, specifies that the stat_id parameter is to be used as the statistics ID to be created.

- BCM_REGEX_STAT_WITH_ID

Returns

BCM_E_XXX

bcm_regex_stat_destroy

Create stat collection entity.

Syntax

```
#include <bcm/bregex.h>
int bcm_regex_stat_destroy(int unit,
                           int stat_id);
```

Parameters

unit	(IN) Unit number.
stat_id	(IN) Statistics entity ID.

Description

Create stat collection entity.

Returns

BCM_E_XXX

bcm_regex_policy_stat_attach

Attach statistics entity to Regex policy.

Syntax

```
#include <bcm/bregex.h>
int bcm_regex_policy_stat_attach(int unit,
                                bcm_regex_policy_t policy,
                                int stat_id);
```

Parameters

unit	(IN) Unit number.
policy	(IN) Regex policy ID.
stat_id	(IN) Statistics entity ID.

Description

The purpose of this API is to attach statistics collection entity to a regex policy.

Returns

BCM_E_XXX

bcm_regex_policy_stat_detach

Detach statistics entity from Regex policy.

Syntax

```
#include <bcm/bregex.h>
int bcm_regex_policy_stat_detach(int unit,
                                bcm_regex_policy_t policy,
                                int stat_id);
```

Parameters

unit	(IN) Unit number.
policy	(IN) Regex policy ID.
stat_id	(IN) Statistics entity ID.

Description

The purpose of this API is to detach statistics collection entity to a regex policy.

Returns

BCM_E_XXX

bcm_regex_policy_stat_get

Get 64 bit counter value for specific statistic type.

Syntax

```
#include <bcm/bregex.h>
int bcm_regex_policy_stat_get(int unit,
                             bcm_regex_policy_t policy,
                             int *stat_id);
```

Parameters

unit	(IN) Unit number.
policy	(IN) Regex policy ID.
stat_id	(OUT) Statistics entity ID.

Description

The purpose of this API is to check if any statistics collection entity is attached to a policy.

Returns

BCM_E_XXX

REGEX SESSION MANAGEMENT

The Regex engine provides for management of the session table.

bcm_regex_session_key_t_init

Initialize regex session key structure.

Syntax

```
#include <bcm/bregex.h>
void bcm_regex_session_key_t_init(bcm_regex_session_key_t *session_key);
```

Parameters

session_key	(IN/OUT) Pointer to the session key to initialize.
-------------	--

Description

Initialize regex session key structure.

The following structure summarizes the session key:

```
typedef struct bcm_regex_session_key_s {
```

```

    int flags;           /* REGEX_SESSION_KEY_xxx flags */
    bcm_ip_t sip;        /* Source IPV4 address. */
    bcm_ip_t dip;        /* Destination IPV4 address. */
    bcm_ip6_t sip6;      /* Source IPV6 address. */
    bcm_ip6_t dip6;      /* Destination IPV6 address. */
    uint32 dst_port;     /* L4 destination port */
    uint32 src_port;     /* L4 source port */
    uint8 protocol;      /* IP protocol. */
} bcm_regex_session_key_t;

```

The flags member of the `bcm_regex_session_key_t` structure controls various features of the session table. The following table summarizes the various flags that can be used with the session keys.

Table 37: *bcm_regex_session_key_t* flags

<i>flag Value</i>	<i>Description</i>
<code>BCM_REGEX_SESSION_KEY_IPV6</code>	Key is IPv6. If not set, key is IPv4.
<code>BCM_REGEX_SESSION_KEY_REPLACE</code>	If key found in table when adding, replace entry; if not found, then return error.

Returns

`BCM_E_XXX`

bcm_regex_session_t_init

Initialize regex session structure.

Syntax

```

#include <bcm/bregex.h>
void bcm_regex_session_t_init(bcm_regex_session_t *session);

```

Parameters

`session` (IN/OUT) Pointer to the session data to initialize.

Description

Initialize regex session structure.

The following structure summarizes the session object:

```

typedef struct bcm_regex_session_s {
    int flags;           /* REGEX_SESSION_xxx flags */
    bcm_regex_policy_t policy; /* The policy to apply to this flow. */
    uint32 inactivity_timeout; /* Units are usec. */
    uint32 timestamp;     /* Output - session entry's timestamp. */
} bcm_regex_session_t;

```

The flags member of the `bcm_regex_session_t` structure controls various features of the session table. The following table summarizes the various flags that can be used with the session objects.

Table 38: *bcm_regex_session_t* flags

flag Value	Description
BCM_REGEX_SESSION_STATIC	This flag will either convert an existing dynamic session to static or create a new static session. If this flag is not set, the session is assumed to be dynamic and will only be updated if it already exists.

Returns

BCM_E_XXX

bcm_regex_session_add

Adds or updates a session entry. Flags param for future use, values 0x1-0x8 are reserved.

Syntax

```
#include <bcm/bregex.h>
int bcm_regex_session_add(int unit,
                          int flags,
                          bcm_regex_session_key_t *key,
                          bcm_regex_session_t *session);
```

Parameters

unit	(IN) Unit number.
flags	(IN) REGEX_SESSION_XXX flags.
key	(IN) The session key.
session	(IN) The session data.

Description

Adds or updates a session matching the key specified in `bcm_regex_session_key_t`. Session must be in an appropriate state in order to be updated. Sessions that are in a Retired state are never updated. The flags parameter is supplied for future use by the api, though flag values 0x1-0x8 are reserved for internal use.

Returns

BCM_E_XXX

- BCM_E_BUSY
- BCM_E_FULL
- BCM_E_NOT_FOUND



bcm_regex_session_policy_update

Updates the policy ID in a session entry.

Syntax

```
#include <bcm/bregex.h>
int
bcm_regex_session_policy_update(
    int unit,
    int flags,
    int flow_index,
    bcm_regex_policy_t policy);
```

Parameters

unit	(IN) Unit number.
flags	(IN) REGEX_SESSION_XXX flags.
flow_index	(IN) The index into the session table.
policy	(IN) The policy ID to be updated in the session table.

Description

Updates the policy ID in a session entry. The session is referred to by parameter `flow_index`, which is the index into the session table. This `flow_index` is provided by the egress metadata packet sent when a regex match event occurs.

Returns

BCM_E_XXX

bcm_regex_session_delete

Deletes an entry from the regex session table.

Syntax

```
#include <bcm/bregex.h>
int bcm_regex_session_delete(int unit,
                             bcm_regex_session_key_t *key);
```

Parameters

unit	(IN) Unit number.
key	(IN) The session key.

Description

Deletes an entry from the regex session table.

Returns

BCM_E_XXX

bcm_regex_session_get

Returns the session data (if any). Flags param for future use.

Syntax

```
#include <bcm/bregex.h>
int bcm_regex_session_get(int unit,
                          int flags,
                          bcm_regex_session_key_t *key,
                          bcm_regex_session_t *session);
```

Parameters

unit	(IN) Unit number.
flags	(IN) REGEX_SESSION_XXX flags.
key	(IN) The session key.
session	(OUT) The session data.

Description

Returns the session data (if any).

Returns

BCM_E_XXX

bcm_regex_session_traverse

Traverse regex sessions.

Syntax

```
#include <bcm/bregex.h>
int bcm_regex_session_traverse(int unit,
                              int flags,
                              bcm_regex_session_traverse_cb cb,
                              void *user_data);
```

Parameters

<code>unit</code>	(IN) Unit number.
<code>flags</code>	(IN) REGEX_SESSION_xxx flags.
<code>cb</code>	(IN) A pointer to the callback function to call for
<code>user_data</code>	(IN) Pointer to user data to supply in the callback

Description

This API will traverse the session table and call function `cb` for each entry.

The signature of the callback function must be like this:

```
typedef int (*bcm_regex_session_traverse_cb)(int unit,
                                             bcm_regex_session_key_t
*session_key,
                                             bcm_regex_session_t *session_data,
                                             void *user_data);
```

By default, only static sessions are traversed. If the flag `BCM_REGEX_SESSION_TRAVERSE_ALL` is set, then all sessions (dynamic and static) are traversed.

Returns

`BCM_E_XXX`

PACKET RX/TX

The packet timestamp mode options describe the timestamp modes which may be specified in SOBMH header for OAM DM TX packets.

Table 39: OAM Packet time stamp mode Descriptions

<i>Name</i>	<i>Description</i>
BCM_PKT_TIMESTAMP_MODE_NONE	No timestamp
BCM_PKT_TIMESTAMP_MODE_PTP	Timestamp mode is PTP.
BCM_PKT_TIMESTAMP_MODE_NTP	Timestamp mode is NTP.

New packet loss measurement counter mode options describe the LM counter actions which may be specified in SOBMH header for OAM LM TX packets.

Table 40: OAM Packet time stamp mode Descriptions

<i>Name</i>	<i>Description</i>
BCM_PKT_OAM_LM_COUNTER_MODE_NONE	No LM counter operation
BCM_PKT_OAM_LM_COUNTER_MODE_INCREMENT	Increment LM counter.
BCM_PKT_OAM_LM_COUNTER_MODE_SAMPLE	Sample LM counter value.

Existing field datatype has been updated in `bcm_pkt_t` structure.

Table 41: `bcm_pkt_t` Structure Description

<i>Field</i>	<i>Type</i>	<i>Description</i>
<code>src_trunk</code>	<code>bcm_trunk_t</code>	Source trunk group ID if <code>src_port/src_mod</code> is not used.

New fields have been added to `bcm_pkt_t` structure.

Table 42: `bcm_pkt_t` Structure Description

<i>Field</i>	<i>Type</i>	<i>Description</i>
<code>_dcb</code>	<code>void *</code>	Pointer for dcb. Used when <code>BCM_RX_F_PKT_UNPARSED</code> flag is set. See flags descriptions in <code>bcm_rx_chan_cfg_t</code> .
<code>oam_lm_counter_index_2</code>	<code>uint16</code>	OAM Second LM counter index used in SOBMH header. See Packet Flags Descriptions for flags2 (page 60)
<code>ma_ptr</code>	<code>uint16</code>	OAM MA Pointer value. For BCM5645x, this corresponds to endpoint group index. See Packet Flags Descriptions for flags2 (page 60)

Table 42: bcm_pkt_t Structure Description

Field	Type	Description
timestamp_mode	bcm_pkt_timestamp_mode_t	OAM DM timestamp mode. See Packet Flags Descriptions for flags2 (page 60) and OAM Packet time stamp mode Descriptions (page 59)
counter_mode_1	bcm_pkt_oam_lm_counter_mode_t	OAM LM counter-1 mode. See Packet Flags Descriptions for flags2 (page 60) and OAM Packet time stamp mode Descriptions (page 59)
counter_mode_2	bcm_pkt_oam_lm_counter_mode_t	OAM LM counter-2 mode. See Packet Flags Descriptions for flags2 (page 60) and OAM Packet time stamp mode Descriptions (page 59)
timestamp_offset	uint8	Offset to be placed in the timestamp of the packet

New Packet flags have been added.

Table 43: Packet Flags Descriptions for flags2

Flag	Description
BCM_PKT_F2_TIMESTAMP_MODE	This flag indicates the transmitted OAM packet needs to be inserted with the timestamp mode value in SOBMH mode.
BCM_PKT_F2_SAMPLE_RDI	This flag indicates that transmitted OAM packet needs to sample RDI bit in SOBMH mode.
BCM_PKT_F2_MA_PTR	This flag indicates that transmitted OAM packet needs to insert MA PTR value in SOBMH mode.
BCM_PKT_F2_MEP_TYPE_UPMEP	This flag indicates that transmitted OAM packet needs to make use of SOBMH UPMEP TX mode. If this flag is not specified, DOWNMEP TX mode is used.
BCM_PKT_F2_LM_COUNTER_INDEX_2	This flag indicates the transmitted packet is specified with Second Loss Measurement counter index to be inserted into packet in SOBMH mode
BCM_PKT_F2_COUNTER_MODE_1	This flag indicates the transmitted OAM packet needs to make use of the counter action specified in counter mode 1 in SOBMH mode.
BCM_PKT_F2_COUNTER_MODE_2	This flag indicates the transmitted OAM packet needs to make use of the counter action specified in counter mode 2 in SOBMH mode.

New Packet Rx Reason codes have been added.

Table 44: Packet RX Reasons.

Reason	Description
bcmRxReasonOAMCCMSlowpath	OAM CCM Packets to CPU - slowpath processing
bcmRxReasonBHHOAM	BHH OAM Packets to CPU

SUBPORT CONFIGURATION

New Subport Group flag has been added.

Table 45: Subport Group Flags

<i>Name</i>	<i>Purpose</i>
BCM_SUBPORT_GROUP_TYPE_SUBPORT_PKT_TAG	Create a LLTAG subport group

New enums for Subport Match criteria have been added.

Table 46: SUBPORT Match Criteria

<i>Name</i>	<i>Purpose</i>
BCM_SUBPORT_MATCH_INVALID	Illegal.
BCM_SUBPORT_MATCH_PKT_VID	Mod/port/trunk + LLTAG VID.
BCM_SUBPORT_MATCH_PKT_VID_INNER_VLAN	Mod/port/trunk + LLTAG VID + inner VLAN.
BCM_SUBPORT_MATCH_PKT_VID_OUTER_VLAN	Mod/port/trunk + LLTAG VID + outer VLAN.

New fields have been added to `bcm_subport_config_t` structure.

```
typedef struct bcm_subport_config_s {
    ...
    bcm_vlan_t inner_vlan;           /* 12-bit inner VLAN */
    bcm_vlan_t outer_vlan;          /* 12-bit outerVLAN */
    ...
    bcm_subport_match_t criteria;    /* match criteria. */
} bcm_subport_config_t;
```

SWITCH CONTROL

New Switch Controls have been added.

Table 47: Switch Type Values

<i>Value</i>	<i>Description</i>	<i>Arg Value</i>
bcmSwitchMirrorUnicastCosq	Set the CoS queue for mirrored unicast traffic.	0-15, -1 to disable
bcmSwitchMirrorMulticastCosq	Set the CoS queue for mirrored multicast traffic.	0-15, -1 to disable
bcmSwitchHashNivSrcIfEtagSvidSelect0	Select VN-TAG.src_vif or E-Tag.svid for hashing computation in Hash A buckets (default 0).	0-1
bcmSwitchHashNivSrcIfEtagSvidSelect1	Select VN-TAG.src_vif or E-Tag.svid for hashing computation in Hash B buckets (default 0).	0-1
bcmSwitchHashNivDstIfEtagVidSelect0	Select VN-TAG.dst_vif or E-Tag.vid for hashing computation in Hash A buckets (default 0).	0-1
bcmSwitchHashNivDstIfEtagVidSelect1	Select VN-TAG.dst_vif or E-Tag.vid for hashing computation in Hash B buckets (default 0).	0-1
bcmSwitchBstSnapshotEnable	Enable/Disable BST Snapshot mode for each THDO/THDI/CFAP resource.	0-7 (each bit for one resource)

Table 47: Switch Type Values

<i>Value</i>	<i>Description</i>	<i>Arg Value</i>
bcmSwitchSymmetricHashControl	Selects which starting packet to use for symmetric hashing	<ul style="list-style-type: none"> • BCM_SYMMETRIC_HASH_0_IP4_ENABLE - Enable symmetric key hashing on Hash A for IPV4 packets. • BCM_SYMMETRIC_HASH_1_IP4_ENABLE - Enable symmetric key hashing on Hash B for IPV4 packets. • BCM_SYMMETRIC_HASH_0_IP6_ENABLE - Enable symmetric key hashing on Hash A for IPV6 packets. • BCM_SYMMETRIC_HASH_1_IP6_ENABLE - Enable symmetric key hashing on Hash B for IPV6 packets. • BCM_SYMMETRIC_HASH_0_SUPPRESS_UNIDIR_FIELD_ENABLE - Enable setting SPI, TEID, L2 GRE Key to zero for Hash A calculation. • BCM_SYMMETRIC_HASH_1_SUPPRESS_UNIDIR_FIELD_ENABLE - Enable setting SPI, TEID, L2 GRE Key to zero for Hash B calculation. • BCM_SYMMETRIC_HASH_0_FCOE_ENABLE - Enable symmetric key hashing on Hash A for FCoE packets. • BCM_SYMMETRIC_HASH_1_FCOE_ENABLE - Enable symmetric key hashing on Hash B for FCoE packets.
bcmSwitchL2ExtLearn	Select where L2 addresses are learnt	<ul style="list-style-type: none"> • bcmSwitchL2LocInternal /* Learn MAC addresses on Internal Memory */ • bcmSwitchL2LocExternal /* Learn MAC addresses on External Memory */
BcmSwitchMcQueueSchedMode	Schedule mode select for multicast queues.	<ul style="list-style-type: none"> • bcmSwitchMcUcPairGroupMode - Each MC queue is paired with one UC queue. • bcmSwitchAllMcGroupMode - All MC queues are grouped together.

Table 47: Switch Type Values

<i>Value</i>	<i>Description</i>	<i>Arg Value</i>
bcmSwitchHashSelectControl	BCM56700/BCM56800/BCM56580 field selection control for enhanced hashing algorithm.	<ul style="list-style-type: none"> BCM_HASH_FIELD0_DISABLE_TUNNEL_IP4_GRE_IP4 - selection 0 for tunnel IPv4 over GRE IPv4 pkts BCM_HASH_FIELD0_DISABLE_TUNNEL_IP4_GRE_IP6 - selection 0 for tunnel IPv4 over GRE IPv6 pkts BCM_HASH_FIELD1_DISABLE_TUNNEL_IP4_GRE_IP4 - selection 1 for tunnel IPv4 over GRE IPv4 pkts BCM_HASH_FIELD1_DISABLE_TUNNEL_IP4_GRE_IP6 - selection 1 for tunnel IPv4 over GRE IPv6 pkts BCM_HASH_FIELD0_DISABLE_TUNNEL_IP6_GRE_IP4 - selection 0 for tunnel IPv6 over GRE IPv4 pkts BCM_HASH_FIELD0_DISABLE_TUNNEL_IP6_GRE_IP6 - selection 0 for tunnel IPv6 over GRE IPv6 pkts BCM_HASH_FIELD1_DISABLE_TUNNEL_IP6_GRE_IP4 - selection 1 for tunnel IPv6 over GRE IPv4 pkts BCM_HASH_FIELD1_DISABLE_TUNNEL_IP6_GRE_IP6 - selection 1 for tunnel IPv6 over GRE IPv6 pkts

TRILL MANAGEMENT

New Trill port flags have been added.

Table 48: TRILL port flags

<i>Name</i>	<i>Purpose</i>
BCM_TRILL_MULTICAST_REPLACE_DYNAMIC	Replace an existing dynamic L2 entry with TRILL entry, when table is full
BCM_TRILL_PORT_VIRTUAL	Virtual/pseudo nicknames for trill multi homing support

VLAN MANAGEMENT

New Port match criteria for a Logical Layer 2 has been added.

Table 49: bcm_vlan_port_match_t

<i>Value</i>	<i>Meaning</i>
BCM_VLAN_PORT_MATCH_PORT_TUNNEL_PCP_VLAN	Mod/port/trunk + Tunnel Value + outer PCP + outer VLAN.

bcm_vlan_control_vlan_selective_set **bcm_vlan_control_vlan_selective_get**

Set or retrieve current VLAN properties selectively.

Syntax

```
#include <bcm/vlan.h>
int bcm_vlan_control_vlan_selective_set(int unit,
                                       bcm_vlan_t vlan,
                                       uint32 valid_fields,
                                       bcm_vlan_control_vlan_t *control);
int bcm_vlan_control_vlan_selective_get(int unit,
                                       bcm_vlan_t vlan,
                                       uint32 valid_fields,
                                       bcm_vlan_control_vlan_t *control);
```

Parameters

unit	BCM device number
vlan	VLAN
valid_fields	Valid fields for VLAN control structure
control	(for "_set", IN) (for "_get", OUT) structure which contains VLAN property, see bcm_vlan_control_vlan_t

Description

Sets/gets miscellaneous VLAN-specific properties selectively. The valid fields is used to control which fields will be got/set, and can be any combination of BCM_VLAN_CONTROL_VLAN_MASK_table. The control properties are from bcm_vlan_control_vlan_t, see bcm_vlan_control_vlan_set/get for detail.

Table 50: VLAN Control Valid Field Mask

<i>VLAN Control Valid Field Mask</i>	<i>Meaning</i>
BCM_VLAN_CONTROL_VLAN_VRF_MASK	Enable .vrf field.
BCM_VLAN_CONTROL_VLAN_FORWARDING_VLAN_MASK	Enable .forwarding_vlan field.
BCM_VLAN_CONTROL_VLAN_INGRESS_IF_MASK	Enable .ingress_if field.
BCM_VLAN_CONTROL_VLAN_OUTER_TPID_MASK	Enable .outer_tpid field.



Table 50: VLAN Control Valid Field Mask

VLAN Control Valid Field Mask	Meaning
BCM_VLAN_CONTROL_VLAN_IP6_MCAST_FLOOD_MODE_MASK	Enable .ip6_mcast_flood_mode field.
BCM_VLAN_CONTROL_VLAN_IP4_MCAST_FLOOD_MODE_MASK	Enable .ip4_mcast_flood_mode field.
BCM_VLAN_CONTROL_VLAN_L2_MCAST_FLOOD_MODE_MASK	Enable .l2_mcast_flood_mode field.
BCM_VLAN_CONTROL_VLAN_IF_CLASS_MASK	Enable .if_class field.
BCM_VLAN_CONTROL_VLAN_FORWARDING_MODE_MASK	Enable .forwarding_mode field.
BCM_VLAN_CONTROL_VLAN_URPF_MODE_MASK	Enable .urpf_mode field.
BCM_VLAN_CONTROL_VLAN_COSQ_MASK	Enable .cosq field.
BCM_VLAN_CONTROL_VLAN_QOS_MAP_ID_MASK	Enable .qos_map_id field.
BCM_VLAN_CONTROL_VLAN_DISTRIBUTION_CLASS_MASK	Enable .distribution_class field.
BCM_VLAN_CONTROL_VLAN_BROADCAST_GROUP_MASK	Enable .broadcast_group field.
BCM_VLAN_CONTROL_VLAN_UNKNOWN_MULTICAST_GROUP_MASK	Enable .unknown_multicast_group field.
BCM_VLAN_CONTROL_VLAN_UNKNOWN_UNICAST_GROUP_MASK	Enable .unknown_unicast_group field.
BCM_VLAN_CONTROL_VLAN_TRILL_NONUNICAST_GROUP_MASK	Enable .trill_nonunicast_group field.
BCM_VLAN_CONTROL_VLAN_SOURCE_TRILL_NAME_MASK	Enable .source_trill_name field.
BCM_VLAN_CONTROL_VLAN_TRUNK_INDEX_MASK	Enable .trunk_index field.
BCM_VLAN_CONTROL_VLAN_PROTOCOL_PKT_MASK	Enable .protocol_pkt field.
BCM_VLAN_CONTROL_VLAN_NAT_REALM_ID_MASK	Enable .nat_realm_id field.
BCM_VLAN_CONTROL_VLAN_L3_IF_CLASS_MASK	Enable .l3_if_class field.
BCM_VLAN_CONTROL_VLAN_ALL_MASK	Enable all fields in bcm_vlan_control_vlan_t structure.

Returns

BCM_E_NONE	Operation completed successfully
BCM_E_UNAVAIL	Operation not supported
BCM_E_XXX	Operation failed.

VXLAN MANAGEMENT

New VXLAN port flags have been added.

Table 51: VXLAN port flags

<i>Name</i>	<i>Purpose</i>
BCM_VXLAN_VPN_REPLACE	Replace attributes of an existed VPN
BCM_VXLAN_VPN_UNKNOWN_UCAST_REPLACE	Replace unknown unicast mc-group of an existed VPN
BCM_VXLAN_VPN_UNKNOWN_MCAST_REPLACE	Replace unknown multicast mc-group of an existed VPN
BCM_VXLAN_VPN_BCAST_REPLACE	Replace broadcast mc-group of an existed VPN

Following VXLAN port flags has been deprecated.

Table 52: VXLAN port flags

<i>Name</i>	<i>Purpose</i>
BCM_VXLAN_MULTIPATH	Multipath flag for VXLAN

Section 7: Resolved Issues for 6.3.4

The following issues are resolved in version 6.3.4 of the SDK.

Table 53:

Number	CSP #	Chips	Release Notes For 6.3.4
SDK-4934		56024_B0 56024_A0	Fixed counter thread crash when running gsanity on 56024.
SDK-31914	364321	All	Added Diag shell command to dump group info without entries
SDK-37866		88650_A0 88640_A0 56850_A0 56850_A1 56850_A2	Fix conflicted command gport with getreg
SDK-38177		All	BCM_FIELD_USER_XXX flags are deprecated. All those flags are still used in code so they are moved to include/bcm_int/esw/field.h file.
SDK-38956		56640_A0 56548_A0 56546_A0 56545_A0 56544_A0 56542_A0 56541_A0 56540_A0 56641_A0 56642_A0 56643_A0 56644_A0 56645_A0 56648_A0	Added UDF support for MPLS packets with 3,4 and 5 labels in Triumph 3 device
SDK-39298		56640_A0 56640_A1	Added a new feature to control metering in egress mode
SDK-39435	625583	56846_A0 56845_B0 56845_A2 56844_A0 56842_A0 56840_A0 56850_A0 56855_A0 56843_B0 56841_A3 56846_A1 56841_B0 56854_B0 56854_A0 56850_A1	Add supports for the dual-lane forced speed mode running with CL72. It requires FW version A041_003 or above.
SDK-41137	549821	All	Instead of iterating on all ports. The iteration is on the list of ports added to the multicast group.
SDK-41495	557384	56640_B0	Support Triumph 3 in bcm_switch_pkt_info_hash_get() API and fix incomplete functionalities in compute load balancing and compute trunk hash of tridtn2.
SDK-42414		56640_A0	Fixed max threshold being set to zero for wred on triumph3 devices.
SDK-42899	558213	56640_A0 56850_A0	When the traffic is running, issuing a stats clear can cause the MMU unicast drop counters to get into a state, where the counts are not updated. The entry has 3 fields packet count, byte_count and parity field and all the fields need to be cleared if parity is not enabled. Fixed the issue. .

Table 53:

Number	CSP #	Chips	Release Notes For 6.3.4
SDK-43520		56640_A0 56440_A0 56450_A0	When SDK is initialized along with Firmware, queue configuration is required to indicate the Rx queues mapped to external CPU (Ehost) and microcontrollers (UC0, UC1). If the queue configuration is not present then SDK init fails. An error message is now displayed indicating if SDK init fails due to missing queue configuration.
SDK-44138	717410	56634_A0	snmpDot1dBasePortMtuExceededDiscards only counts packets dropped on Rx and does NOT include the count of packets dropped by the pipeline.
SDK-44342	601905	56640_A0 56640_A1 56640_B0	Triumph3 chip supports attaching up to 3 counters for an entry in IFP. Field STAT APIs have been enhanced to support the same in SDK.
SDK-45115		88650_B0	BCM shell: Typing "diag pp MODE_info_Set ?" in BCM shell would cause segmentation fault.
SDK-46005	615704	56640_A0 56540_A0	It has been observed that the BFD state toggled between UP and No error, Down + mis-connectivity. The issue is fixed by sending the CV packets/sec in down and mis-connectivity state to avoid the Toggling issue.
SDK-46431		56334_B0	Made code changes to configure L3_IIFf in VLAN_TABm during init.
SDK-46612	628861	56640_A0 56641_A0 56642_A0 56643_A0 56644_A0 56645_A0 56648_A0 56640_A1 56643_A1 56644_A1 56640_B0 56644_B0 56643_B0 56648_B0 56649_B0 56649_A0	Fix to address inconsistent callbacks on TR3, in polling mode.
SDK-46638	634464	56640_A0 56340_A0	Changed bcm_regex_match_check() to *actually* return number of bytes (although it was described that way, it previously returned number of states). Also added new API bcm_regex_engine_info_get() to get the SME and engine sizes.
SDK-46734	636372	56448_B0 All 56440_A0 56445_A0 56440_A1 56445_A1 56444_A1 56450_A0 56449_B0 56445_B0 56440_B0 56447_B0 56443_B0 56441_B0 56446_B0	Introduced new flag 'BCM_PORT_MATCH_PORT_VLAN16' in bcm_port_match_t to match mod-port/trunk+16 bit outer VLAN TAG for VLAN translation
SDK-48018	652215	56840_A0	SDK-48018 & SDK-48095 cosq bandwidth related setting.
SDK-48130	663340	56640_A0 56640_A1	Added code to initialize rtag7 flow based hash related parameters to enable macroflow offset APIs.
SDK-48272	665127	56334_B0 56334_A0	there was 'if' check preventing to return the egress enabled flags. For this, code fixed, to return the egress mirroring enabled flag .

Table 53:

Number	CSP #	Chips	Release Notes For 6.3.4
SDK-48433	627988	56224_B0 56224_A0	Removed the check in SDK which prevents the customer from configuring both <code>BCM_L2_LEARN_LIMIT_ACTION_DROP</code> and <code>BCM_L2_LEARN_LIMIT_ACTION_CPU</code> at the same time when making calls to <code>bcm_l2_learn_limit_set()</code> The corresponding actions are supported in the hardware for RAPTOR/RAVEN/HAWKEYE devices.
SDK-48449		56850_A2	The support for one-lane port running CL72 is added for the JIRA. Customers need to put 1) <code>port_init_cl72=0x1</code> in their configuration file, or 2) call API to enable the CL72 mode, then set the port speed. This JIRA requires FW version A041_002 or above.
SDK-49328	680979	56850_A0	Support add higg port into a trunk and related functions.
SDK-49342	681800	56142_A0 53001_A0 56850_A0 56450_A0	Control characters removed from SDK files
SDK-49347		NA	Updated the grog file for <code>bcm_port_encap_config_t</code> documentation.
SDK-49464	681536	88650_A0 88650_B0 88650_B1	When the packet is trapped and parsed in the CPU, the Source-System-Port parsing was not considering the LAG case. This is fixed, by setting the <code>src_trunk</code> parameter for the LAG Id, and the <code>src_port</code> and <code>src_mod</code> parameters corresponding to the selected LAG member port.
SDK-49473	683076	54680E_A1 54680E_B0 54682E_A1 54682E_B0 54685E_A1	In earlier releases there were Display errors in the EEE command for BCM54685E. This has been fixed.
SDK-49746		88650_A0 88650_B0 88650_B1	Enable Bounce back filter for 2-pass trill: In the second pass going back to trill packets are filtered by bounce-back-filter.
SDK-49829	684594	56440_B0	Fixed the code to configure the <code>RQE_PORT_CONFIG</code> in the <code>bcmPortControlCustomerQueueing</code> switchcontrol set for Katana/Katana2
SDK-50029	682932	56334_B0 56142_A0 56132_A0	Modified to install the selcodes in the slice if the slice was not empty and this is the first entry for the group in that slice
SDK-50066		88660_A0	In BCM88660, introduce new support for IPMC and IGMP after exiting tunnel (VXLAN, L2GRE, VPLS). See <code>cint_igmp_example.c</code> for application explanation and valid packet flows.
SDK-50108		56640_A0 56340_A0	Fixed crashes in regex module when - using <code>bcm_regex_match_check()</code> - issuing "regex show dfa" with counters not enabled.
SDK-50121		88650_A0	KBP Serdes init sequence changed to use KBP SDK API. Internal implementation change, no affect on customer application
SDK-50142	690184	56850_A0 56850_A1 56850_A2	According to port and cosq, retrieve hw queue number used by PBSMH header.
SDK-50162	692128	All	Multiple RX interrupt packet handlers would be called when a packet was handled.
SDK-50212		56850_A2	The code supports for 40G/42G HG FEC are added.
SDK-50288	692335	All	This is a duplicate of SDK-50288 BFD can not be supported in the LAN network because of IP addresses limitation. This has been fixed.

Table 53:

Number	CSP #	Chips	Release Notes For 6.3.4
SDK-50377	686726	56150_A0	Add KNET support for switch devices attached via iProc AXI bus.
SDK-50481	692651	All	Modified to check fiber channel inner and outer fields with BCM_FIELD_DATA_FORMAT_FIBRE_CHAN_ANY instead of 0
SDK-50498	696599	All	Add KNET support for BCM56150 family of devices.
SDK-50541	694835	56640_A0 56641_A0 56642_A0 56643_A0 56644_A0 56645_A0 56648_A0 56640_A1 56643_A1 56644_A1 56640_B0 56644_B0 56643_B0 56648_B0 56649_B0 56649_A0	There was an issue in the "_bcm_ft_report_process_export_entry" code where the flags returned by the FT call back process function was overlapping. This has been fixed.
SDK-50595		88650_A0 88650_B0	ERSPAN: Outbound Multicast ERSPAN mirroring is not supported in default application. To support multicast ERSPAN outbound mirroring a new soc property introduce "custom_feature_erspan_mc_support=1". In case it is set, first 16 entries in ISID-table are used for ERSPAN feature. When custom feature is enabled, User can allocate for MIM, VXLAN, L2GRE only VPNs that pass the constraint (vsi & 0xFFFF) > 16. Additionally, VPN must be allocated for those application WITH-ID only. See more details in cint_mirror_erspan.c
SDK-50611	684857	88650_A0	In Field Processor in Egress stage, an HW limitation requires that none or both lookup keys are valid in Egress PMF. If a single lookup key is valid, the second lookup key returned result will be invalid once used in the future. To handle this limitation, the Driver uses the last TCAM DB Profile (ID 47). It allows the user to define only 47 TCAM Databases instead of 48. To disable this implementation (e.g. if Egress Field Processor is not used), set the SOC property custom_feature_egress_pmf_lookups_always_valid_disable=1.
SDK-50637	689475	All	Add new soc property eb2_2bytes_big_endian to support EB2 endianness
SDK-50651	697868	All	Improve counter thread performance.
SDK-50753		88650_A0 88650_B0 88650_B1 88660_A0	Add new diag "diag_ing_congestion" to display ingress global resource.
SDK-50757		88650_A0 88650_B0 88650_B1 88660_A0	Added diagnostics "diag_ratesch" to display E2E scheduler rate.
SDK-50758		88650_A0 88650_B0 88650_B1 88660_A0	Added diagnostics "Gtimer" to control gtimer in sub-block for rate calculation. Added interval option for "diag counter".
SDK-50823	699173	88650_A0 88650_B0 88650_B1	At egress, the user can define a packet to be trapped and sent to the CPU. By default, the trap profile (action profile) was sending the packet to the Egress Queue Pair with ID = CPU Port number instead of sending to the CPU. This is fixed
SDK-50828	686923	88650_B1	STG: bcm_stg_vlan_add() and bcm_stg_stp_set() do not return BCM_E_NOT_FOUND when passed in a spanning tree group that does not exist. Update verification on those functions.



Table 53:

Number	CSP #	Chips	Release Notes For 6.3.4
SDK-50836		88650_A0 88650_B0 88650_B1 88660_A0	Add new diag(tdm edit show [port=15]) to display tdm edit information.
SDK-50859	697873	56850_A0	It was covered that 15 profiles could be created for the mapping from internal priority to MPLS Exp at the egress but 16 profiles could be created successfully when repeating the profiles creation. It is fixed in this release and max 15 profiles can be created.
SDK-50881	695207	56640_A0 56540_A0	IN earlier releases there was an issue with the function to create bfd endpoint with designate remote discriminator. Fixed the issue in both SDK and uKernel version 3.2.2..
SDK-50982	703790	56850_A0	Add BCM shell CLI support and HG_TRUNK mode for packet hash select API.
SDK-51019	687800	56850_A1	Implemented in the new policer mode bcmPolicerGroupModeShortIntPri for creation of 8 internal policers.
SDK-51065	705285	All 56643_A0 56643_A1 56643_B0	Updated to make triumph_3 devices to default boot in 64 port single modid mode and if config variable spn_MODULE_64PORTS = 0 then boot in dual modid mode
SDK-51127	702045	56640_A0 56643_A0 56640_A1 56643_A1 56640_B0 56643_B0	Corrected the offset of the qualifiers L4SrcPort, L4DstPort for external FP during qualifiers init.
SDK-51154	701733	56640_A0 56440_A0 56643_A0 56644_A0 56648_A0 56850_A0 56445_A0 56440_A1 56445_A1 56444_A1 56340_A0 56640_A1 56643_A1 56644_A1 56640_B0 56644_B0 56643_B0 56648_B0 56649_B0 56649_A0 56449_B0 56445_B0 56440_B0 56447_B0 56850_A1 56443_B0 56441_B0 56446_B0 56448_B0 56850_A2 56342_A0 56442_B0	Added bcmFieldActionETagNew [Add/Change ETAG] & bcmFieldActionETagDelete [Delete ETAG] in IFP to support Port Extenders Etag add/delete/change options.
SDK-51230	708240	All	Support added for new API to retrieve member port for DLB HG Trunk
SDK-51254		56850_A1	Fix provided for the functionality of clearing the 'lc_pbm_remote_fault' port-bitmap when a port is removed from SW/HW linkscan.
SDK-51340	709181	88650_B1	Upon FEC creation (bcm_l3_egress_create) Correct the verification of LAG ID to allow also group IDs that are higher than 32.
SDK-51348		88650_A0	To end a tdm session using you have two options: 1.Set destination port to an invalid destination - BCM_GPORT_BLACK_HOLE. 2.Call bcm_port_control_set () with type bcmPortControlRxEnable. Be advised, for tdm ports, when disabling a port rx, the valid range cell size min filter must be of 192B or above, and this configuration affects all of the other tdm sessions.
SDK-51357	708045	56440_A0	In earlier releases BCM_BFD_ENDPOINT_UPDATE did NOT update the tunnel initiator label . This has been addressed in uKernel 3.2.2.



Table 53:

Number	CSP #	Chips	Release Notes For 6.3.4
SDK-51405		56640_A0 56640_A1 56640_B0	L2 entries learnt on the trunk ports are not deleted on ring flush. The trunk ports are now matched with the Trunk port module ID (0x80) and the entry is deleted on ring flush in addition to the line ports.
SDK-51451		56846_A0 56845_B0 56845_A2 56844_A0 56842_A0 56840_A0 56850_A0 56843_B0 56841_A3 56846_A1 56841_B0 56850_A1 56850_A2	Support BCM_L2_STATION_COPY_TO_CPU configuration in l2 station entry for TD/TD2/TT2.
SDK-51506		56640_A0 56548_A0 56546_A0 56545_A0 56544_A0 56542_A0 56541_A0 56540_A0 56641_A0 56642_A0 56643_A0 56644_A0 56645_A0 56648_A0 56640_A1 56643_A1 56644_A1 56640_B0 56644_B0 56643_B0 56648_B0 56649_B0 56649_A0 56545_A1 56540_B0 56541_B0 56546_B0 56544_B0 56547_A0 56545_B0 56542_B0	Fixed issue in handling flushing MAC entries by Virtual Port's correctly. On Triumph3, the key_type is not being set correctly for Flush-by-VP calls. The key_type for MPLS, MiM, L2GRE, VXLAN VFI types needs to be set to VFI type
SDK-51521		88650_B1	Diagnostics: "diag pp Parsing_Info" sometimes output incorrect inner_vid value due to wrong initialization.
SDK-51534 SDK-52302		88650_A0	Improved performance bcm_port_enable_set (FALSE) - relevant to init as well
SDK-51553	710528	56850_A0 56850_A1 56850_A2	Correct the VLAN_PROFILEm configuration flow in qos module.
SDK-51568	705719	56850_A0 56850_A1 56830_A1 56850_A2 56830_A0 56830_A2	Modify memory scan with dma-disabled.
SDK-51597	704238	56224_B0 56224_A0	Made code changes to allow '-1' as valid port parameter in bcm_vlan_translate_add() for 56224 devices. '-1' is valid for 56224 as given in the Programmer's reference guide which indicates configuration on all the ports. The function bcm_esw_vlan_translate_add() should now able to configure for '-1' as well for 56224 devices.
SDK-51599	712774	All	In earlier releases SDK cli "mc show" did not display all OIFs for a multicast groupfixed to support any number of OIFs. This has been fixed to support any number of OIFs.
SDK-51636	693966	56850_A0 56850_A1 56850_A2	The TCL MBIST code has been converted to C code, now the code covers all memories, cams, and all multi-port and single port register files.

Table 53:

Number	CSP #	Chips	Release Notes For 6.3.4
SDK-51652	703012	88650_A0 88650_B0 88660_A0	L3 Egress object optimization: When connecting between MPLS/IP tunnel to link-layer (<code>bcm_l3_egress_create</code>), API always set Link-layer information even in case no Link-layer information has been modified. Use combination of flags <code>BCM_L3_KEEP_DSTMAC</code> , <code>BCM_L3_KEEP_VLAN</code> and <code>BCM_L3_REPLACE</code> and valid <code>encap_id</code> to modify only connection between MPLS/IP tunnel to link-layer. No link-layer modifications are done.
SDK-51665	713519	All	Add vlan control vlan selective set/get API.
SDK-51677	695953	88650_B0 88650_B1	When egress packets are dropped at the EGQ, i.e. EGQ-delete-queue is receiving traffic, it'll take priority over the NIF ports, and might cause packet drop. After the fix delete queue will get priority over NIF only if it is almost full.
SDK-51811	713635	56640_A0 56850_A0 56640_A1 56640_B0 56850_A1 56850_A2	Support symmetric hash for Resilient Hashing in TD2/TR3.
SDK-51814		88650_A0 88660_A0	When configuring VRRP for ARAD+, up to 4k VSIs can be assigned to each VRID. There was an error that made it impossible to delete a VRID if exactly 4k (4096) VSIs entries were assigned to it. The error is now fixed.
SDK-51823	716406	88030_A0	ppe config error carse variable length of packet header not work. modify ppe associate structure define to fix this issue.
SDK-51857	715638	All 56440_A0 56440_A1 56440_B0	Fixed bug in <code>stat_group_create</code> which was initializing '256' counters, which was causing this behavior,
SDK-51865		56450_A0	Changes made to use the existing field <code>encap_id</code> in <code>bcm_mpls_port_t</code> structure to pass the NHI for <code>bcm_mpls_port_add</code> .
SDK-51900		56640_B0	The table supports 16 entries per profile. There is an error in validating the number of entries parameter which was corrected
SDK-51902	705911	56440_A0 56440_B0	Corrected issue with BFD event thread not exiting by increasing the timeout to 5 seconds.
SDK-51920		88660_A0	OAM/BFD events: Support the DMA reroute writes intended to the Interrupt Message Register to a local host memory. To support this functionality the following soc properties should be configured: 1) <code>oamp_fifo_dma_enable</code> - enables fifo dma mode. Default is 0. 2) <code>oamp_fifo_dma_buffer_size</code> - length of the messages buffer we store in the CPU. 3) <code>oamp_fifo_dma_timeout</code> - the time for generating an interrupt when the fifo is not full. Value 0 indicates interrupt is sent only when fifo is full. Default is 0 4) <code>oamp_fifo_dma_threshold</code> - the number of events written until interrupt is generated.
SDK-51925	702621	88650_A0 88650_B0 88650_B1	Trill allows now multiple flooding-groups with the same nickname. This can be used to create flooding with the same nickname for different VSIs. Procedures which used both nickname and ID as the key (like <code>trill_port_get</code>) will work only with id. See an example of configuration in <code>cint_trill:trill_with_two_vlan_flooding</code> .

Table 53:

Number	CSP #	Chips	Release Notes For 6.3.4
SDK-51933		88660_A0	<p>In stacking systems, BCM88660 is able to pass 16 bits of Load-Balancing key and to reproduce the hashing decision in the second system. Thus, any limitation or performance decrease in hashing trunk is removed when using this option.</p> <p>In the data path, the first LB-Key byte is copied in the FTMH.LB-Key-Extension, whereas the second byte is copied in the second User-Header. At egress editor block of the first system, the second User-Header is copied to the start of packet to be extracted by the Ingress PMF in the second system.</p> <p>This option can be enabled by setting the following SOC properties: 1. <code>system_ftmh_load_balancing_ext_mod</code> <code>e=FULL_HASH</code> 2. <code>first_header_size<all stacking ports>=1</code> <code>3.field_class_id_size_1=8</code></p>
SDK-51934		88650_A0	<p>In Field Processor, the Direct table is one of possible Databases (<code>bcmFieldGroupModeDirect</code>). Its key is very short (10 bits maximum) and corresponds to the index line of the TCAM Action table. The support of the Warmboot was faulty in the Driver: the entry content was not retrieved correctly. This is fixed.</p>
SDK-51939	717396	All 56850_A0 56850_A1 56850_A2	<p>Modify <code>bcm_port_queued_count_get()</code> to support in Trident2</p>
SDK-51961	712277	88650_B0	<p>MIM: DEFAULT BEHAVIOR CHANGE . <code>bcm_l2_station_get()</code> API failed in some cases when VSI for MyMac was considered to be B-MyMac. This happened when the MIM indication bit in the created <code>station_id</code> was wrongfully set due to an overlap in the <code>station_id</code> encoding. This is fixed by changing the encoding of the <code>station_id</code> so that there is no overlap with the MIM indication bit. The MIM indication bit in <code>station_id</code> changed from bit 7 to bit 29.</p>
SDK-51967	718092	56850_A0	<p>Show MC prefix MCAST PERMITS in 'show c'</p>
SDK-51984	711243	56640_A0 56641_A0 56642_A0 56643_A0 56644_A0 56645_A0 56648_A0 56640_A1 56643_A1 56644_A1 56640_B0 56644_B0 56643_B0 56648_B0 56649_B0 56649_A0	<p>Corrected the bit number values for detecting the memory type.</p>
SDK-51993		88660_A0	<p>Trill: Introduce Multi-homing connectivity to the trill network allow a host to have access to trill campus using more than one RBridges. The host treats a group of edge RBridges as an Uplink link bundle that works in an active-active load sharing model. Arad+ support up to 3 virtual RBridges in system.</p> <p>See <code>cint_trill_multi_homing.c</code> for more description and packet-flows</p>

Table 53:

Number	CSP #	Chips	Release Notes For 6.3.4
SDK-51994	707370	88650_B1	IP tunnel termination lookup key is defined by SOC property: bcm886xx_ip4_tunnel_termination_mode. Added 2 new lookup key for IPV4 tunnel termination: bcm886xx_ip4_tunnel_termination_mode = 4 - Key is : {DIP, SIP, IPV4.Next-protocol} bcm886xx_ip4_tunnel_termination_mode = 5 - Keys are : {DIP, SIP, IPV4.Next-protocol}, {DIP} Lookup IPV4 next protocol is useful to configure multiple separate VPNs, with same DIP and SIP, but with different tunnel-types. See an example of use in: cint_ip_tunnel_term.c
SDK-52013		56440_A0 56243_B0 56240_B0 56242_B0	1. Corrected configuration of shared pool sizes for Saber. 2. Only ports 25 tot 28 of MXQPorts use PG7. SDK was setting it for ports 25 to 34. This is corrected now. 3. Corrected configuration of RQE_WQE, CFAPI, CFAPE and QENTRY free address pools based on how device is OTPd. This will prevent ECC errors when using Saber(BCM56240).
SDK-52033		56150_A0	Fixed DXGS mode of HG ports may not be consistently programmed.
SDK-52038	718933	56850_A2	In port speed set command, the driver will not enable the port if the port is not enabled.
SDK-52050	718941	56850_A0	Update trie code with trie_split fix.
SDK-52081		56850_A2	The JIRA fixes the temperature reading bug in the TSC driver. Also it provides the chip version information in DSC dump.
SDK-52098		56850_A0	Renamed BCM_FCOE_VSAN_NORMALIZED_CHECK to BCM_FCOE_VSAN_NORMALIZED_ZONE_CHECK
SDK-52110	720063	88030_A0	Support the encoding and decoding of ITMH, NPH and OAM headers in cint.
SDK-52142	719652	All	Documentation update for Field API bcm_field_entry_prio_set.
SDK-52148	718595	56846_A0 56845_B0 56845_A2 56844_A0 56842_A0 56840_A0 56850_A0 56855_A0 56843_B0 56841_A3 56846_A1 56841_B0 56854_B0 56854_A0 56850_A1 56851P_A1 56851_A1 56850_A2 56851_A2 56851P_A2 56854_A2 56853_A2 56852_A2 56855_A2 56851_A0 56852_A0 56852_A1 56853_A0 56853_A1	In double wide mode CosQCpuNew and ServicePoolIdNew actions are not treated as conflicting by putting them in different parts of the entry.
SDK-52166	715996	88650_A0 88650_B0 88650_B1	In External TCAM, when used with forwarding tables, each entry content (data and mask) is saved internally in a hash table to get the KBP Driver Entry-ID. This hash table had an incorrect key-size (only according to data), thus 2 entries with same data but different masks were considered as being identical. This is fixed.

Table 53:

Number	CSP #	Chips	Release Notes For 6.3.4
SDK-52168		88750_A0	Minor change to FE1600 isolation sequence, no effect on functionality or customer application.
SDK-52169		88650_A0 88650_B0 88650_B1 88660_A0	PON: bcmVlanPortIgnoreInnerPktTag can be used only for PON-Ports. NNI/CPU/Recycle ports do not support that vlan control value.
SDK-52189		88650_A0 88650_B0 88650_B1	The ISSU version handling is fixed. Otherwise, 6.3.4 would not be ISSU-able from 6.3.3.
SDK-52234	720648	All 56850_A0 56850_A1 56850_A2	added logic to find a matched entry in <code>l3_iif_profile</code> table during update of a entry.
SDK-52241		56850_A0 56850_A2	This fix modifies driver code to support HG20G non-scramble mode with DFE off. The scramble mode requires the DFE to be on.
SDK-52247	721059	56643_A0 56644_A0 56643_A1 56644_A1	Added fix to update the field group selector (IFP) during warm boot if vpn qualifier is part of the qset.
SDK-52253	716433	56850_A0 56850_A1 56850_A2	If there is a more specific match (in case of a bucket miss) for a destination IP, in some cases the more specific match could miss and hit the global default. This change fixes that issue.
SDK-52264	721288	56850_A0	Counter XAUI activity feature support for TD2 has been removed. <code>_soc_xgs3_update_link_activity</code> will not be called for TD2.
SDK-52358	722565	56850_A0	Support to get rtag7 hash value in port based HiGig proxy mode.
SDK-52361	722981	56850_A2	Add L3 lock in ser correction call to avoid deadlock in mem op and dpc ser correction thread. Moved definition of L3 lock from BCM to SOC layer.
SDK-52362	723016	88650_A0	PON: Creation of VLAN-Port with port parameter as VOQ-PON resulted in the API failure in the case where the PON PortnProfile that associate to the VLAN-Port is not profile 0. The sequence to support it 1.create VOQ per destination system-port (PON-port 0-7) 2. <code>bcm_vlan_port_create</code> with port being flow-VOQ gport. API will retrieve the correct PortnProfile and update the learn-information of PON-LIF to be VOQ
SDK-52368	721631	88650_A0	<code>cint_vlan_control_config.c</code> CINT example missing documentation specifying that <code>dflt_frwr</code> variable must be set to 1 in ARAD/ARAD+. VSI flooding group must be set the same for all unknown-uc/unknown-mc/broadcast fields. In order to set various default forwarding modes, e.g unknown unicast, unknown multicast and broadcast, use: <code>bcmPortControlFloodUnknownUcastGroup</code> , <code>bcmPortControlFloodUnknownMcastGroup</code> , <code>bcmPortControlFloodBroadcastGroup</code>
SDK-52397	722792	88030_A0	Fixed bcm88030 A1 port status LED issue
SDK-52405	723353	88650_A0 88650_B0 88650_B1	RX-LOS application - added support interlaken ports
SDK-52407	723478	56850_A0	Support Concatenate mode in calculating ECMP, LAG and HGT rtag7 hash index.
SDK-52416		88660_A0	ARAD+ fails to init OAM after WB when adding lm or dm object.
SDK-52419		All	Added a check to prevent statistics increment if replace and ID flags are set

Table 53:

Number	CSP #	Chips	Release Notes For 6.3.4
SDK-52434	723350	56640_A0 56640_A1 56640_B0	Fixed packet alignment issue on higig port. When a higig port is connected to external phy and if user configures 42K speed on it, then <code>xlgmii_align</code> bit should be set with 1. This fix sets the <code>xlgmii_align</code> bit when higig port is configured in 42000 speed.
SDK-52469	701853	All	<code>BCM_FIELD_DATA_QUALIFIER_OFFSET_NEGATIVE</code> is not valid on xgs ,hence returning <code>BCM_E_UNAVAIL</code> when qualifier is set
SDK-52474		56850_A1 56850_A2 56850_A0	Added doc changes for <code>bcmFieldActionETagNew</code> [Add/Change ETAG] & <code>bcmFieldActionETagDelete</code> [Delete ETAG] in IFP to support Port Extenders Etag add/delete/change options.
SDK-52476		56850_A1 56850_A2 56850_A0	Added <code>bcmFieldActionETagNew</code> [Add/Change ETAG] & <code>bcmFieldActionETagDelete</code> [Delete ETAG] in IFP to support Port Extenders Etag add/delete/change options.
SDK-52490	724657	56640_A0 56440_A0 56440_B0	Added support to specify the timestamp offset during CPU packet tx.
SDK-52496	723483	84756_A0 84756_C0	<code>phy84756_fcmap.c</code> driver : Added pluggable PHY support
SDK-52501		56640_B0	NL11K external tcam uses 80-bit wide registers. The CLI command "tcam dbreg" is using only 72bits causing the upper byte on the register value to be truncated. Fixed the code to use 80bits.
SDK-52512		88650_A0 88660_A0	MPLSVPNcreation <code>bcm_mpls_vpn_id_create</code> is now valid for both VPN ranges 0-4K and 4K-32K.
SDK-52513		88650_A0	VLAN-Port: SW-DB forwarding information of VLAN-Port might not update correctly because of uninitialized parameters caused <code>bcm_vswitch_port_add</code> to fail on random cases.
SDK-52518	705177	88650_B1	STG Warmboot: Warmboot stored STP state per port up to STG-ID 12 and so didn't recover for all other groups. Updated Warmboot STG allocation size to correct size.
SDK-52519		88750_B0	Snake test with external loopback failed when running it over BCM88750_B0 . Fixed.

Table 53:

Number	CSP #	Chips	Release Notes For 6.3.4
SDK-52526	719683	88650_A0 88650_B0 88650_B1 88660_A0	<p>VLAN: A VLAN-Port object can be created per port by calling the API <code>bcm_vlan_port_create()</code> with a <code>MATCH_PORT</code> criteria and can be identified by a <code>vlan_port_id</code> value. The object may be destroyed using <code>bcm_vlan_port_destroy()</code> by supplying the <code>vlan_port_id</code>. Destroying the object frees the <code>vlan_port_id</code> that can be used for some other VLAN-Port object creation when the <code>WITH_ID</code> flag is used and the <code>vlan_port_id</code> is supplied.</p> <p>A problem occurs when performing a create and destroy sequence for 3 times with the same <code>vlan_port_id</code>. The third creation fails as some resources weren't freed correctly during the destroy of objects with <code>MATCH_PORT</code> criteria.</p> <p>The resource freeing during destroy, was fixed for the <code>MATCH_PORT</code> criteria objects as well.</p> <p>The issue detailed above affects the unicast RPF mode per RIF feature (the SOC property <code>bcm886xx_l3_ingress_urpf_enable=1</code>). When this feature is used by specifying a uRPF mode other than <code>BCM_SWITCH_URPF_DISABLE</code> in <code>bcm_l3_ingress_t.urpf_mode</code> for <code>bcm_l3_ingress_create</code>, deleting LIFs which are members of RIFs that use uRPF with the <code>MATCH_PORT</code> criteria will result in undefined behavior.</p>
SDK-52529		88660_A0	Support oam accelerated loopback. See an example of use in: <code>cint_oam_arad_plus.c</code>
SDK-52575	725460	53343_A0 56150_A0	Correct supported number of multicast replication interface of BCM56150.
SDK-52583	710089	56450_A0	CLI command "oam endpoint show" fixed to exhibit correct endpoint information for BCM56450
SDK-52584	725729	56450_A0	Added queue configuration assuming internal-lossless settings
SDK-52588	725824	56450_A0	Fixed to handle -1 as numq for scheduler gport.
SDK-52592		88650_A0 88650_B0 88650_B1 88660_A0	<p>MPLS VPNs can be created using <code>bcm_petra_mpls_vpn_id_create()</code>. In DNX Arch only VPLS mode requires valid VPN ID. VPWS does not require to go by VPN (Cross-connect only). The VPWS VPN creation isn't supported but the API succeed to allocate a VPN that in fact is created with VPLS encoding. For the 6.3 branch, the ability to enter VPWS VPN is valid only for ID 0 For 6.4, the VPWS flag is no longer supported, as it is not required in MPLS VPWS sequence. See <code>cint_vswitch_cross_connect_p2p.c</code> for more information on VPWS connection.</p>
SDK-52600		88650_A0 88650_B0 88650_B1 88660_A0	<p>A LIF can be created with no Ingress AC-Key matching by calling <code>bcm_vlan_port_create()</code> with a criteria field set to <code>BCM_VLAN_PORT_MATCH_NONE</code>. Later, the LIF values may be edited by calling the same BCM API with the additional <code>BCM_VLAN_PORT_REPLACE</code> flag. The modification of LIFs (using <code>BCM_VLAN_PORT_REPLACE</code>) that were originally created with criteria <code>BCM_VLAN_PORT_MATCH_NONE</code>, was failed.</p>

Table 53:

Number	CSP #	Chips	Release Notes For 6.3.4
SDK-52601		88650_A0	In Warmboot, Some modules were performing a wrong version verification during Warmboot reload. This is fixed, otherwise 6.3.4 would not be ISSU-able from 6.3.3.
SDK-52618	724270	88030_A0	SDk-52618 RCE Errors (ECC etc) - was test packet
SDK-52622		56850_A1	1. Resolved RPC issue for the new API array arguments by fixing the papi. 2. Updated internal API implementation using bitmaps instead of multiple iterations to improve the performance.
SDK-52628		88660_A0	CGE1 traffic fall in NBI in case of 2Cau1 +Elk was fixed
SDK-52629		88660_A0	Fixed: PRBS APIs support 2 CAUI + ELK
SDK-52630	726283	56450_A0	Changed the delete sequence for L0 and L1 Nodes First delete the subtree node first and then delete the parent node
SDK-52633		88650_A0 88650_B0 88650_B1	In 6.3.3, a version compiled without the WARMBOOT compilation flags was failing at initialization due to minor code missing in switch init. This is fixed.
SDK-52637		88650_A0 88660_A0	In Policar, a single 2-rate color blind meter with the default configuration (32 range mode, SERIAL) would not do rate limitation. This behavior is now corrected.
SDK-52639	710412	88650_A0 88650_B0 88660_A0	In Egress L2, an HW field (CustomLearn) was set by mistake - it is a debug-only not-validated field intended to allow more packets to be learnt.
SDK-52643	723104	88650_B1	In 1588 application, an ITMH packet can be injected with an OAM-TS header above to indicate the header offset for the timestamp. Due to HW implementation, the usage of User-Header requires the following action from the user: - if a SOC property <code>field_class_id_size_X</code> is set, then an injected packet of type Ethernet over OAM-TS over ITMH over PTCH-2 requires: 1. to insert the User-Header to be inserted between Ethernet and OAM-TS 2. the Opaque-Attribute.LSB in PTCH-2 (bit 12) must be set 3. the ITMH destination is of type System-Port
SDK-52667	724073	88750_A0 88650_A0 88650_B0 88650_B1	Fixed a misconfiguration when setting FE1600 to work in repeater mode, that could cause occasional drops.
SDK-52668	725913	56850_A0 56850_A1 56850_A2	Fixed issue where hash-move when moving an invalid entry may break wider conflict entry.
SDK-52673	726396	56850_A0 56850_A1 56850_A2	When port is disabled or link down, remove related bitmap from below three registers. Thus traffic will not be enqueued to these ports any more. THDU_OUTPUT_PORT_RX_ENABLE0_64 MMU_THDM_DB_PORTSP_RX_ENABLE0_64 MMU_THDM_MCQE_PORTSP_RX_ENABLE0_64
SDK-52678		88750_A0 88650_A0 88650_B0 88650_B1	In a multi-stage system, live removal of an FE1600 or ARAD device could result in occasional drops. Fixed.
SDK-52683		88650_A0	Nif fc indication mask - i.e the mask which defines to the nif which flow control indications it should ignore and which not - is now in accordance with fc receive path setting.

Table 53:

Number	CSP #	Chips	Release Notes For 6.3.4
SDK-52691	726146	88650_A0 88650_B0 88650_B1 88660_A0	VLAN-Port Advanced VLAN translation: Packet discard can be set either per physical port or per LIF. In standard VLAN edit mode, the API <code>bcm_port_discard_set()</code> is used to set the discard state both for physical ports and for Out-LIFs. In Advanced VLAN edit mode, the API <code>bcm_port_tpid_class_set()</code> is used to set the physical discard state, while Out-LIF discard is also blocked in <code>bcm_port_discard_set()</code> . The API <code>bcm_port_discard_set()</code> is now available for setting Out-LIF discard state in AVT mode as well. The same way, <code>bcm_port_discard_get()</code> now retrieves an Out-LIF discard state in AVT mode.
SDK-52699	725215	88650_B1	Fabric source routed cell receive did not support multiple SR cells in parallel. Fixed.
SDK-52715		56850_A2	Reduced the proxy access wait time to no longer than 2.5 sec if it was longer before. This fix is to prevent some systems from crashing if a long wait time occurs.
SDK-52731		88650_A0 88650_B0 88650_B1	Fixed corrective action in case of parity error interrupt in WDF table
SDK-52741	720579	88650_A0 88650_B0 88650_B1 88660_A0	Fast flush enables clearing MACT entries for LIFs that are associated with a ring protection group FEC using <code>bcm_l2_replace()</code> using the <code>BCM_L2_REPLACE_PROTECTION_RING</code> flag. A LIF association to a group is done by calling <code>bcm_port_class_set()</code> with the class set to <code>bcmPortClassL2Lookup</code> . A LIF association of a remote LIF to ring protection group performs LIF HW configuration instead of only SW DB configuration, resulting potential problems when remote LIFs are used. The API <code>bcm_port_class_set()</code> has changed so that it configures the LIF HW only for local LIFs. Ring Protection CINTs and tests were updated to support a multidevice setup. See <code>cint_l2_fast_flush.c</code>
SDK-52742		88650_A0 88660_A0	Support TDM (OTN/CBR) traffic for mixed systems. Specially for mixed systems with ARAD and PetraB, when using VCS256 fabric cells, the packets are split to smaller cells by fabric devices (FE1600) during their transport, and are reassembled at the receiving FAP. The reassemble is done based on an attribute called "source-FAP-ID". This source FAP-ID is calculated as the FAP-ID of the source FAP plus a configurable offset. This source-FAP-ID value must be unique in the TM domain, and different from all FAP-IDs in the TM domain. The offset is specified by a new soc property called <code>tdm_source_fap_id_offset</code> . If it is not specified by the soc property, its default value is 256.
SDK-52759		56850_A0 56850_A1 56850_A2	Fixed range check for VXLAN VN_ID and L2GRE VPNID during vpn create API
SDK-52760		88650_A0 88650_B0 88650_B1	PON: VLAN-Port destroy for 3-tags manipulation in PON application should clean also EEDB resource.
SDK-52762	728229	56450_A0	CoE/LinkPHY subports are not added to default VLAN 1. Customer application needs to manage the VLAN 1 membership for CoE/LinkPHY subports. The subport should be added to the VLAN 1 after creating the scheduler tree for the subport.
SDK-52763	719360	88650_A0 88650_B0 88650_B1 88660_A0	Fixed mirroring and snooping settings that did not work in certain cases.

Table 53:

Number	CSP #	Chips	Release Notes For 6.3.4
SDK-52766		88650_A0 88650_B0 88650_B1 88660_A0	When a CAUI port is disabled and then enabled (no traffic is running), the MIB counters show incorrect values. The issue was fixed.
SDK-52771		88650_A0 88650_B0 88650_B1	RSPAN: does not work when port control bcmPortControlErsanEnable is set to 1
SDK-52772		88650_A0 88650_B0 88660_A0	OAM snooped packets are corrupted - snooped packet arrives to the CPU with trap headers.
SDK-52774	728360	56850_A0	Clear the egress mirroring MTP index of port unless the MTP slot is released.
SDK-52782	728467	56850_A0	In this release, we can use DISABLE_TUNNEL_IP4_GRE_IP6 DISABLE_TUNNEL_IP4_GRE_IP4 to set DISABLE_HASH_INNER_IPV4_OVER_GRE_I PV6_A/B ,DISABLE_HASH_INNER_IPV4_OVER_GRE_ IPV4_A/B individually, or still use the old flag BCM_HASH_FIELD0_DISABLE_TUNNEL_IP4 GRE to set both fields in RTAG7_HASH_CONTROLr as legacy. IPv6 flags are same to IPv4.
SDK-52788	728597	All	Solved FIELD_ENTRY_MISMATCH problem in bcm_field_qualify_IpType_get by implementing new device specific functions to get iptype encoding using hw_data and hw_mask.
SDK-52795	728851	56447_B0	MMU threshold settings for extended queues has been updated for Katana (BCM5644x)
SDK-52796	728261	56450_A0	Fixed IFP packet resolution for BCM56450
SDK-52800		88650_A0	When calling bcm_petra_cosq_fc_path_get with bcmCosqFlowControlGeneration and vsq llfc or pfc as the trigger, fc indications where not set correctly. fixed.
SDK-52806	728092	56648_A0	On change of priority for the VLAN. A small delay is introduced as new priority mapping happens after deletion of old index. On live traffic, this transitional delay causes some packets to be on priority 0 queue as the mapping is under transition. Fixed in the transitional delay for smooth traffic flow on priority transition.
SDK-52821		56850_A0	Updated documentation for the following new API:s added. bcm_cosq_stat_sync_get, bcm_cosq_stat_sync_get32
SDK-52823		56850_A0	New API's added for cosq_stat retrieval bcm_cosq_stat_sync_get bcm_cosq_stat_sync_get32. Same as bcm_cosq_stat_get(), value returned is software accumulated counter synced with the hardware counter.
SDK-52830		88030_A0	Fixed taps unified mode ucode lookup issue with certain config on bcm88030
SDK-52831		88030_A0	Fixed taps capacity resource leak update rate and host memory leak issue found in last patch on bcm88030
SDK-52833 SDK-52190		56850_A2	This JIRA fixes the problem that TSCMOD doesn't have a clean restart for CL72, such that it may cause incorrect training results. The probability of the training problem is about 1% of link restart.
SDK-52836	728502	All	Fixed Assert While installing VFP entries with flex counters attached
SDK-52844	728330	56450_A0	Code fixed to update the reference count properly (next hop entry used by mpls port)



Table 53:

Number	CSP #	Chips	Release Notes For 6.3.4
SDK-52848		88650_A0 88660_A0	The BCM shell command "l2 show" displays the L2 MACT entries for the unit. There was an error when in case the forwarding information included an OutLIF value, this value wasn't displayed. The problem was fixed, and the OutLIF is displayed properly now.
SDK-52857	695985	All	Updated grog for Inports to reflect the correct behavior
SDK-52859	707972	54680_A0 54682E_A1	Enhancing documentation/description for the config property <code>phy_port_primary_and_offset_<port></code>
SDK-52860	728139	88650_B1	In some scenarios, dependent on the allocated ports and typically involving CAUI ports, an underrun may occur resulting in not reaching full port capacity. Fixed.
SDK-52873	729725	56450_A0	Fixed the following issues for BCM56450 1. programming of <code>FP_DOUBLE_WIDE_SELECT.slice_x_f1</code> . 2. proper initialization of <code>IFP_SINGLE_WIDE_F1_5</code> .
SDK-52918	729962	56840_A0	Added support for handling remote fault link status.
SDK-52923		88660_A0	OAM: New support in updating loss and delay objects was added. New object is created using <code>bcm_oam_loss/delay_add()</code> . The update is performed using the same api with the flag <code>BCM_OAM_LOSS/DELAY_UPDATE</code> flag set.
SDK-52924		88650_A0 88650_B0 88650_B1 88660_A0	MPLS: A VSI can be associated as an MPLS VPN by calling <code>bcm_mpls_vpn_id_create()</code> . The VPN ID should be supplied as well as a <code>BCM_MPLS_VPN_WITH_ID</code> flag. Changing VPN fields is possible after creation, using the additional <code>BCM_MPLS_VPN_REPLACE</code> flag. The same VSI may also be used for vswitch, MIM, etc. The handling of the <code>BCM_MPLS_VPN_WITH_ID</code> & <code>BCM_MPLS_VPN_REPLACE</code> flags wasn't correct. Performing a create, with the replace flag <code>BCM_MPLS_VPN_REPLACE</code> , failed for an allocated VPN ID instead of succeeding. The same way, for an unallocated VPN ID, the API succeeded instead of failing. The behavior of the <code>BCM_MPLS_VPN_WITH_ID</code> & <code>BCM_MPLS_VPN_REPLACE</code> flags in <code>bcm_mpls_vpn_id_create()</code> was fixed.
SDK-52925		88660_A0	arad+ : minimum number of links warning message will be displayed only when current number of links < minimum number of links configured
SDK-52930	728932	56850_A0 56855_A0 56854_B0 56854_A0 56850_A1 56851P_A1 56851_A1 56850_A2 56851_A2 56851P_A2 56854_A2 56853_A2 56852_A2 56855_A2 56851_A0 56852_A0 56852_A1 56853_A0 56853_A1	In the previous release it was found that if you set <code>bcmPortControlMmuDrain</code> control to an admin-down port (disabled port), then after the port is re-enabling, the traffic to that port will be blocked. This issue was fixed by restoring the value of <code>XLMAC_CTRL</code> after draining cell.
SDK-52943	730095	56840_A0	New option "nocache" added to dump command, to display h/w table contents skipping cache.

Table 53:

Number	CSP #	Chips	Release Notes For 6.3.4
SDK-52949 SDK-52269		88650_A0	For packets with meters (policing), the color (aka Drop-precedence) resulting from the metering was never stamped on the FTMH.EGRESS-DP, even if the device was configured to do this. This affects many QoS applications - one example is that the PCP cannot be changed according to the meter result. This is now fixed - when the meter result is configured to go to Egress (e.g. with <code>BCM_FIELD_USE_POLICER_RESULT_EGRESS</code>), it is stamped on the FTMH and can be used at egress.
SDK-52951		88650_A0	Enabling of slow rate 2 corrected: Previously, calling: <code>bcm_cosq_control_set</code> with control: <code>bcmCosqControlFlowSlowRate</code> and <code>arg=1</code> would have set <code>slowRate2</code> . If the same API was called with the same control and <code>arg=2</code> an error would occur. Both were corrected so now calling with <code>arg=0</code> disables <code>slow_rate</code> , calling with <code>arg=1</code> enables <code>slow_rate1</code> and calling with <code>arg=2</code> enables <code>slow_rate2</code>
SDK-52952		88650_A0 88650_B0 88660_A0	OAM-BFD co-existence: <code>bcm_bfd_init</code> resets some of the oam registers (in <code>bcm_oam_init</code>). Thus no oam endpoints can be added before calling <code>bfd_init</code> .
SDK-52953		88650_A0	Fixed ilknn oob default calendar setting to XON. Note: XON indications means port should be on - no fc.
SDK-52971		88660_A0	ARAD plus device supports either BFDpPWE or BFDCCoMPLSTP encapsulations. This should be defined by the user with a soc property. <code>bfd_encapsulation_mode</code> soc property is setting <code>bfd pwe</code> (mode 0) or <code>bfd cc mplstp</code> mode (mode 1). 0 by default. See example of use in <code>cint_bfd.c</code> .
SDK-52990	730016	88650_A0 88650_B0 88650_B1 88660_A0	Advanced VLAN translation: Upon Configuration of an advanced VLAN edit action entry using <code>bcm_vlan_translate_action_id_set()</code> , the TPID values that will be used are mandatory fields. At the Ingress side, those TPIDs are matched with an existing TPID profile value that is passed to the Egress. The API is failed if no such TPID profile matching is found. The TPID profile consists of up to two global TPIDs. The TPID profile matching consists of two stages: 1. Exact match - The supplied TPIDs are similar to those of the TPID profile and are similarly positioned (Outer/Inner). 2. Opposite match - The supplied TPIDs are similar to those of the TPID profile but are inversely positioned (Outer/Inner). The problem occurs when supplying two similar TPIDs: Only a TPID profile that consists of two instances of this TPID will be matched. If no such TPID profile exists, the command will be failed. A third matching lookup was added to address the cases where two similar TPIDs are supplied. This lookup requires that this TPID will be included only once in a TPID profile, in any position, in order to match the TPID profile.
SDK-53007		88650_A0 88650_B0 88660_A0	<code>bcm_oam_opcode_map_set/get</code> is now functional
SDK-53011		88650_A0 88650_B0 88650_B1 88660_A0	<code>bcm_port_learn_set</code> now supports enable/disable SA when destination is Flow-ID



Table 53:

Number	CSP #	Chips	Release Notes For 6.3.4
SDK-53019		88660_A0	OAM: Add support for <code>bcm_oam_loss_get</code> , <code>bcm_oam_delay_get</code> , <code>bcm_oam_loopback_get</code> apis.
SDK-53045	730837	56540_B0	Added new redirect soc APIs for autoneg and loopback configurations to get accessed for phy specific GPORTs. Implemented this into existing APIs <code>bcm_port_autoneg_set/get()</code> <code>bcm_port_loopback_set/get()</code> APIs.
SDK-53056		88650_A0 88650_B0 88650_B1	PON: Recycle and mirror ports must be allocated from port 128 and above. Other ports (0-127) are used for PON side.
SDK-53082	730548	All	Prevent potential data corruption after KNET kernel driver call to <code>skb_padto</code> .
SDK-53099		88650_A0 88650_B0 88660_A0	Trill RPF-Check: In SDK 6.3.3 RPF check was moved to LEM + PMF. See <code>cint_trill.c</code> for more information. In SDK 6.3.4 removed unused code <code>bcm_trill_multicast_source_add/</code> <code>bcm_trill_multicast_source_delete/</code> <code>bcm_trill_multicast_source_get</code> for ARAD.
SDK-53108		88650_A0	Different ports can now be set with <code>pfc/llfc</code> (could not be set differently before). Also - disabling one port <code>fc</code> will not stop <code>fc</code> in a device level - Fixed
SDK-53109		88650_A0	VLAN: Change the macros <code>VLAN_CHK_PRIO</code> and <code>VLAN_CHK_ACTION</code> to <code>BCM_DPP_VLAN_CHK_PRIO</code> and <code>BCM_DPP_VLAN_CHK_ACTION</code> These definition in <code>include/bcm_int/dpp/vlan.h</code> appears also in <code>include/bcm_int/esw/vlan.h</code> and causes compilation errors.
SDK-53110		88650_A0	VLAN: Change the structure <code>bcm_vlan_info_s</code> to <code>bcm_dpp_vlan_info_s</code> . This structure appears also in <code>include/bcm_int/esw/vlan.h</code> and causes compilation errors.
SDK-53111		88650_A0	MPLS: Change the struct <code>_bcm_tr_mpls_bookkeeping_s</code> to <code>_bcm_dpp_mpls_bookkeeping_s</code> The struct <code>_bcm_tr_mpls_bookkeeping_s</code> appears also in <code>include/bcm_int/esw/mpls.h</code> and causes build errors.
SDK-53129	731105	56850_A0 56850_A1 56850_A2	Fixed link interrupt miss issue in 1G mode
SDK-53132		88650_A0	Trunk: Change the structure <code>trunk_private_s</code> (<code>trunk_private_t</code>) to <code>bcm_dpp_trunk_private_s</code> (<code>bcm_dpp_trunk_private_t</code>) This structure is defined also in <code>include/bcm_int/esw/trunk.h</code> and causes building error.
SDK-53149		88650_A0 88650_B0 88660_A0	Fixed wrong check pon port when setting and getting <code>bcmVlanPortIgnoreInnerPktTag</code> for pon port.
SDK-53183	728584	All	API <code>bcm_cosq_gport_connection_get</code> returned error for ISQ ports. The API is now valid also for ISQ ports.

Table 53:

Number	CSP #	Chips	Release Notes For 6.3.4
SDK-53192		88650_A0 88650_B0 88650_B1	L3 APIs replace: 1.Support to replace vrf, mac addr, ttl, mtu and dscp qos map id by bcm_l3_intf_create with BCM_L3_REPLACE flag. 2.Support to replace l3 intf, next hop mac, port tgid and encap id by bcm_l3_host_add with BCM_L3_REPLACE flag. 3.Support to replace l3 intf and port tgid by bcm_l3_route_add with BCM_L3_REPLACE flag.
SDK-53194		88650_A0 88650_B0	Support the replace for bcm_mim_vpn_create and bcm_trill_vpn_create.
SDK-53195 SDK-53298		88650_A0 88650_B0 88650_B1 88660_A0	1.Support to replace mc-group and L3 route interface by bcm_ipmc_add with BCM_IPMC_REPLACE flags. 2.Support to replace unknown unicast mc-group, unknown multicast mc-group and broadcast mc-group by bcm_l2gre_vpn_create with BCM_L2GRE_VPN_REPLACE, BCM_L2GRE_VPN_UNKNOWN_UCAST_REPLACE, BCM_L2GRE_VPN_UNKNOWN_MCAST_REPLACE, BCM_L2GRE_VPN_BCAST_REPLACE flags. 3.Support to replace match port and flag with/without BCM_L2GRE_PORT_NETWORK by bcm_l2gre_port_add with BCM_L2GRE_PORT_REPLACE flag. 4.Support to replace unknown unicast mc-group, unknown multicast mc-group and broadcast mc-group by bcm_vxlan_vpn_create with BCM_VXLAN_VPN_REPLACE, BCM_VXLAN_VPN_UNKNOWN_UCAST_REPLACE, BCM_VXLAN_VPN_UNKNOWN_MCAST_REPLACE, BCM_VXLAN_VPN_BCAST_REPLACE flags. 5.support to replace match port and flag with/without BCM_VXLAN_PORT_NETWORK by bcm_vxlan_port_add with BCM_VXLAN_PORT_REPLACE flag.

Table 53:

Number	CSP #	Chips	Release Notes For 6.3.4
SDK-53196		88650_A0 88650_B0 88650_B1	MPLS APIs Replace: 1.Support bcm_mpls_port_add to replace match_label, vpn, and flags (BCM_MPLS_PORT_CONTROL_WORD, BCM_MPLS_PORT_ENTROPY_ENABLE) with BCM_MPLS_PORT_REPLACE and mpls_port_id. In case of mpls_port_id is protected, egress_label.label and port of FEC can also be replaced. 2.Support bcm_mpls_tunnel_initiator_create to replace label, vsi and action with BCM_MPLS_EGRESS_LABEL_REPLACE and tunnel_id. 3.Support bcm_mpls_tunnel_switch_create to replace egress_label, qos_map_id, tunnel_if and flags (BCM_MPLS_SWITCH_FRR, BCM_MPLS_SWITCH_LOOKUP_SECOND_LABEL, BCM_MPLS_SWITCH_ENTROPY_ENABLE, BCM_MPLS_SWITCH_TRAP_TTL_0, BCM_MPLS_SWITCH_TRAP_TTL_1, BCM_MPLS_SWITCH_SKIP_ETHERNET, BCM_MPLS_SWITCH_NEXT_HEADER_L2, BCM_MPLS_SWITCH_NEXT_HEADER_IPV4, BCM_MPLS_SWITCH_NEXT_HEADER_IPV6) with BCM_MPLS_SWITCH_REPLACE and in_label, in case of action is BCM_MPLS_SWITCH_ACTION_POP. 4.Support bcm_mpls_vpn_id_create to replace broadcast_group, unknown_multicast_group and unknown_unicast_group with flags BCM_MPLS_VPN_VPLS BCM_MPLS_VPN_WITH_ID. The replaced broadcast_group should be equal to unknown_multicast_group and also equal to unknown_unicast_group.
SDK-53201	710888	88650_A0 88650_B0	ARP extender provides the ability for IPV4 UC packets MAC extension offset from IPV4 host table to next-hop mac address. In ARAD-A/B ARP extender is implemented using the egress-editor micro-code. Program caused on some Trill packets to drop. Modified ARP extender program to handle only IPV4 UC packets as it should be.
SDK-53202	727655	88650_B0	bcm_bfd_endpoint_create WITH_ID ignores the given id and returns a new allocated one.
SDK-53225		88650_A0 88660_A0	VLAN: SDK/src/examples/dpp/cint_vlan_translation_new_mode.c was renamed to appropriate name: SDK/src/examples/dpp/cint_advanced_vlan_translation_mode.c
SDK-53227	733542	56450_A0	Corrected code for Multicast traffic. PID will be updated by cosq scheduler function at run time (for subport queue configuration etc)
SDK-53255	728560	56640_B0	check the fiber_pref during speed set
SDK-53283	733471	56450_A0	Clear HQOS configuration while switching from extended queuing to diffserv queuing.

Table 53:

Number	CSP #	Chips	Release Notes For 6.3.4
SDK-53286	733518	88650_A0 88660_A0	PON: Add a new criteria "BCM_VLAN_PORT_MATCH_PORT_TUNNEL_PCP" to classify PON InLIF based on PON-Port, Tunnel-ID and outer PCP.
SDK-53289	734160	56450_A0	Fixed SOURCE_TRUNK_MAP_MODBASE and SOURCE_TRUNK_MAP configuration for BCM56450
SDK-53290		88660_A0	When a link status changed , fabric min number of links feature might not work, and traffic won't stop. Fixed.
SDK-53301 SDK-53047		88650_A0 88660_A0	Trill functionality always enabled Trill designated VLAN check: A single VLAN allowed for Trill encapsulated packet on a specific port. Device supports up to 8 different designated VLANs. In case more than 8 different designated VLANs are needed, user needs to disable this check. New soc property added to disable this check - trill_designated_vlan_check_disable=1. User can mimic check using ACLs.
SDK-53304		88660_A0	<p>Introduce a new VLAN-Port property : FORWARD_GROUP In the regular VLAN-Port settings MACT forward to VLAN-Port. In order to forward to VLAN-Port MACT needs two fields information: Out-LIF (outgoing logical interface) and Out-Port (physical destination). Forward-Group allows instead of using the MACT to result for forwarding information, have indirection group (forward-group) to provide the information on destination and the other bits to use the FP settings in a flexible way.</p> <p>The indirection object (Forward-group) that consist both the physical-destination and the outgoing logical-interface (out-LIF) is implemented in DNX using FEC.</p> <p>To allow such a scheme a flag indicate it BCM_VLAN_PORT_FORWARD_GROUP /* Use forwarding group */ Note: When supporting Forward-Group device must disable HW learning and use only CPU learning.</p>
SDK-53327		88650_A0 88650_B0 88650_B1	PON: In application level, upstream and downstream should use different MC-ID upon VPN PON service creation.
SDK-53338		56850_A1 56850_A2 56850_A0	Fixed range check for VXLAN VN_ID and L2GRE VPNID during vpn create API
SDK-53341		88650_A0	Calculation of channelized interface shaper is now corrected when calling: bcm_cosq_gport_bandwidth_set(unit, parent_port, cosq, 0, kbits_per_sec, 0); Where parent_port is: BCM_COSQ_GPORT_E2E_PORT_SET(e2e_port, port); bcm_fabric_port_get(unit, e2e_port, 0, parent_port);
SDK-53345	734829	88650_A0 88650_B0 88650_B1 88660_A0	Warmboot: Performing WB or synchronizing the warmboot DB using bcm_switch_control_set() may have caused DB segmentation fault due to a short buffer that handles protection FECs. The buffer size was fixed. In 6.3.3, if protection FECs with values of 8K and above were used or if a warmboot was performed, a device reboot in 6.3.4 is required in order to eliminate any possible memory override issues.

Table 53:

Number	CSP #	Chips	Release Notes For 6.3.4
SDK-53356		All	Ensure that KNET DMA abort works correctly on idle DMA channels on CMiCe-based devices such as BCM5684x.
SDK-53358		88660_A0	OAM LM packets are always counted in ARAD due to HW bug. In ARAD+ LM packets are counted only upon user request (can be configured using <code>bcm_oam_endpoint_action_set</code> api).
SDK-53359		88650_A0 88660_A0	Field Processor initialization was failing during ISSU (in service software upgrade) from SDK 6.3.3 to 6.3.4. This is fixed.
SDK-53360		All	Fixed potential Tx DMA lockup in KNET kernel module.
SDK-53362		88650_A0	In Field Processor, when using direct extraction tables, a segmentation fault may have occurred in some cases when setting qualifiers. This is fixed.
SDK-53363	732741	88650_A0	On some operating systems in previous releases, init might fail with segmentation fault in egress editor init. This has been fixed
SDK-53374		88650_A0 88650_B0 88650_B1 88660_A0	The default range of the credit watchdog was fixed to include all queues. The default range before the fix was one queue - queue zero. A side affect of the driver coming with the previous default and not changing it later is that if the system comes up under traffic, queues may get stuck and require ingress soft-reset.
SDK-53431		88650_A0 88660_A0	TM only mode: When <code>bcm.user</code> loads in TM mode, it shouldn't matter what PP soc properties are active, since PP is disabled. There was a problem where setting the Advanced Vlan Translation mode soc property caused a conflict that made <code>bmc.user</code> crash at startup. The problem was fixed, and now the device can start normally with both modes on.
SDK-53470	736427	56450_A0	Fixed issue with mpls port delete for CoE subport on BCM56450
SDK-53472		88650_A0 88650_B0 88650_B1	In the example application (called by <code>arad.soc</code>), the RX module was not activated after warmboot. This is fixed by calling DPP application in WB mode. Reference code for customer application. No driver change.
SDK-53473	736455	56450_A0	Released hardware resources of strict priority children when number of children becomes zero and make node unresolved function to be consistent with node resolve.
SDK-53478		88650_A0 88650_B0 88650_B1 88660_A0	MPLS: <code>bcm_mpls_vpn_id_get()</code> retrieves VPN information from a VSI that was associated as an MPLS VPN (<code>bcm_mpls_vpn_id_create</code>). The same VSI may also be used for vswitch, MIM, etc. The supplied VSI to <code>bcm_mpls_vpn_id_get()</code> was validated for VSI existence, but it also successfully retrieved VSI info for VSIs that were allocated by other applications, but were not used by the MPLS. The validation for <code>bcm_mpls_vpn_id_get()</code> was fixed so that VSIs that are not used by the MPLS, return an <code>E_NOT_FOUND</code> error.
SDK-53513	736830	All	Initialize common logical to physical index and reverse mapping tables in alpm mode.

Table 53:

Number	CSP #	Chips	Release Notes For 6.3.4
SDK-53531	727653	88650_A0	BFD packets may now be trapped to custom gports. When calling <code>bcm_bfd_endpoint_create()</code> , set the <code>remote_gport</code> field to a valid gport for trapping BFD frames to that gport. Macros such as <code>BCM_GPORT_LOCAL_SET()</code> should be used for converting ports to gports and setting <code>remote_gport</code> . If the default behavior is preferred, <code>remote_gport</code> should be set to <code>BCM_GPORT_INVALID</code> (this is configured in <code>bcm_bfd_endpoint_info_t_init()</code>).
SDK-53542		88650_A0	ECMP - Trunk: a new CINT has been inserted, emulating the 88650 HW and how an hash member is selected in ECMP and Trunk (i.e., LAG). The CINT is called: <code>cint_trunk_ecmp_lb_key_and_member_retrieve.c</code> . This CINT does not apply on BCM88660.
SDK-53619		88650_A0 88650_B0 88660_A0	Within advanced VLAN mode, <code>cos_profile</code> should be explicitly attached to LIF using <code>bcm_qos_port_map_set()</code> .

Section 8: Unresolved Issues for 6.3.4

The following issues are unresolved in version 6.3.4 of the SDK.

Table 54:

<i>Number</i>	<i>CSP #</i>	<i>Chips</i>	<i>Release Notes</i>
SDK-30856		All	When mirror-to port resides on a different unit, the mirrored packet may not egress correctly.
SDK-32461		56846_A0 56845_B0 56845_A2 56844_A0 56842_A0 56840_A0	On BCM5684x devices one can observe inaccurate packet discard, when it is based on packet color (CNG bits).
SDK-32676	381244	All	The switch control bcmSwitchL2PortBlocking is not correctly preserved for Level 2 warmboot.
SDK-33686	389108	56634_A0	If a MiM virtual port has statistics enabled for it and if such MiM port is replaced using BCM API <code>bcm_mim_port_add()</code> along with flag <code>BCM_MIM_PORT_REPLACE</code> then the statistics of that MiM port might be lost.
SDK-35755	411572	56820_A0 56820_B0	Compared to older releases, L2 Notification thread (bcmL2X) requires more CPU bandwidth to run in polling mode (<code>l2xmsg_mode=0</code>), due to the requirement for more thorough entry comparisons. The recommendation, however, is to run L2 notification thread using <code>L2MOD_FIFO DMA</code> mechanism, which is much more efficient and provides more functionality. To do that, please, set the configuration variable (property) <code>l2xmsg_mode</code> to 1.
SDK-37821		56846_A0 56845_B0 56845_A2 56844_A0 56842_A0 56840_A0 56440_A0 56843_B0 56841_A3 56846_A1 56841_B0	<code>bcm_cosq_config_set()</code> had traditionally been used to set the system wide number of COSQs. This does not apply to devices with hierarchical schedulers. For these devices, the hierarchy constructed at device initialization time is dependent upon the number of COSQs defined in the system configuration at the time of initialization. Changing the queue count after the hierarchy has been constructed has no effect.
SDK-42259		56440_A0 56440_A1	Spurious error messages may be seen when executing Rx/TX tests TR90 and TR91 when the KNET modules is loaded.
SDK-42527		88650_A0	TR90 and TR91 are not supported for the Arad (88650). These TR's Run a TX/RX reload test to check DMA speed.
SDK-44416		88640_A0	1. API is reading the wrong register from the device. 2. API is missing the parameter of <code>ResetLoad</code> , so this value cannot be configured.
SDK-44471	599747	56544_A0	BCM56544 XAUI ports support single lane GE operation via lane 0 (at boot time). The applicable config is <code>bcm56544_4x10_12x10=1</code> . However, current software has not supported this yet. Modifying the <code>src/soc/esw/triumph3.c->port_speed_max_94</code> as following can support GE operation: <pre>static const int port_speed_max_94[] = { -1, 1/* 10 */, -1, -1, -1, -1, -1, -1, -1, -1, -1, -1, -1, -1, 1/* 10 */, -1, -1, -1, -1, -1, -1, -1, -1, -1, -1, -1, 1/* 10 */, -1, -1, -1, -1, -1, -1, -1, -1, -1, -1, -1, -1, -1, -1, 1/* 10 */, -1, -1, -1, -1, -1, -1, -1, 10, 10, 10, 10, -1, -1, -1, -1, -1, -1, -1, -1, -1, -1, 10, 10, 10, 10, 10, 10, 10, -1, -1, -1, -1, -1 };</pre> However, there should be more decent way to achieve this feature.
SDK-44506	593957	56842_A0	If an L3 interface entry is in the my station TCAM instead of the usual L2 table it will not be restored upon warmboot.

Table 54:

Number	CSP #	Chips	Release Notes
SDK-45075		All	When an interrupt occurs on different blocks of the same type (e.g. multiple FMAC blocks), the count will be accumulated in the same counter. For example RX-LOS interrupt may occur on different FMAC blocks, and counted as same recurring event, although it is in fact a different interrupt. This may affect corrective action in case it is different for a recurring event, in the case if recurring-threshold for this event is crossed.
SDK-45234		88650_A0 88650_B0 88650_B1	src/examples/dpp/cint_pkt_test example returns an error when executed
SDK-45366	611273	56440_A0	When the API <code>bcm_cosq_port_bandwidth_set(...)</code> is called on a particular port and COSq to enable egress rate limiting, sometimes the CLI command "show c" will show the incorrect dropping statistics on a irrelevant port.
SDK-45965	623105	56446_B0 56440_A0 56445_A0 56440_A1 56445_A1 56444_A1 56449_B0 56445_B0 56440_B0 56447_B0 56443_B0 56441_B0	Due to an oversight, the fields <code>new_inner_pkt_priority</code> and <code>new_inner_cfi</code> , <code>priority</code> and <code>new_outer_cfi</code> from <code>bcm_van_action_set_t</code> are not programmed correctly for a default, port-based action.
SDK-46556	621213	88650_A0 88650_B0 88650_B1	<code>bcm_l2_cache_delete()</code> API does not delete <code>general_trap</code> entry configuration in HW
SDK-46641	633505	88650_A0 88650_B0	Simple bridge: When packet comes in with length = 0 (i.e. ethertype = 0) then packet is parsed incorrectly as Trill packet and not as Ethernet packet.
SDK-47366	642398	All	The implementation of SER (Soft Error Recovery mechanism) requires the SDK to perform periodical scanning of certain memories. The infrastructure for this scanning is provided by the optional MEM_SCAN feature (component) of the SDK. Since SER is a mandatory component, that can't be compiled out, MEM_SCAN becomes a mandatory component too as long as you are using a device, supported by SER.
SDK-47739	628786	56540_A0 56540_B0	For devices in the BCM56540 family, the CPU queues are allocated differently depending on the revision of the device (Ax vs. Bx). This force the developer to include revision specific code in the application.
SDK-47905	654763	All	The structure <code>bcm_pkt_t</code> representing the packet metadata contains the <code>src_trunk</code> field, which is filled with the trunk ID in the case the packet ingresses on a port, that is a member of a trunk (LAG). The width of the <code>src_trunk</code> field in <code>bcm_pkt_t</code> is 8 bits. However, a number of modern devices allow up to 1024 trunk IDs. If a packet is received on such a trunk and is passed to the CPU, the <code>src_trunk</code> field will contain only the lower 8 bits of the trunk ID.
SDK-48091	662661	56850_A0 56850_A1 56850_A2	For BCM56850 devices, when only a single GigE port is allocated to a TSC lane (the other 3 TSC lanes are not used), that port may be configured incorrectly resulting in port that appears functional but is not.
SDK-48101	689094	56845_B0 56845_A2	The "phy diag prbs" command does not work correctly on BCM56850 device in 40G mode and should not be used.
SDK-49047		88650_B0	when enabling 1588 for port A: <code>bcm_port_timesync_config_set(unit, A, config_1,);</code> 1588 packets received from any other port will be stamped/dropped/trapped according to the 1588 'config_1' configured for port A. then, when configuring port B with <code>config_2</code> : <code>bcm_port_timesync_config_set(unit, B, config_2,);</code> when 1588 packets received from port B will be stamped/dropped/trapped according to the configuration in 'config_2'. 1588 received from A or any other port will be stamped/dropped/trapped according to 'config_2'.

Table 54:

Number	CSP #	Chips	Release Notes
SDK-49107	669198	56634_A0 56634_B0	Under certain conditions, the counters associated with the external TCAM may not counter Red/Yellow packets as they should resulting in incorrect counts.
SDK-49543	663298	88650_A0 88650_B0 88650_B1	The LED on NEGEVII does not work well. Even the link is on, the LED is off.
SDK-49910		56640_A0 56640_A1 56640_B0	If the default schedule hierarchy is changed, subsequent calls to various "cos" commands may fail with an "INVALID PORT" error, "cos config" is one example.
SDK-50431		88660_A0	ERSPAN with XGS MAC extender is not working for ARAD+.
SDK-50788		56640_B0	For BCM56640 (Triumph3) family devices (B0 stepping), if queues are detached and reattached, subsequent calls to <code>bcm_cosq_gport_sched_set()</code> may fail.
SDK-50899	634474	56840_A0	When configuring BCM56840 (Trident) family devices for Weighted Random Early Discard (WRED) the TCP specific flags <code>BCM_COSQ_DISCARD_TCP</code> and <code>BCM_COSQ_DISCARD_NONTCP</code> have the opposite effect. The "discard TCP" flag causes non-TCP packets to be discarded and the "discard non-TCP" flag causes TCP packets to be discarded.
SDK-51099	695521	88650_A0 88650_B0 88650_B1	In L2, in distributed systems under extreme scenario, the MAC Table reply FIFO may be empty but its interrupt is up. In this case, the interrupt should be reset before trying inserting a MAC Table address, otherwise a failure in the insertion will be returned by the Driver.
SDK-51144		88660_A0	Arad+ OAM: Currently no support for accelerated SLM
SDK-51182	704777	All	Functions in CINT can be redeclared but the redeclaration does not take effect. The function <code>cint_reset()</code> must be called to delete the original function.
SDK-51352	708790	56846_A0 56845_B0 56845_A2 56840_A0 56846_A1	The memory test built in the diagnostic shell "tr 50" may report false errors on some memories. This is a result of some bits in these memories being "read only". Parity is an example of a read only bit in memory.
SDK-51360	692893	56840_A0	For BCM56840 (Trident) family devices, requests for VFP stat counters may be rejected if other non-VFP flex counters have already been created.
SDK-51443	692824	56850_A0 56850_A1 56850_A2	Setting 100M forced speed mode may cause link down, or FCS error.
SDK-51658		88650_A0 88650_B0 88650_B1 88660_A0	Out-LIF non VLAN-Port: Out-LIF discard state for LIFs of type other than VLAN (MPLS, MIM, VXLAN, etc) isn't reset during Out-LIF deletion or creation. The following sequence will not work for example: 1. Create MPLS-Port using <code>bcm_mpls_port_add</code> 2. Call <code>bcm_port_discard_set</code> for <code>mpls_port_id</code> with the value <code>BCM_PORT_DISCARD_EGRESS</code> . 3. Destroy MPLS-Port using <code>bcm_mpls_port_delete</code> 4. Create again same <code>mpls_port_id</code> using <code>bcm_mpls_port_add</code> 5. Discard Out-LIF state will be drop and all packets on that MPLS-Port will drop until calling <code>bcm_port_discard_set</code> with removing discard value.
SDK-51698		88650_A0 88650_B0	VLAN-Port VTT lookups: In case port is double-lookup enable (<code>bcmVlanPortDoubleLookupEnable</code>) packet will not match correctly for packet with two valid TPIDs on that port and outer-tag is Priority tag (VLAN ID 0)
SDK-51810		88650_B1 88660_A0	<code>bcm_vlan_port_find</code> returns <code>failover_port_id==1</code> even though port has no protection.
SDK-51978		88650_A0	In a device with channalized CPU ports, where some of the CPU ports are Higig and some not, the WB wont preserve the Higig indication correctly.
SDK-52072	716983	88650_A0	ERSPAN: ERSPAN removal is not done correctly in SW DB. Following sequence will fail: 1. Create ERSPAN entry with ID X. 2. Destroy ERSPAN entry ID X 3. Create again ERSPAN entry ID X.



Table 54:

Number	CSP #	Chips	Release Notes
SDK-52125		88650_A0 88650_B0 88660_A0	Piggy back CCM (CCMs with LM statistics stamped on them) has only been implemented for accelerated endpoints on arad+, but not in other cases.
SDK-52355		56846_A0 56845_B0 56845_A2 56844_A0 56850_A0 56843_B0 56846_A1 56841_B0 56854_A0 56850_A1 56830_A1 56850_A2 56854_A2	This problem affects Inserts/Delete calls for memories (Mostly hashed) which do not have inline correction support. Insert: Many of the BCM APIs perform a read followed by an insert. If there is an Parity error sitting in the memory index being read, then read will generate an event, but the soc call for read will succeed as it returns cached data and expects it to get fixed by SER correction mechanism in the DPC Thread. Now BCM API continues further (since soc read is successful) and then issues an insert command which sees a failure as the correction has still not happened. We will see similar problem for delete. A patch for this will be available in December
SDK-52383		88650_A0 88650_B0	Cud extension for Arad is not supported
SDK-52454		88650_A0 88660_A0	VLAN destroy all (bcm_vlan_destroy_all) returns error when VXLAN/VPLS VPNs exist in the device
SDK-52635	726506	88650_A0	When using api bcm_trunk_delete_membr to delete trunk member some members can not be delete when using ModPort. User can still delete trunk members with in following ways: 1. Use bcm_trunk_set () API to remove members. 2. Use system port and not ModPort 3. Delete members in decreasing order
SDK-53529		88650_B1	When a DMM packet is trapped it is added OAM-TS header on which the clock is stamped. Bug: The OAM-TS only contains the 4LSBs of the clock and there is no way to retrieve the MSB clock information.
SDK-53625	737814	88650_A0 88650_B0 88660_A0	when creating a new mep with mdlevel 0 the SDK returns error.
SDK-53824		56450_A0	SDK initialization sequence fails when maximum number(128) of sub ports configured in BCM56450_A0 . This specific configuration tries to configure THDO_OPNCONFIG memory with invalid index that results in a failure. A patch for this will be available in December.
SDK-53890		88750_A0 88650_A0 88650_B0 88660_A0	Compilation fail when adding KBP support flags and removing following Warmboot flags : CFGFLAGS += - DBCM_WARM_BOOT_SUPPORT CFGFLAGS += - DBCM_WARM_BOOT_SUPPORT_SW_DUMP CFGFLAGS += - DBCM_EASY_RELOAD_WB_COMPAT_SUPPORT

Section 9: Test Statistics

HOW TO READ THE DATA

The below tables represent a spread of data gathered per-device, per-suite, per-release. The percentages represent the aggregate rate of failure for that suite when run against all variants of the family of devices.

OVERVIEW

Each suite listed below is indicative of a specific module. Golden refers to a suite of tests that takes representation across multiple modules and serves as a sanity regression. Each suite contains tests of various types, loosely categorized as follows:

Table 55:

<i>Test Categories</i>	<i>Description</i>
Configuration Tests	Tests that verify that each API functions appropriately and can configure the device as expected.
Functionality Tests	Tests that further validate each of the API through functional use often requiring traffic to be run through the system.
Semantic Tests	Tests that ensure that the proper error handling mechanisms are working and users cannot crash the device through the API.

NOTE

The below data is not meant to be a precise indication of quality but instead serves as a guideline for improvements release-over-release. Additionally, although some cells show 0% failures, this does not necessarily mean the feature is supported in the device - tests are run to validate the appropriate SDK support even for unsupported features on older devices to ensure graceful handling of all API.

Finally, some devices have fewer columns listed if they were introduced recently.

TOTAL TESTS

The below data represents the number of unique cases for each release.

Note that although a particular test case will execute for each and every chip, it's only counted once.

Table 56:

	<i>sdk-6.3.4</i>	<i>sdk-6.3.3</i>	<i>sdk-6.3.2</i>	<i>sdk-6.2.9</i>
golden	154	154	154	154
warmboot	2208	2208	1644	1524
bfd	16	16	16	16
bhh	15	15	15	15
cosq	290	290	289	289
dvapi	1003	1001	997	985
fcoe	23	20	19	0
field	711	704	704	704
higigproxy	129	129	123	0
l2	229	223	223	222
l3	219	213	212	211
l3.alpm.combined	63	61	N/A	N/A
l3.alpm.combined.64	51	49	N/A	N/A
l3.alpm.parallel	63	61	N/A	N/A
l3.alpm.parallel.64	51	49	N/A	N/A
mpls	81	81	81	80
ptp	115	115	115	1
ser	52	52	46	N/A
stack	49	49	49	49
stat	98	98	71	65
trill	40	40	40	36
trunk	173	139	139	139
tunnel	65	65	65	65
subport	12	12	12	12
vlan	199	199	199	186
vxlan	42	42	41	41
Total	6151	6043	5254	4794

TEST RESULTS

Below tables show percentages of failures for corresponding test suites per SDK release.

ALL DEVICES

Note: This section represents aggregate results for all devices in the release.

Table 57:

	<i>sdk-6.3.4</i>	<i>sdk-6.3.3</i>	<i>sdk-6.3.2</i>	<i>sdk-6.2.9</i>
golden	2.5 %	2.6 %	3.3 %	5.1 %
warmboot	3.2 %	4.4 %	7.8 %	8.2 %
bfd	0.6 %	0.1 %	0.1 %	0.0 %
bhh	1.7 %	4.8 %	4.7 %	5.5 %
cosq	1.7 %	2.4 %	2.3 %	3.2 %
dvapi	2.5 %	2.6 %	3.1 %	3.4 %
fcoe	0.1 %	0.4 %	0.7 %	DNE
field	1.9 %	1.8 %	1.9 %	2.2 %
higigproxy	1.7 %	1.7 %	2.3 %	DNE
l2	3.0 %	2.5 %	2.8 %	1.8 %
l3	2.8 %	2.3 %	2.4 %	3.1 %
l3.alpm.combined	0.0 %	18.9 %	16.7 %	10.4 %
l3.alpm.combined.64	0.0 %	25.5 %	DNE	DNE
l3.alpm.parallel	0.0 %	18.9 %	13.6 %	10.2 %
l3.alpm.parallel.64	0.0 %	28.6 %	DNE	DNE
mpls	2.2 %	2.3 %	0.9 %	1.3 %
ptp	0.0 %	0.0 %	0.0 %	0.0 %
ser	0.6 %	1.0 %	2.2 %	DNE
stack	0.1 %	0.4 %	1.1 %	1.2 %
stat	0.6 %	0.4 %	1.1 %	4.5 %
trill	2.2 %	2.5 %	8.1 %	10.5 %
trunk	1.8 %	0.8 %	1.1 %	1.3 %
tunnel	0.8 %	0.1 %	0.1 %	0.2 %
subport	6.2 %	9.6 %	33.8 %	36.6 %
vlan	1.8 %	2.1 %	3.1 %	1.5 %
vxlan	0.0 %	1.0 %	1.7 %	2.2 %
Total	1.8 %	1.9 %	2.4 %	2.8 %

TRIDENT2

Table 58:

	<i>sdk-6.3.4</i>	<i>sdk-6.3.3</i>	<i>sdk-6.3.2</i>	<i>sdk-6.2.9</i>
golden	0.6 %	1.3 %	3.2 %	6.5 %
warmboot	4.7 %	5.0 %	12.3 %	11.3 %
bfd	0.0 %	0.0 %	0.0 %	0.0 %
bhh	0.0 %	0.0 %	0.0 %	0.0 %



Table 58:

	<i>sdk-6.3.4</i>	<i>sdk-6.3.3</i>	<i>sdk-6.3.2</i>	<i>sdk-6.2.9</i>
cosq	0.3 %	1.4 %	1.4 %	3.1 %
dvapi	1.4 %	1.5 %	3.0 %	2.7 %
fcoe	0.0 %	5.0 %	10.5 %	DNE
field	0.7 %	0.9 %	1.0 %	1.1 %
higigproxy	0.8 %	0.8 %	0.8 %	DNE
l2	1.3 %	0.9 %	0.9 %	0.0 %
l3	1.4 %	0.5 %	0.5 %	0.5 %
l3.alpm.combined	0.0 %	8.2 %	DNE	DNE
l3.alpm.combined.64	0.0 %	10.2 %	DNE	DNE
l3.alpm.parallel	0.0 %	19.7 %	DNE	DNE
l3.alpm.parallel.64	0.0 %	14.3 %	DNE	DNE
mpls	2.5 %	2.5 %	1.2 %	1.3 %
ptp	0.0 %	0.0 %	0.0 %	0.0 %
ser	7.7 %	7.7 %	0.0 %	DNE
stack	0.0 %	0.0 %	0.0 %	0.0 %
stat	0.0 %	0.0 %	1.4 %	3.1 %
trill	5.0 %	5.0 %	27.5 %	25.0 %
trunk	1.7 %	2.2 %	2.2 %	1.4 %
tunnel	0.0 %	0.0 %	0.0 %	0.0 %
subport	0.0 %	0.0 %	50.0 %	50.0 %
vlan	0.5 %	1.5 %	1.5 %	1.1 %
vxlan	0.0 %	11.9 %	22.0 %	24.4 %
Total	1.0 %	1.9 %	2.2 %	2.5 %

TRIUMPH3

Table 59:

	<i>sdk-6.3.4</i>	<i>sdk-6.3.3</i>	<i>sdk-6.3.2</i>	<i>sdk-6.2.9</i>
golden	0.6 %	0.6 %	3.2 %	7.8 %
warmboot	1.4 %	4.5 %	N/A	13.8 %
bfd	0.0 %	0.0 %	0.0 %	0.0 %
bhh	0.0 %	0.0 %	0.0 %	0.0 %
cosq	0.0 %	0.7 %	1.0 %	2.8 %
dvapi	1.9 %	2.4 %	3.0 %	3.4 %
fcoe	0.0 %	0.0 %	0.0 %	N/A
field	8.0 %	8.1 %	8.1 %	8.4 %
higigproxy	0.8 %	0.8 %	2.4 %	N/A
l2	3.1 %	2.7 %	2.7 %	1.4 %
l3	2.3 %	2.3 %	6.6 %	6.6 %
mpls	1.2 %	0.0 %	0.0 %	1.3 %
ptp	0.0 %	0.0 %	0.0 %	0.0 %
ser	0.0 %	0.0 %	0.0 %	N/A
stack	0.0 %	0.0 %	0.0 %	0.0 %
stat	0.0 %	0.0 %	1.4 %	16.9 %
trill	7.5 %	7.5 %	17.5 %	27.8 %
trunk	1.2 %	0.7 %	0.7 %	0.7 %
tunnel	0.0 %	0.0 %	0.0 %	0.0 %

Table 59:

	<i>sdk-6.3.4</i>	<i>sdk-6.3.3</i>	<i>sdk-6.3.2</i>	<i>sdk-6.2.9</i>
subport	0.0 %	8.3 %	41.7 %	41.7 %
vlan	2.0 %	3.0 %	4.5 %	2.2 %
vxlan	0.0 %	0.0 %	0.0 %	0.0 %
Total	2.6 %	2.9 %	3.7 %	4.6 %

HURRICANE2

Table 60:

	<i>sdk-6.3.4</i>	<i>sdk-6.3.3</i>	<i>sdk-6.3.2</i>
golden	3.9 %	2.6 %	3.9 %
warmboot	4.0 %	5.8 %	N/A
bfd	0.0 %	0.0 %	0.0 %
bhh	0.0 %	0.0 %	0.0 %
cosq	0.7 %	1.0 %	0.7 %
dvapi	1.4 %	1.9 %	1.8 %
fcoe	0.0 %	0.0 %	0.0 %
field	1.8 %	2.0 %	2.3 %
higigproxy	0.0 %	0.0 %	0.0 %
l2	1.7 %	1.3 %	2.7 %
l3	1.8 %	0.9 %	0.9 %
mpls	1.2 %	1.2 %	0.0 %
ptp	0.0 %	0.0 %	0.0 %
ser	0.0 %	0.0 %	0.0 %
stack	0.0 %	0.0 %	0.0 %
stat	0.0 %	0.0 %	0.0 %
trill	0.0 %	0.0 %	0.0 %
trunk	1.2 %	1.4 %	1.4 %
tunnel	0.0 %	0.0 %	0.0 %
subport	0.0 %	0.0 %	0.0 %
vlan	2.5 %	2.5 %	2.5 %
vxlan	0.0 %	0.0 %	0.0 %
Total	1.3 %	1.4 %	1.5 %

HELIX4

Table 61:

	<i>sdk-6.3.4</i>	<i>sdk-6.3.3</i>	<i>sdk-6.3.2</i>
golden	1.3 %	1.9 %	3.2 %
warmboot	4.0 %	DNE	DNE
bfd	0.0 %	0.0 %	0.0 %
bhh	0.0 %	0.0 %	0.0 %
cosq	0.0 %	0.7 %	1.0 %

Table 61:

	<i>sdk-6.3.4</i>	<i>sdk-6.3.3</i>	<i>sdk-6.3.2</i>
dvapi	1.9 %	2.6 %	2.6 %
fcoe	0.0 %	0.0 %	0.0 %
field	1.4 %	1.3 %	1.8 %
higigproxy	0.8 %	0.8 %	4.1 %
l2	3.9 %	3.6 %	4.0 %
l3	2.7 %	2.8 %	2.8 %
mpls	1.2 %	1.2 %	0.0 %
ptp	0.0 %	0.0 %	0.0 %
ser	0.0 %	0.0 %	0.0 %
stack	0.0 %	0.0 %	0.0 %
stat	1.0 %	1.0 %	1.4 %
trill	5.0 %	5.0 %	5.0 %
trunk	0.6 %	0.0 %	0.0 %
tunnel	0.0 %	0.0 %	0.0 %
subport	0.0 %	41.7 %	41.7 %
vlan	2.0 %	3.5 %	4.0 %
vxlan	0.0 %	0.0 %	0.0 %
Total	1.4 %	1.8 %	2.2 %

KATANA2

Table 62:

	<i>sdk-6.3.4</i>	<i>sdk-6.3.3</i>	<i>sdk-6.3.2</i>
golden	2.6 %	2.6 %	3.2 %
warmboot	4.9 %	8.3 %	N/A
bfd	0.0 %	0.0 %	0.0 %
bhh	0.0 %	0.0 %	0.0 %
cosq	1.4 %	2.8 %	3.5 %
dvapi	1.9 %	1.8 %	2.3 %
fcoe	0.0 %	0.0 %	0.0 %
field	1.7 %	1.7 %	1.6 %
higigproxy	0.8 %	0.8 %	2.4 %
l2	3.9 %	3.6 %	2.7 %
l3	3.7 %	3.3 %	3.3 %
mpls	2.5 %	2.5 %	1.2 %
ptp	0.0 %	0.0 %	0.0 %
ser	0.0 %	0.0 %	0.0 %
stack	0.0 %	0.0 %	8.2 %
stat	0.0 %	0.0 %	0.0 %
trill	0.0 %	0.0 %	0.0 %
trunk	1.2 %	0.0 %	0.7 %
tunnel	0.0 %	0.0 %	0.0 %
subport	0.0 %	8.3 %	41.7 %
vlan	2.5 %	2.5 %	2.5 %
vxlan	0.0 %	0.0 %	0.0 %
Total	1.7 %	1.7 %	2.1 %

STATIC CODE QUALITY ANALYSIS

Continued progress in whittling down static analysis defects per plan.

Table 63:

	<i>Initial Reported Issues</i>	<i>Reported Issues SDK 6.3.3</i>	<i>Reported Issues SDK 6.3.4</i>
DNX	664	688	628
XGS	271	292	327
SBX	600	421	323
SerDes	147	147	133
Common	2827	408	188

Section 10: Device and Platform Support

The section describes all devices, platforms, and operating systems that are supported by this release.

SWITCH DEVICES

Table 64: Switch Devices

<i>Family</i>	<i>Devices</i>	<i>Description</i>
BCM5389	BCM5389 A0	8-Port GbE Switch with Integrated Serdes
	BCM5389 A1	8-Port GbE Switch with Integrated Serdes
BCM5396	BCM5396 A0	16-Port GbE Switch with Integrated Serdes
BCM53010	BCM53010 A0	5-Port Gigabit Ethernet Managed Switch integrated with single core ARM Cortex-A9 processor
	BCM53010 A2	
	BCM53011 A0	5-Port Gigabit Ethernet Managed Switch integrated with dual cores ARM Cortex-A9 processor
	BCM53011 A2	
BCM53012	BCM53012 A0	5-Port Gigabit Ethernet Managed Switch with one RGMII I/F integrated with dual cores ARM Cortex-A9 processor
	BCM53012 A2	
	BCM53017 A0	2-Port Gigabit Ethernet Managed Switch with one RGMII I/F integrated with dual cores ARM Cortex-A9 processor
	BCM53018 A0	5-Port Gigabit Ethernet Managed Switch with one RGMII I/F integrated with dual cores ARM Cortex-A9 processor
BCM53019	BCM53019 A0	5-Port Gigabit Ethernet Managed Switch integrated with dual cores ARM Cortex-A9 processor
	BCM58522 A0	5-Port Gigabit Ethernet Managed Switch integrated with 2 PHYs, ARM Cortex-A9 processor and macsec cores
	BCM58525 A0	5-Port Gigabit Ethernet Managed Switch integrated with 2 PHYs, SGMII I/F, ARM Cortex-A9 processor and macsec cores
	BCM58622 A0	8-Port Gigabit Ethernet Managed Switch integrated with 5 PHYs, ARM Cortex-A9 processor and macsec cores
BCM58623	BCM58623 A0	8-Port Gigabit Ethernet Managed Switch integrated with 5 PHYs, ARM Cortex-A9 processor and macsec cores
	BCM58625 A0	8-Port Gigabit Ethernet Managed Switch integrated with 5 PHYs, SGMII I/F, ARM Cortex-A9 processor and macsec cores
	BCM53101 A0	5-Port Fast Ethernet Managed Switch + 1 Fast Ethernet WAN port
	BCM53101 B0	
BCM53115	BCM53115 A0	5-Port GbE Managed Switch + 1 Gigabit WAN port with integrated serdes
	BCM53115 A1	
	BCM53115 B0	
	BCM53115 B1	
	BCM53115 C0	
BCM53118	BCM53118 A0	8-Port Gigabit Ethernet Switch
	BCM53118 B0	
	BCM53118 B1	
BCM53125	BCM53125 A0	5-Port Gigabit Ethernet Switch with 1 Gigabit WAN port and 8051 processor
	BCM53125 B0	
BCM53128	BCM53128 A0	8-Port Gigabit Ethernet Switch with embedded 8051 processor
	BCM53128 B0	
BCM53242	BCM53242 A0	Managed Switch with 24 FE Ports + 2 GbE Interface
	BCM53242 B0	



Table 64: Switch Devices

Family	Devices	Description
	BCM53242 B1	
	BCM53262 A0	Managed Switch with 24 FE Ports + 4 GbE Interface
	BCM53262 B0	
	BCM53262 B1	
BCM53280	BCM53282 A0	8-Port Fast Ethernet + 2-Port Gigabit Ethernet Multilayer Switch
	BCM53282 B0	
	BCM53282 B1	
	BCM53282 B2	
	BCM53283 A0	16-Port Fast Ethernet + 2-Port Gigabit Ethernet Multilayer Switch
	BCM53283 B0	
	BCM53283 B1	
	BCM53283 B2	
	BCM53284 A0	24-Port Fast Ethernet + 2-Port Gigabit Ethernet Multilayer Switch
	BCM53284 B0	
	BCM53284 B1	
	BCM53284 B2	
	BCM53286 A0	24-Port Fast Ethernet + 4-Port Gigabit Ethernet Multilayer Switch
	BCM53286 B0	
	BCM53286 B1	
	BCM53286 B2	
	BCM53288 A0	24-Port Fast Ethernet + 2-Port Gigabit Ethernet Multilayer Switch with one 2.5GbE Uplink Port
	BCM53288 B0	
	BCM53288 B1	
	BCM53288 B2	
BCM53300	BCM53300 A0	Managed 24-port L2 Switch
	BCM53300 A1	
	BCM53301 A0	Managed 16-port L2 Switch
	BCM53301 A1	
	BCM53302 A0	Managed 24-port L2 Switch
	BCM53302 A1	
BCM53310	BCM53312 A0	BCM53312 Integrated Multilayer Switch and CPU
	BCM53312 B0	
	BCM53313 A0	BCM53313 Integrated Multilayer Switch and CPU
	BCM53313 B0	
	BCM53314 A0	BCM53314 Integrated Multilayer Switch and CPU
	BCM53314 B0	
BCM53320	BCM53322 A0	BCM53322 Integrated Multilayer Switch and CPU
	BCM53323 A0	BCM53323 Integrated Multilayer Switch and CPU
	BCM53324 A0	BCM53324 Integrated Multilayer Switch and CPU
BCM53600	BCM53602 A0	8-Port Fast Ethernet + 3-Port Gigabit Ethernet Switch with one 1/2G-EPON ONU MAC/SerDes and embedded 600MHz MIPS32 74K processor

Table 64: Switch Devices

Family	Devices	Description
	BCM53603 A0	16-Port Fast Ethernet + 3-Port Gigabit Ethernet Switch with one 1/2G-EPON ONU MAC/SerDes and embedded 600MHz MIPS32 74K processor
	BCM53604 A0	24-Port Fast Ethernet + 3-Port Gigabit Ethernet Switch with one 1/2G-EPON ONU MAC/SerDes and embedded 600MHz MIPS32 74K processor
	BCM53606 A0	24-Port FE with S3MII interface + 3-Port Gigabit Ethernet Switch with one 1/2G-EPON ONU MAC/SerDes and embedded 600MHz MIPS32 74K processor
BCM89500	BCM89500 A0	4-Port Integrated Dedicated BRPHY + 3-Port Gigabit Ethernet Switch with embedded ARM processor
	BCM89500 B0	
BCM89500	BCM89501 A0	4-Port Integrated Dedicated BRPHY + 1-Port Integrated Dual-Mode BRPHY + 2-Port Gigabit Ethernet Switch with embedded ARM processor
	BCM89501 B0	
BCM89500	BCM89200 A0	1-Port Integrated Dedicated BRPHY + 1-Port Integrated Dual-Mode BRPHY + 2-Port Gigabit Ethernet Switch with embedded ARM processor
	BCM89200 B0	
BCM53710	BCM53714 A0	BCM56714 Integrated Multilayer Switch and CPU
	BCM53714 A1	
	BCM53714 A2	
	BCM53716 A0	BCM56716 Integrated Multilayer Switch and CPU
	BCM53716 A1	
	BCM53716 A2	
	BCM53718 A0	BCM56718 Integrated Multilayer Switch and CPU
	BCM53718 A1	
	BCM53718 A2	
BCM53720	BCM53724 A0	Managed 24-port L2 Switch with Integrated CPU
	BCM53724 B0	
	BCM53726 A0	Managed 24-port L2 Switch with Integrated CPU
	BCM53726 B0	
	BCM5675 A1	
	BCM5676 A0	4-Port, 96-Gbps Switch Fabric
	BCM5676 A1	
BCM56010	BCM56014 A0	24-Port Integrated Multilayer Switch and CPU
	BCM56014 A1	
	BCM56014 A2	
	BCM56018 A0	48-Port Integrated Multilayer Switch and CPU
	BCM56018 A1	
	BCM56018 A2	
	BCM56018 A1	48-Port Integrated Multilayer Switch and CPU
BCM56020	BCM56024 A0	24-Port Integrated Multilayer Switch and CPU
	BCM56024 B0	
	BCM56025 A0	24-Port Integrated L2 Switch and CPU
	BCM56025 B0	
	BCM56026 A0	24-Port Integrated L2 Switch and CPU
	BCM56026 B0	



Table 64: Switch Devices

Family	Devices	Description
BCM56100	BCM56100 A0	24-Port Fast Ethernet and 2-Port Gigabit Ethernet Multilayer Switch
	BCM56100 A1	
	BCM56101 A0	24-Port Fast Ethernet and 2-Port Gigabit Ethernet Multilayer Switch with One 10-Gigabit Ethernet/HiGig Port
	BCM56101 A1	
	BCM56102 A0	24-Port Fast Ethernet and 2-Port Gigabit Ethernet Multilayer Switch with Two 10-Gigabit Ethernet/HiGig Ports
	BCM56102 A1	
	BCM56105 A0	24-Port Fast Ethernet and 2-Port Gigabit Ethernet Layer 2 Switch
	BCM56105 A1	
	BCM56106 A0	24-Port Fast Ethernet and 2-Port Gigabit Ethernet Layer 2 Switch with One 10-Gigabit Ethernet/HiGig Port
	BCM56106 A1	
	BCM56107 A0	24-Port Fast Ethernet and 2-Port Gigabit Ethernet Layer 2 Switch with Two 10-Gigabit Ethernet/HiGig Ports
	BCM56107 A1	
BCM56110	BCM56110 A0	24-Port Fast Ethernet and 2-Port Gigabit Ethernet Multilayer Switch
	BCM56111 A0	24-Port Fast Ethernet and 2-Port Gigabit Ethernet Multilayer Switch with One 10-Gigabit Ethernet/HiGig Port
	BCM56112 A0	24-Port Fast Ethernet and 2-Port Gigabit Ethernet Multilayer Switch with Two 10-Gigabit Ethernet/HiGig Ports
	BCM56115 A0	24-Port Fast Ethernet and 2-Port Gigabit Ethernet Layer 2 Switch
	BCM56116 A0	24-Port Fast Ethernet and 2-Port Gigabit Ethernet Layer 2 Switch with One 10-Gigabit Ethernet/HiGig Port
	BCM56117 A0	24-Port Fast Ethernet and 2-Port Gigabit Ethernet Layer 2 Switch with Two 10-Gigabit Ethernet/HiGig Ports
BCM56130	BCM56132 A0	24-Port Fast Ethernet Multilayer Switch with Two 10-GbE/HiGig2 and Two 1G/2.5Gb Uplink Ports
	BCM56132 B0	
	BCM56132 B1	
	BCM56134 A0	24-Port Fast Ethernet Multilayer Switch with four 1G/2.5Gb Uplink Ports
	BCM56134 B0	
BCM56140	BCM56134 B1	
	BCM56140 A0	24-Port Gigabit Ethernet/6-Port SGMII GbE Multilayer switch with combination of two/four 1G/2.5/HiGig2 Uplink Ports
	BCM56142 A0	24-Port Gigabit Ethernet Multilayer switch with combination of two/four 1G/2.5/HiGig2 Uplink Ports
	BCM56143 A0	24-Port Gigabit Ethernet Multilayer switch with combination of two/four 1G/2.5/HiGig2 Uplink Ports
	BCM56144 A0	16-Port Gigabit Ethernet Multilayer switch with four 1G/2.5HG Uplink Ports
	BCM56146 A0	24-Port Fast-Ethernet Multilayer switch with four 2.5HG Uplink Ports
	BCM56147 A0	24-Port Fast-Ethernet Multilayer switch with combination of one/two/four 1G/2.5G/10/12/13HG Uplink Ports
BCM56150	BCM56150 A0	24-port GbE Managed Switch with 4-port 10 GbE uplinks, integrated CPU and 16 copper PHYs
	BCM56151 A0	24-port GbE Managed Switch with 4-port 10 GbE uplinks, integrated CPU (without PHYs)
	BCM56152 A0	24-port GbE plus 2-port GbE and 2-port 1GbE/13GbE uplinks Managed Switch, integrated CPU and 16 copper PHYs
	BCM53342 A0	8-port GbE Multilayer WebSmart Switch with Integrated CPU and Copper PHYs



Table 64: Switch Devices

Family	Devices	Description
	BCM53343 A0	16-port GbE plus 4-port GbE uplinks Multilayer WebSmart Switch with Integrated CPU and 16 Copper PHYs
	BCM53344 A0	24-port GbE plus 2-port GbE and 2-port 1GbE/13GbE uplinks WebSmart Switch, integrated CPU and 16 copper PHYs
	BCM53346 A0	24-port GbE Multilayer WebSmart Switch with 4-port 10 GbE uplinks, integrated CPU and 16 copper PHYs
	BCM53393 A0	14-port GbE Multilayer Embedded Switch with integrated CPU (without PHY)
	BCM53394 A0	10-port GbE Multilayer Embedded Switch with 4-port 10 GbE uplinks, integrated CPU (without PHY)
BCM56210	BCM56212 A0	
	BCM56212 A1	
	BCM56212 A2	
	BCM56213 A0	
	BCM56213 A1	
	BCM56213 A2	
	BCM56214 A0	BCM56214 Integrated Multilayer Switch and CPU
	BCM56214 A1	
	BCM56214 A2	
	BCM56215 A0	
	BCM56215 A1	
	BCM56215 A2	
	BCM56216 A0	BCM56216 Integrated Multilayer Switch and CPU
	BCM56216 A1	
	BCM56216 A2	
	BCM56217 A0	
	BCM56217 A1	
	BCM56217 A2	
	BCM56218 A0	BCM56218 Integrated Multilayer Switch and CPU
	BCM56218 A1	
	BCM56218 A2	
	BCM56219 A0	BCM56219 Integrated Multilayer Switch and CPU
	BCM56219 A1	
	BCM56219 A2	
BCM56220	BCM56224 A0	24 GbE + 4 x 1 Gb/2.5 Gb, L3/L2+
	BCM56224 B0	24 GbE + 4 x 1 Gb/2.5 Gb, L3/L2+
	BCM56225 A0	24 GbE + 4 x 1 Gb/2.5 Gb, L2+
	BCM56225 B0	24 GbE + 4 x 1 Gb/2.5 Gb, L2+
	BCM56226 A0	16 GbE + 4 x 1 Gb/2.5 Gb, L3/L2+
	BCM56226 B0	16 GbE + 4 x 1 Gb/2.5 Gb, L3/L2+
	BCM56227 A0	16 GbE + 4 x 1 Gb/2.5 Gb, L2+
	BCM56227 B0	16 GbE + 4 x 1 Gb/2.5 Gb, L2+
	BCM56228 A0	8 GbE + 4 x 1 Gb/2.5 Gb, L3/L2+
	BCM56228 B0	8 GbE + 4 x 1 Gb/2.5 Gb, L3/L2+

Table 64: Switch Devices

Family	Devices	Description
BCM56230	BCM56229 A0	8 GbE + 4 x 1 Gb/2.5 Gb, L2+
	BCM56229 B0	8 GbE + 4 x 1 Gb/2.5 Gb, L2+
	BCM56230 B1	12-Port GbE Multilayer Switch
	BCM56231 B1	6-Port GbE Multilayer Switch
BCM56300	BCM56300 A0	24-Port Gigabit Ethernet Multilayer Switch
	BCM56300 A1	
	BCM56300 B0	
	BCM56300 B1	
	BCM56301 A0	Four 10-Gigabit Ethernet/HiGig+ Ports
	BCM56301 A1	
	BCM56301 B0	
	BCM56301 B1	
	BCM56302 A0	24-Port Gigabit Ethernet Multilayer Switch with Two 10-Gigabit Ethernet/HiGig+ Ports
	BCM56302 A1	
	BCM56302 B0	
	BCM56302 B1	
	BCM56303 A0	24-Port Gigabit Ethernet Multilayer Switch with Three 10 Gigabit Ethernet/HiGig+ Ports
	BCM56303 A1	
	BCM56303 B0	
	BCM56303 B1	
	BCM56304 A0	24-Port Gigabit Ethernet Multilayer Switch with Four 10-Gigabit Ethernet/HiGig+ Ports
	BCM56304 A1	
	BCM56304 B0	
	BCM56304 B1	
	BCM56305 A0	24-Port Gigabit Ethernet Multilayer Switch
	BCM56305 A1	
	BCM56305 B0	
	BCM56305 B1	
	BCM56306 A0	16 Port Gigabit Ethernet Switch
	BCM56306 A1	
	BCM56306 B0	
	BCM56306 B1	
	BCM56307 A0	24-Port GE L2 Switch with Two 10 GE/HiGig+ Ports
	BCM56307 A1	
	BCM56307 B0	
	BCM56307 B1	
	BCM56308 A0	24-Port GE L2 Switch with Three 10 GE/HiGig+ Ports
	BCM56308 A1	
	BCM56308 B0	
	BCM56308 B1	



Table 64: Switch Devices

Family	Devices	Description
	BCM56309 A0	24-Port GE L2 Switch with Four 10 GE/HiGig+ Ports
	BCM56309 A1	
	BCM56309 B0	
	BCM56309 B1	
BCM56310	BCM56310 A0	BCM56310 Series 24-Port GbE Multilayer Switch with Four 10-GbE/HiGig+ Uplink Ports
	BCM56311 A0	Four 10-Gigabit Ethernet/HiGig+ Ports
	BCM56312 A0	24-Port Gigabit Ethernet Multilayer Switch with Two 10-Gigabit Ethernet/HiGig+ Ports
	BCM56313 A0	24-Port Gigabit Ethernet Multilayer Switch with Three 10-Gigabit Ethernet/HiGig+ Ports
	BCM56314 A0	24-Port Gigabit Ethernet Multilayer Switch with Four 10-Gigabit Ethernet/HiGig+ Ports
	BCM56315 A0	BCM56310 Series 24-Port GbE Layer 2 Switch with Four 10-GbE/HiGig+ Uplink Ports
	BCM56316 A0	Four 10-Gigabit Ethernet/HiGig+ Ports
	BCM56317 A0	24-Port Gigabit Ethernet Layer 2 Switch with Two 10-Gigabit Ethernet/HiGig+ Ports
	BCM56318 A0	24-Port Gigabit Ethernet Layer 2 Switch with Three 10-Gigabit Ethernet/HiGig+ Ports
	BCM56319 A0	24-Port Gigabit Ethernet Layer 2 Switch with Four 10-Gigabit Ethernet/HiGig+ Ports
	BCM56320 A0	24-Port GbE Multilayer Switch with Four 10-GbE/HiGig2 Uplink Ports
	BCM56320 B0	
BCM56320	BCM56320 B1	
	BCM56321 A0	24-Port GbE Multilayer Switch with Four 10-GbE/HiGig2 Uplink Ports
	BCM56321 B0	
	BCM56321 B1	
	BCM56330	
BCM56330	BCM56331 A0	24-Port GbE Multilayer Switch with Four 2.5GbE Uplink Ports
	BCM56331 B0	
	BCM56331 B1	
	BCM56333 A0	16-Port GbE Multilayer Switch
	BCM56333 B0	
	BCM56333 B1	
	BCM56334 A0	24-Port GbE Multilayer Switch with Four 10-GbE/HiGig2 Uplink Ports
	BCM56334 B0	
	BCM56334 B1	
	BCM56338 A0	8-Port GbE Multilayer Switch with two 10-GbE/HiGig2 Uplink Ports
	BCM56338 B0	
	BCM56338 B1	
	BCM56440	
	BCM56440 A0	24-Port GbE Multilayer Switch with Four 10-GbE/HiGig2 Uplink ports
	BCM56440 B0	
BCM56440	BCM56441 A0	8-Port GbE Multilayer Switch with Two 10-GbE/HiGig2 Uplink ports
	BCM56441 B0	
	BCM56442 A0	16-Port GbE Multilayer Switch
	BCM56442 B0	
	BCM56443 A0	8-Port 2.5GbE Multilayer Switch with Two 10-GbE/HiGig2 Uplink ports

Table 64: Switch Devices

Family	Devices	Description
	BCM56443 B0	
	BCM56445 A0	24-Port GbE Multilayer Switch with Four 10-GbE/HiG2 Uplink ports pin compatible with BCM56334
	BCM56445 B0	
	BCM56446 A0	8-Port GbE Multilayer Switch with Two 10-GbE/HiG2 Uplink ports pin compatible with BCM56338
	BCM56447 A0	16-Port GbE Multilayer Switch pin compatible with BCM56333
	BCM56447 B0	
	BCM56448 A0	24-Port GbE Multilayer Switch with Four 1GbE/ One 2.5G Uplink ports
	BCM56448 B0	
BCM56500	BCM56500 A0	24-Port Gigabit Ethernet Multilayer Switch
	BCM56500 A1	
	BCM56500 B0	
	BCM56500 B1	
	BCM56500 B2	
	BCM56501 A0	Four 10-Gigabit Ethernet/HiGig+ Ports
	BCM56501 A1	
	BCM56501 B0	
	BCM56501 B1	
	BCM56501 B2	
	BCM56502 A0	24-Port GbE Multilayer Switch with Two 10-GbE/HiGig+ Ports
	BCM56502 A1	
	BCM56502 B0	
	BCM56502 B1	
	BCM56502 B2	
	BCM56503 A0	24-Port GbE Multilayer Switch with Three 10-GbE/HiGig+ Ports
	BCM56503 A1	
	BCM56503 B0	
	BCM56503 B1	
	BCM56503 B2	
	BCM56504 A0	24-Port GbE Multilayer Switch with Four 10-GbE/HiGig+ Ports
	BCM56504 A1	
	BCM56504 B0	
	BCM56504 B1	
	BCM56504 B2	
	BCM56505 A0	24-Port GbE Layer 2 Switch
	BCM56505 A1	
	BCM56505 B0	
	BCM56505 B1	
	BCM56505 B2	
	BCM56506 A0	Four 10-Gigabit Ethernet/HiGig+ Ports
	BCM56506 A1	

Table 64: Switch Devices

Family	Devices	Description
	BCM56506 B0	
	BCM56506 B1	
	BCM56506 B2	
	BCM56507 A0	24-Port GbE Layer 2 Switch with Two 10-GbE/HiGig+ Ports
	BCM56507 A1	
	BCM56507 B0	
	BCM56507 B1	
	BCM56507 B2	
	BCM56508 A0	24-Port GbE Layer 2 Switch with Three 10-GbE/HiGig+ Ports
	BCM56508 A1	
	BCM56508 B0	
	BCM56508 B1	
	BCM56508 B2	
	BCM56509 A0	24-Port GbE Layer 2 Switch with Four 10-GbE/HiGig+ Ports
	BCM56509 A1	
	BCM56509 B0	
	BCM56509 B1	
	BCM56509 B2	
BCM56510	BCM56510 A0	24-Port Gigabit Ethernet Multilayer Switch
	BCM56511 A0	Four-Port 10-GbE/HiGig+ Multilayer Switch
	BCM56512 A0	24-Port GbE Multilayer Switch With Two 10-GbE/HiGig+ Ports
	BCM56513 A0	24-Port GbE Multilayer Switch With Three 10-GbE/HiGig+ Ports
	BCM56514 A0	24-Port GbE Multilayer Switch With Four 10-GbE/HiGig+ Ports
BCM56520	BCM56520 A0	24-Port GbE Multilayer Switch
	BCM56520 B0	
	BCM56522 A0	24-Port GbE Multilayer Switch with Two 10-GbE/HiGig2 Uplink Ports
	BCM56522 B0	
	BCM56524 A0	24-Port GbE Multilayer Switch with Four 10-GbE/HiGig2 Uplink Ports
	BCM56524 B0	
BCM56530	BCM56526 A0	28-Port GbE Multilayer Switch with Six 10-GbE/HiGig2 Uplink Ports
	BCM56526 B0	
	BCM56534 B0	24-Port GbE Multilayer Switch with Four 10-GbE/HiGig2 Uplink Ports
BCM56540	BCM56538 B0	48-Port GbE Multilayer Switch with Four 10-GbE/HiGig2 Uplink Ports
	BCM56540 A1	48xGE + 2xHG[42] + 2xHG[21] + 1GE, 48xGE + 4xXFI + 2xHG[42] + 1GE, 48xGE + 8xXFI + 1GE Multilayer Ethernet Switch
	BCM56540 B0	
BCM56540	BCM56541 A1	28xGE + 2xHG[42] + 2xHG[21] + 1GE, 28xGE + 4xXFI + 2xHG[42] + 1GE, 28xGE + 8xXFI + 1GE Multilayer Ethernet Switch
	BCM56541 B0	
BCM56540	BCM56542 A1	28xGE + 2xF.XAUI/2x10GE + 2xF.HG[42] + 2xF.HG[21] + 1GE, 28xGE + 8xGE/8x2.5GE + 2xHG[42] + 2xHG[21] + 1GE Multilayer Ethernet Switch
BCM56540	BCM56544 A1	10xF.XAUI + 4xHG[21] + 1GE, 10xF.XAUI + 4xXFI, 10xF.XAUI + 2xHG[42], 4xXAUI + 12xXFI + 1GE Multilayer Ethernet Switch

Table 64: Switch Devices

Family	Devices	Description
BCM56540	BCM56545 A1	48xGE + 2xHG[42] + 2xHG[21] + 1GE, 48xGE + 4xXFI + 2xHG[42] + 1GE, 48xGE + 8xXFI + 1GE Multilayer Ethernet Switch
BCM56540	BCM56546 A1	28xGE + 2xHG[42] + 2xHG[21] + 1GE, 28xGE + 4xXFI + 2xHG[42] + 1GE, 28xGE + 8xXFI + 1GE Multilayer Ethernet Switch
	BCM56546 B0	
BCM56580	BCM56580 A0	16 x 2.5 GbE + 4 x 10 GbE Ethernet Multilayer Switch
BCM56620	BCM56620 A0	
	BCM56620 A1	
	BCM56620 B0	
	BCM56620 B1	
	BCM56620 B2	
	BCM56624 A0	49 port 1-GbE Multilayer Ethernet Switch with 4 x 10-GbE/HiGig2 Uplink ports and External Table Expansion
	BCM56624 A1	
	BCM56624 B0	
	BCM56624 B1	
	BCM56624 B2	
	BCM56626 A0	25 port 1-GbE Multilayer Ethernet Switch with 6 x 10-GbE/HiGig2 Uplink ports and External Table Expansion
	BCM56626 A1	
	BCM56626 B0	
	BCM56626 B1	
	BCM56626 B2	
	BCM56628 A0	8 port 10-GbE/HiGig2 Multilayer Ethernet Switch with External Table Expansion
	BCM56628 A1	
	BCM56628 B0	
	BCM56628 B1	
	BCM56628 B2	
	BCM56629 B0	25 port 1-GbE Multilayer Ethernet Switch with 8 x 10-GbE/HiGig2 Uplink ports and External Table Expansion
	BCM56629 B1	
	BCM56629 B2	
BCM56630	BCM56630 A0	24-Port GbE Multilayer Switch with Four 10-GbE/HiGig2 Uplink Ports
	BCM56630 B0	
	BCM56634 A0	48-Port GbE Multilayer Switch with Four 10-GbE/HiGig2 Uplink Ports
	BCM56634 B0	
	BCM56636 A0	24-Port GbE + 2-Port 10-GbE Multilayer Switch with Four 10-GbE/HiGig2 Uplink Ports
	BCM56636 B0	
	BCM56638 A0	4-Port 10-GbE Multilayer Switch with Four 10-GbE/HiGig2 Uplink Ports
	BCM56638 B0	
	BCM56639 A0	24-Port GbE + 4-Port 10-GbE Multilayer Switch with Four 10-GbE/HiGig2 Uplink Ports
	BCM56639 B0	

Table 64: Switch Devices

Family	Devices	Description
BCM56640	BCM56640 A1	1x100GE + 1xHG[127], 1x100GE + 4xHG[32], 1x100GE + 8xHGd[16], 3xF.HG[42] + 1xHG[127], 3xF.HG[42] + 4xHG[32], 3xF.HG[42] + 8xHGd[16], 3xF.HG[42] + 3xF.HG[42] Multilayer Ethernet Switch
	BCM56640 B0	
BCM56640	BCM56643 A1	48xGE + 4xXFI + 4xHG[42] + 1GE Multilayer Ethernet Switch
	BCM56643 B0	
BCM56640	BCM56644 A1	48xGE + 2xHG[25] + 2xHG[25] + 1GE Multilayer Ethernet Switch
	BCM56644 B0	
BCM56640	BCM56648 A1	48xGE + 2xHG[42] + 2xHG[21] + 1GE, 48xGE + 4xXFI + 2xHG[42] + 1GE, 48xGE + 8xXFI + 1GE Multilayer Ethernet Switch
	BCM56648 B0	
BCM56640	BCM56649 A1	28xGE + 2xHG[42] + 2xHG[21] + 1GE, 28xGE + 4xXFI + 2xHG[42] + 1GE, 28xGE + 8xXFI + 1GE Multilayer Ethernet Switch
	BCM56649 B0	
BCM56680	BCM56680 A0	25 port 1-GbE/2.5GbE Multilayer Ethernet Switch with 4 x 10-GbE/HiGig2 Uplink ports
	BCM56680 A1	
	BCM56680 B0	
	BCM56680 B1	
	BCM56684 A0	24 port 1-GbE/2.5GbE Multilayer Ethernet Switch with 4 x 10-GbE/HiGig2 Uplink ports
	BCM56684 A1	
	BCM56684 B0	
	BCM56684 B1	
BCM56685	BCM56685 A0	24-Port GbE Multilayer Switch with Four 10-GbE/HiGig2 Uplink Ports
	BCM56685 B0	
	BCM56689 A0	24-Port GbE Multilayer Switch with Four 10-GbE/HiGig2 Uplink Ports
	BCM56689 B0	
BCM56700	BCM56700 A0	16-Port, 192-Gbps Lossless Switch Fabric
	BCM56701 A0	12-Port, 144-Gbps Lossless Switch Fabric
BCM56720	BCM56720 A0	16 Port, 16-Gbps HiGig2 Switch Fabric
	BCM56721 A0	12 Port, 16-Gbps HiGig2 Switch Fabric
BCM56725	BCM56725 A0	8 Port, 20-Gbps + 4 Port, 16-Gbps HiGig2 Switch Fabric
BCM56740	BCM56743 A0	480 Gbps Switch fabric
	BCM56743 A1	
	BCM56743 A2	
	BCM56743 A3	
	BCM56743 A4	
	BCM56743 B0	
	BCM56743 B1	
	BCM56745 A0	640 Gbps Switch fabric
	BCM56745 A1	
	BCM56745 A2	
	BCM56745 A3	
	BCM56745 A4	

Table 64: Switch Devices

Family	Devices	Description
	BCM56745 B0	
	BCM56745 B1	
BCM56740_PLUS	BCM56744 A0	480 Gbps Switch fabric
	BCM56744 A1	
	BCM56746 A0	640 Gbps Switch fabric
	BCM56746 A1	
BCM56800	BCM56800 A0	20-Port 10-Gigabit Ethernet Multilayer Switch
	BCM56801 A0	10-Port 10-Gigabit Ethernet and 8-Port HiGig2/10GbE Multilayer Switch
	BCM56802 A0	16-Port 10-GbE/HiGig2 Multilayer Switch
	BCM56803 A0	12 Port 10GE/HiGig2 Multilayer Switch
BCM56820	BCM56820 A0	24 x 10-GbE + 4 x 1-GbE Multilayer Ethernet Switch
	BCM56820 B0	
	BCM56821 A0	12 x 10-GbE + 8 x HiGig2 + 4 x 1-GbE Multilayer Ethernet Switch
	BCM56821 B0	
	BCM56822 A0	12 x 10-GbE + 4 x 20-Gbps HiGig2 + 4 x 1-GbE Multilayer Ethernet Switch
	BCM56822 B0	
	BCM56823 A0	8 x 10-GbE + 4 x 20-Gbps HiGig2 + 4 x 1-GbE Multilayer Ethernet Switch
	BCM56823 B0	
	BCM56825 B0	16 x 10-GbE + 8 x 20-Gbps HiGig2 + 1 x 1-GbE Multilayer Ethernet Switch
BCM56740	BCM56743 A0	480 Gbps Switch fabric
	BCM56743 A1	
	BCM56743 A2	
	BCM56743 A3	
	BCM56743 A4	
	BCM56743 B0	
	BCM56743 B1	
	BCM56745 A0	640 Gbps Switch fabric
	BCM56745 A1	
	BCM56745 A2	
	BCM56745 A3	
	BCM56745 A4	
	BCM56745 B0	
	BCM56745 B1	
BCM56740_PLUS	BCM56744 A0	480 Gbps Switch fabric
	BCM56744 A1	
	BCM56746 A0	640 Gbps Switch fabric
	BCM56746 A1	
BCM56840	BCM56841 A0	320 Gbps Ethernet Multilayer Switch
	BCM56841 A1	
	BCM56841 A2	
	BCM56841 A3	
	BCM56841 A4	



Table 64: Switch Devices

Family	Devices	Description
	BCM56841 B0	
	BCM56841 B1	
	BCM56843 A0	480 Gbps Ethernet Multilayer Switch
	BCM56843 A1	
	BCM56843 A2	
	BCM56843 A3	
	BCM56843 A4	
	BCM56843 B0	
	BCM56843 B1	
	BCM56845 A0	640 Gbps Ethernet Multilayer Switch
	BCM56845 A1	
	BCM56845 A2	
	BCM56845 A3	
	BCM56845 A4	
	BCM56845 B0	
	BCM56845 B1	
BCM56840_PLUS	BCM56842 A0	320 Gbps Ethernet Multilayer Switch
	BCM56842 A1	
	BCM56844 A0	480 Gbps Ethernet Multilayer Switch
	BCM56844 A1	
	BCM56846 A0	640 Gbps Ethernet Multilayer Switch
	BCM56846 A1	
BCM56850	BCM56850 A1	1.28Tbps I/O, 1Tbps Core Ethernet Switch
	BCM56854 A1	
BCM88732	BCM88732 B2	Eight-Port 10 GbE or 2-Port 40 GbE MAC Aggregation Switch with 80 Gbps Uplink Capacity
BCM88020	BCM88020 A0	XGS Core (XCore/SBX) Fully Programmable Carrier Packet Processor with 24 GbE Ports, 2 10GbE Ports and 2 SPI Interfaces
	BCM88020 A1	
	BCM88020 A2	
BCM88025	BCM88025 A0	XGS Core (XCore/SBX) Fully Programmable Carrier Packet Processor with 24 GbE Ports, 2 10GbE Ports and 2 SPI Interfaces
BCM88030	BCM88030 A0	XGS Core (XCore/SBX) Scalable Switching 100 Gbps Fully Programmable Carrier Packet Processor
BCM88130	BCM88130 A0	XGS Core (XCore/SBX) 630 Gbps Bandwidth Manager and Switching Engine
	BCM88130 A1	
BME-3200	BME-3200 A0	XGS Core (XCore/SBX) Fabric Bandwidth Manager with 32 SCI control ports and up to 40 SFI data ports
	BME-3200 B0	
QE-2000	QE-2000 A1	XGS Core (XCore/SBX) Fabric Queueing Engine with 49 SPI 4.2 subports
	QE-2000 A2	
	QE-2000 A3	
	QE-2000 A4	
BCM88230	BCM88230 A0	XGS Core (XCore/SBX) Fabric Queueing Engine with Integrated Traffic Management with 4 HiGig2 ports, 50Gbps



Table 64: Switch Devices

Family	Devices	Description
	BCM88230 B0	
	BCM88235 A0	XGS Core (XCore/SBX) Fabric Queueing Engine with Integrated Traffic Management with 4 HiGig2 ports, 80Gbps
	BCM88235 B0	
	BCM88231 A0	XGS Core (XCore/SBX) Traffic Manager with 4 HiGig2 ports, 50Gbps
	BCM88231 B0	
	BCM88236 A0	XGS Core (XCore/SBX) Traffic Manager with 4 HiGig2 ports, 80Gbps
	BCM88236 B0	
BCM56930	BCM56931 A0	XGS pass-through and standalone Traffic Manager, 4 HiGig2 ports, 50Gbps
	BCM56931 B0	
	BCM56936 A0	XGS pass-through and standalone Traffic Manager, 4 HiGig2 ports, 80Gbps
	BCM56936 B0	
BCM88640	BCM88640 A0	DNX 100G Flexible Packet Processor with Integrated Traffic Management
	BCM88640 B0	
BCM88650	BCM88650 A0	DNX 200G Flexible Packet Processor with Integrated Traffic Management
	BCM88650 B0	
	BCM88650 B1	
BCM88660	BCM88660 A0	DNX 200G Flexible Packet Processor with Integrated Traffic Management
BCM88750	BCM88750 A0	DNX 1600 GBps Switch Fabric
	BCM88750 B0	

Table 65: SER Supported Devices

Family	Devices
Trident	56841, 56842, 56843, 56844, 56845, 56846, 56850
Triumph	56640, 56643, 56644, 56648, 56649, 56540, 56541, 56542, 56544, 56545
Katana	All SKUs
Katana2	56450, 56455, 56456, 56248L, 55455
Enduro2	All SKUs
Hurricane2	56150, 56151, 53344, 53346, 53393, 53394
Helix4	56340, 56040, 56344, 56042, 56342, 56041
Firebolt4	56545, 56546

Table 66: Switch Devices that support Warm boot

Family	Devices	Description
BCM5675	BCM5675 A0	8-Port, 192-Gbps Switch Fabric
	BCM5675 A1	
	BCM5676 A0	4-Port, 96-Gbps Switch Fabric
	BCM5676 A1	
BCM56020	BCM56024 A0	24-Port Integrated Multilayer Switch and CPU
	BCM56024 B0	

Table 66: Switch Devices that support Warm boot

Family	Devices	Description
	BCM56025 A0	24-Port Integrated L2 Switch and CPU
	BCM56025 B0	
	BCM56026 A0	24-Port Integrated L2 Switch and CPU
	BCM56026 B0	
BCM56130	BCM56132 A0	24-Port Fast Ethernet Multilayer Switch with Two 10-GbE/HiGig2 and Two 1G/2.5Gb Uplink Ports
	BCM56132 B0	
	BCM56132 B1	
	BCM56134 A0	24-Port Fast Ethernet Multilayer Switch with four 1G/2.5Gb Uplink Ports
	BCM56134 B0	
	BCM56134 B1	
BCM56142	BCM56142 A0	24-Port Fast Ethernet Multilayer Switch with four 1G/2.5Gb/HiGig2/HG Lite Uplink Ports
BCM56150	BCM56150 A0	24-port GbE Managed Switch with 4-port 10 GbE uplinks, integrated CPU and 16 copper PHYs
	BCM56151 A0	24-port GbE Managed Switch with 4-port 10 GbE uplinks, integrated CPU (without PHYs)
	BCM56152 A0	24-port GbE plus 2-port GbE and 2-port 1GbE/13GbE uplinks Managed Switch, integrated CPU and 16 copper PHYs
	BCM53342 A0	8-port GbE Multilayer WebSmart Switch with Integrated CPU and Copper PHYs
	BCM53343 A0	16-port GbE plus 4-port GbE uplinks Multilayer WebSmart Switch with Integrated CPU and 16 Copper PHYs
	BCM53344 A0	24-port GbE plus 2-port GbE and 2-port 1GbE/13GbE uplinks WebSmart Switch, integrated CPU and 16 copper PHYs
	BCM53346 A0	24-port GbE Multilayer WebSmart Switch with 4-port 10 GbE uplinks, integrated CPU and 16 copper PHYs
	BCM53393 A0	14-port GbE Multilayer Embedded Switch with integrated CPU (without PHY)
	BCM53394 A0	10-port GbE Multilayer Embedded Switch with 4-port 10 GbE uplinks, integrated CPU (without PHY)
BCM56220	BCM56224 A0	24 GbE + 4 x 1 Gb/2.5 Gb, L3/L2+
	BCM56224 B0	24 GbE + 4 x 1 Gb/2.5 Gb, L3/L2+
	BCM56225 A0	24 GbE + 4 x 1 Gb/2.5 Gb, L2+
	BCM56225 B0	24 GbE + 4 x 1 Gb/2.5 Gb, L2+
	BCM56226 A0	16 GbE + 4 x 1 Gb/2.5 Gb, L3/L2+
	BCM56226 B0	16 GbE + 4 x 1 Gb/2.5 Gb, L3/L2+
	BCM56227 A0	16 GbE + 4 x 1 Gb/2.5 Gb, L2+
	BCM56227 B0	16 GbE + 4 x 1 Gb/2.5 Gb, L2+
	BCM56228 A0	8 GbE + 4 x 1 Gb/2.5 Gb, L3/L2+
	BCM56228 B0	8 GbE + 4 x 1 Gb/2.5 Gb, L3/L2+
	BCM56229 A0	8 GbE + 4 x 1 Gb/2.5 Gb, L2+
	BCM56229 B0	8 GbE + 4 x 1 Gb/2.5 Gb, L2+
BCM56230	BCM56230 B1	12-Port GbE Multilayer Switch
	BCM56231 B1	6-Port GbE Multilayer Switch
BCM56320	BCM56320 A0	24-Port GbE Multilayer Switch with Four 10-GbE/HiGig2 Uplink Ports
	BCM56320 B0	
	BCM56320 B1	

Table 66: Switch Devices that support Warm boot

Family	Devices	Description
	BCM56321 A0	24-Port GbE Multilayer Switch with Four 10-GbE/HiGig2 Uplink Ports
	BCM56321 B0	
	BCM56321 B1	
BCM56330	BCM56331 A0	24-Port GbE Multilayer Switch with Four 2.5GbE Uplink Ports
	BCM56331 B0	
	BCM56331 B1	
	BCM56333 A0	16-Port GbE Multilayer Switch
	BCM56333 B0	
	BCM56333 B1	
	BCM56334 A0	24-Port GbE Multilayer Switch with Four 10-GbE/HiGig2 Uplink Ports
	BCM56334 B0	
	BCM56334 B1	
	BCM56338 A0	8-Port GbE Multilayer Switch with two 10-GbE/HiGig2 Uplink Ports
	BCM56338 B0	
	BCM56338 B1	
BCM56340	BCM56340 A0	12xF.QSGMII + Flex[4x10] + 2xHG[21] + 1GE, 12xF.QSGMII + 4xSGMII + 2xXFI + 2xHGd[21] + 1GE
	BCM56342 A0	7xF.QSGMII + Flex[4x10] + 2xHG[21] + 1GE
	BCM56344 A0	10xF.QSGMII + 3xFlex[4x10] + 1GE
	BCM56040 A0	1xF.QSGMII + 3xF.HG[42] + 1GE
	BCM56041 A0	Ranger device, meant for embedded connectivity supports 1Ge (port 49), 2 X GE (iPROC), Flex 4x10G, 3 X 4 X 10G
	BCM560547 A0	10xF.QSGMII + 3xF.HG[42] + 1GE, 12xF.QSGMII + 2xF.HG[42] + 1GE, 12xF.QSGMII + F.HG[42] + 2xHG[42] + 1GE
	BCM560548 A0	7xF.QSGMII + 3xF.HG[42] + 1GE
BCM56240	BCM56240 A0	2-Port 10GbE (OR 8 *2.5GbE) Multilayer Switch with Two 10-GbE/Hig2 Uplink ports
BCM56240	BCM56240 B0	2-Port 10GbE (OR 8 *2.5GbE) Multilayer Switch with Two 10-GbE/Hig2 Uplink ports
	BCM56241 A0	6-Port GbE Multilayer Switch with Two 2.5GbE Uplink ports
	BCM56242 A0	8-Port 2.5GbE Multilayer Switch with Two 2.5GbE Uplink ports
	BCM56243 A0	4-Port 2.5GbE Multilayer Switch
BCM56440	BCM55441 A0	24-Port GbE Multilayer Switch with Four 10-GbE/Hig2 Uplink ports
	BCM56440 A0	24-Port GbE Multilayer Switch with Four 10-GbE/Hig2 Uplink ports
	BCM56440 B0	24-Port GbE Multilayer Switch with Four 10-GbE/Hig2 Uplink ports
	BCM56441 A0	8-Port GbE Multilayer Switch with Two 10-GbE/Hig2 Uplink ports
	BCM56442 A0	16-Port GbE Multilayer Switch
	BCM56443 A0	8-Port 2.5GbE Multilayer Switch with Two 10-GbE/Hig2 Uplink ports
	BCM56445 A0	24-Port GbE Multilayer Switch with Four 10-GbE/Hig2 Uplink ports pin compatible with BCM56334
	BCM56446 A0	8-Port GbE Multilayer Switch with Two 10-GbE/Hig2 Uplink ports pin compatible with BCM56338
	BCM56447 A0	16-Port GbE Multilayer Switch pin compatible with BCM56333
	BCM56448 A0	24-Port GbE Multilayer Switch with Four 1GbE/ One 2.5G Uplink ports
BCM56450	BCM56450 A0	

Table 66: Switch Devices that support Warm boot

<i>Family</i>	<i>Devices</i>	<i>Description</i>
	BCM56455 A0	
	BCM56456 B0	
BCM56500	BCM56500 A0	24-Port Gigabit Ethernet Multilayer Switch
	BCM56500 A1	
	BCM56500 B0	
	BCM56500 B1	
	BCM56500 B2	
	BCM56501 A0	
	BCM56501 A1	Four 10-Gigabit Ethernet/HiGig+ Ports
	BCM56501 B0	
	BCM56501 B1	
	BCM56501 B2	
	BCM56502 A0	24-Port GbE Multilayer Switch with Two 10-GbE/HiGig+ Ports
	BCM56502 A1	
	BCM56502 B0	
	BCM56502 B1	
	BCM56502 B2	
	BCM56503 A0	
	BCM56503 A1	24-Port GbE Multilayer Switch with Three 10-GbE/HiGig+ Ports
	BCM56503 B0	
	BCM56503 B1	
	BCM56503 B2	
	BCM56504 A0	24-Port GbE Multilayer Switch with Four 10-GbE/HiGig+ Ports
	BCM56504 A1	
	BCM56504 B0	
	BCM56504 B1	
	BCM56504 B2	
	BCM56505 A0	
	BCM56505 A1	24-Port GbE Layer 2 Switch
	BCM56505 B0	
	BCM56505 B1	
	BCM56505 B2	
	BCM56506 A0	Four 10-Gigabit Ethernet/HiGig+ Ports
	BCM56506 A1	
	BCM56506 B0	
	BCM56506 B1	
	BCM56506 B2	
	BCM56507 A0	
	BCM56507 A1	24-Port GbE Layer 2 Switch with Two 10-GbE/HiGig+ Ports
	BCM56507 B0	
	BCM56507 B1	
	BCM56507 B1	



Table 66: Switch Devices that support Warm boot

<i>Family</i>	<i>Devices</i>	<i>Description</i>
	BCM56507 B2	
	BCM56508 A0	24-Port GbE Layer 2 Switch with Three 10-GbE/HiGig+ Ports
	BCM56508 A1	
	BCM56508 B0	
	BCM56508 B1	
	BCM56508 B2	
	BCM56509 A0	24-Port GbE Layer 2 Switch with Four 10-GbE/HiGig+ Ports
	BCM56509 A1	
	BCM56509 B0	
	BCM56509 B1	
	BCM56509 B2	
BCM56510	BCM56510 A0	24-Port Gigabit Ethernet Multilayer Switch
	BCM56511 A0	Four-Port 10-GbE/HiGig+ Multilayer Switch
	BCM56512 A0	24-Port GbE Multilayer Switch With Two 10-GbE/HiGig+ Ports
	BCM56513 A0	24-Port GbE Multilayer Switch With Three 10-GbE/HiGig+ Ports
	BCM56514 A0	24-Port GbE Multilayer Switch With Four 10-GbE/HiGig+ Ports
BCM56520	BCM56520 A0	24-Port GbE Multilayer Switch
	BCM56520 B0	
	BCM56522 A0	24-Port GbE Multilayer Switch with Two 10-GbE/HiGig2 Uplink Ports
	BCM56522 B0	
	BCM56524 A0	24-Port GbE Multilayer Switch with Four 10-GbE/HiGig2 Uplink Ports
	BCM56524 B0	
BCM56526	BCM56526 A0	28-Port GbE Multilayer Switch with Six 10-GbE/HiGig2 Uplink Ports
	BCM56526 B0	
	BCM56534 B0	24-Port GbE Multilayer Switch with Four 10-GbE/HiGig2 Uplink Ports
	BCM56538 B0	48-Port GbE Multilayer Switch with Four 10-GbE/HiGig2 Uplink Ports
	BCM56620 A0	
BCM56620	BCM56620 A1	
	BCM56620 B0	
	BCM56620 B1	
	BCM56624 A0	49 port 1-GbE Multilayer Ethernet Switch with 4 x 10-GbE/HiGig2 Uplink ports and External Table Expansion
	BCM56624 A1	
	BCM56624 B0	
	BCM56624 B1	
	BCM56624 B2	
	BCM56626 A0	25 port 1-GbE Multilayer Ethernet Switch with 6 x 10-GbE/HiGig2 Uplink ports and External Table Expansion
	BCM56626 A1	
	BCM56626 B0	
	BCM56626 B1	
	BCM56626 B2	

Table 66: Switch Devices that support Warm boot

Family	Devices	Description
	BCM56628 A0	8 port 10-GbE/HiGig2 Multilayer Ethernet Switch with External Table Expansion
	BCM56628 A1	
	BCM56628 B0	
	BCM56628 B1	
	BCM56628 B2	
	BCM56629 B0	25 port 1-GbE Multilayer Ethernet Switch with 8 x 10-GbE/HiGig2 Uplink ports and External Table Expansion
	BCM56629 B1	
	BCM56630	
	BCM56630 A0	24-Port GbE Multilayer Switch with Four 10-GbE/HiGig2 Uplink Ports
	BCM56630 B0	
	BCM56634 A0	48-Port GbE Multilayer Switch with Four 10-GbE/HiGig2 Uplink Ports
	BCM56634 B0	
	BCM56636 A0	24-Port GbE + 2-Port 10-GbE Multilayer Switch with Four 10-GbE/HiGig2 Uplink Ports
	BCM56636 B0	
	BCM56638 A0	4-Port 10-GbE Multilayer Switch with Four 10-GbE/HiGig2 Uplink Ports
	BCM56638 B0	
	BCM56639 A0	24-Port GbE + 4-Port 10-GbE Multilayer Switch with Four 10-GbE/HiGig2 Uplink Ports
	BCM56639 B0	
BCM56540	BCM56540 A0	48xGE + 2xHG[42] + 2xHG[21] + 1GE, 48xGE + 4xXFI + 2xHG[42] + 1GE, 48xGE + 8xXFI + 1GE Multilayer Ethernet Switch (Preview)
	BCM56540 A1	
BCM56540	BCM56541 A0	28xGE + 2xHG[42] + 2xHG[21] + 1GE, 28xGE + 4xXFI + 2xHG[42] + 1GE, 28xGE + 8xXFI + 1GE Multilayer Ethernet Switch (Preview)
	BCM56541 A1	
BCM56540	BCM56542 A0	28xGE + 2xF.XAUI/2x10GE + 2xF.HG[42] + 2xF.HG[21] + 1GE, 28xGE + 8xGE/8x2.5GE + 2xHG[42] + 2xHG[21] + 1GE Multilayer Ethernet Switch (Preview)
	BCM56542 A1	
BCM56540	BCM56544 A0	10xF.XAUI + 4xHG[21] + 1GE, 10xF.XAUI + 4xXFI, 10xF.XAUI + 2xHG[42], 4xXAUI + 12xXFI + 1GE Multilayer Ethernet Switch (Preview)
	BCM56544 A1	
BCM56540	BCM56545 A0	48xGE + 2xHG[42] + 2xHG[21] + 1GE, 48xGE + 4xXFI + 2xHG[42] + 1GE, 48xGE + 8xXFI + 1GE Multilayer Ethernet Switch (Preview)
	BCM56545 A1	
BCM56540	BCM56546 A0	28xGE + 2xHG[42] + 2xHG[21] + 1GE, 28xGE + 4xXFI + 2xHG[42] + 1GE, 28xGE + 8xXFI + 1GE Multilayer Ethernet Switch (Preview)
BCM56640	BCM56640 A0	1x100GE + 1xHG[127], 1x100GE + 4xHG[32], 1x100GE + 8xHGd[16], 3xF.HG[42] + 1xHG[127], 3xF.HG[42] + 4xHG[32], 3xF.HG[42] + 8xHGd[16], 3xF.HG[42] + 3xF.HG[42] Multilayer Ethernet Switch (Preview)
	BCM56640 A1	
BCM56640	BCM56643 A0	48xGE + 4xXFI + 4xHG[42] + 1GE Multilayer Ethernet Switch (Preview)
	BCM56643 A1	
BCM56640	BCM56644 A0	48xGE + 2xHG[25] + 2xHG[25] + 1GE Multilayer Ethernet Switch (Preview)
	BCM56644 A1	
BCM56640	BCM56648 A0	48xGE + 2xHG[42] + 2xHG[21] + 1GE, 48xGE + 4xXFI + 2xHG[42] + 1GE, 48xGE + 8xXFI + 1GE Multilayer Ethernet Switch (Preview)

Table 66: Switch Devices that support Warm boot

Family	Devices	Description
	BCM56648 A1	
BCM56640	BCM56649 A0	28xGE + 2xHG[42] + 2xHG[21] + 1GE, 28xGE + 4xXFI + 2xHG[42] + 1GE, 28xGE + 8xXFI + 1GE Multilayer Ethernet Switch (Preview)
BCM56680	BCM56680 A0	25 port 1-GbE/2.5GbE Multilayer Ethernet Switch with 4 x 10-GbE/HiGig2 Uplink ports
	BCM56680 A1	
	BCM56680 B0	
	BCM56680 B1	
	BCM56684 A0	24 port 1-GbE/2.5GbE Multilayer Ethernet Switch with 4 x 10-GbE/HiGig2 Uplink ports
	BCM56684 A1	
	BCM56684 B0	
	BCM56684 B1	
BCM56685	BCM56685 A0	24-Port GbE Multilayer Switch with Four 10-GbE/HiGig2 Uplink Ports
	BCM56685 B0	
	BCM56689 A0	24-Port GbE Multilayer Switch with Four 10-GbE/HiGig2 Uplink Ports
	BCM56689 B0	
BCM56700	BCM56700 A0	16-Port, 192-Gbps Lossless Switch Fabric
	BCM56701 A0	12-Port, 144-Gbps Lossless Switch Fabric
BCM56720	BCM56720 A0	16 Port, 16-Gbps HiGig2 Switch Fabric
	BCM56721 A0	12 Port, 16-Gbps HiGig2 Switch Fabric
BCM56725	BCM56725 A0	8 Port, 20-Gbps + 4 Port, 16-Gbps HiGig2 Switch Fabric
BCM56800	BCM56800 A0	20-Port 10-Gigabit Ethernet Multilayer Switch
	BCM56801 A0	10-Port 10-Gigabit Ethernet and 8-Port HiGig2/10GbE Multilayer Switch
	BCM56802 A0	16-Port 10-GbE/HiGig2 Multilayer Switch
	BCM56803 A0	12 Port 10GE/HiGig2 Multilayer Switch
BCM56820	BCM56820 A0	24 x 10-GbE + 4 x 1-GbE Multilayer Ethernet Switch
	BCM56820 B0	
	BCM56821 A0	12 x 10-GbE + 8 x HiGig2 + 4 x 1-GbE Multilayer Ethernet Switch
	BCM56821 B0	
	BCM56822 A0	12 x 10-GbE + 4 x 20-Gbps HiGig2 + 4 x 1-GbE Multilayer Ethernet Switch
	BCM56822 B0	
	BCM56823 A0	8 x 10-GbE + 4 x 20-Gbps HiGig2 + 4 x 1-GbE Multilayer Ethernet Switch
	BCM56823 B0	
	BCM56825 B0	16 x 10-GbE + 8 x 20-Gbps HiGig2 + 1 x 1-GbE Multilayer Ethernet Switch
BCM56840	BCM56841 A0	320 Gbps Ethernet Multilayer Switch
	BCM56841 A1	
	BCM56841 A2	
	BCM56841 A3	
	BCM56841 A4	
	BCM56841 B0	
	BCM56841 B1	
	BCM56843 A0	480 Gbps Ethernet Multilayer Switch
	BCM56843 A1	

Table 66: Switch Devices that support Warm boot

Family	Devices	Description
	BCM56843 A2	
	BCM56843 A3	
	BCM56843 A4	
	BCM56843 B0	
	BCM56843 B1	
	BCM56845 A0	640 Gbps Ethernet Multilayer Switch
	BCM56845 A1	
	BCM56845 A2	
	BCM56845 A3	
	BCM56845 A4	
	BCM56845 B0	
	BCM56845 B1	
	BCM56840 PLUS	
	BCM56842 A0	320 Gbps Ethernet Multilayer Switch
	BCM56842 A1	
	BCM56844 A0	480 Gbps Ethernet Multilayer Switch
	BCM56844 A1	
	BCM56846 A0	640 Gbps Ethernet Multilayer Switch
	BCM56846 A1	
	BCM56854 A0	1.28Tbps I/O, 1Tbps Core Ethernet Switch
	BCM56850 A1	1.28Tbps I/O, 1Tbps Core Ethernet Switch
	BCM56854 A1	1.28Tbps I/O, 1Tbps Core Ethernet Switch
	BCM88640	
	BCM88640 A0	80GBps DNX Traffic manager + Packet processor
	BCM88640 B0	
	BCM88650	
	BCM88650 A0	200GBps DNX Traffic manager + Packet processor
	BCM88650 B0	
	BCM88650 B1	
BCM88660	BCM88660 A0	200GBps DNX Traffic manager + Packet processor
BCM88750	BCM88750 A0	1600GBps DNX Switch fabric
	BCM88750 B0	

Note: There is no warm boot support for External table expansion in BCM56620, BCM56630 and BCM56640 device family.

Table 67: Switch Device Codenames

Product Family	Architecture	Codename
BCM5650	StrataXGS	-
BCM5665	StrataXGS	-
BCM5670	StrataXGS	-
BCM5673	StrataXGS	-
BCM5674	StrataXGS II	-
BCM5675	StrataXGS II	-
BCM5690	StrataXGS	-
BCM5695	StrataXGS II	-
BCM53310	StrataXGS III	Hawkeye



Table 67: Switch Device Codenames

Product Family	Architecture	Codename
BCM53710	StrataXGS III	Raptor
BCM53720	StrataXGS III	Raven
BCM56010	StrataXGS III	Raptor
BCM56020	StrataXGS III	Tropicana
BCM56100	StrataXGS III	Felix
BCM56110	StrataXGS III	Felix+
BCM56140	StrataXGS IV	Hurricane
BCM56150	StrataXGS IV	Hurricane2
BCM56210	StrataXGS III	Raptor
BCM56220	StrataXGS III	Raven
BCM56300	StrataXGS III	Helix
BCM56310	StrataXGS III	Helix+
BCM56320	StrataXGS IV	Helix3
BCM56340	StrataXGS V	Helix4
BCM56330	StrataXGS IV	Enduro
BCM56130	StrataXGS IV	Stardust
BCM56230	StrataXGS IV	Dagger
BCM56440	StrataXGS IV	Katana
BCM56445	StrataXGS IV	Enduro2
BCM56450	StrataXGS IV	Katana2
BCM56500	StrataXGS III	Firebolt
BCM56510	StrataXGS III	Firebolt2
BCM56520	StrataXGS IV	Apollo
BCM56530	StrataXGS IV	Firebolt3
BCM56540	StrataXGS IV	Apollo2
BCM56580	StrataXGS III	Goldwing
BCM56600	StrataXGS III	Easyrider
BCM56620	StrataXGS IV	Triumph
BCM56629	StrataXGS IV	Triumph
BCM56630	StrataXGS IV	Triumph2
BCM56640	StrataXGS IV	Triumph3
BCM56680	StrataXGS IV	Valkyrie
BCM56685	StrataXGS IV	Valkyrie2
BCM56700	StrataXGS III	Humv
BCM56720	StrataXGS IV	HUMV+
BCM56725	StrataXGS IV	Conqueror
BCM56740	StrataXGS IV	Titan
BCM56744	StrataXGS IV	Titan+
BCM56800	StrataXGS IV	Bradley
BCM56820	StrataXGS IV	Scorpion
BCM56825	StrataXGS IV	Sco320G
BCM56840	StrataXGS IV	Trident
BCM56840_PLUS	StrataXGS IV	Trident+
BCM56850	StrataXGS V	Trident2
BCM88732	StrataXGS IV	Shadow
BCM88020	XGS Core	Caladan FE-2000
BCM88025	XGS Core	Caladan2
BCM88030	XGS Core	Caladan3
BCM88130	XGS Core	Polaris
BCM88230	XGS Core	Sirius
BCM88235	XGS Core	Sirius+

Table 67: Switch Device Codenames

<i>Product Family</i>	<i>Architecture</i>	<i>Codename</i>
BCM88231	XGS Core	Sirius TM
BCM88236	XGS Core	Sirius+ TM
BCM56931	XGS Core	Sportster
BCM56936	XGS Core	Sportster+
BCM53010	ROBO	Northstar
BCM53018	ROBO	Costar
BCM53020	ROBO	Northstar+
BCM53101	ROBO	Lotus
BCM53115	ROBO	Vulcan
BCM53118	ROBO	Blackbird
BCM53125	ROBO	Starfighter
BCM53128	ROBO	Blackbird2
BCM53242	ROBO	Harrier
BCM53280	ROBO	Thunderbolt
BCM53600	ROBO	Voyager
BCM89500	ROBO	Polar
BCM88X4X	SAND	Petra-B
BCM88650	SAND	Arad
BCM88660	SAND	Arad+
BCM88750	SAND	FE1600

PHYS

Table 68: PHYs

<i>Device</i>	<i>Driver Family</i>	<i>Description</i>
BCM5218	522x	10/100Base-TX/FX Octal-PHY(tm) Transceiver
BCM5220	522x	10/100BASE-TX/FX Mini-F(tm) Transceiver
BCM5221	522x	10/100BASE-TX/FX Mini-F(tm) Transceiver
BCM5226	522x	10/100 BASE- TX/FX Hex-PHY(tm) Transceiver
BCM5228	522x	10/100BASE-TX/FX Octal-F(tm) Transceiver
BCM5238	522x	10/100BASE-TX OCTAL-f(tm) Transceiver
BCM5248	522x	10/100BASE-TX Octal-F(tm) Transceiver
BCM52681E A1	54680	Octal 10/100 Ethernet Transceiver
BCM5401	5401	10/100/1000BASE-T Gigabit Copper Transceiver
BCM5402	5402	10/100/1000BASE-T Gigabit Copper Transceiver
BCM5404	5404	Quad-Port 10/100/1000BASE-T Gigabit Copper Transceiver
BCM5424	5424	Quad 10/100/1000BASE-T Gigabit Ethernet Transceiver
BCM5434	5424	Quad 10/100/1000BASE-T Gigabit Ethernet Transceiver
BCM5411	5411	10/100/1000BASE-T Gigabit Copper Transceiver
BCM5421	5421S	10/100/1000BASE-T Gigabit Copper Transceiver
BCM5421S	5421S	10/100/1000BASE-T Gigabit Copper Transceiver with SerDes
BCM5461	5464	10/100/1000BASE-T Gigabit Ethernet Transceiver
BCM5464	5464	Quad-Port 10/100/1000BASE-T Gigabit Copper Transceiver
BCM5464R	5464	Quad-Port 10/100/1000BASE-T Gigabit Copper Transceiver
BCM5464S	5464	Quad-Port Gigabit Copper Transceiver with Copper/Fiber Media Interface
BCM5464SR	5464	Quad-Port Gigabit Copper Transceiver with Copper/Fiber Media Interface
BCM5466	5464	Quad-Port 10/100/1000BASE-T Gigabit Copper Transceiver
BCM5466R	5464	Quad-Port 10/100/1000BASE-T Gigabit Copper Transceiver
BCM5466S	5464	Quad-Port Gigabit Copper Transceiver with Copper/Fiber Media Interface
BCM5466SR	5464	Quad-Port Gigabit Copper Transceiver with Copper/Fiber Media Interface
BCM5482	5482	Dual-Port 10/100/1000BASE-T Gigabit Ethernet Transceiver
BCM5488	5464	Octal 1000/100/10BASE-T Gigabit Ethernet Transceiver
BCM54240_C0	54280	Quad 1000/100/10BASE-T Gigabit Ethernet Transceiver
BCM54240_C1	54280	Quad 1000/100/10BASE-T Gigabit Ethernet Transceiver
BCM54280_A0	54280	Octal 1000/100/10BASE-T Gigabit Ethernet Transceiver
BCM54280_C0	54280	Octal 1000/100/10BASE-T Gigabit Ethernet Transceiver
BCM54280_C1	54280	Octal 1000/100/10BASE-T Gigabit Ethernet Transceiver
BCM54282_A0	54280	Octal 1000/100/10BASE-T Gigabit Ethernet Transceiver
BCM54282_C0	54280	Octal 1000/100/10BASE-T Gigabit Ethernet Transceiver
BCM54282_C1	54280	Octal 1000/100/10BASE-T Gigabit Ethernet Transceiver
BCM54285_C0	54280	Octal 1000/100/10BASE-T Gigabit Ethernet Transceiver
BCM54285_C1	54280	Octal 1000/100/10BASE-T Gigabit Ethernet Transceiver
BCM54290_A0	54280	Octal 1000/100/10BASE-T Gigabit Ethernet Transceiver (1588 feature is Preview)
BCM54292_A0	54280	Octal 1000/100/10BASE-T Gigabit Ethernet Transceiver (1588 feature is Preview)
BCM54294_A0	54280	Quad 1000/100/10BASE-T Gigabit Ethernet Transceiver (1588 feature is Preview)
BCM54340_B0	54380	Quad 1000/100/10BASE-T Gigabit Ethernet Transceiver (Needs additional software component)
BCM54340_C0	54380	Quad 1000/100/10BASE-T Gigabit Ethernet Transceiver (Needs additional software component)

Table 68: PHYs

Device	Driver Family	Description
BCM54340_C1	54380	Quad 1000/100/10BASE-T Gigabit Ethernet Transceiver (Needs additional software component)
BCM54380_B0	54380	Octal 1000/100/10BASE-T Gigabit Ethernet Transceiver (Needs additional software component)
BCM54380_C0	54380	Octal 1000/100/10BASE-T Gigabit Ethernet Transceiver (Needs additional software component)
BCM54380_C1	54380	Octal 1000/100/10BASE-T Gigabit Ethernet Transceiver (Needs additional software component)
BCM54382_B0	54380	Octal 1000/100/10BASE-T Gigabit Ethernet Transceiver (Needs additional software component)
BCM54382_C0	54380	Octal 1000/100/10BASE-T Gigabit Ethernet Transceiver (Needs additional software component)
BCM54382_C1	54380	Octal 1000/100/10BASE-T Gigabit Ethernet Transceiver (Needs additional software component)
BCM54385_B0	54380	Octal 1000/100/10BASE-T Gigabit Ethernet Transceiver (Needs additional software component)
BCM54385_C0	54380	Octal 1000/100/10BASE-T Gigabit Ethernet Transceiver (Needs additional software component)
BCM54385_C1	54380	Octal 1000/100/10BASE-T Gigabit Ethernet Transceiver (Needs additional software component)
BCM54616_A0	54616	Single-Chip 10/100/1000BASE-T Gigabit Ethernet Transceiver
BCM54640	54640	Quad-Port Gigabit Copper Transceiver with Copper/Fiber Media Interface
BCM54640E_A1	54640	Quad-Port Gigabit Copper Transceiver with Copper/Fiber Media Interface
BCM54640E_B0	54640	Quad-Port Gigabit Copper Transceiver with Copper/Fiber Media Interface
BCM54680_A0	54680	Octal-Port 10/100/1000BASE-T Gigabit Ethernet Transceiver
BCM54680E_A1	54680	Octal-Port 10/100/1000BASE-T Gigabit Ethernet Transceiver
BCM54680E_B0	54680	Octal-Port 10/100/1000BASE-T Gigabit Ethernet Transceiver
BCM54682E_A1	54682	Octal-Port 10/100/1000BASE-T Gigabit Ethernet Transceiver with 2 Copper/Fiber Media Interface
BCM54682E_B0	54682	Octal-Port 10/100/1000BASE-T Gigabit Ethernet Transceiver with 2 Copper/Fiber Media Interface
BCM54684_D0	54684	Octal-Port 10/100/1000BASE-T Gigabit Ethernet Transceiver
BCM54684E_B0	54682	10/100/1000 Octal (65nm) QSGMII-Copper/Fiber(2) with EEE
BCM54685	54682	Octal QSGMII to 10/100/1000BaseT or Fiber Ethernet Transceiver
BCM54685E_A1	54682	Octal-Port 10/100/1000BASE-T Gigabit Ethernet Transceiver with Copper/Fiber Media Interface
BCM54810_A0	54880	BroadR-Reach Single-Port 10/100/1000BASE-T Gigabit Ethernet Transceiver
BCM54880_A0	54880	Octal-Port 10/100/1000BASE-T Gigabit Ethernet Transceiver with BroadR-Reach support
BCM54880_B0	54880	Octal-Port 10/100/1000BASE-T Gigabit Ethernet Transceiver with BroadR-Reach support
BCM54880E_A1	54680	Octal-Port 10/100/1000BASE-T Gigabit Ethernet Transceiver
BCM54880E_B0	54680	Octal-Port 10/100/1000BASE-T Gigabit Ethernet Transceiver
BCM54881_B0	54880	Octal 10/100Base/Tx Ethernet BroadReach Transceiver
BCM54942_A0	84728	Quad-Channel 10GbE XAUI-to-XFI PHY. Firmware version 0124
BCM54980_B2	54980	Octal 1000/100/10BASE-T Gigabit Ethernet Transceiver
BCM54980_C0	54980	Octal 1000/100/10BASE-T Gigabit Ethernet Transceiver
BCM54980_C1	54980	Octal 1000/100/10BASE-T Gigabit Ethernet Transceiver
BCM8040_A2	8040	Eight-Channel Multirate 1-Gbps - 3.2-Gbps Retimer/Switch
BCM8073_A0	8072	Dual-Channel Serial 10-GbE BASE-KR to XAUI Transceiver. Firmware version d502.
BCM8074_A0	8072	Quad-Channel Serial 10-GbE BASE-KR to XAUI Transceiver. Firmware version 010C.
BCM8704	8703	Serial 10-Gigabit Ethernet/Fibre Channel Transceiver with XAUI Interface



Table 68: PHYs

Device	Driver Family	Description
BCM8705	8705	Serial 10-Gigabit Ethernet/Fibre Channel Transceiver with WIS Layer and XAUI Interface
BCM8725	8705	Dual Serial 10-Gigabit Ethernet/Fibre Channel Transceiver with WIS Layer and XAUI Interface
BCM8726_A0	8706	Dual Serial 10-Gigabit Ethernet/Fibre Channel Transceiver with XAUI Interface
BCM8726_B1	8706	Dual Serial 10-Gigabit Ethernet/Fibre Channel Transceiver with XAUI(TM) Interface. Firmware version 0x0127
BCM8727_B0	8706	Dual Serial 10-Gigabit Ethernet/Fibre Channel Transceiver with XAUI Interface. Firmware version 0406.
BCM8727_C0	8706	Dual Serial 10-Gigabit Ethernet/Fibre Channel Transceiver with XAUI Interface. Firmware version 050D.
BCM84727_A0	84728	Dual SFI to XAUI with 1588 (Firmware version 0x124. Preview)
BCM8728_A0	8706	Dual-Channel 10-GbE SFI-to-XAUI(TM) Transceiver with EDC. Firmware version 0511. (Preview)
BCM8742	8706	Quad-Channel 10-GbE SFI-to-XAUI(TM) Transceiver. Firmware version 0511.
BCM8747_A0	8706	Quad-Channel 10-GbE SFI-to-XAUI(TM) Transceiver with EDC. Firmware version 0511.
BCM8750_A0	8750	Dual-Channel 10 GbE SFI-to-XFI PHY with EDC
BCM8752_A0	8750	Dual-Channel 10 GbE SFI-to-XFI PHY with EDC
BCM8754_A0	8750	Quad-Channel 10 GbE SFI-to-XFI PHY with EDC. Firmware version 0411.
BCM8481_B0	8481	10GBASE-T Transceiver (Firmware version B0 02.10)
BCM8481_C0	8481	10GBASE-T Transceiver (Firmware version C0 02.13)
BCM84164	BCM84740	Quad 10GBASE-KR-to-XFI or 40GBASE-KR4-to-XLAUI Transceiver Firmware version 0x128
BCM84168	BCM84740	Octal 10GBASE-KR-to-XFI or Dual 40GBASE-KR4-to-XLAUI Transceiver Firmware version 0x128
BCM82328_A0	82328	Dual 40 GbE/Octal 10 GbE QSFP+ XLPPI-to-XLAUI PHY. Firmware version 6 "(Preview)
BCM84328_A0	84328	Dual 40 GbE/Octal 10 GbE QSFP+ XLPPI-to-XLAUI PHY. Firmware version D025
BCM84328_B0	84328	Dual 40 GbE/Octal 10 GbE QSFP+ XLPPI-to-XLAUI PHY. Firmware version D025
BCM84333_B1	8481	Quad 10GBASE-T Transceiver. Firmware version 1.67 (Preview) (Needs additional software component)
BCM84334_B1	8481	Quad 10GBASE-T Transceiver. Firmware version 1.67 (Preview) (Needs additional software component)
BCM84336_B1	8481	Dual 10GBASE-T Transceiver. Firmware version 1.67 (Preview) (Needs additional software component)
BCM84793_A0	84793	100GbE/OTN 4x25/28G VSR28 to 10x10/11G CAUI Gearbox PHY. Firmware version 0xD009 (Preview - Mode-1 and Mode-3)
BCM84812_A0	8481	Dual 10GBASE-T Transceiver. Firmware version 2.13
BCM84821_A0	8481	10GBASE-T Transceiver. Firmware version 2.13 (Preview)
BCM84822_A0	8481	Dual 10GBASE-T Transceiver. Firmware version 3.02
BCM84823_A0	8481	Dual 10GBASE-T Transceiver. Firmware version 3.02
BCM84823_B0	8481	Dual 10GBASE-T Transceiver. Firmware version 4.02
BCM84823_B1	8481	Dual 10GBASE-T Transceiver. Firmware version 4.02
BCM84833_B1	8481	Dual 10GBASE-T Transceiver. Firmware version 1.67(Driver support for IEEE 1588 features are preview)
BCM84834_B1	8481	Quad 10GBASE-T Transceiver. Firmware version 1.67(Driver support for IEEE 1588 features are preview)
BCM84836_B1	8481	Dual 10GBASE-T Transceiver. Firmware version 1.67(Driver support for IEEE 1588 features are preview)
BCM84844_A0	8481	Quad 10GBASE-T Transceiver. Firmware version 1.06(Driver support is preview)
BCM84846_A0	8481	Dual 10GBASE-T Transceiver. Firmware version 1.06(Driver support is preview)



Table 68: PHYs

Device	Driver Family	Description
BCM84848_A0	8481	Quad 10GBASE-T Transceiver. Firmware version 1.06(Driver support is preview)
BCM84728 A0	84728	Dual-Channel 10 GbE SFI-to-XAUI LAN/WAN PHY with 1588. Firmware version 0124 (Driver support for IEEE 1588 features is preview)
BCM84729_A0	84729	Dual-Channel SFI to XAUI with Macsec, 1588 (Firmware version 0x124. Driver support for IEEE 1588 features are preview)
BCM84740 A0	84740	40 GbE PPI-to-XLAUI PHY with EDC. Firmware version D106.
BCM84741 B0	84756	40GbE XLPI-to-XLAUI/Quad 10G with IEEE MACsec/1588 Firmware version 0x0128 [Preview]
BCM84747_A0	84728	Quad SFI to XAUI with 1588 (Firmware version 0x124. Preview)
BCM84748_A0	84728	Quad SFI to XAUI with WAN/1588 (Firmware version 0x124. Preview)
BCM84749_A0	84749	Quad SFI to XAUI with Macsec, 1588 (Firmware version 0x124. Driver support for IEEE 1588 features are preview)
BCM84752 A0	84740	Dual-Channel 10 GbE SFI-to-XFI PHY with EDC. Firmware version D105. (Preview)
BCM84753 A0	84740	Quad-Channel 10 GbE SFI-to-XFI PHY with EDC. Firmware version D105.
BCM84754 A0	84740	Quad-Channel 10 GbE SFI-to-XFI PHY with EDC. Firmware version D105.
BCM84756 A0	84756	Quad SGMII/XFI to SGMII/SFI Transceiver Firmware version D105. (Needs additional software component)
BCM84756 B0	84756	Quad SGMII/XFI to SGMII/SFI Transceiver Firmware version 0x0128(Needs additional software component)
BCM84756 C0	84756	Quad SGMII/XFI to SGMII/SFI Transceiver Firmware version 0x0128(Needs additional software component) [Preview]
BCM84758	84740	10GbE Quad SFI-XFI PHY with IEEE 1588 Firmware version 0x128
BCM84759 A0	84756	Quad SGMII/XFI to SGMII/SFI Transceiver Firmware version D105.
BCM84759 C0	84756	Quad SGMII/XFI to SGMII/SFI Transceiver Firmware version 0x0128. (Preview)
BCM84780_A0	84740	Octal-Channel 10 GbE SFI-to-XFI PHY with 1588. Firmware version 0x128 (Preview)
BCM84784_A0	84740	Dual 40GbE/Octal 10GbE QSFP+ XLPI-to-XLAUI PHY. Firmware version 0x125 (Preview)
BCM84764_A0	84728	Quad SFI to RXAUI with 1588 (Firmware version 0x124. Preview)
BCM84064 A0	84740	Quad 10G-KR-to-XFI or 40G-KR4-to-XLAUI Transceiver. Firmware version 0108.
BCM84074_A0	84728	Quad KR to XAUI (Firmware version 0x124. Preview)

OPERATING SYSTEMS

The SDK provides the SAL and BDE abstraction implementations necessary for running the SDK on the following operating systems. See the Platform Guide (56XX-PG810-R) for instructions on porting the SDK to another platform.

Table 69: Operating Systems

<i>Operating System</i>
VxWorks 5.5
VxWorks 6.2
VxWorks 6.4
VxWorks 6.5
VxWorks 6.6
Linux 2.6.21 User Mode
Linux 2.6.21 Kernel Resident Mode
Linux 2.6.25 User Mode
Linux 2.6.25 Kernel Resident Mode
Linux 2.6.27 User Mode
Linux 2.6.27 Kernel Resident Mode
Linux 2.6.35 User Mode
Linux 2.6.35 Kernel Resident Mode
POSIX Compliant (SAL ONLY)

CPU SUBSYSTEMS

Table 70: CPU Subsystems

<i>CPU Subsystem</i>	<i>Description</i>
BCM98245	CPCI 32-bit PPC with Motorola 8245 Processor
BCM98548XMC	XMC 32-bit PPC with Freescale 8548 Processor
BCM953003C	XMC 32-bit MIPS74Kc with BCM53003 Processor
BCM5300X	32-bit MIPS74Kc with BCM5300X Processor
BCM5301X	Integrated ARM Cortex-A9 CPU on BCM5301X Switch Devices
BCM5302X	Integrated ARM Cortex-A9 CPU on BCM5302X Switch Devices
BCM5621X	Integrated MIPS CPU on BCM5621X Switch Devices
BCM5622X	Integrated MIPS CPU on BCM5622X Switch Devices
BCM5331X	Integrated MIPS CPU on BCM5331X Switch Devices
BCM5360X	Integrated MIPS74Kc CPU on BCM5360X Switch Devices

CPU AND OPERATING SYSTEM COMBINATIONS

The following CPU and Operating System combinations are supported by the SDK (in addition to the above):

Table 71: CPU and Operating System Combinations

<i>CPU Subsystem</i>	<i>Operating System</i>	<i>Description</i>
BCM98245	VxWorks 6.2	BSP Provided
BCM98245	Linux 2.6.21	Available through WindRiver Linux 2.0
BCM5621X	VxWorks 6.4	BSP Provided
BCM5621X	Linux 2.6.21	Available through WindRiver Linux 2.0 bcm_ntswics
BCM5331X	VxWorks 6.4	BSP Provided
BCM5331X	Linux 2.6.21	Available through WindRiver Linux 2.0 bcm_ntswics
BCM98548XMC	VxWorks 6.5	BSP Provided
BCM98548XMC	Linux 2.6.27	Available through WindRiver Linux 3.0. Note: Additional patches for issues WIND00172598 and WIND00161649 are required. Contact your WindRiver support personnel for these patches and other WindRiver information.
BCM5300X	VxWorks 6.6	BSP Provided
BCM5300X	Linux 2.6.21	Available through WindRiver Linux 2.0
BCM5300X	Linux 2.6.27	Available through WindRiver Linux 3.x
BCM5301X	Linux 2.6.35	Available through Broadcom Customer Support Portal
BCM5302X	Linux 2.6.35	Available through Broadcom Customer Support Portal
BCM5360X	VxWorks 6.6	BSP Provided
BCM5360X	Linux 2.6.21	Available through WindRiver Linux 2.0
BCM5360X	Linux 2.6.27	Available through WindRiver Linux 3.x
Generic X86	Linux 2.6.25/2.6.27	

REFERENCE DESIGNS

The following Switch Reference Designs are available from Broadcom and are supported in the SDK.

Table 72: Reference Designs

<i>Platform</i>	<i>Description</i>
BCM953001R24M	24-port FE + 2-port GE 53242 SW Ref. Design with BCM53001 Processor
BCM953115R5GM	5-port GE + 1-port serdes 53115 Ref. Design
BCM953125RM	5-port GE 53125 Ref. Design
BCM953242R24M	24-port FE + 2-port GE 53242 SW Ref. Design
BCM953262R24M	24-port FE + 4-port GE 53262 SW Ref. Design
BCM953284R	24-port FE + 2-port GE 53284 SW Ref. Design
BCM953284MDU	24-port FE 53284 SW Ref. Design with TK3715 EPON ONU MAC/Serdes
BCM953286R	24-port FE + 4-port GE 53286 SW Ref. Design
BCM953300	24-port GE 53300 Switch Ref Design
BCM953302	48-port GE 53302 Switch Ref Design
BCM953314K	24-port GE - 53314 System Verification Kit
BCM953314R24GS	24-port GE - 53314 Switch Ref Design
BCM953604R	24-port FE + 1-port 1/2G EPON ONU MAC/SerDes Reference Design
BCM989501R	5-port BR + 1-port GE - 89501 Ref. Design
BCM989501RD	5-port BR + 1-port GE - 89501 Ref. Design
BCM956018K48T	48-port FE + 2-port GE + 2-port HGL(CAT 7) - 56018 SVK
BCM956024K24T	24-port FE + 4-port HGL(CAT 7) - 56024 SVK
BCM956102R48XS	48-port FE + 4 port GE 56102 SW Ref Design w/2-HiGig/10GE
BCM956112R48XS-02	48-port FE + 4 port GE 56112 SW Ref Design w/2-HiGig/10GE - PPC8245
BCM956132K	24-port FE 56132 SW SVK Design w/ two 10GE/HiGig2 and two 1G/2.5Gb Uplink Ports
BCM956214R26T	26-port GE (2 TX/SX) + 2-port HGL(CAT 7) - 56214 Reference Design
BCM956219K50T	50-port GE + 2-port HGL(CAT 7) - 56218 - PPC8245 SVK
BCM956218K50T	50-port GE + 2-port HGL(CAT 7) - 56218 System Verification Kit
BCM956224K24T	24-port GE + 4-port HGL(CAT 7) - 56224 SVK
BCM956224R24F	24-port GE + 4-port GE SFP - BCM56224 Reference board.
BCM956300R24	24-port GE 56300 Switch Ref Design
BCM956304R24XS	24-port GE (2 TX/SX) 56304 SW Ref Des w/2-HiGig + 2-10GE
BCM956314R24ST	24-port GE + 4 HiGig/2.5GE(CAT 7) 56314 Ref Design
BCM956314R24XST	24-port GE + 4 10GE/HiGig/2.5GE(CX4) - 56314 Ref Design
BCM956334K_02/BCM956334K_03	24xGE + 4x10G/13HG (iPass) with BCM56334 switch
BCM956500R24	24-port GE 56500 Switch Ref Design
BCM956504R24XS	24-port GE (2 TX/SX) 56504 SW Ref Des w/2-HiGig + 2-10GE
BCM956504R48XSP	48-port GE (12 w/POE) 56504 Switch Ref Design 4 - HiGig/10GE
BCM95650K24	24-port FE + 4 port GE Switch Development Kit
BCM95650R24	24-port FE + 4 port GE (TX or SFP) Reference Design
BCM956514R24XST	24-port GE + 4 10GE/HiGig/2.5GE(CX4) - 56514 Ref Design
BCM956514R48XSP	48-port GE (12 w/POE) 56514 Switch Ref Design 4 - HiGig/10GE
BCM956580K16TXS	16-port 2.5G SFP Fibre + 4 HiGig/10GE 56580 SDK
BCM956601K12D	12-port GE + 1-HiGig 56601 DDR SDRAM SDK
BCM956601K12N	12-port GE + 1-HiGig 56601 Netlogic TCAM SDK
BCM956602KXSN	1-HiGig + 1-10GE 56602 Netlogic TCAM SDK
BCM95665K48	48-port FE + 4 port GE TX/SX + 1HiGig Switch Development Kit
BCM956700K16S	16-port HiGig CX4 56700 SDK



Table 72: Reference Designs

Platform	Description
BCM95670K8	8-port 5670 GE Switch Development Kit
BCM95673K2S	2 x 5673 10-GE + HiGig Switch Development Kit
BCM95673R8	8-port 5673 10 GE XFP Switch Reference Design
BCM95673R8CX4	8-port 5673 10 GE CX4 Switch Reference Design
BCM95675K8	8-port 5675 GE Switch Development Kit
BCM95675K8U	8-port 5675 GE Switch Development Kit - PPC8245
BCM956800K20X	20-port 10 GE CX4 56800 SDK
BCM95690K24S	24-port 5690 GE Switch Development Kit w/2HiGig
BCM95690K24	24-port 5690 GE Switch Development Kit
BCM95690P24REF	24-port 5690 GE + 5671 w/2HiGig Ports Reference Design
BCM95690R24	24-port 5690 GE Ports Reference Design
BCM95690R24S	24-port 5690 GE + 5671 w/2HiGig Ports Reference Design
BCM95690R48S	48-port 5690 GE + 5670 w/4HiGig Ports Reference Design
BCM95690R48X2S	48-port 5690 GE + 5670 w/2-HiGig Ports + 2-10-GE Ports Ref. Design
BCM95691K12	12-port 5691 GE Switch Development Kit
BCM95695K24	24-port 5695 GE Switch Development Kit
BCM95695R24S	24-port 5695 GE + 5671 w/2HiGig Ports Reference Design
BCM95695R24X2S	24-port 5695 GE + 2-port 5675 HiGig + 2-port 5674 10GE CX4
BCM95695R48X2S	48-port 5695 GE + 5670 w/2-HiGig Ports + 2-10-GE Ports Ref. Design
BCM91125CFM16	BCM956010CS Dual 5675 Fabric + 1125H CPU
BCM91125CFM8	BCM956006CS Single 5675 Fabric + 1125H CPU
BCM956501LM	12-port 10GE CX4 56501/5675 Line Module
BCM956504LM	48-port GE 56504 Line Module
BCM956700CFM16	16-HiGig 56700 Fabric + BCM1125 CPU Module
BCM95674LM	6-port 10GE CX4 5674/5675 Line Module
BCM956802LM	12-port 10GE CX4 56802 Line Module
BCM95695LM	48-port GE 5695/5675 Line Module
BCM956802CFM8	BCM956006CS 56802 Fabric + 8 10GE + 1125H CPU
BCM956680K24TS_02/BCM956680K24TS_05	25 port 1-GbE/2.5GbE Multilayer Ethernet Switch with 4 x 10-GbE/HiGig2 Uplink ports SVK
BCM956624K49TS_02/ BCM956624K49TS_05	49 port 1-GbE Multilayer Ethernet Switch with 4 x 10-GbE/HiGig2 Uplink ports and External Table Expansion SVK
BCM956624R49S_02	49 port 1-GbE Multilayer Ethernet Switch with 4 x 10-GbE SFP+ Uplink ports BCM56624 reference board
BCM956634K49S_02	49xGE + 4 x XAUI/HG (iPass) with BCM56634 switch
BCM956636K25S_02	24x1GE + 2x12HG + 4x16HG (iPass) with BCM56636 switch
BCM956638K8XS_02	4x12HG + 4x16HG (iPass) with BCM56638 switch
BCM956639K25S_02	24x1GE + 8x10G (iPass) with BCM56639 switch
BCM956526K29S_02	28x1GE + 6x12HG (iPass) with BCM56526 switch
BCM956685K24TS_02	24 port 1-GbE/2.5GbE Multilayer Ethernet Switch with 4 x 10-GbE/HiGig2 Uplink ports SVK
BCM956820K24XG_02/BCM956820K24XG_05	24 x 10-GbE + 4 x 1-GbE Multilayer Ethernet Switch SVK
BCM956820R24XG_02	24 x 10-GbE + 4 x 1-GbE BCM56820 Multilayer Ethernet Switch Reference board with SFP+ interface.
BCM956825K24XG_02	16 x 10-GbE + 8 x 20-Gbps HG2 + 1 x 1-GbE Multilayer Ethernet Switch Reference board.
BCM956720K16S_02/BCM956720K16S_05	16-Port, 256-Gbps Switch Fabric + 4 x 1-GbE SVK
BCM956725K16S_02/BCM956725K16S_05	8-Port (20Gbps) + 4-port (16Gbps) Switch Fabric + 4 x 1-GbE SVK
BCM988020QSK24X2	Carrier Ethernet 24-port GE + 2-port 10GbE Reference Design (also known as Metrocore)
BCM988130FK24X2	Carrier Ethernet 24-port GE + 2-port 10GbE Reference Design (also known as Polaris Line card)

Table 72: Reference Designs

Platform	Description
BCM988025QSK24X2	Carrier Ethernet 24-port GE + 2-port 10GbE Reference Design (also known as C2 SVK)
BCM988130K_02	BCM88130 SVK with 96 fabric serdes connections (24 iPass ports)
BCM988235K_02	BCM88235 SVK with 4 HiGig2 ports (4 iPass), 2 flow control ports (2 iPass)
BCM953724R26WS	26-Port, 26-Gbps Integrated Multilayer Switch and CPU
BCM956628K8TS	8 port 10-GbE/HiGig2 Multilayer Ethernet Switch with External Table Expansion
BCM956620K24TS	24 port 1-GbE Multilayer Ethernet Switch with 4 x 10-GbE/HiGig2 Uplink ports
BCM956684K24TS	24 port 1-GbE/2.5GbE Multilayer Ethernet Switch with 4 x 10-GbE/HiGig2 Uplink ports
BCM956725K16S	8 Port, 20-Gbps + 4 Port, 16-Gbps HiGig2 Switch Fabric
BCM956626K8TS	25 port 1-GbE Multilayer Ethernet Switch with 6 x 10-GbE/HiGig2 Uplink ports and External Table Expansion
BCM956629K24S	25 port 1-GbE Multilayer Ethernet Switch with 8 x 10-GbE/HiGig2 Uplink ports and External Table Expansion
BCM956224R50T	50-port GE + 2-port HGL(CAT 7) - 2 X BCM56224
BCM956024R50T	48-port FE + 2-port GE + 2-port HGL(CAT 7) - 2 X BCM56024
BCM956524K24S_02	24xGE + 4 x XAUI/HG (iPass) with BCM56524 switch
BCM956521K_02	24-Port GbE Multilayer Switch with 10 GbE/HiGig2 Uplink Ports
BCM956740K_02	480/640 Gbps Switch fabric
BCM956743K_02	480/640 Gbps Switch fabric
BCM956840K_02	320/480/640 Gbps Ethernet Multilayer Switch
BCM956845K_02	320/480/640 Gbps Ethernet Multilayer Switch
BCM956846KQ	320/480/640 Gbps Ethernet Multilayer Switch
BCM98727MC	16 port iPass to SFP+ Media Converter
BCM956534K24TS	24xGE + 4 x XAUI/HG (iPass) with BCM56534 switch
BCM956538K49S	48-Port GbE Multilayer Switch with Four 10-GbE/HiGig2 Uplink Ports SVK
BCM956640K_02	BCM56640 SVK
BCM956643K_02	BCM56643 SVK
BCM956644K_02	BCM56644 SVK
BCM9NEGEV	Two BCM988640TMM line cards (3x10Gb SFP+ phys, 6x20Gb QSFPs) + FE600 switch fabric.
BCM9NEGEVII	BCM988750FEM fabric card
BCM956850K	1.2Gbps Ethernet Multilayer Switch

Note: The flash sizes of some old BCM53XX platforms are 4 MBytes only. As the code size of SDK increases, the 4 MB flash is not enough for this release. Replace the flash to 8 MB or above for those reference designs.

Section 11: SDK Externally Licensed Software Components

SDK contains a number of third-party externally licensed software components. This appendix contains information regarding these components, the license for each of these components, and where these components are used in SDK.

Table 73: EXTERNALLY LICENSED SOFTWARE COMPONENTS

Component	Origin	Location in source tree	License terms and conditions
EDITLINE	/afs/athena.mit.edu/contrib/sipb/src/editline	src/sal/appl/editline	See (EDITLINE License terms and conditions) (page 141)
ED Editor	USENET comp.sources.misc Volume 9, Issue 36	src/appl/diag/edline.c	See (ED Editor License terms and conditions) (page 143)
CINT	http://www.gnu.org/software/bison/	src/appl/cint/cint_parser.[ch]	See (CINT parser license terms and conditions) (page 144)
CES Driver	BATM Advanced Communications Ltd	src/soc/ces/nemo_driver/*. [ch], src/soc/ces/clsbuilder/*. [ch]	See (Circuit Emulation Service (CES) Driver terms and conditions) (page 145)
BIGDIGITS	David Ireland, copyright (c) 2001-11 by D.I. Management Services Pty Limited < www.di-mgt.com.au >	src/soc/dpp/SAND/Utils/sand_u64.c	See (BIGDIGITS license terms and conditions) (page 146)
APIMODE	http://www.gnu.org/software/bison/	src/appl/diag/api/api_grammar.tab.[ch]	See (APIMODE parser license terms and conditions) (page 147)
VxWorks	Wind River Systems, Inc.	systems/vxworks	See (Wind River Systems license terms and conditions) (page 148)

EDITLINE LICENSE TERMS AND CONDITIONS

This package was obtained from the following location, and was modified for purposes of inclusion into the SOC diagnostics shell.

Removed files:

MANIFEST Make.os9 Makefile os9.h sysos9.c testit.c unix.h

Added files:

sysvxworks.c Makefile

Changed functionality:

Merged unix.h into editline.h

M-P and M-N now behave like tcsh.

list_history(count) routine displays history

Commented out completion

Changed rl_complete and rl_list_possib into caller-settable global functions

Don't ring bell on TAB if word is already complete

Index of /afs/athena.mit.edu/contrib/sipb/src/editline

[]	Name	Last modified	Size	Description

[DIR]	Parent Directory	11-May-99 03:40	-	
[]	MANIFEST	07-Jul-97 11:20	1k	
[]	Make.os9	07-Jul-97 11:20	1k	
[]	Makefile	01-Sep-97 00:34	2k	
[]	complete.c	07-Jul-97 11:20	4k	
[]	editline.3	07-Jul-97 11:20	5k	
[]	editline.c	07-Jul-97 11:20	25k	
[]	editline.h	07-Jul-97 11:20	2k	
[]	os9.h	07-Jul-97 11:20	1k	
[]	sysos9.c	07-Jul-97 11:20	1k	
[]	sysunix.c	07-Jul-97 11:20	3k	
[]	testit.c	07-Jul-97 11:20	1k	
[]	unix.h	07-Jul-97 11:20	1k	

\$Revision: 1.7 \$

This is a line-editing library. It can be linked into almost any program to provide command-line editing and recall.

It is call-compatible with the FSF readline library, but it is a fraction of the size (and offers fewer features). It does not use standard I/O. It is distributed under a "C News-like" copyright.

Configuration is done in the Makefile. Type "make testit" to get

a small slow shell for testing.

This contains some changes since the posting to comp.sources.misc:

- Bugfix for completion on absolute pathnames.
- Better handling of M-n versus showing raw 8bit chars.
- Better signal handling.
- Now supports termios/termio/sgttyb ioctl's.
- Add M-m command to toggle how 8bit data is displayed.

The following changes, made since the last public release, come from J.G. Vons <vons@cesar.crbcal.sinet.slb.com>:

- History-searching no longer redraws the line wrong
- Added ESC-ESC as synonym for ESC-?
- SIGQUIT (normally ^) now sends a signal, not indicating EOF.
- Fixed some typo's and unclear wording in the manpage.
- Fixed completion when all entries shared a common prefix.
- Fixed some meta-char line-redrawing bugs.

Enjoy,

Rich \$alz
<rsalz@osf.org>

Copyright 1992,1993 Simmule Turner and Rich Salz. All rights reserved.

This software is not subject to any license of the American Telephone and Telegraph Company or of the Regents of the University of California.

Permission is granted to anyone to use this software for any purpose on any computer system, and to alter it and redistribute it freely, subject to the following restrictions:

1. The authors are not responsible for the consequences of use of this software, no matter how awful, even if they arise from flaws in it.
2. The origin of this software must not be misrepresented, either by explicit claim or by omission. Since few users ever read sources, credits must appear in the documentation.
3. Altered versions must be plainly marked as such, and must not be misrepresented as being the original software. Since few users ever read sources, credits must appear in the documentation.
4. This notice may not be removed or altered.

ED EDITOR LICENSE TERMS AND CONDITIONS

ed - standard editor
^^

Authors: Brian Beattie, Kees Bot, and others

Copyright 1987 Brian Beattie Rights Reserved.

Permission to copy or distribute granted under the following conditions:

- 1). No charge may be made other than reasonable charges for reproduction.
- 2). This notice must remain intact.
- 3). No further restrictions may be added.

- - - - -
TurboC mods and cleanup 8/17/88 RAMontante.
Further information (posting headers, etc.) at end of file.
- - - - -

Modification log:

25Aug92 (W.Metzenthen) Changed malloc() call to calloc() in makebitmap()
to remove bugs under Linux. Changed a few '^' to the correct '~'.
General tidying. Recognize Linux via the __linux__ symbol.
Main change based upon suggestion by Wolfgang Thiel.
07Sep99 Changed large amounts of stuff to simplify --Curt McDowell

CINT PARSER LICENSE TERMS AND CONDITIONS

The C code for the CINT parser was generated by using GNU Bison parser generator from the file `cint_grammar.y`. CINT is an optional diagnostic tool that can be included in your system by adding CINT to the `FEATURE_LIST` in SDK compilation flags.

Removed files:

None

Added files:

None

Changed functionality:

None

```
-----
/* A Bison parser, made by GNU Bison 2.4.1.  */

/* Skeleton implementation for Bison's Yacc-like parsers in C

   Copyright (C) 1984, 1989, 1990, 2000, 2001, 2002, 2003, 2004, 2005, 2006
   Free Software Foundation, Inc.

   This program is free software: you can redistribute it and/or modify
   it under the terms of the GNU General Public License as published by
   the Free Software Foundation, either version 3 of the License, or
   (at your option) any later version.

   This program is distributed in the hope that it will be useful,
   but WITHOUT ANY WARRANTY; without even the implied warranty of
   MERCHANTABILITY or FITNESS FOR A PARTICULAR PURPOSE. See the
   GNU General Public License for more details.

   You should have received a copy of the GNU General Public License
   along with this program. If not, see <http://www.gnu.org/licenses/>.  */

/* As a special exception, you may create a larger work that contains
   part or all of the Bison parser skeleton and distribute that work
   under terms of your choice, so long as that work isn't itself a
   parser generator using the skeleton or a modified version thereof
   as a parser skeleton. Alternatively, if you modify or redistribute
   the parser skeleton itself, you may (at your option) remove this
   special exception, which will cause the skeleton and the resulting
   Bison output files to be licensed under the GNU General Public
   License without this special exception.

   This special exception was added by the Free Software Foundation in
   version 2.2 of Bison.  */

/* C LALR(1) parser skeleton written by Richard Stallman, by
   simplifying the original so-called "semantic" parser.  */
```



CIRCUIT EMULATION SERVICE (CES) DRIVER TERMS AND CONDITIONS

The Circuit Emulation Services (CES) driver code provided herewith is provided by BATM Advanced Communications Ltd (BATM) and is subject to licensing agreement between BATM and Broadcom Corporation.

BIGDIGITS LICENSE TERMS AND CONDITIONS

Contains BIGDIGITS multiple-precision arithmetic code originally written by David Ireland, copyright (c) 2001-11 by D.I. Management Services Pty Limited <www.di-mgt.com.au>, and is used with permission.

David Ireland and DI Management Services Pty Limited make no representations concerning either the merchantability of this software or the suitability of this software for any particular purpose. It is provided "as is" without express or implied warranty of any kind. Our liability will be limited exclusively to the refund of the money you paid us for the software, namely nothing. By using the software you expressly agree to such a waiver. If you do not agree to the terms, do not use the software.

APIMODE PARSER LICENSE TERMS AND CONDITIONS

The C code for the APIMODE parser was generated by using GNU Bison parser generator from the file `api_grammar.y`. APIMODE is an optional diagnostics shell interface that can be included in your system by adding APIMDOE to the `FEATURE_LIST` in SDK compilation flags.

See (CINT parser license terms and conditions) ([page 144](#)) for the Bison licence.

WIND RIVER SYSTEMS LICENSE TERMS AND CONDITIONS

See `WRS_LICENSE.pdf` contained in each `systems/vxworks` subdirectory.

Section 12: Resolved Issues for 6.3.3

The following issues are resolved in version 6.3.3 of the SDK.

Table 74:

Number	CSP #	Chips	Release Notes For 6.3.3
SDK-31403	354011	56643_A0	<p>ISSUE: The BCM API's doesn't support programming of KNOWN_MCAST_BLOCK_MASK table/register for port flooding.</p> <p>File name: include/bcm/port.h</p> <p>MACRO already available: /* Flood blocking modes. */ #define BCM_PORT_FLOOD_BLOCK_BCAST 0x1 #define BCM_PORT_FLOOD_BLOCK_UNKNOWN_UCAST 0x2 #define BCM_PORT_FLOOD_BLOCK_UNKNOWN_MCAST 0x4 #define BCM_PORT_FLOOD_BLOCK_ALL 0x8 #define BCM_PORT_FLOOD_BLOCK_UNKNOWN_IP_MCAST 0x10 #define BCM_PORT_FLOOD_BLOCK_UNKNOWN_NON_IP_MCAST 0x20</p> <p>New MACRO: #define BCM_PORT_FLOOD_BLOCK_KNOWN_MCAST 0x40</p> <p>USABILITY: This MACRO will be used by the client to program the KNOWN_MCAST_BLOCK_MASK table/register.</p> <p>Functions where it used: bcm_esw_port_flood_block_set/ bcm_esw_port_flood_block_get _bcm_port_flood_block_op</p> <p>Based on the flag set by the client the KNOWN_MCAST_BLOCK_MASK table/register will be programmed.</p> <p>CHIPS Having this register: TRX, TRDX, KATANA</p>
SDK-32124	367945	56526_A0 56524_A0 56521_A0	snmplfInErrors now counts oversize packets for both 1G and 10G ports.
SDK-35270	443089	All	Handling of missing error types on L2 address add failures.
SDK-37274		56640_A0 56440_A0 56850_A0	Port and VLAN flex counter can be detached according to the given statistics counter ID.
SDK-38701	640562	56445_A1	When schedule mode is set to BCM_COSQ_WEIGHTED_ROUND_ROBIN the PACKET_MODE_WRR_ACCOUNTING_ENABLE bit is enabled in LLS_PORT_CONFIG.
SDK-41493	557290	56640_A0 56440_A0 56334_A0	Fixed bcm_oam_endpoint_create & bcm_oam_endpoint_get APIs to store and return opcode_flags field.
SDK-42056	566321	56840_A0	Removed temporary code used for AV support.

Table 74:

Number	CSP #	Chips	Release Notes For 6.3.3
SDK-44303		56640_A0	The semaphore lock for L2_USER_ENTRY before the write operation is now appropriately called.
SDK-44726	607522	56846_A0 56845_B0 56843_B0 56841_B0	EUC port support bcmCosqStatDroppedPackets uc traffic.
SDK-44957	592869	56640_A0 56640_A1 56640_B0	Can count PERQ_PKT/PERQ_BYTE correctly.
SDK-44977		56846_A0 56840_A0 56746_A0 56744_A0 56850_A0 56755_A0 56640_B0	Fixed warmboot recovery for 5664x LPM on external TCAM
SDK-45248	616287	88030_A0	The status of individual interlaken lanes are shown as part of the "port" diag command. User doesnt have to decode lane status from register data.
SDK-45272		88750_A0	Implement a SW workaround for the following Errata, affecting multistage systems only: when a local link state (on the FE1600 device) is changed from up to down, and then a remote FAP is connectivity-wise gone, the all-reachable vector will include only the links which are locally gone, causing all multicast traffic to be dropped. The workaround is implemented as a corrective action in the interrupt handling code (application level, {SDK}/src/appl).
SDK-45358	616935	5389_A0	Fixed the issue that some enums of register/field/memory were not properly wrapped with the INDEX() macro for Robo SDK.
SDK-45857	620172	88650_A0 88650_B0 88650_B1	Added support for unicast trill with transit ECMP, and a cint example:trill_uni_with_transit_e cmp
SDK-46170	620208	88650_A0	Fixed "version" command does not give a list of DUNE chips supported
SDK-46248		88660_A0	In BCM88660, the Stateful Load balancing feature (aka Consistent Hashing) is implemented
SDK-46640		5396_A0	Add back bcm5396 support in sdk release.
SDK-47045	640610	88650_A0	VLAN translation: Fixed bcm_vlan_translate_egress_action _get() returning incorrect information for TPID action. Return TPID action none instead of modify on several egress actions.
SDK-47432		88650_A0 88650_B0 88650_B1 88660_A0	VSWITCH: bcm_vswitch_destroy_all should delete all vswitch configurations. This includes VSI instances that were marked as vswitch VSI when created using bcm_vswitch_create & bcm_vswitch_create_with_id, as well as VSI disassociation of the gports that were previously added to those VSIs using bcm_vswitch_port_add. The API function performed the gport association from the relevant VSIs, but didn't delete the VSIs. The fix added VSI removal after the gport disassociation for all the relevant VSIs.
SDK-47484 SDK-41472		56640_B0 56644_B0	Fixed warmboot recovery for 5664x LPM on external TCAM
SDK-47596	648378	All	Modified the code to fix the silent failure in ERSpan case.

Table 74:

Number	CSP #	Chips	Release Notes For 6.3.3
SDK-48100	631751	56142_A0 56143_A0 56144_A0 56146_A0	set the sw pause override so that pause settings from software take effect when autoconfig is enabled
SDK-48107	663194	56840_A0 56620_B0 56850_A0 56340_A0 56850_A1 56850_A2	Fix bcm_xgs3_l3_egress_create may decrease BCM_XGS3_L3_ENT_REF_CNT incorrectly
SDK-48113	649349	56540_B0	Added check to reject provisioning of Endpoints which are not within range (0-7)
SDK-48241	665503	All 56440_A0 56334_B0 56334_A0 56440_A1 56440_B0	Code fixed and there are no duplicate entries created in EGR_MPLS_VC_AND_SWAP_LABEL table.
SDK-48333		88660_A0	VXLAN: BCM88660 introduces VXLAN encapsulation enhancement: In BCM88650, VXLAN encapsulation is supported by ucode (egress editor program). In BCM88660, VXLAN encapsulation is supported by the regular pipeline using EEDB IP Tunnel VXLAN encapsulation mode. The change is only internal and include removing the egress editor program that build VXLAN tunnel and changing the encapsulation mode field in EEDB IP tunnel format. The change only change internal implementation and does not change the BCM API and BCM calling sequence of the VXLAN application.
SDK-48514	669177	88650_A0 88650_B0	sal_free() asserted corrupt pointer on 2nd warmboot attempt when running with bcmSwitchControlAutoSync
SDK-48546		88650_A0 88650_B0 88650_B1 88660_A0	fixed undesirable "on the fly" Warm boot external storage updates. Warm boot external storage is updated only upon explicit request, by calling to bcm_switch_control_set(unit, bcmSwitchControlSync, 1).
SDK-48767		88650_A0 88650_B0 88650_B1 88660_A0	VLAN translation advanced mode: The API bcm_port_tpid_class_set() defines a tag format value per a combination of TPIDs and priority flag. Untagged packets (tpid1=tpid2=BCM_PORT_TPID_CLASS_TPID_INVALID) can only use tag format '0'. This validation was added to the bcm_port_tpid_class_set() API.
SDK-48780		88650_A0	Added a new compilation flag: BCM_RX_DISABLE When compiled with this flag, BCM_RX module (CPU packets receive) is not available. Compiling with this flag allows to save DMA memory resources, otherwise allocated as part of the driver initialization sequence. Customers that do not want to initialize the RX module should add to their makefile the following: CFGFLAGS += -DBCM_RX_DISABLE

Table 74:

Number	CSP #	Chips	Release Notes For 6.3.3
SDK-48816		88030_A0	<p>"ddrphytune" CLI command was failing when run from the BCM prompt. To work around this issue, it was required to run the "ddrphytune" command twice or running the TR 53 command first and then the "ddrphytune" command to operate properly. This issue has been fixed.</p> <p>The Correct syntax for "ddrphytune" can be obtained by typing "help ddrphytune" on the BCM prompt. Only even set of CI to be tuned has to be given as parameter, and these should be of the format "ciX" where X is the even CI number</p>
SDK-48912	672983	56143_A0 56146_A0	Fixed port bitmap error on BCM5614x device when a port is set to Higi2
SDK-49024	676736	88750_A0	bcm_port_enable_get API return always disabled after WB. Issue is fixed.
SDK-49109	675316	56850_A0 56855_A0 56854_B0 56854_A0 56850_A1 56851P_A1 56851_A1 56850_A2 56851_A2 56851P_A2 56854_A2 56853_A2 56852_A2 56855_A2 56750_A0 56750_A1 56750_A2 56851_A0 56852_A0 56852_A1 56853_A0 56853_A1	Add the support of modify core clock frequency during init through SOC property.
SDK-49232	680330	56850_A0	<p>Added new API for reading the following registers</p> <p>THDI_PORT_LIMIT_STATES THDI_POOL_DROP_STATE THDI_GLOBAL_HDRM_COUNT_PIPEX THDI_GLOBAL_HDRM_COUNT_PIPEY THDI_FLOW_CONTROL_XOFF_STATE</p>
SDK-49238	669211	88650_A0 88650_B0 88650_B1 88660_A0	<p>Egress filter acceptable frame type: The HW supports Egress filtering per each TPID class type as it does at the Ingress. The Egress filtering can be done both at the ERPP and the ETPP, while filtering at the ERPP also requires trap configuration. The Ingress filter configuration is currently available via the bcm_port_tpid_class_set() API by manipulating the BCM_PORT_TPID_CLASS_DISCARD flag per supplied port, TPIDs and Priority tag. Added egress filter configuration with the existing sequence.</p> <p>Important note: Default behavior changed. bcm_port_tpid_class_set() now configures the Egress filtering on top of the existing Ingress filtering. Meaning Egress filtering will apply as well when BCM_PORT_TPID_CLASS_DISCARD is set.</p> <p>An example of use see: cint_egress_acceptable_frame_type.c</p>



Table 74:

Number	CSP #	Chips	Release Notes For 6.3.3
SDK-49240	675673	88650_A0 88650_B0 88650_B1	VLAN translation: bcm_vlan_port_egress_default_act ion_set doesn't allocate new out ac and doesn't assign correct AC per port when it is called on the second time. Second time will assign it to Out-AC 0. Issue is fixed. User can call twice to API with no AC allocation issues.
SDK-49358		88030_A0	Fixed a segfault in counter thread during fast reconfig for 88030.
SDK-49370	682076	56450_A0	Added support to create l3 egress object for 'LinkPHY/3rd Vlan SubportPktTag' subport gport
SDK-49373	681189	88650_B1	In IP TCAM, Field Processor, or any TCAM-based Database, the entry insertion performance has been significantly improved for a large number of entries. This required modifying all the TCAM data structures for better performance. No feature has been added / changed. ISSUE: Due to this major change, TCAM entries cannot be retrieved from 6.3.2 after ISSU. The user must delete first all its TCAM entries, de-init init the system, and then re-insert them after the system initialization.
SDK-49407	681991	56850_A0	Issue1 and issue2 specified are now fixed.
SDK-49447		88650_A0	MPLS FRR: FRR (Fast Reroute) is supported in BCM SDK. See cint_mpls_lsr.c for utility functions.
SDK-49449		56450_A0	Used offset based mechanism per chip-id and cfg range will be available for each chip
SDK-49593		88650_A0	PON: When the custom_pon_enable is set, the PON ISEM classification scheme is different: Double tag is in ISEM_B, Single-tag/Untag is in ISEM_A TLS is part of TCAM database.
SDK-49610	685129	56850_A0 56850_A1 56850_A2	Changes to allow CPU ports to be added as part of multicast groups, on Trident2.
SDK-49645		88030_A0	Fixed a memory leak during fast reset of 88030.
SDK-49658	681216	All	Support application managed vp group vlan membership
SDK-49675	685913	88030_A0	To share taps tables for multiple c3 units, Two things need to be configured: 1. Add host_memory_table_share.<unit>=1 in config.bcm. It points out which unit would share the same LPM tables. 2. Add host_share_table=1 in g3p1_tmu_cfg.lrp. It means which taps table is shared. The default value is 0, it means this table isn't shared.

Table 74:

Number	CSP #	Chips	Release Notes For 6.3.3
SDK-49717	686082	56850_A0 56850_A1 56850_A2	Added support for two new field qualifiers(bcmFieldQualifySrcVxlanGport and bcmFieldQualifyDstVxlanGport) to qualify VXLAN source and destination gport. So following four new API are opened up bcm_esw_field_qualify_SrcVxlanGport bcm_esw_field_qualify_DstVxlanGport bcm_esw_field_qualify_SrcVxlanGport_get bcm_esw_field_qualify_DstVxlanGport_get
SDK-49757		56450_A0	Made PG7 for lane0 ports and 30,33,36,39 ports and PG0 for remaining ports
SDK-49761	684785	All 56850_A0 56850_A1 56850_A2	Added code support to allow each service pool to be configured separately in device level and port level
SDK-49776		88660_A0	VRRP ARAD+: flexible VRRP capabilities. Feature 1# VRRP is not supported using CAM table that match MAC address against 8 possible MAC addresses. One use of it is for VRRP application which is supported in the same sequence as ARAD. In ARAD+: 1. VRID range can be 0-255 (with limitation of only 8 VRIDs are supported) 2. IPV6 distinct is supported also when l3_vrrp_max_vid = 4096. Important note: Default behavior of VRRP in ARAD+ has changed. l3_vrrp_max_vid 4K/2K/1K/512 are now implemented the same way using the CAM table. Meaning, max_vid 2K/1K/512 can also support 4K range of VIDs. Feature 2# VRRP flexiable HW implementation provide the ability of having up to 8 non-VRRP L2 termination address. To enable the feature call: l3_multiple_mymac_termination_enable = 1 l3_multiple_mymac_termination_mode = 0/1 /* 0 - don't distinct between L3 protocols , 1 - distinct between IPV4 and other L3 packets */ Note: To use the feature soc properties: l3_vrrp_ipv6_distinct and l3_vrrp_max_vid must be set to 0.



Table 74:

Number	CSP #	Chips	Release Notes For 6.3.3
SDK-49793	687002	88650_A0 88650_B0 88650_B1	<p>Trunk support in PP APIs: When calling PP APIs with port being trunk gport: * set APIs should set the same information on all PP ports that are members of the trunk group on the specific unit. * get APIs should retrieve the information from one of the PP ports member (no matter which).</p> <p>On many APIs, implementation used macro DPP_PBMP_TO_SINGLE_PORT_GET to retrieve one member of the trunk group instead of DPP_PBMP_SINGLE_PORT_GET. This caused failure on get APIs when port parameter is trunk group with at least two members.</p> <p>Here are the list of APIs that are fixed and now can support also trunk group with at least two members:</p> <pre>bcm_qos_port_map_get, bcm_stg_stp_get, bcm_vlan_gport_*, bcm_vlan_stp_get, bcm_vlan_port_default_action_*, bcm_vlan_port_protocol_action_*, bcm_vlan_translate_action_*, bcm_port_control_set/get, bcm_auth_mode_*, bcm_port_tpid_class_*</pre>
SDK-49807		88660_A0	A new flag has been introduced (bcmOamActionSlmEnable) in order to support synthetic loss measurement on Arad+
SDK-49828	688539	88030_A0	fix race condition for tmu fifo manager on bcm88030
SDK-49867	688614	88650_A0	<p>When using External TCAM for forwarding or ACLs (External Lookup), the user can from now on cache configured external lookup entries and commit them in a batch. 1. Set ELK caching mode by calling bcm_switch_control_set with control type bcmSwitchFieldCache (arg 1 - enabled, arg 0 - disabled. default:0). 2. Define all the entries via FP APIs (ACLs) or forwarding APIs (e.g. IP APIs). These entries are saved in the SW. 3. Commit all these configured cached entries via bcm_switch_control_set with control type bcmSwitchFieldCommit.</p>
SDK-49890	682698	88030_A0	support TCAM prbs command for bcm88030
SDK-49891	676355	All	"diag cosqprint_flow_and_up" FC counter value will always be zero even there is FC on the port. The issue is fixed.
SDK-49913	688017	All	Fixed KNET IOCTL interface for proper alignment on a 64-bit Linux kernel with a 32-bit user mode application.
SDK-49920	666273	88650_A0 88640_A0	Port TPID: bcm_port_inner_tpid_get should return the inner tpid of port. On some cases of port tpid settings (when soc property is bcm886xx_vlan_translate_mode=0) inner tpid did not return the correct value. The issue is now fixed.
SDK-49922	672561	88640_A0	<pre>petra_mgmt_all_ctrl_cells_enable_get()</pre> API looks at mesh_topology.mesh_topology_reg.trig instead of rtp.rtp_enable_reg.rtp_up_en.



Table 74:

Number	CSP #	Chips	Release Notes For 6.3.3
SDK-49959		88030_A0	improve the OCM memory allocation debug dump for 88030
SDK-49979	687189	56640_A1 56643_A1 56643_B0	With this fix, external ACL can successfully filter MLPS terminated packets with assigned SVP, on TR3
SDK-50009	688266	56640_A0 56640_A1 56640_B0	Added a new L2 flag to configure REMOTE bit in L2 table.
SDK-50017		56850_A1 56850_A2 56850_A0	Updated documentation for two new field qualifiers and four new API's bcmFieldQualifySrcVxlanGport bcmFieldQualifyDstVxlanGport bcm_esw_field_qualify_SrcVxlanGport bcm_esw_field_qualify_DstVxlanGport bcm_esw_field_qualify_SrcVxlanGport_get bcm_esw_field_qualify_DstVxlanGport_get
SDK-50019		56850_A1 56850_A2 56850_A0	Added support for two new field qualifiers(bcmFieldQualifySrcVxlanGport and bcmFieldQualifyDstVxlanGport) to qualify VXLAN source and destination gport. So following four new API are opened up bcm_esw_field_qualify_SrcVxlanGport bcm_esw_field_qualify_DstVxlanGport bcm_esw_field_qualify_SrcVxlanGport_get bcm_esw_field_qualify_DstVxlanGport_get
SDK-50039		88650_A0	PON: For In-AC-LIF matching, PON priority tag packets are matched same as untagged packets.
SDK-50068	690957	56640_A0 56643_A0	Added the following missing switch controls in bcm_esw_switch_control_port_get for TR3 bcmSwitchHashFCOEFld0, bcmSwitchHashFCOEFld1, bcmSwitchHashL2TrillFld0, bcmSwitchHashL2TrillFld1, bcmSwitchHashL3TrillFld0, bcmSwitchHashL3TrillFld1, bcmSwitchHashTrillTunnelFld0, bcmSwitchHashTrillTunnelFld1
SDK-50073		56340_A0	Enabled MSI Function Page in EP mode, for CMICd devices.
SDK-50097	692006	56450_A0	Enabled missing true egress mirroring support for KT2
SDK-50127	692117	88650_A0	STG: Several STG APIs do not recognize STG-ID 64 as a valid value, caused several APIs to fail.

Table 74:

Number	CSP #	Chips	Release Notes For 6.3.3
SDK-50132	692195	56450_A0	<p>1. The config variables 'pbmp_subport' is now used to indicated which ports will be allowed for CoE configuration at run time. 2. The config variable 'num_subports' is used for reserving the CoE subports at init time. Maximum of 128 subports can be reserved. 3. To switch between a CoE<->non-CoE at run time, use the API <code>bcm_port_control_set(unit, port, bcmPortControlSubportTagEnable, <enable>)</code>. Note: Customer application will need to delete the ETS tree and cleanup the added subports, if any, before converting from CoE-to->non-CoE at run time. 4. For performing flex-IO operation on a block, the customer application need to first disable CoE on all ports in the block.</p> <p>For example: <code>pbmp_subport=0x2222</code> <code>num_subports=12</code></p> <p>This will reserve 48 subports, 12 each for physical port numbers 1,5,9,13. This also indicates that only ports (1,5,9,13) can be converted from non-CoE<->CoE port at run time.</p>
SDK-50158	686085	56850_A0 56850_A1	EFP entries will create with right <code>key_match_type</code> for the given set of qualifiers qualified in an entry.
SDK-50161 SDK-51336	692857	All	Added missing multicast types in <code>cmd_multicast_parse_type</code> array. Also updated the code to handle the missing types in future.
SDK-50163	680158	88030_A0	Caladan3 can work with Interlaken interfaces running at 12.5G. To set this configuration the SWS and ILKN core clock needs to be increased. With this setup, The ILKN will have at the max 11 lanes and meet the 100G duplex speed.
SDK-50223	687869	88650_A0 88650_B0 88650_B1	Port-Protocol VLAN assignment: When having more than one profile and calling multiple same-port but different ethertypes <code>bcm_vlan_port_protocol_action</code> APIs disable settings on other ports. Fixed the management of profiles in API to resolve the case.
SDK-50224	676993	All	Compiler warning when building SDK with -O3 fails are corrected
SDK-50245		88650_A0	System PP resources: Added several more examples of encoding of different BCM objects, among which are : VLAN-Port gport (<code>vlan_port_id</code>), MPLS-Port gport (<code>mpls_port_id</code>) and L3 interface objects (RIF, LIF, FEC). This usage is exemplified via utility functions in : <code>cint_system_vswitch_encoding.c</code>
SDK-50273	685449	56850_A0	Fix wrong calculation in <code>min_burst/</code> <code>max_burst</code> of CPU port.
SDK-50302	693871	56850_A0 56850_A1 56850_A2	Resolved deficit round robin scheduling configuration error
SDK-50315	693904	56850_A0 56850_A1 56850_A2	Write ECMP ptr or next hop to <code>L3_ENTRY_IPV4_MULTICASTm</code> for ensuring nh not being lost when hit ingress DNAT entry aging out.
SDK-50325		56450_A0	Accounted for SGMII ports, post 1xXAUI-->4xSGMII flexio operation, for 'priority mapping' and 'outer tpid' related initialization



Table 74:

Number	CSP #	Chips	Release Notes For 6.3.3
SDK-50336	692831	88030_A0	Fixed
SDK-50342		All	Added PCIe Gen2 compliance support.
SDK-50360		88660_A0	In BCM88660, the LAG-Load-Balancing-Key improvements are implemented.
SDK-50393	694977	56850_A0	Supported NIV virtual port for <code>bcm_vlan_translate_egress_action_add()</code> / <code>delete()</code> APIs
SDK-50398	692944	56850_A0	<code>bcm_switch_control_port_set/get()</code> can take GPORT PROXY ports for RTAG7 hash controls
SDK-50414	695716	56450_A0	A new register is added in the pair of dynamic registers which are used during schedule mode change. LLS_SP_WERR_DYN_CHANGE_0A, LLS_SP_WERR_DYN_CHANGE_0B, LLS_SP_WERR_DYN_CHANGE_0C configuring of the LLS_SP_WERR_DYN_CHANGE_0C register was missing out of above set . Modified the code to configure this register.
SDK-50418	694439	88650_A0	Implemented <code>bcmPortControlPFCRefreshTime</code> control. Set to 0 to disable Priority Flow Control refresh, or positive value to enable at the given rate. If enabling at the default rate is desired the control should be set to -1
SDK-50446	684943	56640_A0 56640_A1 56640_B0	Improved some API's performance in cosq module.
SDK-50457	695970	All	Input a key&length, return the payload and the lpm key&length.
SDK-50470		All	Fixed several issues with the Linux KNET kernel module on SMP systems.
SDK-50476		88660_A0	Support in ARAD+ new event types and multiple events interrupt.
SDK-50483 SDK-51208		56850_A0 56850_A1 56850_A2	Added the supported for FCOE data any in UDF module
SDK-50510	696350	56640_A0 56643_A0 56640_A1 56643_A1 56640_B0 56643_B0	The issue about MAC DA lookup in EXT_L2_ENTRY_1 on TR3 is fixed.
SDK-50522		88750_A0	FE2 multistage could not work in a mixed cell format system (VSC256VSC128).
SDK-50531		88650_A0 88650_B0 88650_B1 88660_A0	VLAN Port Assymetric-LIF: <code>bcm_vlan_port_create</code> operation for a symmetrical should fail when LIF was already allocated. Before when calling API with EGRESS_ONLY flag, API didn't return error when LIF was previously created.
SDK-50532		88650_A0 88650_B0 88660_A0	Fix a potential misconfiguration of mirroring destination that is a multicast group.
SDK-50537		88650_A0 88650_B0 88660_A0	PRGE Egress editor new diagnostic: <code>diag prge_last</code> : shows last program selected in the programmable editor <code>diag prge_info</code> : shows all programs loaded in the programmable editor

Table 74:

Number	CSP #	Chips	Release Notes For 6.3.3
SDK-50572		56649_A0 56640_A0 56643_A0 56643_B0 56648_B0 56644_A0 56641_A0 56640_B0 56642_A0 56644_B0 56649_B0 56645_A0 56648_A0 56644_A1 56643_A1 56640_A1	Added a new L2 flag to configure REMOTE bit in L2 table.
SDK-50575	697636	56850_A0	soc_cm_deinit is made external
SDK-50598		88650_A0 88650_B0 88660_A0	Adding ability for the user to set snooping in action_set api.
SDK-50603		88650_A0 88650_B0 88660_A0	Allow oam_endpoint_create() with the flag WITH_ID set and ID > 0x1000.
SDK-50604		88650_A0	FLP & VTT diagnostics: New FLP and VTT diagnostics added to show the last programs invoked in VT , TT and FLP stages. See example by sending packet and calling: BCM.0>diag pp flp last=1
SDK-50606	697917	88650_A0 88650_B0 88650_B1 88660_A0	In Advanced VLAN editing, the TPID configuration is mapped to a tag_format using the API function bcm_port_tpid_class_set(). The API configures HW entries in several Ingress/Egress LLVP tables that has port LLVP profiles that are referred to by the port HW tables. A Port profile holds tag_format and other TPID identification info per a combination of a TPID pair and a priority bit. The handling of the Port profiles included a bug in copying one profile to another as part of updating a port profile or creating a new one. The bug influenced several C-TAG identification fields in the Egress LLVP table as well as S-TAG identification at the Ingress LLVP. This led to wrong packet classifications when handling C-TAGs at the Egress and S-TAGs at the Ingress. Example: 1. Create port classification for an outer C-TAG using bcm_port_tpid_class_set(). 2. Create port classification for an inner C-TAG using bcm_port_tpid_class_set(). 3. The outer C-TAG classification may have wrong C-TAG identification stored in the HW. The fix enables to read the C-TAG identification from an LLVP HW entry (bcm_port_tpid_class_get), thus fixing the copy of the entry to a port profile. It also fixes the flags field value that is returned by bcm_port_tpid_class_get().
SDK-50607		88650_A0 88650_B0 88650_B1	Support MAC move event in PON application has been added. In the case of mac move, the system will report the mac move event including old_ac/new_ac, vsi and mac address. The User can register a callback function by bcm_l2_addr_register() to handle this event. User can also use bcm_switch_event_control_set() to enable/disable this event. See more information in cint_pon_mact_move.c.

Table 74:

Number	CSP #	Chips	Release Notes For 6.3.3
SDK-50608		88660_A0	<p>EEDB formats are now aligned to bcm88660 device.</p> <p>Background: EEDB formats were changed between BCM88650 and BCM88660: Trill EEDB format is now with prefix 0001 instead of 0000 (Format not in use today) AC EEDB format is now with prefix 0000 and sub-prefix 000 instead of prefix 0000 and sub-prefix 00X AC Data EEDB format is now with prefix 0000 and sub-prefix 001 (BCM88660 New format)</p> <p>Issue: EEDB formats were already aligned in SW management but HW change did not apply correctly (for the AC, AC data and trill formats) . In that case AC data and trill couldn't be used correctly.</p> <p>Default behavior change: Modifies default behavior for BCM88660 EEDB AC, AC data and trill formats.</p>
SDK-50623		88650_A0	ARAD_A0 does not support CNM usage and will return error upon enabling attempt
SDK-50644		88660_A0	<p>In Arad+ (BCM88660), the polynom-based hashing functions for ECMP, LAG and Stateful Load Balancing (SLB) are configured only via the following literals: -</p> <p>BCM_HASH_CONFIG_CRC16_0x8003 - BCM_HASH_CONFIG_CRC16_0x8011 - BCM_HASH_CONFIG_CRC16_0x8423 - BCM_HASH_CONFIG_CRC16_0x8101 - BCM_HASH_CONFIG_CRC16_0x84a1 - BCM_HASH_CONFIG_CRC16_0x9019</p>
SDK-50647		56850_A0 56850_A1 56850_A2	<p>If the start index was not 0 then then internal counter to count the number of entries was never incremented.</p> <p>This would not call any user callback as it would think that entry is still not in the range that user asked for.</p> <p>Fixed this scenario by incrementing the counter irrespective of start index and doing some sanity checking on start and end indexes.</p>
SDK-50654	698063	56850_A0	Fix port flush sequence to allow all cells drained properly without seeing timeout on BCM5685x
SDK-50684	697633	All 56640_A0 56850_A0 56150_A0 56640_A1 56640_B0 56850_A1 56850_A2	Fix soc_counter_stop hung in sbusdma operation
SDK-50695		88650_A0	<p>The following Interrupts handling (corrective action) was modified</p> <p>1. Interrupt name: SecIfma(b)foA(B) (FRR). Interrupt description: Overflow of one of the FDR FIFOs (Size bigger than 250, reported in 'FDROverflows And Fifos Statuses FDRASecondary' register) Corrective action: soft reset. 2. Interrupt name: IlknTxPort0(1)StatusErrInt (NBI). Interrupt description: indicates that one of Interlaken Tx errors occurred. The specific error is reported in Tx Ilkn Status register. Corrective action: Soft Reset.</p>

Table 74:

Number	CSP #	Chips	Release Notes For 6.3.3
SDK-50698		88650_A0 88650_B0 88650_B1 88660_A0	VLAN-Port Asymmetric LIF: Asymmetric LIF (one side LIF) can be created using <code>bcm_vlan_port_create</code> and flags (<code>BCM_VLAN_PORT_CREATE_INGRESS_ONLY</code> , <code>BCM_VLAN_PORT_CREATE_EGRESS_ONLY</code>). When calling <code>bcm_vlan_port_destroy</code> with an Asymmetric LIF, API destroyed both sides while it should destroy only the appropriate Ingress/Egress side. Added logic in <code>bcm_vlan_port_destroy</code> to destroy only one side of LIF and not both sides when calling with Asymmetric LIF.
SDK-50737		56640_B0	Correctly writing the wlan tunnel entry without overwriting older entries.
SDK-50743	695226	88650_A0 88650_B0 88650_B1	In Field Processor, the diagnostic "diag field RES" shows and checks the resources used by the Field groups. A verification was erroneous concerning the needed TCAM action size per Field group. This is fixed.
SDK-50761		88660_A0	Add support in api to map oam opcode to internal 0-15 opcode.
SDK-50762		88660_A0	OAMP can trap to different destination with different trap codes. User can edit the code and destination through trap apis, using a special OAMP trap types.
SDK-50786 PHY-1115 SDK-50934		84328_A0 84328_B0	Fastboot support for external PHY BCM84328
SDK-50792	691032	88650_A0	IP Tunnel: <code>bcm_tunnel_initiator_clear</code> returned internal error when destroying valid IP tunnel. Issue is now fixed.
SDK-50794	699750	All 56840_A0 56640_A0 56850_A0 56340_A0 56640_A1 56640_B0 56850_A1 56850_A2	Fix non-blocking wait for <code>l2x_lock</code> in some cases.
SDK-50821		88650_A0 88650_B0 88650_B1 88660_A0	VLAN Port remote LIF creation: Creating a remote LIF is required, when adding a LIF that has to be synced between various units, for all the units for which the LIF isn't local. This allocation scheme is required only <code>bcm88xxx_system_resource_management=0</code> (Global). when In this case only the driver SW should be updated with the LIF allocation as the entity HW isn't local. So far API in case of remote LIF creation configured by mistake the HW and set invalid HW settings that could cause also a failure upon API call. The fix eliminates HW configuration in case of a remote LIF.
SDK-50855	693960	88650_B1	PetraA compatibility support for OLP port programmable editor fix.
SDK-50865	701337	56850_A0	When a prefix group has no entries, it should be deleted. Otherwise it will cause an infinite loop when a new entry with same prefix length is added.
SDK-50868	690830	88650_B1	Fixed <code>bcm_multicast_ingress_get()</code> to properly handle trunk/LAG destinations.

Table 74:

Number	CSP #	Chips	Release Notes For 6.3.3
SDK-50873		56548_A0	Necessary code changes completed, reviewed and checked in. Gsanity completed on both GTO and iProc running Linux and VxWorks for branches Head and 6_3.
SDK-50878	701804	88030_A0	Resolved timing conflict between fast reconfig and statistics collection with CMU.
SDK-50879	699134	56850_A0 56850_A1 56850_A2	Added warmboot support in RX module to recover per Queue PPS, Burst and level pps, burst and max_length parameters
SDK-50885		88650_A0	PON: Support bcm_port_control_set(unit, port, bcmPortControlL2Move, value) on trunk gport.
SDK-50887	699827	88650_A0 88650_B0 88650_B1 88660_A0	bcm_trunk_get used to return invalid member_id for members located in other device. this issue was solved.
SDK-50911	702676	56450_A0	enabled execution of bcm_port_dscp_map_mode_set(unit, virtual_port_gport, mode) for BCM56450 devices to configure SOURCE_VP.trust_dscp_v4/v6.
SDK-50917	668924	56640_A0 56640_A1	Fixed QCN cos issue.
SDK-50923		56146_A0 56150_A0	Correct the register name of Head Of Line blocking drop as HOL_DROP, which is used for the counter snmpIfOutDiscards of Hurricane2/Wolfhound.
SDK-50931	700875	56850_A2	On bcmSim or simulation environment, draining cells (WAR) is not needed as there is no real LLS HW for which WAR needs to be done, so WAR is skipped for simulation environments. Code changes made accordingly.
SDK-50936	703200	56850_A0 56850_A1 56850_A2	I3 ip6route show could not show more than 4096 routes. Updated bcm_xg3_l3_info to allow the show command to expect higher no. of routes for ALPM.
SDK-50939		88650_A0 88650_B0 88650_B1 88660_A0	Fixed the following issues when MAC limit per tunnel is enabled for PON application: 1) Fix the issue that duplicated MACs are reported when traversing MACT. 2) Add a mutex to keep ukernel from multiple access.
SDK-50949	701065	88650_B1	When using the user-header (in cascaded Ingress-Egress ACL, in VMAC, or other), all the packets are appended the User-Header in the fabric. This user-header is removed at egress editor. In a specific case, when sending a non-Ethernet packet to an Ethernet port, the User-header was not removed.

Table 74:

Number	CSP #	Chips	Release Notes For 6.3.3
SDK-50951		88650_A0 88650_B0 88650_B1 88660_A0	<p>PORT MATCH: A port can be matched to a LIF using <code>bcm_port_match_add</code> or during LIF creation. The match can be configured for Ingress or Egress. On the Ingress side, the HW matching table is static and an entry per port always exists.</p> <p>Using <code>bcm_port_match_add</code> to match a port (<code>BCM_PORT_MATCH_PORT</code> in the match field) on the Ingress side, failed due to a validation that ensured that the added matching doesn't already exist in the HW. A validation that is only relevant in case of a VLAN-Port matching that uses a dynamic HW table (match that is different than NONE).</p> <p>The fix removed the matching validation on the Ingress side for <code>BCM_PORT_MATCH_PORT</code></p>
SDK-50968	703823	88650_A0 88650_B0 88650_B1	<p>In External TCAM (ELK), the RPF lookup can be disabled in IPv4 by setting the SOC property <code>ext_ip4_uc_rpf_fwd_table_size</code> to 0 and setting the IPv4 Unicast table size with <code>ext_ip4_fwd_table_size</code> instead. With this method, the IPv4 unicast table can be expanded to all the KBP device (without entry duplication) if all the other tables have a null size.</p>
SDK-50970		88650_A0 88650_B0 88650_B1 88660_A0	<p>VLAN: A user can discard/enable traffic to an Out-LIF using <code>bcm_port_discard_set</code>. The HW for the Out-LIF is set as a result.</p> <p>Important note: The following change the default behavior of Out-LIF creation using <code>bcm_vlan_port_create</code></p> <p>Creating an Out-LIF, with a LIF ID that was previously used and destroyed while the discard indication for the Out-LIF was set, doesn't reset the discard indication in the HW. Thus, by default, in such a scenario, the traffic for the Out-LIF is discarded until set otherwise using <code>bcm_port_discard_set</code>.</p> <p>The fix performs a reset of the discard HW indication upon each LIF creation using <code>bcm_vlan_port_create</code>.</p>
SDK-50976	700368	88650_B1	<p>VXLAN: When going from native to VXLAN, encapsulation header might overwrite incorrectly inner native DMAC. The issue is seen when applying VLAN translation actions with adding more than 1 VLAN tag.</p>
SDK-50977		88650_A0 88650_B0 88650_B1 88660_A0	<p>Improved the code that handles Asymmetric LIFs in order to minimize the Asymmetric LIF dedicated code. No driver behavior implications.</p>
SDK-50978		88650_A0 88650_B0 88650_B1 88660_A0	<p>An asymmetric LIF is a LIF that is defined either only at the Ingress or only at the Egress side. The proper support for SW LIF allocations was introduced in 6.3.2 for VLAN port LIFs.</p> <p>The <code>cint_port_match.c</code> example that shows multiple Ingress/Egress HW mappings to a single LIF ID was modified to support usage and as example of Asymmetric LIFs.</p>
SDK-50995	703503	88650_A0 88650_B0 88660_A0	<p>I3 interface delete was not deleting MTU profile causing crash after many insertions and deletions</p>
SDK-51000		88650_A0	<p>In E2E scheduler TCG, WFQ was always set is invalid. This issue is fixed.</p>



Table 74:

Number	CSP #	Chips	Release Notes For 6.3.3
SDK-51004		88650_A0 88660_A0	cint_mpls_elsp.c is fixed by adding a dependency to it: now it also depends on cint_qos.c.
SDK-51011		88660_A0	Support accelerated LM/DM/IDM.
SDK-51013		88650_A0 88650_B0 88650_B1 88660_A0	When using External TCAM and ACLs (Field Processor APIs), the SW state memory consumption of each external TCAM entry was of ~1K, with a maximum of one million entries. Some external TCAM entries settings such as qualifier values, action values and priority are no longer saved in FP SW state once the entry is installed into the HW. Furthermore, the number of TCAM entries that can be created and not installed is limited via the flag <code>_BCM_DPP_FIELD_NOF_PRE_INSTALL_TCAM_ENTRIES</code> . The default value of this limit is 28K entries (number of possible entries in internal TCAM), but can be freely changed by the user.
SDK-51014		88650_A0 88650_B0 88660_A0	When using External TCAM for ACLs (i.e. Field Processor APIs), a sorting of the external TCAM entries in a linked list was done previously to be defined in the KBP driver. This sorting of external TCAM entries at BCM level according to priority is removed since the KBP driver handles the sorting internally. Removing the sorting of the external TCAM entries reduces the entry insertion complexity at BCM level (strictly) to O(1) instead of O(n).
SDK-51031	702737	56850_A0 56850_A1 56850_A2	Changed the parity type of memories PGW OBM and PGW BOD from <code>_SOC_PARITY_TYPE_GENERIC</code> to <code>_SOC_PARITY_TYPE_ECC</code> as the JIRA description.
SDK-51043	701072	88130_B0 88130_A1	Warmboot sync fix implemented for SBX devices - misaligned write/offset/size was incorrect in fabric configuration.
SDK-51074	705248	56850_A0	The assertion was caused during configuration of ECMP group with mode = <code>BCM_L3_ECMP_DYNAMIC_MODE_RESILIENT</code> . This ECMP group had duplicate members. Resilient hashing feature currently does not support duplicate members in an ECMP group. The fix is to return <code>BCM_E_PARAM</code> error in case the ECMP group have duplicate members.
SDK-51076		88660_A0	Remote fault transmission: In case of link down detection on CAUI port remote fault will be send towards the peer device, till detection of link up. Note: this required Linkscan to be on.
SDK-51077	705804	88650_A0 88650_B0 88650_B1	In External TCAM (KBP), the IPv6 master-key includes the SIP to allow: - RPF lookup - Source-Specific IPv6 MC forwarding lookup This field is part of the master-key by default, and can be removed when disabling the compilation flag <code>ARAD_KBP_IPV6_INSERT_SIP_IN_MASTER_KEY_FOR_VRF</code> .

Table 74:

Number	CSP #	Chips	Release Notes For 6.3.3
SDK-51079	701427	88650_A0	When using External TCAM (KBP), both IP Unicast and Multicast had to be in the same location (internal or external tables). Otherwise, an error was returned since the Multicast RPF may fail. This error is removed to allow the user to decouple the location of the IP Unicast and Multicast tables, when not using the RPF lookup for the Multicast packets.
SDK-51084	701071	56850_A0 56850_A1 56850_A2	Added support for following Field APIs in SDK: bcm_field_qualify_FcoeVersionIsZero bcm_field_qualify_FcoeVersionIsZero_get bcm_field_qualify_FcoeSOF bcm_field_qualify_FcoeSOF_get
SDK-51100	700597	88650_A0 88650_B1	PVLAN: A new port control type called 'bcmPortControlPrivateVlanModeSet' to set PVLAN mode per System-port. Argument = 2/1/0 (0 : community, 1 : isolate, 2 : promiscuous). The port control type value is the same as bcmPortControlPrivateVlanIsolate but introduce also a way to set new mode promiscuous. Important note: Default behavior changed: Calling PVLAN port control with value non 0 has now two meanings: 1 - isolate, 2 - promiscuous. Others are invalid range. Until now non 0 was only isolate.
SDK-51102	703702	88650_A0 88650_B0 88650_B1 88660_A0	Port Flooding: bcm_port_control_set/get bcmPortControlFlood* types returned internal errors on per port information retrieval.
SDK-51111	703092	56846_A0	Added Port Control Support for CPU port on Trident+
SDK-51116		56850_A2	Changes to set/unset SOURCE_TRUNK_MAP.SVP_VALID on BCM_MIM_PORT_MATCH_PORT match criteria for Mim port add/delete, for regular and trunk ports.
SDK-51123	706556	88750_A0	Failure when trying to access sfi ports in Port shell diagnostics was fixed.
SDK-51125		88650_A0 88660_A0	Field Processor: When trying to configure a number of ACL entries that exceeds the max number of ELK entries a segmentation fault is received, due to a wrong allocation size of KBP location table. Allocation size is fixed.
SDK-51137		56640_A0	support for port CE HIGIG and HIGIG2 encapsulation.
SDK-51151 SDK-51277	706694	88660_A0	oam_classifier_advanced_mode soc property in ARAD+ enables switching between ARAD+ classifier mode and ARAD mode (default is 1)
SDK-51158	702539	56640_A0 84756_A0	Phy speed issue has been fixed.
SDK-51172	707302	88650_B1	Fix the judgment error of checking double tag vlan range inside bcm_petra_vlan_translate_action_range_add.
SDK-51173		88660_A0	Add support in new RDI flags and remote flags, configuring different OAMP remote behavior profiles.

Table 74:

Number	CSP #	Chips	Release Notes For 6.3.3
SDK-51177		88660_A0	Stateful Load Balancing (SLB) is now supported in LAG. To enable SLB, the SOC property <code>resilient_hash_enable</code> must be set to 1. To set a LAG group to be stateful, the selection criteria must be set when the <code>bcm_trunk_psc_set</code> or <code>bcm_trunk_set</code> APIs are used, with <code>bcm_trunk_info_t.psc = BCM_TRUNK_PSC_DYNAMIC_RESILIENT</code> .
SDK-51178		88660_A0	Stateful Load Balancing (SLB) is now supported in ECMP. To enable SLB, the SOC property <code>resilient_hash_enable</code> must be set to 1. To use SLB with ECMP, the ECMP group should be created with the <code>bcm_l3_egress_ecmp_create</code> API, and <code>bcm_l3_egress_ecmp_t.dynamic_mode</code> must be set to <code>BCM_L3_ECMP_DYNAMIC_MODE_RESILIENT</code> .
SDK-51193	707727	56850_A0 56850_A1 56850_A2	For flexible mirror destinations, shifted the <code>mtp_index</code> back to original if <code>flex_slot_shift</code> was done prior and also reset <code>hardware_mtp_index</code> to invalid in cases where <code>mtp_index</code> goes out of expected range.
SDK-51196		88650_A0	In IP Multicast, the In-RIF is part of the key. Only 8 bits were copied instead of 12 bits of In-RIF in the TCAM key during the entry insertion. This has been fixed.
SDK-51199	707793	56450_A0	Added fix to account for the SGMII ports, post flexio operation (1xXAUI-->4xSGMII), for configurations done using <code>bcm_vlan_control_set()</code> API. For example 'VLAN translate enable'
SDK-51207	707745	56440_A0 56450_A0	Issue of <code>SVM_OFFSET_TABLE</code> entry 0 not getting initialized during re-init is fixed.
SDK-51280		88650_A0 88650_B0 88650_B1	VLAN translation : User can call <code>bcm_vlan_port_create</code> with match criteria <code>BCM_VLAN_PORT_MATCH_NONE</code> and later add match criteria using <code>bcm_port_match_add</code> . When calling <code>bcm_vlan_port_create</code> with match criteria <code>BCM_VLAN_PORT_MATCH_NONE</code> and then action create/delete without adding valid match criteria using <code>bcm_port_match_add</code> . BCM APIs of <code>bcm_vlan_translate_action_create/delete</code> will return failure. Issue resolved by eliminating the need of retrieving information of match criteria for a given valid LIF ID.

Table 74:

Number	CSP #	Chips	Release Notes For 6.3.3
SDK-51288		88650_A0 88650_B0 88650_B1 88660_A0	Egress CoS: If there is a port configured to work in one-priority mode (single Egress Queue per OTM-port), only one Multicast Service Pool can be used. In other words, if two Service Pools are required to allow MC traffic prioritization in resource allocation, all ports must be configured to work in at least two-priorities mode. If only one Multicast Service Pool is allocated, EGQ buffer resources will be shared between High and Low priority MC. Change description: modified default Arad initialization (<code>bcm_init</code>) so that if 1 priority port exists, all In-TCs will be mapped to SP0 (1st Service Pool). No changes to customer application are required.
SDK-51290		88650_A0 88650_B0 88650_B1 88660_A0	When setting TCTCG shapers to minimum rate, the rate used to be set to 0. It was fixed such that minimum TC/TCG shaper rate changed to be non-zero
SDK-51297		88650_A0 88650_B0 88660_A0	In Field Processor module, an error in the TCAM entry install API inserting an entry into HW may result in a lack of error message and an unexpected behavior due to a wrong error handling. This is fixed.
SDK-51298	702867	88650_A0 88650_B0 88650_B1	In Field Processor module, in the internal function <code>ARAD_PP_FP_QUAL_VAL_verify()</code> , there was a missed overflow consideration for 32 bit systems when checking max value for <code>qual_length</code> . In case of <code>qual_length=32</code> , it may have caused unexpected behavior. A special handling for 32 bit long max value is added.
SDK-51329		56850_A2	On Trident2 the CPU cos which ranges from 0~47, is shown as value=16~63 in EFP logic, basically the H/W adds 16 to the cos value in the key. So in S/W, 16 has to be added to actual data value and adjust the mask accordingly passed by application code.
SDK-51335	708236	56850_A0	Fixed <code>DISABLE_L2_ENTRY_LP</code> setting to properly disable it for both dedicate L2 banks on BCM5685x.
SDK-51341		88660_A0	In TM mode, when scheduling compensation feature is enabled (SOC property <code>scheduler_compensation_enable=1</code>), the user header removal performed by the egress editor is not done correctly and is causing unwanted removal of payload. In this mode, the user header size is included in the internal system header size computation, and the egress editor does not need to remove additional bytes.
SDK-51359	706692	88650_B0 88650_B1 88660_A0	1588 time stamping is enabled only in Arad B0 and above. In order to use 1588 timestamping, <code>endpoint_info.timestamp_format</code> must be set to <code>bcmOAMTimestampFormatIEEE1588v1</code> when calling <code>bcm_oam_endpoint_create()</code> . By default endpoints use the NTP timestamp format. Note that for accelerated DMMs in Arad+ only 1588 time stamping is enabled.

Table 74:

Number	CSP #	Chips	Release Notes For 6.3.3
SDK-51361	709904	56640_A0 56641_A0 56642_A0 56643_A0 56644_A0 56645_A0 56648_A0 56640_A1 56643_A1 56644_A1 56640_B0 56644_B0 56643_B0	Issue is fixed by ignoring rx_nmac_csm_cres_crc_err (0x8292, 0x8293) and crx_idle_crc24_err (0x8185) CRC24 error registers (Erratum).
SDK-51363	708436	56540_A0	Pointer needed to be set as NULL after freeing the same.
SDK-51364		88650_A0 88660_A0	L2GRE: Default behavior change in L2GRE module: Mapping between Local-VSI (VPN) and Global-VSI (VPNID) was changed and is now similar to VXLAN. Instead of doing such mapping in bcm_l2gre_port_add, functional was moved to the proper place in VPN settings (bcm_l2gre_vpn_create). Please see CINT example L2GRE changes in : \$SDK/src/examples/cint_l2gre.c
SDK-51369	707630	88650_A0 88650_B0 88650_B1 88660_A0	VLAN-Port, MPLS-Port: Protection FEC ID value range in Arad is up to 32K. The local/remote status for each protection FEC ID is stored and used by the warm boot. Creating a protected LIF, using bcm_vlan_port_create fails when using a FEC ID value above 8K in the vlan_port_id field and attaching to a protection group by using a valid failover_id field value. The same applies for MPLS protection LIF creation. Valid FEC ID values for non protection applications remain unaffected and can use the whole FEC ID value range. The fix increases the protection local/remote status buffer to the correct size that enables usage of the full FEC ID value range for protection as well.
SDK-51420		56150_A0	Support LED intensity control.
SDK-51422		56150_A0	Support LED intensity control.
SDK-51487	711130	56850_A0	Fixed a bug in TR144 that could cause a crash when run on memories that do not support SER correction.
SDK-51496	711386	56450_A0	1.Enable/Disable MMU CoE support when port CoE status is changed dynamically. 2.For dynamically updating the EPC_LINK_BMAP associated with the port undergoing 'CoE to/from non-CoE' state change, use the following API sequence: bcm_port_enable_set(unit, port, FALSE);bcm_port_control_set(unit, port, bcmPortControlSubportTagEnable, 1 /*1=coE, 0 = non-CoE */); bcm_port_enable_set(unit, port, TRUE);
SDK-51501		56150_A0	Support EEE burst and batch mode for Hurricane2 devices.
SDK-51524	663415	88030_A0	fix counter read under vxworks for bcm88030
SDK-51537	682672	88650_A0 88650_B0 88650_B1 88660_A0	Fixed the MBIST logic of 88650 and 88660. Before the fix, MBIST could fail occasionally. The fix increases the time of the MBIST test by 0.15 seconds.

Table 74:

Number	CSP #	Chips	Release Notes For 6.3.3
SDK-51538		88650_A0 88650_B0 88660_A0	<p>In Field processor, internal software state initialization includes the creation of a TCAM entries free list. The last element of this list was not initialized correctly. This is fixed.</p> <p>Also, when trying to install a configured entry to a full TCAM, an internal uninstalled entries counter was wrongly decremented, even though the install action failed. This may cause unexpected behavior in case a wrap around occurs. This is fixed.</p>
SDK-51576 SDK-51574		56850_A0	During fp mirror destination delete, for flexible mirror destinations, shifted the <code>mtp_index</code> back to original if <code>flex_slot_shift</code> was done prior.
SDK-51582	712323	56850_A0	Implemented Replace support to the Mirror destination create APIs and MTP port Add APIs for ingress and egress mirroring.
SDK-51589		88650_A0 88650_B0	<p>VLAN-Port initial-VID: SOC property <code>vlan_translation_initial_vlan_enable_<port></code> introduced in SDK 6.3.2. User can decide per port to separate SEM databases between Untagged packets and tagged packets. In case SOC property is enable (default behavior), user maintain two databases: <code>PORT_INITIAL_VLAN</code> (untagged packets) and <code>PORT_VLAN</code> (tagged packets). In case SOC property is disable, user maintain one database for both untagged and tagged according to Initial-VID procedure.</p> <p>In case port support <code>bcmVlanPortDoubleLookupEnable</code>, double-tag packets should lookup both <code>MATCH_PORT_VLAN_STACKED</code> database (double-tag database) and one-tag database when packet has two-tags. Lookup of one-tag database was incorrect in case <code>vlan_translation_initial_vlan_enable</code> was set to 0 caused double-tag packets with no match on <code>PORT_VLAN_STACKED</code> database to drop the packet instead of lookup of one-tag database. Issue was in VTT ucode and fixed.</p>
SDK-51591	712663	56450_A0	<p>KT2:Flex-IO code uses 1 (<code>PORT_FLUSH</code>) operation and KT2/cosq performs queue flush (<code>FLUSH_TYPE=0</code>).</p> <p>After flex-io operation, <code>FLUSH_TYPE</code> remained as 1 but cosq function didn't reset it to 0 before initiating queue-flush operation. This field is newly introduced for KT2 device and was not present in KT so it was missed in code. Due to that HW was assuming <code>PORT_FLUSH</code> operation i.s.o. queue flush causing time-out issue</p>
SDK-51598	712590	56850_A0	missing Gport types are added in L2 dump function
SDK-51608		88650_A0 88650_B0 88650_B1	A new port control type 'bcmPortControlPrivateVlanModeSet' is added to set all PVLAN mode, including community, isolate and promiscuous.
SDK-51609		88650_A0 88650_B0 88650_B1	Add 'bcmPortControlPrivateVlanModeSet' to set all PVLAN mode, including community, isolate and promiscuous.

Table 74:

Number	CSP #	Chips	Release Notes For 6.3.3
SDK-51611		56850_A0 56850_A1 56850_A2	A new port control type 'bcmPortControlPrivateVlanModeSet' is added to set all PVLAN modes, including community, isolate and promiscuous.
SDK-51612		88650_A0	New SoC properties for ILKN retransmit: ilkn_retransmit_rx_reset_when_error_enable ilkn_retransmit_rx_reset_when_aligned_error_enable ilkn_retransmit_rx_reset_when_retry_error_enable ilkn_retransmit_rx_reset_when_wrap_after_disc_error_enable ilkn_retransmit_rx_reset_when_wrap_before_disc_error_enable ilkn_retransmit_rx_reset_when_timeout_error_enable ilkn_retransmit_tx_wait_for_seqnum_change_enable ilkn_retransmit_tx_ignore_requests_when_fifo_almost_empty for more information see TM user manual
SDK-51620	712303	56450_A0	Code modified to set the portcontrol (bcmPortControlCustomerQueueing) for KATANA2, and also to configure the EGR_QUEUE_TO_PP_PORT_MAP for extended queue also, during cosq_gport_attach of extended q to L1 gport.
SDK-51623	712568	All 88650_A0 88640_A0 88650_B0 88650_B1 88660_A0	Slow-start enable/disable API for bcmCosqGportTypeGlobalFabricCloseFmqBestEffort configured the wrong FMQ.
SDK-51644	713422	56850_A2	Remove the dormant codes confusing the reporter.
SDK-51684		88750_A0	Fixed a bug where fabric isolate might caused cells drop.
SDK-51695	715154	56850_A0	Fixed issues in alpm delete error recovery, and in alpm insert error recovery.
SDK-51699	714936	88030_A0	Earlier SDK releases did not initialize the PPE property table with the parameters defined in the PPE configuration .lrp file. This has been fixed.
SDK-51717	715701	56450_A0	FP_PORT_FIELD_SEL configuration enabled on CoE subports and flex-IO ports
SDK-51744		88660_A0	In LAG and ECMP, the hash function is configured via bcmSwitchTrunkHashConfig or bcmSwitchECMPHashConfig. In BCM88660, the Hash functions are different. The get function was faulty and has been fixed.
SDK-51755	713642	88650_A0 88650_B0 88650_B1 88660_A0	System resources FEC remove: The API bcm_vlan_port_destroy() enables deletion of VLAN-Ports as well as protection FEC IDs. The API failed when a FEC ID was the supplied gport_id.
SDK-51756	715429	88030_A0	The RCE byte count for mpls packets was always 4 times the correct value. It is fixed.

Table 74:

Number	CSP #	Chips	Release Notes For 6.3.3
SDK-51757	711558	56820_A0 56820_B0	Fixed an issue in <code>bcm_mirror_egress_get()</code> API which results in a number of mirror related diag shell commands and port encap command fails on bcm56820 switch devices
SDK-51791	715551	All	fix COP policer and timer inaccuracy when running lrp at 1.1G on bcm88030
SDK-51798	712798	88650_A0 88650_B0	Bug: Init fails if TDM and next-hop mac are both enabled in the config. Fix: Redundant check of conflicting programs (TDM and Next-hop mac extension) in PRGE removed.
SDK-51801		88030_A0	Configure "host_update_mode = manual" to disable background ejection for simple64 counter. For this counter type, host_update_mode = automatic is not allowed.
SDK-51809	713140	88650_A0 88650_B0	In the statistic-interface, the billing mode allows the user to define at ingress 2 Counter-Pointers (via Field Processor APIs) of 21 bits and transmit them on the Statistic-Records. From 88650_B0, the Billing-Queue-Number mode allows the second Counter-Pointer to be the VOQ-ID. However, setting the first Counter-Pointer via FP APIs was missing. It is now fixed.
SDK-51819	716579	88650_B1	In Field Processor, at the ingress Stage, 2 cycles are available at HW for the Field group insertion. Direct Extraction field groups must be in the second cycle. Cascaded Field groups must be in different cycles. However, the other ingress Field groups can be in both cycles. A bug was found and fixed, where a cycle with highest probability of insertion success was chosen by default, but the other cycle was not considered.
SDK-51826	716849	56850_A0	Mirror control structures for shared MTP and Ingress MTP are verified for NULL pointer before accessing the reference count to avoid segmentation fault.
SDK-51868		88650_A0 88650_B0 88660_A0	Bug: Adding new CPU destination using <code>action_set</code> causes allocation of new trap code Fix: Don't allocate new trap code in case of CPU destination.
SDK-51870	715547	56450_A0	Fixed "bcm_multicast_egress_delete() returns -4 while CoE port is present in config"
SDK-51871		88650_A0 88650_B0 88660_A0	OAM upmep trap codes from PRGE (LM,DM) all changed to 0xe0
SDK-51899		88750_A0	<code>soc_dfe_deinit</code> failed if warm boot was not initialized.
SDK-51918	717593	88030_A0	Customer can use p2e set and ep2e set to update PPE variable.
SDK-52002	718462	88650_A0 88650_B0 88650_B1 88660_A0	Fixed TDM warm boot failures.
SDK-52129		88750_B0 88650_B1 88660_A0	When using the example Linux BDE supplied with the SDK, and building with - <code>D_DUNE_LINUX_BCM_CPU_PCIE</code> The driver executable would not work. This is now fixed.

Section 13: Resolved Issues for 6.3.2

The following issues are resolved in version 6.3.2 of the SDK.

Table 75:

Number	CSP #	Chips	Release Notes For 6.3.2
SDK-33418	406892	All	Document change - Hardware link scan - port+1 requirement does NOT apply to XGS3 and later devices
SDK-34257		56846_A0 56840_A0	Add API to read and Clear CNM counters
SDK-38821		56640_A0 56548_A0 56546_A0 56545_A0 56544_A0 56542_A0 56541_A0 56540_A0 56641_A0 56642_A0 56643_A0 56644_A0 56645_A0 56648_A0	DVP and CLASSID Qualifiers support added for EFP_KEY4_DVP_SELECTOR as secondary selector for EFP_KEY4 .
SDK-39012		All	Sample application code in \$SDK/src/appl now uses soc_cm_debug exclusively for debug messages in order to allow customer applications to control all debug output through the configuration manager (CM) interface.
SDK-40877		88650_A0 88650_B0 88650_B1	Initial-VID: VLAN ISEM classification introduce 2 types of VLAN: Compressed-VID and Initial-VID. Compressed-VID is introduced according to VLAN range compression procedure. Initial-VID is introduced according to Initial-VID procedure. By default: ISEM classify untagged and priority tag packets to Initial-VID, otherwise according to Compressed-VID. In order to eliminate the use of Compressed-VID per port, use a new soc property: vlan_translation_initial_vlan_enable.<port>=0 Also in case user will not use Compressed-VID globally then the number of VTT programs will be reduced. This can be done by vlan_translation_initial_vlan_enable=0 (i.e. global and not per port). See an example of use in : cint_vlan_port_initial_vid.c
SDK-40883		88650_A0	EEDB soc properties: soc property egress_encap_bank_phase_<bank id> = access phase provides the ability to decide on init time the phase of each egress bank database. Note: Synchronize EEDB banks (AC, PWE) do not support static phasing.
SDK-40887		88650_A0	MPLS_PORT: Introduce global settings of Control Word value in case PWE encapsulation include CW. Global settings are done by Switch control bcmSwitchMplsPWControlWord
SDK-41687	560595	56440_A0	Implemented new switch controls: bcmSwitchSynchronousPortClockSourceBkupDivCtrl bcmSwitchSynchronousPortClockSourceDivCtrl



Table 75:

Number	CSP #	Chips	Release Notes For 6.3.2
SDK-41927		56640_A0	56640_A0 : Added support for updating L2 mac limits for L2 SER correction
SDK-42160		56450_A0	The SER feature is supported on Katana2 platform.
SDK-42544		88650_A0 88650_B0 88650_B1 88660_A0	Support a new feature - Asymmetric LIFs for VLAN ports. <code>bcm_vlan_port_create</code> used with <code>BCM_VLAN_PORT_CREATE_INGRESS_ONLY/BCM_VLAN_PORT_CREATE_EGRESS_ONLY</code> will produce single sided LIFs with a dedicated VLAN-Port gport encoding.
SDK-42657	574320	88650_A0	MPLS: 1+1 protection support added for PWES. See an example : <code>cint_vswitch_cross_connect_p2p.c</code>
SDK-42912	578283	56840_A0 56850_A0	Add a new enum for port control of PFCXOffTime.
SDK-43334	584814	56640_A0 56542_A0 56540_A0 56640_A1 56640_B0	No need to config <code>CMIC_MISC_CONTROL</code> register when port link from down to up.
SDK-43693		88650_A0 88640_A0	CL independent per flow proportional mode support: option to config CL from independent per flow type weight's as higher weight higher priority by set the flag <code>BCM_COSQ_GPORT_SCHEDULER_CLASS_WFQ_MODE_INDEPENDENT_PROPORTIONAL</code> in the <code>gport_add</code> . Note: The definition of the CL independent per flow mode is global for All the CLs and when proportional mode defined inverse mode cannot be used and the opposite
SDK-43892	593937	All	Correct the port link status display when it is in link-up / link-fail / link-remote-fault.
SDK-44060	595562	56840_A0 56640_A0 56640_A1 56640_B0	Both IPv4 and IPv6 packets can be terminated when tunnel type is <code>bcmTunnelTypeIpAnyIn4</code> or <code>bcmTunnelTypeIpAnyIn6</code> .
SDK-44188	591442	56846_A0 56845_B0 56845_A2 56844_A0 56842_A0 56840_A0 56843_B0 56841_A3 56846_A1 56841_B0	Correct the index of <code>SOURCE_TRUNK_MAPm</code> when configure MIM in TD/TD+.
SDK-44313	602140	All	Explicitly configure GE ports on XGXS_1-lane serdes, without an external phy to be <code>INDEPENDENT_LANE</code> .
SDK-44477		56640_A0 56640_A1 56640_B0	Added SER support for OAM - RMEP and MA_STATE tables.
SDK-44966	612411	56440_A0	Module Id was not getting programmed correctly in LMEP and L3 tables (DGLP, SGLP fields). This has been corrected.
SDK-45024		88650_A0 88650_B0 88650_B1	Added SOC property to support MPLS-TP My-mac termination: <code>mpls_tp_mymac_reserved_address</code> . Note: MPLS-TP my-mac termination address & Trill do not co-exist on the same device.

Table 75:

Number	CSP #	Chips	Release Notes For 6.3.2
SDK-45477		88650_A0 88650_B0	<p>Trill Adjacency lookup has been moved from LLR to FLP, in order to free LLR lookup for other application. Following this change, the logic which drops the packets in case RPF check has failed as also changed, and moved to FP. Summary of the API sequence changes: - <code>bcm_trill_multicast_source_add</code> which added RPF related entries to the LEM is not supported anymore. It should be replaced by a dedicated FP code. - <code>bcmRxTrapAdjacentCheckFail</code> is not supported anymore, and should not be configured to drop. - <code>sa_authentication_soc</code> property is not required for Trill adjacency check anymore.</p> <p>Example of the required changes exists on <code>src/examples/dpp/cint_trill.c</code>, with specific attention to <code>'rpf_drop_set'</code> and <code>'trill_multicast_source_add'</code></p>
SDK-45665		88660_A0	<p>L3 RPF: In the past the unicast RPF mode (loose or strict) could only be configured globally for all RIFs together. This was done using a switch control to set the global unicast RPF mode.</p> <p>With this enhancement, it is possible to configure the unicast RPF mode for each RIF, by specifying the unicast RPF mode to <code>bcm_l3_ingress_create</code>.</p> <p>To operate in this mode the SOC property <code>bcm886xx_l3_ingress_urpf_enable</code> must be set to 1.</p>
SDK-45717	619170	88650_A0	<p>Add a compilation macro <code>SCHAN_OPTIMIZATION_1</code> to support the performance improvement of <code>schan_op</code>.</p>
SDK-45750		88650_A0 88650_B0 88650_B1	<p>Support API to associate BFMC0-2 GFMC with flow control indication:</p> <pre>bcm_cosq_gport_flow_control_set(unit, fmq_port, 0, flow_control_mask);</pre> <p><code>fmq_port</code> is a gport handle to BFMC0-2 and GFMC. <code>flow_control_mask</code> is a 4 bits bitmap, where <code>flow_control_mask[i]</code> means that the FMQ class is sensitive to FC i.</p>
SDK-45926		88660_A0	<p>Added support for fair adaptive tail drop in 88660. Added support for two credit sizes in 88660. Added support for selecting the Traffic Class source in the statistics report, in 88660.</p>
SDK-46033		88650_A0 88650_B0 88650_B1	<p>Modify the algorithm for deleting Egress MC groups (<code>bcm_multicast_egress_delete</code>), so that the delete will always succeed. Egress multicast groups are configured in a way that optimizes the HW resources allocation, and allows hit-less updates. Before the modification, the delete sequence could result in exhausting all MC table entries in the HW, and fail due to out-of-resources error. This behavior is now changed. Upon egress replication deletions that would fail due to a full multicast table, the replications are instead just marked as disabled. These causes the deletions to never fail, but at the cost of less efficient egress multicast groups when such deletions are performed and the multicast table is full. Note that unless deleting only one egress replication, it is recommended (and more efficient) to use <code>bcm_multicast_egress_set</code> and not <code>bcm_multicast_egress_delete</code>.</p>

Table 75:

Number	CSP #	Chips	Release Notes For 6.3.2
SDK-46090	617790	56440_A0	Fixed LAG_FAILOVER_CONFIG programming for MXQPORTs
SDK-46210	623614	All	fix the interrupts assertion. interrupts function could go in to endless loop because of variable that was not initialized properly.
SDK-46328		88650_B0	When traversing the Large Exact Match table (e.g. in MACT with bcm_l2_traverse), some entries were missed in specific scenarios when these entries were in the first lines. This bug is fixed.
SDK-46414	629572	88750_A0 88750_B0	Wrong initialization on interrupt DB caused wrong handling of DcHUnExpCellP and DcHUnExpCellS interrupts. This has been fixed.
SDK-46416	619344	56850_A0 56850_A1	Added code to allow BCM_COSQ_DISCARD_DEVICE with gport as -1
SDK-46645		88650_A0 88650_B0 88650_B1	TRILL unicast route add: A route consists of a LEM and a SEM entry. If SEM entry add succeeded, but LEM entry add failed, SEM entry was not removed.
SDK-46656	628944	88030_A0	Already fixed.
SDK-46785	634877	56850_A1	The final per lane AMP control is fixed and released in 6.2.7 or 6.3.2.
SDK-46864	634919	56845_B0 56843_B0 56841_B0	Fixed an issue that ports with remote fault will have its forward state represented by EPC_LINK_BMAP incorrectly enabled when processing an unrelated port's linkdown event.
SDK-46897		88030_A0	MPLS Header compression feature is implemented. It can be enabled or disabled through port control API. bcm_port_control_set Control: bcmPortControlMpls Value Action (0) Disable MPLS (1) Enable MPLS (2) Enable Header compression (3) Disable Header compression
SDK-46900		88030_A0	Caladan 3 g3p1 S-OAM CCM microcode and soc layer.
SDK-47014	640047	56850_A0	SPID, QLIMIT_ENABLE and Q_COLOUR_ENABLE_CELLf are independent of groupid, so moving out of the if loop, so that SPID, QLIMIT_ENABLE and Q_COLOUR_ENABLE_CELLf fields gets programmed properly.
SDK-47067	636477	88030_A0	In case customer need to use unified mode, they need to configure "instance" and "divide_ratio" in g3p1_tmu_cfg.lrp. Set "instance" to 2, it means to use unified mode for this table. The range of "divide_ratio" is [0,10]. It means how many entries allocated in taps0. If set to 0, it means no entry in taps0. If set to 10, it means all of entries exist in taps0 and no entry in taps1.
SDK-47080		56640_B0	Issues in ESM Serdes PRBS test
SDK-47152	642576	88030_A0	Fields crossing 32bit boundaries are now supported and will generate ucode register references for the two 32bit registers that the field will fall in to.
SDK-47198	641750	88650_A0	VLAN: In case user set specific VLAN-Port to be dropped by API bcm_port_discard_set, discard settings being overwrite by mistake in egress VLAN translate APIs or when replacing existing VLAN-Port information in bcm_vlan_port_create.
SDK-47205	637114	56440_A0	Resolved the bcm_port_timesync_config_get() issue on KATANA

Table 75:

Number	CSP #	Chips	Release Notes For 6.3.2
SDK-47232	643531	56640_A0 56641_A0 56648_A0	Fixed an issue that <code>bcm_vlan_translate_action_add()</code> API overwrites existing vlan translation entry created by other applications such as MPLS.
SDK-47241	644482	56850_A0 56855_A0 56854_B0 56854_A0 56850_A1 56851P_A1 56851_A1 56850_A2 56851_A2 56851P_A2 56854_A2 56853_A2 56852_A2 56855_A2	fix egress port cos metering accuracy issue(packet-mode)
SDK-47250	643637	56440_A0 56450_A0 56440_B0	Excluded CES and CI blocks in soc dump and some test operations in Enduro2.
SDK-47320	642011	88650_A0 88650_B0 88650_B1	TPID management: Fix ingress VLAN translation with only single inner TPID value.
SDK-47326		88750_A0 88750_B0	"tr 50"/"tr 51"/"tr 52"/"tr 71" - Memory Fill/Verify test caused failures when running with a read only or write only memories. A warning was added when trying to run "tr 50" with read only or write only memories.
SDK-47342	641978	88650_A0 88650_B0 88650_B1	Advanced VLAN edit mode was introduced under the new SOC property <code>bcm886xx_vlan_translate_mode</code> , with new dedicated BCM APIs. The new mode is aimed to enable user enhanced utilization and flexibility of the HW VLAN edit capabilities. In the Advanced mode, a user can configure any port configured TPID for every VLAN edit action. For CINT usage examples please refer to <code>cint_vlan_translation_new_mode.c</code>
SDK-47406	632213	56640_A0 56850_A0	Timestamp can be added correctly to IEEE 1588 packet after modification.
SDK-47441	629284	88650_A0	MPLS + DoubleLookupEnable: Added new improvement to be able to have on L2 LIF DoubleLookup port (<code>bcmVlanPortDoubleLookupEnable</code>) also MPLS termination in case packet is tagged/untagged. To have it enabled use soc property: <code>bcm886xx_mpls_termination_database_mode=1/3</code> (1 - used in case MPLS termination is unindex up to 2 MPLS termination, 3 - used in case MPLS termination is indexed up to 3 MPLS termination).
SDK-47460		88660_A0	IP Tunnels: In BCM88660 we introduce the ability to counter/meter IP tunnel packets. In-LIF is now being updated for IP tunnel termination packets. See an example in: <code>src/examples/dpp/cint_field_dir_ext_counter_inlif.c</code>
SDK-47476		88650_A0 88650_B0	XGS MAC extender: We introduce a new method for mappings between ARAD and XGS ports. New mapping must be defined by user in new APIs: <code>bcm_stk_modport_remote_map_set/get</code> when ARAD device is connected to XGS for MAC extender. New method provides more flexible port settings between ARAD and XGS and support also trunk ports. See example of settings in: <code>cint_xgs_mac_extender_mappings.c</code> . For Negev application example see: <code>appl_dpp_stk_diag_init</code> function in <code>src/appl/diag/dcmn/init.c</code> file

Table 75:

Number	CSP #	Chips	Release Notes For 6.3.2
SDK-47500	649907	56850_A0	bcm_l2_station_add() API now supports gport type of src_port and src_port_mask parameters
SDK-47565		88650_A0	In Field Processor, the Field groups may be of type TCAM, Direct Extraction or Direct Table. In Direct Table case, the key is accessing as index the TCAM Action to retrieve the actions to perform. By definition, keys of different entries cannot overlap since they access the same table index. Due to a bug, non-overlapping keys were returning error at insertion. This is fixed.
SDK-47666		88650_A0 88650_B0 88660_A0	Interrupt were enabled in SOC layer before Interrupt application Initialization. Interrupt application clear asserted interrupts. Interrupt handler constantly handled Interrupts that were asserted after SOC init and before Interrupt application since they were never cleared. The same state can occur on Deinit/Detach sequence. This state was fixed by enable interrupts only after Interrupt application initialization.
SDK-47680		88650_A0 88650_B0 88650_B1	"diag egq" command is now under cosq, meaning diagnostics for egq will now be displayed using "diag cosq egq"
SDK-47699	661949	88650_A0	When ILKN OOB interface is in constant error stage (e.g. disconnected) the interface will be flow controlled. Thus disabling NIF port (using bcm_port_enable_set API) results in an error, because queues can't get empty. It was fix such that an error in an ILKN OOB will not raise flow control indication.
SDK-47721	652422	56851_A2 56851_A1 56852_A2 56853_A2 56851P_A1 56851P_A2 56854_A2 56855_A2 56850_A2 All 56850_A0 56855_A0 56854_B0 56854_A0 56850_A1	Code modified for programming DSCP_TABLE and PORT_TABLE for proper functioning of DSCP mapping for TD2 device.
SDK-47723 SDK-50275	652431	56850_A0 56854_A0 56850_A1 56850_A2	ETAG_PCP or ETAG_DE marking is done based on incoming OTAG/IVID/default (port) values This configuration is done in PORT_TAB table based on field - ETAG_PCP_DE_SOURCE. When ETAG_PCP_DE_SOURCE is set to value "2" ETAG_PCP/ETAG_DE are picked up from PORT_TAB for the port.
SDK-47738	650174	All 56850_A0	Reverted the code changes, so that parser behaves properly
SDK-47764		88650_A0 88650ACP_A0 88650_B0 88650_B1 88660_A0	ILKN traffic is always segmented into bursts and transmitted as non-interleaved bursts. Removed the SoC property "ilkn_is_burst_interleaving" for arad.
SDK-47787	653154	88650_A0	Background: When OAMP packets are injected, they are forwarded with forward strength 7. Bug: This strength is hard coded and cannot be configured. Should be taken from default_trap_strength soc property.

Table 75:

Number	CSP #	Chips	Release Notes For 6.3.2
SDK-47811	654131	88650_A0 88650_B0 88650_B1	In Counter processor module, when counting per VOQ, the <code>bcm_cosq_gport_statistic_multi_get</code> API is supported to get VOQ statistics after one call. An optimization is done to update the SW counters only before reading the first counter for a best performance. The <code>gport</code> param is unused and the <code>lgl_gport</code> is the desired voq's gport.
SDK-47815	644109	88650_A0	VLAN: We are introducing a cint example that illustrates different usages of <code>bcm_vlan_gport_add()</code> . For more information, please see <code>src/examples/dpp/cint_vlan_gport_add.c</code> .
SDK-47816	653943	88030_A0	There was an issue in queue setup for 3x40G TDM which caused some ports to not function as expected. This has been resolved.
SDK-47862	654758	56342_A0 56344_A0	Support is already available in TOT
SDK-47894		88650_A0 88650_B0 88650_B1	ERSPAN: a new ERSPAN calling sequence implemented for ARAD A0,B0 & B1 (see <code>src/examples/dpp/cint_mirror_erspan.c</code> for details). Changes were done to support Inbound mirroring + Routing. The new sequence also includes setting the outgoing mirror destination port as ERSPAN via a new bcm port control <code>bcmPortControlErspanEnable</code> . Notes: 1. Old sequence is not supported in ARAD A0,B0 & B1. 2. Each outgoing mirror destination port can be used for ERSPAN or SPAN (but not both). 3. Known issue: ERSPAN with XGS MAC extender is not working for ARAD+.
SDK-47928	657449	84757_C0 84744_A0	FCMAP port config get API fixed to return correct <code>mapper_len</code> (Also fixed error handling code to do unlock of <code>bfcmap_lock</code>)
SDK-47962	661178	56851_A0 56852_A1 56852_A0 56853_A1 56853_A0 56850_A0 56855_A0 56854_B0 56854_A0 56850_A1 56851P_A1 56851_A1 56850_A2 56851_A2 56851P_A2 56854_A2 56853_A2 56852_A2 56855_A2	fix wrong meter flag used in <code>_bcm_td2_cosq_bucket_set</code> .

Table 75:

Number	CSP #	Chips	Release Notes For 6.3.2
SDK-47990		88650_A0 88650_B0 88650_B1	<p>BCM88650 fabric multicast queue eligibility can be regulated by leaky buckets, random-backoff and slow-start mechanisms: for details, refer to section Fabric Multicast Queue Eligibility in the 88650-AG2XX document. Added support for these mechanisms to the driver.</p> <p>To enable/disable GCI leaky bucket mechanism call: bcm_fabric_control_set(unit, bcmFabricGciLeakyBucketEnable, enable) Default: enabled. To configure leaky bucket congestion threshold call: bcm_fabric_link_thresholds_set(unit, -1, array_count, array_types, array_values) The API received a list of thresholds (array_types) and values to configure (array_values). Relevant threshold types are: bcmFabricLinkGciLeakyBucket1Congestion bcmFabricLinkGciLeakyBucket2Congestion bcmFabricLinkGciLeakyBucket3Congestion bcmFabricLinkGciLeakyBucket4Congestion Threshold range: [0, 0xff] Default: 0x4 To configure leaky bucket full threshold (the highest value of the leaky bucket) call: bcm_fabric_link_thresholds_set(unit, -1, array_count, array_types, array_values) The API received a list of thresholds (array_types) and values to configure (array_values). Relevant threshold types are: bcmFabricLinkGciLeakyBucket1Full bcmFabricLinkGciLeakyBucket2Full bcmFabricLinkGciLeakyBucket3Full bcmFabricLinkGciLeakyBucket4Full Threshold range: [0, 0xff] Default: 0x80</p> <p>To enable/disable GCI random backoff mechanism call: bcm_fabric_control_set(unit, bcmFabricGciBackoffEnable, enable) Default: disabled.</p>
SDK-47998	660572	88030_A0	Tolltip is visible until mouse pointer has left field region.
SDK-48003		88650_A0	<p>VLAN: _bcm_dpp_vlan_info_vlan_exist_set/get is the API to the vlan_info SW DB. The API function was not used correctly in all relevant places and the SW DB might have used inconsistent data. The VLAN SW DB was integrated into alloc_mgr so that it should not be handled separately.</p>
SDK-48004	660608	88030_A0	<p>Implemented as part of "conditional breakpoint subsystem". Now user can define condition for breakpoint or create "interruption point". Interruption point contains the same expression as conditional breakpoint, but interruption point has no association with instructions and streams. Program execution will be interrupted if conditional breakpoint/interruption point expression is calculated to true value. To stop if "something" has been changed, write expression like that: <addr_expr> == *, where <addr_expr> can be register expression, variable expression, header expression, ocm table expression, etc.</p>

Table 75:

Number	CSP #	Chips	Release Notes For 6.3.2
SDK-48005	660612	88030_A0	Instead of customization, now user can create separate view for each register "page" (GPR, TPR, etc.), and locate those views at any position on screen. ShowView dialog (main menu) requests a "type" of register view to be created/activated.
SDK-48058		88650_B0 88650_B1	PON VMAC: We introduce a new capability in PON application called VMAC (Virtual MAC). In the upstream traffic, OLT Receives the source MAC (from now on called Original MAC or oMAC) and replaces it with an LLID derived MAC address (from now on called Translated MAC or vMAC). In the downstream traffic, OLT receives the Translated MAC and replaces it with the Original MAC. See more information in : <code>src/examples/dpp/pon/cint_pon_vmac.c</code>
SDK-48085	649507	88650_A0 88650_B0 88650_B1	The following diagnostic shell commands changed to print to both console and log file (if available). The previous implementation output was printed just over the console. - "diag cosq non_empty_queues" - "diag cosq print_flow_and_up" - "diag cosq voq"
SDK-48093	662986	All	The port control bcmPortControlEEEStatisticsClear now returns the correct return value.
SDK-48098	653246	56850_A0	Updated the BCM_PORT_PHY_CONTROL_TX_LANE_SQUELCH handler in tscmod to turn off the Analog Tx. With out this change, when the port is in loopback mode, it's link partner(LP) would not go down automatically as the LP continues to receive some garbage signal from local ports's analog Tx. This fix would quiesce the link and the link partner would go down automatically.
SDK-48108		56150_A0	Configured LED Processor scan delay values for Hurricane-2.
SDK-48131	651142	88650_B1	Fixed definitions of EEDB tables.
SDK-48144	661311	88650_B1	Field Processor: Data qualifiers configuration was only relevant for Ingress PMF lookup. Stage parameter was added to <code>bcm_field_data_qualifier_t</code> struct, in order to allow the user to configure the lookup stage for the data qualifier. Supported values for the stage parameters are: <code>bcmFieldStageIngress</code> , <code>bcmFieldStageEgress</code> and <code>bcmFieldStageExternal</code> . Ingress and external stages can be used for predefined and header data qualifiers. Egress stage can be used for predefined data qualifiers only (header DQ not supported). Backwards compatibility is supported. If the stage is not indicated, the default stage is ingress.
SDK-48157	653203	88650_B0 88650_B1 88660_A0	Issue #1: Separated configuration of <code>add_crc</code> in <code>bcm_fabric_tdm_editing_set</code> api for Egress and Ingress. Previously it configured both ingress and egress at the same time. Issue #2: TDM cells coming from PB to ARAD have VCS128 format. Modified ARAD B0/B1/+ default configuration to account for discard information in VCS128 cells.
SDK-48162	614371	88650_B1	L2Gre cint example: fix and enhance documentation.

Table 75:

Number	CSP #	Chips	Release Notes For 6.3.2
SDK-48183	664095	All 56440_A0 56440_A1 56440_B0	When probe port was configured and GPORT_UMAC_CONTROL register was set for the entire block to which the port belongs, the entire block of ports were reset losing the pre-configuration. Now, it resets only the corresponding probe port.
SDK-48184	664509	56640_A0 56850_A0 56450_A0 56340_A0 56640_B0	The code which generated the DFA states was disabled. Having zero states was causing the crash (zero states should never happen).
SDK-48228	665377	88650_A0 88650_B0 88650_B1	Added additional RCI (Routing Congestion-Indication) support. No change in default configuration. RCI is a mechanism used to indicate the level of congestion in the fabric. This indication is used by the end to end schedule to throttle the credit rate accordingly. *. Configure RCI increment value - the value that will be added to RCI bucket whenever a cell carrying RCI indication arrives. <code>bcm_port_control_set(unit, bcmFabricRCIIncrementValue, value);</code> Threshold range: [0, 0x7f] * Generating RCI Flow Control Local RCI.(This mechanism changed to be enabled by default) 1. Enable/Disable generating Local RCI by calling: <code>bcm_fabric_control_set(unit, bcmFabricRCIControlSource, enable_source)</code> ARAD local RCI generation Enable/Disable per pipe is not supported. Therefore, the possible values for <code>enable_source</code> are as follow Values are as follows: NONE(0) BOTH (3). Local RCI generation is enabled by default. 2. Adjust local RCI threshold by calling: <code>bcm_fabric_link_thresholds_set(unit, -1, array_count, array_types, array_values) :</code> The API receives list of thresholds (<code>array_types</code>) and values to configure (<code>array_values</code>) . Relevant threshold types: o <code>bcmFabricLinkRciFC</code> Threshold range: [0, 0x7f]
SDK-48229	665380	88650_A0 88650_B0 88650_B1	Added new thresholds to control the fabric rx interface delete-FIFO, at the device egress. Default configuration did not change (backward compatible). To configure Delete-FIFO thresholds, use the following SOC properties: - <code>egress_fabric_drop_threshold_multicast_low</code> Drop multicast best effort according to Delete-FIFO available resources (number of packet descriptors which can be added to Delete-FIFO). - <code>egress_fabric_drop_threshold_multicast</code> Drop multicast according to Delete-FIFO available resources (number of packet descriptors which can be added to Delete-FIFO). - <code>egress_fabric_drop_threshold_all</code> Drop all traffic according to Delete-FIFO available resources (number of packet descriptors which can be added to Delete-FIFO).
SDK-48274	661389	88650_A0 88650_B0 88650_B1	Diagnostics: Fixed error tag information from diag command "diag pp parsing info".

Table 75:

Number	CSP #	Chips	Release Notes For 6.3.2
SDK-48275		All	<code>bcm_attach()</code> of remote devices would fail if <code>BCM_CONTROL_API_TRACKING</code> was enabled.
SDK-48277		All	Added defensive checks to keep the get/set reg commands from firing asserts, when they are dumped from the diag shell, using invalid combinations of addresses/block numbers.
SDK-48278		88650_A0 88650_B0 88650_B1	For certain configurations with both Petra B and Arad devices, the configuration of adding fabric CRC for TDM bypass packets needs to be different in ingress and in egress. We now allow configuring this way. When the new <code>BCM_FABRIC_TDM_EDITING_NON_SYMMETRIC_CRC</code> flag is used in the structure provided to the <code>bcm_fabric_tdm_editing_set</code> API, the CRC configuration is made only to ingress/egress based on the <code>BCM_FABRIC_TDM_EDITING_INGRESS/BCM_FABRIC_TDM_EDITING_EGRESS</code> flag that is used. <code>bcm_fabric_tdm_editing_get</code> will use the new flag to return the specific CRC configuration of the ingress/egress.
SDK-48281	652032	88650_A0	Added SOC property <code>stat_if_report_multicast_single_copy</code> that indicate if a report should be sent for every copy or one time per MC packet in the ingress.
SDK-48292	666051	88650_A0	L3 RPF: Change the soc RPF definition as the bcm RPF definition.
SDK-48296		88650_A0	When working with external TCAM, a master-key is sent from BCM886XX to KBP device with all the necessary fields for the forwarding and external ACL lookups. A diagnostic has been built to show the order of the fields in the master-key and master-result: <code>BCM> kbp print master</code>
SDK-48305 SDK-43330	665205	56850_A0 56850_A1 56850_A2	Fix Ypipe index error when operating <code>MMU_QCN_ENABLE_1</code> memory(for Ypipe port).
SDK-48308	666639	88030_A0	BCM88030 - C3Debug application respects the task and predication of the original instruction.
SDK-48330	652729	88650_B1	Bug: A new mep is always added with a default profile, and after an existing mep profile was changed adding a new one should result in failure. Fix: Add a default profile unless there already was a mep configured on same lif, then we will give it the same profile as to the existing mep.
SDK-48334	662397	56440_A0 56440_B0	Corrected retrieval of port and queue info in <code>bcm_multicast_egress_subscriber_get</code> .
SDK-48349	667677	88030_A0	Support added for configuring PPE rules using CSV type syntax. This enables the rules to be edited in a spreadsheet. Please see the release notes for how to use, examples and formats.
SDK-48350	667675	88030_A0	GoTo feature (combined with search and selection by colors) are now part of new version (for vars, consts, and labels)
SDK-48355	667475	88650_A0 88650_B0 88650_B1	When <code>bcm_cosq_gport_sched_set()</code> was called to change the fabric clos or fabric mesh scheduler weights the shaper settings are also changed even though <code>bcm_cosq_gport_bandwidth_set()</code> is not being called. The issue was fixed.

Table 75:

Number	CSP #	Chips	Release Notes For 6.3.2
SDK-48357	663576	88650_A0	In Field Processor, at ingress stage (Ingress PMF HW block), the HW allows (per PMF-Program) the allocation of multiple keys in 2 cycles. When inserting a new Database, by default, the Driver was selecting the cycle with most number of available instructions. The cycle selection is optimized: if one of the cycle does not admit a 320 bit key, this cycle is tested first. This way, a 160b key will not consume the place of a 320b key.
SDK-48365	667957	56634_A0 56640_B0	Wlan virtual port assignment is now independent of the other type virtual port assignment
SDK-48366		88660_A0	BCM88660 introduces PON 3 Tags manipulation which includes 2 Egress VLAN editing and Tunnel-ID tag addition. See an example in : <code>src/examples/dpp/pon/cint_pon_application.c</code>
SDK-48373	667548	88650_A0	Programmable editor SW state was not saved per unit, thus not supporting multiple unit with a different set of programs under the same SDK instance.
SDK-48398	665296	88030_A0	12x10G to 12x10G is not a supported swap case in the last patch. Please try 1x100G to 12x10G as described in the release doc
SDK-48399	665287	88030_A0	Fixed.
SDK-48401	667520	56850_A0 56850_A1 56850_A2	Fix to cleanup invalid action data structures.
SDK-48405	662234	56440_A0 56440_B0	The encoding of NH and INTF in <code>EXT_MC_QUEUE_LIST0</code> is corrected to forward packets correctly through subscriber queues.
SDK-48488		56150_A0	The phy542xx.c driver accepts the correct primary and offset values for the built-in QGPHYs in BCM56150.
SDK-48493	667641	All 88030_A0	fix the taps resource leak during delete for bcm88030 device
SDK-48500	664376	88650_B1 88660_A0	In Field Processor module, a SOC property is added to control the size of the Trap action: - <code>custom_feature_reduced_trap_action</code> - when set, the trap action encoding includes only trap code and trap strength (11 bits). The trap qualifier is not included in the trap action encoding and its value is not used by the user. When not set, the trap action encoding includes trap code, trap strength and trap qualifier (27 bits).
SDK-48516	666270	88650_B1	TPID settings: Added an error in case the number of different TPIDs is larger than device capabilities (4 in ARAD)
SDK-48518		88650_A0 88650_B0 88650_B1	SW perform soft reset without fabric as default action for interrupt "hard_reset" corrective action, and where fabric reset is needed SW perform soft reset with fabric
SDK-48522	667062	88650_A0 88640_A0	Fix for a possible contention issue in the resource manager init. Resource management actions may be called in parallel for different units, but init and detach of a specific unit must not be called concurrently with other functions for that same unit.
SDK-48524	667951	88030_A0	If the OCM memory allocation exceeds that which is available the assembler will quit with an error message and a table of the current allocations. Additionally if a port allocation exceeds that which is available to it the assembler will quit with an error message and a table of the current port allocations.

Table 75:

Number	CSP #	Chips	Release Notes For 6.3.2
SDK-48530	670224	All	fixed the tx dma error during taps insert when ipv6 table is almost full for bcm88030
SDK-48547	668480	88030_A0	hread constraint added. Violating the constraint will produce the following error: Error! [51059] g3p1_ing_bridge.lrp->236:32->1.95 = constraint H-000-2 Header Load Latency (1)
SDK-48558	621392	88650_A0 88650_B0	Initial-VID: Initial VID is now supported. In order to support a port to be Initial-VID for both tagged and untagged packets enable port use soc property <code>vlan_translation_initial_vlan_enable</code> . <code>bcmVlanLookupMACEnable</code> didn't work correctly before. Now the VLAN control enable Only MAC VLAN Assignment procedure. See an example of use in <code>src/examples/dpp/cint_vlan_port_initial_vid.c</code>
SDK-48572	669205	56640_A0 56850_A0 56855_A0 56854_B0 56854_A0 56850_A1 56851P_A1 56851_A1 56850_A2 56851_A2 56851P_A2 56854_A2 56853_A2 56852_A2 56855_A2	Added the support for forwarding type and forwarding field in egress mode for Trident 2
SDK-48573 SDK-50119	668627	All	Added little-endian host support.
SDK-48574	636126	88650_B1	VSWITCH: One directional cross connect is now supported using flag <code>BCM_VSWITCH_CROSS_CONNECT_DIRECTIONAL</code>
SDK-48578	662404	88650_A0	Vxlan: packet native to VLAN had corrupted encapsulation - IP and UDP length fields were incorrect - The I flag was set to 0, instead of 1.
SDK-48581		88650_A0	In Field Processor, a change in 6.3.0 implies that the <code>bcmFieldQualifyForwardingType</code> is mapped to 2 HW qualifiers to allow the support of <code>bcmFieldForwardingTypeMplsLabel1/2/3</code> . This option can be disabled by commenting the compilation flag <code>_BCM_DPP_FIELD_FORWARDING_TYPE_COMPOSED</code> .
SDK-48586		88650_A0 88650_B0 88650_B1	1. <code>cint_cnm</code> example was fixed. 2. When a CNM queue was configured (using <code>bcm_cosq_qcn_config_set</code> API), it could override the parameter for all queues. This issue is fixed.
SDK-48587		88650_A0	Field Processor: 2 SOC properties are added: 1. <code>custom_feature_fp_restricted_forwarding_type</code> - when set, this SOC property does not allow the <code>bcmFieldQualifyForwardingType</code> to be a composed qualifier. In this case, the values <code>bcmFieldForwardingTypeMplsLabel1/2/3</code> cannot be used. 2. <code>custom_feature_pmf_320b_key_opt_disable</code> - when set, the 320 bit key optimization is disabled during key allocation.

Table 75:

Number	CSP #	Chips	Release Notes For 6.3.2
SDK-48612	670951	88650_A0 88650_B0 88650_B1	The Counter Processor module runs background threads to collect the highest counters into a SW database. If the Soc property <code>counter_engine_sampling_interval</code> is set to 0, the Counter Processor background thread will not run during the initialization sequence. This must be used only if: - either the user is not using the Counter processor - or all the Counter Processor formats (<code>counter_engine_format_</code>) are PACKETS or BYTES
SDK-48613	670936	88030_A0	RXAUI 10G port support for specific configurations (up to 6x10G) is now supported on Caladan3.
SDK-48615		56524_A0 56524_B0	<code>bcmPortControlLinkFaultLocalEnable</code> and <code>bcmPortControlLinkFaultRemoteEnable</code> results in segmentation fault in <code>bcm_port_control_get()</code> for devices using bigmac, such as BCM56524.
SDK-48643		88650_A0	<code>inband_mem_handle()</code> would leak memory on error return.
SDK-48644		All	<code>_topo_info_t_create()</code> would leak memory on an error return
SDK-48649		56524_A0 56524_B0	<code>bcm_port_control_set()</code> does not set correct value for <code>bcmPortControlLinkFaultLocalEnable</code> and <code>bcmPortControlLinkFaultRemoteEnable</code> for devices using bigmac, such as BCM56524.
SDK-48650	671419	56224_B0 56224_A0	Fixed tunnel initiator warm boot recovery for XGS III chips
SDK-48653	670916	56640_A0 56644_A0	The issue is fixed in SDK so that user can create FP group with <code>bcmFieldQualifyIpProtocol</code> qualifier when using ESM and ESM_IPv4 or ESM_L2_IPv4 profile. With this fix, following IP protocol numbers (used in the Protocol field of the IPv4 header), can be used to qualify the packets using IpProtocol qualifier: TCP (6), UDP (17), ICMP (1), IGMP (2), IPv4 (4), IPv6 (41), MPLS (137)
SDK-48656	669385	All 56850_A0 56855_A0 56854_B0 56854_A0 56850_A1 56851P_A1 56851_A1 56850_A2 56851_A2 56851P_A2 56854_A2 56853_A2 56852_A2 56855_A2	fixed code to support sp schedule for cpu port.
SDK-48666	660786	88650_A0 88650_B0 88650_B1	VLAN-Port: Added a fix to support 32K AC-LIFs. On some cases specific LIF IDs returned Internal error when created.
SDK-48667	644027	88650_A0 88650_B0 88650_B1 88660_A0	G.8032 Ring Protection: It is now possible to associate Fast Flush LIFs to ERP blocking groups. The <code>ingress_failover_id</code> & <code>failover_port_id</code> fields can be modified by <code>bcm_vlan_port_create</code> in REPLACE mode, with the values of a <code>failover_id</code> that is dedicated to ERP grouping. A CINT example is provided in <code>cint_l2_fast_flush.c</code> .

Table 75:

Number	CSP #	Chips	Release Notes For 6.3.2
SDK-48668	651858	88650_A0 88650_B0 88650_B1	Tail drop for ISQs per color was not supported. Added support for accepting ISQ gport types. Now it is possible to use BCM_COSQ_GPORT_ISQ_SET(gport, qid) And then bcm_cosq_gport_color_size_set(unit, gport, cosq, bcmColorBlack, BCM_COSQ_GPORT_SIZE_BYTES, &q_size_ucast); Instead a work around: Configuring the wanted ISQ qid, by using BCM_GPORT_UNICAST_QUEUE_GROUP_SET(gport, qid);
SDK-48669		88650_A0	Added a new compilation flag BCM_CONTROL_API_TRACKING With this flag is in use, BCM_API calls are not allowed when the device is detached
SDK-48681	669901	56850_A0 56850_A1 56850_A2	1. Enabling ING_HASH_CONFIG_0 register 2. Fix existing bug on programming RTAG7_HASH_CONTROL 3. Adding valid bit to a flex_hash_entry before it is programmed into the tcam
SDK-48683		88650_A0	Release/Free/Destroy Semaphores/Mutexes which were allocated during init.
SDK-48684	670470	56640_A0 56640_A1 56640_B0	OAM endpoint traversal would skip the remaining endpoints if the callback routine modifies the endpoint. This has been corrected.
SDK-48693	670822	56450_A0	With wc40.c patch , RXAUI mode is working fine. Also with below config variables, RXAUI mode works fine with init all. port_init_autoneg_xe6=0 port_init_speed_xe6=10000
SDK-48694	664945	56850_A0	Fix confusion when configuring CPU's queue assignment after XE's.
SDK-48697		All	The Linux kernel module linux-kernel-bde now supports enabling/disabling the use of MSI interrupts on PCIe.
SDK-48700		88650_A0	IPv4 Multicast and IPv6 forwarding tables are located in the TCAM. The entry shuffle in the TCAM for these Databases was flawed for specific scenarios and is fixed.
SDK-48704	635324	88650_A0 88650_B1	Warmboot state was not recovered for unit different than zero
SDK-48714		All	Added Coverity killpath annotation to _sal_assert()
SDK-48715	671569	88650_A0	bcm_cosq_gport_threshold_set was setting the wrong parameter, causing the port FC threshold (port_fc_data_buffers) to not get configured. The issue is fixed.
SDK-48721	653118	56224_B0 56224_A0	UDF_ETHERTYPE_MATCH issue has been addressed.
SDK-48726	671075	88650_A0	Port LLP COS profile: Drop precedence profile should be 2 bits (0-3) and not 1.
SDK-48733		88650_A0	Added port controls, allowing to separately enable/disable fabric links in RX/TX directions: bcm_port_control_set(unit, port, bcmPortControlRxEnable, value = 0/1); bcm_port_control_set(unit, port, bcmPortControlTxEnable, value = 0/1);

Table 75:

Number	CSP #	Chips	Release Notes For 6.3.2
SDK-48738		56340_A0	Added support for BCM56340 for flushing the MMU, clearing the backpressure and freezing the egress metering when the port is disabled.
SDK-48743		88650_A0	For BCM886xx devices, a gport may have more than one QoS profile. In this case, the <code>bcm_qos_port_map_get</code> has no way to know which one should be returned. In this enhancement a new API is introduced - <code>bcm_qos_port_map_type_get</code> that allows the user to get a QoS profile of a gport according to the QoS profile type (the same QoS type that is passed to <code>bcm_qos_map_create</code>).
SDK-48759		88650_A0 88660_A0	<p>Changes in the color resolution are done: 1. The egress Drop Precedence was equal to Drop-Precedence / 2 by mistake, taking only the values 0/1. It is equal to incoming Drop Precedence from now (when the DP-Meter command is set to modify the egress DP, e.g. by default)</p> <p>2. The policer 'yellow' was encoded as DP=2. It is DP=1 from now on.</p> <p>3. In BCM88660, a differentiation of RED from Ethernet policer and meter processor is implemented. Usually when a packet is assigned a red color by a meter, the user has no way of knowing how this decision was made. Red is always represented by DP=3.</p> <p>In this enhancement a new drop resolution mode is presented that allows the user to obtain more information about the drop source (i.e. the component that assigned the red color to the packet). If <code>policer_color_resolution_mode=1</code>, then this mode is active. In this mode, there are two types of red. Pre-Meter drop (DP=3): If the meter receives a red packet, then the output DP would be 3 (e.g. if an Ethernet policer dropped the packet). Meter drop (DP=2): If the meter assigns a red color to the packet, then the output DP would be 2.</p>
SDK-48775	671603	56850_A0 56850_A1 56850_A2	Resolve strict priority failed on TD2.
SDK-48792		All	Resolution of an issue where the diag command 'fp stat create' would intermittently crash.
SDK-48798	672473	56850_A0 56850_A1 56850_A2	Delete ingress nat entries no matter the following flags set or not in hardware table, when they are not set in argument flags in <code>bcm_l3_nat_ingress_delete_all</code> : <code>BCM_L3_NAT_INGRESS_HIT</code> , <code>BCM_L3_NAT_INGRESS_MULTIPATH</code> , <code>BCM_L3_NAT_INGRESS_RPE</code> , <code>BCM_L3_NAT_INGRESS_DST_DISCARD</code> .
SDK-48817	654269	88650_A0 88650_B0 88650_B1	Counter processors are counting according to one of multiple sources, e.g. Ingress or Egress OAM. The following modifications have been done when counting with OAM source: - remove redundant code in the assignment of OAM counter processors
SDK-48825	668611	88650_A0	tr40 add type ID variable with default: <code>tpid=0x8100</code> , before the fix this value was hard coded to <code>0x9000</code>
SDK-48836		88650_A0 88650_B0 88650_B1	Allow using <code>bcm_cosq_pfc_config_set</code> API to configure FC for VSQ types: CT, CTTC, CTCC, STF.
SDK-48837		88650_A0 88650_B0 88650_B1	For Out Of Band FC, fix configuration of reception path to LLFC, using <code>bcm_cosq_fc_path_add</code> API.

Table 75:

Number	CSP #	Chips	Release Notes For 6.3.2
SDK-48839	640074	88650_A0 88650_B0 88650_B1	In the Statistic-Interface configuration, the configuration of the egress Counter-Pointer format was done through the Counter Processor configurations. The user can configure from now on the Egress Counter_pointer formats without configuring a Counter Engine to count at egress by using the following SoC properties: counter_engine_source_stat0 counter_engine_source_stat1
SDK-48844	671536	88650_A0 88650_B0 88650_B1	In ELK application, the KBP diagnostic "BCM>kbp print" displays also per Database: 1. the number of entries 2. an estimation of the remaining capacity (number of entries). This estimation is valid only when the Database has at least an entry.
SDK-48854		88650_A0	TDM: API bcm_fabric_editing_set returns error by mistake when System port allocations is not symmetric (same port allocation on all devices). Fix included removed the constraint between Symmetric systems and API handle.
SDK-48857		88650_A0 88650_B0 88650_B1 88660_A0	<p>The credit watchdog configuration and the predefined credit request profiles, now work properly with warm boot.</p> <p>The burstiness of credit watchdog configurations using a small range of queues was improved.</p> <p>A new credit watchdog mode was added for 88660 only. It is called the Common Message Generation Period mode, and is the default mode for 88660. In this mode the Message Generation Period is common to the whole device, the same for all the queues in the credit watchdog range. The supported (common) message generation periods are 0 (disabled), 125us, 250us, 500us, 1ms, 2ms (default), 4ms. The lower periods require that the credit watchdog will not be configured for all of the queues. The precise rule on the number of queues configured for the credit watchdog is: number_of_queues < 120 * scan_time_in_us. The supported range of the delete queue threshold is also 2ms-7.6s, and the default is 512ms.</p> <p>Changing back to this mode after changing to a different mode is done using:</p> <pre>bcm_fabric_control_set(unit, bcmFabricWatchdogQueueEnable, BCM_FABRIC_WATCHDOG_QUEUE_ENABLE_C OMMON_STATUS_MESSAGE);</pre> <p>In this mode the Common Message Generation Period can be set and retrieved using:</p> <pre>bcm_cosq_delay_tolerance_t dt; dt.credit_request_watchdog_status_ msg_gen = 125; /*period in us, or 0 for no messages */ bcm_cosq_delay_tolerance_level_set (unit, BCM_COSQ_DELAY_TOLERANCE_SET_COMMO N_STATUS_MSG, &dt); /* set the period */ bcm_cosq_delay_tolerance_level_get (unit, BCM_COSQ_DELAY_TOLERANCE_SET_COMMO N_STATUS_MSG, &dt); /* get the period */</pre>
SDK-48870	666202	88650_B1	After warmboot recovery, only 16K AC-LIFs were recovered. now all LIFs should recover.

Table 75:

Number	CSP #	Chips	Release Notes For 6.3.2
SDK-48873	673082	All 56850_A0 56850_A1 56850_A2	Weight 0 can be configured for WRR or WERR scheduled nodes.. Configuration to support hybrid combination of scheduling, strict+WRR or strict+WERR is allowed.
SDK-48887	670870	88650_A0 88650_B0 88650_B1	In Field Processor, the entry-ids are allocated according to the Database type: 1. The TCAM databases get the first entry-ids [0 ; x-1] 2. The Direct extraction have 16 possible entry-ids [x ; x+16] Due to the insertion of external TCAM database support, the following changes are done: 1. The external databases get a third range of entries [x; 2x] 2. When compiling the KBP code, x=SOC_TMC_TCAM_NL_88650_MAX_NOF_ENTRIES=1<<16 . Otherwise, x=28K 3. The SW state increases tremendously when compiling with KBP code. Most of the SW state saves the FP entry attributes (1 KB per entry). Thus the SW state size is 1K * x. 4. To reduce the SW state, the user can reduce the maximal number of qualifiers (SOC_PPC_FP_NOF_QUALS_PER_DB_MAX set to 32) and actions (SOC_PPC_FP_NOF_ACTIONS_PER_DB_MAX set to 16) according to the maximal size in its scenarios. 5. For KBP users, the x can be changed to the maximum by defining SOC_TMC_TCAM_NL_88650_MAX_NOF_ENTRIES=1<<20 .
SDK-48889	674382	88650_A0	bcm_port_force_forward_set() returned an error when called on a disabled port
SDK-48895	670658	88650_A0 88650_B0 88650_B1	In Field processor, the user can define data qualifiers. The number of data qualifiers is increased from 16 to 64.
SDK-48896		88650_A0 88650_B0 88650_B1	Add the option configure the WFQ weight of port schedule to 0 (both ETM and E2E ports). When weight 0 is set for a TCG it'll get SP.
SDK-48897	611729	88650_A0 88650_B0	Disabling NIF port (using bcm_port_enable_set API) results in an error whe port is extremely shaped and oversubscribed. Workaround; Disable port shaping before disabling a port. Resolved by disabling and enabling back the shapers inside the API.
SDK-48917		88650_A0 88650_B0 88650_B1	In bcm_vlan_port_create port.learn_ac is set for all non CEP ports, even if the port was previously set to no learning.
SDK-48918		88650_A0	Added support for HCFC protocol in oob port (fc_oob_type=3)
SDK-48930 SDK-49401		88650_A0 88650_B0 88650_B1	Advanced VLAN edit mode supports PCP/TPID modifications for tags with unchanged VID value.
SDK-48943	675017	56640_A0 56634_A0 56634_B0	56640_A0 56634_A0 : Added support for handling SER events for IPFIX tables.

Table 75:

Number	CSP #	Chips	Release Notes For 6.3.2
SDK-48959		88650_A0	LIF & L2 FEC System resources: The BCM API has an allocation manager. When an object is created and <code>WITH_ID</code> flag is set, then user can provide the allocation of the object. In case of LIF and L2 FEC we introduce two modes of system resources: Global and Local. Global is the default mode where it assumes that LIF & L2 FEC are global resources. In case LIF is being allocated on one device, it is expected to run <code>WITH_ID</code> over all other devices with the same settings. In global mode, the system can support up to 64K LIFs and 16K L2 FECs (the same as one device). In case of Local mode, user has a full control of the allocation IDs. Thus, allowing use of LIF entries, and FEC entries in different devices with the same ID to store different objects. The allocation of objects IDs is done at the user application level. Local mode is available for <code>VLAN_PORT</code> and <code>MPLS_PORT</code> . To enable system resource soc property use: <code>bcm88xxx_system_resource_management</code> See CINT examples of local mode in: <code>src/examples/dpp/cint_system_vswitch.c</code> <code>src/examples/dpp/cint_system_vswitch_vpls.c</code>
SDK-48962		88660_A0	MPLS termination: In BCM88650 a MPLS tunnel is determined both by the label and the BOS bit. In BCM88660 introduces a new mode that allows the driver to ignore the BOS bit. The MPLS tunnel is determined by the label. If the SOC property <code>bcm886xx_mpls_termination_key_mode</code> is 1 then the BOS bit is ignored, and only the label is used as a key (for tunnel lookup).
SDK-48965		88650_A0	New improvement PON Local route switch: PON Local route switch introduce the ability of sending traffic from PON-LIF to other PON-LIF. 1. To enable feature set soc property: <code>local_switching_enable=1</code> ; 2. For Forwarding group rules set <code>bcmPortClassForwardIngress</code> and <code>bcmPortClassForwardEgress</code> in <code>bcm_port_class_get/set()</code> APIs. 3. To enable Local Route switch per LIF set <code>bcmPortControlLocalSwitching</code> in <code>bcm_port_control_get/set()</code> APIs. Full application and example can be read in <code>cint_pon_local_route.c</code>
SDK-48990		88650_A0	Allocating dual shaper egress scheduler element might fail. Fixed.
SDK-49002	675026	88650_A0 88650_B0 88650_B1	Setting and getting the assigned credit request profile of Ingress Shaping Queues (ISQs), using the <code>bcm_cosq_gport_sched_set</code> API, is now supported.
SDK-49003		88650_A0 88650_B0 88650_B1	VLAN translation new mode: All PP application examples cintns are compatible with the new vlan translation mode (soc property <code>bcm886xx_vlan_translate_mode=1</code>). For specific examples of VLAN translation new mode see <code>src/examples/dpp/cint_vlan_translation_new_mode.c</code>
SDK-49010	676225	56850_A0 56850_A1 56850_A2	Trident2 weights can be calculated based on LLS/HSP based scheduling type associated to the port, in either case the maximum weight can be 127.



Table 75:

Number	CSP #	Chips	Release Notes For 6.3.2
SDK-49012	673165	88650_A0	88650 interrupts: EGQ ECC interrupt may be raised with no real reason for BufLink memory, in this case we changed the corrective action in the interrupts application to none.
SDK-49025	676726	88650_A0	Fix "diag count" - internal counters diagnostics command. Some counters names were not displayed correctly.
SDK-49031		88650_A0	TM/PP device mode: In case device mode is TM then no need to initialize port PP settings and QOS module.
SDK-49032		88650_A0	In Field Processor, the same BCM Action (bcmFieldActionSrcGportNew) was mapped to 2 HW actions: 1. Source-System-Port 2. In-LIF Thus, the action size is increased when adding the BCM action and it prevents these actions from being used for Direct Extraction (a 1x1 mapping between the BCM and HW action is mandatory). The BCM mapping has been changed: - bcmFieldActionSrcGportNew is mapped to Source-System-Port - bcmFieldActionIngressGportSet is mapped to In-LIF The user MUST change its BCM action from bcmFieldActionSrcGportNew to bcmFieldActionIngressGportSet when the In-LIF is changed in Field processor.
SDK-49040		All	Improve KNET NAPI performance by increasing the number of packets processed per interrupt.
SDK-49056		88750_A0 88750_B0	88750: BCM command shell "diag queues" now shows different format: it shows [link number, max size]
SDK-49057	676332	88650_B0	Fix default MC TC mapping to service pools such that: 1. TC0-3 are mapped to SP0 2. TC4-7 are mapped to SP1 regardless of number of priorities mode.
SDK-49083	676830	88650_B1	VPLSoGRE: MPLS ttl0 trap invoked in case of running VPLSoGRE packet. Added a new FLP program in order to remove trap issue.
SDK-49090		88650_A0	Failover: API function bcm_failover_cleanup() did not clean the failover SW DB in alloc mngr. Added proper handling to failover SW DB.
SDK-49094	670228	56342_A0 56344_A0 56340_A0	APIs bcm_l2_age_timer_set/get() should now work for bcm56340 type switch devices.
SDK-49099	669195	88650_A0	new soc property provided: ilkn_retransmit_rx_reset_upon_watchdog_error_enable. previous setting was set to enabled. This new property is provided in order to avoid resetting when watchdog error occurs.
SDK-49100	664670	56850_A0 56850_A1 56850_A2	Set VOQ_COS_MAP.VOQ_COS_USE_MOD to enable DMVOQ feature in MMU.
SDK-49104		88660_A0	Add new values to bcm_cosq_gport_stats_t: bcmCosqGportNotGreenDroppedPkts bcmCosqGportNotGreenDroppedBytes bcmCosqGportNotGreenAcceptedPkts bcmCosqGportNotGreenAcceptedBytes These modes are in use in the third entry in FULL_COLOR, GREEN_NOT_GREEN and in 88660 in SIMPLE_COLOR_DROP and SIMPLE_COLOR_FWD.

Table 75:

Number	CSP #	Chips	Release Notes For 6.3.2
SDK-49115		88650_B1	In VxLAN application, no default trap or snoop can be configured in case of no hit in VNI mapping and Source-IP lookups. A Field processor CINT is proposed to handle this case: <code>cint_field_vxlan_lookup_unfound.c</code>
SDK-49128		88650_A0 88650_B0 88650_B1	In Advanced VLAN edit mode, the number of Egress VLAN edit profiles changes from 8 to 16 as the HW permits. Hence, the number of supported Egress VLAN edit actions changed from 128 to 256.
SDK-49133		88650_A0	<code>diag cosq print_flow_and_up</code> didn't display accurate value of Credit rate , now it displays the accurate value
SDK-49150	678454	56640_A0 56850_A0 56640_A1 56640_B0 56850_A1 56850_A2	Initialized the LAG and HGTRUNK resolution on Triumph 3 and Trident 2 devices.
SDK-49151		88650_A0 88650_B0 88650_B1	Advanced VLAN editing: Added in CINT examples the support of advanced VLAN mode (soc property <code>bcm886xx_vlan_translate_mode=1</code>) on PON application CINTs.
SDK-49152		88650_A0	VPLSoGRE: Update CINT of VPLSoGRE 2 pass solution to have a correct RIF when sending to recycle port. Before RIF caused on the second pass "sa equals da" trap. For more details about the solution see <code>cint_vswitch_vpls_gre.c</code> .
SDK-49153		88650_B0 88650_B1	Port field in Trill adjacency check was not enabled (feature was added in Arad-B0, but was not enabled by SDK).
SDK-49159	678514	88650_A0	In previous versions (pre 6.3.2) the vlan information (id, priority, cfi) was encoded inside the vlan field in <code>bcm_port_congestion_config_t</code> struct. The implementation changed such that the following fields in <code>bcm_port_congestion_config_t</code> represent the VLAN information: - vlan - cfi - pri When 'vlan' is set to <code>BCM_VLAN_INVALID</code> , the vlan, cfi and pri won't be configured to the device. The API is used to control the CNM PDU vlan tag. It's also optional to provide vlan edit command when working in PP mode. The API configures the vlan id, pri & cfi in the edit command fields, but it doesn't update the command field (default command is don't edit). Modifying VLAN edit command is currently not supported by API (can be done on register-level, please consult BCM AE team if relevant)

Table 75:

Number	CSP #	Chips	Release Notes For 6.3.2
SDK-49166		88650_A0	<p>Added new feature. Feature description: The BCM88650BCM88660 device has the ability to save User-Data in the DRAM packet memory. The DRAM is partitioned into fixed-size buffers. These buffers are typically used for packet queuing. A sub-range of DRAM buffers can be allocated to store User-DATA. The number of DRAM buffers used for packet queuing is the minimum of Packet Descriptors Memory (PDM) maximum buffers descriptors capacity DRAM size divided by DRAM buffer size, where the DRAM size is total available DRAM size minus the number of buffers allocated for User-Data. The amount of User-Data DRAM buffers is defined by the user. The total number of DRAM buffers descriptors is 2M buffers. With 8 DRAM interfaces, each interface serving two DRAM devices of 2Gbit, the DRAM total size is 4GByte. For example, in a system with standard PDM configuration, with 8 DRAM interfaces, the maximal descriptors capacity for packet queuing is 1.5M buffer descriptors. When DRAM buffer size is set to 1KB, up to 1.5GB of DRAM memory can be used for packet queuing. The remaining 0.5M buffers can be allocated to user-data, without effecting the amount of memory available for data queuing. Notes: Access to DRAM User Data is available only after completing the device initialization. Performing DRAM calibration (Shmoo), Device Hard reset will corrupt the DRAM Use-Data.</p> <p>Driver Reference SoC Properties The SoC property <code>user_buffer_size_dram=<User-Data MBytes></code> (Default: 0) Sets the User-Data size. BCM API To access User-Data buffer: <code>int bcm_switch_user_buffer_write(int unit, uint32 flags, bcm_switch_user_buffer_type_t buff_type, uint8 *buf, int offset, int nbytes); int bcm_switch_user_buffer_read(int unit, uint32 flags, bcm_switch_user_buffer_type_t buff_type, uint8 *buf, int offset, int nbytes);</code> flags - for logical to physical address translation use <code>BCM_SWITCH_USER_BUFFER_LOGICAL2PHY_TRANS</code> flag. Note: Due to HW errata in BCM88650-A0/BCM88650-B0, logical to physical address translation must be used if OCB enabled in the system.</p> <p><code>buff_type</code> - for DRAM User buffer type use <code>BcmSwitchUserBufferTypeDram</code>. <code>*buf</code> - In write access function contain Data buffer to be written to DRAM User buffer, in read function store the data read from DRAM User buffer. <code>offset</code> - The offset in the User DRAM buffer where. Start of dram User buffer resides in offset '0'. <code>nbytes</code> - Number of bytes to be written or read. WarmBoot DRAM User-Data can be used to save WarmBoot Database. By registering DRAM User Data access function to WarmBoot Callbacks, the WarmBoot Database will be saved to DRAM. Since part of WarmBoot sequence is done during SOC initialization, before BCM API calls are accessible, the corresponding SoC API can be used instead: <code>uint32 soc_arad_user_buffer_write(int unit, uint32 flags, uint8 *buf, int offset, int nbytes); uint32 soc_arad_dram_user_buffer_read(int unit, uint32 flags, uint8 *buf, int offset, int nbytes);</code> The functions parameters match those of the corresponding BCM API functions.</p>

Table 75:

Number	CSP #	Chips	Release Notes For 6.3.2
SDK-49181		88650_A0 88650_B0 88650_B1	VLAN translation new mode: IVE action ids 0-13 had incorrect FHEI size (3B). FHEI size (5B) is now set instead.
SDK-49190	672457	88650_A0 88650_B0 88650_B1	When traversing the Large Exact Match table (e.g. when traversing MACT or IP host tables), some entries were appearing twice in some scenarios. This bug is fixed.
SDK-49194	676557	All 56634_B0	fix <code>vlan_subnet_entry_delete</code> error when <code>VLAN_SUBNET</code> table is full
SDK-49195	675324	88650_B0 88650_B1	Interop between PB and ARAD in PP mode. In order to support this mode, ARAD should be configured to handle PB FTMH. If ARAD is working in PP mode and PB in the system is configured, Arad will be automatically configured to support PB FTMH headers. Relevant only for ARAD B0/B1 devices
SDK-49198	679516	88650_B0	Fixed bug in port speed set by auto-negotiation - <code>bcm_port_update</code> : in case of link up as a result of auto negotiation, set also the mac speed according to the auto negotiation. <code>bcm_port_speed_get</code> : read the speed from the serdes.
SDK-49200	677111	88650_A0 88650_B0 88650_B1	When using external TCAM for IPv6 Multicast forwarding lookup, the lookup key was in the Multicast table: {In-RIF, Destination-Multicast-Group[119:0]}. It is from now on: {In-RIF, Source-IPv6[127:0], Destination-Multicast-Group[119:0]}. The Source-IPv6 parameter is set during the entry addition via ' <code>s_ip6_addr</code> ' in <code>bcm_ipmc_addr_t</code> .
SDK-49203		56640_A0 56640_A1 56640_B0	CRC checking is enabled when device operates with a maximum of 16 lanes.
SDK-49212	679834	56850_A0	Completed support for internal priority override on mirror packets.
SDK-49221	679524	56850_A0	Corrected the initializing code, so that it doesn't throw false alarm
SDK-49222	680016	56334_B0 56334_A0	Disabled <code>sample_thresh16</code> feature for enduro as sflow threshold is changed from 16bit to 24bit in enduro.
SDK-49243	636292	88650_A0 88650_B0 88650_B1	In Field Processor, the following BCM qualifiers were not correctly implemented for IPv6 routed packets: - <code>bcmFieldQualifyIp6NextHeader</code> = <code>bcmFieldQualifyIpProtocol</code> - <code>bcmFieldQualifyIp6FlowLabel</code>
SDK-49258	675009	88650_A0	Fixed: allocation of two composite scheduling elements with two sequential <code>flow_ids</code> might fail.
SDK-49260	673477	56850_A0	Added code, so that forwarded vlan is configured irrespective of <code>ingress_map_mode</code> config variable
SDK-49261		56640_B0	N/A
SDK-49286 SDK-49309		88650_A0 88650_B0	Background: The OAMP has a configuration corresponds to the correct core clock. Bug: This value is fixed to 500Mhz clock. Solution: Clock is taken from <code>SYSTEM_REF_CORE_CLOCK</code> soc property.
SDK-49292		56850_A0 56850_A1 56850_A2	<code>bcmFieldQualifyVnTag</code> qualifier(F2-7) offsets are adjusted to correct values in VFP.
SDK-49293 SDK-49294		56640_A0 56640_B0	Issue fixed to make external L2 ACL work on TR3
SDK-49302	680992	88030_A0	Read API for coherent counter.
SDK-49305	677200	88650_A0	Congestion Notification: fix CNM packets generation in sampling mode. 1. Driver code fixes 2. Add missing functionality to cint example (<code>src/examples/dpp/cint_cnm.c</code>)



Table 75:

Number	CSP #	Chips	Release Notes For 6.3.2
SDK-49307	678192	88650_A0 88650_B0 88650_B1	For IP forwarding databases located in TCAM, the traverse function was skipping entries. This is fixed.
SDK-49310	681349	56850_A0	Add code reading of yellow limit is for multicast queue
SDK-49312	680636	56850_A1	Corrected the code in routine <code>_soc_counter_trident2_non_dma_init</code> to fix the problem of memory being over-written.
SDK-49333	671402	All 56850_A0 56850_A1 56850_A2	Corrected SNAT HIT status.
SDK-49339	680069	88650_B1	Fixed: If recycle ports are defined (in config.bcm), and outbound mirroring of a port was set up and then deleted, then <code>bcm_cosq_gport_bandwidth_set()</code> would fail. This may also have happened with OAM/PMF/egress ACL and not just with mirroring.
SDK-49340	671446	88650_A0 88650_B0 88650_B1	VLAN: Set lif VSI assignment mode equals VLAN if vlan port criteria is <code>BCM_VLAN_PORT_MATCH_PORT</code> and vsi is -1.
SDK-49346	678063	All	Support Encapsulated HiGig packet in Both L2 and IP GRE mode.
SDK-49348		56852_A1 56852_A0 56850_A0 56852_A2	The release notes has been updated with Preview mode support for 56852.
SDK-49349	674832	56640_A0 56641_A0 56642_A0 56643_A0 56644_A0 56645_A0 56648_A0 56640_A1 56643_A1 56644_A1 56640_B0 56644_B0 56643_B0 56648_B0 56649_B0 56649_A0	Fixed the counters issue for oversize and runtime packets on TR3 platform
SDK-49350	681799	56640_A0 56340_A0	Flx for retrieving available and free counters on TR3 and Helix4
SDK-49360	668571	88650_A0	L2GRE: Use bounce back filter to perform split horizon. The filter is now configured at the init stage in the driver in case L2GRE/VXLAN is enabled. To activate the bounce back filter, use: <code>bcm_rx_trap_set</code> . See example in <code>cint_l2gre</code>
SDK-49366	682107	56450_A0	Enhanced init time port attributes (which were missing) for SubportPktTag and LinkPHY support
SDK-49389	678486	56340_A0	Support 25Mhz clock source in Helix4
SDK-49390	680811	56840_A0 56640_A0 56850_A0 56850_A1	EFP_TCAM entry KEY field width is increased in TD2 and TR3 as compared to TD/TR2. So, relevant changes are made in EFP recovery logic (warm boot) to support this change for TD2 and TR3 separately. Also, changes are made to recover SrcIp, DstIp qualifiers without Ip4 qualifier being part of the Group's QSET.
SDK-49396	680823	56850_A0 56850_A1 56850_A2	Call user defined callback in <code>bcm_l3_nat_ingress_age</code> .
SDK-49402		88650_A0 88650_B0 88650_B1	Cannot dump <code>EPNI_AC_FORMAT</code> for banks different than 0, this issue have been solved.
SDK-49403		88650_A0	If the IPv4 Unicast table is located in the external TCAM (KBP), the handling of the IPv4 Multicast BiDir processing was missing.
SDK-49408	681629	88650_A0	Unnecessary dynamic allocation that cause run time overhead replaced by using the system's stack.

Table 75:

Number	CSP #	Chips	Release Notes For 6.3.2
SDK-49411	679277	56640_A0 56620_B0 56850_A0 56640_A1 56640_B0 56850_A1 56850_A2	Removed incorrect check for invalid virtual port number - 1 in <code>bcm_mpls_port_add()</code> API. This potentially fixes an issue that the API cannot create more than 31 VPWS ports due to the result of compiler dependent negative value shift operation.
SDK-49423		56851_A0 56852_A1 56852_A0 56853_A1 56853_A0 56850_A0 56855_A0 56854_B0 56854_A0 56850_A1 56851P_A1 56851_A1 56850_A2 56851_A2 56851P_A2 56854_A2 56853_A2 56852_A2 56855_A2	Fixed incorrect register access in <code>bcm_rx_queue_channel_get()</code> to read rx queue vs. channel mapping.
SDK-49427	682375	All	Leave CPU COS queue DMA mappings unchanged if warm-booting.
SDK-49431	680820	56150_A0	Support new port configuration, $24*1G+2*1/10G(TSC0)+2*1/10G(TSC1)$, of BCM56150, BCM56151 and BCM53346.
SDK-49435	681921	88650_A0 88650_B0 88650_B1	In Field Processor, the key-id allocation of the 2nd-lookup cascaded Field Group (i.e. with the qualifier <code>bcmFieldQualifyCascadedKeyValue</code> in its QSET) was always Key-A. This field group was superposing other Field groups already using the same Key-A by mistake. After the fix, an analysis is performed in the Driver to find the same Key-ID in all the PMF-Programs where this Field Group is present. The constraint of a unique Key-ID is specific to 2nd-lookup cascaded Field Groups: the Key-ID is written in the TCAM entry action when changing the cascaded value.
SDK-49436		88650_A0	Diagnostic "show counters full" BCM shell command wasn't functional for fabric links. Fixed.
SDK-49438		88650_A0	Calling <code>bcm_cosq_gport_bandwidth_set</code> with fabric clos fmq gport and max rate 0, caused segmentation fault. Fixed.
SDK-49457	683576	56850_A0	Atmost eight contiguous child nodes can be configured with schedule mode strict priority.
SDK-49459	681835	All	fixed 'snmpIfOutDiscards always returns BCM_E_PARAM for MXQports'
SDK-49463	683475	56150_A0	Add the support to enable bcm953150's QSGMII/SerDes to work at SGMII/SerDes mode.
SDK-49466		88650_A0	XGS programs in the programmable editor should be loaded only if at least one XGS port exists.
SDK-49483	683903	All	Sounds like TD+ from CSP
SDK-49485	684014	All 56850_A0 56850_A1 56850_A2	fix issue: deleting NAT egress entries incorrectly.
SDK-49489	680869	56640_A0 56540_A0	Aligned Module Id offset in LMEP.DEST field.
SDK-49499	684229	56450_A0	Provided patch files (as attachment) for 6.3.1 branch from HEAD-TOT(6.3.2) branch
SDK-49511	683836	88030_A0	fixed TMU chain hash delete issue for non-64 bits chained hash on bcm88030

Table 75:

Number	CSP #	Chips	Release Notes For 6.3.2
SDK-49528	684297	56851_A0 56852_A1 56852_A0 56853_A1 56853_A0 56850_A0 56855_A0 56854_B0 56854_A0 56850_A1 56851P_A1 56851_A1 56850_A2 56851_A2 56851P_A2 56854_A2 56853_A2 56852_A2 56855_A2	Added 10 bit ClassID for TD2 and TR3 devices in L3_ENTRY_IPV4_UNICAST and L3_ENTRY_1 respectively.
SDK-49532	684507	All	Fix BAD_PTR check for 64-bit pointers.
SDK-49546		All	Binaries output in systems/linux target folders has been replaced with soft-links to binaries in build directory in order to save space.
SDK-49550	684265	56820_A0 56820_B0	Support BCM_IPMC_HIT_CLEAR in firebolt ipmc.
SDK-49557		88650_A0	In TCAM, two shuffle methods are used: 1. "Old method": Each database has different set of entries, gathered by priority. For each new insertion, at the most one entry per group will be shuffled by being written in the new location and remove from the previous location. The number of shuffles is limited by the number of priorities. This method is used for non-FP TCAM Databases and Direct table databases since their number of entry priorities is limited. 2. "New method": use the HW TCAM command allowing to move a whole block of entries (data, mask and action) in one command. This method is used for FP databases, since the number of entry priorities may be huge. The Driver allows to use the "old method" for Field groups when setting the BCM_FIELD_GROUP_CREATE_SPARSE_ENTRY_PRIORITIES flag at their creation. This method is recommended if the user knows that the number of priorities used for this Database will be low, since it is an upper limit on the number of shuffles for each new entry insertion. It is recommended to use this flag with the BCM_FIELD_GROUP_CREATE_INSERTION_ORDER_LOOSE flag
SDK-49560		88650_A0	In Policer module, Meter configurations (meter profiles) are by default managed by the driver in the background. This simplifies the interface for the user by allowing the specification of configuration for a meter, without having to manage separate configurations as well as meters. New policer attributes (BCM_POLICER_REPLACE_SHARED and entropy_id) allows direct control over the meter configuration, called a meter profile. With this new API, changing the configuration of a meter profile can change the configurations of all meters that use this profile atomically. More details can be found in the user manual and in the CINT example cint_policer_metering_example.c

Table 75:

Number	CSP #	Chips	Release Notes For 6.3.2
SDK-49563		88650_A0	ITMH and RX Trap collision: Due to an HW constraint, the parsing of the ITMH snoop fields requires an equal number of RX user-defined traps previously allocated to the number of snoop commands. Thus, at init, the HW order of the user-defined traps is changed: 1. The User-defined HW traps indexes are changed. It may have an influence on the user when parsing the FTMH trap code in CPU packets 2. The 16 last user-defined traps are allocated by default at init for the ITMH.Snoop field parsing. If the user wants to increase the number of User-defined traps without using the whole Snoop field in ITMH, a control (bcmRxControlTmSnoopCount) is given to indicate the number of User-Defined traps to reserve for the TM
SDK-49570	660874	88650_A0	Fixed SGMII 10Mbps mode
SDK-49572		88750_A0 88750_B0	Default thresholds values at the DCM block (drop thresholds, GCI thresholds and fullalmost full thresholds) were not configured correctly during initialization. Fixed. Note: default configuration change. Applied upon cold boot only.
SDK-49573		56850_A0 56854_A0 56850_A1 56850_A2	Fixed AT_vxlan_08 related to Higig Proxy forwarding on TD2 hardware
SDK-49598	680786	88640_A0	In BCM88640, in Field Processor, the definition of the L4 ports (UDP / TCP Source and Destination ports) were set according to an offset from the IP header as base-header. To support their extraction even when the IP header has options, their definition is set according to base-header=header-after-IP.
SDK-49600		88650_A0	Add clearing IDR memory to avoid ECC errors upon initialization. The fix is committed under SDK-49166.
SDK-49607	685078	56640_A0 56640_A1 56640_B0	With this fix in SDK, OVID is supported as a key in ESM_L2_IPV4_ACL profile on TR3.
SDK-49620	684645	56850_A0	Fixed addition of a member to an empty LAG, Higig trunk or ECMP group, when resilient hashing is enabled. This fix is applicable to BCM56850 device.
SDK-49621	672357	88650_A0 88650_B0 88650_B1 88660_A0	When trying to delete one of first 257 CL SE using bcm_cosq_gport_delete API error is returned. Fixed.
SDK-49628		88650_A0 88650ACP_A0 88650_B0 88650_B1	In advanced VLAN edit mode, The VID value of the outer most tag for added or replaced VIDs, is always set according to the configured new outer VID. Therefore, if the outer most tag after a VLAN editing operation, was created due to Add or Replace VID actions (bcm_petra_vlan_translate_action_id_set), the VID value will be according to the new_outer_vlan value (configured by bcm_vlan_port_translation_set). In the same way, the VID value for the next tag is derived from new_inner_vlan value in case it's a result of Add or Replace VID actions. This logic is irrespective to whether the tag was created/modified by bcm_petra_vlan_translate_action_id_set using the dt_outer or dt_inner fields.
SDK-49633	685543	All 56639_A0 56636_A0 56634_A0 56638_B0 56636_B0 56634_B0	bcm_init() should work now for BCM56636 with DEBUG_IFDEFS=FALSE in make file

Table 75:

Number	CSP #	Chips	Release Notes For 6.3.2
SDK-49647		56850_A0	EFP bcmFieldQualifyForwardingVlan/vrf/Vpn qualifier initialization has been fixed for Trident2 device.
SDK-49653	683688	56334_B0 56334_A0	Fixed policer delete internal function.
SDK-49654	686137	All	bcm_esw_vlan_gport_delete/_all delete UMC_IDXf/UUC_IDXf when it's in wlan.
SDK-49672	686076	56850_A0	Introduced new flags to Drop or Copy IPMC packets to CPU on RPF failure
SDK-49679		All	Fixed Warmboot link flap issue on "exit clean"
SDK-49680	685195	56840_A0	bcm_vlan_control_vlan_set() API should now work with protocol packet control feature on the BCM56840 device
SDK-49681	671511	56334_B0 56334_A0	Corrected remote endpoint replace procedure.
SDK-49685	675798	56850_A2	Resolving bcm_td2_l3_ent_parse() tries to access NULL pointer issue which lead to SDK crash when we use bcm_l3_host_add().
SDK-49695	681301	88030_A0	improve taps lookup performance on bcm88030
SDK-49705		88650_A0	Configuring max burst using the following API with E2E gport is no longer supported. bcm_cosq_control_set(unit, gport, 0, bcmCosqControlBandwidthBurstMax, value). The API was not functional, now considered deprecated for E2E gport and will return error if called.
SDK-49731	685391	88650_A0 88650_B0 88650_B1	Source routed cell debug feature - generating source routed cells was not functional - fixed.
SDK-49732		88650_A0	A mutex-destroy was missing in soc_dfe_attachdetach, causing a memory leak. Fixed.
SDK-49736	685097	88650_B1	OAM DA MAC address should be identified as multicast only if LSB on 1st byte is 0x1 (and not if first byte value is 0x1)
SDK-49739	679590	88650_B1	L2GRE: Added support for GRE Tunnel Keepalives (Next-Protocol == 0). In that case, packet is not terminated and expected to forward the packet to CPU according to the packets DIP.
SDK-49744	680968	88650_A0	Device Soft Reset is used as a corrective action for some device interrupts. Device soft reset should not be triggered during an active DMA transaction. To insure this, we now take DMA mutexes/semaphores before performing Device Soft Reset.
SDK-49749		88030_A0	fix taps route delete not working for certain routes on bcm88030 device
SDK-49751	681330	56340_A0 56640_A1 56640_B0 56643_B0 56540_B0	Disable parity on PORT_OR_TRUNK_MAC_COUNT and PORT_OR_TRUNK_MAC_LIMIT.
SDK-49760		56150_A0	1. Double Wide Mode is not supported for VFP on HR2, removed the Support. 2. Fixed the VFP_KEY_CONTROL update implementation, it was overwritten by 2nd Part of the VFP TCAM during TCAM parts iteration.
SDK-49768	675820	56850_A0	bcm_port_ifg_set() API should now be able to configure the interframe gap parameter for the port speeds greater than 10G on BCM56850 switches

Table 75:

Number	CSP #	Chips	Release Notes For 6.3.2
SDK-49779		88650_A0	In Field processor, when the user is using the VLAN-Editing advanced mode (the SOC property <code>bcm886xx_vlan_translate_mode</code> is set to 1), the <code>param0</code> of the <code>bcmFieldActionVlanActionSetNew</code> action is the explicit HW VLAN-Edit-Command. <code>param1</code> is unused.
SDK-49783		88650_A0	Counter was not stamped on OAM upmep LMM injected packets
SDK-49784	686895	88650_B0	In a system with both VSC128 and VSC256 FAPs. Cells sent by VSC128 FAP was dropped at the egress of VSC256 ARAD_B0 device. Fixed.
SDK-49786	648116	88030_A0	Burst size will remain 1000 bit for 1k, fixed minor bugs in burst size calculation on bcm88030
SDK-49800		88650_A0 88650_B0	0 is a valid value of sip. Add a fix to support to bind sip 0 under ip anti-spoofing mode.
SDK-49802	687697	88650_A0 88650_B0 88650_B1	For non-Field Processor TCAM databases (e.g. IP TCAM databases), the entry insertion in the TCAM is done according to the entry content. An hash list is built internally to allocate a unique entry-id to each new entry content. When adding an existing entry to a full TCAM, the TCAM insertion function is returning an error without removing the existing entry. However, the existing entry was removed from the hash list, generating a mismatch between the TCAM state and the hash list state.
SDK-49818		56640_A0	56640_A0 : Added locks during counter accumulation..
SDK-49856	688600	56640_A0 56640_A1	SOURCE_FIELD_MASK in MY_STATION_TCAM is programmed correctly
SDK-49859	687640	88030_A0	support RCE table access API on bcm88030
SDK-49870		88650_A0	New PP diagnostics: diag alloc InLif/OutLif/FEC. Display used inlif, outlif or fec. diag pp GPort id=123. Display information about gport id. Existing resources for this gport id: inLif, outLif, fec, multicast id. diag pp CC. Display cross connection between inlif and outlif. (cross connection: an inlif is connected directly to an outlif, no need to mac table lookup)
SDK-49874	686953	88030_A0	The LP, OI, FT resource leak for MPLS LSR is fixed.
SDK-49876		88660_A0	Diagnostics shell improvement: If PQP_Discard or RQP_Discard counters are non-zero, diag count diagnostics command will display the reasons for discarding packets
SDK-49879	686328	88030_A0	Fixed taps update excessive error message on bcm88030.
SDK-49880	688875	56850_A0	Add WRED Time Domain configuration.
SDK-49881		56150_A0	Add timestamping support for Hurricane2: - Enable 2-step timestamping for packet TX/RX - <code>bcm_time_capture_get</code> to do immediate capture and read timestamp from FIFO
SDK-49886	688548	56850_A0	The L3_HG_HDR_SEL field is always set to 1 for the virtual port routing feature
SDK-49906		All	Avoid potential divide-by-zero when reading KNET Linux proc file <code>/proc/bcm/knet/debug</code> .
SDK-49912	683210	54640E_B0	The duplex setting in the SGMII slave mode is now correctly reported for BCM54640(E)/BCM682(E)/BCM685(E) PHYs.
SDK-49914	689580	56850_A0	Fixed L3 ingress replace when both <code>BCM_L3_INGRESS_REPLACE</code> and <code>BCM_L3_INGRESS_WITH_ID</code> flags are set



Table 75:

Number	CSP #	Chips	Release Notes For 6.3.2
SDK-49919	687667	88650_B1	Deleting VOQ connector using <code>bcm_cosq_gport_delete</code> wasn't saved in Warm Boot SW-DB. This could result in a WB error in some cases. The issue was fixed.
SDK-49921	688574	88650_A0 88650_B0 88650_B1	V-LAN fields in the <code>endpoint_info_t</code> struct must be consistent (either both the <code>tpid</code> and the <code>vlan</code> are 0 or neither one of them is zero) and the <code>tx_gport</code> must be a either invalid or a system port.
SDK-49939	688983	88650_A0	In TCAM, the database id of the Coupling LSR accessed at Termination block and Database 0 of ACL block (PMF) was identical. This is fixed.
SDK-49952	689261	56150_A0	Prevent 10G MAC been unable for packet transmit always after port is disabled.
SDK-49960	689627	56850_A0	<code>bcm_l3_egress_create</code> api supports the change operation in which the flags can also be modified. The flags can be unset by user application and thus has to be unset from the SDK/hw. the code to unset the flag was missing in sdk and therefore once set, the flags will always remain set. With this fix, SDK will always look into the incoming flags and set/unset the L3 flags. The user application has the onus to set/unset the flags according to its needs and always pass the flags which it wants to remain set. SDK does not maintain any local copy of flags.
SDK-49963	688347	56440_B0	TOQ memory needs to be updated in B0 when redirection pointer is modified.
SDK-49986		88650_A0	In Field Processor, the entry value settings for the actions <code>bcmFieldActionSrcGportNew</code> & <code>bcmFieldActionLearnSrcPortNew</code> were incorrect.
SDK-49987	686341	88650_B1	moved warmboot modules definitions to a central location to protect scache handlers from collisions.
SDK-49998	687589	56850_A0	Added additional check to make sure the correct node is picked up in case of Y pipe ports.
SDK-50008	690020	56850_A1	In the function <code>_bcm_tx_gport_resolve()</code> , the virtual port get is complete
SDK-50010		88650_A0	MPLS termination: added the ability to change the location of MPLS termination databases. In BCM886XX, there are up to three MPLS databases that reside in 2 physical databases SEM-A and SEM-B. SOC property: <code>bcm886xx_mpls_termination_database_mode</code>
SDK-50027		88650_A0	In Field Processor, the action allocation for Ingress TCAM Field groups is done via HW FES machines. Due to HW constraints related to FES, the <code>bcmFieldActionClassDestSet</code> & <code>bcmFieldActionClassSourceSet</code> actions are limited to 31b in their action value when used for TCAM Field groups.
SDK-50050	691203	88650_A0 88650_B0 88650_B1	In the Counter processor module, the DMA access was not disabled during the counter processor detach, causing DMA transactions even after the device was detached.

Table 75:

Number	CSP #	Chips	Release Notes For 6.3.2
SDK-50077		88650_A0 88650_B0 88650_B1 88660_A0	To define VOQ as a "Push Queue" you need to call: bcm_cosq_gport_sched_set(unit, VOQ, cosq.BCM_COSQ_DELAY_TOLERANCE_15, 0) This stopped working in release 6.2.2. This was fixed to work again. Now bcm_cosq_delay_tolerance_level_set /get(unit, BCM_COSQ_DELAY_TOLERANCE_15, &delay_tolerance); will return an error. This is since BCM_COSQ_DELAY_TOLERANCE_15 represents push queues and not a credit request profile which can be changed.
SDK-50078	690440	All 88030_A0	The problem was that the packet was going to exception stream since an invalid value was returned by v6sa table. The reason for this issue was that there was no default route for on chip mode. This is now fixed by inserting a default entry 0/0.
SDK-50086	691136	56440_A0 56440_A1 56440_B0	Fixed issue with non-zero modid for bcmFieldActionFabricQueue for BCM5644x devices.
SDK-50100	692001	56450_A0	Allocated memory for all (including unused) port at init time so that when ports are created fresh with flex-io operations, NULL pointer situation will not arise.
SDK-50116		56850_A0	Added support for creating multicast L3 egress object on virtual ports. Please see the bcm_l3_egress_create API description for more details.
SDK-50120	681772	88650_B1	bcmVlanPortDoubleLookupEnable: In case port supports double lookup (Port x VLAN x VLAN and Port x VLAN), Untagged and priority tag packets were dropped. Added a new program selection and program to take care of untagged and priority tag packets
SDK-50123		88650_A0	In L2 module, the MACT entry insertion performance has been improved.
SDK-50135	662939	88650_A0	Trap strength remain with its default value of 4, and was not changed while using bcm_l2_cache APIs
SDK-50140		All	(1) soc properties now have whitespace stripped before being parsed, so "x = 7" is equivalent to "x=7". (2) "make propgen" now creates a big list of all valid properties in property.h, and sal_config_refresh uses the list to determine if a given property is valid, and displays a warning when invalid ones are set (3) A new soc property can be set to suppress the warnings from item #2: suppress_unknown_prop_warnings=1 Code review #11759
SDK-50159	692837	56850_A0 56850_A1 56850_A2	Resolved SDK crash when "show pci" diag shell command is run without probing any device.
SDK-50177		88650_A0 88650_B0 88650_B1 88660_A0	diag EGQ graphic displayed TCG bandwidth 0 as unlimited. Fix to display 0.
SDK-50198	691823	88650_B1	IP packets with Priority tag packets: Fixed IPV4oE packet with priority tag (VLAN = 0) to classify according to initial-VID.
SDK-50221	693418	88650_A0	During the detach of the Counter Processor module (bcm_dpp_counter_detach), the background SW counter thread must be de-initialized only if it was initialized. This was not the case.
SDK-50257	689596	88030_A0	fix 8x10G+16x1G linerate issue on bcm88030



Table 75:

Number	CSP #	Chips	Release Notes For 6.3.2
SDK-50286	690665	56150_A0	Fixed the incorrect number of meter pairs per slice for Hurricane2.
SDK-50287	692402	56150_A0 56450_A0 56340_A0	Added iProc support for VxWorks BDE on Keystone processor.
SDK-50294		88650_A0	In IP TCAM management, when all the IP route entries of a TCAM bank were removed from a TCAM bank, the bank was not freed for other purposes than IP. Now it can be used also for Ingress/Egress PMF or Termination (VTT).
SDK-50301		56845_B0 56845_A2 56840_A0 56640_A0 56644_A0 56850_A0 56843_B0 56841_A3 56841_B0 56850_A1	Trill Payload offset base is supported in UDF
SDK-50417		88650_A0	While loading SerDes firmware using SoC property <code>load_firmware=2</code> (fast load), the initialization sequence might fail in a multistage environment (Few devices controlled by the same CPU). Fixed.
SDK-50424		88650_A0 88650_B0 88650_B1 88660_A0	VLAN: In case match criteria is <code>BCM_VLAN_PORT_MATCH_NONE</code> , <code>bcm_vlan_port_create</code> add an ESEM entry while it shouldn't. Bug fix was to eliminate the addition of ESEM entry. To add entries to ESEM in that case should be done using <code>bcm_port_match_add</code> .
SDK-50428		88750_A0	Fixed possible memory leak when <code>soc_dfe_init</code> fails.
SDK-50439	695545	88030_A0	Has been implemented already (see MDEStatementView in Multistream Editor Prespective)
SDK-50448		56640_A0	The API Guide is updated regarding warm boot support.
SDK-50461	696000	56450_A0	For BCM5645x device, added fix for port property configuration which was missing after flex IO swap from xau1 to 4xGE
SDK-50480		88650_A0 88650_B1	Warmboot feature should now work for devices !=0 it didnt work due to hard coded 0 "prime_handle" field in sand data structures. changed the field to equal <code>device_id</code>
SDK-50503	696244	88650_A0	SMPFullLevel1, SMPFullLevel2 and FCTFIFOvf interrupts are not cleared correctly. this issue is solved.
SDK-50552		88660_A0	In PMF HW-block, the default action in Arad+ was to set the PCP-DEI value to 0 instead of doing nothing. It implied that Ingress-VLAN-Editing with a new non-zero value of PCP or DEI was faulty.
SDK-50586	697601	88030_A0	Low 32register and high 32register has been swapped for LrpEditor tooltip.
SDK-50609		88650_A0 88650_B0 88650_B1	L2 PON: Flush database isn't set to be invalid after flushing action done by "l2 clear all". Issue caused traffic to drop after l2 clear all. Issue is now fixed.
SDK-50744	699029	88650_A0	OAM warmboot SW database allocated 67125248 entries instead of 16K
SDK-50856		56640_A0 56850_A0 56150_A0 56340_A0 56640_B0	CMICm-based devices (XGS5) no longer require any calls to the BCM Rx API when the Linux KNET module is configured to use socket buffers for DMA (<code>use_rx_skb=1</code>).
SDK-50870	694419	56640_A0 56850_A0 56640_A1 56640_B0	Unlock semaphore correctly in <code>bcm_tr2_vlan_gport_add()</code> .
SDK-51003		56850_A0	N/A



Table 75:

<i>Number</i>	<i>CSP #</i>	<i>Chips</i>	<i>Release Notes For 6.3.2</i>
SDK-51755	713642	88650_A0 88650_B0 88650_B1 88660_A0	System resources FEC remove: The API <code>bcm_vlan_port_destroy()</code> enables deletion of VLAN-Ports as well as protection FEC IDs. The API failed when a FEC ID was the supplied <code>gport_id</code> .
SDK-51797	716343	56850_A0	Application can use <code>BCM_PORT_PHY_CONTROL_TX_LANE_SQUELCH</code> before enabling mac loopback to avoid noise on the link.

Section 14: Resolved Issues for 6.3.1

The following issues are resolved in version 6.3.1 of the SDK.

Table 76:

Number	CSP #	Chips	Release Notes For 6.3.1
SDK-20665		All	Fix 'bcm_field_qualify_InnerIp6HopLimit' and 'bcm_field_qualify_InnerIp6NextHeader_get' API support for XGS devices.
SDK-30093		All	Update modular debug print interface to support management by external application. Previously the modular debug print interface could only be controlled via the Broadcom CLI.
SDK-34767	434653	56548_A0 56546_A0 56545_A0 56544_A0 56542_A0 56541_A0 56540_A0 56526_A0 56524_A0 56521_A0 56545_A1 56526_B0 56524_B0 56540_B0 56541_B0 56546_B0	Fixed auto addition of InPort/InPorts qualifier in group's QSET during warm start.
SDK-35130	441537	56639_A0 56638_A0 56636_A0 56634_A0	Modified field processor entry reinstall to update only the policy table without modifying the TCAM table
SDK-36480		88650_A0 88640_A0	Added support for System Red in BCM SDK. For more details please reference System RED section in UM.
SDK-38173		56840_A0	TERR in snmpIfOutErrors counter
SDK-39043	513610	All	AllChips: Preserve DROP and COPYTOCPU CML flags during L2 freeze.
SDK-39202 SDK-42621		56640_A0 56540_A0	Fixed bcmFieldActionCopyToCpu action support for Triumph3 Stage Egress.
SDK-39512		88650_A0	88650: bcm_port_local_ability_get - should return bitmap in the field of full_duplex instead of the maximum speed
SDK-39576		56846_A0	Set/Get value mismatch for port control bcmPortControlPrbsRxEnable
SDK-39784		56840_A0 56640_A0 56440_A0	Added support for flag BCM_L2_REPLACE_AGE to perform selective aging on L2 entries using L2_BULK_CONTROL
SDK-40510		88650_A0	Dump NBI tables through diag shell was fixed
SDK-41648	555907	88650_A0	MACT learning management: 1. Provided BCM API to handle the MACT events directly by Host CPU without the intervention of OLP. please refer to cint_l2_cpu_learning.c for example to use. 2. In order to enable Host CPU learning use bcm_l2_addr_msg_distribute_set. Parsing DSP packets examples can be seen in rx_nonintr_callback().
SDK-41680	560553	All	gcc warnings resolved



Table 76:

Number	CSP #	Chips	Release Notes For 6.3.1
SDK-41788	558335	56440_A0	Added support for micro meter creation with different policer group modes.
SDK-41793	554763	88650_A0	MACT traverse: add new API to traverse MACT entries match given rule with masking. new API added <code>bcm_l2_replace_match</code> . Example of usage: <code>SDKsrcexamplesdppcint_mact_bulk_operations.c</code> : <code>mact_bulk_rule_mask_vlan_example</code>
SDK-42140	566499	56840_A0	Made below actions as color independent actions <code>bcmFieldActionColorIndependent</code> <code>bcmFieldActionL3ChangeVlan</code> <code>bcmFieldActionL3ChangeVlanCancel</code> <code>bcmFieldActionL3ChangeMacDa</code> <code>bcmFieldActionSrcMacNew</code> <code>bcmFieldActionDstMacNew</code> <code>bcmFieldActionL3ChangeMacDaCancel</code> <code>bcmFieldActionL3Switch</code> <code>bcmFieldActionL3SwitchCancel</code> <code>bcmFieldActionAddClassTag</code> <code>bcmFieldActionOuterVlanNew</code> <code>bcmFieldActionRedirectVlan</code> <code>bcmFieldActionRedirectMcast</code> <code>bcmFieldActionRedirectIpmc</code> <code>bcmFieldActionEgressPortsAdd</code> <code>bcmFieldActionEgressMask</code> <code>bcmFieldActionRedirectCancel</code> <code>bcmFieldActionRedirect</code> <code>bcmFieldActionRedirectTrunk</code> <code>bcmFieldActionRedirectEgrNextHop</code> <code>bcmFieldActionVnTagNew</code> <code>bcmFieldActionVnTagDelete</code> <code>bcmFieldActionRedirectPbmp</code> <code>bcmFieldActionOffloadRedirect</code> <code>bcmFieldActionRedirectBcastPbmp</code> <code>bcmFieldActionFabricQueue</code> <code>bcmFieldActionMirrorEgress</code>
SDK-42313	569643	88650_A0 88650_B1	The mirroring probability of a mirror destination is set using the two new fields of the <code>bcm_mirror_destination_t</code> structure listed below. They are passed to <code>bcm_mirror_destination_create()</code> when creating the destination. <code>uint32 sample_rate_dividend; /* The probability of mirroring a packet is: sample_rate_dividend >= sample_rate_divisor ? 1: sample_rate_dividend / sample_rate_divisor */uint32 sample_rate_divisor; /* For Arad we recommend a divisor of 0x10000 which matches the resolution that the hardware can provide */</code>
SDK-42318	569513	All	Incorrect <code>otmh_extensions.en.outlif_ext_en</code> was used when not using FTMH extension with mesh. The incorrect extension used was <code>PETRA_PORTS_FTMH_EXT_OUTLIF_IF_M C</code> . This is now changed to <code>PETRA_PORTS_FTMH_EXT_OUTLIF_NEVE R</code> .



Table 76:

Number	CSP #	Chips	Release Notes For 6.3.1
SDK-42377	483568	56840_A0	Add the support to enable/disable the event of L2_OVERFLOW and the dealing process for L2_OVERFLOW event, which will call the related callback routines.
SDK-42895	579601	56640_A0 56541_A0	Using BCM_OAM_GROUP_REPLACE flag was causing creation of a new OAM group, this has been fixed and BCM_OAM_GROUP_REPLACE now updates the existing group instead of creating a new one.
SDK-42962	581130	56440_A0	bcm_field_qualify_data_get API is now supported for Katana and Katana2 devices.
SDK-43000	568920	88030_A0	Support software linkscan
SDK-43051	581274	All	Removed duplicate comments in release notes.
SDK-43078	572351	88650_A0	Enable Mirroring to other TM domain port in stacking system.
SDK-43094		88650_A0	Fixed incorrect configuration when working ILKN+XMAC under same MLDCLP. Note: ILKN reserve 8 lanes also when it uses less than 8 lanes. So only upper XMAC can be used for bob-ILKN ports.
SDK-43210 SDK-43201	583727	56850_A0	Change code to allow XLMAC to support 20G front panel port.
SDK-43230	584608	88750_A0	88750: BCM88750 endianness configuration has been changed to be identical to BCM88650 endianness configuration. Wrong configuration of the endianness can cause access failures at the initialization sequence/ access tests. BCM88750 will not support soc property 'system_set_dma_low_endianness'. Instead endianness configuration will be done using soc_cm_device_init (unit, and dev_vectors). PCI specific endianness: dev_vectors.big_endian_pio - Must be set to 1 if CPU register read/write operations are big endian, or 0 otherwise. dev_vectors.big_endian_other - Must be set to 1 if non-packet DMA operations are big endian, or 0 otherwise. Broadcom application reference configure endian parameters (dev_vectors.big_endian_pio and dev_vectors.big_endian) according to compilations flags: SYS_BE_PIO and SYS_BE_OTHER.
SDK-43330 SDK-48305	584507	56850_A0	release version is 6.3.1
SDK-43342	586043	56744_A0	BCM diag shell command "cos show" should now work on BCM56840 type switch devices
SDK-43361		NA	1. Increased the size of the (_BCM_CLI_STAT_ARR_SIZE) macro to print all stat enumerations. 2. Made changes in diag shell parser code to print strings correctly.
SDK-43389	580332	All	Add support for remote loopback for xgxl6g11 driver
SDK-43459		88650_A0	state of bcmSwitchControlAutoSync is no longer lost, user doesnt need to re-configure it any more.
SDK-43485	583737	88650_A0	88650: Unidirectional traffic loss in mesh configuration. The driver fixed to reconfigure MESH_TOPOLOGY block according to system properties. All the fabric links must configured to the same encoding and speed. The registers are reconfigured automatically in case of changing the speed or the encoding.



Table 76:

Number	CSP #	Chips	Release Notes For 6.3.1
SDK-43523	588139	56643_A0 56643_A1	Added support for OAM Y.1731 Loss and Delay Measurement.
SDK-43535		88650_A0	Diagnostics: All diag pp commands can be retrieved by entering "diag pp ?" in BCM shell.
SDK-43667		88750_B0 88650_B0 88650_B1	Add new SOC API and UI to get the device AVS (= Adjustable Voltage Scaling) .
SDK-43760		56840_A0 56850_A0	Fixed trill port resolution for Empty ECMP group
SDK-43883		88650_A0 88650_B0 88650_B1	Added support for EVB application. Please see more information in the CINT example <code>src/examples/dpp/cint_evb_example.c</code>
SDK-44018	566118	88640_A0	Flooding traffic transmitted out from one port of LAG members. This port is selected from the FTMH. A new soc property <code>system_ftmh_load_balancing_ext_mode.BCM88640</code> is added to support this feature.
SDK-44053	584161	56640_A0 56850_A0 56640_B0 56440_B0	Made changes in <code>bcm_rx_redirect_reasons_set</code> function to configure all entries of <code>CMIC_PKT_REASON_{0/1}_TYPE[0:15]</code> register with valid reason codes.
SDK-44081		88650_A0 88650_B0 88650_B1	Added <code>soc_ppd_frwrdd_trill_multicast_source_get</code> . The BCM implementation needs API changes.
SDK-44122		88650_A0 88650_B0 88650_B1	All vlan/mppls/mim_port APIs that support the REPLACE flag follow the defined guidelines: Usage of the WITH_ID flag without the REPLACE flag allowed only for non-existent ports. Usage of the WITH_ID with the REPLACE flag allowed only for existing ports of the required type. Usage of the REPLACE flag without the WITH_ID flag isn't allowed. A REPLACE operation will be allowed only for parameters that dont participate in the appropriate table key, and for parameters that dont allocate resources. Other replace APIs will follow those guidelines whenever it's possible.
SDK-44125	598954	88650_A0	Added support for probability of mirror destinations. The probability is specified using two new fields of <code>bcm_mirror_destination_t: uint32 sample_rate_dividend; /* The probability of mirroring a packet is: sample_rate_dividend >= sample_rate_divisor ? 1: sample_rate_dividend / sample_rate_divisor */uint32 sample_rate_divisor;</code> The recommended value of <code>sample_rate_divisor</code> is 0x10000 to match the hardware resolution.

Table 76:

Number	CSP #	Chips	Release Notes For 6.3.1
SDK-44186	599876	56640_A0 56640_A1 56640_B0	Added support for following qualifiers for Triumph3 External Stage bcmFieldQualifySrcClassL2 bcmFieldQualifySrcClassL3 bcmFieldQualifySrcClassField bcmFieldQualifyDstClassL2 bcmFieldQualifyDstClassL3 bcmFieldQualifyDstClassField bcmFieldQualifyInterfaceClassPort bcmFieldQualifyInterfaceClassL3 bcmFieldQualifyInterfaceClassL2
SDK-44200	599325	56850_A1 56850_A0	Fix code to prevent disabling CPU port through pbmp_valid.
SDK-44277		All	Fixed using uninitialized values during SOC INIT of the Out Fabric Port rates channelized arbiters.
SDK-44291	601612	56440_A0	Included the code for GRRPKT and GRRBYT
SDK-44410	600714	56840_A0	Fixed the validation of the classification tag value.
SDK-44418		88750_A0 88650_A0 88640_A0	fixed the compilation error, the code now compiles successfully when compiling with BCM_WARM_BOOT_SUPPORT and without BCM_WARM_BOOT_SUPPORT_SW_DUMP.
SDK-44466		56340_A0	Stacking support for BCM956340K added.
SDK-44476		56840_A0 56850_A0 56841_B0 56850_A1	Soft-Error Recovery support added for TCAM tables on BCM5684x and BCM5685x devices.
SDK-44485		88650_A0 56640_B0	Disable cl73 bam while cl73 is enabled
SDK-44552		88650_A0	The field code which is part of the configuration necessary to operate in the mode of 32K I-SIDs for Mac-in-Mac was moved to a cint (cint_field_mim_32k_isids.c). Customers using this mode must run the cint before making any MiM configurations.
SDK-44564 SDK-45299	605416	56850_A1	TD2. Added flexibility in SP node configuration and corrected bugs during Node attach, affecting existing SP children of the current Node's siblings.
SDK-44582		NA	N/A
SDK-44602		88650_A0	Added support for Warmboot for Mac-In-Mac
SDK-44605	608221	88650_A0	Fixed setting dtm_flow_mapping_mode_region configuration, So there is no need to configure at least one region of type 2.
SDK-44616	608210	88650_A0 88640_A0 88650_B0	VLAN: Fixed a bug where bcm_vlan_translate_action_traverse did not traverse over the actual correct vlan_translate actions.
SDK-44674		88750_A0 88650_A0 88640_A0	Replaces all 'static' declaration on functions with 'STATIC' in DNX code
SDK-44733		All	Improved portability to non-POSIX platforms that do not support File IO.
SDK-44749		88650_A0	Fixed using uninitialized values in template manager during BCM INIT; uninitialized values in vsq rate cls: the field wred_ignore_packet_size insize_exact_rate_class_info, was not set.
SDK-44750		88650_A0	memory overrun at warmboot: writes & read immediately after allocated memory. Fixed offset for memory write in template manager warmboot.

Table 76:

Number	CSP #	Chips	Release Notes For 6.3.1
SDK-44802 SDK-45614	608366	88650_A0	Support 2-pass solution for Trill-MC: New implementation used 1st pass in the ARAD to send copies to next-hop RBridges. If directly connected hosts are attached, a copy is snooped to recycle port, and packet is bridged during 2nd pass in the Arad. Example: See <code>cint_trill.c</code> , <code>trill_mc_transit_fecless_config</code> . Configured port 40 is recycling port is also required for this example. Known issue: When there is no match in the MACT in the 2nd pass and the packet is flooded, copies that go back to the trill network are not filtered (bounce-back filter).
SDK-44822		All	Fix to remove unnecessary lock of stack in API <code>bcm_ptp_time_format_set()</code> .
SDK-44824		All	Added error check for the function.
SDK-44848		56450_A0	1.MMU settings corrected for 10G and CPU port. Following issues are fixed. a. 10G ports was being allocated the same amount of headroom as the 1G ports. b. CPU queues was always being bound to internal memory. 2. Corrected the default THDO_OPNCONFIG programming
SDK-44863	609656	56840_A0	The memory allocated is released and reallocated to prevent under-runs(if any).
SDK-44891		56634_A0 56440_A0	N/A
SDK-44911	610117	56850_A0	Added new actions "bcmFieldActionIngSampleEnable" and "bcmFieldActionEgrSampleEnable" to control Ingress and Egress SFLOW sampling in Ingress Field Processor.
SDK-44922		88650_A0	Compilation error when compiling ARAD for PCID
SDK-44982		88650_A0	Adding <code>bcm_oam_group_traverse</code> and <code>bcm_oam_endpoint_traverse</code> apis
SDK-44988 SDK-47952		88650_A0	OAM Warmboot support
SDK-44995	553755	88650_A0	Support MACT entries traverse/replace according to group-id Example <code>cint_mact_bulk_operations.c</code>
SDK-45009	608116	All	Support the following Soft Reset modes: <code>SOC_DPP_RESET_MODE_BLOCKS_AND_FA</code> <code>BRIC_SOFT_RESET 0x100</code> <code>SOC_DPP_RESET_MODE_BLOCKS_AND_FA</code> <code>BRIC_SOFT_INGRESS_RESET 0x200</code> <code>SOC_DPP_RESET_MODE_BLOCKS_AND_FA</code> <code>BRIC_SOFT_EGRESS_RESET 0x400</code> Change Arad traffic disable sequence, mainly Fabric traffic stop (instead of packet discarding, trap packets) to avoid Fabric Irrecoverable states.
SDK-45012		56224_B0 56224_A0 56018_A2 56018_A0 56018_A1 56014_A2 56014_A1	Memory Leak in <code>_field_raven_stage_reinit()</code> function for Raven is Fixed.

Table 76:

Number	CSP #	Chips	Release Notes For 6.3.1
SDK-45019		88650_A0 88650_B0 88650_B1	MPLS: The WITH_ID and REPLACE functionalities are now supported for the following features with the following flags: bcm_mpls_tunnel_switch_create: Add flag BCM_MPLS_SWITCH_REPLACE Add flag BCM_MPLS_SWITCH_WITH_ID bcm_mpls_tunnel_initiator_create: Add flag BCM_MPLS_EGRESS_LABEL_REPLACE Add flag BCM_MPLS_EGRESS_LABEL_WITH_ID
SDK-45047		56840_A0 56640_B0 56850_A1	56840, 56640: Handle L2 BULK operation during SER.
SDK-45090	607085	88650_A0	Added support for creation of composite FQ and HR aggregates, as part of the end-to-end scheduler hierarchy. Creating composite aggregates is possible only in region type 2. To configure a region to type 2, use the following SOC property: dtm_flow_mapping_mode_region_<region_id>.BCM88650=2 Please be advised that there are dependencies between available resources of VOQ connectors and composite SEs in region type 2 - please refer to Arad user manual documentation for details.
SDK-45117		All	Changed an assert() in declaration parameter checking to an error return.
SDK-45138		56440_A0	Fixed LED Scan issue in Katana, when one or more GPORT blocks are disabled.
SDK-45143	556970	84064_A0	Properly handle HiGig packets while in reverse mode
SDK-45148		56725_A0 56720_A0	SOC Port Valid check is applied to avoid the segmentation fault as it exceeds the MAX limit and corrupts the stack. The issue is seen only in case of CONQUEROR.
SDK-45154 PHY-883	607244	54380_B0	Cable diag for BCM543xx/BCM532xx returns with error "operation failed" fixed
SDK-45163	509662	88750_A0	In "phy diag eyescan" shell command, add the option to set the eyescan counter parameter as a string.
SDK-45168	611724	88650_A0	Fixed API's bcm_port_enable_set failures to clear queues when disabling a port.
SDK-45194	612584	56334_B0	Add switch control 'bcmSwitchWredForAllPkts' to apply WRED per color profiles on all packets for Enduro.
SDK-45215		88650_A0	API bcm_stat_get for ILKN port did not take into consideration interleaving, resulting in incorrect counter values - fixed.
SDK-45217		88650_A0	ARAD: Fixed the unexpected return value for external phy that doesn't support remote loopback.
SDK-45249	611829	88030_A0	Add "QueueInfo" command for C3
SDK-45263	615806	56850_A0 56850_A1	Add the support of L2 overflow for Trident2.
SDK-45265		88650_A0	VLAN translation: bcm_vlan_translate_egress_action_delete did not update correctly VLAN_PORT unmap action-id once action is deleted. This caused error on bcm_vlan_translate_egress_action_add right after delete on the same VLAN_PORT. The issue is now fixed.



Table 76:

Number	CSP #	Chips	Release Notes For 6.3.1
SDK-45267	613345	88650_A0 88650_B0 88650_B1	Egress editor for ARAD-XGS MAC extender boards: Added new program combining xgs MAC extension and SPAN
SDK-45276		88650_A0	MACT: Support multiple match rules in one Hardware traverse API: New switch control bcmSwitchTraverseMode with values according bcm_switch_table_update_mode_t enumeration.
SDK-45296	613481	88650_A0	In TCAM management, the user can define databases (Field groups in FP) and add entries but does not set explicitly the location of the resources. The TCAM management handles them. After allocating multiple entries and destroyed part of them, the user can compress the Database in FP via a new supported API: bcm_field_group_compress. Besides, during the attribution of a new bank, an optimization is implemented to balance the load of the Database between the adjacent banks.
SDK-45304	603917	88650_A0	IPv4: dumping IPv4 host table run into dead loop in some cases.
SDK-45307	616535	88650_B0 88650_B1	Fix Enable EGQ-Reassembly misconfiguration, that could potentially lead to MulticastTraffic being dropped between FRD and RQP
SDK-45335		56850_A0 56850_A1	Turn off Trill and NIV counter parity in TD2 A1 due to TD2-3465.
SDK-45352 SDK-44428		All	Changed the description of the Enum 'bcmFieldActionOuterTpidNew' to the right meaningful sentence in sdk/doc/grog/api/field.grg.
SDK-45358	616935	5389_A0	Fixed the issue that some enums of register/field/ memory were not properly wrapped with the INDEX() macro for Robo SDK.
SDK-45373	617575	56840_A0 56850_A0 56854_B0	support for Matching SRC mod/port for a trunk member is added
SDK-45387	617450	56640_B0	All the HIT fields are processed
SDK-45393	618025	56850_A0 56850_A1	Fixed BCM56850 default trust DSCP ptr value.
SDK-45394	570376	88650_A0 88650_B0 88650_B1	ARAD 88650 print_flow_and_up command used to fail during heavy traffic. problem solved with addition of FQP bubbling configuration.
SDK-45419		56046_B0 56045_B0	Added FP support (all stages) for Ranger+ (BCM56045/BCM56046) device
SDK-45475		88650_A0	Background: IPv4 MC program may do RPF check as well as MC entry search. In that case the search is done in the IPv4 UC tables. Limitation: When using ELK for IPv4 MC tables - then IPv4 UC tables should use ELK as well for the RPF check to succeed. Same happens when IPv4 MC doesn't use ELK. The driver forces the use of ELK for both tables or none (will produce an error if MC table uses ELK but UC table doesn't or the opposite).
SDK-45480		88650_B0 88650_B1	NVGRE MC: Added support for 2-pass solution for NVGRE MC. On first pass, multicast is according to IP header. One packet is snoop to recycle port (using FP APIs). On second pass, multicast is according to inner Ethernet header.
SDK-45484	608351	56440_A0 56440_B0	Enabled bcm_mpls_port_add to accept Next Hop egress port is of type Unicast Subscriber Queue.



Table 76:

Number	CSP #	Chips	Release Notes For 6.3.1
SDK-45523		All 56850_A0 56850_A1	Fix PGW_MAC_RSV_MASK programming on BCM5685x.
SDK-45545	605346	56620_B0	Fixed incorrect new inner vlan assignment for bcm_vlan_translate_action_add() API on bcm56620 type switch devices
SDK-45547		56636_A0	bcmFieldActionL3IngressSet Action is added to set L3_IIF from vfp
SDK-45549		56636_A0	New Action bcmFieldActionL3IngressSet is added to set L3_IIF from VFP
SDK-45577	616395	88650_A0	The bug was ,when statistic interface defined as 4 lanes port and stat_if_enable flag is set, then the interface would not work well. It was fixed in the code that determines if the statistic interface is Rxau14, Rxau15 or else.
SDK-45598		88650_B0	MIM learning implementation was changed. Lookup done for Learning moved from LLR to FLP. Learning lookup includes In-Port, BVID and BSA and not only BVID,BSA as before. To support the learning sequence, FP rules were introduced. Please see the additional FP settings of MIM learning in cint_mim_mp.c , cint_field_mim_learn_info_set.c
SDK-45601	612031	56840_A0	Use vp-less MPLS port to support the software based failover for switch devices such as BCM56680
SDK-45604	617859	88030_A0	Added traverse routines for LPM Taps.
SDK-45606		All	bcm_attach() could segfault if called from multiple threads.
SDK-45607		All	bcm_detach() could crash while BCM calls are active in other threads. This has been fixed.
SDK-45609		All	bcm_pkt_flags_init() now track if BCM API calls are active.
SDK-45612		All	bcm_esw_stk_init() erroneously using BCM_IS_LOCAL
SDK-45618		88650_A0	Ingress-Egress Cascaded Field Processor is a useful ability to transmit data from ingress FP to Egress. This can be Egress FP or Egress Editor. This feature is based on configurable User-Headers that are added in the fabric between the system headers (FTMH, PPH) and the network headers. The register configuration to retrieve the location of these headers in the packet are different in Arad-A0, and thus this feature is not supported on Arad-A0
SDK-45626		88650_A0 88650_B0 88650_B1	MAC-in-MAC: Function bcm_mim_port_delete() returns error value E_PARAM by mistake. Fix includes proper use of soc_ppd_soc in bmac_key construction, which is used to access the bmac and remove the entry.
SDK-45627		88650_A0	88650: RX LOS application - The default value stand for the time the application waiting between RX sequence restart and link up check should be bigger. The time required for link with autoneg is bigger. Fix: Default value of "short sleep" changed to 500000 micro seconds
SDK-45634		88650_A0 88650_B0	PON: Added support to have the option of ingress learning mode when PON L3 Source-bind is enabled.
SDK-45638	619034	56640_A0 56640_A1	FP counter wrap if fixed

Table 76:

Number	CSP #	Chips	Release Notes For 6.3.1
SDK-45640		88650_A0	In Petra-B compatibility mode, the packets have all a Petra-B FTMH packet format to enable smooth data path between Petra-B (88640) and Arad (88650) devices. However, both ITMH and OTMH headers are according to the device (in Petra-B mode in Petra-B devices, in Arad mode in Arad devices).
SDK-45642		56640_A0 56314_A0 56641_A0 56642_A0 56643_A0 56644_A0 56645_A0 56648_A0 56640_A1 56643_A1 56644_A1 56640_B0 56644_B0 56643_B0 56648_B0 56649_B0 56649_A0	Fix to configure meter settings in valid meter locations.
SDK-45648		88650_A0	bcm_port_stat_get get local port -gport as parameter
SDK-45654		56624_B0	srcTrunk Qualifier on HIGIG port is corrected.
SDK-45658		88650_A0	In stacking application, the "egress device" receives packets starting with their original FTMH (the one built in the first device). In Petra-B mode, the FTMH is a Petra-B FTMH. The Multicast-ID extracted was of 16b instead of only 14b Multicast-ID.
SDK-45660	618207	56648_B0	At the ingress stage (IFP) changed counter hardware allocation logic in the implementation of bcm_field_entry_prio_set API.
SDK-45661	611636	88650_A0 88650_B0 88650_B1	Double tagged frame with outer-tag being priority tag (VLAN = 0) should be forwarded according to Initial-VID and not the inner-vlan.
SDK-45668		88650_A0 88660_A0 88650_B0 88650_B1	VLAN-port: Introduce new settings to enable/disable Same-interface filter per Incoming-LIF. In case SOC property bcm886xx_logical_interface_bridge_filter_enable is set, then a property of the Incoming-LIF (1b from the In-Lif-Profile) is used to denote Same-interface-filter-Enable. Per Incoming-LIF user can disable same-interface-filter (using bcmPortControlBridge) and is qualified/ set with bcmField*IngressVPortBridgeDisable. In case same interface filter per Incoming-LIF is set then LIF-profile is encoded in only 3 bits instead of 4. The LSB bit is taken for the Same-interface-filter. In ARAD, user needs to have additional FP settings to enable same-interface per Incoming LIF functionality, see an example of settings in: cint_field_learn_data_rebuild.c An example functionality that use Same-interface-filter is EVB (Reflective-Relay enable). For more information see cint_evb_example.c
SDK-45680	618979	All	Remove statistic interface from the list of NIFs in the linkscan test(TR60)
SDK-45682		56850_A0	Allow preemphasis setting per lane based on SOC_PHY_CONTROL_PREEMPHASIS_LANE [0-3] or per port based on SOC_PHY_CONTROL_PREEMPHASIS through API.

Table 76:

Number	CSP #	Chips	Release Notes For 6.3.1
SDK-45709		88650_A0	Shared pool assignment in case of number of priorities = 0 is fixed
SDK-45710	599083	88030_A0	Check that configured epoch length does not exceed actual epoch length. This only applies if the user specifies the epoch length and epoch extension is not used. Example error message: Error! [51055] inject->2:0->1.0 = Actual epoch length 147 does not equal configured epoch length 100
SDK-45718	618015	88030_A0	PSC functionality added to C3.
SDK-45730	619631	56440_A0 56440_A1	Added new configurations for Katana.
SDK-45745		88750_A0 88650_A0	Interrupt handler crashed if interrupt deinit is called more than one time, fixed by checking NULL pointers on freed resources. solved in SDK-45757 - deinit interrupt cause assertion on the second run.
SDK-45758		88640_A0	When starting up the device in Mesh mode, the IPT thresholds were being configured incorrectly. Due to an incorrect sequence of actions the IPT thresholds were being configured before the fabric connectivity mode. Therefore when setting the IPT thresholds the driver assumed the mesh mode is disabled. This is now fixed, and the driver correctly identify the mesh mode and then set the IPT thresholds accordingly.
SDK-45762	618633	88230_C0 88230_B0 88230_A0	Fix for Sirius device - changing the scheduling discipline (bcm_cosq_sched_set()) might fail when egress independent flow control is enabled. Provided fix to prevent this issue.
SDK-45777	612311	88030_A0	G3P1 microcode v.200 fixes qos and dscp qos table segmentation in g3p1_ocm_cfg.lrp
SDK-45787		56850_A0 56850_A1	Action fields bcmFieldActionNewClassId, EgressClassSelect and HiGigClassSelect are supported in Ingress Stage for Trident2.

Table 76:

Number	CSP #	Chips	Release Notes For 6.3.1
SDK-45796	607348	88650_A0	<p>Description: At egress Field Processor, the HW correlates the counting action (bcmFieldActionStat) with the redirection (bcmFieldActionRedirect). An improper SW implementation was forcing the user to set a stat-id related to the entry-id for simplicity. Since the number of stat-ids is limited, an error was occurring for high entry ids.</p> <p>Fix: The sequence of using both actions at egress (bcmFieldActionStat & bcmFieldActionRedirect) is changed: - when an entry must redirect and count, the user must indicate in bcmFieldActionRedirect the destination port, and in bcmFieldActionStat the stat-id (in param0). From now on, the user sets also in param1 of bcmFieldActionStat the destination port again. The stat-id must be between 1024 and 3839 (Counter-ID value). Refer to <code>cint_field_egress_modify_tc_per_port.c</code> for example. - when an entry must only redirect, the user must call both actions (bcmFieldActionStat & bcmFieldActionRedirect) similarly to the previous, with stat-id = 0 to indicate the Counter-ID is not to be changed. - An entry cannot only change the Counter-ID without redirecting due to an HW limitation</p> <p>Besides, the user cannot use <code>bcm_field_stat_create[_id]</code> and <code>bcm_field_entry_stat_attach</code> at egress.</p> <p>WA: None</p>
SDK-45800	618773	56850_A0 56855_A0 56854_B0 56854_A0 56850_A1	bcm_port_phy_get/set/modify API should now work with MDIO bus number greater than three.
SDK-45808	620297	88650_A0	TRILL: Delete MAC entries according to <code>dest_nick_name</code> in payload doesn't work
SDK-45829	621360	All	<code>_bcm_board_trunk_make()</code> could segfault under some conditions.
SDK-45834		All	WCMOD: Incorrect use of <code>soc_port_if_t</code> in interface set
SDK-45851	617348	56544_A0 56542_A0 56540_B0 56541_B0	Memory sanity scripts are included in the FILES.esw package.
SDK-45852	621548	88650_A0 88650_B0 88650_B1	88650: When using dynamic ports change. the initial speed port (after dynamic change) is taken from the soc property "port_init_speed". This might cause an error if this speed is not supported by this interface. Fixed - When using dynamic ports the interface speed will be the default speed.
SDK-45868		88650_A0	implemented Arad RCPU support. For implementation detail use Arad UM, cint example application <code>cint_cmhc_rcpu.c</code>
SDK-45872		88650_A0	Change of default behavior: Initialization will fail if dram is not tuned (previous behavior was to print a warning). If oen want to initialize without tuning, SOC property 'bist_enable_dram' should be set to 0 (default is 1), which will not run bist during init.

Table 76:

Number	CSP #	Chips	Release Notes For 6.3.1
SDK-45875	606387	88650_A0 88650_B0 88650_B1	88650: At unreachable-credit events, wrong queue number was reported as OFF to the SCH. FCT unreachable destination was then asserted. Now, the interrupt application will change the flows queue status to OFF, so credits to this queue will be stopped.
SDK-45879	612625	56850_A0 56850_A1	Added support for L3 multicast cut-through mode in BCM56850. Specifically, the L3_IPMC table's REPL_HEAD_BASE_PTR field is now configured by bcm_multicast_* APIs.
SDK-45885	618944	All 56640_A0 56640_A1 56640_B0	Clear counters when there no flex object references to flex counters.
SDK-45892	620498	56846_A0	Toggling 20G link causes adjacent 10G link to bounce on same warpcore
SDK-45893		56850_A0 56850_A1	HW PCB hang problem causing register access failure is fixed by SW WAR (SDK-46060).
SDK-45901	600961	88650_A0	Controlling flooding for unknown IPMC: "bcmSwitchL3McastL2" switch control should be used instead of "bcmSwitchIpmcCompatibleEnable".
SDK-45908		56854_A0 56850_A0 56855_A0	bcmFieldQualifyColor qualifier is now supported in Trident2 device Ingress Stage.
SDK-45915		All	New interrupt thread is no longer created when SDK re-initialized after detach if previous thread is still running.
SDK-45917		All	Support pluggable PHYs phy8481.c phy84740.c phy8706.c
SDK-45918	619564	56850_A1	Clear out the encoding Rx reason codes if it is not part of the input reasons.
SDK-45933	622328	56850_A1	Add SOC property low_power to indicate whether the unused shared UFT banks are disabled or not.
SDK-45941		88750_A0	88750: Added support for FE1600 soft reset and graceful shutdown. Soft reset: - graceful shutdown - reset it without changing configuration - un-graceful shutdown API: soc_init(unit) Graceful shut down: - isolate the device - reset the links API: bcm_fabric_control_set(unit, bcmFabricShutdown, is_shutdown)
SDK-45943		88650_A0 88650_B0	ARAD Field warm boot, following was not restored after : 1. preselectors. 2. tcam actions. 3. entry flags (less critical, has effect only when doing WB in the middle of field API sequence).
SDK-45946	621865	88640_A0	In BCM88640, the ITMH Source-System-Port extension did not support LAG ports in its parsing. This issue is fixed.
SDK-45953	623653	88650_A0	88650: Diagnostic commands: "phy measure" and "diag nif" does consider correctly lane swap. Fixed.
SDK-45954 SDK-44501	622527	All 56440_A0 56850_A0 56440_A1 56440_B0 56850_A1	Fixed host entry add with ipv6_lpm_128b_enable set to zero.
SDK-45957	611540	56636_A0 56636_B0	Moving of entries in the FP_GLOBAL_MASK_TCAM table is fixed.

Table 76:

Number	CSP #	Chips	Release Notes For 6.3.1
SDK-45968		88650_A0 88650_B0	compilation error when compiling for ARAD only with warm boot support: BCM_PTL_SPT=1 BCM_88650_A0=1 BCM_88650_B0=1 # BCM_88640_A0=1 (No definition) CFGFLAGS += -DBCM_WARM_BOOT_SUPPORT
SDK-45972	619045	56850_A0 56855_A0 56854_B0 56854_A0 56850_A1	Process channel 0 for I2 mod fifo in case of TD2.
SDK-45973		88750_A0 88650_A0 88750_B0 88650_B0	Interrupts data protection were added to prevent situation when the interrupts data accessed after interrupts deinit.
SDK-45988	618997	56850_A0 56850_A1	Fixed QOS port map setting with VXLAN port.
SDK-45995	620949	56440_A0 56450_A0	Added IPBM Overlay support for Katana and Katana2 in order to support fields like S_FIELD in second slice.
SDK-46012	620324	88030_A0	The issue has been resolved.
SDK-46014	629346	56850_A1	Added sw based L2 matched traverse support.
SDK-46020		88650_A0 88650_B0	Bug description: When enabling default OAM behavior, it uses the same profile as the non-default. Thus both default trap behavior and trapping through endpoint insertion can not be use in the dame time.
SDK-46021		88650_A0 88650_B0	LM and DM packets that are trapped to the CPU have OAM-TS header that contains the counter / timestamp information. Bug: In OAM-TS header bit 42 is indicating up-mep direction. was always 0.
SDK-46022		88650_A0	88650: SerDes might be un-functional if configuring it while HW linkscan is enabled. Fixed.
SDK-46031	623835	56820_A0 56820_B0	Deadlocks from I3 memory locks are resolved with I3 module locks for all I3 xgs routines.
SDK-46039	623076	All	Shell command "GlobalMeter Policer Set" help [misspelling] for <Committed> is corrected
SDK-46041		56640_A0 56640_A1 56640_B0	Updated doc about bcmSwitchFieldStageEgressToCpu switch control.
SDK-46043		56640_A0 56641_A0 56642_A0 56643_A0 56644_A0 56645_A0 56648_A0 56640_A1 56643_A1 56644_A1 56640_B0 56644_B0 56643_B0 56648_B0 56649_B0 56649_A0	New switch control has been added to enable egress copy-to-cpu action.
SDK-46044		56640_A0 56440_A0	Support for configuring policers for all group modes in 2 level service meters has been added by incorporating new API bcm_policer_envelop_group_create
SDK-46059	622251	88650_A0	Fixed the following: during soft reset sequence full multicast dbuff pointers autogen bit was not reasserted, breaking the Ingress MC replication logic.
SDK-46075		88750_A0 88650_A0 88750_B0 88650_B0 88650_B1	Fixed issue: 'phy measure' diag shell command returns wrong results, or no results at all for fabric ports.
SDK-46076	625611	88130_B0 88130_A1 88025_A0 88020_A0 9600_A0 3200_B0 2000_A1	Convert static function to macro to prevent compiler warning for certain compilers on xcore devices.

Table 76:

Number	CSP #	Chips	Release Notes For 6.3.1
SDK-46099		88650_A0 88650_B0	VLAN port create does not provide an ability to allocate local Ingress LIF. Until 6.3.0 SDK version, the allocation of Ingress was according to <code>vlan_port_t.vsi != 0</code> . Now, <code>vlan_port_t.vsi != 0</code> has the only meaning of identify if to allocate ISEM, ESEM entries. New flags introduce <code>BCM_VLAN_PORT_CREATE_INGRESS_ONLY</code> , <code>BCM_VLAN_PORT_CREATE_EGRESS_ONLY</code> to allocate local asymmetric LIF. Those flags are not implemented yet. Workaround provided to allocate local ingress LIF as previous behavior before 6.3.0 release.
SDK-46102		88650_A0 88650_B1	ARAD-XGS MAC extender: Added the support of having RSPAN in a system with XGS MAC extender application
SDK-46103		88650_B1	Support for ARP extender + XGS interop for 1G LC
SDK-46114	625123	56850_A1	Counters update properly for X and Y pipes for PG and WRED based counters.
SDK-46127	625111	88650_A0	Arad: Dynamic NIF change- After change port the eg calendar was not updated and as a result in transition that increased the bandwidth for single logical port (e.g: 4*10G to 1*40G) we got FCS. Fix: use <code>custom_feature_soc</code> property <code>dynamic_port</code> . In this mode we update the eg calendar due to the new configuration.
SDK-46132		88650_A0	When enabling HW linkscan it'll report all links are down, instead of reporting actual link status, until first interrupt will occur. This issue is fixed.
SDK-46134	620221	88650_A0	<code>ipmc_enable</code> issue after warmboot was fixed.
SDK-46135		88750_A0 88650_A0	88650, 88750: <code>bcm_port_link_status_get</code> for fabric links returns true (link is up indication) if the port is disabled. Fixed.
SDK-46137		88650_A0	Disallow higg mode speed on non-higg port
SDK-46140		88650_A0 88650_B0 88650_B1	The module detach function is called for DNX devices in two separate cases: - during Warm-boot. Then no HW access must be done by definition (only the SW is reset). - during init / de-init. Then the init comprises also a SOC init, i.e. a device reset. Thus, any HW access at the de-init phase has no influence since the device is reset. In Field Processor, the HW was accessed during de-init (all the Field group entries were removed). This HW access is removed.
SDK-46142	575762	88640_A0	In BCM88640, in stacking application, the FTMH extension Stacking-Route-History indicates for each packet its TM-Domain history. It must be set to 0 at the first TM domain, and for each TM-Domain, the respective bit is set in this bitmap. Its value was not set to 0 but was depending on the packet content. This is fixed.
SDK-46143	624493	All	Fixed PHY partial compile failure

Table 76:

Number	CSP #	Chips	Release Notes For 6.3.1
SDK-46147		88650_B1	In Field Processor, the qualifier <code>bcmFieldQualifyHeaderFormat</code> was enumerating explicit L2 & L3 packet format codes. For example, <code>bcmFieldHeaderFormatIp4</code> selects Layer-4overIPv4overETH packets, but not IPv4overIPv4overETH packets. New Header-Formats are introduced all types of IPv4 or IPv6 or MPLS-1/2/3 packets: <code>bcmFieldHeaderFormatIp4AnyL2L3</code> , <code>bcmFieldHeaderFormatIp6AnyL2L3</code> , <code>bcmFieldHeaderFormatMplsLabel1AnyL2L3</code> , <code>bcmFieldHeaderFormatMplsLabel2AnyL2L3</code> , <code>bcmFieldHeaderFormatMplsLabel3AnyL2L3</code> For example, the user can match all the IPv4 packets with <code>bcmFieldHeaderFormatIp4AnyL2L3</code>
SDK-46169	621365	88650_A0	<code>bcm_mpls_tunnel_switch_get()</code> fails when the entry hit indication is set
SDK-46182	624961	88650_A0	QOS: Default mapping of Egress PCP mapping was changed in case of untagged packets. In case of untagged packets default egress VLAN editing adds a new VLAN tag, VLAN = VSI. The new mapping of PCP field will be according to TC. The default mapping is useful in order to maintain the incoming COS value. User can control the default mapping by creating Egress PCP-DEI QOS default profile handle: <code>bcm_qos_map_create</code> flags <code>BCM_QOS_MAP_L2_VLAN_PCP BCM_QOS_MAP_EGRESS BCM_QOS_MAP_WITH_ID</code> and profile = 0. Add QOS mappings of TC,DP to PCP by <code>bcm_qos_map_add</code> .
SDK-46191		84848_A0	Warpcore: 100M (SGMII) Transmit FIFO issue
SDK-46194		56850_A0 56850_A1	Fix <code>MMU_THDU_X/YPIPE_CONFIG_PORT</code> and <code>MMU_THDU_X/YPIPE_RESUME_PORT</code> index calculation for pool 1, 2, and 3. Fix <code>MMU_THDM_DB_PORTSP_CONFIG_0/1</code> and <code>MMU_THDM_MCQE_PORTSP_CONFIG_0/1</code> index calculation on BCM5685x.
SDK-46200	626518	53115_B0	BCM CLI command mode to ROBO mode is available in BCM CLI init process.
SDK-46202	623810	88650_A0 88650_B0	Trill Adjacent - Bug fix -The port in the key was not included correctly
SDK-46208		88650_B1	Added support for outbound mirror for XGS MAC extender ports (with HG header).
SDK-46216	624606	88230_C0 88230_B0 88230_A0	Set the default behavior for the Sirius ts scheduler hierarchy setup configured through <code>bcm_cosq_gport_sched_set()</code> to allow for a scheduling element parent with a single child to be set up in flat scheduling mode as the root relay to allow for additional children to be added at a later time. <code>ts_single_child_passthrough_disable</code> is by default set to 0. To force a parent to only be configured as the root relay if it has multiple children, clear this property.
SDK-46235	619508	88650_A0	MIM: Added the support for Split horizon in MIM application. In case packet comes from MIM port (PBB) and send back to MIM port then packet will be dropped. In order to disable Split horizon filter call <code>bcm_rx_trap_type_destroy</code> with <code>trap_type = bcmRxTrapEgSplitHorizonFilter</code> .



Table 76:

Number	CSP #	Chips	Release Notes For 6.3.1
SDK-46237		88650_A0 88650_B0 88650_B1	warmboot: dynamic variables get wrong error for being size=0 before being enabled. changed <code>add_var</code> to not return error on size=0 for dynamic vars
SDK-46263	627186	56334_B0 56334_A0	Added the code for outbound counters in <code>stat_fe.c</code> and <code>stat_xe.c</code>
SDK-46264		88650_B1	Background: Arad uses XGS as MAC extender In the ingress direction, XGS will set VID=1 in HIGIG header by default. In the egress direction, XGS only recognizes VID=1 in the HIGIG Header by default. Bug: SDK should be changed to set VID=1 in the egress direction so that there will be no need to change the XGS default configuration.
SDK-46268		88650_A0 88650_B0	OAM LM Bug: LM downmep packet trapping increases egress counters.
SDK-46273		88650_A0	Fixed: <code>bcm_cosq_fc_path_add</code> API returns error when configuring PFC/SAFC reception.
SDK-46277	628080	88650_A0 88650_B0 88650_B1	In Petra-B compatible mode, the parsing of the FTMH is different at egress because the FTMH is in Petra-B mode. The CUD was not parsed correctly at egress in Petra-B compatible mode. Therefore, the CUD extension value in OTMH was not correct.
SDK-46311	627975	All	"Wait for Linkup" after serdes loopback set, moved out of the port lock scope.
SDK-46313 SDK-44449	617061	All	IngressGportSet support is added for new GPORT types
SDK-46326		88750_A0 88650_A0	88650, 88750: RX LOS application - two connected ports which monitored by RX LOS application might have done many iterations of RX resetting on system initialize.
SDK-46330	627749	88650_A0 88650_B0 88650_B1	The the default value for STP per port is now set to Block instead of Forward, as required. Attachment of a port to an STP group will not block traffic.
SDK-46331	540502	88650_A0	Skip dynamic read only Tables during table access TR (50, 51, 52)
SDK-46342	609631	88650_A0 88650_B0 88650_B1	Fix Arad throughput below line rate when working with 4 DRAM devices
SDK-46378		88650_A0	MPLS: When calling <code>bcm_mpls_tunnel_initiator_create</code> there might be a use of memory outside of the allocated memory which could lead to undefined behavior. Fix implemented as part of another issue. It includes appropriate memory usage in <code>shr_res_bitmap_alloc_align()</code> .
SDK-46380		88650_A0	When calling <code>bcm_petra_tunnel_terminator_create</code> there might be a use of uninitialized stack variables that could lead to undefined behavior. Fix implemented as part of another issue but basically includes initializing these stack variables.
SDK-46387		88650_A0	L2 remote CPU mode disables XGS programmable editor programs to avoid conflicting instructions

Table 76:

Number	CSP #	Chips	Release Notes For 6.3.1
SDK-46390	615798	88750_A0 88750_B0	Compiling with both BCM_WARM_BOOT_SUPPORT and BCM_EASY_RELOAD_SUPPORT was not allowed. In order to support both Easy Reload feature and Warm boot feature in the same SDK image (for different devices), use the following compilation flags: BCM_WARM_BOOT_SUPPORT, BCM_EASY_RELOAD_WB_COMPAT_SUPPORT.
SDK-46391	626558	88650_A0	TDM direct routing fixed (bcm_fabric_tdm_direct_routing_set) : Before: configuring cells to be routed through was ignored; routing was done through all cells.
SDK-46393	628573	All	Resolved as part of SDK-47244. add "DUNE_GTO_BCM_CPU" macro above all "cpu_i2c_write" operation in kbp.c.
SDK-46398	627557	All 56440_A0 56445_A0 56440_A1 56445_A1 56444_A1 56449_B0 56445_B0 56440_B0 56447_B0 56443_B0 56441_B0 56446_B0	Fixed Katana VFP source mod-port qualifiers.
SDK-46405		88650_B0 88650_B1 88660_A0	Mac-in-MAC: Split horizon filter was enabled in MIM application globally and didn't allow users to support ISID-to-ISID application. Support of flag BCM_MIM_PORT_TYPE_PEER was added in function bcm_mim_port_add(), which sets the ISID orientation as SPOKE and thus, prevents the hub-hub split horizon filtering.
SDK-46411		All	Applied proper validation checks for the return type of functions _field_group_free_unused_slices() and bcm_esw_field_group_compress and _field_stage_groups_compress().
SDK-46426		88650_A0 88650_B0	OAM: MIP is both upMEP and downMEP - should have no passive side. MIP packets should be handled from both ingress and egress.
SDK-46429		88650_A0	The NIF to EGQ Flow-Control mapping is wrong for 1P and 2P modes. When working with less than 8 priorities PFC indication will be incorrect, or won't appear at all. Mapping was fixed.
SDK-46461	627415	56850_A1	Change MMU port number and queue assignment for BCM5685x to meet VBS ports restriction.
SDK-46480	629751	88650_B1	In Field Processor, the allocation of preselectors & Field groups is dynamic. The SW Driver must handle the PMF-Program, TCAM databases and all their attributes internally. At egress stage, the TCAM DB profile of existing Field groups were not kept when duplicating PMF-Programs. The bug is fixed. WA: none
SDK-46481	629771	All	Reinstate DV integrity check in soc_dma_done_chain() for CMIC-based devices.
SDK-46482	631621	All	GPL versions of the Linux BDE kernel modules now compile again.

Table 76:

Number	CSP #	Chips	Release Notes For 6.3.1
SDK-46500	627006	56840_A0	In this release we now handle MPLS type of egress object for <code>bcm_l3_egress_stat_attach()</code> API correctly.
SDK-46501	631625	56850_A0 56850_A1	VXLAN Network ports may share the same egress object. In such a scenario, deletion of a specific VXLAN port should not affect the behavior of the egress object. Fixed the problem observed during such sharing scenarios for VXLAN functionality.
SDK-46503		56640_A0 56640_A1 56640_B0	ESM may not be bypassed if there is no esm configuration on a Tr3 device. This fix makes sure ESM is bypassed if there are no external tables configured on a tr3 device.
SDK-46507	497533	56846_A0 56840_A0 56846_A1	Disabled parity for <code>FP_METER_TABLE</code> on TD/TD+.
SDK-46511	631335	88030_A0	Fixed Caladan3 synchronous ethernet clock default value
SDK-46515	629523	All 56850_A1	New flag is added to disable TTL check on multicast packets
SDK-46517	619145	88650_A0 88650_B0 88650_B1	VLAN: creation AC-LIF without any transforms, using the <code>bcm_vlan_port_create()</code> API are supported now for both ingress and egress. Use flags <code>BCM_VLAN_PORT_OUTER_VLAN_PRESERVE</code> and <code>BCM_VLAN_PORT_INNER_VLAN_PRESERVE</code> .
SDK-46518	619042	88650_A0 88650_B0	Vlan ports can now be created without port match. To use, call <code>bcm_vlan_port_create</code> with <code>criteria=BCM_VLAN_PORT_MATCH_NONE</code> . Port matches can later be added by using <code>bcm_port_match_add</code> . Note that as a side effect, when using this method vlan translation will not be defined either, and will need to be added separately.
SDK-46519		88650_A0 88650_B0	L3: Extend ARP table from 32K to 256K (32K x 16) by providing additional 4b from Host table. To enable the feature set SOC property: <code>bcm886xx_next_hop_mac_extension_enable</code> /* If set ARP table (next Hop MAC address) is extended. In BCM 88650 ARP table extend from 32K to 256K, in case soc property is set System headers for PP packets always contain 5Bytes Learn extension header. */
SDK-46523	631635	56640_B0	IPFIX enabled during init.
SDK-46531	631038	56224_B0 56224_A0	Fixed configuration issue of <code>IFP_PORT_FIELD_SEL</code> table.
SDK-46549	633259	56334_B0 56334_A0	Fix is already available in TOT.
SDK-46557		88030_A0	Add VRRP to IPv4
SDK-46564	631612	88750_A0 88650_A0 88750_B0 88650_B0 88650_B1	88750, 88650: Added new BCM API which retrieves the current link-partner information of a single link. <code>extern int bcm_fabric_link_connectivity_status_single_get(int unit, bcm_port_t link_id, bcm_fabric_link_connectivity_t *link_partner_info);</code>



Table 76:

Number	CSP #	Chips	Release Notes For 6.3.1
SDK-46573		88650_A0 88650_B0 88650_B1	Incorrect pointer assignment caused segmentation fault in ELK application initialization UI. This has been fixed.
SDK-46576	616031	88650_A0	Support ICMP packets trapping: APIs to use - <code>bcm_switch_control_port_set(0, port, bcmSwitchIcmpRedirectToCpu, enable);</code> //per port ICMP trap enable - <code>bcmRxTrapIcmpRedirect</code> : RX trap to globally control ICMP trapped packets.
SDK-46581	633727	88650_A0	<code>bcm_port_phy_control_get</code> - add support to get gport in order to enable get phy control information about the internal and external phy.
SDK-46591	627700	56850_A0 56855_A0 56854_B0 56854_A0 56850_A1	Add the support of cut-through by adding a switch control property to <code>api_bcm_switch_control_port_set</code> .
SDK-46599		88650_A0 88650_B0	When working in Petra-B mode (<code>system_is_petra_b_in_system=1</code>), the header formats are: - FTMH is in Petra-B mode - ITMH and OTMH are in Arad mode A bug in the parsing of the ITMH in this mode is fixed. WA: none
SDK-46601		88650_A0 88650_B0 88660_A0	schan HW timeout is now proportionate (and smaller in time) than schan SW timeout
SDK-46602	632985	88650_A0 88650_B0 88650_B1	Direct mapping supported systems with more than 4K System Ports. The API <code>bcm_cosq_gport_add</code> return error for such ports in direct mode. Fixed.
SDK-46606		All	Fixed macro
SDK-46608		8750_A0 8752_A0 8754_A0	control phy bcm875x for low power mode while setting phy enabled or not to generate link status change interrupt
SDK-46610	632939	56850_A0	Fix <code>soc_mem_field_get</code> buffer overrun for L2_USER_ENTRY TCAM mask.
SDK-46611 SDK-50006	632888	88650_A0	Arad: Use the soc property <code>bcm_stat_jumbo</code> to change the size of packets that counted as jumbo packets. The default value is 1518.
SDK-46618		88650_A0 88650_B0 88650_B1	VLAN translation: New BCM API VLAN actions were added in order to support Egress Vlan Editing usage of VSI as the source VID - <code>bcmVlanActionMappedAdd</code> & <code>bcmVlanActionMappedReplace</code> . Those actions values can be used the same way as <code>bcmVlanActionAdd</code> & <code>bcmVlanActionReplace</code> are used, but the VLAN value result that is used is the VSI instead of a newly supplied VLAN value as in the latter actions.
SDK-46619		88650_A0 88650_B0 88650_B1	New BCM API actions were added in order to support EVE usage of VSI as the source VID - <code>bcmVlanActionMappedAdd</code> & <code>bcmVlanActionMappedReplace</code> . Those actions values can be used the same way <code>bcmVlanActionAdd</code> & <code>bcmVlanActionReplace</code> are used respectively, but the VLAN value that is used is the VSI instead of a newly supplied VLAN value as in the latter actions.

Table 76:

Number	CSP #	Chips	Release Notes For 6.3.1
SDK-46622		88660_A0	ARAD+: To set rx clock recovery lane use the SOC property caui_rx_clock_recovery_lane: caui_rx_clock_recovery_lane_x(0/1)=0-3 (default value: 0) In warm boot and dynamic port we read this soc property again.
SDK-46642	627589	88650_B1	When deleting an entry from TCAM (bcm_trill_multicast_source_delete for example), an error wasn't returned if entry did not exist
SDK-46650	634058	88650_A0 88650_B0 88650_B1	Added support for setting the credit request profile (queue type) of Fabric Multicast Queues (FMQs). The bcm_cosq_gport_sched_set API can now be used with FMQ gport type as input.
SDK-46651	627582	88650_B1	Background: Validation of TCAM entries is done while reading all entries per database. The loop which reads the entries used the wrong database ID range, which may have been invalid in some cases. Fix: Change of database ID to right range.
SDK-46653	634167	84756_A0 84756_C0	New sequence so link stays up when link partner disables auto negotiation
SDK-46678	620403	56440_A0	Fixed stack overflow issue while invoking bcm shell group create command in linux kernel mode.
SDK-46679		56634_B0	Data returned by bcm_custom_port_get() from a remote device could be corrupted.
SDK-46680	633317	All	Code now includes exclusion of Interlaken ports when generating port list at appropriate code points.
SDK-46683	633416	56850_A0 56855_A0 56854_B0 56854_A0 56850_A1	Interface CLaSS_ID classifier for IFP is added for Trident2
SDK-46712	634930	56840_A0	MC Prio2Cos values have been corrected to reset properly
SDK-46718	628264	56850_A1	TD2 BST issues corrected.
SDK-46722	624598	56640_A0 56640_A1 56640_B0	Hardware does not support Ingress Port match capability in TR3 external FP stage. Removed InPort qualifier initialized in ACL_L2C database in SDK. Alternate method to qualify on Ingress Port is to match on the Port Class ID value using "bcmFieldQualifyInterfaceClassPort" qualifier in TR3 External Stage.
SDK-46732		88650_A0 88650_B0 88650_B1	When de-attach MPLS port using bcm_vswitch_port_delete, API returned error since PWE LIF settings weren't cleared correctly.
SDK-46742	636288	88030_A0	Integration of BCM shell and MDE GUI is implemented. MDEConnectionsView has been rewritten completely, and new view (MDE Execution Status view) was been created. Now, user can use Telnet sessions to interact with BCM from MDE GUI application. MDE GUI supports any number of telnet connections simultaneously, ne Telnet console per session. This is a prt of MDE GUI 2.138 release.
SDK-46769	636075	All	Change SW sequence after blocks init in order to avoid IQM Schan error.

Table 76:

Number	CSP #	Chips	Release Notes For 6.3.1
SDK-46773		88650_A0	Support IPv4 MC BIDIR protocol and APIs. Remarks: - Cint example with all details at SDKsrcexamplesdppcint_ipmc_bidir.c -bcm_ipmc_range_add not implemented.
SDK-46782		88650_A0 88650_B0 88650_B1	MIM: LIF-ID for ISID creation could not be controlled by the user. An option to control the allocated ISID LIF-ID was added. bcm_if_t service_encap_id member was added to bcm_mim_port_t and bcm_mim_vpn_config_t structs. This new member may be used to control the allocated LIF-ID with the use of the new supported flags BCM_MIM_PORT_SERVICE_ENCAP_WITH_ID and BCM_MIM_VPN_SERVICE_ENCAP_WITH_ID used in functions bcm_mim_port_add() and bcm_mim_vpn_create() respectively.
SDK-46791		88650_A0 88650_B0 88650_B1	88650: ARAD interlaken interface supports sending status messages through an out-of-band interface. In order to avoid sending this messages use the following soc property: "ilkn_interface_status_oob_ignore=1"
SDK-46795		88750_A0 88650_A0	88650, 88750: RX LOS application - rx_los_unit_attach is running over RX LOS semaphore. Using rx_los_unit_attach when all the ports are in stable state might cause RX LOS application to stuck. Fixed.
SDK-46800		88650_A0	At egress Field Processor, the user can preselect according to the Forwarding-Type. The following Forwarding-Types were failing: bcmFieldForwardingTypeSnoop, bcmFieldForwardingTypeTrafficManagement and bcmFieldForwardingTypeFCoE. By default, a different space in preselection table is allocated for TM field groups and Ethernet-based Field groups at ingress stage. At egress, the fix is to have a single space for both types. The user can preselect on every supported Forwarding-Types. The user needs after this fix to preselect on Forwarding-Type=bcmFieldForwardingTypeAny to get a preselection only on Ethernet packets (except FCoE packets). After this fix, a Database without preselection is applied both on TM (e.g. OLP learning messages) and Ethernet-based packets.
SDK-46801		88750_A0 88750_B0	compilation error for 88750 single chip compilation when compiling with WB flags: BCM_PTL_SPT=1 BCM_88750_A0 = 1 CFGFLAGS += - DBCM_WARM_BOOT_SUPPORT CFGFLAGS += - DBCM_WARM_BOOT_SUPPORT_SW_DUMP
SDK-46814	618010	88030_A0	fix interrupt handling to support large tmu hash capacity in caladan3 device



Table 76:

Number	CSP #	Chips	Release Notes For 6.3.1
SDK-46847	631611	All	<p>88650, 88750: RX LOS application - register a callback</p> <p>RX LOS application will notify when port is stable (i.e. the port status do not requires RX resetting)</p> <p>Therefore, the RX LOS application will use a callback mechanism. The callback will be called when a port move to a stable state or active stable state: *</p> <pre>rx_los_state_ideal_state * rx_los_state_no_signal * rx_los_state_no_signal_active</pre> <p>Registering a callback is supported per unit:</p> <pre>typedef void (*rx_los_callback_t) (int unit, bcm_port_t port, rx_los_state_t state); int rx_los_register(unit, rx_los_callback_t callback);</pre>
SDK-46856	627827	88650_A0 88650ACP_A0 88650_B0 88650_B1	<p>ARAD: Change number of ILKN lanes without disable the port is possible with <code>bcm_port_control_set(bcmPortControlLanes)</code>. This feature is supported for ILKN interface up to 12 lanes. It's impossible to increase the number of lanes above the init number of lanes. To see the actual number of lanes use the <code>bcm_port_control_get(bcmPortControlLanes)</code> function. Diagnostic will show the init num of lanes and will not update by the use of this feature.</p>
SDK-46858		88750_A0 88650_A0 88750_B0 88650_B0 88650_B1	<p>PHY speed which requires refclock of 125MHz might be not configured correctly in previous release. This has been fixed.</p>
SDK-46860	616502	88030_A0	<p>The following syntax is now supported on all but ELEN type <code>pkt_header</code> descriptions:</p> <pre>varlen_mod = true : varlen_units = 0 : varlen_size = 48 : varlen_posn = 12</pre>
SDK-46863	632416	88030_A0	<p>Wrapped TMU table creation with <code>SOC_IF_ERROR_RETURN</code> to catch exceptions.</p>
SDK-46865	636822	88030_A0	<p>You should use these cmds to dump RCE entries</p> <pre>BCM.0> g3p1rceget Usage (G3P1RceGet): g3p1rceget all g3p1rceget {ifp efp} all g3p1rceget {ifp efp} <groupId> all g3p1rceget {ifp efp} <groupId> <entryId></pre>
SDK-46878		88650_A0 88650_B0 88650_B1	<p>The <code>bcm_mpls_vpn_id_destroy_all</code> API removes all the configured VPNs for the unit, not just the MPLS ports as previously.</p>
SDK-46882	638847	56150_A0	<p>Fixed</p>
SDK-46889		88030_A0	<p>Support added for 3 label lookup. Now the labels are unique per interface per layer. - First label lookup uses port, label1, 0 (for label2) as index to labels table. - Second label lookup uses port, label1, label2 as index to labels table. - Third label lookup uses port, label1, label2 as index.</p> <p>Limitations: 1. The per layer unique label support assumes the LSP label is same on both ingress and egress direction. 2. The trunk update support needs to be added for per-interface per layer unique label feature.</p>

Table 76:

Number	CSP #	Chips	Release Notes For 6.3.1
SDK-46914		89500_A0 53010_A0 53017_A0 53022_A0 53011_A2	Fix the problem about the packets egress to NNI port are always untagged on BCM5301x, BCM5302x and BCM8950x devices.
SDK-46921		88650_A0	Issue: Packet incomes from VXLAN port and flooded over VSI gports was sent toward VXLAN network Fix: configure bounce back filter to discard such copies at egress.
SDK-46932		56820_B0	FP reinstall Assertion Fixed: The assertion happened because it was trying to install the invalid action of the entry. The check has been made to process only the valid actions.
SDK-46956		88650_A0 88650_B0	Bug description: In case <code>action_set</code> is used with <code>downmep</code> endpoint and then with <code>upmep</code> endpoint while destination is the same, <code>upmep</code> trapping will not work.
SDK-46957		All	Added support for KNET feature on iProc host.
SDK-46961	636587	88650_A0	VLAN: When port is enabled <code>bcmVlanPortDoubleLookupEnable</code> then by mistake untagged packets were not matched correctly.
SDK-46964		88650_A0	Several BCM APIs use uninitialized stack variables which may lead to undefined behavior. Fix includes initializing these stack variables in <code>_bcm_ppd_frwrdd_ip4_mc_route_fin</code> <code>_d()</code> , <code>arad_iqm_cnm_ds_tbl_set_unsafe()</code> , <code>arad_pp_eg_qos_params_remark_get_unsafe()</code>
SDK-46965	637707	All	Access the register with the correct function. Use the function which can access 64Bit register, instead of 32Bit.
SDK-46968		88650_A0	VLAN: When calling <code>bcm_vlan_port_protocol_action_add/delete</code> there might be a use of uninitialized stack variables that could lead to undefined behavior. Fix includes initializing of these stack variables in <code>_bcm_petra_vlan_port_protocol_entry_set()</code> .
SDK-46971		88650_A0	MPLS: When calling <code>bcm_mpls_port_add</code> there might be a use of uninitialized stack variables that could lead to undefined behavior.. Fix includes initializing of these stack variables in <code>_bcm_dpp_mpls_port_pwe_set()</code> .
SDK-46972		88650_A0	When calling some BCM API functions that approach the LIF table (<code>bcm_petra_vxlan_port_add()</code> for example), there might be an internal use of uninitialized stack variables which could lead to undefined behavior. Fix includes initialization of these stack variables.
SDK-46976		88650_A0	When calling some BCM API functions that get entry information from the Egress encapsulation, there might be a memory copy command with source and destination overlapping. Fix includes removal of unnecessary memcopy from <code>arad_pp_eg_encap_data_entry_data_exact_info_get_unsafe()</code> .

Table 76:

Number	CSP #	Chips	Release Notes For 6.3.1
SDK-46979		88650_A0 88650_B0 88650_B1	VPN creation: Add ability to update exist VPN (created by <code>vswitch_create</code>) for MiM usage without impact traffic
SDK-46982	639073	56850_A0 56855_A0 56854_B0 56854_A0 56850_A1	Fixed 'l3 replace' for ecmp for BCM5685x devices.
SDK-46983	637395	56850_A0 56850_A1	<code>bcm_l2_replace(MATCH_DEST)</code> can now be changed from <code>NIV_gport</code> to <code>trunk_gport</code> successfully.
SDK-46998	638019	88030_A0	Before this change, we were not able to change the speed on 10G port to 1G because of the consistency check that would block such and change. This has been fixed
SDK-47024	640408	All	Recovery of qualifierID's greater than 255 is now handled properly.
SDK-47033		88650_A0	88650 there is a HW bug in DRAM mmu indirect reading/writing under traffic. That is why deleted dram buffers seems to be changed under traffic. The problem solved when OCB is disabled.
SDK-47037		88650_A0 88650_B0 88650_B1	88650: If the packet is rejected at the egress (reassembly errors, filtered packets or due to congestion), the packet descriptor stored in the delete FIFO. ARAD egress did not allocate bandwidth to the delete fifo - required in order to delete the packet data.
SDK-47038		88650_A0 88650_B0 88650_B1	88650: Link-Level Flow Control (LLFC) This flow control is generated by the BCM88650 according to the fabric link receiver fifo occupancy. The fabric LLFC role is to adjust the incoming rate from the input link due to momentary congestion. To tune this mechanism, call <code>bcm_fabric_link_thresholds_set(unit, -1, array_count, array_types, array_values)</code> : While the array types includes the following type and array count his matching value: <code>bcmFabricLinkRxFifoLLFC</code> Threshold range: [0, 0xff]

Table 76:

Number	CSP #	Chips	Release Notes For 6.3.1
SDK-47039		88650_A0	<p>88650: BCM88650 fabric multicast queue eligibility can be regulated by random-backoff and slow-start mechanisms. Added tuning support using BCM APIs. To tune the GCI random-backoff mechanism use the following API:</p> <pre>bcm_fabric_link_thresholds_set(unit, -1, array_count, array_types, array_values)</pre> <p>While the array types includes the following types and array count their matching values: o bcmFabricLinkTxGciLvl1FC o bcmFabricLinkTxGciLvl2FC o bcmFabricLinkTxGciLvl3FC Threshold range: [0, 0x800-1]</p> <p>To enable the slow start mechanism: Obtain the appropriate gport handles for fabric MC contexts by calling: bcm_cosq_gport_handle_get(unit, gport_type, &gport_info) with gport_type: bcmCosqGportTypeGlobalFabricClosFmqGuaranteed bcmCosqGportTypeGlobalFabricClosFmqBestEffort</p> <p>Enable the mechanism using the following API bcm_cosq_control_set(unit, gport, 0, bcmCosqControlFlowSlowRate, enable)</p> <p>To configure rate1 or rate2 of slow start mechanism: Configure a percentage value between 0 to 100 from the normal mode shaper using the following APIs bcm_cosq_control_set(unit, gport, 0, bcmCosqControlFlowSlowRate1, rate1_percent) bcm_cosq_control_set(unit, gport, 0, bcmCosqControlFlowSlowRate2, rate2_percent)</p>
SDK-47040		88650_A0 88650_B0 88650_B1	<p>Wrong default configuration of internal Flow Control mapping in the device ingress path (between IPT and IPS blocks). Wrong behavior: Flow control from some class stops only its own class, instead of its own and lower priority classes. This configuration could potentially cause sub-optimal performance of the ingress path. The issue was fixed.</p>
SDK-47078		88650_A0 88650_B0 88650_B1	<p>Fixed bcm_cosq_gport_sched_get, With flags bcmCosqGportTypeLocalPortTCG to return correct configuration. That is: Before disabling WFQs for TCG gport caused enabling it, and enabling WFQs for TCG gport caused disabling it.</p>
SDK-47081	638082	88650_A0	<p>Private VLAN is supported both for single port and trunk.</p>
SDK-47087	642080	88030_A0	<p>The Asm3 tool now supports "direction = both" for the OCM and TMU tables where the "direction" argument is supported. Using the "direction = both" argument will result in generation of both ing_* and egr_* LRP variables.</p>
SDK-47089	640570	88030_A0	<p>Fixed cmc corruption issue during interrupt mask handling on cmicm.</p>

Table 76:

Number	CSP #	Chips	Release Notes For 6.3.1
SDK-47090	636591	88650_A0 88650_B0 88650_B1	Advanced VLAN edit mode was introduced under the new SOC property <code>bcm886xx_vlan_translate_mode</code> , with new dedicated BCM APIs. The new mode is aimed to enable user enhanced utilization and flexibility of the HW VLAN edit capabilities. In the Advanced mode, all the entries in the HW VLAN edit action table are available for user configuration as well as freedom to associate an action with any combination of up to 16 user defined tag formats that are TPID based, and up to 8 user defined VLAN edit profiles. For CINT usage examples please refer to <code>cint_vlan_translation_new_mode.c</code>
SDK-47093		88650_A0 88650_B0	Mirror: Added support to set system mirror ID for Egress-Mirror ports using new API <code>bcm_mirror_port_info_set</code> . When egress mirroring is configured per egress port, it is sent through the recycling interface to a reassembly context in the ingress and is associated with the System-Source-Port carried in the FTMH. It is used by the receiving CPU to identify the packet as an egress-mirrored packet from a specific port. Thus, every port is associated with an Egress-Mirror-System-Source-Port, which is the Source-Port field in the FTMH of the egress mirrored packets from that port.
SDK-47102	642084	88030_A0	Because fatal key definition errors had been suppressed the key status records contained invalid indexes and should not have been used in subsequent key validation checks.
SDK-47104	640327	88030_A0	G3P1 PPE egress rules skipped cam 1 (and used cam 0 twice). Rule update to correct the cam usage convention.
SDK-47113	640154	88650_A0	Fixed statistic counters: <code>snmpBcmEtherStatsPkts4095to9216Octets</code> , <code>snmpBcmReceivedPkts9217to16383Octets</code> , <code>snmpBcmTransmittedPkts9217to16383Octets</code>
SDK-47158	635512	56850_A0	Fixed <code>bcm_trunk_set()</code> API failure issue with the HiGig trunk IDs on BCM56850 switch devices
SDK-47161	636799	88030_A0	Tools support has been added. Please see the sample <code>g3p1_rce_cfg.lrp</code> file for configuration format.
SDK-47174	634117	88650_A0	Relevant for Arad-A0 only. Fixed the workaround for the IQM hardware bug (VoQ corrupt Errata).
SDK-47176	636654	88650_A0	MIM: VPN destroy does not work correctly, returns error by mistake. Fix includes proper use of <code>vlan_info</code> SW DB which was partially supported by the BCM MIM API.
SDK-47206		88650_A0 88650_B0	Overlay (VXLAN, NVGRE, Trill, MIM) Multicast: Added enhancement to support multicast Overlay application. Multicast requires 2pass solution. First pass is for multicast transit replications and second pass is for multicast access replications. PRGE program is introduced to provide the same Source-System-Port/In-PP-Port on the 2nd pass.

Table 76:

Number	CSP #	Chips	Release Notes For 6.3.1
SDK-47208	635229	88650_A0 88650_B0 88650_B1	Control packets (IGMP, etc.) over IP tunnels: Issue: In case control packets are send over IP tunnels then ARAD terminates IP tunnel even tough IP tunnels should not be terminated. Solution: Added the support for control packets over IP tunnels. This is done by defining a new VTT program selection to different between control packets and other packets (In case Packet format code is IPV4oE then it is control packets, otherwise it is tunnel for example EoIPoE, IPoIPoE...). In case of match in VTT program selection do not terminate IP tunnel.
SDK-47210		88750_A0	88750: Easy Reload - diagnostic: Controlling Easy Reload flags with BCM shell commands: " Usage (XXReload): Parameters on -- Put the chip in reload mode off -- Put the chip in the normal mode show -- Show the mode "
SDK-47213		56850_A1 56850_A0	Added WAR per DE inputs. Pls refer attached PPT.
SDK-47219	635011	56440_A0	TCP control Qualifier offset for double wide mode has been fixed.
SDK-47220	643269	All 88750_A0 88750_B0	Only TR tests which are supported by BCM88750 can be run on it.
SDK-47224	643297	88030_A0	The incorrect port width was being used to calculate bit positions for OCM metadata table entry.
SDK-47226		56640_A0	Fixed OAM endpoint deletion failing after OAM group name modification.
SDK-47236		88650_A0 88650ACP_A0 88650_B0 88650_B1	PON: Fixed bcmVlanPortDoubleLookupEnable Port property. Once enabled, PON double lookup classification introduced. First lookup key is {PON-Port, Tunnel-ID, SVLAN, CVLAN}, Second lookup key is {PON-Port, Tunnel-ID, SVLAN}.
SDK-47237		88650_A0 88650_B0 88650_B1	Fixed: bcm_port_selective_get with BCM_PORT_ATTR_FRAME_MAX_MASK on ILKN ports fails. As a result: 1. bcm_port_selective_get with BCM_PORT_ATTR_ALL_MASK fails for ILKN ports. 2. bcm_petra_port_info_get fails for ILKN ports. 3. Enable linkscan for ILKN port fails. 4. PS command will fail when ILKN port is defined.
SDK-47248	608493	88030_A0	Fixed in 6.3.0 and TOT
SDK-47252	642876	All	Zeroed out private area at the end of phy_ctrl_t struct (This private area of size=pc->size is maintained by the phy driver)
SDK-47253	568886	88030_A0 88025_A0	Removed invalid VID checks in bcm_l2_addr_delete_by APIs.
SDK-47261	642571	88030_A0	Not supported by hardware.
SDK-47262	645248	All	Fix bug in setting KNET interrupt disable mask for CMICe-based devices.
SDK-47263		88650_A0	VLAN: When calling bcm_vlan_port_add/get/remove and bcm_vlan_gport_get VLAN membership information might return wrong information when ports numbers are > 32. Fix included on clearing correctly ports array in arad_pp_llp_filter_ingress_vlan_membership_get_unsafe.
SDK-47274	641649	56334_B0 56334_A0 56132_B0 56132_A0	Fix port configuration fail on HiGig Lite port.



Table 76:

Number	CSP #	Chips	Release Notes For 6.3.1
SDK-47286		All	Ensure that Linux KNET module can be safely unloaded with active interrupts on SMP systems.
SDK-47350		56850_A0	Do not allow to bypass oversubscribe buffer if more than one port is configured in an OBM on BCM5685x_A0 and A1.
SDK-47365	647769	56850_A1	TSCMOD changes its design to support interop with TD+.
SDK-47370	643041	56640_A0 56641_A0 56642_A0 56643_A0 56644_A0 56645_A0 56648_A0 56640_A1 56643_A1 56644_A1 56640_B0 56644_B0 56643_B0 56648_B0 56649_B0 56649_A0	Fix field names for L2_ENTRY_2 memory.
SDK-47373	622583	88650_A0	The initialization (to zero) of the two dynamic memories in the MMU IDF and FDF is inserted. The absence of initialization was causing 1b/2b ECC errors during the first read access.
SDK-47384		56640_A0 56640_A1 56640_B0	After this fix, the entries with counter attached to it, can move across slices.
SDK-47388	620800	88650_A0 88650_B0 88650_B1	IPv4 Multicast entries encoding in ELK was defected in the calculation of important bits. Fixed.
SDK-47394	644395	88650_A0	VLAN: Added the support of matching priority tagged frames with bcmVlanPortDoubleLookupEnable set on a port.
SDK-47420	587404	All	Fix Linux kernel oops caused by calling printk with SPL lock held.
SDK-47429	620063	56850_A1	Added the feature set to support 8 meter pools for 56850
SDK-47434	640577	56640_A0 56440_A0	Fix for proper computation of meter granularity when committed rate is zero is provided.
SDK-47436	648381	56334_B0 56334_A0	Reverted code changes done in SDK-44254, which broke F2.8 Enduro UDF support.
SDK-47439		88650_A0	In Field Processor, the Counter action may have 2 sizes at ingress: - 16 bits when using it for Counter Processor - 22 bits when using it for the Statistic Report in billing mode. The cint_field_dir_ext_counter_inlif.c CINT is updated to support both modes.
SDK-47442	649144	88650_A0	In Arad, the egress counter header compensation is done with the bcmSwitchCounterAdjust switch control and not bcmSwitchCounterEgressAdjust as written previously.
SDK-47450	649166	56440_A0 56440_B0	Modified bcm_cosq_gport_delete to accept non zero modid.
SDK-47460		88660_A0	IP Tunnels: In BCM88660 we introduce the ability to counter/meter IP tunnel packets. In-LIF is now being updated for IP tunnel termination packets. See an example in: src/examples/dpp/cint_field_dir_ext_counter_inlif.c
SDK-47461		56850_A1	Print out error message if ALPM is enabled but ALPM code is not compiled in.

Table 76:

Number	CSP #	Chips	Release Notes For 6.3.1
SDK-47471	642164	56440_A0 56440_A1 56440_B0	subscriber add stores EGR_NEXT_HOP or L3_INTERFACE index, the subscriber delete call checks the encap_id if valid for stored EGR_NEXT_HOP or L3_INTERFACE for subscriber entry.
SDK-47480	649548	56640_A0 56644_B0 56643_B0	Fixed warmboot system crash issue when bcm_port_stat_enable_set() API is used with MPLS VPWS port on BCM56640 type of devices.
SDK-47481	649799	56644_B0	At the ingress stage (IFP), the issue related to the recovery of FP group information during warm boot level 2 is fixed.
SDK-47485	653227	88650_A0 88650_B0 88650_B1	When disabling a port using bcm_port_enable_set, the API blocks traffic from entering the relevant queues at the EGQ and then waits for these queues to become empty. In case of high rate traffic towards the disabled port, compared to the configured port shaper rate, the EGQ isn't cleared within timeout. Fixed by increasing the timeout.
SDK-47492	650009	All	N/A
SDK-47504	643596	56440_A0	For assignment of egress queue using action = bcmFieldActionFabricQueue in API bcm_field_action_add(int unit, bcm_field_entry_t entry, bcm_field_action_t action, uint32 param0, uint32 param1) use param0 to pass ucast queue group/subscriber queue group cosq gport and param1 to pass the BCM_FABRIC_QUEUE_XXX flags and QoS profile index (qos map id). If (param1 == BCM_FABRIC_QUEUE_CUSTOMER) then it will set EH_TAG_TYPE=1 If (param1 = BCM_FABRIC_QUEUE_DEST_OFFSET profile_index) i.e., If(param1 & BCM_FABRIC_QUEUE_CUSTOMER) then it will set EH_TAG_TYPE=2
SDK-47509	649460	56850_A1	Fixed the Gport API's for HSP ports.
SDK-47510	648141	88030_A0	Implement additional parameter checking for Taps LPM driver on bcm88030
SDK-47511		88650_A0 88650_B0 88650_B1	Fixed issue where bcm_cosq_fc_path_get with direction-generation returns wrong result.
SDK-47523	648942	56850_A0 56850_A1	Fixed configuration of PORT_INITIAL_COPY_COUNT_WIDTH register on BCM56850.
SDK-47560		All	After this fix, the newly added port in the existing trunk inherits the INNER_VLAN_RANGE properties of the existing ports in the trunk.
SDK-47565		88650_A0	In Field Processor, the Field groups may be of type TCAM, Direct Extraction or Direct Table. In Direct Table case, the key is accessing as index the TCAM Action to retrieve the actions to perform. By definition, keys of different entries cannot overlap since they access the same table index. Due to a bug, non-overlapping keys were returning error at insertion. This is fixed.

Table 76:

Number	CSP #	Chips	Release Notes For 6.3.1
SDK-47568	638934	88650_A0	88650: ARAD uses Soc property 'port_init_speed_sfi' in order to configure initial fabric links rate. Loading the chip without soc property port_init_speed_sfi!=0 wasn't functional. Fixed (the fabric links rate will be max rate).
SDK-47573	648718	88650_A0 88650_B0 88650_B1	Remove ELK interface from the EGQ calendars
SDK-47582	633655	56334_B0 56334_A0 56150_A0	Fix Enduro, Hurricane2 bcm_field_data_qualifier_create() and bcm_field_data_qualifier_packet_format_add() API support.
SDK-47593		88650_A0 88650_B0 88650_B1	When using Counter processor to count VOQs, all the types of gport mapped to VOQs in the HW should be supported in bcm_cosq_gport_stat_get(). The ingress shaping are now also supported.
SDK-47601	650723	All	Fixed reference count for ECMP table.
SDK-47624	650405	56850_A0	bcm_vxlan_stat_detach() API now detaches both ingress counter and egress counter.
SDK-47626	650791	88030_A0	Route autocaching supported for multiple units
SDK-47627	638988	88650_A0 88650_B0 88650_B1	VLAN translation (bcm886xx_vlan_translate_mode=1) : 1. Added an example of settings Ingress vlan editing (IVE) action with TPID transparent. Example demonstrates how to configure IVE so that the TPID is transparent and only vlan-id is replaced. See reference example in cint_vlan_translation_new_mode.c main function: ive_translation_main 2. Added an example of settings Egress vlan editing (EVE) action with TPID transparent. Example demonstrates how to configure EVE so that the TPID is transparent and only vlan-id is replaced. See reference example in cint_vlan_translation_new_mode.c main function: eve_translation_main
SDK-47630	649094	88650_A0 88650_B0	VLAN translation (bcm886xx_vlan_translate_mode=1) new mode examples: 1. Added an example of settings Ingress Port default Ingress vlan editing (IVE) action. Action invoked when no lookup found in L2 ISEM database. See reference example in cint_vlan_translation_new_mode.c main function: ive_main_port_default_run 2. Added an example of settings Egress Port default Egress vlan editing (EVE) action. Action invoked when no lookup found in L2 ESEM database. See reference example in cint_vlan_translation_new_mode.c main function: eve_default_translation_main

Table 76:

Number	CSP #	Chips	Release Notes For 6.3.1
SDK-47639		88650_A0	MAC-in-MAC: It is not possible for the user to control LIF-IDs of default MIM-L2-LIFs which are allocated in MIM_INIT. New SOC properties, "logical_port_mim_in/out", are supported to allow the user to control the default MIM-L2-LIF-IDs.
SDK-47654	650672	56850_A1 56850_A2	Support added for DF configuration for IPV6 using BCM_TUNNEL_INIT_IPV6_SET_DF
SDK-47661	650813	88650_A0	MACT dump: in MACT dump entry 130 was showed twice.
SDK-47664		88650_A0 88650_B0	L2CP bcm traps added: For drop or peer actions, create a trap with bcm_rx_trap_t bcmRxTrapL2cpPeer or bcmRxTrapL2cpDrop for DROP
SDK-47681		88750_A0 88650_A0	88650, 88750: RX LOS App - Waiting for a stable port. RX LOS application API will return when the requested port is stable (i.e. the port status do not requires RX resetting) The API will returned when a port move to a stable state or active stable state: rx_los_state_ideal_state * rx_los_state_no_signal * rx_los_state_no_signal_active int rx_los_port_stable(int unit, bcm_port_t port, int timeout_usec, rx_los_state_t *state); timeout_usec defines the max time the API will wait for the port RX LOS state to change to stable. state is the specific stable state (mentioned above), if the port is not monitored by RX LOS application the returned state value will be rx_los_states_count.
SDK-47708	631536	88650_A0 88650_B0 88650_B1	MAC-in-MAC: add option to create MIM gport with dummy protection, and later update the gport with actual protection. seunqnce example: examplesdppoint_mim_mp.c: mim_port_with_reserved_protection
SDK-47712	651282	56850_A0	1. API bcm_ipmc_add() should have BCM_IPMC_POST_LOOKUP_RPF_CHECK flag set 2. API bcm_ipmc_add() is called with, bcm_ipmc_addr_t.l3a_intf =< EXPECTED_L3_IIF> 3. Default action for packets not matching EXPECTED_L3_IIF --> 'packet drop and copy to CPU'.
SDK-47719		56640_A1 56850_A1	Modid retrieval corrected.
SDK-47747 SDK-29527 SDK-30977	653228	All	Ensure QoS mapping takes effect when bcm_qos_port_vlan_map_set() is called

Table 76:

Number	CSP #	Chips	Release Notes For 6.3.1
SDK-47761	653323	88650_A0	MIM: Added the support of having on the same port MIM packets and Single-tag P2P services. In previous versions, when port is MIM (i.e. when calling <code>bcm_port_control_set</code> <code>bcmPortControlMacInMac</code>) all packets with no I-TPID were discarded. Now, in order to mimic this logic, call <code>bcm_port_discard_set</code> with <code>BCM_PORT_DISCARD_TAG</code>
SDK-47766	651289	88650_A0	MIM: TPID changes were not handled correctly. Validated TPID changes for MIM and EVE
SDK-47776	653504	56640_B0 56643_B0	removed the constraint for the switch from 40G to 1G
SDK-47784		88650_A0 88650_B0 88650_B1	Fixed: Driver initialization fail with SOC property <code>fc_oob_type=1</code> due to register size mismatch.
SDK-47792		56846_A0 56845_B0 56845_A2 56844_A0 56842_A0 56840_A0 56843_B0 56841_A3 56846_A1 56841_B0	Added support for MMU_IPMC_GROUP_TBLs/MMU_IPMC_VLAN_TBL mems SER correction.
SDK-47796	653773	88750_A0 88650_A0 88750_B0 88650_B0 88650_B1	Eyescan: Error message was added when the sample time is bigger than time upper bound (default value: 256000).
SDK-47807	653522	56620_B0	Added conflicts for <code>PrioPktAndIntNew</code> when <code>PrioIntNew</code> is already added for stage ingress and stage external
SDK-47810		88650_A0 88650_B0 88660_A0	In the PPH (base); <code>FW_HEADER_OFFSET</code> should point to the start of the PDU rather than start of the Ethernet frame.
SDK-47813	654097	88030_A0	fix assert in taps driver insert route error handling code for bcm88030 device
SDK-47817	654102	88030_A0	fix taps driver command pool leak issue for bcm88030 device
SDK-47832	654476	88650_B1	In Field Processor, the qualifiers <code>bcmFieldQualifyOutPort</code> and <code>bcmFieldQualifyOutPorts</code> can be used to preselect according to outgoing port(s). A bug was inserted where the internal configuration of these qualifiers for preselectors was failing. This bug is fixed.
SDK-47833		All	The Linux KNET uk-proxy support is now turned off (compiled out) by default. For best performance, the recommended user/kernel communication path for KNET is native IOCTL, which requires that an associated device file is created: <code>mknod /dev/linux-bcm-knet c 122 0</code>
SDK-47834	643585	88650_A0	Added the ability to have IP tunnels and VXLAN on the same device.
SDK-47837		All	<code>VIRTUAL_PORT_ENF</code> is been validated on all supported silicon
SDK-47843		All	Added information about new port control in document.
SDK-47852	651897	56850_A0 56850_A1 56850_A2	only 6.2.7 release have this issue.
SDK-47856	653182	56850_A0 56850_A1 56850_A2	Functionality for IFP NAT action 'bcmFieldActionNatEgressOverride' is added. Warmboot support for the actions <code>bcmFieldActionNatCancel</code> , <code>bcmFieldActionNat</code> and <code>bcmFieldActionNatEgressOverride</code> are also added.



Table 76:

Number	CSP #	Chips	Release Notes For 6.3.1
SDK-47896	650788	All	Fixed bcm_xgs3_tunnel_initiator_set() when a mix of IPV4 and IPV6 entries are added.
SDK-47902		88650_A0 88650ACP_A0 88650_B0	Advanced VLAN edit mode was introduced under the new SOC property bcm886xx_vlan_translate_mode, with new dedicated BCM APIs. The new mode is aimed to enable user enhanced utilization and flexibility of the HW VLAN edit capabilities. In the Advanced mode, all the entries in the HW VLAN edit action table are available for user configuration as well as freedom to associate an action with any combination of up to 16 user defined tag formats that are TPID based, and up to 8 user defined VLAN edit profiles. For CINT usage examples please refer to cint_vlan_translation_new_mode.c
SDK-47903		88650_A0 88650_B0 88650_B1	Advanced VLAN edit mode was introduced under the new SOC property bcm886xx_vlan_translate_mode, with new dedicated BCM APIs. The new mode is aimed to enable user enhanced utilization and flexibility of the HW VLAN edit capabilities. In the Advanced mode, all the entries in the HW VLAN edit action table are available for user configuration as well as freedom to associate an action with any combination of up to 16 user defined tag formats that are TPID based, and up to 8 user defined VLAN edit profiles. For CINT usage examples please refer to cint_vlan_translation_new_mode.c
SDK-47913	660352	56640_A1 56850_A1	Updated with the correct sequence of init during Warm boot.
SDK-47923	644598	88030_A0	fix taps driver memory leak issue for bcm88030 device
SDK-47947	660194	88650_A0	Support of down-MEP/MIP trapping of CFM frames inside a MiM service. To enable MIM configure soc property custom_feature_oam_mim = 1.
SDK-47965		88650_A0	When dumping debug signals, all signals were shown as zeros
SDK-47966		88650_A0 88650_B0 88650_B1	VLAN: Fixed an error that happened when creating new vlan ports - their vsi was not saved in the software database. Therefore, when deleting them, their egress ac port vsi info was not cleared. The vsi is now saved, and cleaned properly.
SDK-47971	652191	88650_A0 88650_B0 88650_B1	Fix incorrect interpretation of gport handles by bcm_cosq_gport_sched_set(), when used to configure ingress scheduler weights. When configuring ingress shaper weights, the matching between the GPORT types to actual field in the device was incorrect. Note: this change will cause a different behavior under existing application!!! The weight effected by each gport type changed.
SDK-47984	638594	56640_A0	Prevent Seg Fault(Div by 0) when calculating the default burst size.

Table 76:

Number	CSP #	Chips	Release Notes For 6.3.1
SDK-47987		88650_A0	In Field Processor, the BCM TCAM entry IDs were spanning from 0 to 64K. The Direct Extraction entry IDs were over 64K. Due to the implementation of ACLs over external TCAM (KBP), the number of TCAM entry IDs is increased to 1M. The Direct Extraction entry IDs start over 1M. A modification in an application which is managing the entry id (when creating entries with specific IDs) may be needed.
SDK-47994		88650_A0	<p>The Ethernet policer is a mechanism that filters Ethernet packets based on ports and Ethernet type. Ethernet policers allow a certain configured rate of packets to pass. There are two modes for the rate - bit mode (where the rate is specified in kbit/s) and packet mode (where the rate is specified in packets per second).</p> <p>Using the <code>bcm_rate_bandwidth_set</code> function, the rate can be set. This API usually treats the rate in kbit/s, but if the <code>BCM_RATE_PACKET_MODE</code> flag is specified, then the rate is in packets per second.</p> <p>Due to an internal bug, in packet mode, the configured rate used for a meter was actually double of the expected rate. This is fixed.</p> <p>To work around this problem without the fix, specify half the rate for the Ethernet policer to get the expected rate.</p>
SDK-47996	648261	88030_A0	The model now supports arbitrary user defined TMU tables.
SDK-47999	660575	88030_A0	Added counter support in the simulator.
SDK-48000	660580	88030_A0	If PPE and/or PED data debugging verbosity is enabled, the MDE now shows: PPE header dump PED in header dump PED out (reassembled) header dump.
SDK-48001	660600	88030_A0	Skipped instructions (both for software simulator and hardware environment) are marked by colour and special marker (in style which is similar to breakpoints markers). See also JIRAs 44235 and 40773.
SDK-48008	661383	56850_A0	Fix dynamic load balancing on BCM5685x.
SDK-48012	661373	54682E_A1 54685	Removed the extraneous reset after running cable diags in 65nm GPHY devices. Reset and restore the port settings if link was broken in 65nm GPHY devices while running cable diags.
SDK-48027		88650_B1	Programmable editor: On some cases stacking program was not consistent and resolved in corrupt functionality. This issue has been fixed.
SDK-48066	662330	56640_A0 56641_A0 56642_A0 56643_A0 56644_A0 56645_A0 56648_A0 56640_A1 56643_A1 56644_A1 56640_B0 56644_B0 56643_B0 56648_B0 56649_B0 56649_A0	<code>bcm_vlan_port_default_action_set</code> () API should now set the user supplied inner vlan priority to the BCM56640 type switch devices

Table 76:

Number	CSP #	Chips	Release Notes For 6.3.1
SDK-48069	661399	88650_B1	Background: bcm_oam_endpoint_action_set api allows changing the trap destination of OAM packets. Bug: If action_set is called twice with the same destination, the trap code will be deleted and no more packets will be trapped to this destination.
SDK-48080		56640_A0 56641_A0 56642_A0 56643_A0 56644_A0 56645_A0 56648_A0 56640_A1 56643_A1 56644_A1 56640_B0 56644_B0 56643_B0 56648_B0 56649_B0 56649_A0	Fixed packet corruption issues by adjusting the dv dma buffer size.
SDK-48086	604702	All	Add lock to synchronize interrupt_disconnect with interrupt handler in Linux user mode.
SDK-48117	662857	88030_A0	To enable locking on the TMU for multithreaded applications add the following to Make.local: CFGFLAGS += BCM_SOC_TMU_USE_LOCKS
SDK-48122	662582	88030_A0	add 2133 DDR support for bcm88030 device
SDK-48123	662902	56440_A0	User can set the exp and ttl values in the MPLS outer label by setting the egress_label.exp and egress_label.ttl values in bcm_bfd_endpoint_info_t.
SDK-48127	401812	All	Assign POSIX thread names in Linux user mode if supported by the operating system.
SDK-48129	660820	56640_A1	Endpoint index was not getting populated correctly in OAM callbacks. Added mapping for Remote endpoint H/w index to logical index.
SDK-48145	663550	All	Add API details in document.
SDK-48147	663680	56850_A1	(SDK-46806) tracks support for Oversub Flex port.
SDK-48152	634262	88650_B1	MAC-in-MAC: Tunnel termination programs were loaded even if MIM was not supported in SOC properties. Fix includes loading of MIM related TT programs according to SOC property bcm886xx_auxiliary_table_mode value (indicated MIM support).

Table 76:

Number	CSP #	Chips	Release Notes For 6.3.1
SDK-48155		88650_A0 88650_B0 88650_B1	Predefined credit resolution profiles were not configured properly, and this was fixed. Some of the user defined profiles that contain thresholds with absolute values above 28*1024, may also have been misconfigured. This bug was fixed. Some of the thresholds of the BCM_COSQ_DELAY_TOLERANCE_200G_LO W_DELAY profile were changed to be in the range that the hardware supports. These profiles changed to work with the correct credit resolution: BCM_COSQ_DELAY_TOLERANCE_1G: Delay tolerance adjusted for 1Gb ports BCM_COSQ_DELAY_TOLERANCE_10G_LOW _DELAY: Delay tolerance adjusted for low delay 10Gb ports BCM_COSQ_DELAY_TOLERANCE_40G_LOW _DELAY: Delay tolerance adjusted for low delay 40Gb ports BCM_COSQ_DELAY_TOLERANCE_100G_SL OW_ENABLED: Delay tolerance adjusted for slow enabled 100Gb ports BCM_COSQ_DELAY_TOLERANCE_200G_SL OW_ENABLED: Delay tolerance adjusted for slow enabled 200Gb ports
SDK-48180	663907	88030_A0	Support 1.1Ghz LRP clock for bcm88030 device
SDK-48182	650104	All	All modes now default to setting HDR_XLATE_T_ENABLE to TRUE on BCM8823X devices
SDK-48185	630458	56840_A0	Fixed Trill stat clear issue
SDK-48197	663864	88030_A0	Removed #ifdef that was only including some code when compiled with QE2000 support.
SDK-48237		88650_A0	When changing learning mode from BCM_L2_EGRESS_INDEPENDENT to BCM_L2_INGRESS_CENT, driver had transitioned vi an intermediate state that enabled learning incorrect MAC addresses.
SDK-48252	665219	All	Update GPL modules license to Broadcom dual GPL/ Proprietary license.
SDK-48259	640482	88650_A0 88650_B0 88650_B1	VPLS: When packet is PWE terminated and next header is Ethernet. In case inner DA ethernet header is 00:00:07:xx:xx:xx then packet won't be terminated by mistake. Fix include changing MPLS ELI (Reserved label 7) program selection to be more restrictive
SDK-48261	654482	88650_A0 88650_B0 88650_B1	The longest prefix match has the highest priority for ip subnet VLAN assignment.
SDK-48262	665967	56150_A0	Implemented SMBUS Block Read / Write Functions.
SDK-48268	666152	56850_A0 56850_A1	Fix mirrored packets destined for remote MTP problem on BCM5685x
SDK-48286	665552	56850_A0	Added iif_profile update functionality in _bcm_l3_iif_profile_add() Before new iif_profile add, code (_bcm_l3_iif_profile_entry_updat e()) will search for existing iif profile and if iif_profile exist, entry will be updated otherwise new iif_profile entry will be added
SDK-48307		84848_A0	Enabled the HW_FR_EMI_MODE and EMI_MODE after running pair swaps at initialization in BCM8483X/BCM8484X.



Table 76:

Number	CSP #	Chips	Release Notes For 6.3.1
SDK-48319		88650_A0	VPLS QOS: Provided a full example of VPLS QOS application. CINT set mapping between PCP <-> EXP. On the case of PWE termination, set EXP to PCP. On the case of PWE encapsulation, set PCP to EXP. Please find the example in: <code>src/examples/dpp/cint_qos_vpls.c</code>
SDK-48326	616118	88650_A0 88650_B0 88650_B1	MACT traverse: calling SOC diag API <code>soc_ppd_frwrdd_mact_traverse</code> returned incorrect number of matched entries.
SDK-48347		All	RPC client-only applications not calling <code>soc_cm_init()</code> would segfault in <code>bcm_attach()</code> with <code>BCM_CONTROL_API_TRACKING</code> enabled.
SDK-48393	665225	88650_A0	For the hardware flush is very-very fast, so the current code just poll the <code>REPLY_FIFO_ENTRY_COUNT</code> until it is full and then stop the flush and read the entry from the REPLY FIFO, but this code only will be run on <code>block_range->entries_to_act == 130</code> , so change the code to set the <code>entries_to_act = 130</code> .
SDK-48395	664224	88650_A0 88650_B0 88650_B1	For the following types: <code>bcmCosqGportTypeGlobalFmqRoot</code> , <code>bcmCosqGportTypeGlobalFmqGuaranteed</code> and <code>bcmCosqGportTypeGlobalFmqBestEffortAggregate</code> , the bandwidth resolution (using <code>bcm_cosq_gport_bandwidth_set</code> API) was <code>8*credit_size</code> . The API fixed and the resolution is now <code>1*credit_size</code> .
SDK-48490		88650_A0	MPLS ELI: Introduced new soc property to enable / disable ELI VTT programs. In case user does not use ELI (Entropy Label Indicator) then he can disable the feature by setting SOC property: <code>mpls_entropy_label_indicator_enable</code> .
SDK-48532	669895	56850_A0	Mode Mask updated for IPV6 entries
SDK-48542		88650_A0	VLAN_PORT: When deleting remote VLAN_PORT and then creating it again an error might happen. Fixed issue by clearing correctly a remote VLAN_PORT when calling <code>bcm_vlan_port_destroy</code> .
SDK-48553	670263	56850_A0 56850_A1 56850_A2	Resolve L2 address notifications do not contain VPN ID in the VLAN field for addresses, learned on VXLAN ports
SDK-48556	651240	88650_A0	VLAN: Fixed a case where <code>bcm_vlan_gport_get</code> received port x VLAN that mapped to P2P service. In order to retrieve VLAN only information call <code>bcm_vlan_gport_info_get</code> with <code>flags=0</code> and <code>vlan</code> . In order to retrieve VSI only information call <code>bcm_vlan_gport_info_get</code> with <code>flags = BCM_VLAN_GPORT_ADD_SERVICE</code> and <code>vsi</code> .
SDK-48557	669206	88650_B1	VLAN translation (<code>bcm886xx_vlan_translate_mode=1</code>): New mode allows to set different VLAN editing for priority tagged packets using API <code>bcm_port_tpid_class_set()</code> . See reference example in <code>cint_vlan_translation_new_mode.c</code>



Table 76:

Number	CSP #	Chips	Release Notes For 6.3.1
SDK-48641	669208	88650_A0	VLAN translation (bcm886xx_vlan_translate_mode=1) : Added a Cint example of configuration that sets different priority packets handling on different in-ports. Configuration is done in LLVP using the API <code>bcm_port_tpid_class_set()</code> . See reference example in <code>cint_vlan_translation_new_mode.c</code> main function: <code>ive_priority_tags_main()</code>
SDK-48714		All	Added Coverity killpath annotation to <code>_sal_assert()</code>
SDK-48791	673145	56846_A0 56640_A0 56850_A0	TR3/TD/TD2 - Packet based WRED counting is not supported. Only Byte based discard supported. Use of flag <code>BCM_COSQ_DISCARD_BYTES</code> is required for above devices
SDK-48892	652937	56850_A0	Fixed HSP port attach for Y pipe based ports.
SDK-49630		56850_A0 56850_A1 56850_A2	Fixed to retain the valid actions when unwanted action is removed
SDK-49878	688698	88030_A0	Queue allocation can be driven from the config file. Queue parameters can also be set from the config file
SDK-50118	690082	56850_A1	BST thread exit code added.
SDK-53793	739917	88030_A0	Avoid reordering by source queue

Section 15: Resolved Issues for 6.3.0

The following issues are resolved in version 6.3.0 of the SDK.

Table 77:

Number	CSP #	Chips	Release Notes For 6.3.0
SDK-25090		All	Updated <code>bcm_field_entry_remove()</code> API to check entry installed status before performing remove from hardware operation.
SDK-28441		All	Updated field grog documentation for <code>bcm_field_group_create()</code> API, priority input parameter restrictions.
SDK-30761		88230_B0 88230_A0	FIC mode no longer generates bitmap entries for requeue ports.
SDK-32674		56334_B0	Fixed the reference count of VLAN range profiles when creating, updating, or deleting VLAN range translation on a trunk group.
SDK-32951		56634_A0 56624_B0	Fixed ESM hardware counter mode to software STAT type bitmap translation routines for Triumph and Triumph2 devices.
SDK-34493	424317	All	Resolved removing FP mirror actions mirrors unwanted packets to <code>modport(0,0)</code> , i.e CPU in case of single chip unit, for a short while issue.
SDK-36480		88650_A0 88640_A0	Added support for System Red in BCM SDK. For more details please reference System RED section in UM.
SDK-37680		All	The default value of the configuration property <code>trunk_extend</code> has been changed from 0 to 1, since the devices that do not support extended trunk mode are no longer supported in the SDK.
SDK-38133		All	When adding more than 256 FQ scheduling elements, the driver will start using already allocated FQs. Fixed by changing the order of execution so the <code>pool_base</code> and <code>pool_offset</code> will be calculated correctly. After this change, using more than 256 FQs will not use already allocated FQs.
SDK-38185		All	<code>bcm_field_data_packet_format_t_init()</code> API initializes input parameter structure in a backwards-compatible manner.
SDK-38826	442465	88025_A0	Added to 5.0.0-exa branch
SDK-38960		All	<code>topo_board_program()</code> was calling <code>_topo_stk_ports_update()</code> twice.
SDK-40250		88750_A0	Added new diagnostics: * Bcm shell cmd 'diag link clear' * Diagnostics for fifos thresholds
SDK-40304		56845_B0 56725_A0 56720_A0 56700_A0 56685_B0 56680_A1 56639_A0 56538_B0 56841_A3 56841_B0 56526_B0	Fixed <code>bcm_trunk_failover_get</code> API to return correct Higi trunk failover ports.

Table 77:

Number	CSP #	Chips	Release Notes For 6.3.0
SDK-40893		88650_A0 88640_A0	88650: Mac-in-Mac packets that arrive at egress with B-tag, are not recognized as tagged packets. Fixed the miss-configuration of Mac-in-Mac TPID profile, to allow Mac-in-Mac packets with B-tag, to be recognized as tagged packets in egress.
SDK-41286		88650_A0	The packet trap print has been adjusted to routing for ARAD. The VRF field was added and the fields in_ac & rif are assigned depending only when relevant.
SDK-41307		88650_A0	Add new SOC property for padding runt packets. The property is per port, it's available for NIF ports (except ILKN). Property name: packet_padding_size Values range:0-127 Default:0 - means disable padding
SDK-41581		All	Removed unused STATIC routines from the ~bcm/field.c file: 1. _field_qual_stage_name() 2. _field_qual_IpType_name()
SDK-41865		88650_A0	Stop counter processor on TR 6. Note: the counter processor should be manually activated after running TR 6.
SDK-41870		88640_A0	In PetraB, when configuring the port header type to be TDM_RAW, the user must set the static destination of each source TM-Port. The encoding translation of this destination was not correct.
SDK-41989		88650_A0	L2GRE IP: IP tunnel termination can be done by one lookup of <SIP,DIP> or two separated lookups of <DIP>, <SIP> this can be control by soc-property bcm886xx_ip4_tunnel_termination_mode.
SDK-42018	563672	88640_A0	"phy info" command is not supported by Petra-B. Fix the current command to return failure in case of Petra-B.
SDK-42124		88650_A0	Background: RX packets parsing would fail if rx port_header_type_out is not CPU. Fix: Port is now checked for having CPU header type. Otherwise parsing is skipped.
SDK-42159		56440_A0 56440_A1	Add TCAM SER protection support for KT. Clear TCAM mems at init time.
SDK-42685		88650_A0	88650: traffic fails when changing port configuration dynamically from 100G to 10G.

Table 77:

Number	CSP #	Chips	Release Notes For 6.3.0
SDK-42777		88640_A0	Implement outbound mirror for Petra-B based on port or port-vlan. Note: outbound mirror in Petra-B allocate only one mirror profile per port. The Petra-B mirror can support two mirror modes. Use <code>bcm_mirror_mode_set/get</code> to set mirror mode. If the mode equals to 0, then device supports only Inbound mirroring using <code>bcm_mirror_port_set</code> API. else, device support both inbound and outbound mirroring using <code>bcm_mirror_destination_create</code> API. Default mode was changed and it is set to 1 (<code>bcm_mirror_destination_create</code>). Basic sequence to support mirror in Petra-B will be as below: 1. <code>bcm_mirror_destination_create</code> to create the inbound or outbound mirror profile. 2. <code>bcm_mirror_port_vlan_destination_add</code> or <code>bcm_mirror_port_destination_add</code> to attach the mirror profile to inbound mirror port or outbound mirror port. 3. <code>bcm_mirror_port_vlan_destination_destroy</code> or <code>bcm_mirror_port_destination_destroy</code> to dis-attach the mirror profile to inbound mirror port or outbound mirror port.
SDK-42855	575758	88640_A0	Minor fix, no functional change. Fixed tables database issue with <code>pcb_link_tbl</code> attributes being overwritten. Both <code>irr.rsq_fifo_tbl</code> and <code>pcb_link_tbl</code> databases are configured correctly. These tables are not accessed by the driver, and therefore the bug did not have any functional impact
SDK-42866		56340_A0	Using misc init from TR3 thereby enabling memscan.
SDK-42907		88750_A0	Added missing counters in DCM.
SDK-42933		88650_A0	A new TM application allows TM packets to go through two rounds (via recycle port), where the packet format consists in a double-ITMH-Tag. This application requires a specific microcode at egress editor, and is set per port at init via <code>tm_port_otmh_outlif_ext_mode_<port-id>=DOUBLE_TAG</code>
SDK-43023	577999	88650_A0	The IVE size in the FHEI for IVEC-IDs that are associated with IVE Profiles 0 & 1 was changed to 0 & 3B respectively (instead of 5B).
SDK-43024	581020	All	Add support for <code>bcm_port_queues_count_get</code> API on BCM5684x.
SDK-43139	575201	88640_A0	PetraB port names were changed to "prefix, local port num" (now port names are xe1, xe2 .. and not xe0, xe1..)
SDK-43175	580345	56640_A0 56641_A0 56642_A0 56643_A0 56644_A0 56645_A0 56648_A0 56640_A1 56643_A1 56644_A1 56640_B0 56644_B0 56643_B0 56648_B0 56649_B0 56649_A0	<code>bcm_mpls_port_stat_counter_get()</code> API instead of <code>bcm_mpls_label_stat_counter_get()</code> API should be used to retrieve counters associated with the MPLS gport.
SDK-43299	584719	56334_A0	Remove unnecessary checking when setting <code>bcm_rate_mcast_set()</code> .

Table 77:

Number	CSP #	Chips	Release Notes For 6.3.0
SDK-43300		88650_A0 88650_B0 88650_B1	88650: turn off WC4 in case not in use for power consumption efficiency (previously: was always on in case of ILKN0 with more than 12 lanes).
SDK-43354	567520	88650_A0	Fixed info get for COSQ VOQs that were created using TM_FLOW_ID flag.
SDK-43404		88650_A0	Added support for APIs: bcm_port_match_add/delete/set/replace in order to have multiple match criteria. Sequence is to create first vlan port by calling bcm_vlan_port_create then call bcm_port_match_* APIs with Ingress only or egress only flags and specify the additional match lookups required for the same Logical interface. Supported APIs: bcm_port_match_add/delete/replace/set. Limitation: User can't remove / replace the original match that was specified by bcm_vlan_port_create. In order to remove it call bcm_vlan_port_destroy. Note: Logical interface with multiple match criteria learn information should be disabled.
SDK-43500	587499	56440_A0 56445_A0 56440_A1 56445_A1 56444_A1 56445_B0 56440_B0	Resolving this JIRA as the customer case is resolved
SDK-43522	589162	88230_C0	Fixed bug in parity_enable support.
SDK-43572	583285	88650_A0	A new cosq control type bcmCosqControlMulticastPriorityIngressScheduling was added to map ITMH->TC to HP-MC and LP-MC. The new control will be called from bcm_cosq_control_set API. Where cosq is the traffic class to be mapped is the traffic class to be mapped, a and arg is the priority the traffic class is mapped to: BCM_COSQ_HIGH_PRIORITY or BCM_COSQ_LOW_PRIORITY. bcm_petra_cosq_control_set(int unit, bcm_gport_t port, bcm_cos_queue_t cosq, bcm_cosq_control_t type, int arg) Where: Port=0 Cosq=TC Type=bcmCosqControlMulticastPriorityIngressScheduling Arg=BCM_COSQ_HIGH_PRIORITY / BCM_COSQ_LOW_PRIORITY
SDK-43574		88650_A0 88650_B0 88650_B1	BCM diag commands: "diag pp Ing Vlan Edit info" and "diag pp PKT_associated_TM_info" where updated to Arad settings. For the latter command, new TM info fields were added: ETH_METER_PTR, INGRESS_SHAPING_DEST, ETH_ENCAPSULATION, ETH_DA_TYPE, ST_VSQ, LAG_LB_KEY & IGNORE_CP.

Table 77:

Number	CSP #	Chips	Release Notes For 6.3.0
SDK-43589	589004	88650_A0	Added support for multicast id offset, Please use SOC property <code>multicast_id_offset</code> as such: <code>multicast_id_offset_<port-id>.BCM88650=<offset></code> For example <code>multicast_id_offset_2.BCM88650=10000</code> Or <code>multicast_id_offset_rcy.BCM88650=10000</code> Etc... So, if a multicast packet will be received through <code><port-id></code> its multicast-id will be changed to <code><offset+multicast-id></code> This fix is relevant for Arad only.
SDK-43599		All	gcc 4.7.2 compilation support.
SDK-43604		All	fix gcc 4.7.1 warnings(unused-but-set-variable).
SDK-43605		All	fix gcc 4.7.1 warnings(unused-but-set-variable).
SDK-43606		All	fix gcc 4.7.1 warnings(unused-but-set-variable).
SDK-43607		All	fix gcc 4.7.1 warnings(unused-but-set-variable).
SDK-43608		88650_A0	BFD API enhancements: 1) Flag in <code>endpoint_info</code> <code>BCM_BFD_ENDPOINT_IN_HW</code> , to indicate whether the endpoint is handled in HW or not. 2) Timeout events: <code>bcmBDFEventEndpointRemote</code> , <code>bcmBDFEventEndpointRemoteUp</code> flags. 3) <code>bcm_bfd_endpoint_t.remote_gport</code> field - remote destination of BFD packets.
SDK-43612		All	fix gcc 4.7.1 warnings(unused-but-set-variable).
SDK-43613		All	fix gcc 4.7.1 warnings(unused-but-set-variable).
SDK-43614		All	fix gcc 4.7.1 warnings(unused-but-set-variable).
SDK-43616		All	fix gcc 4.7.1 warnings(unused-but-set-variable).
SDK-43617		All	fix gcc 4.7.1 warnings(unused-but-set-variable).
SDK-43618		All	fix gcc 4.7.1 warnings(unused-but-set-variable).
SDK-43619	589674	88650_A0	88650: fixed "show patches" bcm shell command (was missing on 6.2.1-hotfix1)
SDK-43623 SDK-44728	586564	56850_A0	LED support is added for TD2. 'led init' in sdk will work as long as the physical - logical port mapping is sorted. random mapping between physical and logical port will require <code>CMIC_REMAP</code> registers to be programmed through a soc script.
SDK-43631	590287	88650_A0	88650: BCM Diagnostics Shell command "diag cosq non_empty_queues" doesn't work for FMQs, In case of non-empty FMQs with SOC property <code>voq_mapping_mode=DIRECT</code> , the diagnostics reports errors for FMQs, but still prints correct information for VoQs.
SDK-43706	591471	56850_A0 56855_A0 56854_B0 56854_A0 56850_A1	Fixed incorrect routing behavior due to flag bit overloading.
SDK-43713	589448	88650_A0	The OTMH formats were not correct in case of <code>IF_MC_OTMH-CUD-Extension</code> mode: in this case, the extension is from now on added only for Multicast packets, according to the latest CUD known on the egress pipe (similarly to the ALWAYS mode)
SDK-43716	591808	56440_A0	The stat value for GT16383 and GR 16383 can be read from API <code>bcm_stat_get</code>
SDK-43740	592383	88650_A0	DNX: Fixed help text for "dump" command



Table 77:

Number	CSP #	Chips	Release Notes For 6.3.0
SDK-43770		88650_A0	Added CGM Counters to BCM shell diagnostics diag counters graphical diag counters packet_flow
SDK-43807		88650_A0	BCM88650: "diag retransmit" command added. when called, presents relevant retransmit parameters for ILKN0 and ILKN1.
SDK-43837		88650_B0	Vxlan: in encapsulated packet IP protocol was set to GRE instead of UDP
SDK-43872		88650_A0	The BCM Meter Action (bcmFieldActionPolicerLevel*) was changing both Meter-Pointer0/1 and the DP-Meter-Command. A double HW action is impossible when using the TM & FP functionality. Besides, the DP-Meter-Command has a dedicated BCM action (bcmFieldActionUsePolicerResult), and the default value (0) is the value changing both at ingress and egress. Thus the DP-Meter-Command HW action is not needed and removed from the meter actions.
SDK-43883		88650_A0 88650_B0 88650_B1	Added support for EVB application. Please see more information in the CINT example src/examples/dpp/cint_evb_example.c
SDK-43921		88650_B0	In the Counter processor, in Arad-B0, different packet statistics can be set with 1 counter per Counter processor line (i.e. per Counter-ID): FWD, DROP, and ALL. In case the user sets one of them, but requires the counters of another (e.g., he sets DROP and requires the FWD counters), the Driver should fail instead of returning the counter of DROP.
SDK-43949		88650_A0	Support a new feature - Ring Protection Fast Flush. CINT example - cint_l2_fast_flush.c
SDK-43956	595868	All	WC B0: KR2(brcm) link does not resolve in SDK branches after SDK_6_2_0_EA2
SDK-43957		88650_A0 88650_B0	The egress does not terminate large headers correctly. Thus, a walk-around (WA) is built to terminate headers at ingress FP stage when the Forwarding-Header is too far (more than 32 Bytes). The WA removes up to the 14 Bytes after the Ethernet header location.
SDK-43977	595227	56850_A0	Fixed inaccuracy in shaper programming on TD2
SDK-43986		56640_A0 56640_A1 56640_B0	Added diag shell support for field action set. Supported options are Add/Delete/Clear/Show.
SDK-43992	581119	All	Fixed.
SDK-43993	583971	88030_A0	TPID getting/setting now supported
SDK-43994	560768	88030_A0	OCM table access methods will now work correctly for entries that are not 32bit aligned.
SDK-43996		56640_A0 56641_A0 56642_A0 56643_A0 56644_A0 56645_A0 56648_A0 56640_A1 56643_A1 56644_A1 56640_B0 56644_B0 56643_B0 56648_B0 56649_B0 56649_A0	In RCPU scenario, to redirect incoming packet from CMIC to a specific port in the same unit, we have to configure prepare DCB and that DCB information should be configured in CMIC_PKT_RMhX CMIC registers. On earlier chips, to redirect a packet (SOBMH) from CMIC to a specific port, configuring that port information in DCB would be sufficient, but on latest devices where we can configure cosq's flexibly, we have to specify the cosq number in DCB. Otherwise all redirected packets will go to 0th cosq. This patch configures the cosq number of the egress port in dcb, so that CMIC will inject SOBMH packets to that cosq.
SDK-44001	571844	88650_A0	88650, 88750: Add show temp-PVT command to help message

Table 77:

Number	CSP #	Chips	Release Notes For 6.3.0
SDK-44004		56850_A0 56850_A1 56850_A2	Failover feature on front panel lag is now enabled.
SDK-44010	597002	All	fixed the bug in the port enable function for QSGMII core
SDK-44016		88650_A0 88650_B0 88650_B1	Outbound mirror functionality is now working correctly.
SDK-44021		88650_A0 88640_A0 88650_B0 88650_B1	VSQ discard set and color size set should not take into account VSQ Global - added type checking
SDK-44022		88650_A0 88650_B0 88650_B1	Set VSQs rate class default values for Tail Drop to be maximum as defined by hardware.
SDK-44027	594874	88650_A0	In case ARAD port is in XGS-MAC-EXT mode, PP port is derived according to FRC.Source-Port[7:0]. It is user responsible to configure system ports in ARAD to be as follows: [XGS.Modid][ARAD.LocalPort]. Example: In case ARAD local port 41 is faced to XGS Modid 1 then ARAD system port is 297.
SDK-44036		88650_A0	The ITMH Destination has different modes. The modes where the Destination Extensions are used, are setting the Destination incorrectly - mainly the Out-LIF mode and the Ingress Shaping mode.
SDK-44038	597121	88650_A0 88650_B0 88650_B1	<code>bcm_mpls_tunnel_switch_create()</code> with the <code>BCM_MPLS_SWITCH_ACTION_POP</code> action now returns the <code>tunnel_id</code> created. In addition, it can be called with <code>tunnel_id != 0</code> and <code>flags = 0x02000000</code> (temporary, a flag <code>BCM_MPLS_SWITCH_REPLACE</code> will be added to API) to update existing switch.
SDK-44045		88650_A0	The Counter Processor uses the DMA FIFO mechanism to collect the counters from HW. In HW, the counters of the Counter Processors are buffered in a FIFO with approx. 60 entries. This FIFO is read repeatedly by the FIFO DMA and the results are saved in a buffer. The size of this buffer was 1K, and is increased now to its maximum, 16K. Besides, the timers are changed in BCM level (SW timers of CPU access to DMA FIFO buffer that can increase the CPU usage) to minimize the CPU usage from ~50 ms to ~0.5 sec. These timers are dynamic and their values are adapted according to the load of the DMA FIFO.
SDK-44047		88650_B0 88650_B1	Multicast Overlay: Added support for overlay IPMC Recycle port use: <code>bcmPortControlIPTerminationOverlayRecycle</code>
SDK-44070		All	Removed non-ASCII characters from register description.
SDK-44074		56850_A0	Code reorganized to handle mem clear issues in simulations.
SDK-44078		88650_A0 88650_B0 88650_B1	DNX: Packet that is trapped to CPU can be parsed either in non-interrupt context (default), or in interrupt-context (using compilation flag <code>BCM_ARAD_PARSE_PACKET_IN_INTERRUPT_CONTEXT</code>) . In the second case the device is not accessed and fields <code>src_port</code> <code>src_mod</code> will be set to 0.
SDK-44086		88650_A0	In Counter Processor, one of the statistics was documented as: - <code>FWD_COLOR</code> : forward green, forward not green counters Actually, the HW supports the following mode, which replaces <code>FWD_COLOR</code> : - <code>SIMPLE_COLOR</code> : green, not green counters
SDK-44105		All	Removed -Wp per-processor option from Kernel flags as options are not passed.

Table 77:

Number	CSP #	Chips	Release Notes For 6.3.0
SDK-44118		88750_A0 88650_A0	API <code>bcm_stk_module_enable</code> has a parameter where it can disable/enable fabric connectivity. The API was implemented that traffic enable sequence was run, without referring to enable parameter. The issue is fixed.
SDK-44123	598867	88650_A0 88650_B0 88650_B1	TDM optimize : Maximum destination ports in FTMH for TDM traffic is fixed
SDK-44170	597142	56850_A1 56850_A0	Support for UDF qualifiers for VCAP/VFP stage.
SDK-44171		88650_A0	In Petra-compatible header mode, the program parsing packets arriving at ingress with an FTMH header (e.g. for stacking, or after recycling / outbound mirroring) was not implemented and is implemented now.
SDK-44180		88650_A0	In Field Processor, up to 32 simple action macros (called FESes) can be used per PMF-Program. In general, the user tries to allocate the first 16 actions to the 2nd FES group: FES 16-31. Once this FES group is full, the Driver tries to allocate in the 1st FES group: 0-15. In case there is no Direct Extraction Database, and there is a less important Database in the 2nd FES group, the Driver moves this FES to the 1st FES group and allocates the new FES at its place. A bug was not considering the FES-group-index correctly.
SDK-44191		All	TC 2 TC mapping for 8 priorities mode, did not map traffic classes 3-7 properly. TC 2 TC mapping 8 priorities mode did not consider global offset of flow2voq mapping, hence - when called the gport value should have been minus the offset, after the fix use the gport value should be the value retrieved by <code>BCM_COSQ_GPORT_UCAST_QUEUE_GROUP</code> as usual.
SDK-44194		88650_A0	The LAG ranges of each port are defined in the HW table EGQ.PPCT which is accessed according to the Queue-Pair. This table was accessed only according to the Base-Queue-Pair of each port, and not according to all the port Queue-Pairs. Fixed now EGQ.PPCT init for all Queue-Pairs.
SDK-44205	595775	88750_A0	<code>bcm_stk_modid_set</code> activated reachability messages for each link. This operation took 128 readwrite operations and 128 sleep(20ms). API performance improved: Reduced to one readwrite to register operation and one sleep for all 128 links.
SDK-44212		88650_A0	<code>bcm_port_force_forward_get</code> returned and error for multicast id as GPORT
SDK-44216		88650_B0	Register access optimization for ARAD (redundant verification was removed). Speeds up Negev initialization by 10%.
SDK-44228	597091	56334_B0	Fix erroneous counter status in <code>bcm_field_group_status_get</code> API.
SDK-44233		56840_A0 56634_A0 56440_A0 56850_A0 56640_B0	Start automatic TCAM memscan only if parity is enabled.
SDK-44238	598928	88650_A0	Fixed <code>bcm_cosq_port_mapping_set</code> for system ports, Please use <code>BCM_GPORT_SYSTEM_PORT_ID_GET</code> to get a handle to system ports
SDK-44239		88640_A0	hub/spoke orientation setting for out-AC using <code>ppd_eg_filter_split_horizon_out_ac_orientation_set</code> failed.

Table 77:

Number	CSP #	Chips	Release Notes For 6.3.0
SDK-44246		88650_A0	In Field Processor, data qualifiers allow the user to extrapolate bits either from the packet headers or from common qualifiers. In case of packet headers, the user can control the number of bits, and the location which is composed of the base-header and how many bits to jump. In 88650, the jump can be done in both directions (i.e. the offset can be positive or negative): inside the base-header or from the previous header. For example, extracting EtherType without considering the number of VLAN tags is done by taking the base-header as Header-after-Ethernet, and jumping 2 bytes backward. The implementation of the negative offset (BCM_FIELD_DATA_QUALIFIER_OFFSET_NEGATIVE flag) was not done
SDK-44270	599851	88650_A0	Statistics counter flag: all fabric counters thread priority flags were updated to High. This means that all fabric counters are accumulated by the counters thread. This change makes the property <code>soc_counter_control_level</code> not relevant for fabric ports.
SDK-44273	600308	56640_A0 56640_A1 56640_B0	Fix L2 mem locks w.r.t freeze and thaw.
SDK-44284		88650_A0	Fixed the usage of partially uninitialized buffers.
SDK-44299		56540_A0 56340_A0 56640_A1 56643_A1 56640_B0 56643_B0 56648_B0	Add per unit global variable instances for port and flex config.
SDK-44321		88650_A0	Both ingress & egress Field Processors can match on IpType, which corresponds to a parsed EtherType. For MPLS, at egress the parsing of <code>bcmFieldIpTypeMplsUnicast</code> was not correct. Besides, <code>bcmFieldIpTypeMplsMulticast</code> was added both at ingress and egress.
SDK-44324		88650_A0	In the Field Processor & ITMH (aka PMF-Extension-Headers) application, Field groups are preselected with particular preselectors, when Forwarding-Type = <code>bcmFieldForwardingTypeTrafficManagement</code> . The release of these preselectors was not correct. Thus, when using the same preselector-id for an Ethernet-based Field group, an internal error was appearing.
SDK-44325		88650_A0	In Field Processor, both: - Implement <code>bcmFieldQualifyTranslated*</code> qualifiers at ingress - and fix the parsing of <code>bcmFieldQualifyTranslated*</code> at egress
SDK-44336		88650_A0 88650_B0 88650_B1	Implemented BCM diag command "diag pp ENCAP" for 88650
SDK-44341		56850_A0	Resolved under SDK-44074 .
SDK-44344		88640_A0	Vlan editing: Change Egress vlan editing operation of NONE on tagged vlan from Ignore to Remove and Add again. This will let Transmit tag/untag and Outbound mirroring features to work.

Table 77:

Number	CSP #	Chips	Release Notes For 6.3.0
SDK-44348		88650_A0	Due to incorrect allocation of reserved packet descriptors during init, some EGQ resources were wasted. Wasting EGQ resources can limit the device max supported traffic rate. The reason for this wrong allocation was that the formula for Service Pools in the EGQ was counting the reserved resources per port twice, instead of counting per service pool only the ports that used it. The fix was to calculate the reserved packet descriptors per Service Pool by only counting the resources of the ports using the service pool.
SDK-44352		88650_A0 88650_B0	CrpsActCntsCnt counters were removed from "diag counters", due to the fact that these counters should not be read when counter mode is QSIZE and "diag" is general to all modes.
SDK-44357		88650_A0	In Field Processor, the user can assign a new trap with the action bcmFieldActionTrap. In previous implementation, this action sets the new {Trap-strength; Trap-Id} according to the assumed HW abilities. 2 options were given to the user when setting the action value with bcm_field_action_add: 1. param0 is a Trap GPORT, encoding the strength and the new trap-code. param1 is not used 2. param0 is the new trap-code, param1 is the trap strength. In practice, the HW assigns {Trap-qualifier, Trap-strength and Trap-Id}. Thus when setting the action value with bcm_field_action_add, the use must indicate: - param0 is a Trap GPORT, encoding the strength and the new trap-code - param1 is the trap qualifier The user must pay attention that this action size goes from 11 bits to 27 bits.
SDK-44359		88650_A0	Solved OAM event not being generated by the OAMP.
SDK-44363		88650_A0	The detach feature in Field Processor was not working properly in case that Direct Extraction Field groups with entries were installed to the HW. This is fixed.
SDK-44367	601121	88650_A0	learning setting Fixes: - Enable to configure distribution header (bcm_l2_learn_msgs_config_set) separately from enable message generation. - when learning managed by OLP (not CPU) then both learning and shadow FIFOs have dsp-generation configured
SDK-44379		88650_A0	OAM mirroring did no work if OAM init was called before calling outbound mirroring API. Now OAM allocates the highest mirror profiles for mirroring, so order does not matter.
SDK-44380		88650_A0 88650_B0 88650_B1	Release to customers trunk example cint_trunk.c
SDK-44395		88650_A0	In Field Processor, the SOC property field_class_id_size sets the User-Header size that can be located between the end of System-Headers (FTMH + PPH + their extensions) and the beginning of the Network headers (Ethernet and following header stack). This SOC property is used for example in the Cascaded-Ingress-Egress Field Processor application. The location of the beginning of the Network headers was not correct in 2 cases: - in the HW, because of an internal misconfiguration at egress - in the parsing of the trapped packets. Both cases are solved.
SDK-44396		88750_A0 88650_A0 88750_B0 88650_B0 88650_B1	88650, 88750: bcm_port_phy_control_get (BCM_PORT_PHY_CONTROL_PREEMPHASIS) returns lane 0 taps for all lanes.



Table 77:

Number	CSP #	Chips	Release Notes For 6.3.0
SDK-44399		56546_A0 56542_A0 56541_A0 56545_A1	Bringup and sanity fixes done.
SDK-44423		All	LDK-3.0.3 software for iProc is integrated into SDK
SDK-44425	600706	56850_A0 56850_A1	Fixed E2ECC message not being transmitted on TD2
SDK-44436		All	Created src/soc/common/ser.c file
SDK-44439		88650_A0	When closing MAC loopback on the NIF side, MAC loopback FIFOs are sometimes out of sync. This occasionally results in partial traffic loss. Fixed.
SDK-44444		88650_A0	Added a soc property "mim_num_vsis". Values are 4096 (default) or 32768. If it is set to 32768, then 32K different I-SIDs may be configured, but ingress VLAN editing is disabled for access facing (UNI) In-ACs.
SDK-44458		88650_A0	Background: The ITMH parsing is done through microcode. Some of the ITMH formats (Out-LIF, Ingress-Shaping, MC-Flow) are using the Destination extension. In the case of Ingress-Shaping, the microcode is supposed to indicate that the forwarding decision (i.e. the destination) is taken according to the ITMH-Destination-extension field. Limitation: A bug was found on the microcode of the Ingress-Shaping parsing. This bug is fixed. WA: None
SDK-44487		88650_B0 88650_B1	ECN using queue size in bytes to determine congestion is now supported in 88650 B0 and up. But (88650 B0/B1) due to a hardware erratum, only values of up to 0x7e00000 bytes (126MB) can be supported (the limitation is only when using bytes and not descriptors!) A value of 0x80000000 (2GB) can be used to disable the bytes limit after it is set. If the bytes limit is used in B0/B1, be sure to also configure tail drop of less than 128MB on the same queues. If values above 126MB are needed in B0,B1 the same affect can be achieved using the ECN WRED configuration.
SDK-44489		88650_B0	Added support for Fine-grained Trill. See example in cint_trill.c.
SDK-44494		All	The CINT API wrapper for bcm_l2_addr_t_init() would fail to compile with the Wind River Diab Compiler dcc.
SDK-44510	606330	88650_A0	XGS Diffserv: Added support for new system port encoding where System port is being extracted according to [FRC.MODID 8 bits , 0, FRC.PORT 7 lsbs]. Default mode was taking [0,FRC.MODID 7 bits, FRC.PORT 8 bits].
SDK-44519		All	Updated license information for APIMODE, BIGDIGITS, CINT, ED Editor and VxWorks
SDK-44528		56640_A0	Fixed bcm_tr3_cosq_port_sched_set return BCM_E_PARAM if port gport is passed as argument.
SDK-44536	595066	56850_A0 56850_A1	In TD2, for Adv Flex Counter, set operation on stats should set both X and Y pipe.
SDK-44554		88650_A0	Add to tr 140 NoReset parameter, DRAM bist perform soft reset in the end of the test unless this parameter set to 1.

Table 77:

Number	CSP #	Chips	Release Notes For 6.3.0
SDK-44556		88650_A0 88650_B0 88650_B1	Command added to api: DIAG rates <OPTION> <parameters> OPTIONS: - EGQ - to calculate EGQ rate. Requires: port=<port_id> tc=<traffic_class> - PQP - to calculate PQP rate. Requires: port=<port_id> tc=<traffic_class> - EPEP- to calculate EPE port rate. Requires: port=<port_id> tc=<traffic_class> - EPEI- to calculate EPE interface rate. Requires: if=<interface_id> - EPNI- to calculate EPNI interface rate. Requires: scheme=<measure_scheme> [bw=<bw_id>] Schemes available: 0-measure total, 1-bw on interface, 2-bw on port, 3-bw on Q-pair, 4-bw on channel, 5-bw for mirror/not mirror
SDK-44581	607129	88650_A0	APIs bcm_port_frame_max_setget were fixed to configure fram_max on MAC. These APIs are supported for all NIF ports except ILKN.
SDK-44583		56820_A0 56725_A0 56680_A0 56624_B0 56624_A0	Added new reg files and ran code generation script.
SDK-44592		All	bcm_stk_port_set() now avoids updating hardware tables if the stack port membership has not changed.
SDK-44595		88650_A0 88650_B0 88650_B1	TDM Optimized mode, bcm_fabric_tdm_editing_set/get: Fixed getting user defined field from TDM editing in case of TDM optimized should always return 0. Please notice that this field can be configured only when using standard TDM mode. Note: When getting the user define count field in TDM standard mode, the return value will always be the maximum number of bits allowed for user define field.
SDK-44598		88650_A0 88650_B0 88650_B1	PON 3 tags manipulation is supported completely. Tunnel tag is processed in bcm_port_vlan_create. And other 2 VLAN tags are processed by PON egress VLAN translation.
SDK-44600		88650_A0 88650_B0 88650_B1	Fixed: When setting port_init_speed=-1 on the NIF side, default rate is set to a wrong value.
SDK-44617	608209	88650_A0	MAC based VLAN assignment: In order to enable the functionality user needs to set soc property sa_auth_enabled = 1.
SDK-44633		56840_A0 56640_B0 56540_B0	For SER related soc_switch_event callbacks, removed the newer enums defined for use in BCM5664x and BCM5685x devices. Add encoding in the second to last param of the event notifier for the new data formats.
SDK-44636		88650_A0 88650_B0 88650_B1	BCM_VLAN_PORT_MATCH_PORT_TUNNEL_VL AN_ETHERTYPE is now supported for AC creation on Tunnel_ID + SVLAN. BCM_VLAN_PORT_MATCH_PORT_TUNNEL_VL AN_STACKED_ETHERTYPE is now supported for AC create on Tunnel_ID + SVLAN + CVLAN.
SDK-44645		88650_A0	88650: Added warm boot support for dynamic ports change.
SDK-44646	606367	56850_A0	Fixed BUD/LEAF loopback port init/deinit issue.
SDK-44672	604494	56850_A0 56850_A1	bcm_cosq_gport_add can allocate more than NUM_COS UC queues for td2 and tr3.

Table 77:

Number	CSP #	Chips	Release Notes For 6.3.0
SDK-44688		88650_B0 88650_B1	88650: Added new SOC property to indicate which implementation of ECN for MPLS is used: <code>mpls_ecn_mode</code> . Valid values are 1 (1-bit mode), or 2 (2-bits mode).
SDK-44740	609484	56546_A0 56545_A0 56544_A0 56542_A0 56541_A0 56540_A0 56545_A1 56540_B0	Fixed LPM memory sizes for various configs/SKUs.
SDK-44748		88650_A0	Fixed access (reads) to non allocated memory during driver startup, which may have caused segmentation faults in some systems.
SDK-44766	610133	88650_A0 88650_B0 88650_B1	Port command was fixed to support also Fabric ports.
SDK-44800		88650_A0 88640_A0	QOS: Changed logic of <code>WITH_ID</code> flag in <code>bcm_qos_map_create</code> to handle correctly the value of <code>qos_id</code> .
SDK-44803		All	Fix function by Adding check to BCM state - init/deinit
SDK-44806		88650_A0 88650_B0 88650_B1	New option: <code>diag cosq voq</code> Displays all of the non empty VOQs and their current size in bytes. Two filtering option are enabled: <code>diag cosq voq most=x</code> - displays only the <x> most congested VOQs. <code>diag cosq voq id=x</code> - displays only VOQ <x>
SDK-44813		88750_A0	88750: Multi-thread support: Missing <code>bcm_lock</code> to <code>bcm_dfe_init</code> was added.
SDK-44839	607723	88650_A0 88650_B0 88650_B1	Background: When the port header type set to <code>STACKING</code> , its internal <code>LB_PROFILE</code> is set to <code>ONE</code> . Limitation: The port internal <code>LB_PROFILE</code> was not set to 0 when the header type was set to Ethernet for example, and not stacking. WA: None.
SDK-44857	606402	56540_A0 56540_B0	Corrected String length for <code>strncat</code> , such as not to over run buffer in corner cases.
SDK-44912	612131	88640_A0	Resolved: Internal indexing error could result in failure to enable control cells during initialization when using FEC.
SDK-44918	605584	88650_A0	Background: The ITMH parsing of the Mirror-Enable bit (aka <code>IN_MIRR_FLAG</code>) should disable mirroring if the bit is unset. Limitation: If this bit is unset, the mirror profile should be 0. It was in practice dependent on packet's content. This is fixed WA: None
SDK-44926		88650_A0	In Field processor, a CINT called <code>cint_field_dir_ext_counter_inlif.c</code> has been added to illustrate how to attach a Counter-Pointer = In-LIF to the packet via Direct Extraction Field group.
SDK-44930	612050	88650_A0	MIM: Added support <code>WITH_ID</code> flag for <code>bcm_mim_port_add</code> API.
SDK-44947		All	Improve performance of API <code>bcm_tunnel_initiator_set()</code> when called before any next hop entries are set for a given interface (e.g. L3 egress objects).
SDK-44968	606209	88650_A0	In Stacking system, MC over stacking ports was not working due to bug in header programming, The issue was fixed.

Table 77:

Number	CSP #	Chips	Release Notes For 6.3.0
SDK-44969	609615	56850_A1	cleaned up detachment of node and free up index range when all the children are gone.
SDK-44984		88650_A0	OAM: When sending upmep LM RX packet in is trapped to the CPU but in addition the counter with the index of the stamped value is increased.
SDK-44991		88650_A0 88650_B0 88650_B1	When external phy is connected, TX parameters for lane 0 in a quad not always set correctly (depends on ext phy implementation). This issue was fixed.
SDK-45067 SDK-44051	613032	56850_A0	Fixed VXLAN functionality for match criterion = BCM_VXLAN_PORT_MATCH_PORT_VLAN
SDK-45132		All	New switch controls bcmSwitchDosAttackIcmpV4, bcmSwitchDosAttackIcmpV6 added to enable/disable ICMPV4 and ICMPV6 size check respectively
SDK-45148		56725_A0 56720_A0	SOC Port Valid check is applied to avoid the segmentation fault as it exceeds the MAX limit and corrupts the stack. The issue is seen only in case of CONQUEROR.
SDK-45151		88750_A0 88650_A0	88650, 88750: RX los application improvements - Updated application notes will be supplied.
SDK-45158		88650_A0 88650_B0 88650_B1	Setting port_init_speed <p>=-1 should disable port p. However this configuration influence other ports. This was fixed.
SDK-45179		88650_A0 88650_B0 88650_B1	Allow setting FW mode by SOC property for 10G ports. Use serdes_firmware_mode=0 (default) to reserve current behavior.
SDK-45239	612680	56640_A0 56640_A1 56640_B0	Adjusted default hash offset configs to take into account the scenario when all banks are used by a single memory type.
SDK-45249	611829	88030_A0	Add "QueueInfo" command for C3
SDK-45256	615804	56846_A1	Link flap on the port associated with lane0 if port associated with lane2 is disabled/enabled in KR2 mode
SDK-45261		All	Skip mem cache use in test mode in all memory ops. Enable test mode in tr tests like cpu benchmark tests tr 21 etc.
SDK-45289	576151	88640_A0	Background: In Field Processor module, Field groups (aka Databases) do not have necessarily pre-selectors. If not set, for the BCM88640 device, an implied pre-selector is selected according to the Field group qualifiers. Issue: Databases without explicit pre-selectors were not selected because the implied pre-selector was not set correctly. WA: None
SDK-45295	617162	88750_A0	88750: Software Reset should not isolate the chip. Fixed.
SDK-45331		88650_A0 88650_B0 88650_B1	Change (without any additional configuration) the division to 1/64 instead of 1/16. Add the ability to use "virtual stack" (will be limited to 4 TMD connection). User can define any set of stacking ports as virtual stack.
SDK-45339	617523	88650_A0	Add user parameters validation to bcm_cosq_threshold_set() API. The QDCT_TABLE PD thresholds are 15 bits wide but the values are restricted to 4k. The driver will now throw an error when trying to configure those thresholds with illegal values. When calling the API bcm_cosq_threshold_set() to set queue's PD threshold (either drop or flow control) the API will return an error if trying to set a value greater than 4k.

Table 77:

Number	CSP #	Chips	Release Notes For 6.3.0
SDK-45340		88650_A0	88650: ARAD supports changing port interfaces dynamically. The feature supports the following interfaces: XFI, XLAUI, CAUI. Support for the following interfaces added: ILKN, RXAUI, XAUI and SGMII.
SDK-45342		88650_A0	Egress same-interface filter was disabled on init, by mistake. Fixed the code to enable the same-interface filter. User can control per port enable/disable the filter by calling API <code>bcm_port_control_set</code> with <code>control_type = bcmPortControlBridge</code>
SDK-45353		88650_A0 88650_B0 88650_B1	Force all incoming traffic from given port to invalid destination in the IRE. The default configuration is not change, meaning no additional configuration needed for one which is not using this feature (Panini for example). In order to discard the traffic, the API should be called. Please refer to the following example: Driver init: 1. Call to <code>bcm_stk_my_modid_set()</code> to set the mod-id. 2. Disable all the TDM ports by calling the API. 3. Call to <code>bcm_stk_module_enable()</code> . Provisioning example 1. Configure the Ingress and Egress by calling to <code>bcm_fabric_tdm_editing_set()</code> 2. Enable the traffic by calling the <code>bcm_port_control_set()</code> De-provisioning sequence example 1. Disable incoming traffic by calling to <code>bcm_port_control_set()</code> Bug
SDK-45385	617412	56840_A0	Added Rx packet rate control for Linux KNET kernel module.
SDK-45475		88650_A0	Background: IPv4 MC program may do RPF check as well as MC entry search. In that case the search is done in the IPv4 UC tables. Limitation: When using ELK for IPv4 MC tables - then IPv4 UC tables should use ELK as well for the RPF check to succeed. Same happens when IPv4 MC doesn't use ELK. The driver forces the use of ELK for both tables or none (will produce an error if MC table uses ELK but UC table doesn't or the opposite).

Table 77:

Number	CSP #	Chips	Release Notes For 6.3.0
SDK-45476		88650_A0	<p>Restrict APIs from committing changes during traffic.</p> <p>=== CAUTION === This change may affect existing applications. Some invalid scenarios, previously not verified by the driver, are now verified and will return an error indication if encountered. The APIs/attributes listed below must be called before enabling traffic, which is done by the <code>bcm_stk_module_enable()</code> API. Calling these APIs after <code>bcm_stk_module_enable()</code> is not permitted, and will result in driver error. The following APIs will return an error if called after traffic is enabled: - <code>bcm_cosq_gport_threshold_set()</code> + if threshold->type = <code>bcmCosqThresholdAvailablePacketDescriptors</code> + if threshold->type = <code>bcmCosqThresholdAvailableDataBuffers</code> - <code>bcm_cosq_gport_egress_multicast_config_set()</code> + Always, regardless of input parameters. - <code>bcm_cosq_gport_egress_map_set()</code> + Always, regardless of input parameters. -- An override option using a custom SOC property is available, to be used only if guided by Broadcom AE.</p> <p>Also, before enabling traffic the driver verifies the following: - Each egress queue can only use a single service pool. - The MAX reserved value is equal to the sum of the reserved PDs per queue per service pool - The MAX reserved value is less than the maximum PDs allowed per service pool (13k)</p>
SDK-45491	616124	All	<p>Jumps in time provided by <code>sal_time()</code> no longer cause discrepancies in signaling message times, given that the SAL has a monotonic <code>sal_time_usecs()</code> function.</p>
SDK-45521		56850_A0	<p>Following qualifiers are now supported in Trident2 Egress Stage with the JIRA fix <code>bcmFieldQualifySrcClassL3</code> <code>bcmFieldQualifySrcClassField</code> <code>bcmFieldQualifySrcClassL2</code> <code>bcmFieldQualifyDstClassL3</code> <code>bcmFieldQualifyDstClassField</code> <code>bcmFieldQualifyDstClassL2</code> <code>bcmFieldQualifyInterfaceClassL2</code> <code>bcmFieldQualifyInterfaceClassL3</code></p>
SDK-45576		88650_A0 88650_B0	<p>wrong warmboot data restore that can mainly effect following APIs after warmboot: <code>bcm_cosq_gport_threshold_set/get</code> <code>bcm_cosq_control_set/get</code></p>
SDK-45585		56840_A0 56845_B0 56841_B0	<p>Handle TD+ MMU SER correction for ES, THDI, MTRO regs.</p>
SDK-45613		88650_A0 88650_B1	<p>Fixed the FC init function to properly handle SAFC settings due to SOC Properties.</p>
SDK-45624		88650_A0	<p>Fixed an issue that when calling <code>bcm_vlan_translate_egress_action_set</code> to change <code>outer_tpid_action</code> and then <code>bcm_vlan_translate_egress_action_get</code>, the returned inner tpid was the new <code>outer_tpid</code>.</p>

Table 77:

Number	CSP #	Chips	Release Notes For 6.3.0
SDK-45643		53600_A0 53288_A0 53286_A0 53284_A0 53283_A0 53282_A0 53262_B1 53242_B1 53242_A0 53001_A0	Fix the issue that removing FE0 port from the bcm config pbmp_valid causes the initialization fail for FE+GE switches of ROBO FE family
SDK-45727	619823	56850_A1	56850: Fixed issue with group create on EFP with CpuQueue(bcmFieldQualifyCpuQueue) as qualifier.
SDK-45729		88650_A0 88650ACP_A0 88650_B0 88650_B1	For PON 2 tags manipulation, bcm_vlan_translate_egress_action_add of PON ports just needs to do the outer VLAN translation. It's not necessary to take care of tunnel_id anymore.
SDK-45768	587055	88650_A0 56640_A0 56640_B0	Always return SOC_E_FUNC_NOT_FOUND for function searchPCSFuncTable
SDK-45796	607348	88650_A0	<p>Description: At egress Field Processor, the HW correlates the counting action (bcmFieldActionStat) with the redirection (bcmFieldActionRedirect). An improper SW implementation was forcing the user to set a stat-id related to the entry-id for simplicity. Since the number of stat-ids is limited, an error was occurring for high entry ids.</p> <p>Fix: The sequence of using both actions at egress (bcmFieldActionStat & bcmFieldActionRedirect) is changed: - when an entry must redirect and count, the user must indicate in bcmFieldActionRedirect the destination port, and in bcmFieldActionStat the stat-id (in param0). From now on, the user sets also in param1 of bcmFieldActionStat the destination port again. The stat-id must be between 1024 and 3839 (Counter-ID value). Refer to cint_field_egress_modify_tc_per_port.c for example. - when an entry must only redirect, the user must call both actions (bcmFieldActionStat & bcmFieldActionRedirect) similarly to the previous, with stat-id = 0 to indicate the Counter-ID is not to be changed. - An entry cannot only change the Counter-ID without redirecting due to an HW limitation</p> <p>Besides, the user cannot use bcm_field_stat_create[id] and bcm_field_entry_stat_attach at egress.</p> <p>WA: None</p>
SDK-45798	620819	88650_B1	<p>Background: When calling entry install, a first attempt is performed to insert the entry and if it fails because there is no bank or bank is full, a new bank is allocated to the field group. The problem was that there was no validation that this bank has free entries. Then a second attempt is performed and if the allocated bank had no free entries the action fails.</p> <p>Fix: Add validation that bank is not full when allocating it.</p>
SDK-45807	616113	88650_B1	<p>Background: In Field processor configuration, PMF programs are HW entities not directly handled by the user. The PMF program is unique by its set of supported Databases. When removing a FP database, the Driver looks if another PMF program exists with the same set of Databases. If not, the resources taken by this database in this program are freed. If so, the whole PMF program is freed by copying a clean program to it. In case of an Egress database, the PMF program erase was not correct.</p> <p>Fix: Added a fix in the copy method of Egress programs.</p>



Table 77:

Number	CSP #	Chips	Release Notes For 6.3.0
SDK-45851	617348	56544_A0 56542_A0 56540_B0 56541_B0	Memory sanity scripts are included in the FILES.esw package.
SDK-45908		56854_A0 56850_A0 56855_A0	bcmFieldQualifyColor qualifier is now supported in Trident2 device Ingress Stage.
SDK-45943		88650_A0 88650_B0	ARAD Field warm boot, following was not restored after : 1. preselectors. 2. tcam actions. 3. entry flags (less critical, has effect only when doing WB in the middle of field API sequence).
SDK-45944	622458	88130_B0 88130_A1	bcm_crossbar_enable_set () fix for BM9600 - when BAG rate is 0, do not scale result to avoid divide by 0 issue.
SDK-45968		88650_A0 88650_B0	compilation error when compiling for ARAD only with warm boot support: BCM_PTL_SPT=1 BCM_88650_A0=1 BCM_88650_B0=1 # BCM_88640_A0=1 (No definition) CFGFLAGS += -DBCM_WARM_BOOT_SUPPORT
SDK-46651	627582	88650_B1	Background: Validation of TCAM entries is done while reading all entries per database. The loop which reads the entries used the wrong database ID range, which may have been invalid in some cases. Fix: Change of database ID to right range.
SDK-47645	649813	All 88650_A0 88650_B0 88650_B1	Added support for running ARAD dram tunning algorithm ('shmoo') on multiple devices in parallel
SDK-50501	696776	56850_A0	It is required to disable linkscan on the port to be converted by flex port, and re-enable linkscan afterward. This is defined in flex port section in port module of API reference manual.
SDK-51442	707742	56850_A2	Disabling CL37 error timer to prevent TSC to restart CL37 through link down process will fix the problem of this JIRA.

