

Software Development Kit Release Notes SDK 6.4.11

March 07, 2016

Broadcom
Network Switching

Section 1: About This Document

These are the Release Notes for the Broadcom Network Switching Software Development Kit Release 6.4.11.

This document provides a general description of the release and its new features. It also describes the chips supported by the release, BCM API additions or changes, resolved issues, and any relevant open issues. The reader should refer to prior release notes for 6.4.x, as only new features or issues are described in this version of the release notes.

Section 2: Product Documentation

The following documents in `Product Documentation` ([page 3](#)) are available through Broadcom's Customer Support Portal, <http://support.broadcom.com>. They are the primary source of information and should be referenced when using this release:

Table 1: Product Documentation

Document	Description
56XX-PG6411-R	BCM API Reference Guide. This manual describes the theory of operations of the API and all existing BCM APIs for this release.
56XX-PG707-R	Stacking Software Guide This guide describes how to use the discovery and stacking applications provided in this release.
56XX-PG819-R	Platform Guide This guide describes the SDK source and Makefile structure, abstraction and porting layers, device specific interactions, and the platform/operating system specific features of the SDK. If this is your first time working with the SDK, start with this document.

Section 3: New Devices added to this release

For any given SDK release, support for certain devices may be provided in Preview or Supported status. Devices in Supported Switch Devices (page 4) and Supported PHYs (page 4) have completed the full QA process and are intended for use in production systems. It is expected that customers would integrate the version of the SDK which provides "Supported" status for their use on actual development or production systems.

Devices in Preview Switch Devices () and Preview PHYs (page 4) are provided to allow early integration of the customer's application with the SDK APIs that support that device. This software has not been fully tested on the physical target device and should not be expected to fully function.

Table 2: Supported Switch Devices

Family	Devices	Description
BCM56260	BCM56233 B0	4xGE UNI + 2xGE NNI + 2.5GE to FPGA
BCM56960	BCM56961 B1	64x40GbE port configuration
	BCM56962 B1	24x 100GbE/48x 40GbE Multilayer Switch
	BCM56968 B1	32x HG[106]/64x HG[42] Multilayer Switch

Table 3: Supported PHYs

Device	Driver Family	Description	Switch qualified against
BCM82864	82864	40GbE PMA MUX/DEMUX with 100GbE Bypass	BCM56960
BCM82790 A0	82790	100GbE/OTN CAUI-to-10GbE VSR/CR4/SR4/LR4/KR4 Gearbox PHY	BCM56860
BCM82792 A0	82790	Dual 100G/OTN CAUI-to-100GbE VSR/CR4/SR4/LR4 Gearbox PHY	BCM56860
BCM82796 A0	82790	Dual 100G/Quad 40G VSR/CR4/SR4/LR4 Gearbox PHY	BCM56860
BCM84328	84328	Dual 40GbE/Octa1 10GbE QSFP+ XLPPI-to-XLAUI PHY	BCM56860
BCM82328	84328	Dual 40GbE/Octa1 10GbE QSFP+ XLPPI-to-XLAUI PHY	BCM56860

Table 4: Preview PHYs

Device	Driver Family	Description	Switch qualified against
BCM82332	82332	1x 100G/3x 40G/12x 10G Ethernet PHY	BCM56860
BCM82793	82332	100G Gearbox for 100GBASE CR4/SR4/LR4 & SR10	BCM56860



Section 4: New Features per Device

BCM56860 UPDATES

ADDITIONAL FEATURES SUPPORTED

This release adds GA functionality for IoT support on VPLS and Beta functionality for IoT support on L2GRE.

BCM88670-FAMILY GA RELEASE

This release is for the BCM88370-Family and BCM88670-Family product lines. Compared to 6.4.10, the 6.4.11 release delivers increased quality as well as introducing new features.

The subsequent sections describe the increment in available features compared to 6.4.11, major bug-fixes and known issues.

IMPORTANT NOTES

- Release is aligned with KBP-SDK 1.3.12 for external TCAM and KAPS.
- Scheduled Warmboot is supported
- ERSPAN header encapsulation is now changed: In the GRE header, the K flag is reset and the S flag is set (aligned to ERSPAN type2 RFC).
- P2P traffic set packets now to be considered as Known-DA, in previous versions it was set as unknown-DA. This influence for example: Ethernet policer functionality and Egress filtering according to DA-type. Note: PON application still consider P2P traffic as Known-DA (see errata).
- In system mode where `bcm886xx_vlan_translate_mode` soc property is set to 0, packets with IVE command 0 (NOP action) will have now PPH increased by 3 bytes in order to pass important information such as In-LIF filtering resolution at the egress and allow Up-MEP OAM functionality
- Qualifier `bcmFieldQualifyOutPort` is blocked for 88670 (since it does not have a 'core' bit). Use `bcmFieldQualifyDstPort` instead.

BCM88670-FAMILY B0 REVISION SUPPORT

Following is the list of the expected bug fixes and enhancements that require SDK support and its timeframe.

Table 5: BCM88670-Family B0 revision support status

Feature/Bug fix	SDK JIRA	Documentation	Timeframe	Comments
OAM UP-MEP LIF-profile	SDK-87294	Errata#1	6.5.4	
ETPP Counter Pointer by OutLIF	SDK-76171	Errata#3	6.4.10	Completed
Hierarchical FEC Does Not Work When the 1st FEC Hierarchy is Unprotected	SDK-75505	Errata#17	6.4.9	Coding & Validation completed
OAM Classifier Can Not Count Per Priority	SDK-84890	Errata#18	6.4.11	

Table 5: BCM88670-Family B0 revision support status

Feature/Bug fix	SDK JIRA	Documentation	Timeframe	Comments
ROO remarking of Native IP Header	SDK-76172	Errata#19	6.4.11	6.4.9 coding is done. Completed validation in 6.4.11.
Routing out of Mac-in-MAC Tunnel (part of ROO SPB)	SDK-76178	Errata#20	6.4.10	
IP-MC Fallback to Bridge PCP/DEI	SDK-76174	Errata#21	6.4.10	
MPLS LSR EXP remark	SDK-76175	Errata#22	6.5.3	
GLEM Trap is Not Reliable	SDK-75507	Errata#23	6.4.10	
Mapping TC-DP to EXP/TOS at the ETPP is using wrong profile	SDK-88249	Errata#33	6.4.11	Most coding in 6.4.9. Validation completed in 6.4.11.
Egress VLAN Editing (EVE) Used to Remove VLAN Tags Causes Outbound Mirroring to Work Improperly	SDK-76177	Errata#34	6.4.10	Implemented and validated
MPLS EEDB Utilization Improvement, MPLS PUSH2SWAP	SDK-81282	Section in 88670-AG304-R document	6.4.10	
Forwarding and Link-Layer MTU per Out-LIF	SDK-76184	Section in 88670-AG304-R document	TBD	
Egress VLAN Membership Check	SDK-76177	Section in 88670-AG304-R document	6.4.10	Implemented and validated
14 MPLS Push Commands	SDK-79923	Section in next 88670-AG304-R document (not published yet)	6.4.10	
LB Key Enhancements	SDK-82302	Section in next 88670-AG304-R document (not published yet)	6.4.11	

VALIDATED FEATURES

Basic data path, connectivity and Traffic Management features:

- Packet size mechanism for Metering
- SAT Frame Delay
- Header compensation for E2E Scheduler and CRPS
- NIF Priority Drop

Packet Processing:

- PON (including ARM)
- OAM: SAT Up-MEP LBM/TST
- L3 LPM(KAPS) now supports single DB mode. The value 0 for the soc property `public_ip_frwrdd_table_size` is now valid.
- Routing over AC (`cint_route_over_ac.c`)
- Support SLM transmission through the OAMP
- MPLS TUNNEL (B0 only): One egress encapsulation entry can be used for both push and swap commands,



according to the incoming packet parameter (forwarding protocol and the entry location in the EE stack). In case forwarding protocol is MPLS and the entry is the innermost encapsulation, SWAP will be performed. Otherwise PUSH command will be executed. To enable this functionality soc property `mpls_encapsulation_action_swap_or_push_enable` should be set to 1 and `bcm_tunnel_initiator_create` action should be set to `BCM_MPLS_EGRESS_ACTION_SWAP_OR_PUSH`.

- For L3VPN application, tunnels that were terminated according to DIP, SIP & VRF are now terminated according to DIP, SIP, VRF, IP Protocol and GRE Protocol Type (where applicable). IP Protocol & GRE Protocol Type are set according to a Tunnel type value.

NEW FEATURES

- Added new API procedures (`bcm_field_action_width_set()`, `bcm_field_action_width_get()`) to control number of bits (width) required per action. Details are in the updated 88X7X-PG1XX Programmer's Guide document.
- BCM88670 ITMH is only parsed when SOC property `itmh_programmable_mode_enable` is set to '0'. For BCM88670 to parse ITMH header of BCM88660 correctly, user should set `itmh_programmable_mode_enable=1` and `itmh_arad_mode_enable=1`.
- The qualifier `bcmFieldQualifyOutPort` may not be used on BCM88670. Instead, user should take `bcmFieldQualifyDstPort`.

MAJOR BUGFIXES

The list below refers to major bugfixes, and does not provide a comprehensive coverage of various bugfixes on all levels.

Basic data path, connectivity and Traffic Management features:

- ROP fix for Jericho`MX B0.

Packet Processing:

- In FCoE, delete and get LPM route (using flag `BCM_FCOE_DOMAIN_ROUTE`) failed due to internal error. Issue fixed and now it is possible to get and delete LPM entries.
- In L3, when calling `bcm_l3_host_traverse()`, only up to 129 entries were handled by the callback function, even if more hosts reside in the host table.
- In L3, when setting the SOC property "`bcm886xx_l3_ingress_urpf_enable=1`", a bit was allocated in the inLIF profile for uRPF handling (as in ARAD+). This behavior is correct only for ARAD+, because in Jericho, the inRIF profile controls the uRPF behavior. All redundant LIF configurations related to uRPF have been removed for Jericho.
- P2P traffic set packets to be considered as Unknown-DA while it is expected to be Known-DA. This influence for example: Ethernet policer functionality and Egress filtering according to DA-type. This is now fixed.
- When using the API `bcm_l2_replace()` with the flag `BCM_L2_REPLACE_MIGRATE_PORT`, the destination was not properly updated
- Tunnel termination mode 6 (DIP,SIP,VRF) did not relate to TunnelType
- The creation of multiple endpoints using `bcm_oam_endpoint_create`, `bcm_oam_endpoint_action_set` run time was improved by an order of magnitude.
- ERSPAN IP Length was fixed for IP routed packets.
- IPv4 tunnel termination was not terminated correctly when `bcm886xx_ipv6_tunnel_enable` was set to '0'. There was wrong processing in Tunnel Termination micro-code.
- Outbound mirroring for out-port has been fixed. Extended API (`bcm_mirror_port_vlan_destination_add()`) now updates profile corresponding to 'mirror_dest'.

ERRATA

The list below relates to major open bugs that are not resolved:

Packet Processing:

- OAMP report mode is not supported
- OAM server is not supported
- BFD: Remote Multiplier detection is not functional
- OAM/BFD statistics is not functional
- When UDH is enabled in the system (User-define-header) following OAM/BFD applications are not functional: MAID 11B, BFD echo, BFD PWE GAL, Micro-BFD
- PON application consider P2P traffic as known DA instead of unknown DA.

FEATURE STATUS

Table 6: Features Status

Features	Status
Initialization sequence, Register Access, PCID, Access TR Tests	GA
ARAD+ : Base Legacy Features (L2, L3, STG, MPLS, COSQ,QOS, RX/TX)	GA
FP (PMF)	GA
Ports and Interfaces	
10GE KR/XFI	GA
10GE RXAUI	GA
10GE XAUI	GA
40GE XLGE	GA
40GE XLGE-2	GA
100GE CGE	GA
SGMII	GA
QSGMII	GA
ILKN-12	GA
ILKN-24	GA
Eyescan	GA
Autoneg (CL72/73/93...)	GA
LinkScan	GA
NL12	GA
Statistics/Counting	
MIB counters	GA
Statistics Interface	GA
Counter Processor	GA
CPU/Access	
Packet DMA (CPU RX/TX)	GA
RCPU	GA
Fabric	
TDM	GA
Pipes: single, dual, triple	GA
Cell packing	GA
Repeater link	GA

Table 6: Features Status

Features	Status
Reachability enhancements: routing bitmap, links to destination	GA
Fabric RX/TX FIFO Scheduling	GA
Fabric RX FC, Drop & RCI	GA
Link Level FC	GA
Mesh Connectivity	GA
Source Routed Cells	GA
Live card Insertion/removal	GA
Fabric Isolation	GA
Traffic Management and Queuing	
Basic UC/MC	GA
MC double-CUD	GA
Mirroring	GA
Recycling	GA
VSQ	GA
SYSTEM RED	GA
Other Legacy Features (Routing & Tunneling & Leased svcs)	
TRILL	GA
LAG	GA
Tunnel	GA
MIM	GA
FCOE	GA
Cell-packing	GA
VPLS	GA
FEC Management	GA
Vxlan	GA
Vswitch	GA
ECMP	GA
Flow Control	
Inband Link level	GA
Inband PFC	GA
Inband ILKN	GA
OOB ILKN	GA
HCFC	GA
SPI	GA
COE	GA
FC Generation (based on VSQ/Ing. Resources)	GA
New or Enhanced Features	
Policer	GA
Routing	
MPLS Enhancements	GA
Hierarchical-FEC L3	GA
VRMP Enhancements	GA
RIOT/ROO (Unicast)	GA
TDM	GA
IPV4 (LPM)	GA
IPV6 (LPM)	GA
H-FEC VPLS	GA
MPLS/VPLS Multicast	GA

Table 6: Features Status

Features	Status
Routing Improvements	GA
Overlay/ROO/RIOT MC	GA
Routing over Trill	GA
DCB	
ECN	GA
802.1BR, UC L2 bridging only	GA
Miscellaneous	
Interrupts	GA
External PHY (mechanism only, each specific phy/reTIMER requires dedicated interop)	LGA
Dynamic Port Provisioning	GA
HiGig	GA
SER Protection	GA
SyncE	GA
Protection improvements : Coupled-mode OutLIF	GA
EVPN	GA
Ingress Congestion Management	GA
Ingress Shaping	GA
SAT	Beta
OAM & Access	
Ethernet OAM over LAG	GA
OAM (ARAD+ compatible)	GA
BFD (ARAD+ compatible)	GA
OAM/BFD enhancements	GA

BCM88770 (FE3600) RELEASE

The Broadcom BCM88770 (formerly named BCM88950) is the fourth generation in the Dune product line of Fabric Element (FE) devices.

This is a sustain release of BCM88950 driver, with all major features supported.

BCM88660 (ARAD+) RELEASE

This is a sustain release of BCM88660 driver, with all major features supported.

MAJOR BUGFIXES

- OAMP server: destroying, updating Up MEP failed.

NEW EXTERNAL PHY SUPPORT

BCM8279X ADDITIONAL SUPPORT

The BCM82792/6 is a dual 100Gbps Gearbox PHY that multiplexes and demultiplexes eight 25Gbps channels to/from twenty 10Gbps channels supporting Ethernet and Optical Transport Networking(OTN). The BCM82792/796 is compli-

ant with the IEEE 802.3ba standard for 100GbE and ITU OTL4.4 signaling, as well as 40GbE, OTL 3.4, and OTL 4.10. The Lane interface supports four bidirectional lanes at 25.78125/27.952493 Gbps for 100GbE/OTL4.4 applications.

This release is considered GA for BCM8279x. Additional functionality supported in this release:

- HIGIG2
- All flexport modes including these added in the release: 100G GB to 40G Mux 100G GB to 10G PT Enzo mode 40G Mux to 100G 10G PT Enzo mode to 100G GB 40G PT Enzo mode to 40G Mux

Limitations:

- Chip reset will reset all the ports that share the same PHY-ID (MDIO ADDR).

BCM82864 ADDITIONAL SUPPORT

The BCM82864 is a 40Gbps PMA Gearbox phy that demultiplexes eight 20Gbps channels to sixteen 10Gbps channels supporting Ethernet and Optical Transport Networking(OTN). Additionally the device will operate in 100GbE mode where the BCM82864 supports two full-duplex 100Gbps ports.

This release is considered GA for BCM82864. Additional features supported in this release:

- LR2/SR2/CR2/KR2 are supported in this release.
- CAUI4, CAUI-C2C, CAUI-C2M interfaces are supported in this release
- Retimer is supported in this release.

Driver Limitations:

- Chip reset will reset all the ports that share the same PHY-ID (MDIO ADDR).
- Flexport and Higig are supported at Beta level in this release.

BCM82328/BCM84328 SUPPORT

BCM82328 is a low power, low latency PHY integrating retiming and equalizer functions supporting 40-GbR and 10GbE applications. In 40G mode it supports two full-duplex 40GbE ports (XLPPPI-to-XLAUI/KR4) for SR4, LR4, and copper CR4 QSFP+ line-card applications. In 10G mode, it supports eight full-duplex 10GbE ports (SFI-to-XFI/KR) for SR, LR and copper CR SFP+ line-card applications. Operates with the following reference clocks: Single 156.25 MHz differential clock for 1.25 Gbps, 10.3125 Gbps and 11.5 Gbps Functionality Supported:

- Link status
- Speed and Interface configuration
- port enable/disable
- Duplex set/get
- Polarity inversion
- Power set/get
- PRBS
- Loopback set/get
- Diagnostics
- Tx set/Get
- Rx set/Get
- Auto negotiation
- Reg read/write
- PHY Reset
- I2C module controller

- Auto module detect
- Probe

Driver Limitations:

- Repeater mode only, no retimer operation
- Clause 73 only for starting Clause 72 and requesting FEC. No speed resolution performed. No Clause 73 in 11.5 Gbps line rate, only Clause 72 supported. Clause 72 may be enabled standalone for close systems. Clause 37 is not supported. No on-chip FEC encoding/decoding, but shall pass-through FEC-encoded data.

BCM84328 is a low power, low latency PHY integrating retimer and equalizer functions supporting 40-GbR and 10GbE applications. In 40G mode it supports two full-duplex 40GbE ports (XLPPI-to-XLAUI/KR4) for SR4, LR4, and copper CR4 QSFP+ line-card applications. In 10G mode, it supports eight full-duplex 10GbE ports (SFI-to-XFI/KR) for SR, LR and copper CR SFP+ line-card applications. Operates with the following reference clocks: Single 156.25 MHz differential clock for 1.25 Gbps, 10.3125 Gbps and 11.5 Gbps. Functionality Supported:

- Link status
- Speed and Interface configuration
- port enable/disable
- mdix set/get
- Polarity inversion
- Power set/get
- PRBS
- Loopback set/get
- Diagnostics
- Tx set/Get
- Rx set/Get
- Auto negotiation
- Reg read/write
- PHY Reset
- Probe
- I2C module controller
- Auto module detect

Driver Limitations:

- Repeater mode only, no retimer operation.
- Clause 73 only for starting Clause 72 and requesting FEC. No speed resolution performed. No Clause 73 in 11.5 Gbps line rate, only Clause 72 supported. Clause 72 may be enabled standalone for close systems. Clause 37 is not supported. No on-chip FEC encoding/decoding, but shall pass-through FEC-encoded data

Section 5: Things to note

This section lists items that require special attention that are new to this release. Please see prior 6.4.x release notes for a list of older items that should also be noted.

ALERT ON END OF MAINTENANCE RELEASE CYCLE FOR SDK 6.4

This SDK 6.4.11 release is the last official maintenance release under the SDK 6.4 delivery stream. For new designs or software releases, customers should plan on moving to the upcoming SDK 6.5.3 release.

ROUTE INSTALLATION CONSIDERATIONS ON BCM56960 IN ALPM MODE

In BCM56960, due to the relatively small size of UFT and the design of sharing one UFT bucket between multiple pivots, the `bcmSwitchObjectL3RouteV4RoutesMax`, `bcmSwitchObjectL3RouteV6Routes64bMax` and `bcmSwitchObjectL3RouteV6Routes128bMax` in ALPM mode return the number of maximum possible routes that could be installed respectively. The actual number of routes that could be installed may be smaller than those objects.

BCM56860 FLEXPOR MAXIMUM NUMBER LOGICAL PORTS WHEN SUPPORTING PORT

BCM56860 supports only up to 44 logical ports per pipeline (i.e. 88 for entire device) when system is configured for port speeds $\geq 100\text{GE}$.

SLIGHT DEVIATION OF TRAFFIC DISTRIBUTION ACCURACY ON BCM56860

BCM56860 customers may see some slight deviations with the accuracy of traffic distribution in MMU. The amount of deviation is less than 1%, and depends on the packet size and traffic conditions. The issue will remain intermittent until Broadcom completes internal verification and tuning of MMU parameters as a part of BCM56860 PRA preparation.

Once optimized MMU settings become available, they will be integrated into a future SDK release

MINIMUM VXLAN VPN ID FOR BCM56860 AND BCM56960

VPN ID 0x7000 is allowed when calling `bcm_vxlan_vpn_create` with `BCM_VXLAN_PORT_WITH_ID` on BCM56850. It is not allowed for BCM56860 and BCM56960 due to VPN ID 0x7000 is reserved on those devices.

BCM56960 - MIX OF AUTONEG AND FORCED SPEED PORTS

WITHIN A SINGLE FALCON

Due to a single PLL constraint inside the Falcon, a mix of both autoneg and forced speed on a single core is currently not supported. All the ports on a single core should be all in autoneg or forced speed mode. The first port of a core doing autoneg will disable the rest of the forced speed ports on the same core. Once the first port on a core completes autoneg and the VCO is locked, the rest of ports on the same core can only do autoneg with the same VCO.

CHANGES IN TRUNK FIELD ACTION IN BCM56960

BCM56960 supports only RoundRobin and Random hashing unlike older devices. Hence, Field actions - `bcmFieldActionDynamicHgTrunkCancel`, `bcmFieldActionTrunkLoadBalanceCancel`, `bcmFieldActionEcmpLoadBalanceCancel`, which were used to disable dynamic hashing are not supported on BCM56960. These are updated to new field actions `bcmFieldActionHgTrunkRandomRoundRobinHashCancel`, `bcmFieldActionTrunkRandomRoundRobinHashCancel`, `bcmFieldActionEcmpRandomRoundRobinHashCancel` which can be used to disable HG Trunk load balancing, Trunk load balancing and ECMP load balancing respectively.

SPN_PHY_PORT_PRIMARY_AND_OFFSET CONFIG PROPERTY IS REQUIRED FOR NEW PHYS

Setting of the config property `spn_PHY_PORT_PRIMARY_AND_OFFSET` is absolutely required for the following PHYs. BCM54880E BCM54680E BCM54682E BCM54685E BCM54640E BCM542XX

POTENTIAL BCM MODULE DETACH ISSUE IN THE RELEASES PRIOR TO 6.4.7

In pre-6.4.7 releases, during bcm detach, UDF module is detached even before field module. In addition, during Field detach, there is deference to UDF module elements which got freed earlier. This was causing segmentation fault.

If the segmentation fault issue is seen during `bcm_detach`, patch from SDK-76765 needs to be applied.

Table 7: Potential Impacts

Scenarios	Devices
Warmboot	<ul style="list-style-type: none"> • BCM56240
Applications need detaching BCM modules	<ul style="list-style-type: none"> • BCM56260 • BCM56340 • BCM56440 • BCM56450 • BCM56530 • BCM56545 • BCM56630 • BCM56640 • BCM56840_PLUS • BCM56850 • BCM56860 • BCM56960 • BCM56260 • BCM56460

BCM82780 INTERFACE CONSIDERATIONS

If using BCM82780 40G mode with interface type CR4/LR4/SR4/KR4, it is required to set the system interface config side to XLAUI/KR4.

For example:

```
phy_sys_interface_xe0=15 /* to set it to XLAUI */
```

If using BCM82780 10G mode, it is required to set the external PHY primary core number config variable in the config file. If the MDIO address of the first port for a given core is 0x20.., the config variable should be set as follows:

```
Xphy_primary_core_num_32=0x20
Xphy_primary_core_num_33=0x20
Xphy_primary_core_num_34=0x20
Xphy_primary_core_num_35=0x20
```

The syntax is : Xphy_primary_core_num_<mdio address in decimal>=<primary port mdio address> In BCM82780 if the port is in KR4 mode, should the user intend to change the interface the command needs to be executed twice:

```
>port xe0,xel if=xlaui sp=40000 an=0
>port xe0,xel if=xlaui sp=40000 an=0 /* to change interface from KR4 to XLAUI
*/
```

RECENT PHY INTERFACE LIBRARY CHANGES

The 100G interface for BCM56860, BCM86375, and BCM88560 devices required extensive changes to the interface library called "Portmod". In SDK 6.4.8, BCM5686x operations for "Portmod" with BCM8279x family was verified. BCM8279x is GA quality in release SDK 6.4.9. For legacy 10G/40G devices, the "Portmod" changes required the shim layer to be created to enable the drivers to connect to the Falcon and Eagle cores. This work was completed in SDK 6.4.8, and thus made these legacy PHYs operational with the Portmod capable switches noted above.

ENGINEERING SUPPORT STATEMENT FOR OLDER XGS SDK RELEASES

The following releases are now out of XGS engineering support since they are older than 12 months since release:

- SDK 6.4.x releases: 6.4.4, 6.4.3, 6.4.2, 6.4.1, 6.4.0
- SDK 6.3.x releases: 6.3.11 and older
- All 6.2.x and older releases.

Service impacting defects will be reviewed and potentially addressed on these older releases. Support for non-service impacting defects will only be provided to customers running a SDK release that is less than 12 months old.

The following table Resolved issues and improvements per older XGS device family ([page 16](#)) shows the number of issues and improvements that have been added to our supported SDK releases by device over the past 12 months. While the table shows individual devices, many issues and improvements will apply to multiple products, e.g. BCM56850 and BCM56860, or all XGS products.

Table 8: Resolved issues and improvements per older XGS device family

Device specific issues	Bugs resolved in the past 12 months	Improvements added in the past 12 months
BCM56850 family	348	167
BCM56840 PLUS	69	10
BCM56340 family	73	15
BCM56640 family	148	36
BCM56450 family	226	67
BCM56150 family	28	2
BCM56440 family	61	10
BCM53440 family	44	30

NOTES AND CONSIDERATIONS OF WARMBOOT FOR SPECIFIC DEVICES AND FEATURES

WARMBOOT: VALIDATED WARMBOOT UPGRADES

Following warmboot upgrades in Warmboot: Validated Warmboot upgrades ([page 17](#)) have been validated in this release.

Table 9: Warmboot: Validated Warmboot upgrades

Software upgrade Supported	
6.4.10 to 6.4.11	Yes
6.3.12 to 6.4.11	Yes

Warmboot testing and issue resolution has focused on the following family of devices:

- BCM53400/BCM56060
- BCM56150
- BCM56220
- BCM56340
- BCM56440
- BCM56450
- BCM56640
- BCM56840
- BCM56850
- BCM56860
- BCM56960

WARMBOOT SUPPORT FOR EMBEDDED APPLICATIONS

This section describes warmboot support and procedures for associated firmware supported in SDK 6.4.x. Below are the various embedded applications (FW) available and supported with SDK 6.4.x

- BFD
- BHH LM/DM
- MPLS LM/DM
- ETH LM/DM
- Broadsync
- 1588/PTP

All applications support warmboot with the exception of 1588/PTP. Warmboot for the above apps follows the same process like any other module on SDK side. Eapps warmboot support is through Level-2 warmboot i.e. requires information to be stored in sCache.

SDK warmboot doesn't affect execution of embedded applications (except 1588/PTP firmware) on internal ARM cores and they keep running as is and maintain their state.

Warmboot procedures

- Users are expected to invoke "sc ControlSync=1" command in the BCM diag-shell to store the information in sCache
- The corresponding API is `bcm_switch_control_set(int unit, bcm_switch_control_t type, int arg)`
- Note: Typically, storing of information in sCache is required when there is a module or session or context creation on SDK side. Calling of the `bcm_switch_control_set()` API is left to the discretion of user/customer depending on their system requirements for example, after each session creation or module init or before the warmboot procedure initiation

- Free up the resources attached to the unit by calling below API equivalent of "exit clean" BCM shell command. i.e, "`soc_shutdown (int unit)`" Note: BroadSync warmboot procedure mandates usage of the above API. As part of API, SDK informs the embedded ARM core about the warmboot process initiation so that BroadSync FW waits for the SDK warmboot procedure to complete for further communication

Steps to follow during the SDK warmboot

Below is an example sequence of diag-shell commands executed (through `reload.soc`) as part of the SDK warmboot sequence for initializing SDK HOST and firmware communication

- `MCSMsg INIT;`
- `MCSMsg 0;`
- `MCSMsg 1;`
- "MCSMsg INIT" and "MCSMsg x" commands invokes the below APIs respectively:
- `soc_cmhc_uc_msg_start(int unit) /* Allocates Messaging resources/Mutexes */`
- `soc_cmhc_uc_msg_uc_start(int unit, int uc) /* Starts Messaging with specific core.*/`

Customers have to include the above calls in their SW.

COSQ WARMBOOT

The scache file, which is used to store software data related to COSq during level-2 Warmboot for BCM56640 and related SKUs, has a different data structure between 6.3.x releases and 6.4.x releases. However, the data structure difference cannot be distinguished, because they are marked with the same warmboot version number.

If level-2 warmboot is used to upgrade from release 6.3.3 and later to release 6.4.x, the COSq module will be restored with incorrect data. Starting from 6.4.7, the `num_cosq` field has now been added in Scache which is later retrieved during WarmBoot and used.

WARMBOOT COSQ CONSIDERATION FOR BCM56340

In BCM56340 device family, CosQNew implementation was not incorrect in previous version. This programming error has been corrected using SDK-82083/SDK-83152 in 6.5.2 and 6.4.8.

Due to this while upgrading from older version, CosQNew action will be recovered as UcastCosQNew.

FLEXHASH WARMBOOT

Flex hash warmboot was implemented in SDK-6.4.7. If level-2 warmboot is used to upgrade from release 6.3.12, the Flex hash will be restored with incorrect data.

POTENTIAL WARMBOOT ISSUE IN 6.3.12 TO 6.4.7 ON BCM56450 DEVICE FAMILY

In 6.3.12 and earlier releases, the scheduling node properties were programmed in the wrong node for HiGig and loop-back ports. This was corrected in 6.4.5 and later releases. If the configuration was done on 6.3.12, it was configured incorrectly. After the Warmboot upgrade is performed and a read is issued, the reading is taken from the correct node and the comparison test fails for mismatched values.

The values don't match and it is causing failure in some of tests which read back and compare the values.

- 6.3.12 -> 6.3.12 -> Passes - value is configured and read from wrong node. Comparison test passes due to wrong reason.
- 6.4.5/6/7 -> 6.4.5/6/7 -> Passes -> Value is configured and read from correct node.
- 6.3.12 -> 6.4.7 -> Fails -> Value configured on wrong node, but read from right node. Comparison test fails since

value does not match.

The fix has to go into 6.3.12. Patch is available for 6.3.x related branches. It is recommended to patch this in 6.3.12, if scheduling node properties of HG or loop back ports are modified in 6.3.12.

POTENTIAL WARMBOOT ISSUES IN 6.3.12 TO 6.4.7 ON BCM56850 DEVICE FAMILY

In SDK-6.4.6 and SDK-6.3.12 releases, the port index used to store and recover E2ECC configuration during Warmboot synchronization and recovery was incorrect. This issue has been fixed in SDK-6.4.7. As a result, some 6.3.12/6.4.6 -> 6.4.7 warmboot test cases would fail since the port index value doesn't match after the warmboot. To get the case working, customers will require patching the code changes attached in SDK-79646 to SDK-6.4.6 or SDK-6.3.12. Releases starting with SDK-6.4.7 have no such problem.

SDK-6.4.6 and SDK-6.3.12 releases didn't include Warmboot support for the global configuration variable `_soc_td2_mmu_traffic_ctrl` which is used to control whether the traffic to a port should be enabled or not. This would potentially cause traffic to a port to be dropped after system Warmboot-upgrades to SDK-6.4.7. To get the case working, customers will require patching the code changes committed in SDK-77046 to SDK-6.4.6 or SDK-6.3.12. Releases starting with SDK-6.4.7 have no such problem.

In SDK-6.3.12 release, the value of the enum `BCM_PORT_PHY_CONTROL_PARALLEL_DETECTION` was different from that in SDK-6.4.X releases. This would cause the enum value saved in SDK 6.3.12 to not be interpreted correctly in SDK 6.4.7. To get the case working, customers will require patching the code changes attached in SDK-80136 to SDK-6.3.12. SDK-6.4.X releases have no such problem.

SDK-6.3.12 release didn't include Warmboot support for WRED Time Domain Configuration. This would cause the s-cache data structure mismatch between SDK-6.3.12 and SDK-6.4.7. To get the case working, customers will require patching the code changes attached in SDK-72889 to SDK-6.3.12. SDK-6.4.X releases have no such problem.

POTENTIAL WARMBOOT ISSUE UPGRADING TO 6.4.10 FROM RELEASES OLDER THAN 6.4.8

Warm-boot upgrades to release 6.4.10 from releases older than 6.4.8 could fail during "warm-boot sync", to avoid this, a patch would need to be applied before starting the warm-boot.

WARMBOOT CONSIDERATIONS FOR BCM56860 DEVICE FAMILY

In this release, support has been added for 2.5G speed in the BCM56860 devices. Therefore the AN capabilities for this release would have this additional capability and upgrading from SDK 6.4.8 should accommodate for this requirement.

WARMBOOT CONSIDERATION FOR BCM56860 DEVICE FAMILY

The warmboot function for `VLAN_VP_INFO` (Software book keeping for VLAN virtual port information) on BCM56850 was added on version 6.4.10. So warmboot case `AT_WarmBoot_123_Check` would be failed when upgrade from 6.4.9 to 6.4.10.

SCACHE SIZE REQUIREMENTS FOR BCM56960

In BCM56960 the field related software data structures is saved into the s-cache and software recovers and link them back after warm boot. The s-cache size needs to be increased to save all the data structures available in field module. Software depends only on the saved data for the recovery of IFP configurations after warm boot in BCM56960.

The total scache required for IFP in worst case configuration is around 36 MB and total scache requirement is around 40 MB.

SCACHE SIZE REQUIREMENTS FOR DEVICES IN LEGACY IFP SUPPORT

In warmboot design, the software data structures are saved into the sCache during warmboot sync. When the SDK boots in warmboot mode, it recovers the data structures from sCache and initializes the structures. The sCache size is calculated based on total size of various data structures, considering the max value of every field in the data structure.

In BCM56260, the total scache required for all modules together is 573408 bytes

In BCM53400, the total scache required for all modules together is 380188 bytes

INCREASE IN WARMBOOT SCACHE FILE SIZE FOR BCM56860 UPGRADE

Due to changes and/or fixes starting in SDK 6.4.11 in feature sets such as Mirroring and Policer, the minimum required scache file size has increased to 5169152 bytes. If the file size is overridden using manual configuration, it must be a size of at least 5169152 bytes else the warmboot upgrade to SDK 6.4.11 might fail.

Section 6: Summary of BCM API changes and enhancements

This section summarizes BCM API changes in this release. Complete documentation will be available in the Network Switching Software Programmer's Guide newer than 56XX-PG6411-R. (See section 2 earlier in this document for availability).

CLASS OF SERVICE QUEUE CONFIGURATION

New COSq statistics object is added as shown in `bcm_cosq_stat_t` ([page 21](#)) for `bcm_cosq_stat_getXX()` and `bcm_cosq_stat_setXX()` APIs. This is applicable to StrataXGS-III devices only.

Table 10: `bcm_cosq_stat_t`

Name	Description
<code>bcmCosqStatHOLDropPackets</code>	Per COSQ HOL drop packet count.

New COSq control types are added in this release as shown in CoSQ Control Type Values ([page 21](#)) for `bcm_cosq_control_set/get()`.

Table 11: CoSQ Control Type Values

Value	Description
<code>bcmCosqControlIngressPortDropTpid1</code>	<code>cosq</code> ingress port drop global TPID 1.
<code>bcmCosqControlIngressPortDropTpid2</code>	<code>cosq</code> ingress port drop global TPID 2.
<code>bcmCosqControlIngressPortDropUntaggedPCP</code>	<code>cosq</code> ingress port drop untagged PCP

New BCM COSQ APIs are introduced in this release.

`bcm_cosq_gport_pkt_size_adjust_set`

The purpose of this API is to configure a delta value for a source or enable/disable a certain compensation type.

Syntax

```
#include <bcm/cosq.h>
int bcm_cosq_gport_pkt_size_adjust_set(
    intunit,
    bcm_cosq_pkt_size_adjust_info_tadjust_info,
    intdelta);
```

Parameters

unit

BCM device number

adjust_info(IN)

bcm_cosq_pkt_size_adjust_info structure

delta(IN)

delta value

Description

The purpose of this API is to configure a delta value for a source or enable/disable a certain compensation type.

```

/* cosq_pkt_size_adjust_info structure */
typedef struct bcm_cosq_pkt_size_adjust_info_s {
    uint32 flags; /* flags */
    bcm_gport_t gport; /* gport value */
    bcm_cos_queue_t cosq; /* bcm_cos_queue_t */
    /* adjust source (see BCM_COSQ_CONTROL_table)*/
    bcm_cosq_pkt_size_adjust_source_info_t source_info;
} bcm_cosq_pkt_size_adjust_info_t;

/* cosq_pkt_size_adjust_source_info structure */
typedef struct bcm_cosq_pkt_size_adjust_source_info_s {
    bcm_cosq_pkt_size_adjust_source_t source_type; /* compensation source */
    uint32 source_id; /* command id: 0,1 */
} bcm_cosq_pkt_size_adjust_source_info_t;

```

Table 12: Type of a resource allocated.

Types	Description
bcmCosqPktSizeAdjustSourceScheduler	source is Scheduler
bcmCosqPktSizeAdjustSourceCrpsInPP	source is CRPS in PP
bcmCosqPktSizeAdjustSourceCrpsInTM	source is CRPS in TM
bcmCosqPktSizeAdjustSourceStatReportIn	source is Stat Report In
bcmCosqPktSizeAdjustSourceStatReportOut	source is Stat Report Out

Returns

BCM_E_NONE

BCM_E_XXX

bcm_cosq_gport_pkt_size_adjust_get

The purpose of this API is to get the delta value configured for a certain compensation type

Syntax

```

#include <bcm/cosq.h>
int bcm_cosq_gport_pkt_size_adjust_get(
intunit,

```

```
bcm_cosq_pkt_size_adjust_info_tadjust_info,  
int *delta);
```

Parameters

unit	BCM device number
adjust_info (IN)	bcm_cosq_pkt_size_adjust_info structure
delta (OUT)	received delta value

Description

The purpose of this API is to get the delta value configured for a certain compensation type

Returns

```
BCM_E_NONE  
BCM_E_XXX
```

bcm_cosq_pkt_size_adjust_delta_map_set

Scheduler final delta mapping API

Syntax

```
#include <bcm/cosq.h>  
int bcm_cosq_pkt_size_adjust_delta_map_set(  
    int unit,  
    int delta,  
    int final_delta);
```

Parameters

unit	BCM device number
delta (IN)	delta
final_delta (IN)	final delta

Description

Scheduler final delta mapping API

Returns

BCM_E_NONE
BCM_E_XXX

bcm_cosq_pkt_size_adjust_delta_map_get

get the final delta mapping

Syntax

```
#include <bcm/cosq.h>
int bcm_cosq_pkt_size_adjust_delta_map_get(
    int unit,
    int delta,
    int *final_delta);
```

Parameters

unit	BCM device number
delta (IN)	delta
final_delta (OUT)	get the final delta

Description

get the final delta mapping

Returns

BCM_E_NONE
BCM_E_XXX

bcm_cosq_ingress_port_drop_enable_set bcm_cosq_ingress_port_drop_enable_get

set/get enable/disable cosq ingress port drop

Syntax

```
#include <bcm/cosq.h>
int bcm_cosq_ingress_port_drop_enable_set(
    int unit,
    bcm_port_t port,
    uint32 flags,
    int enable);
```

```
int bcm_cosq_ingress_port_drop_enable_get(
```



```
intunit,  
bcm_port_t port,  
uint32 flags,  
int *enable);
```

Parameters

unit	BCM device number
bcm_port_t (IN)	port
flags (IN)	flags
enable (IN) (for	"_set") TRUE to enable, FALSE to disable
enable (OUT) (for	"_get") TRUE to enable, FALSE to disable

Description

enable/disable cosq ingress port drop

Returns

```
BCM_E_NONE  
BCM_E_XXX
```

bcm_cosq_ingress_port_drop_threshold_set **bcm_cosq_ingress_port_drop_threshold_get**

set/get cosq ingress port drop thresholds

Syntax

```
#include <bcm/cosq.h>  
int bcm_cosq_ingress_port_drop_threshold_set(  
intunit,  
bcm_port_t port,  
uint32 flags,  
bcm_color_t color,  
uint32 value);  
  
int bcm_cosq_ingress_port_drop_threshold_get(  
intunit,  
bcm_port_t port,  
uint32 flags,  
bcm_color_t color,  
uint32 *value);
```

Parameters

unit	BCM device number
bcm_port_t (IN)	port
flags (IN)	flags
color (IN)	color
value (IN) (for	"_set") the required value
value (OUT) (for	"_get") the required value

Description

The available flags are Ingress Port Drop Flags ([page 26](#))

Table 13: Ingress Port Drop Flags

Flag
BCM_COSQ_INGRESS_PORT_DROP_FLAGS_THRESHOLD_PRECENT

get/set cosq ingress port drop thresholds

Returns

BCM_E_NONE
BCM_E_XXX

bcm_cosq_ingress_port_drop_map_set
bcm_cosq_ingress_port_drop_map_get

set/get cosq ingress port drop map value

Syntax

```
#include <bcm/cosq.h>
int bcm_cosq_ingress_port_drop_map_set(
    intunit,
    bcm_port_t port,
    uint32 flags,
    bcm_cosq_ingress_port_drop_map_t map,
    uint32 key,
    bcm_color_t color);

int bcm_cosq_ingress_port_drop_map_set(
    intunit,
    bcm_port_t port,
    uint32 flags,
    bcm_cosq_ingress_port_drop_map_t map,
    uint32 key,
```



```
bcm_color_t *color);
```

Parameters

unit	BCM device number
bcm_port_t (IN)	port
flags (IN)	flags
map (IN)	map
key (IN)	key
color (IN) (for	"_set") color
color (OUT) (for	"_get") color

The available flags are Ingress Port Drop Flags ([page 26](#)) The available values for map are:

We may use these macros for the key parameter:

```
#define BCM_COSQ_INGRESS_PORT_DROP_ETH_MAP_KEY(pcp, dei) (((pcp << 1) | dei) & 0xF)
#define BCM_COSQ_INGRESS_PORT_DROP_TM_MAP_KEY(tc, dp) (((tc << 2) | dp) & 0x3F)
```

Description

set/get cosq ingress port drop map value

Returns

```
BCM_E_NONE
BCM_E_XXX
```

FIELD PROCESSOR

New field actions are defined as Field Actions for bcm_field_action_add ([page 27](#)) in this release.

Table 14: Field Actions for bcm_field_action_add

Action	Description	param0	param1
bcmFieldActionStatAndPolicer	Activates both Stat and Policer actions	Stat + Meter Id	n/a
bcmFieldActionSnoopAndTrap	Activates both Snoop and Trap actions	Snoop + Trap GPort	n/a
bcmFieldActionIEEE1588	Setting various parameters for 1588 frames	Packet-is-IEEE-1588(1 Bit); IEEE-1588-Update-Time-Stamp(1 Bit) ; IEEE-1588-Command, (2 Bit) ; IEEE-1588-Encapsulation(1 bits) ; IEEE-1588-Header-Offset(7 bits)	n/a

New field match rules for OAM are shown in the table Match rule value used by OAM CCM Embedded App to indicate MEP type through bcmFieldActionCopyToCpu Action ([page 28](#)) .



Table 15: Match rule value used by OAM CCM Embedded App to indicate MEP type through bcmFieldActionCopyToCpu Action

BCM_FIELD_OAM_MATCHED_RULE_xxx	Description
BCM_FIELD_OAM_MATCHED_RULE_ETHERNET_PORT	Match rule values used by OAM CCM Embedded App to indicate Port MEP type
BCM_FIELD_OAM_MATCHED_RULE_ETHERNET_INNER_VLAN	Match rule values used by OAM CCM Embedded App to indicate Inner vlan MEP type
BCM_FIELD_OAM_MATCHED_RULE_ETHERNET_OUTER_VLAN	Match rule values used by OAM CCM Embedded App to indicate Outer vlan MEP type
BCM_FIELD_OAM_MATCHED_RULE_ETHERNET_INNER_PLUS_OUTER_VLAN	Match rule values used by OAM CCM Embedded App to indicate Inner + Outer vlan MEP type

LAYER 2 ADDRESS MANAGEMENT

A new BCM L2 learning event flag for the new L2 learn distribution is added in this release as shown in L2 Learning events flags ([page 28](#)) .

Table 16: L2 Learning events flags

Name	Purpose
BCM_L2_ADDR_DIST_ACK_EVENT	Acknowledge event

New BCM L2 replace flag BCM_L2_REPLACE_MATCH_AGE is introduced in this release as shown in L2 Replace Flags ([page 28](#)) .bcm_l2_replace

Table 17: L2 Replace Flags

Flags	Description
BCM_L2_REPLACE_MATCH_AGE	L2 replace will be performed on L2 entries of a given age state

New BCM L2 APIs are added as following.

bcm_l2_learn_limit_enable
bcm_l2_learn_limit_disable

Enable/Disable BCM L2 learn limit subsystem.

Syntax

```
#include <bcm/l2.h>
int bcm_l2_learn_limit_enable(int unit);
int bcm_l2_learn_limit_disable(int unit);
```

Parameters

`unit` BCM device number

Description

Enable/Disable BCM L2 learn limit subsystem

Returns

BCM_E_XXX

L2GRE MANAGEMENT

New MPLS port match criteria is as shown in MPLS Port Match Criteria ([page 29](#)) added in this release.

Table 18: MPLS Port Match Criteria

Name	Purpose
BCM_L2GRE_PORT_MATCH_SHARE	Shared logic port

LAYER 3 MANAGEMENT

A new L3 flag for `bcm_l3_egress_create` regarding next hop index and none ECMP overlap.

Table 19: BCM Layer 3 Flags2

Name	Purpose
BCM_L3_FLAGS2_NO_ECMP_OVERLAP	Allocate next hop indexes without overlapping ECMP indexes. This flag is applied to <code>bcm_l3_egress_create</code> only and should not be used together with <code>BCM_L3_WITH_ID</code> .

MAC-IN-MAC MANAGEMENT

A new field `protocol_pkt` of data structure `bcm_mim_vpn_config_t` is added in this release for the MAC-in-MAC VPN attributes.

It allows the application to configure different broadcast, multicast and unknown unicast groups.

```
typedef struct bcm_mim_vpn_config_s {
    ...
    bcm_vlan_protocol_packet_ctrl_t protocol_pkt; /* Protocol packet control
*/
} bcm_mim_vpn_config_t;
```

MIRRORING

New BCM Mirroring flags are added for ingress port untagged/tagged traffic respectively as show in BCM Mirroring Flags ([page 30](#)) .

Table 20: BCM Mirroring Flags

Name	Description
BCM_MIRROR_PORT_UNTAGGED_ONLY	Enable Ingress mirroring for Untagged traffic only
BCM_MIRROR_PORT_TAGGED_DEFAULT	Enable Ingress mirroring for Tagged traffic with unspecified VID

MPLS MANAGEMENT

Two new fields are added in `bcm_mpls_port_t` data structure in this release.

```
typedef struct bcm_mpls_port_s {
    ...
    bcm_failover_t ingress_failover_id;          /* Ingress Failover Object
Identifier. */
    bcm_gport_t ingress_failover_port_id;        /* Ingress Failover MPLS
Port Identifier. */
    ...
} bcm_mpls_port_t;
```

OPERATIONS, ADMINISTRATION, AND MAINTENANCE

A new OAM event type is introduced in this release in OAM Event Types ([page 30](#)) .

Table 21: OAM Event Types

Event type	Description
bcmOAMEventBHHCCMTimeoutClear	Timeout has been cleared on BHH CCM endpoint

New OAM control formats are added in this release as shown in OAM Control Formats ([page 30](#)) .

Table 22: OAM Control Formats

Control Format Type	Description
bcmOamControlSrcMacLsbReserve	Reserve Src-Mac LSB value to be used for OAM endpoints (resource shared with BFD endpoints)
bcmOamControlSrcMacLsbUnReserve	Unreserve Src-Mac LSB value (resource shared with BFD endpoints)
bcmOamControlLmPcpCounterRangeMax	<code>lm_counter_base_ids</code> between Max and Min will count by priority
bcmOamControlLmPcpCounterRangeMin	<code>lm_counter_base_ids</code> between Max and Min will count by priority
bcmOamControlOampPuntPacketIntPri	Bits [1:0] of given value determine the color (DP), bits [4:2] determine the Traffic Class
bcmOamControlOampCCMWeight	Given may be between 0 and 6
bcmOamControlOampSATWeight	Given may be between 0 and 6

Table 22: OAM Control Formats

Control Format Type	Description
bcmOamControlOampResponseWeight	Given may be between 0 and 6

New fields have been added in the `bcm_oam_endpoint_info_t` data structure for OAM endpoint sessions.

```
typedef struct bcm_oam_endpoint_info_s {
    ...
    uint32 session_id;           /* OAM session id for packet processing
                                in BTE. In FP based OAM - This will
                                indicate flex counter base ID */
    uint8 session_num_entries;   /* Number of entries that can result in
                                same session ID. In FP based OAM -
                                This will indicate number of flex
                                counter entries corresponding to same
                                OAM session */
} bcm_oam_endpoint_info_t;
```

Two new fields are added in `bcm_oam_ais_t` data structure for OAM AIS (alarm indication signal) objects.

```
/* OAM AIS (alarm indication signal) object. */
typedef struct bcm_oam_ais_s {
    ...
    uint8 pkt_pri;              /* Egress marking for outgoing AIS
messages. */
    uint8 drop_eligible;        /* Drop Eligibility for AIS. */
} bcm_oam_ais_t;
```

POLICER

A new policer flag as shown in Policer Flags ([page 31](#)) is introduced with regarding to header truncate adjustment.

Table 23: Policer Flags

Name	Purpose
BCM_POLICER_PKT_ADJ_HEADER_TRUNCATE	Indicates that this Policer needs to be considerate of header truncate adjustment.

The new variables `actual_ckbits_sec`, `actual_ckbits_burst`, `actual_pkbits_sec`, `actual_pkbits_burst` in data structure `bcm_policer_config_t` represent actual hardware values configured based on granularity for the given packet rates. These are read-only and will be updated only after field entry install.

```
typedef struct bcm_policer_config_s {
    ...
    /* Granularity adjusted committed rate in kbps or packets per second. */
    uint32 actual_ckbits_sec;
    /* Granularity adjusted committed burst size in kbits or number of
packets. */
```

```
uint32 actual_ckbits_burst;
/* Granularity adjusted peak rate in kbps or packets per second. */
uint32 actual_pkbits_sec;
/* Granularity adjusted peak burst size in kbits or number of packets. */
uint32 actual_pkbits_burst;
} bcm_policer_config_t;
```

New BCM Policer API is introduced in this release.

bcm_policer_group_mode_attr_selector_t_init

Initialize a policer group attribute selector structure.

Syntax

```
#include <bcm/policer.h>
void bcm_policer_group_mode_attr_selector_t_init(
    bcm_policer_group_mode_attr_selector_t *pol_group_mode_attr_selector)
```

Parameters

pol_group_mode_attr Pointer to policer group attribute selector structure to initialize.
_selector

Description

Initialize a policer group attribute selector structure.

Returns

None.

PORT CONFIGURATION

Table 24: New bcm_port_phy_control_t

Control Type	Description
BCM_PORT_PHY_CONTROL_FORWARD_ERROR_CORRECTION_CL91	FEC CL91 on/off on PM 4x25 portmacro
BCM_PORT_PHY_CONTROL_SHORT_CHANNEL_MODE_STATUS	Get the configured status of short channel mode on a port

PRECISION TIME PROTOCOL

New BCM_PTP_SERVO_PHASE_HOLD OVER bit flag is added in this release in addition to the bit flags as shown in Bits in servo configuration flags. (page 33) .



Table 25: Bits in servo configuration flags.

Bit flags	Description
BCM_PTP_SERVO_PHASE_ONLY	Phase-only bit.
BCM_PTP_SERVO_LOCK_SWITCH_FREQ	Switch-frequency lock bit.
BCM_PTP_SERVO_IGNORE_FREQ	Ignore-frequency bit.
BCM_PTP_SERVO_PHASE_HOLDOVER	Servo phase holdover bit.

RATE LIMITING

BCM_RATE_PKT_ADJ_HEADER_TRUNCATE rate limit flag is added in Rate Control Flags ([page 33](#)) that lists the flags for the rate-limiting functions.

Table 26: Rate Control Flags

Name	Purpose
BCM_RATE_PKT_ADJ_HEADER_TRUNCATE	Indicates that this Eth. Policer needs to be considerate of header truncate adjustment

SWITCH CONTROL

New field `pkt_trace_drop_reason` is added in `bcm_switch_pkt_trace_info_t` data structure with the `BCM_SWITCH_PKT_TRACE_DROP_REASON_MAX=4` in this release. The detailed drop reasons are listed in `bcm_switch_pkt_trace_drop_reason_t`.

```
typedef struct bcm_switch_pkt_trace_info_s {
    ...
    uint32 pkt_trace_drop_reason[BCM_SWITCH_PKT_TRACE_DROP_REASON_MAX];
    ...
} bcm_switch_pkt_trace_info_t;

typedef enum bcm_switch_pkt_trace_drop_reason_e {
    bcmSwitchPktTraceNoDrop = 0,
    bcmSwitchPktTraceDropReasonInternal = 1,
    bcmSwitchPktTraceDropReasonMplsLabelLookupMiss = 2,
    bcmSwitchPktTraceDropReasonMplsInvalidAction = 3,
    bcmSwitchPktTraceDropReasonMplsInvalidPayload = 4,
    bcmSwitchPktTraceDropReasonMplsTtlCheckFail = 5,
    bcmSwitchPktTraceDropReasonMplsInvalidControlWord = 6,
    bcmSwitchPktTraceDropReasonL2greSipLookupMiss = 7,
    bcmSwitchPktTraceDropReasonL2greVpnLookupMiss = 8,
    bcmSwitchPktTraceDropReasonL2greTunnelError = 9,
    bcmSwitchPktTraceDropReasonVxlanSipLookupMiss = 10,
    bcmSwitchPktTraceDropReasonVxlanVnidLookupMiss = 11,
    bcmSwitchPktTraceDropReasonVxlanTunnelError = 12,
    bcmSwitchPktTraceDropReasonVlanNotValid = 13,
    bcmSwitchPktTraceDropReasonIngressPortNotInVlanMember = 14,
    bcmSwitchPktTraceDropReasonTpidMismatch = 15,
    bcmSwitchPktTraceDropReasonIpv4ProtocolError = 16,
```

```
bcmSwitchPktTraceDropReasonHigigLoopback = 17,  
bcmSwitchPktTraceDropReasonHigigMirrorOnly = 18,  
bcmSwitchPktTraceDropReasonHigigUnknownHeader = 19,  
bcmSwitchPktTraceDropReasonHigigUnknownOpcode = 20,  
bcmSwitchPktTraceDropReasonLagFailLoopback = 21,  
bcmSwitchPktTraceDropReasonL2SrcEqualL2Dst = 22,  
bcmSwitchPktTraceDropReasonIpv6ProtocolError = 23,  
bcmSwitchPktTraceDropReasonNivVntagPresent = 24,  
bcmSwitchPktTraceDropReasonNivVntagNotPresent = 25,  
bcmSwitchPktTraceDropReasonNivVntagFormat = 26,  
bcmSwitchPktTraceDropReasonTrillErrorFrame = 27,  
bcmSwitchPktTraceDropReasonBpdu = 28,  
bcmSwitchPktTraceDropReasonBadUdpChecksum = 29,  
bcmSwitchPktTraceDropReasonTunnlDecapEcnError = 30,  
bcmSwitchPktTraceDropReasonIpv4HeaderError = 31,  
bcmSwitchPktTraceDropReasonIpv6HeaderError = 32,  
bcmSwitchPktTraceDropReasonParityError = 33,  
bcmSwitchPktTraceDropReasonRpfCheckFail = 34,  
bcmSwitchPktTraceDropReasonCount = 35  
} bcm_switch_pkt_trace_drop_reason_t;
```

Section 7: Test Statistics

HOW TO READ THE DATA

The tables below represent a spread of data gathered per-device, per-suite, per-release. The percentages represent the aggregate rate of failure for that suite when run against all variants of the family of devices.

OVERVIEW

Each suite listed below is indicative of a specific module. Golden refers to a suite of tests that takes representation across multiple modules and serves as a sanity regression. Each suite contains tests of various types, loosely categorized as shown in *Suite Test Types* ([page 35](#))

Table 27: Suite Test Types

Test Categories	Description
Configuration Tests	Tests that verify that each API functions appropriately and can configure the device as expected.
Functionality Tests	Tests that further validate each of the API through functional use often requiring traffic to be run through the system.
Semantic Tests	Tests that ensure that the proper error handling mechanisms are working and users cannot crash the device through the API.

LINUX KERNEL VERSIONS USED IN THIS RELEASE

In SDK 6.4.x, the following Linux kernel versions were used in our development and regression cycles with these main CPUs:

- BCM9XLP208XMC (WRX): 3.10.59
- BCM958625XMC (RSX): 3.6.5
- BCM98548PPCXMC (GTO): 2.6.21.7
- BCM98548PPCXMC (X86): 3.14

Please refer to the Broadcom Network Switching Software Platform Guide for more details about these CPUs.

TOTAL TESTS

The below data in *Tests per Module* ([page 36](#)) represents the number of unique cases for each release.

Note that although a particular test case will execute for each and every chip, it's only counted once.

Table 28: Tests per Module

	sdk-6.4.11	sdk-6.4.10	sdk-6.4.9
golden	153	153	153
warmboot	950	902	864
auth	17	17	17
bfd	37	37	37
bhh	45	45	45
chip	9	9	9
cint	73	73	69
coe	568	568	568
cosq	532	532	514
custom	7	7	7
ea	108	108	108
eav	19	19	19
extender	49	49	45
fabric	7	7	7
failover	8	8	8
fcoe	37	37	37
field	1311	1307	1307
higigproxy	129	129	129
infra	114	114	114
ipfix	17	17	17
ipmc	119	119	116
l2	331	331	330
l2gre	13	13	13
l3	481	481	473
l3.alpm	456	456	440
link	26	26	26
mim	28	28	19
mirror	171	171	171
misc	20	20	20
mpls	374	374	363
multicast	25	25	25
niv	65	64	58
oam	284	272	271
pkt	44	44	44
port	367	366	361
proxy	37	37	37
ptp	115	115	115
qos	13	13	13
rate	21	21	21
rtag7	43	43	42
rx	25	25	25
ser	157	157	157
stack	117	117	117
stat	332	332	326
stg	42	42	42
switch	197	197	197
time	33	33	33
tlvMsg	13	13	13

Table 28: Tests per Module

	sdk-6.4.11	sdk-6.4.10	sdk-6.4.9
trill	40	40	40
trunk	223	223	219
tunnel	133	133	123
subport	31	31	31
vlan	228	228	228
vxlan	186	184	174
wlan	17	17	17
Test Suite Total	8997	8929	8774

API TEST RESULTS

The tables below show percentages of failures for corresponding test suites per SDK release.

ALL DEVICES

Note: This section represents aggregate results for all devices in the release.

Table 29:

	sdk-6.4.11	sdk-6.4.10	sdk-6.4.9
golden	0.1 %	0.2 %	0.1 %
warmboot	0.1 %	0.2 %	0.3 %
bcm.auth	0.0 %	0.0 %	0.0 %
bcm.bfd	0.0 %	0.0 %	0.0 %
bcm.bhh	0.0 %	0.0 %	0.0 %
bcm.chip	0.0 %	0.0 %	0.0 %
bcm.cint	0.0 %	0.0 %	0.0 %
bcm.coe	0.1 %	0.0 %	0.2 %
bcm.cosq	0.1 %	0.1 %	0.2 %
bcm.custom	0.0 %	0.0 %	0.0 %
bcm.ea	0.0 %	0.0 %	0.0 %
bcm.eav	0.0 %	0.0 %	0.0 %
bcm.extender	0.0 %	0.0 %	0.0 %
bcm.fabric	0.0 %	0.0 %	0.0 %
bcm.failover	0.0 %	0.0 %	0.0 %
bcm.fcoe	0.0 %	0.0 %	0.0 %
bcm.field	0.2 %	0.2 %	0.3 %
bcm.higigproxy	0.0 %	0.0 %	0.0 %
bcm.infra	0.0 %	0.0 %	0.0 %
bcm.ipfix	0.1 %	0.1 %	0.2 %
bcm.ipmc	0.1 %	0.1 %	0.1 %
bcm.l2	0.1 %	0.1 %	0.2 %
bcm.l2gre	0.0 %	0.0 %	0.0 %
bcm.l3	0.1 %	0.1 %	0.1 %
bcm.l3.alpm	0.0 %	0.1 %	0.1 %
bcm.link	0.0 %	0.0 %	0.0 %
bcm.mim	0.0 %	0.0 %	0.0 %
bcm.mirror	0.3 %	0.3 %	0.2 %

Table 29:

	sdk-6.4.11	sdk-6.4.10	sdk-6.4.9
bcm.misc	0.0 %	0.0 %	0.1 %
bcm.mpls	0.0 %	0.0 %	0.1 %
bcm.multicast	0.0 %	0.0 %	0.0 %
bcm.niv	0.0 %	0.0 %	0.0 %
bcm.oam	0.0 %	0.2 %	0.0 %
bcm.pkt	0.0 %	0.0 %	0.0 %
bcm.port	0.4 %	0.5 %	0.6 %
bcm.proxy	0.0 %	0.0 %	0.0 %
bcm.ptp	0.0 %	0.0 %	0.0 %
bcm.qos	0.0 %	0.0 %	0.0 %
bcm.rate	0.0 %	0.1 %	0.0 %
bcm.rtag7	0.0 %	0.1 %	0.2 %
bcm.rx	0.0 %	0.0 %	0.0 %
bcm.ser	0.0 %	0.1 %	0.1 %
bcm.stack	0.0 %	0.0 %	0.0 %
bcm.stat	0.2 %	0.2 %	0.1 %
bcm.stg	0.0 %	0.1 %	0.0 %
bcm.switch	0.0 %	0.1 %	0.1 %
bcm.time	0.0 %	0.0 %	0.0 %
bcm.tlvMsg	0.0 %	0.0 %	0.0 %
bcm.trill	0.0 %	0.0 %	0.0 %
bcm.trunk	0.0 %	0.0 %	0.0 %
bcm.tunnel	0.0 %	0.0 %	0.0 %
bcm.subport	0.0 %	0.0 %	0.0 %
bcm.vlan	0.0 %	0.0 %	0.0 %
bcm.vxlan	0.0 %	0.0 %	0.0 %
bcm.wlan	0.0 %	0.0 %	0.0 %
Test Suite Total	0.1 %	0.2 %	0.2 %

TRIDENT2

Table 30:

	sdk-6.4.11	sdk-6.4.10	sdk-6.4.9
golden	0.0 %	0.0 %	0.0 %
warmboot	0.0 %	0.1 %	0.1 %
bcm.auth	0.0 %	0.0 %	0.0 %
bcm.bfd	0.0 %	0.0 %	0.0 %
bcm.chip	0.0 %	0.0 %	0.0 %
bcm.cint	0.0 %	0.0 %	0.0 %
bcm.cosq	0.0 %	0.0 %	0.0 %
bcm.custom	0.0 %	0.0 %	0.0 %
bcm.ea	0.0 %	0.0 %	0.0 %
bcm.eav	0.0 %	0.0 %	0.0 %
bcm.extender	0.0 %	0.0 %	0.0 %
bcm.fabric	0.0 %	0.0 %	0.0 %
bcm.failover	0.0 %	0.0 %	0.0 %
bcm.fcoe	0.0 %	0.0 %	0.0 %

Table 30:

	sdk-6.4.11	sdk-6.4.10	sdk-6.4.9
bcm.field	0.1 %	0.1 %	0.1 %
bcm.higigproxy	0.0 %	0.0 %	0.0 %
bcm.infra	0.0 %	0.0 %	0.0 %
bcm.ipfix	0.0 %	0.0 %	0.0 %
bcm.ipmc	0.0 %	0.0 %	0.0 %
bcm.l2	0.0 %	0.1 %	0.1 %
bcm.l2gre	0.0 %	0.0 %	0.0 %
bcm.l3	0.0 %	0.0 %	0.0 %
bcm.l3.alpm	0.0 %	0.0 %	0.0 %
bcm.link	0.0 %	0.0 %	0.0 %
bcm.mim	0.0 %	0.0 %	0.0 %
bcm.mirror	0.0 %	0.0 %	0.0 %
bcm.misc	0.0 %	0.0 %	0.0 %
bcm.mpls	0.0 %	0.0 %	0.0 %
bcm.multicast	0.0 %	0.0 %	0.0 %
bcm.niv	0.0 %	0.0 %	0.0 %
bcm.oam	0.0 %	0.0 %	0.0 %
bcm.pkt	0.0 %	0.0 %	0.0 %
bcm.port	0.0 %	0.0 %	0.0 %
bcm.proxy	0.0 %	0.0 %	0.0 %
bcm.ptp	0.0 %	0.0 %	0.0 %
bcm.qos	0.0 %	0.0 %	0.0 %
bcm.rate	0.0 %	0.0 %	0.0 %
bcm.rtag7	0.0 %	0.0 %	0.0 %
bcm.rx	0.0 %	0.0 %	0.0 %
bcm.ser	0.0 %	0.0 %	0.0 %
bcm.stack	0.0 %	0.0 %	0.0 %
bcm.stat	0.2 %	0.0 %	0.0 %
bcm.stg	0.0 %	0.0 %	0.0 %
bcm.switch	0.0 %	0.0 %	0.0 %
bcm.time	0.0 %	0.0 %	0.0 %
bcm.tlvMsg	0.0 %	0.0 %	0.0 %
bcm.trill	0.0 %	0.0 %	0.0 %
bcm.trunk	0.0 %	0.0 %	0.0 %
bcm.tunnel	0.0 %	0.0 %	0.0 %
bcm.subport	0.0 %	0.0 %	0.0 %
bcm.vlan	0.0 %	0.0 %	0.0 %
bcm.vxlan	0.0 %	0.0 %	0.0 %
bcm.wlan	0.0 %	0.0 %	0.0 %
Test Suite Total	0.0 %	0.1 %	0.1 %

TRIUMPH3

Table 31:

	sdk-6.4.11	sdk-6.4.10	sdk-6.4.9
golden	0.1 %	0.1 %	0.1 %
warmboot	0.0 %	0.0 %	0.0 %

Table 31:

	sdk-6.4.11	sdk-6.4.10	sdk-6.4.9
bcm.auth	0.0 %	0.0 %	0.0 %
bcm.bfd	0.0 %	0.0 %	0.0 %
bcm.bhh	0.0 %	0.0 %	0.0 %
bcm.chip	0.0 %	0.0 %	0.0 %
bcm.cint	0.0 %	0.0 %	0.0 %
bcm.cosq	0.0 %	0.0 %	0.0 %
bcm.custom	0.0 %	0.0 %	0.0 %
bcm.ea	0.0 %	0.0 %	0.0 %
bcm.eav	0.0 %	0.0 %	0.0 %
bcm.extender	0.0 %	0.0 %	0.0 %
bcm.fabric	0.0 %	0.0 %	0.0 %
bcm.failover	0.0 %	0.0 %	0.0 %
bcm.fcoe	0.0 %	0.0 %	0.0 %
bcm.field	0.1 %	0.1 %	0.1 %
bcm.higigproxy	0.0 %	0.0 %	0.0 %
bcm.infra	0.0 %	0.0 %	0.0 %
bcm.ipfix	0.0 %	0.0 %	0.0 %
bcm.ipmc	0.0 %	0.0 %	0.0 %
bcm.l2	0.0 %	0.0 %	0.0 %
bcm.l2gre	0.0 %	0.0 %	0.0 %
bcm.l3	0.1 %	0.1 %	0.1 %
bcm.link	0.0 %	0.0 %	0.0 %
bcm.mim	0.0 %	0.0 %	0.0 %
bcm.mirror	0.0 %	0.0 %	0.0 %
bcm.misc	0.0 %	0.0 %	0.0 %
bcm.mpls	0.0 %	0.0 %	0.0 %
bcm.multicast	0.0 %	0.0 %	0.0 %
bcm.niv	0.0 %	0.0 %	0.0 %
bcm.oam	0.0 %	0.1 %	0.0 %
bcm.pkt	0.0 %	0.0 %	0.0 %
bcm.port	1.0 %	1.0 %	1.3 %
bcm.proxy	0.0 %	0.0 %	0.0 %
bcm.ptp	0.0 %	0.0 %	0.0 %
bcm.qos	0.0 %	0.0 %	0.0 %
bcm.rate	0.0 %	0.0 %	0.0 %
bcm.rtag7	0.0 %	0.0 %	0.0 %
bcm.rx	0.0 %	0.0 %	0.0 %
bcm.ser	0.0 %	0.0 %	0.0 %
bcm.stack	0.0 %	0.0 %	0.0 %
bcm.stat	0.0 %	0.0 %	0.0 %
bcm.stg	0.0 %	0.0 %	0.0 %
bcm.switch	0.0 %	0.0 %	0.0 %
bcm.time	0.0 %	0.0 %	0.0 %
bcm.tlvMsg	0.0 %	0.0 %	0.0 %
bcm.trill	0.0 %	0.0 %	0.0 %
bcm.trunk	0.0 %	0.0 %	0.0 %
bcm.tunnel	0.0 %	0.0 %	0.0 %
bcm.subport	0.0 %	0.0 %	0.0 %
bcm.vlan	0.0 %	0.0 %	0.0 %
bcm.vxlan	0.0 %	0.0 %	0.0 %
bcm.wlan	0.0 %	0.0 %	0.0 %

Table 31:

	sdk-6.4.11	sdk-6.4.10	sdk-6.4.9
Test Suite Total	0.1 %	0.2 %	0.2 %

KATANA2

Table 32:

	sdk-6.4.11	sdk-6.4.10	sdk-6.4.9
golden	0.1 %	0.1 %	0.0 %
warmboot	0.1 %	0.1 %	0.1 %
bcm.auth	0.0 %	0.0 %	0.0 %
bcm.bfd	0.0 %	0.0 %	0.0 %
bcm.bhh	0.0 %	0.0 %	0.0 %
bcm.chip	0.0 %	0.0 %	0.0 %
bcm.cint	0.0 %	0.0 %	0.0 %
bcm.coe	0.1 %	0.1 %	0.1 %
bcm.cosq	0.0 %	0.0 %	0.0 %
bcm.custom	0.0 %	0.0 %	0.0 %
bcm.ea	0.0 %	0.0 %	0.0 %
bcm.eav	0.0 %	0.0 %	0.0 %
bcm.extender	0.0 %	0.0 %	0.0 %
bcm.fabric	0.0 %	0.0 %	0.0 %
bcm.failover	0.0 %	0.0 %	0.0 %
bcm.fcoe	0.0 %	0.0 %	0.0 %
bcm.field	0.2 %	0.2 %	0.3 %
bcm.higigproxy	0.0 %	0.0 %	0.0 %
bcm.infra	0.0 %	0.0 %	0.0 %
bcm.ipfix	0.0 %	0.0 %	0.0 %
bcm.ipmc	0.0 %	0.0 %	0.0 %
bcm.l2	0.0 %	0.0 %	0.0 %
bcm.l2gre	0.0 %	0.0 %	0.0 %
bcm.l3	0.0 %	0.0 %	0.0 %
bcm.link	0.0 %	0.0 %	0.0 %
bcm.mim	0.0 %	0.0 %	0.0 %
bcm.mirror	0.0 %	0.0 %	0.0 %
bcm.misc	0.0 %	0.0 %	0.0 %
bcm.mpls	0.0 %	0.0 %	0.0 %
bcm.multicast	0.0 %	0.0 %	0.0 %
bcm.niv	0.0 %	0.0 %	0.0 %
bcm.oam	0.0 %	0.0 %	0.0 %
bcm.pkt	0.0 %	0.0 %	0.0 %
bcm.port	0.4 %	0.6 %	0.8 %
bcm.proxy	0.0 %	0.0 %	0.0 %
bcm.ptp	0.0 %	0.0 %	0.0 %
bcm.qos	0.0 %	0.0 %	0.0 %
bcm.rate	0.0 %	0.0 %	0.0 %
bcm.rtag7	0.0 %	0.0 %	0.0 %
bcm.rx	0.0 %	0.0 %	0.0 %
bcm.ser	0.0 %	0.0 %	0.0 %

Table 32:

	sdk-6.4.11	sdk-6.4.10	sdk-6.4.9
bcm.stack	0.0 %	0.0 %	0.0 %
bcm.stat	0.1 %	0.0 %	0.0 %
bcm.stg	0.0 %	0.0 %	0.0 %
bcm.switch	0.0 %	0.0 %	0.0 %
bcm.time	0.0 %	0.0 %	0.0 %
bcm.tlvMsg	0.0 %	0.0 %	0.0 %
bcm.trill	0.0 %	0.0 %	0.0 %
bcm.trunk	0.0 %	0.0 %	0.0 %
bcm.tunnel	0.0 %	0.0 %	0.0 %
bcm.subport	0.0 %	0.0 %	0.0 %
bcm.vlan	0.0 %	0.0 %	0.0 %
bcm.vxlan	0.0 %	0.0 %	0.0 %
bcm.wlan	0.0 %	0.0 %	0.0 %
Test Suite Total	0.1 %	0.2 %	0.2 %

GREYHOUND

Table 33:

	sdk-6.4.11	sdk-6.4.10	sdk-6.4.9
golden	0.0 %	0.0 %	0.0 %
warmboot	0.1 %	0.2 %	0.5 %
bcm.auth	0.0 %	0.0 %	0.0 %
bcm.chip	0.0 %	0.0 %	0.0 %
bcm.cint	0.0 %	0.0 %	0.0 %
bcm.coe	0.0 %	0.0 %	0.0 %
bcm.cosq	0.0 %	0.0 %	0.0 %
bcm.custom	0.0 %	0.0 %	0.0 %
bcm.ea	0.0 %	0.0 %	0.0 %
bcm.eav	0.0 %	0.0 %	0.0 %
bcm.extender	0.0 %	0.0 %	0.0 %
bcm.fabric	0.0 %	0.0 %	0.0 %
bcm.failover	0.0 %	0.0 %	0.0 %
bcm.fcoe	0.0 %	0.0 %	0.0 %
bcm.field	0.0 %	0.0 %	0.1 %
bcm.higigproxy	0.0 %	0.0 %	0.0 %
bcm.infra	0.0 %	0.0 %	0.0 %
bcm.ipfix	0.0 %	0.0 %	0.0 %
bcm.ipmc	0.0 %	0.0 %	0.0 %
bcm.l2	0.0 %	0.0 %	0.0 %
bcm.l2gre	0.0 %	0.0 %	0.0 %
bcm.l3	0.0 %	0.0 %	0.0 %
bcm.link	0.0 %	0.0 %	0.0 %
bcm.mim	0.0 %	0.0 %	0.0 %
bcm.mirror	0.3 %	0.0 %	0.0 %
bcm.misc	0.0 %	0.0 %	0.0 %
bcm.mpls	0.0 %	0.0 %	0.0 %
bcm.multicast	0.0 %	0.0 %	0.0 %

Table 33:

	sdk-6.4.11	sdk-6.4.10	sdk-6.4.9
bcm.niv	0.0 %	0.0 %	0.0 %
bcm.oam	0.0 %	0.0 %	0.0 %
bcm.pkt	0.0 %	0.0 %	0.0 %
bcm.port	0.6 %	0.4 %	0.4 %
bcm.proxy	0.0 %	0.0 %	0.0 %
bcm.ptp	0.0 %	0.0 %	0.0 %
bcm.qos	0.0 %	0.0 %	0.0 %
bcm.rate	0.0 %	0.0 %	0.0 %
bcm.rtag7	0.0 %	0.0 %	0.0 %
bcm.rx	0.0 %	0.0 %	0.0 %
bcm.ser	0.0 %	0.0 %	0.0 %
bcm.stack	0.0 %	0.0 %	0.0 %
bcm.stat	0.0 %	0.0 %	0.0 %
bcm.stg	0.0 %	0.0 %	0.0 %
bcm.switch	0.0 %	0.0 %	0.0 %
bcm.time	0.0 %	0.0 %	0.0 %
bcm.tlvMsg	0.0 %	0.0 %	0.0 %
bcm.trill	0.0 %	0.0 %	0.0 %
bcm.trunk	0.0 %	0.0 %	0.0 %
bcm.tunnel	0.0 %	0.0 %	0.0 %
bcm.subport	0.0 %	0.0 %	0.0 %
bcm.vlan	0.0 %	0.0 %	0.0 %
bcm.vxlan	0.0 %	0.0 %	0.0 %
bcm.wlan	0.0 %	0.0 %	0.0 %
Test Suite Total	0.1 %	0.2 %	0.1 %

TOMAHAWK

Table 34:

	sdk-6.4.11	sdk-6.4.10	sdk-6.4.9
golden	0.0 %	0.0 %	0.1 %
warmboot	0.1 %	0.1 %	0.1 %
bcm.auth	0.0 %	0.0 %	0.0 %
bcm.bfd	0.0 %	0.0 %	0.0 %
bcm.chip	0.0 %	0.0 %	0.0 %
bcm.cint	0.0 %	0.0 %	0.0 %
bcm.coe	0.0 %	0.0 %	0.0 %
bcm.cosq	0.2 %	0.2 %	0.2 %
bcm.custom	0.0 %	0.0 %	0.0 %
bcm.ea	0.0 %	0.0 %	0.0 %
bcm.eav	0.0 %	0.0 %	0.0 %
bcm.extender	0.0 %	0.0 %	0.0 %
bcm.fabric	0.0 %	0.0 %	0.0 %
bcm.failover	0.0 %	0.0 %	0.0 %
bcm.fcoe	0.0 %	0.0 %	0.0 %
bcm.field	0.7 %	0.7 %	0.5 %
bcm.higigproxy	0.0 %	0.0 %	0.0 %

Table 34:

	sdk-6.4.11	sdk-6.4.10	sdk-6.4.9
bcm.infra	0.0 %	0.0 %	0.0 %
bcm.ipfix	0.0 %	0.0 %	0.0 %
bcm.ipmc	0.0 %	0.1 %	0.2 %
bcm.l2	0.0 %	0.1 %	0.1 %
bcm.l2gre	0.0 %	0.0 %	0.0 %
bcm.l3	0.0 %	0.0 %	0.0 %
bcm.l3.alpm	0.0 %	0.0 %	0.0 %
bcm.link	0.0 %	0.0 %	0.0 %
bcm.mim	0.0 %	0.0 %	0.0 %
bcm.mirror	0.0 %	0.0 %	0.0 %
bcm.misc	0.0 %	0.0 %	0.0 %
bcm.mpls	0.0 %	0.0 %	0.0 %
bcm.multicast	0.0 %	0.0 %	0.0 %
bcm.niv	0.0 %	0.0 %	0.0 %
bcm.oam	0.0 %	0.0 %	0.0 %
bcm.pkt	0.0 %	0.0 %	0.0 %
bcm.port	0.0 %	0.1 %	0.1 %
bcm.proxy	0.0 %	0.0 %	0.0 %
bcm.ptp	0.0 %	0.0 %	0.0 %
bcm.qos	0.0 %	0.0 %	0.0 %
bcm.rate	0.0 %	0.0 %	0.0 %
bcm.rtag7	0.0 %	0.0 %	0.0 %
bcm.rx	0.0 %	0.0 %	0.0 %
bcm.ser	0.0 %	0.0 %	0.0 %
bcm.stack	0.0 %	0.0 %	0.0 %
bcm.stat	0.1 %	0.1 %	0.1 %
bcm.stg	0.0 %	0.0 %	0.0 %
bcm.switch	0.0 %	0.0 %	0.0 %
bcm.time	0.0 %	0.0 %	0.0 %
bcm.tlvMsg	0.0 %	0.0 %	0.0 %
bcm.trill	0.0 %	0.0 %	0.0 %
bcm.trunk	0.0 %	0.0 %	0.0 %
bcm.tunnel	0.0 %	0.0 %	0.0 %
bcm.subport	0.0 %	0.0 %	0.0 %
bcm.vlan	0.0 %	0.0 %	0.0 %
bcm.vxlan	0.0 %	0.0 %	0.0 %
bcm.wlan	0.0 %	0.0 %	0.0 %
Test Suite Total	0.2 %	0.2 %	0.2 %

TRIDENT2+

Table 35:

	sdk-6.4.11	sdk-6.4.10	sdk-6.4.9
golden	0.0 %	0.0 %	0.0 %
warmboot	0.0 %	0.2 %	0.3 %
bcm.auth	0.0 %	0.0 %	0.0 %
bcm.chip	0.0 %	0.0 %	0.0 %



Table 35:

	sdk-6.4.11	sdk-6.4.10	sdk-6.4.9
bcm.coe	0.0 %	0.0 %	0.1 %
bcm.cosq	0.0 %	0.1 %	0.3 %
bcm.custom	0.0 %	0.0 %	0.0 %
bcm.eav	0.0 %	0.0 %	0.0 %
bcm.extender	0.0 %	0.0 %	0.0 %
bcm.fabric	0.0 %	0.0 %	0.0 %
bcm.failover	0.0 %	0.0 %	0.0 %
bcm.fcoe	0.0 %	0.0 %	0.0 %
bcm.field	0.0 %	0.1 %	0.1 %
bcm.higigproxy	0.0 %	0.0 %	0.0 %
bcm.ipfix	0.0 %	0.0 %	0.0 %
bcm.ipmc	0.0 %	0.0 %	0.2 %
bcm.l2	0.0 %	0.0 %	0.0 %
bcm.l2gre	0.0 %	0.0 %	0.0 %
bcm.l3	0.0 %	0.0 %	0.0 %
bcm.l3.alpm	0.0 %	0.0 %	0.0 %
bcm.link	0.0 %	0.0 %	0.0 %
bcm.mim	0.0 %	0.0 %	0.0 %
bcm.mirror	0.0 %	0.0 %	0.0 %
bcm.misc	0.0 %	0.0 %	0.0 %
bcm.mpls	0.0 %	0.0 %	0.0 %
bcm.multicast	0.0 %	0.0 %	0.0 %
bcm.niv	0.0 %	0.0 %	0.0 %
bcm.oam	0.0 %	0.0 %	0.0 %
bcm.pkt	0.0 %	0.0 %	0.0 %
bcm.port	0.0 %	0.0 %	0.0 %
bcm.proxy	0.0 %	0.0 %	0.0 %
bcm.ptp	0.0 %	0.0 %	0.0 %
bcm.qos	0.0 %	0.0 %	0.0 %
bcm.rate	0.0 %	0.0 %	0.0 %
bcm.rtag7	0.0 %	0.0 %	0.0 %
bcm.rx	0.0 %	0.0 %	0.0 %
bcm.ser	0.0 %	0.0 %	0.0 %
bcm.stack	0.0 %	0.0 %	0.0 %
bcm.stat	0.1 %	0.1 %	0.1 %
bcm.stg	0.0 %	0.0 %	0.0 %
bcm.switch	0.0 %	0.0 %	0.0 %
bcm.time	0.0 %	0.0 %	0.0 %
bcm.trill	0.0 %	0.0 %	0.0 %
bcm.trunk	0.1 %	0.1 %	0.0 %
bcm.tunnel	0.0 %	0.0 %	0.0 %
bcm.subport	0.0 %	0.0 %	0.0 %
bcm.vlan	0.0 %	0.0 %	0.0 %
bcm.vxlan	0.0 %	0.1 %	0.1 %
bcm.wlan	0.0 %	0.0 %	0.0 %
Test Suite Total	0.0 %	0.2 %	0.2 %

SABER2

Table 36:

	sdk-6.4.11	sdk-6.4.10	sdk-6.4.9
golden	0.1 %	0.1 %	0.1 %
warmboot	0.1 %	0.1 %	0.3 %
bcm.auth	0.0 %	0.0 %	0.0 %
bcm.chip	0.0 %	0.0 %	0.0 %
bcm.coe	0.1 %	0.1 %	0.2 %
bcm.cosq	0.1 %	0.0 %	0.0 %
bcm.custom	0.0 %	0.0 %	0.0 %
bcm.eav	0.0 %	0.0 %	0.0 %
bcm.extender	0.0 %	0.0 %	0.0 %
bcm.fabric	0.0 %	0.0 %	0.0 %
bcm.failover	0.0 %	0.0 %	0.0 %
bcm.fcoe	0.0 %	0.0 %	0.0 %
bcm.field	0.1 %	0.3 %	0.3 %
bcm.higigproxy	0.0 %	0.0 %	0.0 %
bcm.ipfix	0.0 %	0.0 %	0.0 %
bcm.ipmc	0.0 %	0.0 %	0.1 %
bcm.l2	0.1 %	0.1 %	0.1 %
bcm.l2gre	0.0 %	0.0 %	0.0 %
bcm.l3	0.0 %	0.1 %	0.1 %
bcm.link	0.0 %	0.0 %	0.0 %
bcm.mim	0.0 %	0.0 %	0.0 %
bcm.mirror	0.0 %	0.0 %	0.0 %
bcm.misc	0.0 %	0.0 %	0.0 %
bcm.mpls	0.0 %	0.0 %	0.1 %
bcm.multicast	0.0 %	0.0 %	0.0 %
bcm.niv	0.0 %	0.0 %	0.0 %
bcm.oam	0.0 %	0.1 %	0.2 %
bcm.pkt	0.0 %	0.0 %	0.0 %
bcm.port	0.3 %	0.4 %	0.6 %
bcm.proxy	0.0 %	0.0 %	0.0 %
bcm.ptp	0.0 %	0.0 %	0.0 %
bcm.qos	0.0 %	0.0 %	0.0 %
bcm.rate	0.0 %	0.0 %	0.0 %
bcm.rtag7	0.0 %	0.0 %	0.0 %
bcm.rx	0.0 %	0.0 %	0.0 %
bcm.ser	0.0 %	0.0 %	0.0 %
bcm.stack	0.0 %	0.0 %	0.0 %
bcm.stat	0.0 %	0.0 %	0.0 %
bcm.stg	0.0 %	0.0 %	0.0 %
bcm.switch	0.0 %	0.0 %	0.1 %
bcm.time	0.0 %	0.0 %	0.0 %
bcm.trill	0.0 %	0.0 %	0.0 %
bcm.trunk	0.0 %	0.0 %	0.1 %
bcm.tunnel	0.0 %	0.0 %	0.3 %
bcm.subport	0.0 %	0.0 %	0.0 %
bcm.vlan	0.0 %	0.0 %	0.1 %

Table 36:

	sdk-6.4.11	sdk-6.4.10	sdk-6.4.9
bcm.vxlan	0.0 %	0.0 %	0.0 %
bcm.wlan	0.0 %	0.0 %	0.0 %
Test Suite Total	0.1 %	0.2 %	0.2 %

PHY TEST RESULTS

Starting from SDK-6.4.8, we have increased our focus and coverage on testing specific PHY and switch combinations in order to improve our quality in this area. The tables below represent specific results from our interoperability and regression testing for the release. We have been continually working to improve our results and coverage in ongoing releases.

SQA EXTERNAL PHY

Table 37: PHY Suite

Switch Device	External Phy Device	Total Tests	% Fail
56639_A0	phy8747_phy8728__10G	145	2.07%
56846_A0	Warpcore 40G/20G/10G	145	2.07%
56850_A2	phy84856_phy84858_10G	145	4.83%
56960_A0	100GFuria_40GMuxSesto	145	0.69%
56960_A0	10GFuria_10GSesto	145	0.69%
56860_A1	phy84856_phy84858_10G	145	0.69%
56860_A0	10GQuadra28	145	0.69%
56860_A0	40GQuadra28	145	2.07%
56860_A0	100GSesto	145	2.07%
56867_A1	phy82764_10G	145	1.38%
56867_A1	phy82764_40G	145	1.38%
56960_B0	phy82864_100G	145	3.45%
56960_B0	phy82864_100G_alt	145	4.83%
56960_B0	phy82864_40GPt	145	3.45%
56960_B0	phy82864_40GPt_alt	145	6.21%
56960_B0	phy82864_10G	145	4.83%
56960_B0	phy82864_10G_alt	145	5.52%
56960_B0	phy82864_11G	145	4.14%
56960_B0	phy82864_11G_alt	145	4.83%
56960_B0	phy82864_42GPt	145	2.76%
56960_B0	phy82864_42GPt_alt	145	4.83%
56960_B0	phy82864_106G	145	4.83%
56960_B0	phy82864_106G_alt	145	4.83%
56960_B0	phy82864_40G2x20	145	6.21%
56960_B0	phy82864_40G2x20_alt	145	6.90%
56960_B0	phy82864_42G2x20	145	8.97%



Table 37: PHY Suite

Switch Device	External Phy Device	Total Tests	% Fail
56960_B0	phy82864_42G2x20_a lt	145	5.52%
56960_B0	phy82864_40GMux	145	4.83%

INTEROP EXTERNAL PHY

Table 38: P2P Suite

Switch Device	Port Macro	Total Tests	% Fail
56860_A0	XE_QD28_82780_40G	141	0.00%
56860_A0	XE_QD28_82780_10G	171	0.00%
56860_A0	XE_SESTO_82764_40G _MUX	125	3.20%
56860_A0	CE_SESTO_82792_100 G_343	244	1.23%
56860_A0	XE_SESTO_82764_40G _PT	192	1.04%
56860_A0	XE_SESTO_82764_10G _PT	168	1.19%
56860_A0	XE_G28_82322_10G	410	3.17%
56860_A0	XE_G28_82322_40G	344	1.74%
56860_A0	XE_G40_84328_10G	429	1.63%
56860_A0	XE_G40_84328_40G	360	0.56%
56960_A0 (repeater)	HG_MADURA_82864_42 G_PT	60	0.00%
56960_A0 (repeater)	CE_MADURA_82864_10 OG_ALT	189	0.00%
56960_A0 (repeater)	XE_MADURA_82864_10 G	135	0.00%
56960_A0 (repeater)	HG_MADURA_82864_42 G_DUAL_ALT	60	0.00%
56960_A0 (repeater)	XE_MADURA_82864_40 G_PT_ALT	132	0.00%
56960_A0 (repeater)	HG_MADURA_82864_42 G_PT_ALT	60	0.00%
56960_A0 (repeater)	XE_MADURA_82864_40 G_MUX	108	0.00%
56960_A0 (repeater)	HG_MADURA_82864_11 G	60	0.00%
56960_A0 (repeater)	HG_MADURA_82864_10 6G_ALT	87	0.00%
56960_A0 (repeater)	HG_MADURA_82864_42 G_MUX	60	0.00%
56960_A0 (repeater)	XE_MADURA_82864_40 G_DUAL	102	6.86%
56960_A0 (repeater)	HG_MADURA_82864_42 G_DUAL	48	8.33%
56960_A0 (repeater)	XE_MADURA_82864_10 G_ALT	108	0.00%

Table 38: P2P Suite

Switch Device	Port Macro	Total Tests	% Fail
56960_A0 (repeater)	HG_MADURA_82864_11 G_ALT	60	0.00%
56960_A0 (repeater)	HG_MADURA_82864_10 6G	69	17.39%
56960_A0 (repeater)	XE_MADURA_82864_40 G_DUAL_ALT	108	0.00%
56960_A0 (repeater)	CE_MADURA_82864_10 0G	165	6.06%
56960_A0 (repeater)	XE_MADURA_82864_40 G_PT	132	0.00%
56960_A0 (retimer)	HG_MADURA_82864_42 G_PT	90	0.00%
56960_A0 (retimer)	CE_MADURA_82864_10 0G_ALT	235	0.43%
56960_A0 (retimer)	XE_MADURA_82864_10 G	162	0.00%
56960_A0 (retimer)	HG_MADURA_82864_42 G_DUAL_ALT	90	0.00%
56960_A0 (retimer)	HG_MADURA_82864_42 G_PT_ALT	90	0.00%
56960_A0 (retimer)	XE_MADURA_82864_40 G_MUX	162	0.00%
56960_A0 (retimer)	HG_MADURA_82864_11 G	90	0.00%
56960_A0 (retimer)	HG_MADURA_82864_10 6G_ALT	127	0.79%
56960_A0 (retimer)	HG_MADURA_82864_42 G_MUX	90	0.00%
56960_A0 (retimer)	XE_MADURA_82864_40 G_DUAL	138	5.80%
56960_A0 (retimer)	HG_MADURA_82864_42 G_DUAL	66	12.12%
56960_A0 (retimer)	XE_MADURA_82864_10 G_ALT	162	0.00%
56960_A0 (retimer)	HG_MADURA_82864_11 G_ALT	90	0.00%
56960_A0 (retimer)	HG_MADURA_82864_10 6G	87	19.54%
56960_A0 (retimer)	XE_MADURA_82864_40 G_DUAL_ALT	162	0.00%
56960_A0 (retimer)	CE_MADURA_82864_10 0G	219	9.13%
56960_A0 (retimer)	XE_MADURA_82864_40 G_PT	372	1.08%

Table 39: Loopback Suite

Switch Device	Port Macro	Total Tests	% Fail
56860_A0	XE_QD28_82780_40G	47	0.00%

Table 39: Loopback Suite

Switch Device	Port Macro	Total Tests	% Fail
56860_A0	XE_QD28_82780_10G	62	0.00%
56860_A0	XE_SESTO_82764_40G_MUX	25	0.00%
56860_A0	CE_SESTO_82792_100G_343	47	0.00%
56860_A0	XE_SESTO_82764_40G_PT	30	0.00%
56860_A0	XE_SESTO_82764_10G_PT	30	0.00%
56860_A0	XE_G28_82322_10G	30	3.33%
56860_A0	XE_G28_82322_40G	25	0.00%
56860_A0	XE_G40_84328_10G	66	0.00%
56860_A0	XE_G40_84328_40G	55	0.00%
56960_A0 (repeater)	HG_MADURA_82864_42G_PT	44	9.09%
56960_A0 (repeater)	CE_MADURA_82864_100G_ALT	77	9.09%
56960_A0 (repeater)	XE_MADURA_82864_10G	55	0.00%
56960_A0 (repeater)	HG_MADURA_82864_42G_DUAL_ALT	44	9.09%
56960_A0 (repeater)	XE_MADURA_82864_40G_PT_ALT	44	9.09%
56960_A0 (repeater)	HG_MADURA_82864_42G_PT_ALT	44	9.09%
56960_A0 (repeater)	XE_MADURA_82864_40G_MUX	44	9.09%
56960_A0 (repeater)	HG_MADURA_82864_11G	44	0.00%
56960_A0 (repeater)	HG_MADURA_82864_106G_ALT	55	9.09%
56960_A0 (repeater)	HG_MADURA_82864_42G_MUX	44	2.27%
56960_A0 (repeater)	XE_MADURA_82864_40G_DUAL	44	9.09%
56960_A0 (repeater)	HG_MADURA_82864_42G_DUAL	44	9.09%
56960_A0 (repeater)	XE_MADURA_82864_10G_ALT	44	2.27%
56960_A0 (repeater)	HG_MADURA_82864_11G_ALT	44	2.27%
56960_A0 (repeater)	HG_MADURA_82864_106G	55	9.09%
56960_A0 (repeater)	XE_MADURA_82864_40G_DUAL_ALT	44	6.82%
56960_A0 (repeater)	CE_MADURA_82864_100G	55	9.09%
56960_A0 (repeater)	XE_MADURA_82864_40G_PT	44	9.09%
56960_A0 (retimer)	HG_MADURA_82864_42G_PT	66	9.09%

Table 39: Loopback Suite

Switch Device	Port Macro	Total Tests	% Fail
56960_A0 (retimer)	CE_MADURA_82864_10 OG_ALT	99	8.08%
56960_A0 (retimer)	XE_MADURA_82864_10 G	66	0.00%
56960_A0 (retimer)	HG_MADURA_82864_42 G_DUAL_ALT	66	3.03%
56960_A0 (retimer)	XE_MADURA_82864_40 G_PT_ALT	66	9.09%
56960_A0 (retimer)	HG_MADURA_82864_42 G_PT_ALT	66	9.09%
56960_A0 (retimer)	XE_MADURA_82864_40 G_MUX	66	0.00%
56960_A0 (retimer)	HG_MADURA_82864_11 G	66	1.52%
56960_A0 (retimer)	HG_MADURA_82864_10 6G_ALT	99	7.07%
56960_A0 (retimer)	HG_MADURA_82864_42 G_MUX	66	0.00%
56960_A0 (retimer)	XE_MADURA_82864_40 G_DUAL	66	9.09%
56960_A0 (retimer)	HG_MADURA_82864_42 G_DUAL	66	4.55%
56960_A0 (retimer)	XE_MADURA_82864_10 G_ALT	66	0.00%
56960_A0 (retimer)	HG_MADURA_82864_11 G_ALT	66	0.00%
56960_A0 (retimer)	HG_MADURA_82864_10 6G	99	12.12%
56960_A0 (retimer)	XE_MADURA_82864_40 G_DUAL_ALT	66	3.03%
56960_A0 (retimer)	CE_MADURA_82864_10 OG	99	6.06%
56960_A0 (retimer)	XE_MADURA_82864_40 G_PT	66	9.09%

INTEROP INTERNAL PHY

Table 40: P2P Suite

Switch Device	Port Macro	Total Tests	% Fail
56860_A0	HG_32X42	36	0.00%
56860_A0	XE_32X40	99	0.00%
56860_A0	HG_8x100_343	36	0.00%
56860_A0	CE_8X100_343_IEEE	72	0.00%
56860_A0	HG_104x10	16	25.00%
56860_A0	XE_104x10	51	15.69%
56860_A0	CE_8x100_442	72	0.00%

Table 41: Loopback Suite

Switch Device	Port Macro	Total Tests	% Fail
56860_A0	HG_32X42	11	0.00%
56860_A0	XE_32X40	22	0.00%
56860_A0	HG_8x100_343	11	0.00%
56860_A0	CE_8X100_343_IEEE	11	0.00%
56860_A0	HG_104x10	11	45.45%
56860_A0	XE_104x10	22	45.45%
56860_A0	CE_8x100_442	11	0.00%

STATIC CODE ANALYSIS

In early 2015 we upgraded our static analysis code tool to a version with many new checkers and have been steadily working down the backlog of issues. Below Static Code Analysis Summary ([page 52](#)) shows the progress in the ensuing 6.4.x releases:

Table 42: Static Code Analysis Summary

Line Of Business	Initial Reported Issues	New baseline as of 1/31/15	Open Issues SDK 6.4.5	Open Issues SDK 6.4.6	Open Issues SDK 6.4.7	Open Issues SDK 6.4.8	Open Issues SDK 6.4.9	Open Issues SDK 6.4.10	Open Issues SDK 6.4.11
DNX	664	450	295	168	113	108	58	22	4
XGS	271	500	229	116	9	11	4	4	13
SBX	600	650	156	77	23	23	1	0	0
SerDes	147	100	59	49	58	23	21	5	6
Common	2827	400	155	133	29	24	9	10	3
Total	4509	2100	894	543	232	189	93	41	26

Section 8: Service Impacting Defects

A Service Impacting Defect (SID) is any defect (internal or external) that has high potential to severely disrupt network operations in a deployed system. This section lists the SIDs that have been identified since last release in Resolved Service Impacting Defects ([page 53](#)) .

Table 43: Resolved Service Impacting Defects

Number	Chips	Affected versions	Errata Synopsis	Details
SDK-89279	56850_A2 56860_A1	6.4.4, 6.4.5, 6.4.6, 6.4.7, 6.4.8, 6.4.9	Customers running BCM56850 or BCM56860 with SDK release 6.4.4 through 6.4.9 have a risk of seeing ALPM failures and traffic drops in their system.	This issue was introduced by an improvement to the 'raw bucket split' introduced in SDK 6.4.4 and having L3RouteCache set to 1. ALPM IPv6 did not invalidate corresponding memory's cache for old bucket. Both ALPM IPv4 and IPv6 did not invalidate corresponding memory's cache for new bucket. Solution: Set L3RouteCache to 0, thus disabling ALPM memory caching or apply patch for SDK-89279.
SDK-91799	All devices	6.4.9	Potential memory leak with regard to the features that use internal shr_htbl_destroy function	All customers and all devices running Switch SDK might have a risk of encountering table a memory leak. The memory leak appears whenever shr_htbl_destroy was used. Memory leak was observed in DNX OAM/BFD interrupt context. This issue may also occur in BCM56450 OAM, BCM56260 OAM/SAT, BCM56640 OAM, BCM88030 L2/allocator/MPLS/OAM, and BCM88020 MPLS/OAM/L2. Fix of shr_htb_destroy() : Memory freeing performed with a while loop, instead of the for loop which didn't free all of the buffers

Section 9: Resolved Issues for 6.4.11

The following issues are resolved in version 6.4.11 of the SDK.

Table 44:

Number	CSP	Chips	Release Notes For 6.4.11
PHY-2154	1007470	56860_A0 56860_A1	Flag is set to system side before setting TX filter taps.
PHY-2172	1012223	56548_A0	Added support to CL37 autoneg. To enable CL37 user need to enable auto negotiation on 1G SR mode.
SDK-48834		56334_A0 56334_B0 AllChips	1. with config variable <code>sw_timestamp_fifo_enable=0</code> 2. counter thread doesn't read the timestamp fifo 3. API directly access the timestamp fifo. (there will be no delay) 4. **** for link down event, fifo needs to be flushed. ****
SDK-73323	910638	88650_B1 88660_A0	Fixed RFCS and RERPKT error on RXAUI port when traffic is 10G or almost 10G, and packet size is 1518 byte.
SDK-75174	903355	88660_A0	For BCM88650 and BCM88660 the meter id will be only 14 bits since 15 bit overlap in HW with out register Note that bit 15 is allways set hence the values of possible meter id are:16383 - 32767
SDK-76878	930295	88670_A0	added support for phyctrl in diag nif
SDK-80663	950370	88670_A0	Interface to <code>bcm_petra_mirror_port_destination_add()</code> has been extended so that, on BCM88670, PMF egress mirroring is activated and assigned strength for 'copy' and for 'forward'
SDK-80991	947340	88670_A0 88670_B0 AllChips	Fixed presentation of range qualifier in <code>bcm_field_group_dump</code>
SDK-81010	953251	88670_A0	Added an alias for <code>IRR_FABRIC_MC_BASE_QUEUEr</code> for BCM88650.
SDK-81138	911055	88670_A0 88670_B0	SDK initialization with no ports on core 1 is now possible.
SDK-81250	936854	88670_A0	OAM: Occasionally a dynamic table will not get cleared correctly on init, causing the OAMP to pump garbage packets.
SDK-81642	945034	88650_B1 88660_A0	Unexpected error log was removed from code
SDK-81670	938722	88650_B1 88660_A0	packets in certain sizes may cause faulty ECC errors in the first 2k packets sent. this fix prevents those errors from occurring
SDK-81937	959373	88660_A0	CRPS: case of <code>ING_PP</code> , FULL COLOR - problem was found while reading a specific counter set which is being split between 2 engines. issue fixed
SDK-82951	965831	88670_A0	Using cascaded entries does not require any special custom flags now.
SDK-83206		88670_A0	In earlier releases the callback for interrupts was skipped by wrong judgement on BCM88675. In this release, the judgement has been corrected on BCM88675.
SDK-83233	968261	88650_B1 88660_A0 88670_A0	TXXR: When setting <code>SOC_tm_port_header_type_out</code> to CPU, internal dune header will be inserted before packet data. In previous release, 1) internal dune header was treated as part of packet, which cause decoder in packetwatcher work wrongly. 2) packet total length was gotten from internal dune header, which is not correct. In this release, 1) decoder skip internal dune header when parsing packet. 2) packet total length is gotten from DCB.

Table 44:

Number	CSP	Chips	Release Notes For 6.4.11
SDK-83850	972446	88670_A0	In earlier releases interrupt names did not have interface id for BCM88670. In this release, added interface id to interrupt names for BCM88670.
SDK-83938		88670_A0	<p>When systems are over-subscribed, packets might be corrupted or lost due to XLMAC TX_PKT_UNDERFLOW. In that cases, increasing TX_START_TX_THRESHOLD_QMLF_N field of the NBIH_TX_QMLF_CONFIG and NBIL_TX_QMLF_CONFIG registers will solve the problem, with the cost of some packet delay. For that, a custom feature was added to control the TX_START_TX_THRESHOLD_QMLF_N field of the NBIH_TX_QMLF_CONFIG and NBIL_TX_QMLF_CONFIG registers.</p> <p>Details about the custom feature: Name: custom_feature_mac_fifo_start_tx_thrs Default value: 4 Functionality: The value from custom_feature_mac_fifo_start_tx_thrs is written to TX_START_TX_THRESHOLD_QMLF_N field of all NBIH_TX_QMLF_CONFIG and NBIL_TX_QMLF_CONFIG registers!</p>
SDK-83982	940778	88660_A0	<p>The default behavior for DNX FAP devices, is that ingress resource (buffer descriptors) reservation take precedence over discard decisions (WRED, tail drop. FADT) only for DP 0 (green). This means that for DP 1-3 discards were still applied for packets in the reserved/guaranteed resource range.</p> <p>A new soc property is added to control the precedence of guarantee over admit was added. It can be used without a DP to specify all DPs, or with a specific DP: cosq_admission_preference={ADMIT_OVER_GUARANTEE,ADMIT_OVER_GUARANTEE} cosq_admission_preference[0-3]={ADMIT_OVER_GUARANTEE,ADMIT_OVER_GUARANTEE}</p>
SDK-84267	973697	56850_A0 56850_A1 56850_A2	Added the support to set individual lane firmware mode
SDK-84290	974520	88670_A0	Now Egress PMF actions will appear in diag field res
SDK-84600	975898	88670_A0	'bcmFieldQualifyOutPort' does not have a 'core' bit and may, therefore, not be used on BCM88670 and up since pp_port is ambiguous. Use bcmFieldQualifyDstPort instead
SDK-84945	966743	53288_A0	API bcm_trunk_set doesn't clear load balancing key of previous setting if existed. This was fixed.
SDK-85216		88670_A0 88670_B0	ILKN quad memory resources were not verified when dynamically adding a new non-ILKN port. Now, these resources are verified when dynamically adding non-ILKN port.
SDK-85454	981222	88670_A0	Added support for bcmRxTrapEgTxMtuFilter, bcmRxTrapEgTxDiscardFrameTypeFilter and bcmRxTrapEgTxSplitHorizonFilter traps
SDK-85770	979673	88660_A0 AllChips	The feature is redesigned. New PAPI is added for now.
SDK-86453	987959	56960_A0 56960_B0	For BCM56960 IFP, group QSET update after group is created is supported .
SDK-87036	992120	53415_A0 53416_A0	To avoid wrong ext-phy driver been hooked up and wrong phy setting been applied to incorrect ext-phy once user miss the assignment on phy address for a specific port.

Table 44:

Number	CSP	Chips	Release Notes For 6.4.11
SDK-87502	989710	88670_A0	CRPS performance issue: when calling <code>bcm_cosq_gport_statistic_multi_get()</code> , the driver pull all CRPS DB from the SW state and at the end of the procedure, it store it back to the SW state. This operation takes a lot of time. In order to short the time of the <code>bcm_cosq_gport_statistic_multi_get()</code> , the driver will pull from SW state (and store back) only the parameters that required for this procedure.
SDK-87772	950925	56840_A0 56850_A0 56850_A1	When ser parity error occurs on the memories which cannot be accessed by cpu, sdk miss reporting an event to application. Now in this release, sdk will report an event when this case happens.
SDK-87932	994401	56460_A0	Following are the fixes for this Jira 1. Lock both the h/w semaphores on the host(SDK), before resetting any of the cores uC1/uC2. Implemented the timeout mechanism for acquiring these semaphores so as to avoid deadlock 2. Before actually resetting the PTP-core, ensure that the "in_use" flag is set, to ensure that PTP is configured and SDK knows the PTP-core 3. Disable Timesync interrupts as done in SDK-88764 for mhost reset of uC1
SDK-88141	997203	AllChips	If disabling a combo port, power down both copper & fiber media.
SDK-88316	997786	56860_A0	To enable the 1G AN on the PHY84328, the PHY should be programmed at 1G forced speed first, then AN should be enabled. PHY84328 supports only cl37 (no SGMII AN) at 1G speed.
SDK-88338	992728	88660_A0	<code>api_bcm_l2_cache_get</code> did not update bellow flags even if they were set: <code>BCM_L2_CACHE_TRUNK</code> <code>BCM_L2_CACHE_SUBTYPE</code> Now the flags updated in case they are set.
SDK-88395	991918	88660_A0	<code>bcm_field_qualify_SrcPort_get</code> will not return error, so this field can be used for ACL
SDK-88545	1001654	88670_A0	Added a condition to return the default value of the <code>DEFAULT_CPU_TRAP_CODE</code> field in <code>IHP_PINFO_LLR</code> memory when we call <code>bcm_port_force_forward_set()</code> with <code>enable=0</code> .
SDK-88614	1002100	88660_A0	tr 50 changed to skip write only memories.
SDK-88713	993663	88670_A0 88670_B0 88950_a0	Configuring "serdes_firmware_mode" explicitly might mistakenly override other SerDes UCODE configuration.Fixed However, It is recommended to use dedicated control for the required property and not to use SerDes firmware mode control. For example: SerDes DFE on should be enable by: "bcm_port_phy_control_set(unit, port, BCM_PORT_PHY_CONTROL_FIRMWARE_DFE_ENABLE, value);" And not by: "bcm_port_phy_control_set(unit, port, BCM_PORT_PHY_CONTROL_FIRMWARE_MODE, value);"
SDK-88783	1002625	56850_A0 56850_A1 56850_A2 56851_A0 56851_A1 56851_A2 56851P_A1 56851P_A2 56852_A0 56852_A1 56852_A2 56853_A0 56853_A1 56853_A2 56854_A0 56854_A2 56854_B0 56855_A0 56855_A2	In previous releases, port could stop egressing if lower WRED thresholds with traffic on the fly. This has been addressed by removing WRED refresh operations when changing drop profile.

Table 44:

Number	CSP	Chips	Release Notes For 6.4.11
SDK-88808	956238	88670_A0 88670_B0	MPLS PORT: added support for ingress 1+1 & Egress 1:1 protection.
SDK-88908	996575	88660_A0	Bug fix: Parsing of <code>frwrdd_type</code> field for mirror packet.
SDK-88967	1003430	88670_B0	added the support of FEC cl91 set/get function into bcm api.
SDK-89079	997816	88670_A0	Confusion between logic port and TM port when getting tdm packet port was fixed.
SDK-89127	1000525	AllChips AllChips	In earlier releases the flag <code>BCM_QOS_MAP_L2_VLAN_PCP</code> was missed when getting qos egrss pcp vlan flags. In this release, the flag <code>BCM_QOS_MAP_L2_VLAN_PCP</code> has been added.
SDK-89144	999992	88670_A0	dynamic port multiple cycles of add and remove ports is fixed.
SDK-89261	1005946	56340_A0	Updated initialization of EFP keys in the order such that all L2 keys goes into a single slice which would allow to qualify for all types of packets. Order of keys now is KEY4, KEY 1, KEY1_NO_V4, KEY2, KEY3 .
SDK-89312	1003606	88660_A0	Added a program which supports Up tx packets on LAG port.
SDK-89323	1006297	56860_A0 56860_A1	bcm port api support is added to provide dynamically switch between C137, C137BAM, cl73 and C173BAM
SDK-89327	1004665	AllChips	In previous releases, there was a miss of a lock in the internal function <code>bcm_xgs3_tbl_add</code> , which might lead to the incorrect NHI reference counts. In this release, this issue has been addressed.
SDK-89328	1006503	88670_A0 88670_B0	ERSPAN Mirroring modified to coincide with the standard - so that in the GRE header, the K flag is reset and the S flag is set.
SDK-89409	1005606	88670_A0	Dynamically adding logical port with id above the id of the max existing logical port at power-up - was causing a memory leak. Issue is now fixed and counters database is now allocated according to the maximum ports allowed. Moreover, connecting port with logical id beyond the maximum allowed (dynamically or statically) will lead to a BCM error.
SDK-89414		88670_A0 88670_B0	<code>bcm_multicast_delete</code> fixed for 2 CUD case.
SDK-89443	1004266	56060_A0	When <code>bcm_stat_sync_get()</code> API is used, the counter value is fetched from the hardware and the software copy of the counter s also updated, so that the count accumulation done by counter thread does not go out of sync. For 32-bit counter registers, the update to the software copy of the count was being done for wrong indexes causing wrap arounds to be detected. The above problem will be seen only in conjunction with counter thread running at very short interval and calling <code>bcm_atat_sync_get()</code> API in another thread context.
SDK-89496		AllChips	Logic added to check the array size before writing to it.
SDK-89515	1003217	53400_A0	<code>bcm_time_capture_get()</code> called with <code>TIME_CAPTURE_MODE_IMMEDIATE</code> will return the timestamp data
SDK-89519	1007400	56860_A0 56860_A1 56864_A1	In previous releases, configuring <code>bcmSwitchMeterAdjust</code> and <code>bcmSwitchShaperAdjust</code> for front panel ports would not take effect in BCM56864. This has been addressed by disabling the <code>soc_feature_egr_lport_tab_profile</code> check in the APIs.
SDK-89541	1007523	88670_B0	move all the logics for the interface get from glue code to phymod api
SDK-89590	989748	88470_A0 88660_A0 88670_A0	Create HiGiG port with <code>bcm_port_add</code> always fail, fixed.

Table 44:

Number	CSP	Chips	Release Notes For 6.4.11
SDK-89626	1001265	56440_A0 56440_A1 56440_B0	In the current SDK for 56440/56450 devices the RX CPU queues are being initialized before completing the DMA configuration. Moved the code for enabling CPU queues after the DMA channel configuration.
SDK-89663	1007804	56450_A0 56450_B0 56450_B1	As part of this jira, a fix is added to lookup ipmc repl tables correctly for matching interface bitmaps.
SDK-89731	990804	AllChips	update <code>_tx_dv_free()</code> function
SDK-89737	1005911	88670_A0 88670_B0	In the previous release, the 1588 timestanmping mode on QSGMII port was 48-bit by default. In this release, this mode is set to 32-bit.
SDK-89758	1006088	AllChips	In previous releases, routine <code>bcm_rpc_setup</code> might result in memory write overflow. So "ASSERT" had been added to this routine, when there was memory write overflow in the routine, SDK would be stopped.
SDK-89777		88670_A0 88670_B0	Strength bit is not updated correctly, since length of half lif entry is taken incorrectly. This is fixed.
SDK-89941	1009295	56460_A0 56460_B0	Port, Vlan and Level parameters are not required in oam endpoint add CLI for REMOTE endpoints. But this was enforced in the CLI. This has been fixed.
SDK-89942	1009233	56260_A0 56260_B0	Calling <code>bcm_oam_opcode_group_set()</code> was creating a gap between default oam opcode control profile and opcode group mapping. Fixed the issue by refreshing default oam opcode control profile based on new opcode group mapping.
SDK-89978	1009133	56850_A0 56850_A1 56850_A2	In previous releases, after synchronizing MMU traffic flag of one port to WarmBoot cache, there was a chance that the port link status could be changed from UP to DOWN. As a result, the MMU traffic flag was changed, but the new flag was not saved to WarmBoot cache. So when system Warm booted next time, SDK would use old value of the flag which could result in traffic lost. This issue have been solved now.
SDK-90020	1008887	56260_A0	An index allocated from BHH pool was not released when returned with failure. This caused running out of BHH pool indexes after multiple failures. This has been fixed by releasing the BHH pool indexes when endpoint create fails.
SDK-90056		88670_A0	Single Core can be set to ANY FAP ID (and not only even)
SDK-90070	1004651	88670_A0	When working with ILKN, <code>ref_clock</code> of 125MHz and data-rate of 11500, there were two issues: Functional issue with 4x10 port leading to wrong SerDes rate and diag issue in 4x25 port, leading to 0.5 factor in SerDes display (SerDes rate was OK). Both issue were fixed and correct rate is displayed for ILKN with <code>ref_clock</code> of 125MHz and data rate of 11500, both PML and PMH ports.
SDK-90073	1009403	88670_A0	setting different speeds to QSGMII ports resides on the same lane is now supported.
SDK-90080	1009568	56850_A0 56850_A1 56850_A2	In previous releases, <code>L3_IIF_PROFILE.TRUST_DSCP_PTR</code> was not retained with the original value and <code>L3_IIF.L3_IIF_PROFILE_INDEX</code> would be modified when <code>bcm_vlan_control_vlan_set</code> was invoked. This has been addressed in this release by correctly getting trust-qos-map-id in <code>_bcm_tr_l3_ingress_interface_get()</code> .

Table 44:

Number	CSP	Chips	Release Notes For 6.4.11
SDK-90092		56850_A1	In previous releases, <code>bcm_vxlan_port_add</code> didn't check the egress object that was created without <code>BCM_L3_VXLAN_ONLY</code> flag. In this release, <code>bcm_vxlan_port_add</code> will return a <code>BCM_E_CONFIG</code> error if the passed in egress object is created without <code>BCM_L3_VXLAN_ONLY</code> flag.
SDK-90111	999796	56960_A0 56960_B0 56960_B1	Since mode id is released twice, we could make a code change to release mode id for custom mode and then release mode id for regular mode only if it is not custom mode.
SDK-90132	1003575	56960_A0 56960_B0 56960_B1	In previous release, usage of <code>bcmPortControlMmuTrafficEnable</code> & <code>bcmPortControlMmuDrain</code> sequence for down ports will set link bit in <code>LED_DATA_RAM</code> . In this release, it has been fixed.
SDK-90151		88670_A0	Changed wrong "DIAG oam" comment in "Diag buffers" command.
SDK-90170	1009880	88670_A0 88670_B0	Learn Data was not filled for the BCM88670 learn format was not supported before, currently, the Learn Data is enabled for the BCM88670 learn format(FEC+EEL) is right now.
SDK-90218	1010399	56854_A0 56854_A2 56854_B0	In previous releases, port control flag <code>bcmPortControlLLFCTransmit</code> was not explained in detail, i.e. for StrataXGS devices, LLFC flags are used to control SAFC other than 802.3x PAUSE, while PFC flags instead are used for PAUSE configuration. This has been addressed by adding extra notes for these flags.
SDK-90271	970603	88670_A0 88670_B0	QSGMII CRC errors were seen sometimes on random links is fixed
SDK-90272	1010782	56850_A0 56850_A1 56850_A2 56860_A0 56860_A1	The PVTMON8 register has been enabled back in the TD2/ TD2+ code to display the temperature as it was ignored previously due to the wrong temperature readings shown by it.
SDK-90277	1011273	56850_A0 56850_A1 56850_A2	In previous releases, <code>ecmp_refcnt</code> in <code>_bcm_xgs3_l3_reinit()</code> was a static variable and could cause problem in multiunit parallel warm boot initiation. This has been addressed in this release.
SDK-90281	1011271	56840_A0	In this release, invalid mem check has been added in SER correction to prevent device from crash.
SDK-90294	969667	88670_A0 88670_B0	Injecting packets through PWE outlif (directed to PWE network) can be counted using soc property <code>custom_feature_eg_pwe_counting</code> . CCM packets should be injected with PWE label. Second PWE label which will be generated, will be removed by a PRGE program. Note: In this case MPLS tunnel cannot be encapsulated in the same EEDB entry with the PWE. For LMMs they have to add an OAM-TS and the outlif should be the LSP outlif (or whichever outlif comes after the PWE).
SDK-90297	1011195	56260_A0 56260_B0	There was missing cleanup in case <code>bcm_oam_endpoint_create()</code> was called with invalid parameter. Now SDK is modified to carry out proper cleanup in case there is a failure in <code>bcm_oam_endpoint_create()</code>
SDK-90302	1009375	88670_A0	Dynamically detaching ILKN port puts all its PMs out of bypass mode. When a PM is being shared between two (or more) ILKN ports, detach leads to bypass mode change of an active PM. This issue is fixed.
SDK-90328	1010022	88670_A0	assert while calling <code>bcm_cosq_port_mapping_set</code> , because trying to configure <code>IRR_DESTINATION_TABLE</code> per core, but the table is common for both cores. Solution: configure the table only once, using the relevant MACRO

Table 44:

Number	CSP	Chips	Release Notes For 6.4.11
SDK-90369	1006454	88660_A0	Meter (and also Ethernet policer in BCM88X7X) caused data lost in specific rates and bursts configuration. Meter's bucket configured to be smaller than the amount of credit in a given chunk of credits. Issue was fixed by adding verification of the minimum bucket size according to the given rates. By using <code>bcm_policer_get()</code> we will return the actual configured bucket size, which can be slight larger in such immoderate configurations.
SDK-90389	1011916	88670_A0 88670_B0	88675: Fixed an issue where creating a symmetric global lif and then a non symmetric global lif in the same 4k range would make it impossible to delete the non symmetric lif.
SDK-90392	1011831	56440_A0 56440_A1 56440_B0	The field entry dump command is modified to not remove the loopback ports in entry port bitmap mask.
SDK-90458		AllChips	bcmOAMEventBHHCCMTimeoutClear event will be issued when timeout is cleared on an BHH endpoint.
SDK-90460		88670_A0	Fixed presentation of PMF_DATA qualifier in diag field last
SDK-90479	1010074	56850_A0 56850_A1 56850_A2	In previous releases, the API <code>bcm_l3_host_travers</code> would stop getting the routing information once the reference count of an egress object in use was set to zero incorrectly. In this release, this issue has been addressed.
SDK-90489	1008068	88660_A0 88670_A0	In earlier releases SER handler for the memory IRR_MCDB was not right. In this release, SER handler has been corrected.
SDK-90492	1012578	56450_A0 56450_B0 56450_B1	In earlier releases, build issue is seen in non-posix OS due to presence of signal API in DDR test. This has been fixed in this release.
SDK-90497	1012570	56450_A0 56450_B0 56450_B1	Wrong device type check function was used to identify the PCI device when using the "dump pci" cli command . Correct the PCI device identity check with bus type get function in this release.
SDK-90502	996365	88670_A0 88670_B0	soft reset for single core mode is fixed.
SDK-90508	1001311	88670_A0	Global VSQ flow control thresholds was set to 0 be default. Meaning global flow control is always asserted, causing for lossless VSQs not using their shared memory space. The global flow control default was set to maximum value by default. Note that in addition FC thresholds should be configured to be larger than 0 when allocating lossless VSQs.
SDK-90530	1013040	56850_A0 56850_A1 56850_A2	In previous releases, the warm boot of multicast module took too much time. In this release, the time has been reduced.
SDK-90566	1012499	56850_A0 56850_A1 56850_A2	In the previous releases, extender gport was not available for egress VLAN translation. It has been added in this release.
SDK-90599	1012045	56850_A0 56850_A1 56850_A2	Used the correct index style for obtaining the HW index for a given port/cosq.
SDK-90607	1013571	56850_A0 56850_A1 56850_A2	The internal function of getting the ecmp member count was not implemented correctly. When the ecmp group only had one member, SDK missed to handle this scenario. The issue has been fixed in this release.
SDK-90612	998428	88670_A0 88670_B0	modify the description of <code>itmh.base.jer_dest_info</code>
SDK-90627	1011441	88670_A0 88670_B0	Now a pw can be updated even the <code>mpls_tunnel</code> for it has been removed.
SDK-90710	988545	88670_A0 88670_B0	In L2, when using the API <code>bcm_l2_replace()</code> with the flag <code>BCM_L2_REPLACE_MIGRATE_PORT</code> , the destination was not properly updated in the matching MAC table entries. This flag support is now corrected and when used, destination is updated as expected.
SDK-90741	1013393	56340_A0	BCM56345 will use a specified array for flex port interface, and this will not share with other chips.

Table 44:

Number	CSP	Chips	Release Notes For 6.4.11
SDK-90765	1010634	56960_A0 56960_B0 56960_B1	In previous releases, setting <code>bcmCosqControlEgressUCQueueSharedLimitBytes</code> and <code>bcmCosqControlEgressUCQueueMinLimitBytes</code> to zero didn't disable the queue. This has been fixed. <code>bcm_cosq_control_set(0, gport, 3, bcmCosqControlEgressUCQueueSharedLimitBytes, 0);</code> <code>bcm_cosq_control_set(0, gport, 3, bcmCosqControlEgressUCQueueMinLimitBytes, 0);</code>
SDK-90770	1014368	88670_A0 88670_B0	MPLS PORT: <code>failover_id</code> and <code>network_group_id</code> replace operation for pw created with <code>ingress_only</code> flag is now supported.
SDK-90808	1012945	88660_A0	OAM: when adding an RMEP in the OAMP while traffic is running spurious timeouts may occur.
SDK-90820	1008304	88670_B0	In the previous release, auto-neg can not work well on 100G tscf port and 40G tsce port. In this release, auto-neg work well on both 100G tscf port and 40G tsce port.
SDK-90830	1011600	88670_A0	In L3, when setting the SOC property <code>"bcm886xx_l3_ingress urpf enable=1"</code> , a bit was allocated in the inLIF profile for uRPF handling (as in BCM88660). This behavior is correct only for BCM88660, because in BCM88670, the inRIF profile controls the uRPF behavior. All redundant LIF configurations related to uRPF have been removed for BCM88670.
SDK-90843	1014201	56850_A0	The <code>NEW_INT_PRI</code> field of <code>EGR_IM_MTP_INDEX</code> table isn't configured with right value when adding mirror source port after performing warmboot. The root cause is the element <code>int_pri</code> of mirror destination doesn't get recovered during warmboot. Now in this version, this issue is fixed.
SDK-90844	1014681	56850_A0 56850_A1 56850_A2	In previous releases, when the feature of directed flexible mirroring was enabled, the reference counters for ingress and egress MTP index wouldn't be updated correctly. This issue has been fixed in this release.
SDK-90879	1007353	88670_A0 88670_B0	In L3, when calling <code>bcm_l3_host_traverse()</code> , only up to 129 entries were handled by the callback function, even if more hosts reside in the host table. This is fixed so that all configured hosts will be handled when calling <code>bcm_l3_host_traverse()</code> .
SDK-90887	1006296	56960_A0 56960_B0 56960_B1	In previous release, the API <code>bcm_cosq_gport_discard</code> didn't apply to the device-wide discard settings. In this release, it has been fixed.
SDK-90975	1015450	56960_A0 56960_B0 56960_B1	In previous releases, creating an L3 egress object with MPLS port was not supported. This has been implemented in this release.
SDK-90987	1015596	56850_A0 56850_A1 56850_A2	Parameters to <code>TimeStampToCpu</code> and its coloured variants are not properly read from the correct fields after warmboot. Fixed the same.
SDK-91003	1015512	56850_A0 56850_A1 56850_A2	In previous releases, warmboot function of BST module was not implemented. This has been added in this release.
SDK-91008	1013968	88660_A0	<code>defaultforuse_trunk_as_ingress_mc_destination</code> soc property was changes in the following way: for BCM88650 the default is 0 for BCM88660 and BCM88670 the default is 1 this JIRA cause problems with stacking due to new default in BCM88670 and BCM88660. to prevent problems with stacking, use previous default - <code>use_trunk_as_ingress_mc_destination=0</code> this default change meaning is that adding trunk destinations to mc group must be done in the new way (add trunk id gport to mc group) in relevant devices (Jericho and Arad Plus)

Table 44:

Number	CSP	Chips	Release Notes For 6.4.11
SDK-91011		56850_A0 56850_A1 56850_A2	In warmboot recovery, calling right group entry recovery method for EFP expanded slices and updated internal variable initializations
SDK-91024	1015667	56850_A0 56850_A1 56850_A2	The port number validation for qualifier bcmFieldQualifyDstPort and bcmFieldQualifySrcPort in a multi module system is set to appropriate value based on the chip.
SDK-91037	1013249	56860_A0 56860_A1	VLAN tagged packet drop issue should not be seen now as the HG port is been added properly the existing VLANs.
SDK-91072	1017510	AllChips	None
SDK-91124	1013840	88660_A0	Fix issue with 100G ports counters showing bad values after port disable-enable.
SDK-91138	1016489	56260_A0 56260_B0	Addressed the issues in bhh pool index free during endpoint create failure cases
SDK-91148	1016552	56850_A0 56850_A1 56850_A2	Syncing and recovering RedirectIpmc Action Type to set the parameters to right type after warmboot
SDK-91174	1015571	56850_A0 56850_A1 56850_A2	In previous releases, soc_mem_alpm_lookup could cause infinite loop and if there was a parity error in pipe_y then the function soc_mem_alpm_ser_correction was unable to correct it. Now this has been fixed.
SDK-91178	1012350	56850_A0 56850_A1 56850_A2	Before SDK_6_4_8 releases, the initial index of led data RAM was "1". However, in SDK_6_4_8 release, the initial index was changed as "0". So there was mismatch in led port order remap. Now the initial index is reset as "1".
SDK-91214	1011941	88670_A0 88670_B0	Removing or adding dynamically a port will cause for MC packet to be dropped due to wrong CGM configuration. Fixed
SDK-91216	1002182	88670_A0	In KBP , to reduce the initialization time, the flag KBP_DEVICE_PROP_INST_LATENCY was removed for BCM88670 devices. This flag was added since the advanced instructions were sometimes causing ROP error due to flow control. The property disables the advanced instructions which will increase the update rate. this property is not needed in BCM88670.
SDK-91222	1015642	88670_A0	DNX configures autoneg mode in soc/dpp level (jer_nif.c) . Autoneg configuration was added to portmod, which overrun DNX configuration. AUTONEG_CONFIG_SKIP flag added to portmod_port_add_info_t to enable skipping autoneg configuration in portmod. This flag is set on DNX (jer_nif.c)
SDK-91231	1014185	88670_A0	EVPN: No LSP tunnel configuration between PEs is now supported. Note: in this case PMF egress PE pre-selection cannot be done according to TT Termination
SDK-91348	1015662	88650_B1 88660_A0 88670_A0	DNX: Fixed an issue where writing to ESEM without a SW shadow may return success even if the writing was unsuccessful.
SDK-91384	1017345	88660_A0	in IPMC, when the API bcm_ipmc_add() was called without setting the flag BCM_IPMC_REPLACE, "Entry not found" message was printed, as the new entry did not exist. Now the API bcm_ipmc_add() prints the error only in case BCM_IPMC_REPLACE is set. Also, the API bcm_ipmc_find() does not print an error message in case an entry is not found, but returns "entry not found" code value for further use. In API bcm_ipmc_remove() an error is printed if the entry does not exist.

Table 44:

Number	CSP	Chips	Release Notes For 6.4.11
SDK-91385	1016558	56850_A0 56850_A1 56850_A2	In previous releases, the DMA memory space used for packet sending was not freed by "bcmTX" in time, which resulted in DV allocation failures in the next attempt of sending packets by other threads. Now the pending DMA memory space is freed in time.
SDK-91395	1015021	88470_A0 88650_B1 88660_A0 88670_A0 88670_B0	In the previous release, SAV TT program used invalid key constructions and prefix value. In this release, this issue has been addressed by using correct key constructions and prefix value for DHCP IPv4 SAV TT program.
SDK-91411	1016304	56260_A0 56260_B0	Issue: The queues mapped to disabled ports are in enable state after flex operation. This is caused by the race condition between linkscan and port enable function during linkup sequence of flex operation. Solution: The link up sequence of flex operation is modified to enable the linkscan first and then enable/disable port based on default config.
SDK-91421	1017467	AllChips	Calling the API <code>bcm_rx_init()</code> fails on device 56224, starting the SDK Release 6.5.1. This is due calling an internal routine, which is not supported on BCM56224. Added a check to prevent calling the internal routine on unsupported devices.
SDK-91426	1017726	88670_B0	In previous release, auto-neg does not work well on 1G eagle port with cl37 mode. In this release, auto-neg does work well on 1G eagle port with cl37 mode.
SDK-91431	1012177	AllChips	<code>bcm_field_qualify_L3Ingress</code> API accepted only a 12bit inRif value, while the in-RIF range was extended to 15 bits in BCM88670. This qualifier was adjusted to accommodate the full range.
SDK-91432	1017957	56860_A0 56860_A1	Moved the <code>ing_attr</code> pointer into the ingress mode part and adding similar attribute <code>egr_attr</code> and setting the total counter values for the egress mode.
SDK-91446	1016916	88670_A0 88670_B0	In FCoE, delete and get LPM route (using flag <code>BCM_FCOE_DOMAIN_ROUTE</code>) failed due to internal error. Issue fixed and now it is possible to get and delete LPM entries.
SDK-91447	1013585	88660_A0	OAM: The API <code>bcm_oam_delay_get()</code> returns incorrect nanoseconds in <code>delay_min</code> , <code>delay_max</code> , <code>delay</code> fields. Actual nanoseconds value is 4 times greater than the returned value.
SDK-91506		88670_A0	Minor bug fix. The following API may have been malfunctioning regarding order of entries on data base if flag <code>BCM_FIELD_GROUP_CREATE_INSERTION_ORDER_LOOSE</code> has been used: <code>bcm_field_group_config_create()</code> . Note that there was no effect on <code>bcm_field_group_create_id()</code>
SDK-91518	1018043	56960_A0 56960_B0 56960_B1	the sentence of <code>#if 0</code> is added for TD2P DEV branch by Wilson, maybe in order to see some intermittent error with BCMSIM, then merged to master branch, It should be moved.
SDK-91553	1017189	56460_A0 56460_B0	1) Incorrect modid and port was used to construct gport in case of CoE support . 2) Also support port gport was not constructed during warmboot. The above issues have been fixed.
SDK-91564	1018613	56460_A0 56460_B0	In KT2/SB2 EFP Byte counter is 36 bits and IFP Byte counter is 35 bits. Used the corresponding counter update for updating the SW counter as per the stage.
SDK-91598	1017914	56340_A0	In previous releases, the <code>_soc_hx4_age_timer_get</code> API could return <code>enable=1</code> and <code>age_seconds=0</code> . This issue has been fixed in this release.

Table 44:

Number	CSP	Chips	Release Notes For 6.4.11
SDK-91657	1019274	56960_A0 56960_B0 56960_B1	<p>Issue: IFP entries are used in BCM56960 and L2 entries are used in BCM56860 to assign session id to non-zero discriminator BFD packets. This needs to be removed as per customer's requirements.</p> <p>Fix: This is fixed by adding a new config property called "bfd_use_endpoint_id_as_discriminator". When this config property is configured (enabled by setting to 1), the local_discriminator value in the endpoint_info during bfd endpoint create will be ignored and discriminator is arrived at by adding a +1 to the session/endpoint_id. Hence there exists a direct linear mapping between session id and discriminator and those IFP/L2 entries are not required. The +1 is done to avoid zero endpoint_id/session_id giving out zero discriminator.</p>
SDK-91680	1017339	AllChips	Phase holdover mode support is indicated as part of ptp servo config command
SDK-91751	1015676	56850_A0 56850_A1 56850_A2	For legacy flex stat modes, counter attribute information is not saved / retrieved from scache after warm boot. This causes new modes to be created for every user request, after warm boot, due to which the system runs out of HW counter modes (0-3).
SDK-91759	1019317	88670_B0	Sergey created a new label for BCM88670 B0 and I updated the mcmrelease wit the correct BS_PLL_CFG_RESET_B<173> and BS_PLL_CFG_POST_RESET_B<174> in ECI_BS_PLL_CONFIG for BCM88670 B0.
SDK-91761	1016153	88670_A0	The diagnostics command "diag dbal lp " caused a SDK crash. The issue happens only when the packet was using LPM lookup. This issue caused by incorrect use of signal value. This issue is fixed now.
SDK-91796	1019327	56460_A0 56460_B0	<p>Problem: pinfo->vlan_prot_ptr and vp entry is not recovered correctly after warmboot.</p> <p>Solution: Vp entry and Vlan protocol data index (vlan_prot_ptr) are storied in scache and retrieve back during warm boot.</p>
SDK-91799	1018239	AllChips AllChips	All customers and all devices running Switch SDK within the "Affected Versions" have a risk of encountering table a memory leak. The memory leak appears whenever shr_htbl_destroy was used. Memory leak was observed in DNX OAM/BFD interrupt context. This issue may also occur in BCM56450 OAM. BCM56260 OAM and SAT, BCM56640 OAM, BCM88030 I2, BCM88030 allocator, BCM88030 mpls, BCM88030 oam, BCM88020 mpls, BCM88020 oam, BCM88020 I2.
SDK-91824	1019661	56440_A0 56440_A1 56440_B0	In KT EFP Byte counter is 36 bits and IFP Byte counter is 35 bits. Used the corresponding counter update for updating the SW counter based on the stage.
SDK-91852	1017672	AllChips	<p>Problem: If we try to configure both AN(true) and Speed or duplex of a port via a single call of bcm_port_selective_set, the API returns success but the AN status set back to false. This is because as part of speed or duplex config the AN gets disabled.</p> <p>Solution: In case both AN (true) and Speed setting together then forced speed we allow only if AN disabled. If AN enabled for speed configure return param error. In case both AN (true) and duplex setting together then AN we enable and allow duplex to get auto-detected. For duplex configure return param error.</p>

Table 44:

Number	CSP	Chips	Release Notes For 6.4.11
SDK-91858	1016677	88670_A0 88670_B0	In L3, API <code>bcm_l3_route_add()</code> returned the error code <code>BCM_E_INTERNAL</code> (-1) for all error cases. Now <code>BCM_E_FULL</code> error code is returned in case the route DB has reached its limit.
SDK-91895	1019454	88470_A0 88670_A0 88670_B0	Updated the error msg to the correct one.
SDK-91936	1019593	56860_A0 56860_A1	In this release, improved the time performance of API <code>bcm_mpls_port_add()</code> with flags <code>BCM_MPLS_PORT_REPLACE</code> and <code>BCM_MPLS_PORT_EGRESS_TUNNEL</code> specified for non failover port.
SDK-91939	1020205	88670_A0 88670_B0	Tunnel according DIP+SIP+vrf supported together with <code>tst2</code> custom feature
SDK-91955	1019524	56860_A0 56860_A1	<code>MY_MODID</code> is the global parameter for the device. But it resides in <code>PORT_TABm</code> . When <code>flexport</code> is executed, the new entry will be created in <code>PORT_TABm</code> . As part of <code>flexport</code> sequence, current <code>MY_MODID</code> needs to be set to <code>PORT_TABm.MY_MODIDf</code> .
SDK-92025	1020140	88660_A0	OAM: destroying/updating OAM server on server side may fail.
SDK-92029	1011827	88670_A0 88670_B0	<code>cint_route_over_ac.c</code> fixed: 1. EVE is configured for <code>tag_format 0</code> (since L2 header is terminated) 2. <code>ecmp_intf</code> is used (instead of <code>fec_id</code>) in <code>l3_host_create</code> API (LEM entry size limitation)
SDK-92052	1009057	AllChips	Fix to handle PTP master's port re-configuration with new IP address.
SDK-92057	1020287	88670_A0	Now when using the <code>bcm_l3_intf_get</code> the Forwarding MTU will be updated if it was set (the <code>mtu_advanced_mode</code> SOC is mandatory for this)
SDK-92065	1019467	88670_A0 88670_B0	check <code>resilient_hash_enable</code> soc in init, if its enabled on non supported device an error is thrown
SDK-92068	1020449	56640_A0 56640_A1 56640_B0	Issue ===== During warmboot recover, control pool info related to slice was not getting updated properly. In TR3, when a stat is create, one of the counter pool is reserved for that slice. In the given configuration after 2 group with entries are created. Pool id 0 was reserved for entries in slice 0 or group 14 & FP_POLICY_TABLE.ipipe0[0]: COUNTER_SET=0x54000,> // COUNTER_POOL_NUMBER=0 & COUNTER_POOL_INDEX=0 Pool id 1 was reserved for entries in slice 1 or group 20 FP_POLICY_TABLE.ipipe0[512]: COUNTER_SET=0x54200,COUNTER_POOL_NUMBER=1,> // COUNTER_POOL_NUMBER=1 & COUNTER_POOL_INDEX=0 During warmboot recovery, while recovering entries, SW link between counter pool and slice idx was not update properly, due to this SW info says all the counter are free. When a new entry is created for slice 1 or group 20, and stat is attached for it. SW tries to allocated pool id 0 for slice 1. Ideally it should have allocated from pool id 1 as it was reserved for slice 1. Fix == Updated slice id mapping in counter pool during stat recover.
SDK-92081	1014514	88660_A0	CRPS issue: time of <code>bcm_field_stat_multi_get</code> API is too long. the reason is that there are many reading from SW DB. Solution: reduce the number of times reading parameters from SW DB.
SDK-92120	1020402	56960_A0 56960_B0 56960_B1	<code>bcm_field_stat_id_get</code> will not fail even if some entries the group have no stats attached to it.

Table 44:

Number	CSP	Chips	Release Notes For 6.4.11
SDK-92160	1019858	56860_A0 56860_A1	An error in <code>soc_td2p_mmu_flexport_allocate_deallocate_ports()</code> where physical ports were being indexed from 0-127 rather than 1-128, which caused MMU Ports to be improperly marked as free (physical port 128's MMU Port was never marked as in use because of this off by one). Thus, two ports were being assigned the same MMU Port and therefore the same queues.
SDK-92183	1020413	56860_A0 56860_A1	We are setting the PGW_LED_CHAIN_OUT_CONFIG register for all the PGW blocks irrespective of whether it is active or not.
SDK-92280	1021062	88670_A0	MPLS: If the result of MPLS label lookup in the forwarding stage is FEC+Outlif, the following configuration should be used in <code>bcm_mpls_tunnel_switch_struct:egress_if</code> - outlif value encoded as BCM interface of type OutLif port - FEC value encoded as BCM gport of type forwarding port
SDK-92310	1021225	56340_A0	Threshold settings for SC and QM queues (queue number 8 and 9) were blocked in the SDK. These have now been enabled.
SDK-92345	1021506	56334_A0 56334_B0	Issue: Wrongly calculating the trunk member due to that failed to initialize the mirror module after disabling the trunk members. Solution: Retrieving the right active members during the mirror initialization.
SDK-92463	1017019	88670_A0	Full range of MC ID may be used up to defined in the system
SDK-92492	1021749	88670_A0	In the previous release, the API <code>bcm_port_timesync_config_set</code> can't disable 1588 mac function on port. In this release, this issue has been addressed by setting the value of field 'IEEE_1588_MAC_ENABLEf' to 0.
SDK-92625	1021903	88950_a0	In earlier releases there was no recover action when initiate FE3200 RTP ECC error. In this release, added recover action for FE3200 RTP ECC.
SDK-92676	1022834	AllChips	IBOD WAR is being executed on the INVALID ports as well. VALID ports check fix the issue.
SDK-92697	1022680	88670_A0 88670_B0	When a fid is disconnected from a learn profile and it was the last fid using the profile, this profile is cleaned. In case the same fid immediately gets the same profile in <code>_bcm_dpp_am_template_l2_learn_profile_exchange</code> , this profile should not be cleared. Now the learn profile is not cleared in this case
SDK-92782	1023464	88670_A0 88670_B0	In the previous release, aging configuration was updated incorrectly. In this release, this issue has been addressed by not updating the aging configuration when <code>bcm_vlan_control_vlan_set()</code> is called without aging profile and configuration.
SDK-92875	1022739	88660_A0	When SOC property <code>bcm886xx_ipv6_tunnel_enable</code> was set to '0', VXLAN or any IP tunnel type was not terminated properly, due to wrong processing in the tunnel termination stage. The tunnel termination ucode has been changed to support correct handling when <code>bcm886xx_ipv6_tunnel_enable</code> is set to '0' or '1'.
SDK-92891	1025033	56850_A0 56850_A1 56850_A2	In previous releases, parity error in the memory <code>MMU_WRED_UC_QUEUE_TOTAL_COUNT_X_PIPE</code> would not be corrected. This issue has been addressed in this release.
SDK-92901	1023462	88670_A0 88670_B0	When setting <code>itmh_programmable_mode_enable=0</code> and <code>itmh_arad_mode_enable=1</code> on BCM88670, Arad-format ITMH header is now parsed properly.
SDK-93012	1022525	88650_B1	Actions setup for Arad is now operational (Could fail depending on random value on stack). Could fail in <code>bcm_field_group_action_set()</code>

Table 44:

Number	CSP	Chips	Release Notes For 6.4.11
SDK-93253		88670_A0	When setting <code>ilkn_tdm_dedicated_queueing=1</code> soc property device fails during init. Fixed

Section 10: Unresolved Issues for 6.4.11

The following open Urgent priority issues are unresolved in version 6.4.11 of the SDK.

Table 45:

Number	CSP	Chips
SDK-81696	957889	56960_A0
SDK-87026	992730	56960_A0 56960_B0
SDK-88872	1003096	56860_A0 56860_A1
SDK-89832	1006412	56860_A0 56860_A1
SDK-90885	1008608	56340_A0
SDK-92245	1009233	56260_A0 56260_B0
SDK-92356	1020879	88660_A0
SDK-92983	1026411	AllChips

Section 11: Device and Platform Support

The section describes all devices, platforms, and operating systems that are supported by this release.

SWITCH DEVICES

Table 46: Switch Devices

Family	Devices	Description
BCM5389	BCM5389 A0	8-Port GbE Switch with Integrated SerDes
	BCM5389 A1	8-Port GbE Switch with Integrated SerDes
BCM5396	BCM5396 A0	16-Port GbE Switch with Integrated SerDes
BCM53010	BCM53010 A0	5-Port Gigabit Ethernet Managed Switch integrated with single core ARM Cortex-A9 processor
	BCM53010 A2	
	BCM53011 A0	5-Port Gigabit Ethernet Managed Switch integrated with dual cores ARM Cortex-A9 processor
	BCM53011 A2	
	BCM53012 A0	5-Port Gigabit Ethernet Managed Switch with one RGMII I/F integrated with dual cores ARM Cortex-A9 processor
	BCM53012 A2	
BCM53018	BCM53017 A0	2-Port Gigabit Ethernet Managed Switch with one RGMII I/F integrated with dual cores ARM Cortex-A9 processor
	BCM53018 A0	5-Port Gigabit Ethernet Managed Switch with one RGMII I/F integrated with dual cores ARM Cortex-A9 processor
	BCM53019 A0	5-Port Gigabit Ethernet Managed Switch integrated with dual cores ARM Cortex-A9 processor
BCM53020	BCM58522 A0	5-Port Gigabit Ethernet Managed Switch integrated with 2 PHYs, ARM Cortex-A9 processor and macsec cores
	BCM58525 A0	5-Port Gigabit Ethernet Managed Switch integrated with 2 PHYs, SGMII I/F, ARM Cortex-A9 processor and macsec cores
	BCM58622 A0	8-Port Gigabit Ethernet Managed Switch integrated with 5 PHYs, ARM Cortex-A9 processor and macsec cores
	BCM58623 A0	8-Port Gigabit Ethernet Managed Switch integrated with 5 PHYs, ARM Cortex-A9 processor and macsec cores
	BCM58625 A0	8-Port Gigabit Ethernet Managed Switch integrated with 5 PHYs, SGMII I/F, ARM Cortex-A9 processor and macsec cores
BCM53101	BCM53101 A0	5-Port Fast Ethernet Managed Switch + 1 Fast Ethernet WAN port
	BCM53101 B0	
BCM53115	BCM53115 A0	5-Port GbE Managed Switch + 1 Gigabit WAN port with integrated SerDes
	BCM53115 A1	
	BCM53115 B0	
	BCM53115 B1	
	BCM53115 C0	
BCM53118	BCM53118 A0	8-Port Gigabit Ethernet Switch
	BCM53118 B0	

Table 46: Switch Devices

Family	Devices	Description
	BCM53118 B1	
BCM53125	BCM53125 A0	5-Port Gigabit Ethernet Switch with 1 Gigabit WAN port and 8051 processor
	BCM53125 B0	
BCM53128	BCM53128 A0	8-Port Gigabit Ethernet Switch with embedded 8051 processor
	BCM53128 B0	
BCM53242	BCM53242 A0	Managed Switch with 24 FE Ports + 2 GbE Interface
	BCM53242 B0	
	BCM53242 B1	
	BCM53262 A0	Managed Switch with 24 FE Ports + 4 GbE Interface
	BCM53262 B0	
	BCM53262 B1	
BCM53280	BCM53282 A0	8-Port Fast Ethernet + 2-Port Gigabit Ethernet Multilayer Switch
	BCM53282 B0	
	BCM53282 B1	
	BCM53282 B2	
	BCM53283 A0	16-Port Fast Ethernet + 2-Port Gigabit Ethernet Multilayer Switch
	BCM53283 B0	
	BCM53283 B1	
	BCM53283 B2	
	BCM53284 A0	24-Port Fast Ethernet + 2-Port Gigabit Ethernet Multilayer Switch
	BCM53284 B0	
	BCM53284 B1	
	BCM53284 B2	
	BCM53286 A0	24-Port Fast Ethernet + 4-Port Gigabit Ethernet Multilayer Switch
	BCM53286 B0	
	BCM53286 B1	
	BCM53286 B2	
	BCM53288 A0	24-Port Fast Ethernet + 2-Port Gigabit Ethernet Multilayer Switch with one 2.5GbE Uplink Port
	BCM53288 B0	
	BCM53288 B1	
	BCM53288 B2	
BCM53300	BCM53300 A0	Managed 24-port L2 Switch
	BCM53300 A1	
	BCM53301 A0	Managed 16-port L2 Switch
	BCM53301 A1	
	BCM53302 A0	Managed 24-port L2 Switch
	BCM53302 A1	
BCM53310	BCM53312 A0	BCM53312 Integrated Multilayer Switch and CPU
	BCM53312 B0	
	BCM53313 A0	BCM53313 Integrated Multilayer Switch and CPU
	BCM53313 B0	

Table 46: Switch Devices

Family	Devices	Description
	BCM53314 A0	BCM53314 Integrated Multilayer Switch and CPU
	BCM53314 B0	
BCM53320	BCM53322 A0	BCM53322 Integrated Multilayer Switch and CPU
	BCM53323 A0	BCM53323 Integrated Multilayer Switch and CPU
	BCM53324 A0	BCM53324 Integrated Multilayer Switch and CPU
BCM53400	BCM53365 A0	16-port 1GbE/2.5GbE/10GbE Multilayer Ethernet Switch
BCM53400	BCM53402 A0	8 x 1G/2.5G/5G/10G
BCM53400	BCM53405 A0	16-port 10GbE Multilayer Ethernet Switch
	BCM53406 A0	12-port 10GbE plus 8-port 2.5GbE and 4-port 5GbE/2.5GbE Multilayer Ethernet Switch
	BCM53412 A0	8 x 1G/2.5G/5G/10G
	BCM53415 A0	16-port 10GbE Multilayer Ethernet Switch with integrated CPU
	BCM53416 A0	12-port 10GbE plus 8-port 2.5GbE and 4-port 5GbE/2.5GbE Ethernet Switch with integrated CPU
	BCM53422 A0	8 x 1G + 2 x 1G/2.5G/5G/10G
	BCM53424 A0	4 x QSGMII + 8 x 1G + 4 x 1G/2.5G/5G/10G (option1)
	BCM53424 A0	4 x QSGMII + 8 x 1G + 2 x 10G + 2 x HiGigDuo[13] (option2)
	BCM53424 A0	2 x QSGMII + 16x1G + 4 x 1G/2.5G/5G/10G (option3)
	BCM53426 A0	20 x 1G + 4 x 1G/2.5G/5G/10G
	BCM53454 A0	20 x 1G/2.5G + 4 x 1G/2.5G/5G/10G
	BCM53455 A0	20 x 1G/2.5G + 4 x 1G/2.5G/5G/10G with embedded ARM A9 processor
	BCM53456 A0	4 x QSGMII + 8 x 1G/2.5G + 4 x 1G/2.5G/5G/10G (option1)
	BCM53456 A0	4 x QSGMII + 8 x 1G/2.5G + 2 x 10G + 2 x HiGigDuo[13] (option2)
	BCM53456 A0	2 x QSGMII + 16 x 1G/2.5G + 4 x 1G/2.5G/5G/10G (option3)
	BCM53457 A0	4 x QSGMII + 8 x 1G/2.5G + 4 x 1G/2.5G/5G/10G with ARM A9 (option1)
	BCM53457 A0	4 x QSGMII + 8 x 1G/2.5G + 2 x 10G + 2 x HiGigDuo[13] with ARM A9 (option2)
	BCM53457 A0	2 x QSGMII + 16 x 1G/2.5G + 4 x 1G/2.5G/5G/10G with ARM A9 (option3)
BCM53600	BCM53602 A0	8-Port Fast Ethernet + 3-Port Gigabit Ethernet Switch with one 1/2G-EPON ONU MAC/SerDes and embedded 600MHz MIPS32 74K processor
	BCM53603 A0	16-Port Fast Ethernet + 3-Port Gigabit Ethernet Switch with one 1/2G-EPON ONU MAC/SerDes and embedded 600MHz MIPS32 74K processor
	BCM53604 A0	24-Port Fast Ethernet + 3-Port Gigabit Ethernet Switch with one 1/2G-EPON ONU MAC/SerDes and embedded 600MHz MIPS32 74K processor
	BCM53606 A0	24-Port FE with S3MII interface + 3-Port Gigabit Ethernet Switch with one 1/2G-EPON ONU MAC/SerDes and embedded 600MHz MIPS32 74K processor
BCM89500	BCM89500 A0	4-Port Integrated Dedicated BRPHY + 3-Port Gigabit Ethernet Switch with embedded ARM processor
	BCM89500 B0	
BCM89500	BCM89501 A0	4-Port Integrated Dedicated BRPHY + 1-Port Integrated Dual-Mode BRPHY + 2-Port Gigabit Ethernet Switch with embedded ARM processor
	BCM89501 B0	
BCM89500	BCM89200 A0	1-Port Integrated Dedicated BRPHY + 1-Port Integrated Dual-Mode BRPHY + 2-Port Gigabit Ethernet Switch with embedded ARM processor
	BCM89200 B0	
BCM53710	BCM53714 A0	BCM56714 Integrated Multilayer Switch and CPU
	BCM53714 A1	

Table 46: Switch Devices

Family	Devices	Description
	BCM53714 A2	
	BCM53716 A0	BCM56716 Integrated Multilayer Switch and CPU
	BCM53716 A1	
	BCM53716 A2	
	BCM53718 A0	BCM56718 Integrated Multilayer Switch and CPU
	BCM53718 A1	
	BCM53718 A2	
BCM53720	BCM53724 A0	Managed 24-port L2 Switch with Integrated CPU
	BCM53724 B0	
	BCM53726 A0	Managed 24-port L2 Switch with Integrated CPU
	BCM53726 B0	
BCM56010	BCM56014 A0	24-Port Integrated Multilayer Switch and CPU
	BCM56014 A1	
	BCM56014 A2	
	BCM56018 A0	48-Port Integrated Multilayer Switch and CPU
	BCM56018 A1	
	BCM56018 A2	
	BCM56018 A1	48-Port Integrated Multilayer Switch and CPU
BCM56020	BCM56024 A0	24-Port Integrated Multilayer Switch and CPU
	BCM56024 B0	
	BCM56025 A0	24-Port Integrated L2 Switch and CPU
	BCM56025 B0	
	BCM56026 A0	24-Port Integrated L2 Switch and CPU
	BCM56026 B0	
BCM56060	BCM56060 A0	16-port 10GbE Multilayer Ethernet Switch with integrated CPU
BCM56060	BCM56062 A0	2 x QSGMII + 16 x 1G/2.5G + 4 x 1G/2.5G/5G/10G (option1)
	BCM56062 A0	2 x QSGMII + 8 x 1G/2.5G + 2 x XAUI + 4 x 1G/2.5G/5G/10G (option2)
	BCM56062 A0	2 x QSGMII + 16 x 1G/2.5G + 4 x 1G/2.5G/5G/10G (option3)
	BCM56063 A0	16-port 1GbE (QSGMII) plus 4-port 1G/2.5G/5G/10G (XFI) Multilayer Switch with integrated CPU
	BCM56064 A0	24-port GbE (4xQSGMII, 8xSGMII) plus 4-port 10GbE Multilayer Managed Switch with HiGig Uplinks and integrated CPU
	BCM56064 A0	4 x QSGMII, 8 x 1GbE, 4 x 10GbE (option1)
	BCM56064 A0	4 x QSGMII, 8 x 1GbE, 2 x 10GbE, 2 x HiGigDuo[13] (option2)
	BCM56065 A0	12 x 1G/2.5G/5G/10G + 12 x 1G/2.5G
BCM56100	BCM56100 A0	24-Port Fast Ethernet and 2-Port Gigabit Ethernet Multilayer Switch
	BCM56100 A1	
	BCM56101 A0	24-Port Fast Ethernet and 2-Port Gigabit Ethernet Multilayer Switch with One 10-Gigabit Ethernet/HiGig Port
	BCM56101 A1	
	BCM56102 A0	24-Port Fast Ethernet and 2-Port Gigabit Ethernet Multilayer Switch with Two 10-Gigabit Ethernet/HiGig Ports
	BCM56102 A1	
	BCM56105 A0	24-Port Fast Ethernet and 2-Port Gigabit Ethernet Layer 2 Switch

Table 46: Switch Devices

Family	Devices	Description
	BCM56105 A1	
	BCM56106 A0	24-Port Fast Ethernet and 2-Port Gigabit Ethernet Layer 2 Switch with One 10-Gigabit Ethernet/HiGig Port
	BCM56106 A1	
	BCM56107 A0	24-Port Fast Ethernet and 2-Port Gigabit Ethernet Layer 2 Switch with Two 10-Gigabit Ethernet/HiGig Ports
	BCM56107 A1	
BCM56110	BCM56110 A0	24-Port Fast Ethernet and 2-Port Gigabit Ethernet Multilayer Switch
	BCM56111 A0	24-Port Fast Ethernet and 2-Port Gigabit Ethernet Multilayer Switch with One 10-Gigabit Ethernet/HiGig Port
	BCM56112 A0	24-Port Fast Ethernet and 2-Port Gigabit Ethernet Multilayer Switch with Two 10-Gigabit Ethernet/HiGig Ports
	BCM56115 A0	24-Port Fast Ethernet and 2-Port Gigabit Ethernet Layer 2 Switch
	BCM56116 A0	24-Port Fast Ethernet and 2-Port Gigabit Ethernet Layer 2 Switch with One 10-Gigabit Ethernet/HiGig Port
	BCM56117 A0	24-Port Fast Ethernet and 2-Port Gigabit Ethernet Layer 2 Switch with Two 10-Gigabit Ethernet/HiGig Ports
BCM56130	BCM56132 A0	24-Port Fast Ethernet Multilayer Switch with Two 10-GbE/HiGig2 and Two 1G/2.5Gb Uplink Ports
	BCM56132 B0	
	BCM56132 B1	
	BCM56134 A0	24-Port Fast Ethernet Multilayer Switch with four 1G/2.5Gb Uplink Ports
	BCM56134 B0	
	BCM56134 B1	
BCM56140	BCM56140 A0	24-Port Gigabit Ethernet/6-Port SGMII GbE Multilayer switch with combination of two/four 1G/2.5/HiGig2 Uplink Ports
	BCM56142 A0	24-Port Gigabit Ethernet Multilayer switch with combination of two/four 1G/2.5/HiGig2 Uplink Ports
	BCM56143 A0	24-Port Gigabit Ethernet Multilayer switch with combination of two/four 1G/2.5/HiGig2 Uplink Ports
	BCM56144 A0	16-Port Gigabit Ethernet Multilayer switch with four 1G/2.5HG Uplink Ports
	BCM56146 A0	24-Port Fast-Ethernet Multilayer switch with four 2.5HG Uplink Ports
	BCM56147 A0	24-Port Fast-Ethernet Multilayer switch with combination of one/two/four 1G/2.5G/10/12/13HG Uplink Ports
BCM56150	BCM56150 A0	24-port GbE Managed Switch with 4-port 10 GbE uplinks, integrated CPU and 16 copper PHYs
	BCM56151 A0	24-port GbE Managed Switch with 4-port 10 GbE uplinks, integrated CPU (without PHYs)
	BCM56152 A0	24-port GbE plus 2-port GbE and 2-port 1GbE/13GbE uplinks Managed Switch, integrated CPU and 16 copper PHYs
	BCM53342 A0	8-port GbE Multilayer WebSmart Switch with Integrated CPU and Copper PHYs
	BCM53343 A0	16-port GbE plus 4-port GbE uplinks Multilayer WebSmart Switch with Integrated CPU and 16 Copper PHYs
	BCM53344 A0	24-port GbE plus 2-port GbE and 2-port 1GbE/13GbE uplinks WebSmart Switch, integrated CPU and 16 copper PHYs
	BCM53346 A0	24-port GbE Multilayer WebSmart Switch with 4-port 10 GbE uplinks, integrated CPU and 16 copper PHYs
	BCM53347 A0	24-port GbE Multilayer WebSmart Switch with 6xQSGMII + 4x1/10G
	BCM53393 A0	14-port GbE Multilayer Embedded Switch with integrated CPU (without PHY)

Table 46: Switch Devices

Family	Devices	Description
	BCM53394 A0	10-port GbE Multilayer Embedded Switch with 4-port 10 GbE uplinks, integrated CPU (without PHY)
BCM56210	BCM56212 A0	
	BCM56212 A1	
	BCM56212 A2	
	BCM56213 A0	
	BCM56213 A1	
	BCM56213 A2	
	BCM56214 A0	BCM56214 Integrated Multilayer Switch and CPU
	BCM56214 A1	
	BCM56214 A2	
	BCM56215 A0	
	BCM56215 A1	
	BCM56215 A2	
	BCM56216 A0	BCM56216 Integrated Multilayer Switch and CPU
	BCM56216 A1	
	BCM56216 A2	
	BCM56217 A0	
	BCM56217 A1	
	BCM56217 A2	
	BCM56218 A0	BCM56218 Integrated Multilayer Switch and CPU
	BCM56218 A1	
	BCM56218 A2	
	BCM56219 A0	BCM56219 Integrated Multilayer Switch and CPU
	BCM56219 A1	
	BCM56219 A2	
BCM56220	BCM56224 A0	24 GbE + 4 x 1 Gb/2.5 Gb, L3/L2+
	BCM56224 B0	24 GbE + 4 x 1 Gb/2.5 Gb, L3/L2+
	BCM56225 A0	24 GbE + 4 x 1 Gb/2.5 Gb, L2+
	BCM56225 B0	24 GbE + 4 x 1 Gb/2.5 Gb, L2+
	BCM56226 A0	16 GbE + 4 x 1 Gb/2.5 Gb, L3/L2+
	BCM56226 B0	16 GbE + 4 x 1 Gb/2.5 Gb, L3/L2+
	BCM56227 A0	16 GbE + 4 x 1 Gb/2.5 Gb, L2+
	BCM56227 B0	16 GbE + 4 x 1 Gb/2.5 Gb, L2+
	BCM56228 A0	8 GbE + 4 x 1 Gb/2.5 Gb, L3/L2+
	BCM56228 B0	8 GbE + 4 x 1 Gb/2.5 Gb, L3/L2+
	BCM56229 A0	8 GbE + 4 x 1 Gb/2.5 Gb, L2+
	BCM56229 B0	8 GbE + 4 x 1 Gb/2.5 Gb, L2+
BCM56230	BCM56230 B1	12-Port GbE Multilayer Switch
	BCM56231 B1	6-Port GbE Multilayer Switch
BCM56260	BCM56233 B0	4xGE UNI + 2xGE NNI + 2.5GE to FPGA
BCM56260	BCM56260 A0	50 Gbps Integrated Lower Power Carrier Ethernet Access Switch

Table 46: Switch Devices

Family	Devices	Description
	BCM56262 A0	20 Gbps Integrated Lower Power Carrier Ethernet Access Switch
	BCM56263 A0	12x 1GbE Port Integrated Low-Power Carrier Ethernet Access Switch with 4x 1GbE Uplinks, Stacking, additional external packet buffer, and Integrated CPU
	BCM56265 A0	52 Gbps Integrated Lower Power Carrier Ethernet Access Switch without external packet buffer
	BCM56267 A0	20 Gbps Integrated Lower Power Carrier Ethernet Access Switch without external packet buffer
	BCM56268 A0	16 Gbps Integrated Lower Power Carrier Ethernet Access without external packet buffer
	BCM56260 B0	52 Gbps Integrated Lower Power Carrier Ethernet Access Switch
	BCM56262 B0	20 Gbps Integrated Lower Power Carrier Ethernet Access Switch
	BCM56263 B0	12x 1GbE Port Integrated Low-Power Carrier Ethernet Access Switch with 4x 1GbE Uplinks, Stacking, additional external packet buffer, and Integrated CPU
	BCM56265 B0	52 Gbps Integrated Lower Power Carrier Ethernet Access Switch without external packet buffer
	BCM56267 B0	20 Gbps Integrated Lower Power Carrier Ethernet Access Switch without external packet buffer
	BCM56268 B0	16 Gbps Integrated Lower Power Carrier Ethernet Access without external packet buffer
BCM56260	BCM56460 A0	24-Port 1GbE Multilayer Switch with Four 10GbE/HiGig Uplinks
	BCM56461 A0	24-Port 1GbE Multilayer Switch with Four 10GbE/HiGig Uplinks without iHost support
	BCM56463 A0	34 Gbps Throughput Integrated Low-Power Carrier Ethernet Access Switch
	BCM56465 A0	24-Port 1GbE Multilayer Switch with Four 10GbE/HiGig Uplinks without external packet buffer
	BCM56466 A0	24x 1GbE Port Integrated Low-Power Carrier Ethernet Access Switch with 4x 10GbE/HGs[11] Uplinks and Stacking
	BCM56468 A0	34 Gbps Throughput Integrated Low-Power Carrier Ethernet Access Switch without external packet buffer
	BCM56460 B0	24-Port 1GbE Multilayer Switch with Four 10GbE/HiGig Uplinks
	BCM56461 B0	24-Port 1GbE Multilayer Switch with Four 10GbE/HiGig Uplinks without iHost support
	BCM56463 B0	34 Gbps Throughput Integrated Low-Power Carrier Ethernet Access Switch
	BCM56465 B0	24-Port 1GbE Multilayer Switch with Four 10GbE/HiGig Uplinks without external packet buffer
BCM56300	BCM56466 B0	24x 1GbE Port Integrated Low-Power Carrier Ethernet Access Switch with 4x 10GbE/HGs[11] Uplinks and Stacking
	BCM56300 A0	24-Port Gigabit Ethernet Multilayer Switch
	BCM56300 A1	
	BCM56300 B0	
	BCM56300 B1	
	BCM56301 A0	Four 10-Gigabit Ethernet/HiGig+ Ports
	BCM56301 A1	
	BCM56301 B0	
	BCM56301 B1	
	BCM56302 A0	24-Port Gigabit Ethernet Multilayer Switch with Two 10-Gigabit Ethernet/HiGig+ Ports
	BCM56302 A1	
	BCM56302 B0	
	BCM56302 B1	

Table 46: Switch Devices

Family	Devices	Description
	BCM56303 A0	24-Port Gigabit Ethernet Multilayer Switch with Three 10 Gigabit Ethernet/HiGig+ Ports
	BCM56303 A1	
	BCM56303 B0	
	BCM56303 B1	
	BCM56304 A0	24-Port Gigabit Ethernet Multilayer Switch with Four 10-Gigabit Ethernet/HiGig+ Ports
	BCM56304 A1	
	BCM56304 B0	
	BCM56304 B1	
	BCM56305 A0	24-Port Gigabit Ethernet Multilayer Switch
	BCM56305 A1	
	BCM56305 B0	
	BCM56305 B1	
	BCM56306 A0	16 Port Gigabit Ethernet Switch
	BCM56306 A1	
	BCM56306 B0	
	BCM56306 B1	
	BCM56307 A0	24-Port GE L2 Switch with Two 10 GE/HiGig+ Ports
	BCM56307 A1	
	BCM56307 B0	
	BCM56307 B1	
	BCM56308 A0	24-Port GE L2 Switch with Three 10 GE/HiGig+ Ports
	BCM56308 A1	
	BCM56308 B0	
	BCM56308 B1	
	BCM56309 A0	24-Port GE L2 Switch with Four 10 GE/HiGig+ Ports
	BCM56309 A1	
	BCM56309 B0	
	BCM56309 B1	
BCM56310	BCM56310 A0	BCM56310 Series 24-Port GbE Multilayer Switch with Four 10-GbE/HiGig+ Uplink Ports
	BCM56311 A0	Four 10-Gigabit Ethernet/HiGig+ Ports
	BCM56312 A0	24-Port Gigabit Ethernet Multilayer Switch with Two 10-Gigabit Ethernet/HiGig+ Ports
	BCM56313 A0	24-Port Gigabit Ethernet Multilayer Switch with Three 10-Gigabit Ethernet/HiGig+ Ports
	BCM56314 A0	24-Port Gigabit Ethernet Multilayer Switch with Four 10-Gigabit Ethernet/HiGig+ Ports
	BCM56315 A0	BCM56310 Series 24-Port GbE Layer 2 Switch with Four 10-GbE/HiGig+ Uplink Ports
	BCM56316 A0	Four 10-Gigabit Ethernet/HiGig+ Ports
	BCM56317 A0	24-Port Gigabit Ethernet Layer 2 Switch with Two 10-Gigabit Ethernet/HiGig+ Ports

Table 46: Switch Devices

Family	Devices	Description
	BCM56318 A0	24-Port Gigabit Ethernet Layer 2 Switch with Three 10-Gigabit Ethernet/HiGig+ Ports
	BCM56319 A0	24-Port Gigabit Ethernet Layer 2 Switch with Four 10-Gigabit Ethernet/HiGig+ Ports
BCM56320	BCM56320 A0	24-Port GbE Multilayer Switch with Four 10-GbE/HiGig2 Uplink Ports
	BCM56320 B0	
	BCM56320 B1	
	BCM56321 A0	24-Port GbE Multilayer Switch with Four 10-GbE/HiGig2 Uplink Ports
	BCM56321 B0	
	BCM56321 B1	
BCM56330	BCM56331 A0	24-Port GbE Multilayer Switch with Four 2.5GbE Uplink Ports
	BCM56331 B0	
	BCM56331 B1	
	BCM56333 A0	16-Port GbE Multilayer Switch
	BCM56333 B0	
	BCM56333 B1	
	BCM56334 A0	24-Port GbE Multilayer Switch with Four 10-GbE/HiGig2 Uplink Ports
	BCM56334 B0	
	BCM56334 B1	
	BCM56338 A0	8-Port GbE Multilayer Switch with two 10-GbE/HiGig2 Uplink Ports
	BCM56338 B0	
	BCM56338 B1	
BCM56340	BCM56040 A0	1xF.QSGMII + 3xF.HG[42] + 1GE
	BCM56041 A0	BCM56040 device, meant for embedded connectivity supports 1Ge (port 49), 2 X GE (iPROC), Flex 4x10G, 3 X 4 X 10G
	BCM56042 A0	12x2.5GE/1GE + 12x2.5GE/1GE + 1GE
	BCM56340 A0	12xF.QSGMII + Flex[4x10] + 2xHG[21] + 1GE, 12xF.QSGMII + 4xSGMII + 2xXFI + 2xHGd[21] + 1GE
	BCM56342 A0	7xF.QSGMII + Flex[4x10] + 2xHG[21] + 1GE
	BCM56344 A0	10xF.QSGMII + 3xFlex[4x10] + 1GE
BCM56340	BCM56547 A0	10xF.QSGMII + 3xF.HG[42] + 1GE, 12xF.QSGMII + 2xF.HG[42] + 1GE, 12xF.QSGMII + F.HG[42] + 2xHG[42] + 1GE
BCM56340	BCM56548 A0	7xF.QSGMII + 3xF.HG[42] + 1GE
	BCM56548H A0	5xF.QSGMII + Flex[4x10] + 2xHGd[21]/4xHG[11/10] + 2xHGd[21]/4xHG[11/10] + 1GE
BCM56440	BCM56440 A0	24-Port GbE Multilayer Switch with Four 10-GbE/Hig2 Uplink ports
	BCM56440 B0	
	BCM56441 A0	8-Port GbE Multilayer Switch with Two 10-GbE/Hig2 Uplink ports
	BCM56441 B0	
	BCM56442 A0	16-Port GbE Multilayer Switch
	BCM56442 B0	
	BCM56443 A0	8-Port 2.5GbE Multilayer Switch with Two 10-GbE/Hig2 Uplink ports
	BCM56443 B0	
	BCM56445 A0	24-Port GbE Multilayer Switch with Four 10-GbE/Hig2 Uplink ports pin compatible with BCM56334

Table 46: Switch Devices

Family	Devices	Description
	BCM56445 B0	
	BCM56446 A0	8-Port GbE Multilayer Switch with Two 10-GbE/HiG2 Uplink ports pin compatible with BCM56338
	BCM56447 A0	16-Port GbE Multilayer Switch pin compatible with BCM56333
	BCM56447 B0	
	BCM56448 A0	24-Port GbE Multilayer Switch with Four 1GbE/ One 2.5G Uplink ports
	BCM56448 B0	
BCM56450	BCM56248L B0	11xGE + 8x2.5G
BCM56450	BCM56450 A0	24-port GbE Multilayer Switch with 4-port 10 GbE uplinks, stacking, integrated CPU and Traffic Manager
BCM56450	BCM56450 B0	BCM56450 Access 1 x XAUI + 8 x GE without L3 routing and MPLS features
BCM56450	BCM56450 B0	BCM56450 Access-8 FX + 2 F-HG
BCM56450	BCM56450 B1	24-port GbE Multilayer Switch with 4-port 10 GbE uplinks, stacking, integrated CPU and Traffic Manager
BCM56450	BCM56452 B0	24xGE + 4xF.XAUI
BCM56450	BCM56454 B0	8xGE + 2 x F.XAUI
	BCM56455 A0	2 x 20GE (G.INT) + 2 x HG13
	BCM56455 B0	2 x 20GE (G.INT) + 2 x HG13
BCM56450	BCM56456 A0	24x GE + 4x F.XAUI
BCM56450	BCM56456 B0	24x GE + 4x F.XAUI
	BCM56456 B0	1 x XAUI + 8 x GE
BCM56456	BCM56456 B0	9xFXAUI + 1 x XAUI + 1x2.5GbE
BCM56456	BCM56458 B0	8xGE + 2xF.XAUI
BCM56460	BCM56460 A0	24-Port 1GbE Multilayer Switch with Four 10GbE/HiGig Uplink
	BCM56461 A0	24 x GE + 4 x HGs11
BCM56500	BCM56500 A0	24-Port Gigabit Ethernet Multilayer Switch
	BCM56500 A1	
	BCM56500 B0	
	BCM56500 B1	
	BCM56500 B2	
	BCM56501 A0	Four 10-Gigabit Ethernet/HiGig+ Ports
	BCM56501 A1	
	BCM56501 B0	
	BCM56501 B1	
	BCM56501 B2	
	BCM56502 A0	24-Port GbE Multilayer Switch with Two 10-GbE/HiGig+ Ports
	BCM56502 A1	
	BCM56502 B0	
	BCM56502 B1	
	BCM56502 B2	
	BCM56503 A0	24-Port GbE Multilayer Switch with Three 10-GbE/HiGig+ Ports
	BCM56503 A1	
	BCM56503 B0	
	BCM56503 B1	

Table 46: Switch Devices

Family	Devices	Description
	BCM56503 B2	
	BCM56504 A0	24-Port GbE Multilayer Switch with Four 10-GbE/HiGig+ Ports
	BCM56504 A1	
	BCM56504 B0	
	BCM56504 B1	
	BCM56504 B2	
	BCM56505 A0	24-Port GbE Layer 2 Switch
	BCM56505 A1	
	BCM56505 B0	
	BCM56505 B1	
	BCM56505 B2	
	BCM56506 A0	Four 10-Gigabit Ethernet/HiGig+ Ports
	BCM56506 A1	
	BCM56506 B0	
	BCM56506 B1	
	BCM56506 B2	
	BCM56507 A0	24-Port GbE Layer 2 Switch with Two 10-GbE/HiGig+ Ports
	BCM56507 A1	
	BCM56507 B0	
	BCM56507 B1	
	BCM56507 B2	
	BCM56508 A0	24-Port GbE Layer 2 Switch with Three 10-GbE/HiGig+ Ports
	BCM56508 A1	
	BCM56508 B0	
	BCM56508 B1	
	BCM56508 B2	
	BCM56509 A0	24-Port GbE Layer 2 Switch with Four 10-GbE/HiGig+ Ports
	BCM56509 A1	
	BCM56509 B0	
	BCM56509 B1	
	BCM56509 B2	
BCM56510	BCM56510 A0	24-Port Gigabit Ethernet Multilayer Switch
	BCM56511 A0	Four-Port 10-GbE/HiGig+ Multilayer Switch
	BCM56512 A0	24-Port GbE Multilayer Switch With Two 10-GbE/HiGig+ Ports
	BCM56513 A0	24-Port GbE Multilayer Switch With Three 10-GbE/HiGig+ Ports
	BCM56514 A0	24-Port GbE Multilayer Switch With Four 10-GbE/HiGig+ Ports
BCM56520	BCM56520 A0	24-Port GbE Multilayer Switch
	BCM56520 B0	
	BCM56522 A0	24-Port GbE Multilayer Switch with Two 10-GbE/HiGig2 Uplink Ports
	BCM56522 B0	
	BCM56524 A0	24-Port GbE Multilayer Switch with Four 10-GbE/HiGig2 Uplink Ports

Table 46: Switch Devices

Family	Devices	Description
	BCM56524 B0	
	BCM56526 A0	28-Port GbE Multilayer Switch with Six 10-GbE/HiGig2 Uplink Ports
	BCM56526 B0	
BCM56530	BCM56534 B0	24-Port GbE Multilayer Switch with Four 10-GbE/HiGig2 Uplink Ports
	BCM56538 B0	48-Port GbE Multilayer Switch with Four 10-GbE/HiGig2 Uplink Ports
BCM56540	BCM56540 A1	48xGE + 2xHG[42] + 2xHG[21] + 1GE, 48xGE + 4xXFI + 2xHG[42] + 1GE, 48xGE + 8xXFI + 1GE Multilayer Ethernet Switch
	BCM56540 B0	
	BCM56541 A1	28xGE + 2xHG[42] + 2xHG[21] + 1GE, 28xGE + 4xXFI + 2xHG[42] + 1GE, 28xGE + 8xXFI + 1GE Multilayer Ethernet Switch
	BCM56541 B0	
	BCM56542 A1	28xGE + 2xF.XAUI/2x10GE + 2xF.HG[42] + 2xF.HG[21] + 1GE, 28xGE + 8xGE/8x2.5GE + 2xHG[42] + 2xHG[21] + 1GE Multilayer Ethernet Switch
	BCM56544 A1	10xF.XAUI + 4xHG[21] + 1GE, 10xF.XAUI + 4xXFI, 10xF.XAUI + 2xHG[42], 4xXAUI + 12xXFI + 1GE Multilayer Ethernet Switch
	BCM56544 B0	10xF.XAUI + 4xHG[21] + 1GE, 10xF.XAUI + 4xXFI, 10xF.XAUI + 2xHG[42], 4xXAUI + 12xXFI + 1GE Multilayer Ethernet Switch
	BCM56545 A1	48xGE + 2xHG[42] + 2xHG[21] + 1GE, 48xGE + 4xXFI + 2xHG[42] + 1GE, 48xGE + 8xXFI + 1GE Multilayer Ethernet Switch
	BCM56545 B0	48xGE + 2xHG[42] + 2xHG[21] + 1GE, 48xGE + 4xXFI + 2xHG[42] + 1GE, 48xGE + 8xXFI + 1GE, 24xGE + 4xXAUI + 2xXFI + 2xHG[12] + 1GE Multilayer Ethernet Switch
	BCM56546 A1	28xGE + 2xHG[42] + 2xHG[21] + 1GE, 28xGE + 4xXFI + 2xHG[42] + 1GE, 28xGE + 8xXFI + 1GE Multilayer Ethernet Switch
	BCM56546 B0	28xGE + 2xHG[42] + 2xHG[21] + 1GE, 28xGE + 4xXFI + 2xHG[42] + 1GE, 28xGE + 8xXFI + 1GE Multilayer Ethernet Switch
BCM56580	BCM56580 A0	16 x 2.5 GbE + 4 x 10 GbE Ethernet Multilayer Switch
BCM56620	BCM56620 A0	
	BCM56620 A1	
	BCM56620 B0	
	BCM56620 B1	
	BCM56620 B2	
	BCM56624 A0	49 port 1-GbE Multilayer Ethernet Switch with 4 x 10-GbE/HiGig2 Uplink ports and External Table Expansion
	BCM56624 A1	
	BCM56624 B0	
	BCM56624 B1	
	BCM56624 B2	
	BCM56626 A0	25 port 1-GbE Multilayer Ethernet Switch with 6 x 10-GbE/HiGig2 Uplink ports and External Table Expansion
	BCM56626 A1	
	BCM56626 B0	
	BCM56626 B1	
	BCM56626 B2	
	BCM56628 A0	8 port 10-GbE/HiGig2 Multilayer Ethernet Switch with External Table Expansion
	BCM56628 A1	
	BCM56628 B0	

Table 46: Switch Devices

Family	Devices	Description
	BCM56628 B1	
	BCM56628 B2	
	BCM56629 B0	25 port 1-GbE Multilayer Ethernet Switch with 8 x 10-GbE/HiGig2 Uplink ports and External Table Expansion
	BCM56629 B1	
	BCM56629 B2	
BCM56630	BCM56630 A0	24-Port GbE Multilayer Switch with Four 10-GbE/HiGig2 Uplink Ports
	BCM56630 B0	
	BCM56634 A0	48-Port GbE Multilayer Switch with Four 10-GbE/HiGig2 Uplink Ports
	BCM56634 B0	
	BCM56636 A0	24-Port GbE + 2-Port 10-GbE Multilayer Switch with Four 10-GbE/HiGig2 Uplink Ports
	BCM56636 B0	
	BCM56638 A0	4-Port 10-GbE Multilayer Switch with Four 10-GbE/HiGig2 Uplink Ports
	BCM56638 B0	
	BCM56639 A0	24-Port GbE + 4-Port 10-GbE Multilayer Switch with Four 10-GbE/HiGig2 Uplink Ports
	BCM56639 B0	
BCM56640	BCM56044	BCM56044 SKU - 100G + 3xF.HG[42] + 1GE
BCM56640	BCM56045 B0	3xF.40GE + 3xF.HG[42] + 1GE
	BCM56046 B0	3xF.40GE + 2xF.HG[42] + 1GE
	BCM56640 A1	1x100GE + 1xHG[127], 1x100GE + 4xHG[32], 1x100GE + 8xHGd[16], 3xF.HG[42] + 1xHG[127], 3xF.HG[42] + 4xHG[32], 3xF.HG[42] + 8xHGd[16], 3xF.HG[42] + 3xF.HG[42] Multilayer Ethernet Switch
	BCM56640 B0	
	BCM56643 A1	48xGE + 4xXFI + 4xHG[42] + 1GE Multilayer Ethernet Switch
	BCM56643 B0	
	BCM56644 A1	48xGE + 2xHG[25] + 2xHG[25] + 1GE Multilayer Ethernet Switch
	BCM56644 B0	
	BCM56648 A1	48xGE + 2xHG[42] + 2xHG[21] + 1GE, 48xGE + 4xXFI + 2xHG[42] + 1GE, 48xGE + 8xXFI + 1GE Multilayer Ethernet Switch
	BCM56648 B0	
	BCM56649 A1	28xGE + 2xHG[42] + 2xHG[21] + 1GE, 28xGE + 4xXFI + 2xHG[42] + 1GE, 28xGE + 8xXFI + 1GE Multilayer Ethernet Switch
	BCM56649 B0	
BCM56640	BCM56545K	48-port GE switch + 4x10GE + 4xHG[42] / 40GE
BCM56640	BCM56546K	28-port GE switch + 4x10GE + 4xHG[42] / 40GE
BCM56680	BCM56680 A0	25 port 1-GbE/2.5GbE Multilayer Ethernet Switch with 4 x 10-GbE/HiGig2 Uplink ports
	BCM56680 A1	
	BCM56680 B0	
	BCM56680 B1	
	BCM56684 A0	24 port 1-GbE/2.5GbE Multilayer Ethernet Switch with 4 x 10-GbE/HiGig2 Uplink ports
	BCM56684 A1	
	BCM56684 B0	

Table 46: Switch Devices

Family	Devices	Description
	BCM56684 B1	
BCM56685	BCM56685 A0	24-Port GbE Multilayer Switch with Four 10-GbE/HiGig2 Uplink Ports
	BCM56685 B0	
	BCM56689 A0	24-Port GbE Multilayer Switch with Four 10-GbE/HiGig2 Uplink Ports
	BCM56689 B0	
BCM56700	BCM56700 A0	16-Port, 192-Gbps Lossless Switch Fabric
	BCM56701 A0	12-Port, 144-Gbps Lossless Switch Fabric
BCM56720	BCM56720 A0	16 Port, 16-Gbps HiGig2 Switch Fabric
	BCM56721 A0	12 Port, 16-Gbps HiGig2 Switch Fabric
BCM56725	BCM56725 A0	8 Port, 20-Gbps + 4 Port, 16-Gbps HiGig2 Switch Fabric
BCM56740	BCM56743 A0	480 Gbps Switch fabric
	BCM56743 A1	
	BCM56743 A2	
	BCM56743 A3	
	BCM56743 A4	
	BCM56743 B0	
	BCM56743 B1	
	BCM56745 A0	640 Gbps Switch fabric
	BCM56745 A1	
	BCM56745 A2	
	BCM56745 A3	
	BCM56745 A4	
	BCM56745 B0	
	BCM56745 B1	
BCM56740 PLUS	BCM56744 A0	480 Gbps Switch fabric
	BCM56744 A1	
	BCM56746 A0	640 Gbps Switch fabric
	BCM56746 A1	
BCM56800	BCM56800 A0	20-Port 10-Gigabit Ethernet Multilayer Switch
	BCM56801 A0	10-Port 10-Gigabit Ethernet and 8-Port HiGig2/10GbE Multilayer Switch
	BCM56802 A0	16-Port 10-GbE/HiGig2 Multilayer Switch
	BCM56803 A0	12 Port 10GE/HiGig2 Multilayer Switch
BCM56820	BCM56820 A0	24 x 10-GbE + 4 x 1-GbE Multilayer Ethernet Switch
	BCM56820 B0	
	BCM56821 A0	12 x 10-GbE + 8 x HiGig2 + 4 x 1-GbE Multilayer Ethernet Switch
	BCM56821 B0	
	BCM56822 A0	12 x 10-GbE + 4 x 20-Gbps HiGig2 + 4 x 1-GbE Multilayer Ethernet Switch
	BCM56822 B0	
	BCM56823 A0	8 x 10-GbE + 4 x 20-Gbps HiGig2 + 4 x 1-GbE Multilayer Ethernet Switch
	BCM56823 B0	
	BCM56825 B0	16 x 10-GbE + 8 x 20-Gbps HiGig2 + 1 x 1-GbE Multilayer Ethernet Switch
	BCM56743 A0	480 Gbps Switch fabric

Table 46: Switch Devices

Family	Devices	Description
	BCM56743 A1	
	BCM56743 A2	
	BCM56743 A3	
	BCM56743 A4	
	BCM56743 B0	
	BCM56743 B1	
	BCM56745 A0	640 Gbps Switch fabric
	BCM56745 A1	
	BCM56745 A2	
	BCM56745 A3	
	BCM56745 A4	
	BCM56745 B0	
	BCM56745 B1	
BCM56740 PLUS	BCM56744 A0	480 Gbps Switch fabric
	BCM56744 A1	
	BCM56746 A0	640 Gbps Switch fabric
	BCM56746 A1	
BCM56840	BCM56841 A0	320 Gbps Ethernet Multilayer Switch
	BCM56841 A1	
	BCM56841 A2	
	BCM56841 A3	
	BCM56841 A4	
	BCM56841 B0	
	BCM56841 B1	
	BCM56843 A0	480 Gbps Ethernet Multilayer Switch
	BCM56843 A1	
	BCM56843 A2	
	BCM56843 A3	
	BCM56843 A4	
	BCM56843 B0	
	BCM56843 B1	
	BCM56845 A0	640 Gbps Ethernet Multilayer Switch
	BCM56845 A1	
	BCM56845 A2	
	BCM56845 A3	
	BCM56845 A4	
	BCM56845 B0	
	BCM56845 B1	
BCM56840 PLUS	BCM56842 A0	320 Gbps Ethernet Multilayer Switch
	BCM56842 A1	
	BCM56844 A0	480 Gbps Ethernet Multilayer Switch

Table 46: Switch Devices

Family	Devices	Description
	BCM56844 A1	
	BCM56846 A0	640 Gbps Ethernet Multilayer Switch
	BCM56846 A1	
BCM56846	BCM56831	24-port 10GE switch with 40GE support for embedded applications
BCM56846	BCM56835C	(64 x 10 GbE) + (4 x 1 GbE)
BCM56846	BCM56847	(64 x 10 GbE) + (4 x 1 GbE)
BCM56846	BCM56849	(56 x 1GbE/2.5GbE) + (8 x 10GbE)
BCM56850	BCM56751P A1	1.28Tbps I/O, 960Gbps Core Ethernet Switch Fabric
BCM56850	BCM56751P A2	1.28Tbps I/O, 960Gbps Core Ethernet Switch Fabric
BCM56850	BCM56830 A1	960Gbps Ethernet Switch
BCM56850	BCM56830 A2	960Gbps Ethernet Switch
BCM56850	BCM56834	High density 10G and 40G switch for embedded applications
BCM56850	BCM56838	72/320G Devices with 1.25/3.125/6.25G SerDes and 4 SFIs
BCM56850	BCM56850 A1	1.28Tbps I/O, 1Tbps Core Ethernet Switch
	BCM56852 A2	100x10G, 960Gbps Multilayer Switch
	BCM56854 A1	
BCM56851	BCM56751 A2	1.28Tbps I/O, 960Gbps Core Ethernet Switch Fabric
BCM56860	BCM56860 A1	104x 10GbE/32x 40GbE/8x 100GbE Multilayer Switch
	BCM56861 A1	32 x 40GbE/104 x 10GbE Multilayer Switch
	BCM56862 A1	96 x 10GbE/24 x 40GbE/8 x 100 GbE Multilayer Switch
	BCM56864 A1	72 x 10GbE/18 x 40GbE Multilayer Switch
	BCM56865 A1	72 x 10GbE/18 x 40GbE/4 x 100GbE Multilayer Switch
	BCM56866 A1	104 x 10GbE/32 x 40GbE/8 x 100GbE Multilayer Switch
	BCM56867 A1	104x 10GbE/32x 40GbE/8x 100GbE Multilayer Switch
	BCM56868 A1	8 x HG127/32 x HG42
BCM56860	BCM56832 A1	27 x 20GbE
	BCM56833 A1	32 x 40GbE/104 x 10GbE
	BCM56836 A1	8 x 100GbE/32 x 10GbE/32 x 40GbE/104 x 10GbE
BCM56960	BCM56960 A0	32x100 GbE/64x40GbE/128x10 GbE Multilayer Switch
	BCM56960 B0	32x100 GbE/64x40GbE/128x10 GbE Multilayer Switch
	BCM56960 B1	32x100 GbE/64x40GbE/128x10 GbE Multilayer Switch
	BCM56961 A0	64x40GbE port configuration
	BCM56961 B1	64x40GbE port configuration
	BCM56962 B0	24x 100GbE/48x 40GbE Multilayer Switch
	BCM56962 B1	24x 100GbE/48x 40GbE Multilayer Switch
	BCM56963 B0	6x 100GbE + 48x 25GbE Multilayer Switch
	BCM56968 B0	32x HG[106]/64x HG[42] Multilayer Switch
	BCM56968 B1	32x HG[106]/64x HG[42] Multilayer Switch
	BCM56930 A0	130-Port RoHS-compliant, high-capacity, 3.2Tbps Switch device with 10/25/40/100G support.
	BCM56930 B0	130-Port RoHS-compliant, high-capacity, 3.2Tbps Switch device with 10/25/40/100G support.
	BCM56930 B1	130-Port RoHS-compliant, high-capacity, 3.2Tbps Switch device with 10/25/40/100G support.
BCM88732	BCM88732 B2	Eight-Port 10 GbE or 2-Port 40 GbE MAC Aggregation Switch with 80 Gbps Uplink Capacity

Table 46: Switch Devices

Family	Devices	Description
BCM88020	BCM88020 A0	XGS Core (XCore/SBX) Fully Programmable Carrier Packet Processor with 24 GbE Ports, 2 10GbE Ports and 2 SPI Interfaces
	BCM88020 A1	
	BCM88020 A2	
BCM88025	BCM88025 A0	XGS Core (XCore/SBX) Fully Programmable Carrier Packet Processor with 24 GbE Ports, 2 10GbE Ports and 2 SPI Interfaces
BCM88030	BCM88030 A0	XGS Core (XCore/SBX) Scalable Switching 100 Gbps Fully Programmable Carrier Packet Processor
BCM88130	BCM88130 A0	XGS Core (XCore/SBX) 630 Gbps Bandwidth Manager and Switching Engine
	BCM88130 A1	
BME-3200	BME-3200 A0	XGS Core (XCore/SBX) Fabric Bandwidth Manager with 32 SCI control ports and up to 40 SFI data ports
	BME-3200 B0	
QE-2000	QE-2000 A1	XGS Core (XCore/SBX) Fabric Queuing Engine with 49 SPI 4.2 subports
	QE-2000 A2	
	QE-2000 A3	
	QE-2000 A4	
BCM88230	BCM88230 A0	XGS Core (XCore/SBX) Fabric Queuing Engine with Integrated Traffic Management with 4 HiGig2 ports, 50Gbps
	BCM88230 B0	
	BCM88235 A0	XGS Core (XCore/SBX) Fabric Queuing Engine with Integrated Traffic Management with 4 HiGig2 ports, 80Gbps
	BCM88235 B0	
	BCM88231 A0	XGS Core (XCore/SBX) Traffic Manager with 4 HiGig2 ports, 50Gbps
	BCM88231 B0	
	BCM88236 A0	XGS Core (XCore/SBX) Traffic Manager with 4 HiGig2 ports, 80Gbps
	BCM88236 B0	
BCM56930	BCM56931 A0	XGS pass-through and standalone Traffic Manager, 4 HiGig2 ports, 50Gbps
	BCM56931 B0	
	BCM56936 A0	XGS pass-through and standalone Traffic Manager, 4 HiGig2 ports, 80Gbps
	BCM56936 B0	
BCM88640	BCM88640 A0	DNX 100G Flexible Packet Processor with Integrated Traffic Management
	BCM88640 B0	
BCM88650	BCM88650 A0	DNX 200G Flexible Packet Processor with Integrated Traffic Management
	BCM88650 B0	
	BCM88650 B1	200 Gbps DNX Traffic Manager and Packet Processor
BCM88660	BCM88660 A0	DNX 200G Flexible Packet Processor with Integrated Traffic Management
BCM88750	BCM88750 A0	DNX 1600 Gbps Switch Fabric
	BCM88750 B0	

PHYS

Table 47: PHYs

Device	Driver Family	Description	Quality Level
BCM5218	522x	10/100Base-TX/FX Octal-PHY(tm) Transceiver	Beta - with Legacy switches Prior to 534XX ; Bringup with 5686X, not supported with 5696X, 56930, 8867X, 8837X
BCM5220	522x	10/100BASE-TX/FX Mini-F(tm) Transceiver	Beta - with Legacy switches Prior to 534XX ; Bringup with 5686X, not supported with 5696X, 56930, 8867X, 8837X
BCM5221	522x	10/100BASE-TX/FX Mini-F(tm) Transceiver	Beta - with Legacy switches Prior to 534XX ; Bringup with 5686X, not supported with 5696X, 56930, 8867X, 8837X
BCM5226	522x	10/100 BASE- TX/FX Hex-PHY(tm) Transceiver	Beta - with Legacy switches Prior to 534XX ; Bringup with 5686X, not supported with 5696X, 56930, 8867X, 8837X
BCM5228	522x	10/100BASE-TX/FX Octal-F(tm) Transceiver	Beta - with Legacy switches Prior to 534XX ; Bringup with 5686X, not supported with 5696X, 56930, 8867X, 8837X
BCM5238	522x	10/100BASE-TX OCTAL-f(tm) Transceiver	Beta - with Legacy switches Prior to 534XX ; Bringup with 5686X, not supported with 5696X, 56930, 8867X, 8837X
BCM5248	522x	10/100BASE-TX Octal-F(tm) Transceiver	Beta - with Legacy switches Prior to 534XX ; Bringup with 5686X, not supported with 5696X, 56930, 8867X, 8837X
BCM52681E A1	54680	Octal 10/100 Ethernet Transceiver	Beta - with Legacy switches Prior to 534XX ; Bringup with 5686X, not supported with 5696X, 56930, 8867X, 8837X
BCM5401	5401	10/100/1000BASE-T Gigabit Copper Transceiver	Beta - with Legacy switches Prior to 534XX ; Bringup with 5686X, not supported with 5696X, 56930, 8867X, 8837X
BCM5402	5402	10/100/1000BASE-T Gigabit Copper Transceiver	Beta - with Legacy switches Prior to 534XX ; Bringup with 5686X, not supported with 5696X, 56930, 8867X, 8837X
BCM5404	5404	Quad-Port 10/100/1000BASE-T Gigabit Copper Transceiver	Beta - with Legacy switches Prior to 534XX ; Bringup with 5686X, not supported with 5696X, 56930, 8867X, 8837X
BCM5424	5424	Quad 10/100/1000BASE-T Gigabit Ethernet Transceiver	Beta - with Legacy switches Prior to 534XX ; Bringup with 5686X, not supported with 5696X, 56930, 8867X, 8837X
BCM5434	5424	Quad 10/100/1000BASE-T Gigabit Ethernet Transceiver	Beta - with Legacy switches Prior to 534XX ; Bringup with 5686X, not supported with 5696X, 56930, 8867X, 8837X
BCM5411	5411	10/100/1000BASE-T Gigabit Copper Transceiver	Beta - with Legacy switches Prior to 534XX ; Bringup with 5686X, not supported with 5696X, 56930, 8867X, 8837X
BCM5421	5421S	10/100/1000BASE-T Gigabit Copper Transceiver	Beta - with Legacy switches Prior to 534XX ; Bringup with 5686X, not supported with 5696X, 56930, 8867X, 8837X
BCM5421S	5421S	10/100/1000BASE-T Gigabit Copper Transceiver with SerDes	Beta - with Legacy switches Prior to 534XX ; Bringup with 5686X, not supported with 5696X, 56930, 8867X, 8837X
BCM5461	5464	10/100/1000BASE-T Gigabit Ethernet Transceiver	Beta - with Legacy switches Prior to 534XX ; Bringup with 5686X, not supported with 5696X, 56930, 8867X, 8837X
BCM5464	5464	Quad-Port 10/100/1000BASE-T Gigabit Copper Transceiver	Beta - with Legacy switches Prior to 534XX ; Bringup with 5686X, not supported with 5696X, 56930, 8867X, 8837X

Table 47: PHYs

Device	Driver Family	Description	Quality Level
BCM5464R	5464	Quad-Port 10/100/1000BASE-T Gigabit Copper Transceiver	Beta - with Legacy switches Prior to 534XX ; Bringup with 5686X, not supported with 5696X, 56930, 8867X, 8837X
BCM5464S	5464	Quad-Port Gigabit Copper Transceiver with Copper/Fiber Media Interface	Beta - with Legacy switches Prior to 534XX ; Bringup with 5686X, not supported with 5696X, 56930, 8867X, 8837X
BCM5464SR	5464	Quad-Port Gigabit Copper Transceiver with Copper/Fiber Media Interface	Beta - with Legacy switches Prior to 534XX ; Bringup with 5686X, not supported with 5696X, 56930, 8867X, 8837X
BCM5466	5464	Quad-Port 10/100/1000BASE-T Gigabit Copper Transceiver	Beta - with Legacy switches Prior to 534XX ; Bringup with 5686X, not supported with 5696X, 56930, 8867X, 8837X
BCM5466R	5464	Quad-Port 10/100/1000BASE-T Gigabit Copper Transceiver	Beta - with Legacy switches Prior to 534XX ; Bringup with 5686X, not supported with 5696X, 56930, 8867X, 8837X
BCM5466S	5464	Quad-Port Gigabit Copper Transceiver with Copper/Fiber Media Interface	Beta - with Legacy switches Prior to 534XX ; Bringup with 5686X, not supported with 5696X, 56930, 8867X, 8837X
BCM5466SR	5464	Quad-Port Gigabit Copper Transceiver with Copper/Fiber Media Interface	Beta - with Legacy switches Prior to 534XX ; Bringup with 5686X, not supported with 5696X, 56930, 8867X, 8837X
BCM5482	5482	Dual-Port 10/100/1000BASE-T Gigabit Ethernet Transceiver	Beta - with Legacy switches Prior to 534XX ; Bringup with 5686X, not supported with 5696X, 56930, 8867X, 8837X
BCM5488	5464	Octal 1000/100/10BASE-T Gigabit Ethernet Transceiver	Beta - with Legacy switches Prior to 534XX ; Bringup with 5686X, not supported with 5696X, 56930, 8867X, 8837X
BCM54210SE B0	54210	Single Copper/Fiber Gigabit Ethernet Transceiver. 1588 not yet supported	Beta - with Legacy switches Prior to 534XX ; Bringup with 5686X, not supported with 5696X, 56930, 8867X, 8837X
BCM54220SE B0	54220	Dual Copper/Fiber Gigabit Ethernet Transceiver. 1588 not yet supported	Beta - with Legacy switches Prior to 534XX ; Bringup with 5686X, not supported with 5696X, 56930, 8867X, 8837X
BCM54240 C0	54280	Quad 1000/100/10BASE-T Gigabit Ethernet Transceiver	Beta - with Legacy switches Prior to 534XX ; Bringup with 5686X, not supported with 5696X, 56930, 8867X, 8837X
BCM54240 C1	54280	Quad 1000/100/10BASE-T Gigabit Ethernet Transceiver	Beta - with Legacy switches Prior to 534XX ; Bringup with 5686X, not supported with 5696X, 56930, 8867X, 8837X
BCM54280 A0	54280	Octal 1000/100/10BASE-T Gigabit Ethernet Transceiver	Beta - with Legacy switches Prior to 534XX ; Bringup with 5686X, not supported with 5696X, 56930, 8867X, 8837X
BCM54280 C0	54280	Octal 1000/100/10BASE-T Gigabit Ethernet Transceiver	Beta - with Legacy switches Prior to 534XX ; Bringup with 5686X, not supported with 5696X, 56930, 8867X, 8837X
BCM54280 C1	54280	Octal 1000/100/10BASE-T Gigabit Ethernet Transceiver	Beta - with Legacy switches Prior to 534XX ; Bringup with 5686X, not supported with 5696X, 56930, 8867X, 8837X
BCM54282 A0	54280	Octal 1000/100/10BASE-T Gigabit Ethernet Transceiver	Beta - with Legacy switches Prior to 534XX ; Bringup with 5686X, not supported with 5696X, 56930, 8867X, 8837X
BCM54282 C0	54280	Octal 1000/100/10BASE-T Gigabit Ethernet Transceiver	Beta - with Legacy switches Prior to 534XX ; Bringup with 5686X, not supported with 5696X, 56930, 8867X, 8837X
BCM54282 C1	54280	Octal 1000/100/10BASE-T Gigabit Ethernet Transceiver	Beta - with Legacy switches Prior to 534XX ; Bringup with 5686X, not supported with 5696X, 56930, 8867X, 8837X

Table 47: PHYs

Device	Driver Family	Description	Quality Level
BCM54285 C0	54280	Octal 1000/100/10BASE-T Gigabit Ethernet Transceiver	Beta - with Legacy switches Prior to 534XX ; Bringup with 5686X, not supported with 5696X, 56930, 8867X, 8837X
BCM54285 C1	54280	Octal 1000/100/10BASE-T Gigabit Ethernet Transceiver	Beta - with Legacy switches Prior to 534XX ; Bringup with 5686X, not supported with 5696X, 56930, 8867X, 8837X
BCM54290 A0	54280	Octal 1000/100/10BASE-T Gigabit Ethernet Transceiver (1588 feature is Bring-up)	Beta - with Legacy switches Prior to 534XX ; Bringup with 5686X, not supported with 5696X, 56930, 8867X, 8837X
BCM54292 A0	54280	Octal 1000/100/10BASE-T Gigabit Ethernet Transceiver (1588 feature is Bring-up)	Beta - with Legacy switches Prior to 534XX ; Bringup with 5686X, not supported with 5696X, 56930, 8867X, 8837X
BCM54294 A0	54280	Quad 1000/100/10BASE-T Gigabit Ethernet Transceiver (1588 feature is Bring-up)	Beta - with Legacy switches Prior to 534XX ; Bringup with 5686X, not supported with 5696X, 56930, 8867X, 8837X
BCM54295SE B0	54295	Octal Copper/Quad Fiber Gigabit Ethernet Transceiver -1588 not yet supported	Beta - with Legacy switches Prior to 534XX ; Bringup with 5686X, not supported with 5696X, 56930, 8867X, 8837X
BCM54296SE B0	54296	Quad Copper/Fiber Gigabit Ethernet Transceiver - 1588 not yet supported	Beta - with Legacy switches Prior to 534XX ; Bringup with 5686X, not supported with 5696X, 56930, 8867X, 8837X
BCM54340 B0	54380	Quad 1000/100/10BASE-T Gigabit Ethernet Transceiver (Needs additional software component)	Beta - with Legacy switches Prior to 534XX ; Bringup with 5686X, not supported with 5696X, 56930, 8867X, 8837X
BCM54340 C0	54380	Quad 1000/100/10BASE-T Gigabit Ethernet Transceiver (Needs additional software component)	Beta - with Legacy switches Prior to 534XX ; Bringup with 5686X, not supported with 5696X, 56930, 8867X, 8837X
BCM54340 C1	54380	Quad 1000/100/10BASE-T Gigabit Ethernet Transceiver (Needs additional software component)	Beta - with Legacy switches Prior to 534XX ; Bringup with 5686X, not supported with 5696X, 56930, 8867X, 8837X
BCM54380 B0	54380	Octal 1000/100/10BASE-T Gigabit Ethernet Transceiver (Needs additional software component)	Beta - with Legacy switches Prior to 534XX ; Bringup with 5686X, not supported with 5696X, 56930, 8867X, 8837X
BCM54380 C0	54380	Octal 1000/100/10BASE-T Gigabit Ethernet Transceiver (Needs additional software component)	Beta - with Legacy switches Prior to 534XX ; Bringup with 5686X, not supported with 5696X, 56930, 8867X, 8837X
BCM54380 C1	54380	Octal 1000/100/10BASE-T Gigabit Ethernet Transceiver (Needs additional software component)	Beta - with Legacy switches Prior to 534XX ; Bringup with 5686X, not supported with 5696X, 56930, 8867X, 8837X

Table 47: PHYs

Device	Driver Family	Description	Quality Level
BCM54382 B0	54380	Octal 1000/100/10BASE-T Gigabit Ethernet Transceiver (Needs additional software component)	Beta - with Legacy switches Prior to 534XX ; Bringup with 5686X, not supported with 5696X, 56930, 8867X, 8837X
BCM54382 C0	54380	Octal 1000/100/10BASE-T Gigabit Ethernet Transceiver (Needs additional software component)	Beta - with Legacy switches Prior to 534XX ; Bringup with 5686X, not supported with 5696X, 56930, 8867X, 8837X
BCM54382 C1	54380	Octal 1000/100/10BASE-T Gigabit Ethernet Transceiver (Needs additional software component)	Beta - with Legacy switches Prior to 534XX ; Bringup with 5686X, not supported with 5696X, 56930, 8867X, 8837X
BCM54385 B0	54380	Octal 1000/100/10BASE-T Gigabit Ethernet Transceiver (Needs additional software component)	Beta - with Legacy switches Prior to 534XX ; Bringup with 5686X, not supported with 5696X, 56930, 8867X, 8837X
BCM54385 C0	54380	Octal 1000/100/10BASE-T Gigabit Ethernet Transceiver (Needs additional software component)	Beta - with Legacy switches Prior to 534XX ; Bringup with 5686X, not supported with 5696X, 56930, 8867X, 8837X
BCM54385 C1	54380	Octal 1000/100/10BASE-T Gigabit Ethernet Transceiver (Needs additional software component)	Beta - with Legacy switches Prior to 534XX ; Bringup with 5686X, not supported with 5696X, 56930, 8867X, 8837X
BCM54616 A0	54616	Single-Chip 10/100/1000BASE-T Gigabit Ethernet Transceiver	Beta - with Legacy switches Prior to 534XX ; Bringup with 5686X, not supported with 5696X, 56930, 8867X, 8837X
BCM54640	54640	Quad-Port Gigabit Copper Transceiver with Copper/Fiber Media Interface	Beta - with Legacy switches Prior to 534XX ; Bringup with 5686X, not supported with 5696X, 56930, 8867X, 8837X
BCM54640E A1	54640	Quad-Port Gigabit Copper Transceiver with Copper/Fiber Media Interface	Beta - with Legacy switches Prior to 534XX ; Bringup with 5686X, not supported with 5696X, 56930, 8867X, 8837X
BCM54640E B0	54640	Quad-Port Gigabit Copper Transceiver with Copper/Fiber Media Interface	Beta - with Legacy switches Prior to 534XX ; Bringup with 5686X, not supported with 5696X, 56930, 8867X, 8837X
BCM54680 A0	54680	Octal-Port 10/100/1000BASE-T Gigabit Ethernet Transceiver	Beta - with Legacy switches Prior to 534XX ; Bringup with 5686X, not supported with 5696X, 56930, 8867X, 8837X
BCM54680E A1	54680	Octal-Port 10/100/1000BASE-T Gigabit Ethernet Transceiver	Beta - with Legacy switches Prior to 534XX ; Bringup with 5686X, not supported with 5696X, 56930, 8867X, 8837X
BCM54680E B0	54680	Octal-Port 10/100/1000BASE-T Gigabit Ethernet Transceiver	Beta - with Legacy switches Prior to 534XX ; Bringup with 5686X, not supported with 5696X, 56930, 8867X, 8837X
BCM54682E A1	54682	Octal-Port 10/100/1000BASE-T Gigabit Ethernet Transceiver with 2 Copper/Fiber Media Interface	Beta - with Legacy switches Prior to 534XX ; Bringup with 5686X, not supported with 5696X, 56930, 8867X, 8837X

Table 47: PHYs

Device	Driver Family	Description	Quality Level
BCM54682E B0	54682	Octal-Port 10/100/1000BASE-T Gigabit Ethernet Transceiver with 2 Copper/Fiber Media Interface	Beta - with Legacy switches Prior to 534XX ; Bringup with 5686X, not supported with 5696X, 56930, 8867X, 8837X
BCM54684 D0	54684	Octal-Port 10/100/1000BASE-T Gigabit Ethernet Transceiver	Beta - with Legacy switches Prior to 534XX ; Bringup with 5686X, not supported with 5696X, 56930, 8867X, 8837X
BCM54684E B0	54682	10/100/1000 Octal (65nm) QSGMII-Copper/Fiber(2) with EEE	Beta - with Legacy switches Prior to 534XX ; Bringup with 5686X, not supported with 5696X, 56930, 8867X, 8837X
BCM54685	54682	Octal QSGMII to 10/100/1000BaseT or Fiber Ethernet Transceiver	Beta - with Legacy switches Prior to 534XX ; Bringup with 5686X, not supported with 5696X, 56930, 8867X, 8837X
BCM54685E A1	54682	Octal-Port 10/100/1000BASE-T Gigabit Ethernet Transceiver with Copper/Fiber Media Interface	Beta - with Legacy switches Prior to 534XX ; Bringup with 5686X, not supported with 5696X, 56930, 8867X, 8837X
BCM54810 A0	54880	BroadR-Reach Single-Port 10/100/1000BASE-T Gigabit Ethernet Transceiver	Beta - with Legacy switches Prior to 534XX ; Bringup with 5686X, not supported with 5696X, 56930, 8867X, 8837X
BCM54880 A0	54880	Octal-Port 10/100/1000BASE-T Gigabit Ethernet Transceiver with BroadR-Reach support	Beta - with Legacy switches Prior to 534XX ; Bringup with 5686X, not supported with 5696X, 56930, 8867X, 8837X
BCM54880 B0	54880	Octal-Port 10/100/1000BASE-T Gigabit Ethernet Transceiver with BroadR-Reach support	Beta - with Legacy switches Prior to 534XX ; Bringup with 5686X, not supported with 5696X, 56930, 8867X, 8837X
BCM54880E A1	54680	Octal-Port 10/100/1000BASE-T Gigabit Ethernet Transceiver	Beta - with Legacy switches Prior to 534XX ; Bringup with 5686X, not supported with 5696X, 56930, 8867X, 8837X
BCM54880E B0	54680	Octal-Port 10/100/1000BASE-T Gigabit Ethernet Transceiver	Beta - with Legacy switches Prior to 534XX ; Bringup with 5686X, not supported with 5696X, 56930, 8867X, 8837X
BCM54881 B0	54880	Octal 10/100Base/Tx Ethernet BroadReach Transceiver	Beta - with Legacy switches Prior to 534XX ; Bringup with 5686X, not supported with 5696X, 56930, 8867X, 8837X
BCM54942 A0	84728	Quad-Channel 10GbE XAUI-to-XFI PHY. Firmware version 0124	Beta - with Legacy switches Prior to 534XX ; Bringup with 5686X, not supported with 5696X, 56930, 8867X, 8837X
BCM54980 B2	54980	Octal 1000/100/10BASE-T Gigabit Ethernet Transceiver	Beta - with Legacy switches Prior to 534XX ; Bringup with 5686X, not supported with 5696X, 56930, 8867X, 8837X
BCM54980 C0	54980	Octal 1000/100/10BASE-T Gigabit Ethernet Transceiver	Beta - with Legacy switches Prior to 534XX ; Bringup with 5686X, not supported with 5696X, 56930, 8867X, 8837X
BCM54980 C1	54980	Octal 1000/100/10BASE-T Gigabit Ethernet Transceiver	Beta - with Legacy switches Prior to 534XX ; Bringup with 5686X, not supported with 5696X, 56930, 8867X, 8837X
BCM8040 A2	8040	Eight-Channel Multirate 1-Gbps - 3.2-Gbps Retimer/Switch	Beta - with Legacy switches Prior to 534XX ; Bringup with 5686X, not supported with 5696X, 56930, 8867X, 8837X
BCM8073 A0	8072	Dual-Channel Serial 10-GbE BASE-KR to XAUI Transceiver. Firmware version d502.	Beta - with Legacy switches Prior to 534XX ; Bringup with 5686X, Beta support with 5696X, 56930. Not available 8867X, 8837X

Table 47: PHYs

Device	Driver Family	Description	Quality Level
BCM8074 A0	8072	Quad-Channel Serial 10-GbE BASE-KR to XAUI Transceiver. Firmware version 010C.	Beta - with Legacy switches Prior to 534XX ; Bringup with 5686X, Beta support with 5696X, 56930. Not available-8867X, 8837X
BCM8704	8703	Serial 10-Gigabit Ethernet/Fibre Channel Transceiver with XAUI Interface	Beta - with Legacy switches Prior to 534XX ; Bringup with 5686X, Beta support with 5696X, 56930. Not available-8867X, 8837X
BCM8705	8705	Serial 10-Gigabit Ethernet/Fibre Channel Transceiver with WIS Layer and XAUI Interface	Beta - with Legacy switches Prior to 534XX ; Bringup with 5686X, Beta support with 5696X, 56930. Not available-8867X, 8837X
BCM8725	8705	Dual Serial 10-Gigabit Ethernet/Fibre Channel Transceiver with WIS Layer and XAUI Interface	Beta - with Legacy switches Prior to 534XX ; Bringup with 5686X, Beta support with 5696X, 56930. Not available-8867X, 8837X
BCM8726 A0	8706	Dual Serial 10-Gigabit Ethernet/Fibre Channel Transceiver with XAUI Interface	Beta - with Legacy switches Prior to 534XX ; Bringup with 5686X, Beta support with 5696X, 56930. Not available-8867X, 8837X
BCM8726 B1	8706	Dual Serial 10-Gigabit Ethernet/Fibre Channel Transceiver with XAUI(TM) Interface. Firmware version 0x0127	Beta - with Legacy switches Prior to 534XX ; Bringup with 5686X, Beta support with 5696X, 56930. Not available-8867X, 8837X
BCM8727 B0	8706	Dual Serial 10-Gigabit Ethernet/Fibre Channel Transceiver with XAUI Interface. Firmware version 0406.	Beta - with Legacy switches Prior to 534XX ; Bringup with 5686X, Beta support with 5696X, 56930. Not available-8867X, 8837X
BCM8727 C0	8706	Dual Serial 10-Gigabit Ethernet/Fibre Channel Transceiver with XAUI Interface. Firmware version 050D.	Beta - with Legacy switches Prior to 534XX ; Bringup with 5686X, Beta support with 5696X, 56930. Not available-8867X, 8837X
BCM84727 A0	84728	Dual SFI to XAUI with 1588 (Firmware version 0x124. Bring-up)	Beta - with Legacy switches Prior to 534XX ; Bringup with 5686X, Beta support with 5696X, 56930. Not available-8867X, 8837X
BCM8728 A0	8706	Dual-Channel 10-GbE SFI-to-XAUI(TM) Transceiver with EDC. Firmware version 0511. (Bring-up)	Beta - with Legacy switches Prior to 534XX ; Bringup with 5686X, Beta support with 5696X, 56930. Not available-8867X, 8837X
BCM8742	8706	Quad-Channel 10-GbE SFI-to-XAUI(TM) Transceiver. Firmware version 0511.	Beta - with Legacy switches Prior to 534XX ; Bringup with 5686X, Beta support with 5696X, 56930. Not available-8867X, 8837X
BCM8747 A0	8706	Quad-Channel 10-GbE SFI-to-XAUI(TM) Transceiver with EDC. Firmware version 0511.	Beta - with Legacy switches Prior to 534XX ; Bringup with 5686X, Beta support with 5696X, 56930. Not available-8867X, 8837X
BCM8750 A0	8750	Dual-Channel 10 GbE SFI-to-XFI PHY with EDC	Beta - with Legacy switches Prior to 534XX ; Bringup with 5686X, Beta support with 5696X, 56930. Not available-8867X, 8837X
BCM8752 A0	8750	Dual-Channel 10 GbE SFI-to-XFI PHY with EDC	Beta - with Legacy switches Prior to 534XX ; Bringup with 5686X, Beta support with 5696X, 56930. Not available-8867X, 8837X
BCM8754 A0	8750	Quad-Channel 10 GbE SFI-to-XFI PHY with EDC. Firmware version 0411.	Beta - with Legacy switches Prior to 534XX ; Bringup with 5686X, Beta support with 5696X, 56930. Not available-8867X, 8837X

Table 47: PHYs

Device	Driver Family	Description	Quality Level
BCM8481 B0	8481	10GBASE-T Transceiver (Firmware version B0 02.10)	Beta - with Legacy switches Prior to 534XX ; Bringup with 5686X, Beta support with 5696X, 56930. Not available-8867X, 8837X
BCM8481 C0	8481	10GBASE-T Transceiver (Firmware version C0 02.13)	Beta - with Legacy switches Prior to 534XX ; Bringup with 5686X, Beta support with 5696X, 56930. Not available-8867X, 8837X
BCM84164	BCM84740	Quad 10GBASE-KR-to-XFI or 40GBASE-KR4-to-XLAUI Transceiver Firmware version 0x128	Beta - with Legacy switches Prior to 534XX ; Bringup with 5686X, Beta support with 5696X, 56930. Not available-8867X, 8837X
BCM84168	BCM84740	Octal 10GBASE-KR-to-XFI or Dual 40GBASE-KR4-to-XLAUI Transceiver Firmware version 0x128	Beta - with Legacy switches Prior to 534XX ; Bringup with 5686X, Beta support with 5696X, 56930. Not available-8867X, 8837X
BCM84318 A0	84740	10.3 Gbps Octal Port CDR/ Retimer with EDC. Firmware version D007	Beta - with Legacy switches Prior to 534XX ; Bringup with 5686X, Beta support with 5696X, 56930. Not available-8867X, 8837X
BCM82072	82072	CAUI4-TO-KR4 NRZ BACKPLANE PHY/OCTAL 25G BACKPLANE RETIMER.	Beta - with Legacy switches Prior to 534XX ; Bringup with 5686X, Beta support with 5696X, 56930. Not available-8867X, 8837X
BCM82073 A1	82073	CAUI4-to-KR4 NRZ Backplane PHY/Octal 25G Backplane Retimer with 2x2 Crosspoint	Beta - with Legacy switches Prior to 534XX ; Bringup with 5686X, Beta support with 5696X, 56930. Not available-8867X, 8837X
BCM82322 B0	82328	1x 100G/3x 40G/12x 10G Ethernet/FC PHY. Firmware version D	Beta with Legacy switches Prior to 534XX with 40G/ 100G support Bringup with 5686X, Beta support with 5696X, 56930. Not available-8867X, 8837X
BCM82328 A0	82328	Dual 40 GbE/Octal 10 GbE QSFP+ XLPPI-to-XLAUI PHY. Firmware version 9 "(Bring-up)	Beta with Legacy switches Prior to 534XX with 40G/ 100G support Bringup with 5686X, Beta support with 5696X, 56930. Not available-8867X, 8837X
BCM82328 B0	82328	Dual 40 GbE/Octal 10 GbE QSFP+ XLPPI-to-XLAUI PHY. Firmware version D	Beta with Legacy switches Prior to 534XX with 40G/ 100G support Bringup with 5686X, Beta support with 5696X, 56930. Not available-8867X, 8837X
BCM82328F B0	82328	Dual 40GbE/Octal 10GbE QSFP+ XLPPI-to-XLAUI PHY	Beta - with Legacy switches Prior to 534XX with 40G/ 100G support ; Bringup with 5686X, Beta support with 5696X, 56930. Not available-8867X, 8837X
BCM84328 A0	84328	Dual 40 GbE/Octal 10 GbE QSFP+ XLPPI-to-XLAUI PHY. Firmware version D026	Beta - with Legacy switches Prior to 534XX with 40Gbe support ; Bringup with 5686X, Beta support with 5696X, 56930. Not available-8867X, 8837X
BCM84328 B0	84328	Dual 40 GbE/Octal 10 GbE QSFP+ XLPPI-to-XLAUI PHY. Firmware version D026	Beta - with Legacy switches Prior to 534XX with 40Gbe support ; Bringup with 5686X, Beta support with 5696X, 56930. Not available yet -8867X, 8837X
BCM84333 B1	8481	Quad 10GBASE-T Transceiver. Firmware version 1.69 (Bring-up) (Needs additional software component)	Beta - with Legacy switches Prior to 534XX ; Bringup with 5686X, Beta support with 5696X, 56930. Not available-8867X, 8837X
BCM84334 B1	8481	Quad 10GBASE-T Transceiver. Firmware version 1.69 (Bring-up) (Needs additional software component)	Beta - with Legacy switches Prior to 534XX ; Bringup with 5686X, Beta support with 5696X, 56930. Not available-8867X, 8837X

Table 47: PHYs

Device	Driver Family	Description	Quality Level
BCM84336 B1	8481	Dual 10GBASE-T Transceiver. Firmware version 1.69 (Bring-up) (Needs additional software component)	Beta - with Legacy switches Prior to 534XX ; Bringup with 5686X, Beta support with 5696X, 56930. Not available-8867X, 8837X
BCM84793 A0	84793	100GbE/OTN 4x25/28G VSR28 to 10x10/11G CAUI Gearbox PHY. Firmware version 0xD009 (Bring-up - Mode-1 and Mode-3)	Beta - with Legacy switches Prior to 534XX ; Bringup with 5686X, Not available yet -8867X, 8837X
BCM84812 A0	8481	Dual 10GBASE-T Transceiver. Firmware version 2.13	Beta - with Legacy switches Prior to 534XX ; Bringup with 5686X, Beta support with 5696X, 56930. Not available-8867X, 8837X
BCM84821 A0	8481	10GBASE-T Transceiver. Firmware version 2.13 (Bring-up)	Beta - with Legacy switches Prior to 534XX ; Bringup with 5686X, Beta support with 5696X, 56930. Not available-8867X, 8837X
BCM84822 A0	8481	Dual 10GBASE-T Transceiver. Firmware version 3.02	Beta - with Legacy switches Prior to 534XX ; Bringup with 5686X, Beta support with 5696X, 56930. Not available-8867X, 8837X
BCM84823 A0	8481	Dual 10GBASE-T Transceiver. Firmware version 3.02	Beta - with Legacy switches Prior to 534XX ; Bringup with 5686X, Beta support with 5696X, 56930. Not available-8867X, 8837X
BCM84823 B0	8481	Dual 10GBASE-T Transceiver. Firmware version 4.02	Beta - with Legacy switches Prior to 534XX ; Bringup with 5686X, Beta support with 5696X, 56930. Not available-8867X, 8837X
BCM84823 B1	8481	Dual 10GBASE-T Transceiver. Firmware version 4.02	Beta - with Legacy switches Prior to 534XX ; Bringup with 5686X, Beta support with 5696X, 56930. Not available-8867X, 8837X
BCM84833 B1	8481	Dual 10GBASE-T Transceiver. Firmware version 1.69(Driver support for IEEE 1588 features are Bring-up)	Beta - with Legacy switches Prior to 534XX ; Bringup with 5686X, Beta support with 5696X, 56930. Not available-8867X, 8837X
BCM84834 B1	8481	Quad 10GBASE-T Transceiver. Firmware version 1.69(Driver support for IEEE 1588 features are Bring-up)	Beta - with Legacy switches Prior to 534XX ; Bringup with 5686X, Beta support with 5696X, 56930. Not available-8867X, 8837X
BCM84836 B1	8481	Dual 10GBASE-T Transceiver. Firmware version 1.69(Driver support for IEEE 1588 features are Bring-up)	Beta - with Legacy switches Prior to 534XX ; Bringup with 5686X, Beta support with 5696X, 56930. Not available-8867X, 8837X
BCM84844 A0	8481	Quad 10GBASE-T Transceiver. Firmware version 1.07.11(Driver support is Bring-up)	Beta - with Legacy switches Prior to 534XX ; Bringup with 5686X, Beta support with 5696X, 56930. Not available-8867X, 8837X
BCM84846 A0	8481	Dual 10GBASE-T Transceiver. Firmware version 1.07.11(Driver support is Bring-up)	Beta - with Legacy switches Prior to 534XX ; Bringup with 5686X, Beta support with 5696X, 56930. Not available-8867X, 8837X
BCM84848 A0	8481	Quad 10GBASE-T Transceiver. Firmware version 1.07.11(Driver support is Bring-up)	Beta - with Legacy switches Prior to 534XX ; Bringup with 5686X, Beta support with 5696X, 56930. Not available-8867X, 8837X

Table 47: PHYs

Device	Driver Family	Description	Quality Level
BCM84728 A0	84728	Dual-Channel 10 GbE SFI-to-XAUI LAN/WAN PHY with 1588. Firmware version 0124 (Driver support for IEEE 1588 features is Bring-up)	Beta - with Legacy switches Prior to 534XX ; Bringup with 5686X, Beta support with 5696X, 56930. Not available-8867X, 8837X
BCM84729 A0	84729	Dual-Channel SFI to XAUI with Macsec, 1588 (Firmware version 0x124. Driver support for IEEE 1588 features are Bring-up)	Beta - with Legacy switches Prior to 534XX ; Bringup with 5686X, Beta support with 5696X, 56930. Not available-8867X, 8837X
BCM84740 A0	84740	40 GbE PPI-to-XLAUI PHY with EDC. Firmware version D106.	Beta - with Legacy switches Prior to 534XX ; Bringup with 5686X, Beta support with 5696X, 56930. Not available-8867X, 8837X
BCM84741 B0	84756	40GbE XLPPi-to-XLAUI/ Quad 10G with IEEE MACsec/1588 Firmware version 0x0128 [Bring-up]	Beta - with Legacy switches Prior to 534XX ; Bringup with 5686X, Beta support with 5696X, 56930. Not available-8867X, 8837X
BCM84747 A0	84728	Quad SFI to XAUI with 1588 (Firmware version 0x124. Bring-up)	Beta - with Legacy switches Prior to 534XX ; Bringup with 5686X, Beta support with 5696X, 56930. Not available-8867X, 8837X
BCM84748 A0	84728	Quad SFI to XAUI with WAN/1588 (Firmware version 0x124. Bring-up)	Beta - with Legacy switches Prior to 534XX ; Bringup with 5686X, Beta support with 5696X, 56930. Not available-8867X, 8837X
BCM84749 A0	84749	Quad SFI to XAUI with Macsec, 1588 (Firmware version 0x124. Driver support for IEEE 1588 features are Bring-up)	Beta - with Legacy switches Prior to 534XX ; Bringup with 5686X, Beta support with 5696X, 56930. Not available-8867X, 8837X
BCM84752 A0	84740	Dual-Channel 10 GbE SFI-to-XFI PHY with EDC. Firmware version D105. (Bring-up)	Beta - with Legacy switches Prior to 534XX ; Bringup with 5686X, Beta support with 5696X, 56930. Not available-8867X, 8837X
BCM84753 A0	84740	Quad-Channel 10 GbE SFI-to-XFI PHY with EDC. Firmware version D105.	Beta - with Legacy switches Prior to 534XX ; Bringup with 5686X, Beta support with 5696X, 56930. Not available-8867X, 8837X
BCM84754 A0	84740	Quad-Channel 10 GbE SFI-to-XFI PHY with EDC. Firmware version D105.	Beta - with Legacy switches Prior to 534XX ; Bringup with 5686X, Beta support with 5696X, 56930. Not available-8867X, 8837X
BCM84756 A0	84756	Quad SGMII/XFI to SGMII/ SFI Transceiver Firmware version D105. (Needs additional software component)	Beta - with Legacy switches Prior to 534XX ; Bringup with 5686X, Beta support with 5696X, 56930. Not available-8867X, 8837X
BCM84756 B0	84756	Quad SGMII/XFI to SGMII/ SFI Transceiver Firmware version 0x0128(Needs additional software component)	Beta - with Legacy switches Prior to 534XX ; Bringup with 5686X, Beta support with 5696X, 56930. Not available-8867X, 8837X
BCM84756 C0	84756	Quad SGMII/XFI to SGMII/ SFI Transceiver Firmware version 0x0128(Needs additional software component) [Bring-up]	Beta - with Legacy switches Prior to 534XX ; Bringup with 5686X, Beta support with 5696X, 56930. Not available-8867X, 8837X
BCM84758	84740	10GbE Quad SFI-XFI PHY with IEEE 1588 Firmware version 0x128	Beta - with Legacy switches Prior to 534XX ; Bringup with 5686X, Beta support with 5696X, 56930. Not available-8867X, 8837X

Table 47: PHYs

Device	Driver Family	Description	Quality Level
BCM84759 A0	84756	Quad SGMII/XFI to SGMII/SFI Transceiver Firmware version D105.	Beta - with Legacy switches Prior to 534XX ; Bringup with 5686X, Beta support with 5696X, 56930. Not available-8867X, 8837X
BCM84759 C0	84756	Quad SGMII/XFI to SGMII/SFI Transceiver Firmware version 0x0128. (Bring-up)	Beta - with Legacy switches Prior to 534XX ; Bringup with 5686X, Beta support with 5696X, 56930. Not available-8867X, 8837X
BCM84780 A0	84740	Octal-Channel 10 GbE SFI-to-XFI PHY with 1588. Firmware version 0x128 (Bring-up)	Beta - with Legacy switches Prior to 534XX ; Bringup with 5686X, Beta support with 5696X, 56930. Not available-8867X, 8837X
BCM84784 A0	84740	Dual 40GbE/Octal 10GbE QSFP+ XLPP1-to-XLAUI PHY. Firmware version 0x125 (Bring-up)	Beta - with Legacy switches Prior to 534XX with 40GbE Support ; Bringup with 5686X, Beta support with 5696X, 56930. Not available-8867X, 8837X
BCM84764 A0	84728	Quad SFI to RXAUI with 1588 (Firmware version 0x124. Bring-up)	Beta - with Legacy switches Prior to 534XX ; Bringup with 5686X, Beta support with 5696X, 56930. Not available-8867X, 8837X
BCM84064 A0	84740	Quad 10G-KR-to-XFI or 40G-KR4-to-XLAUI Transceiver. Firmware version 0108.	Beta - with Legacy switches Prior to 534XX ; Bringup with 5686X, Beta support with 5696X, 56930. Not available - 8867X, 8837X
BCM84074 A0	84728	Quad KR to XAUI (Firmware version 0x124. Bring-up)	Beta - with Legacy switches Prior to 534XX ; Bringup with 5686X, Beta support with 5696X, 56930.
BCM82381 A2	82381	Dual 100GbE CAUI4-to-CAUI4 PHY/Octal 25G Retimer	Bringup with 5686X. GA support with 5696X, 56930. not available yet-with 8867X, 8837X
BCM82764 A2	82764	Quad 40 GbE PMA MUX/DEMUX	Bringup with 5686X. GA support with 5696X, 56930. Not available yet for 8867X, 8837X
BCM84858 A0	84858	Quad 10GBASE-T Transceiver. Firmware version 1.01.04 - Beta	GA - with Legacy switches Prior to 534XX ; GA with 5686X, GA support with 5696X, 56930. Not available yet for 8867X, 8837X - TBD
BCM84858 B0	84858	Quad 10GBASE-T Transceiver. Firmware version 1.02.02 - Beta	GA - with Legacy switches Prior to 534XX ; GA with 5686X, GA support with 5696X, 56930. Not available yet for 8867X, 8837X
BCM84856 B0	84856	Dual 10GBASE-T Transceiver. Firmware version 1.02.02 - Beta	Beta - with Legacy switches Prior to 534XX ; GA with 5686X, GA support with 5696X, 56930. Not available yet for 8867X, 8837X
BCM82792	82792	Dual 100G/OTN CAUI-to-100GbE VSR/CR4/SR4/LR4 Gearbox PHY	Beta with 5686X, 56930. Not available yet for 8867X, 8837X
BCM82780	82870	10G Octal SFI-XFI PHY with 10GbE and IEEE 1588 Support	Beta - with Legacy switches Prior to 534XX ; GA with 5686X, 56930. Not available yet for 8867X, 8837X
BCM82780F	82780	10G Octal SFI-XFI PHY with 10GbE/40GbE	Beta - with Legacy switches Prior to 534XX ; GA with 5686X, 56930. Not available yet for 8867X, 8837X
BCM82752	82752	10G Dual SFI-XFI PHY with 10GbE IEEE 1588 Support	Beta - with Legacy switches Prior to 534XX ; GA with 5686X, 56930. Not available yet for 8867X, 8837X
BCM82758	82758	10G Quad SFI-XFI PHY with 10GbE/40GbE and IEEE 1588 Support	Beta - with Legacy switches Prior to 534XX ; GA with 5686X, 56930. Not available yet for 8867X, 8837X

Section 12: Compatibility

BROADCOM TASK ENGINES (BTE) FIRMWARE COMPATIBILITY MATRIX

The following table SDK Firmware Compatibility Matrix ([page 96](#)) shows compatibility between different versions of SDK and Firmware releases. Please refer to the appropriate Network Switching SDK Firmware release notes publication (56XX0_88XX0_FW-RNxxx-R) for the indicated version below.

Table 48: SDK Firmware Compatibility Matrix

	SDK-6.4.11	SDK-6.4.10	SDK-6.4.9	SDK-6.4.8	SDK-6.4.7	SDK-6.4.6	SDK-6.4.5
4.2.7	BCM56230	BCM56260					
	BCM56260	BCM56460					
	BCM56460	BCM56445					
	BCM56445	BCM56450					
	BCM56450						
4.2.6			BCM56260				
			BCM56450				
			BCM56640				
			BCM56860				
			BCM88370				
			BCM88650				
			BCM88670				
4.2.5				BCM56450			
				BCM56260			
				BCM56860			
				BCM88660			
				BCM88375			
				BCM88675			
4.2.4					BCM56260		
					BCM56960		
					BCM53903		
4.2.3						BCM88650	
						BCM88370	
						BCM88670	
4.2.2						BCM53400	BCM88650
						BCM56150	
						BCM56440	
						BCM56450	
						BCM56640	
						BCM56850	
						BCM88030	
						BCM56260	
						BCM56340	

Table 48: SDK Firmware Compatibility Matrix

SDK-6.4.11	SDK-6.4.10	SDK-6.4.9	SDK-6.4.8	SDK-6.4.7	SDK-6.4.6	SDK-6.4.5
4.2.0						BCM53400 BCM56150 BCM56440 BCM56450 BCM56640 BCM56850 BCM56260

BMACSEC SDK COMPATIBILITY MATRIX

Table 49: BMACSEC SDK Compatibility Matrix

Switch SDK Release	BMACSEC SDK Release
6.4.5	4.13
6.4.6	4.14
6.4.7	4.14
6.4.8	4.15
6.4.9	4.15
6.4.10	4.15
6.4.11	4.15

PHY FIRMWARE COMPATIBILITY MATRIX

The following table PHY Firmware Compatibility Matrix ([page 97](#)) identifies changes in PHY firmware for newer PHY devices.

Table 50: PHY Firmware Compatibility Matrix

PHY Core	6.4.6 Firmware Versions	6.4.7 Firmware Versions	6.4.8 Firmware Versions	6.4.9 Firmware Versions	6.4.10 Firmware Versions	6.4.11 Firmware Versions
BCM84834/36/38			01.69.00	01.69.00	01.69.00	01.69.00
BCM84848			01.08.01	01.08.01	01.08.04	01.08.04
BCM84858/56	01.02.02	01.02.02	01.02.10	01.02.10	01.02.10	01.02.10
BCM84861/64/68	00.00.09	00.00.10	00.00.10	00.00.10	00.00.10	00.00.10
BCM84328	R027	R027	R027	R027	R029	R029
BCM84744	0xD105(A0)/ 0x0128(B0/C0)	0xD105(A0)/ 0x0128(B0/C0)	0x0132(B0/C0)	0x0132(B0/C0)	0x0132(B0/C0)	0x0132(B0/C0)
BCM84757	0xD105(A0)/ 0x0128(B0/C0)	0xD105(A0)/ 0x0128(B0/C0)	0x0132(B0/C0)	0x0132(B0/C0)	0x0132(B0/C0)	0x0132(B0/C0)
BCM82322/28B1	0xD	0xF	0xF	0xF	0xF	0xF
BCM82780/52/58	0x22	0x22	0x23	0x23	0x23	0x23
BCM82764	D00B	D00F	D011	D015	D016	D017



Table 50: PHY Firmware Compatibility Matrix

PHY Core	6.4.6 Firmware Versions	6.4.7 Firmware Versions	6.4.8 Firmware Versions	6.4.9 Firmware Versions	6.4.10 Firmware Versions	6.4.11 Firmware Versions
BCM82790/92/96	D00B	D00F	D011	D015	D016	D017
BCM82381	D00E	D011	D011	D011	D011	D012
BCM82209	D00E	D011	D011	D011	D011	D012
BCM82073	D00E	D011	D011	D011	D011	D012
BCM82380			D011	D011	D011	D012
BCM82071			D011	D011	D011	D012
BCM82385			D011	D011	D011	D012
BCM82864			D004	D005	D008	D00A
BCM82332					D002	D004
Eagle	D10E_04	D10F_03	D10F_03	D10F_07	D10F_0D	D10F_0D
Falcon	D10A_02	D10A_02	D10A_06	D10B_00	D10B_00	D10B_07

Section 13: SDK Externally Licensed Software Components

SDK contains a number of third-party externally licensed software components. This appendix contains information regarding these components, the license for each of these components, and where these components are used in SDK.

Table 51: EXTERNALLY LICENSED SOFTWARE COMPONENTS

Component	Origin	Location in Source Tree	License Terms and Conditions
EDITLINE	/afs/athena.mit.edu/contrib/sipb/src/editline	src/sal/appl/editline	See (EDITLINE License terms and conditions) (page 99)
ED Editor	USENET comp.sources.misc Volume 9, Issue 36	src/appl/diag/edline.c	See (ED Editor License terms and conditions) (page 101)
CINT	http://www.gnu.org/software/bison/	src/appl/cint/cint_parser.[ch]	See (CINT parser license terms and conditions) (page 101)
BIGDIGITS	David Ireland, copyright (c) 2001-11 by D.I. Management Services Pty Limited < www.di-mgt.com.au >	src/soc/dpp/SAND/Utils/sand_u64.c	See (BIGDIGITS license terms and conditions) (page 102)
APIMODE	http://www.gnu.org/software/bison/	src/appl/diag/api/api_grammar.tab.[ch]	See (APIMODE parser license terms and conditions) (page 103)
VxWorks	Wind River Systems, Inc.	systems/vxworks	See (Wind River Systems license terms and conditions) (page 103)

EDITLINE LICENSE TERMS AND CONDITIONS

This package was obtained from the following location, and was modified for purposes of inclusion into the SOC diagnostics shell.

Removed files:

MANIFEST Make.os9 Makefile os9.h sysos9.c testit.c unix.h

Added files:

sysvxworks.c Makefile

Changed functionality:

Merged unix.h into editline.h

M-P and M-N now behave like tcsh.

list_history(count) routine displays history

Commented out completion

Changed rl_complete and rl_list_possib into caller-settable global functions

Don't ring bell on TAB if word is already complete

Index of /afs/athena.mit.edu/contrib/sipb/src/editline

[]	Name	Last modified	Size	Description

[DIR]		Parent Directory	11-May-99 03:40	-	
[]	MANIFEST	07-Jul-97 11:20	1k	
[]	Make.os9	07-Jul-97 11:20	1k	
[]	Makefile	01-Sep-97 00:34	2k	
[]	complete.c	07-Jul-97 11:20	4k	
[]	editline.3	07-Jul-97 11:20	5k	
[]	editline.c	07-Jul-97 11:20	25k	
[]	editline.h	07-Jul-97 11:20	2k	
[]	os9.h	07-Jul-97 11:20	1k	
[]	sysos9.c	07-Jul-97 11:20	1k	
[]	sysunix.c	07-Jul-97 11:20	3k	
[]	testit.c	07-Jul-97 11:20	1k	
[]	unix.h	07-Jul-97 11:20	1k	

\$Revision: 1.7 \$

This is a line-editing library. It can be linked into almost any program to provide command-line editing and recall.

It is call-compatible with the FSF readline library, but it is a fraction of the size (and offers fewer features). It does not use standard I/O. It is distributed under a "C News-like" copyright.

Configuration is done in the Makefile. Type "make testit" to get a small slow shell for testing.

This contains some changes since the posting to comp.sources.misc:

- Bugfix for completion on absolute pathnames.
- Better handling of M-n versus showing raw 8bit chars.
- Better signal handling.
- Now supports termios/termio/sgttyb ioctl's.
- Add M-m command to toggle how 8bit data is displayed.

The following changes, made since the last public release, come from J.G. Vons <vons@cesar.crbcal.sinet.slb.com>:

- History-searching no longer redraws the line wrong
- Added ESC-ESC as synonym for ESC-?
- SIGQUIT (normally ^) now sends a signal, not indicating EOF.
- Fixed some typo's and unclear wording in the manpage.
- Fixed completion when all entries shared a common prefix.
- Fixed some meta-char line-redrawing bugs.

Enjoy,

Rich \$alz
<rsalz@osf.org>

Copyright 1992,1993 Simmule Turner and Rich Salz. All rights reserved.

This software is not subject to any license of the American Telephone and Telegraph Company or of the Regents of the University of California.

Permission is granted to anyone to use this software for any purpose on any computer system, and to alter it and redistribute it freely, subject to the following restrictions:

1. The authors are not responsible for the consequences of use of this software, no matter how awful, even if they arise from flaws in it.
2. The origin of this software must not be misrepresented, either by explicit claim or by omission. Since few users ever read sources, credits must appear in the documentation.
3. Altered versions must be plainly marked as such, and must not be misrepresented as being the original software. Since few users ever read sources, credits must appear in the documentation.
4. This notice may not be removed or altered.

ED EDITOR LICENSE TERMS AND CONDITIONS

ed - standard editor
^^

Authors: Brian Beattie, Kees Bot, and others

Copyright 1987 Brian Beattie Rights Reserved.

Permission to copy or distribute granted under the following conditions:

- 1). No charge may be made other than reasonable charges for reproduction.
- 2). This notice must remain intact.
- 3). No further restrictions may be added.

TurboC mods and cleanup 8/17/88 RAMontante.

Further information (posting headers, etc.) at end of file.

Modification log:

25Aug92 (W.Metzenthien) Changed malloc() call to calloc() in makebitmap()
to remove bugs under Linux. Changed a few '^' to the correct '~'.
General tidying. Recognize Linux via the __linux__ symbol.
Main change based upon suggestion by Wolfgang Thiel.

07Sep99 Changed large amounts of stuff to simplify --Curt McDowell

CINT PARSE LICENSE TERMS AND CONDITIONS

The C code for the CINT parser was generated by using GNU Bison parser generator from the file cint_grammar.y CINT is an optional diagnostic tool that can be included in your system by adding CINT to the FEATURE_LIST in SDK compilation flags.

Removed files:
None

Added files:

None

Changed functionality:

None

/* A Bison parser, made by GNU Bison 2.4.1. */

/* Skeleton implementation for Bison's Yacc-like parsers in C

Copyright (C) 1984, 1989, 1990, 2000, 2001, 2002, 2003, 2004, 2005, 2006
Free Software Foundation, Inc.

This program is free software: you can redistribute it and/or modify
it under the terms of the GNU General Public License as published by
the Free Software Foundation, either version 3 of the License, or
(at your option) any later version.

This program is distributed in the hope that it will be useful,
but WITHOUT ANY WARRANTY; without even the implied warranty of
MERCHANTABILITY or FITNESS FOR A PARTICULAR PURPOSE. See the
GNU General Public License for more details.

You should have received a copy of the GNU General Public License
along with this program. If not, see <<http://www.gnu.org/licenses/>>. */

/* As a special exception, you may create a larger work that contains
part or all of the Bison parser skeleton and distribute that work
under terms of your choice, so long as that work isn't itself a
parser generator using the skeleton or a modified version thereof
as a parser skeleton. Alternatively, if you modify or redistribute
the parser skeleton itself, you may (at your option) remove this
special exception, which will cause the skeleton and the resulting
Bison output files to be licensed under the GNU General Public
License without this special exception.

This special exception was added by the Free Software Foundation in
version 2.2 of Bison. */

/* C LALR(1) parser skeleton written by Richard Stallman, by
simplifying the original so-called "semantic" parser. */

BIGDIGITS LICENSE TERMS AND CONDITIONS

Contains BIGDIGITS multiple-precision arithmetic code originally
written by David Ireland, copyright (c) 2001-11 by D.I. Management
Services Pty Limited <www.di-mgt.com.au>, and is used with
permission.



David Ireland and DI Management Services Pty Limited make no representations concerning either the merchantability of this software or the suitability of this software for any particular purpose. It is provided "as is" without express or implied warranty of any kind. Our liability will be limited exclusively to the refund of the money you paid us for the software, namely nothing. By using the software you expressly agree to such a waiver. If you do not agree to the terms, do not use the software.

APIMODE PARSER LICENSE TERMS AND CONDITIONS

The C code for the APIMODE parser was generated by using GNU Bison parser generator from the file `api_grammar.y`. APIMODE is an optional diagnostics shell interface that can be included in your system by adding `APIMDOE` to the `FEATURE_LIST` in SDK compilation flags.

See (CINT parser license terms and conditions) ([page 101](#)) for the Bison licence.

WIND RIVER SYSTEMS LICENSE TERMS AND CONDITIONS

See `WRS_LICENSE.pdf` contained in each `systems/vxworks` subdirectory.