

TDC NET

TECHNICAL OPERATIONS MANUAL

Document ID: SOP-001

Title: Cable Fault Resolution Procedures

Category: Cable Fault

Equipment Types: Cisco cBR-8, Arris E6000

Applicable Fault Codes: 812.3, 813.1, 814.2

Last Updated: 2025-10-04

CABLE FAULT RESOLUTION - ERROR CODE 812.3

SAFETY FIRST:

1. Ensure proper PPE (hard hat, safety vest, gloves)
2. Check for electrical hazards before accessing equipment
3. Notify traffic control if working near roadways

DIAGNOSTIC STEPS:

1. Verify fault code 812.3 on Cisco cBR-8 router display
2. Check signal levels using spectrum analyzer
 - Forward path: Should be -7 to +7 dBmV
 - Return path: Should be 16 to 54 dBmV
3. Perform cable continuity test using TDR (Time Domain Reflectometer)
4. Identify fault location within 2-meter accuracy

REPAIR PROCEDURE:

1. Isolate affected cable segment
2. If underground cable:
 - Contact utility marking service (mandatory)
 - Use cable locator to trace exact path
 - Excavate carefully using hand tools near cable
3. If aerial cable:

- Inspect for physical damage, animal interference
 - Check guy wires and support structures
- 4. Replace damaged cable section with approved splice kit**
 - 5. Test signal integrity before restoration**
 - 6. Document GPS coordinates of repair location**

VERIFICATION:

- 1. Confirm error code 812.3 clears from system**
- 2. Test downstream signal levels at customer premises**
- 3. Verify no packet loss over 15-minute test period**
- 4. Update network topology database**

ESTIMATED TIME: 4-8 hours depending on access complexity REQUIRED SKILLS: Cable splicing certification, TDR operation TOOLS REQUIRED: TDR, spectrum analyzer, splice kit, excavation tools

This document contains proprietary information of TDC Net.
Unauthorized distribution is prohibited.