



Go, change the world

Not me But you



National Service Scheme RV College of Engineering®

**REGISTER NOW
UTSARGA MARATHON' 24**

5 KM - ₹399/-

10 KM - ₹449/-

**10
ACTIVITY
POINTS**

**HELP A CHILD,
CHANGE THE WORLD**


Includes

- T-shirt
- Certificate
- Medal
- Breakfast
- Refreshments



**4TH
FEBRUARY**

Exercise No. 01: Write a manual part programming for the component shown in figure below



Operation	Tool	Machining Parameters			Remarks
		(90PM) Speed	(MM/REV) Feed	(MM) Depth of cut	
Rough Turning	Rough	1200	0.2	1	
Finishing Cycle	Left hand	1500	0.15	0.25	
Grooving	External grooving tool (3mm)	800	0.1	2000 μ	

set in mm/rev

N05 G21 G99 ----- All dimension are set to mm & feed rate is in mm/rev
N10 G28 U0 W0 ----- Tool moves to home position
N15 M06 T0101 ----- Tool selection: roughing tool is selected
N20 M03 S1200 ----- Spindle is turned on & set at 1200 rpm
N25 M07 ----- Coolant is switched on
N30 G100 X66 Z2 ----- Cycle start point is set at (66, 2)
N35 G71 U1 R0.5 ----- Roughing cycle parameters
N40 G71 P45 Q90 U0.5 W0.2 F0.2 ----- Depth of cut = 1mm & retract amount is 0.5
N45 G100 X0 ----- Finishing allowance in X & Z axis are 0.5 & 0.2
N50 G101 Z0 ----- feed rate is 0.2 mm/rev
N55 G03 X35.5 Z-7.2 R25 -----
N60 G01 X35.1 Z-27.5 -----
N65 G01 X45.5 Z-45 -----
N70 G01 X45.5 Z-55 -----
N75 G02 X60.5 Z-62.5 R7.5 -----
N80 G01 X60.5 -----
N85 G01 X64 Z-77.5 -----
N90 G01 X64 Z-95 -----
N95 G28 U0 W0 ----- roughing tool goes to home position
N100 M01 Optional Stop
N105 M06 T0202 ----- grooving tool is selected from station 2
N110 G100 X36 Z-22.5 ----- Tool is brought to grooving position
N115 G175 R0.5 ----- grooving parameters with position of groove
N120 G175 X25.35 Z-27.5 P2000 Q2000 F0.1 S800 ----- depth of cutter, each cycle feed rate, spindle feed

N125 G28 U0W0 grooving tool goes to home position

N130 M01 Optional stop

N135 M06 T0303 Finishing tool is selected from station 3 (left hand)

N140 ^G~~G00~~ ~~X56~~ Z2 cycle start point is set (66.2)

N145 G70 P45 Q90 F0.15 S1500 Finishing cycle parameters with feed rate and spindle speed


N150 G28 U0W0 left hand tool moves to home position

N155 M05 spindle stop

N160 M30 program stop and cursor moves to start block

Faculty Signature	ation	Writ	m a	t:	1	CO1	L1
						CO2	L2
						CO3	L3
						CO4	L4

Exercise No.02: Write a manual part programming for the component shown in figure below



Operation	Tool	Machining Parameters			Remarks
		Speed [?]	Feed [?]	Depth of cut ^{mm}	
Rough Turning	Rough	1200	0.2	1	
Finishing cycle	left hand	1500	0.15	0.25	
Grooving	External grooving tool (3mm)	800	0.1	2000 ft	

N05 G21 G99 All dimensions are set in mm & feed rate in mm/rev
 N10 G28 U0 W0 Tool moves to home position
 N15 M06 T0101 Rougher tool is selected from station 1
 N20 M03 S1200 spindle is turned on
 N25 M07 Coolant is turned on
 N30 G00 X52 Z2 Cycle start point is set at (52, 2)
 N35 G71 U1 R0.5 *Roughing parameters are set Depth of cut: 1mm
 retract amount = 0.5. Finishing
 allowance in X & Z axis = 0.5 &
 0.2. Feed rate is 0.2 mm/rev*
 N40 G71 P45 Q10 U0.5 W0.2 F0.2
 N45 G00 X0
 N50 G01 Z0
 N55 G03 X16 Z-50 R9
 N60 G01 X16 Z-10
 N65 G02 X26 Z-15 R5
 N70 G01 X32 Z-18
 N75 G01 X32 Z-28
 N80 G02 X40² Z-33 R5
 N85 G01 X50 Z-55
 N90 G01 X50 Z-85
 N95 G28 U0 W0 Tool returns to home position
 N100 M01 Optional Stop
 N105 M06 T0202 Grooving tool is selected from station 2
 N110 G00 X52 Z-65 Cycle start point is set at (52, -65)

Body of Program.

groove parameters are set: position of groove,
depth of cutter, each cycle feed rate, spindle feed

N115 G75 R0.5

N120 G75 X44 Z-65 P2000 Q0 F0.1 S800

N125 G28 U0 W0 tool moves to home position

N130 M01 Optional Stop

N135 M06 T0303 Finishing (left hand) tool is selected from station 3

N140 G00 X52 Z2 cycle start point is set (52, 2)

N145 G70 P45 Q90 F0.15 S1500 Finishing parameters are set
feed rate & spindle speed

N150 G28 U0 W0 tool returns to home position

N155 M05 Spindle Stop

N160 M30 Cursor Stop cursor moves to start block

10

10


	Diagram: 1M	10 M	CO1	L1
	Procedure: 2M		CO2	L2
	Writing Program: 5M		CO3	L3
	Simulation the program and print out: 2M		CO4	L4

Faculty Signature with Date

Pesh 12/2/24

Exercise No. 03: Write a manual part programming for the component shown in figure below

Show threading calculations here.




Operation	Tool	Machining parameters			Remarks
		Speed	Feed	Depth of Cut	
Rough Turning	Rougher	1200	0.2	1	
Finishing Cycle	Left hand	1500	0.15	0.25	
Grooving Cycle	External grooving tool	600	0.1	2000 μ	
Threading	External threading tool	300	2	200 μ	

N05 G21 G99 All dimensions are set in mm & feed rate in mm/rev
 N10 G28 U0 W0 Tool moves to home position
 N15 M06 T0101 Rough tool is selected from station 1
 N20 M03 S1200 Spindle start & speed is set at 1200 rpm
 N25 M01 Coolant is switched on
 N30 G00 X52 Z2 Cycle start point is set at (52, 2)
 N35 G71 U1 R0.5 Roughing parameters are set. Depth of cut = 1mm
 N40 G71 P45 Q10 U0.5 W0.2 F0.2 Finishing allowance in X & Z
 N45 G00 X0 Z0 subtract amount of 0.5
and is 0.5 & 0.2. Feed rate is 0.2 mm/rev
 N50 G01 X120 Z20
 N55 G02 X30 Z30 R20
 N60 G01 X30 Z40
 N65 G03 X50 Z55 R20
 N70 G01 Z65
 N75 G28 U0 W0 Tool moves to home position
 N80 M01 Optional Stop
 N85 M06 T0202 Finishing (left hand) tool is selected from station 2
 N90 G00 X52 Z2 cycle start point is set (52, 2)
 N95 G70 P45 Q10 F0.15 S1500 Finishing parameters are set
 N100 G28 U0 W0 Tool returns to home position
 N105 M01 Optional Stop
 N110 M06 T0303 grooving tool ^{3mm width} is selected from station 3
 N115 G00 X22 Z17 cycle start point is set (22, -17)

grooving parameters are set. position of groove,
 N120 G75 R0:5 --- depth of cutter, each cycle feed rate & spindle speed
 N125 G15 X15 Z-17 P2000 Q0 F0.1 S600
 N130 G28 U0 W0 tool moves to home position
 N135 M01 Optional Stop
 N140 M06 T0404 Threading tool is selected
 N141 M03 S300
 N145 G00 X20 Z10 Threading position is set to (20,10)
 N150 G76 P051060 Q100 R0.15
 N155 G76 X17.548 Z-17 P1226 Q200 F2
 N160 G28 U0 W0 tool returns to home position
 N165 M05 Spindle Stop
 N170 M30 cursor stops & cursor returns to start block

	Diagram: 1M	10 M	C01	L1
	Procedure: 2M		C02	L2
	Writing Program: 5M		C03	L3
	Simulation the program and print out: 2M		C04	L4

Exercise No. 04: Write a manual part programming for the component shown in Figure below



Operation	Tool	Machining Parameters			Remarks
		Speed	Feed	Depth of Cut	
Rough Turning	Rough	1200	0.2	1	
Finishing Cycle	Left hand	1500	0.15	0.25	
Grooving	External grooving tool	600	0.1	2000 μ	
Threading	External threading tool	300 300	2	200 μ (Inch) 100 (Min)	

N05 G21 G99 All dimension set in mm & feed rate in mm/min
 N10 G28 UD W0 tool moves to home position
 N15 M06 T0101 Rough tool is selected from station 1
 N20 M03 S1200 Spindle on & speed set to 1200 rpm
 N25 M07 Coolant on
 N30 G00 X52 Z2 cycle start position is set to (52, 2)
 N35 G71 U1 R0.5 Roughing parameters: depth of cut = 1mm
 N40 G71 P45 Q80 UD.5 WD.2 FD.2 retract amount 0.5. Finishing allowance
 in X & Z axis = 0.5 & 0.2 feed rate = 0.2 mm/min
 N45 G00 X20 Z0
 N50 G01 Z-20
 N55 G00 X26
 N60 G01 X32 Z-23
 N65 G01 Z-75
 N70 G00 X44
 N75 G01 X50 Z-78
 N80 G01 Z-85
 N85 G28 UD W0 Tool returns to home position
 N90 M01 Optional Stop
 N95 M06 T0202 Finishing tool is selected from station 2
 N100 G00 X52 Z2 cycle start position is set to (52, 2)
 N105 G70 P45 Q80 FD.15 S1500 Finishing parameters: feed rate & spindle speed
 N110 G28 UD W0 tool returns to home position

Body of Program

N115 M01 Optional stop station
 N120 M06 T030 Grooving tool is selected from 3
 N125 G00 X33 Z-20 grooving position is set (33,17)
 N130 G75 X17 Z-20 P2000 Q0 F0.1 S600 grooving parameters
 position, depth of cut, distance b/w grooves
 N135 G00 X33 Z-35 speed rate & spindle speed
 N140 G75 R0.5 Relief clearance is set to 0.5
 N145 ~~G00 X33 Z-62~~ G75 X26 Z-35 P2000 Q0 F0.1 S600
 position, depth of cut, distance b/w grooves
 N150 ~~G00 X33 Z-65~~ speed rate & spindle speed
 N155 G75 R0.5 Relief clearance is set to 0.5
 N160 G75 X26 Z-35 P2000 Q0 F0.1 S600
 N165 G28 U0 W0 tool returns to home position
 N170 M01 Optional stop
 N175 M06 T0404 Threading tool is selected from station 4
 N176 M03 S300
 N180 G00 X20 Z10 threading position is set (20,10)
 threading parameters are
 N185 G76 P05 I0.60 Q100 R0.15 set
 N190 G76 X17.548 Z-17 P1226 Q200 F2
 N195 G28 U0 W0 tool returns to home position
 N200 M05 Spindle stop
 N205 M30 Cursor stop & cursor returns to start
 N161 G00 X33 Z-75 position, depth of cut, block
 N162 G75 R0.5 speed rate & spindle speed, relief
 163 G75 X26 X-75 P2000 Q0 F0.1 S600


89
10

	Diagram: 1M	10 M	C01	L1
	Procedure: 2M		C02	L2
	Writing Program: 5M		C03	L3
	Simulation the program and print out: 2M		C04	L4

Faculty Signature with Date

Keshav 12/2/24

Exercise No.05: Peck Drilling - Write a manual part programming for the component shown in figure below



Operation	Tool	Machining Parameters			Remarks
		Speed [?]	Feed [?]	Depth of Cut [?]	
Rough Turning	Rough	1200	0.2	1	
Finishing Cycle	left hand	1500	0.15	0.25	
Drilling	Drill (dia 6mm)	600	0.15	2000 μ	

N05 G21 G99 All dimensions are set to mm & feed rate in mm/min
 N10 G28 U0 W0 tool moves to home position
 N15 M06 T0101 Rough tool is selected from station 1
 N20 M03 S1200 Spindle is switched on & speed is set at 1200 rpm
 N25 M07 Coolant is switched on
 N30 G00 X52 Z2 cycle start position is set (52, 2)
 N35 G71 U1 R0.5 Roughing parameters are set Depth of cut = 1 mm
 retract amount = 0.5. Finishing allowance
 in X & Z axis is 0.5 & 0.2
 N40 G71 P45 Q85 U0.5 W0.2 F0.2 Feed rate = 0.2 mm/min
 N45 G00 X14 Z0
 N50 G01 X22 Z-4
 N55 G01 X22 Z-20
 N60 G02 X32 Z-25 R5
 N65 G01 X32 Z-40
 N70 G01 X40 Z-44
 N75 G01 X40 Z-55
 N80 G02 X50 Z-60 R5
 N85 G01 X50 Z-80
 N90 G28 U0 W0 Tool moves to home position
 N95 M01 Optional stop
 N100 M06 T0202 Finishing (left hand) tool is selected from station 2
 N105 G00 X52 Z2 cycle start point is set (52, 2)
 Finishing parameters are set
 N110 G70 P45 Q85 F0.15 S1500 feed rate & spindle speed.

N115 G00 U0W0 tool returns to home position.

N120 M01 Optional Stop

N125 M06 T0505 Drilling tool (6mm dia) is selected from station 5

N130 G00 X0 Z2 drilling start point is set (0,2)

N135 G74 R0.5 drilling parameters are set, drilling depth, feed rate, spindle speed and relief amount at end of cut

N140 G74 X0 Z-25 Q1000 F0.15 S600

N145 G28 U0W0 tool returns to home position

N150 M05 Spindle Stop

N155 M30 Curor Stop & Curor returns to start block

