

## Common GTAW problems – Causes & Remedies

### 1.0 COMMON WELDING DEFECTS OBSERVED IN GTAW PROCESS:

The process variables, materials or welding procedures can affect the weld quality. Some of the commonly observed defects in GMA welding and their possible remedies are tabulated below.

<i>Possible Causes</i>	<i>Corrective Actions</i>
------------------------	---------------------------

#### Inclusions

1.	Cleanliness of the base plate.	<ul style="list-style-type: none"> <li>• Clean the plate before making weld passes.</li> </ul>
2.	High travel speeds (film type inclusions).	<ul style="list-style-type: none"> <li>• Reduce the travel speed.</li> </ul>

#### Porosity

1.	Inadequate shielding of arc and weld pool.	<ul style="list-style-type: none"> <li>• Increase the shielding gas flow.</li> <li>• Eliminate drafts (from fans, open doors etc.) blowing into the welding arc.</li> <li>• Reduce the arc gap.</li> <li>• Hold the gun till the molten crater solidifies.</li> </ul>
2.	Work-piece contamination.	<ul style="list-style-type: none"> <li>• Remove oil, grease, rust, paints and dusts from the work surface prior to welding.</li> </ul>

#### Incomplete fusion

1.	Work-piece surface not clean.	<ul style="list-style-type: none"> <li>• Clean all groove surfaces and weld zones.</li> </ul>
2.	Insufficient heat input.	<ul style="list-style-type: none"> <li>• Increase the current or reduce the diameter of the filler metal.</li> <li>• Decrease the travel speed.</li> <li>• Set the appropriate torch angle.</li> <li>• Length-wise grind the tip.</li> </ul>
3.	Too large a weld puddle.	<ul style="list-style-type: none"> <li>• Reduce arc weaving.</li> </ul>
4.	Improper welding technique.	<ul style="list-style-type: none"> <li>• Direct the electrode at the leading edge of the weld pool.</li> </ul>
5.	Improper joint design.	<ul style="list-style-type: none"> <li>• Select proper groove design.</li> </ul>

## Common GTAW problems – Causes & Remedies

<i>Possible Causes</i>	<i>Corrective Actions</i>
------------------------	---------------------------

### Lack of penetration

1.	Improper joint preparation.	<ul style="list-style-type: none"> <li>• Provide/Increase root openings in butt-joint.</li> <li>• Decrease the height of root face.</li> </ul>
2.	Improper welding technique.	<ul style="list-style-type: none"> <li>• Maintain the arc on the leading edge of the weld pool.</li> <li>• Select proper travel angle to achieve maximum penetration.</li> </ul>
3.	Inadequate heat input.	<ul style="list-style-type: none"> <li>• Select right diameter of electrode.</li> <li>• Increase the welding current.</li> <li>• Maintain proper torch angle.</li> </ul>

### White patches in radiographic film

1.	Tungsten electrode contamination.	<ul style="list-style-type: none"> <li>• Avoid touching the electrode with the weld metal.</li> <li>• Re-grind the electrode to desired shape.</li> </ul>
----	-----------------------------------	---

