

Common SAW problems – Causes & Remedies

1.0 COMMON WELDING DEFECTS OBSERVED IN SAW PROCESS:

The process variables, materials or welding procedures can affect the weld quality. Some of the commonly observed defects in SAW welding and their possible remedies are tabulated below.

<i>Possible Causes</i>	<i>Corrective Actions</i>
-------------------------------	----------------------------------

Weld metal cracks

1.	Too high a weld depth-to-width ratio.	<ul style="list-style-type: none"> • Increase the arc voltage or decrease the welding current.
2.	Too small a weld bead.	<ul style="list-style-type: none"> • Decrease the travel speed.
3.	Rapid cooling of the crater at the end of the weld.	<ul style="list-style-type: none"> • Fill craters adequately. • Hold the arc for few seconds by stopping the trolley movement before stop of the welding.

Inclusions

1.	Use of multiple pass, short circuiting type welding (slag).	<ul style="list-style-type: none"> • Clean the previous bead before making subsequent passes.
2.	High travel speeds (film type inclusions).	<ul style="list-style-type: none"> • Reduce the travel speed. • Increase the arc voltage.

Porosity

1.	Inadequate re-drying of flux or long time exposure to open air after re-drying of the flux.	<ul style="list-style-type: none"> • Re-dry the flux as recommended by the manufacturer. • In case of open air exposure or over-night exposure, ensure flux is dried again before use. • Reduce the travel speed. • Reduce the arc gap. • Hold the gun till the molten crater solidifies.
2.	Electrode contamination.	<ul style="list-style-type: none"> • Use clean and dry electrodes. • Eliminate contamination of electrode wire with any lubricant.
3.	Work-piece contamination.	<ul style="list-style-type: none"> • Remove oil, grease, rust, paints and dusts from the work surface prior to welding.
4.	Suitability of the flux	<ul style="list-style-type: none"> • Flux type varies with speed of welding or its characteristics to operate at higher current

Common SAW problems – Causes & Remedies

& AC/DC polarity. Follow the manufacturer recommendation.

Incomplete fusion

1.	Work-piece surface not clean.	<ul style="list-style-type: none"> Clean all groove surfaces and weld zones.
2.	Insufficient heat input.	<ul style="list-style-type: none"> Increase the electrode feed rate and the arc voltage. Decrease the travel speed.
3.	Improper welding technique.	<ul style="list-style-type: none"> Set the wire properly in the position in a multi-layer weld deposit.
4.	Improper joint design.	<ul style="list-style-type: none"> Select proper groove design. Maintain a proper groove angle to provide an easy access to electrode extension.

Lack of penetration

1.	Improper joint preparation.	<ul style="list-style-type: none"> Provide/Increase root openings in butt-joint. Decrease the height of root face.
2.	Improper welding technique.	<ul style="list-style-type: none"> Set the wire position based on the bead profile of the previous bead.
3.	Inadequate heat input.	<ul style="list-style-type: none"> Increase the wires feed rate, voltage and/or reduce travel speed.

Excessive melt through

1.	Excessive heat input.	<ul style="list-style-type: none"> Reduce the electrode feed rate & volt. Increase the travel speed.
2.	Improper joint preparation.	<ul style="list-style-type: none"> Reduce excessive root opening. Increase the height of the root face.

